

Rick L. Gardner Plant Manager

April 08, 2010

WO 10-0024

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555

> Subject: Docket No. 50-482: Licensee Event Report 2010-003-00, "Positive Reactivity Addition in Mode 2 with One Source Range Neutron Flux Channel Inoperable"

Gentlemen:

The enclosed Licensee Event Report (LER) is being submitted in accordance with 10 CFR 50.73, "Licensee event report system," paragraph (a)(2)(i)(B) as a condition prohibited by the plant's Technical Specifications (TS). The LER involves the failure to meet the Required Actions of Condition I of TS 3.3.1, "Reactor Trip System (RTS) Instrumentation." On August 23, 2009, Wolf Creek Generating Station (WCGS) transitioned from Mode 3 to Mode 2 with one Source Range Neutron Flux channel inoperable. Additionally, the transitioning from Mode 3 to Mode 3 to Mode 2 with one Source Range Neutron Flux channel inoperable is a failure to meet Limiting Condition for Operation (LCO) 3.0.4a.

This letter contains no commitments. If you have any questions concerning this matter, please contact me at (620) 364-4156, or Mr. Richard D. Flannigan at (620) 364-4117.

Sincerely,

Rick/L. Gardner

RLG/rlt

Enclosure: -

cc: E. E. Collins (NRC), w/e G. B. Miller (NRC), w/e B. K. Singal (NRC), w/e Senior Resident Inspector (NRC), w/e



				(p. );			er alfred to the	1.21.21.21.01				
	U.S INSEE EVEN See reverse for digits/characte	IT REPO	<b>ORT</b>	<b>(LER)</b>	Y COMMIS	SSION	Estimated request: 80 licensing pr estimate to Nuclear Re e-mail to in and Regula Budget, W collection d not conduc	burden per burden per burden for burden Record burden Record gulatory Co focollects@ tory Affairs, ashington, E boes not disp	Reported less ed back to ind ds and FOIA// mmission, Wa nrc.gov, and t NEOB-10202, 0C 20503. If i lay a currently or, and a per	04 E comply with this ons learned are ustry. Send comr Privacy Service I ishington, DC 200 o the Desk Offica (3150-0104), Offi a means used to valid OMB contro son is not requi	incorporat nents regar Branch (T-5 555-0001, o er, Office of ce of Mana impose an I number, th	y collection ed into the ding burden 5 F52), U.S. r by internet Information gement and information ne NRC may
FACILITY NAME WOLF CREEK	GENERATI	NG ST/	ΑΤΙΟ	DN			2. docke 05	т NUMBE 000 482		3. PAGE 1	OF 3	
	eactivity Ad						ce Rano	e Neut	ron Flux	Channel In	operab	le
5. EVENT DATE	6. LER	NUMBER		7. R	EPORT D				OTHER FAC	ILITIES INVO	LVED DOCKET NUMBER	
ONTH DAY YEAR			REV NO.	MONTH	DAY	YEAR	FACILITY				05000	
02 11 201 OPERATING MODE		004 -	00	04	08	2010	D			CFR§: (Chec	05000	
1 20.2201(b)   20.2201(d) 20.2203(a)(1)   20.2203(a)(2)(i) 20.2203(a)(2)(ii)   20.2203(a)(2)(ii) 20.2203(a)(2)(iii)   20.2203(a)(2)(iii) 20.2203(a)(2)(iii)   100 20.2203(a)(2)(v)   20.2203(a)(2)(v) 20.2203(a)(2)(v)				□ 20.2203(a)(3)(ii) □   □ 20.2203(a)(4) □   □ 50.36(c)(1)(i)(A) □   □ 50.36(c)(2) □   □ 50.36(c)(2) □   □ 50.46(a)(3)(ii) □   □ 50.73(a)(2)(i)(A) □				50.73(a)(2)(i)(C) 50.73(a)(2)(vii)   50.73(a)(2)(ii)(A) 50.73(a)(2)(viii)(A)   50.73(a)(2)(ii)(B) 50.73(a)(2)(viii)(B)   50.73(a)(2)(iii) 50.73(a)(2)(viii)(B)   50.73(a)(2)(viii) 50.73(a)(2)(viii)(B)   50.73(a)(2)(viii) 50.73(a)(2)(viii)(B)   50.73(a)(2)(vi)(A) 50.73(a)(2)(x)(A)   50.73(a)(2)(v)(A) 73.71(a)(4)   50.73(a)(2)(v)(B) 73.71(a)(5)   50.73(a)(2)(v)(C) OTHER   50.73(a)(2)(v)(D) Specify in Abstract below or in NRC Form 366A				(B) A) ct below
			12	2. LICENS	SEE CONT	TACT F	OR THIS L	.ER				
CILITY NAME ichard D. Flanni	gan, Manag	er Regi	ulato	ry Affai	irs					ерноне NUMBEF 20) 364-41	•	a Code)
	13. COMPLE		INE F	OR EACH	I COMPO			DESCRIBE	D IN THIS I	REPORT		
CAUSE SYSTE		FACTU		REPOR TO E		<u>с</u>	AUSE	SYSTEM	COMPONEN	T MANU- FACTURER		RTABLE EPIX
14. SUPPLEMENTAL REPORT EXPECTED 15. EXPECTE   SUBMISSION SUBMISSION   □ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☑ NO						VISSION	MONTH	DAY	YEAR			
STRACT (Limit to 14 On 2/11/2010 t specifications v Condition I, for Source Range A loss of off-sit a result, power channel, SEN0 increased and s	e NRC issue hile in Mode making positi Neutron Flux power even to the Contai 031, was read tabilized sigr	d violati 2." The ve react channel t on 8/1§ nment C ding som	ion 20 inspo tivity a l was 9/200 Cavity newh	009005- ectors id addition inopera 99 cause Cooling at lower er than	009, "Po dentified prohibit able. ed a read g fans wa than So SEN003	ctor tri as lost ource l 32. Or	Reactivi icited vio technica p and tur t. During Range N n 08/20/2	bine trip this per eutron F 009, the	Technical ations in I and the p iod, Sourc lux chann Cavity Co	l Specificatio Mode 2 beca plant enterec ce Range Ne el SEN0032	on 3.3.1, ause one I Mode 3 eutron F t, then ras starte	e 3. As lux

	新,11年198月 男小利 「「小小」」		· .	3			
NRC FORM 366A (9-2007)	t z Isabs en All en		U.S. NUCLE	AR REGUL	ATORY	COMMISS	SION
LICENSEE EVENT REPORT (LER) 1. FACILITY NAME	2. DOCKET		6. LER NUMBER	lyng - Horis Anersystem	3	3. PAGE	
WOLF CREEK GENERATING STATION	05000 482	YEAR	SEQUENTIAL NUMBER	REV NO.	2	OF	3
	a a the second to the	2010	004	00			
PLANT CONDITIONS PRIOR TO EVEN	Ť ,						
MODE – 1 Power – 100							
EVENT DESCRIPTION							
On 2/11/2010 the NRC issued violation 20090 specifications while in Mode 2." The inspecto Condition I, for making positive reactivity addi Source Range Neutron Flux channel [EIIS Co	ors identified a no ition prohibited by	ncited viola technical	ation of Technic	al Specif	ication 3	3.3.1,	
A loss of off-site power event on 8/19/2009 ca As a result, power to the Containment Cavity Flux channel, SEN0031, was reading somew then increased and stabilized significantly hig	Cooling fans was hat lower than So	lost. Duri ource Rang	ing this period, \$	Source R	ange N	eutron	
On 08/20/2009, a Containment Cavity Cooling rapidly returned to near the same relative indi procedure STS IC-231, "Channel Operational Protection Set 1," was completed satisfactoril Range Neutron Flux Trip bistable functions w with surveillance requirement (SR) 3.3.1.1 be	ication of SEN003 I Test Nuclear Ins ly. This surveillar then the trip setpo	32, as exisistrumentati ace injects bint is exce	ted initially. Lat on System Sou a test signal an eded. Channel	er on 08/ rce Rang d verifies checks i	20/2009 je N-31 the Sou n accor	), urce dance	
Outside of the short period of time when the c expected without deviation. It passed all surv SEN0031 was energized, as expected, shorth continuously until de-energized during startup to the period shortly after cavity cooling was k one hour after cavity cooling was restored.	veillances and no by after the Loss of o on 8/23/2009. T	anomalies of Offsite Po The abnorm	were noted du ower and the in nally high indica	ring its op strument tion was	peration function confine	ned d solely	
On 08/22/2009, Wolf Creek entered the mode Creek entered Mode 2 and the reactor becam ascension to point of de-energizing the source applicability, both source range instruments in	ne critical on 8/23 e range instrume	/2009. Du nts above	ring the reactor P-6, which exite	startup and the mo	and pow de of		
During the startup, both channels of Source F procedure GEN 00-003, "Hot Standby to Minin demonstrated that SEN0031 was functioning	mum Load," and	both were	found to be acc	eptable.	This fu	rther	
At the beginning of Refuel Outage 17, Electric 10/10/09 through 10/13/09 that assessed the channels have been operating normally over condition had remained essentially constant o	condition of the c the last few years	letector cir and the E	cuits. The Sou	rce Rang	e Neutr	on Flux	

?

NRC FORM 366A (9-2007) LICENSEE EVENT REPORT (LER)		U.S. NUCLE	AR REGUL	ATORY	COMMISS	SION			
1. FACILITY NAME	2. DOCKET					3. PAGE			
WOLF CREEK GENERATING STATION	05000 482	YEAR	SEQUENTIAL NUMBER	REV NO.	3	OF	3		
WOEF ONEER GENERATING OTATION	00000 402	2010	004	00	5		3		

\*\*\* **v**g -

1.1.1.1.1

# BASIS FOR REPORTABILITY

This condition is being reported based on NRC issuance of noncited violation 2009005-009, "Positive Reactivity Addition Prohibited by technical specifications while in Mode 2." Additionally, during a review of this event, it was identified that the transitioning from Mode 3 to Mode 2, and closing the reactor trip breakers, with one Source Range Neutron Flux channel inoperable is a failure to meet Limiting Condition for Operation (LCO) 3.0.4a.

This condition is being reported per 10 CFR 50.73(a)(2)(i)(B) as an operation or condition prohibited by Technical Specifications.

## CAUSE

The most probable cause of the behavior for SEN0031 following loss of cavity cooling was increased temperature of the detector and associated cabling resulting in increased count rate indication. The violation occurred, because after cavity cooling was restored and SEN0031 indication returned to normal, Wolf Creek did not consider SEN0031 to be inoperable prior to entering the mode of applicability.

## CORRECTIVE ACTIONS

Source range detector SEN0031 was replaced during Refueling Outage 17 in November 2009.

## SAFETY SIGNIFICANCE

The safety significance of this condition is low. Outside of the short period of time when the Containment Cavity Cooling fans were unavailable, SEN0031 performed as expected without deviation. It passed required surveillances and no anomalies were noted during its operation. During the subsequent reactor startup and power ascension to point of de-energizing the Source Range Neutron Flux channels above P-6, which exited the mode of applicability, both Source Range Neutron Flux channels indicated normally and required channel checks were satisfactory. SEN0032 was able to perform its Source Range High Flux Trip function during the modes of applicability, and there is no indication that SEN0031 would not have been able to perform its Source Range High Flux trip function.

# **OPERATING EXPERIENCE/PREVIOUS EVENTS**

None