

J. R. Johnson
Vice President - Farley

**Southern Nuclear
Operating Company, Inc.**
Post Office Drawer 470
Ashford, Alabama 36312-0470

Tel 334 814 4511
Fax 334.814.4728



June 17, 2010

Docket No.: 50-364

NL-10-1151

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555-0001

Joseph M. Farley Nuclear Plant – Unit 2
Licensee Event Report 2010-001-00
Unplanned LOSP during SI with LOSP Testing

Ladies and Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(iv)(A), Southern Nuclear Operating Company (SNC) is submitting the enclosed Licensee Event Report.

This letter contains no NRC commitments. If you have any questions, please contact Doug McKinney at (205)992-5982.

Sincerely,

A handwritten signature in black ink that reads "J. R. Johnson". The signature is fluid and cursive, with a long horizontal stroke extending to the right.

J. R. Johnson
Vice President – Farley

JRJ/WDO

Enclosure: Unit 2 Licensee Event Report 2010-001-00

U. S. Nuclear Regulatory Commission
NL-10-1151
Page 2

cc: Southern Nuclear Operating Company
Mr. J. T. Gasser, Executive Vice President
Mr. J. R. Johnson, Vice President – Farley
Ms. P. M. Marino, Vice President – Engineering
RTYPE: CFA04.054

U. S. Nuclear Regulatory Commission
Mr. L. A. Reyes, Regional Administrator
Mr. R. E. Martin, NRR Project Manager – Farley
Mr. E. L. Crowe, Senior Resident Inspector – Farley
Mr. P. Boyle, NRR Project Manager

**Joseph M. Farley Nuclear Plant – Unit 2
Licensee Event Report 2010-001-00
Unplanned LOSP during SI with LOSP Testing**

Enclosure

Unit 2 Licensee Event Report 2010-001-00

LICENSEE EVENT REPORT (LER)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Joseph M Farley Nuclear Plant – Unit 2	2. DOCKET NUMBER 05000 364	3. PAGE 1 of 3
---	--------------------------------------	--------------------------

4. TITLE
Unplanned LOSP during SI with LOSP Testing

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV. NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
04	30	2010	2010	- 001 -	00	06	17	2010		05000
									FACILITY NAME	DOCKET NUMBER
										05000

9. OPERATING MODE 6	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)									
	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)						
10. POWER LEVEL 000	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)						
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)						
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)						
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)						
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)						
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)						
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER						
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A						

12. LICENSEE CONTACT FOR THIS LER

NAME J. R. Johnson – Vice President	TELEPHONE NUMBER (Include Area Code) (334) 899-5156
---	---

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO	15. EXPECTED SUBMISSION DATE	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On April 30, 2010 at 21:00, an unplanned Loss of Off-Site Power (LOSP) on A-train 4160 volt emergency Bus 2F occurred during a scheduled outage test, Safety Injection (SI) with LOSP. The Emergency Diesel Generator (EDG) 1-2A was being shutdown following the actuation portion of the test. When the B2F Sequencer was reset, the EDG output breaker (DF08-2) unexpectedly opened to generate the LOSP signal on the 2F Bus. As a result, the B2F Sequencer functioned to automatically re-close DF08-2, and start both the 2A Motor Driven Auxiliary Feedwater (MDAFW) pump and 2A High Head Safety Injection (HHSI) pump. All systems functioned as designed for this condition and core cooling was maintained throughout by the B-train 2B Residual Heat Removal (RHR) pump. Unit 1 remained at 100 % power during the event.

A recent design change was implemented to assure EDG sequencer reliability during all modes of EDG operation. Subsequent to this design change, the necessary procedure change had not been properly incorporated in the test procedure. Test guidance relied upon transitioning to the System Operating Procedure (SOP) for operating the newly installed Test Trip Override Switch (TTOS) located on the B2F Sequencer. However, the transition was not at the correct location in the test procedure. Once recognized, the SOP guidance was used and the B2F Sequencer TTOS was operated before resetting the sequencer; and the restoration section was completed without further complications.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Joseph M. Farley Nuclear Plant Unit - 2	05000 364	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2	of
		2010	- 001	- 00		

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Westinghouse -- Pressurized Water Reactor
Energy Industry Identification Codes are identified in the text as [XX]

Description of Event

On April 30, 2010 at 21:00, an unplanned Loss of Off-Site Power (LOSP) on A-train 4160 volt emergency Bus 2F [EB] occurred during a scheduled outage test, Safety Injection (SI) with LOSP. The Emergency Diesel Generator (EDG) 1-2A [EK] was being shutdown following the actuation portion of the test. When the B2F Sequencer (A-train) was reset, the EDG output breaker (DF08-2) unexpectedly opened to generate the LOSP signal on 4160 volt Bus 2F. As a result, the B2F Sequencer functioned to automatically re-close DF08-2 and start both the 2A Motor Driven Auxiliary Feedwater (MDAFW) [BA] pump and 2A High Head Safety Injection (HHSI) [BQ] pump. All systems functioned as designed for this condition, and core cooling was maintained throughout by the B-train 2B Residual Heat Removal (RHR) [BP] pump. Flow to the reactor core was maintained. Unit 1 was not affected and remained at 100 % power during the event.

A recent design change was implemented to assure EDG sequencer reliability during all modes of EDG operation. Subsequent to this design change, the necessary procedure change had not been properly incorporated in the test procedure. Test guidance relied upon transitioning to the System Operating Procedure (SOP) for operating the newly installed Test Trip Override Switch (TTOS) located on the B2F Sequencer. However, the transition was not at the correct location in the test procedure. Once recognized, SOP procedure guidance was used and the B2F Sequencer TTOS was operated before resetting the sequencer, and the restoration section was completed without further complications.

In accordance with 10 CFR 50.72(b)(3)(iv)(A) for a valid actuation of the auxiliary feedwater and emergency core cooling systems, an eight hour non-emergency report was issued on May 1, 2010 at 01:01, Event Notification number 45889.

Cause of Event

A recent design change was implemented to assure EDG sequencer reliability during all modes of EDG operation. Subsequent to this design change, the necessary procedure change had not been properly incorporated in the test procedure. Test guidance relied upon transitioning to the System Operating Procedure (SOP) for operating the newly installed Test Trip Override Switch (TTOS) located on the B2F Sequencer. However, the transition was not at the correct location in the test procedure.

Safety Assessment

This event had no adverse effect on the safety and health of the public. There were no safety system functional failures and all systems functioned as designed.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Joseph M. Farley Nuclear Plant Unit - 2	05000 364	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 of 3
		2010	- 001	- 00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

The Farley onsite standby power source is provided from four EDGs (1-2A, 1B, 2B, and 1C). The continuous service rating of 1C EDG is 2,850 kW and 4,075 kW for EDGs 1-2A, 1B, and 2B. EDG 1-2A and 1C are A-Train and EDGs 1B and 2B are B-Train. Farley also has a fifth diesel generator (2C) that serves as a station blackout diesel, which can be manually aligned to supply B-Train power to either unit and power LOSP loads.

During the restoration portion of the test procedure, EDG 1-2A was operating and tied to the 2F Emergency Bus. When resetting the B2F Sequencer, the failure to operate the TTOS on the B2F Sequencer caused the EDG output breaker (DF08-2) to open. Sensing the LOSP condition, the B2F Sequencer properly functioned to re-close DF08-2 and sequentially start and connect loads on emergency Bus 2F. Both the 2A MDAFW pump and 2A HHSI pump sequentially started as designed to prevent overloading of the EDG. The EDG output breaker closure and sequencing of shutdown loads are required functions of an EDG and therefore had no adverse effect on the safety and health of the public. The B-train 2B EDG was operable and the 2B RHR pump was in operation throughout the event.

Corrective Action

The SI with LOSP test procedure was completed satisfactorily once the TTOS was properly operated. MDAFW Pump 2A and HHSI Pump 2A were secured. The 4160 volt Bus 2F was aligned to the normal offsite power supply.

An enhanced Apparent Cause Determination was performed and corrective actions developed to address the failure to properly revise the test procedure after the design change.

SNC Operating Experience (OE) on the event has been issued.

Additional Information

Previous Similar Events:

LER 2009-001-00 Unit 1 and 2 - EDG 1C Auto Start due to Inadvertent Relay Actuation