

Timothy S. Rausch
Sr. Vice President & Chief Nuclear Officer

PPL Susquehanna, LLC
769 Salem Boulevard
Berwick, PA 18603
Tel. 570.542.3445 Fax 570.542.1504
tsrausch@pplweb.com



JUN 21 2010

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Stop OP1-17
Washington, DC 20555

**SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-387/2010-002-00
LICENSE NO. NPF-14
PLA-6626**

Docket No 50-387

Attached is Licensee Event Report (LER) 50-387/2010-002-00. On April 22, 2010, and on May 14, 2010, Susquehanna Steam Electric Station Unit 1 experienced an automatic reactor scram during planned post-modification testing of a new digital feedwater Integrated Control System (ICS) that was installed during the Unit 1 refueling outage. These events were determined to be reportable under 10 CFR 50.73(a)(2)(iv)(A) for an event that resulted in the manual or automatic actuation of the RPS and RCIC.

In accordance with NUREG-1022, Rev. 2, Section 2.3, "Reporting of Multiple Events," more than one failure or event may be reported in a single LER if; 1) the failures or events are related (i.e., they have the same general cause or consequences), and 2) they occurred during a single activity (e.g., a test program) over a reasonably short time (e.g. 60 days LER reporting). Since, both reactor scrams occurred during implementation of the ICS testing program and are related events, one LER is being submitted for both Unit 1 events.

Because the root cause analysis for these events is not yet complete, the causes and corrective actions documented in this LER are considered preliminary. Upon completion and approval of the root cause analysis, PPL will submit a supplement to the LER by August 1, 2010.

There were no actual consequences to the health and safety of the public as a result of these events.

T. S. Rausch
Senior Vice President - Chief Nuclear Officer

Attachment

Copy: NRC Region I
Mr. P. W. Finney, NRC Sr. Resident Inspector
Mr. R. V. Guzman, NRC Sr. Project Manager
Mr. R. R. Janati, DEP/BRP

bc:	M. H. Crowthers	GENPL4
	D. R. D'Angelo	NUCSB2
	J. M. Helsel	NUCSB3
	P. A. Horn (SRC)	NUCSB2
	L. G. Oberrender	NUCLC
	B. W. O'Rourke	NUCSA4
	R. D. Pagodin	NUCSB3
	J. J. Petrilla III	NUCSA4
	R. M. Rose	GENPL4
	R. R. Schechterly	NUCSA3
	J. J. Scopelliti	SSO
	G. J. Treven	NUCSB2
	T. G. Wales (DBD)	GENPL5
	NRA File	GENPL4
	DCS	GENPL4

Send Microsoft Word copy to: LEREvents@inpo.org

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOF-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Susquehanna Steam Electric Station Unit 1	2. DOCKET NUMBER 05000387	3. PAGE 1 OF 5
--	-------------------------------------	--------------------------

4. TITLE
Automatic Reactor Scrams Occur during Post-Modification Testing of the Digital Feedwater Integrated Control System

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
04	22	2010	2010	- 002 -	00	06	21	2010	FACILITY NAME	DOCKET NUMBER
										05000
										05000

9. OPERATING MODE 1	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)			
10. POWER LEVEL 32%	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER	
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A	

12. LICENSEE CONTACT FOR THIS LER

Facility Name Brenda W. O'Rourke, Senior Engineer - Nuclear Regulatory Affairs	Telephone Number (Include Area Code) (570) 542-1791
---	--

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED <input checked="" type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input type="checkbox"/> NO	15. EXPECTED SUBMISSION DATE	MONTH 08	DAY 01	YEAR 2010
--	-------------------------------------	-------------	-----------	--------------

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On April 22, 2010, at 1051 hours, Susquehanna Steam Electric Station Unit 1 experienced an automatic reactor scram, from 32% power, on low reactor water level (ENS 45866). The low level condition occurred during planned testing of a new digital feedwater Integrated Control System (ICS), which included upgrades to the feedwater level control system, the reactor feed pump turbine speed controls, and the reactor recirculation speed controls. During testing at low power conditions, the second of three reactor feed pumps (RFP) was placed in automatic flow control mode for the first time with the goal of parallel automatic operation of two RFPs. A reactor water level transient occurred when the second RFP began feeding into the reactor. The resulting concurrent flow reduction of both RFPs quickly lowered water level to the low level scram setpoint. Corrective actions were taken to adjust the ICS speed controller gain and master feedwater level controller gain.

At approximately 2301 hours on May 14, 2010, Unit 1 automatically scrambled from 66% power due to a main turbine trip on high reactor water level (ENS 45930). The high level condition occurred during additional planned testing of the digital ICS, which involved the trip of one of the four condensate pumps. The high reactor water level transient was attributed to a large feedwater flow/steam flow mismatch caused by insufficient gain on the ICS master feedwater level control system master water level controller in response to large transient conditions. Corrective actions were taken to increase the system gains for large transients using "gap" control on the ICS level controller and flow controller.

On May 30, 2010, ICS testing of the condensate pump trip event was successfully completed.

The preliminary root cause for both events was due to less than adequate engineering rigor being applied during the development and implementation of the ICS gain factors. There were no actual adverse consequences to the health and safety of the public as a result of these events. The Reactor Protection System (RPS) responded as expected. All control rods fully inserted.

These events are being reported under 10 CFR 50.73(a)(2)(iv)(A) due to the actuation of the RPS and RCIC. Because the root cause analysis for these events is not yet complete, the causes and corrective actions documented in this LER are considered preliminary. Upon completion and approval of the root cause analysis, this LER will be supplemented by August 1, 2010.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Susquehanna Steam Electric Station Unit 1	05000387	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 5
		2010	-002-	00	

NARRATIVE

CONDITION PRIOR TO THE EVENTS

Event 1: April 22, 2010, Unit 1 - Mode 1, 32 percent Rated Thermal Power

Event 2: May 14, 2010, Unit 1 - Mode 1, 94 percent Rated Thermal Power

EVENT DESCRIPTIONS

Event 1 -

On April 22, 2010, at 1051 hours, Susquehanna Steam Electric Station (SSES) Unit 1 experienced an automatic reactor [EIS Code: AC] scram on low reactor water level (+ 13 inches). This scram occurred while implementing planned testing of the new digital feedwater Integrated Control System (ICS) during power ascension following the Unit 1 refueling outage. During the outage, upgrades to the feedwater level control system, the reactor feed pump turbine speed controls, and the reactor recirculation speed controls were made by the installation of ICS. During testing at low power conditions (i.e., 32% power), the second of three (A, B and C) reactor feed pumps (RFP) [EIS Code: SJ] was placed in automatic flow control mode for the first time with the goal of parallel automatic operation of two RFPs. A reactor water level transient occurred when the second RFP began feeding into the reactor. Reactor water level reached a maximum of approximately 12 inches above normal operating level. As a result, the control room operator placed the second RFP speed controller in manual mode and reduced the rate of feed into the reactor vessel in accordance with procedures. Concurrent with this action, the ICS responded to the high level condition by lowering the other operating RFP's speed. The resulting concurrent flow reduction of both RFPs quickly lowered water level to the low water level scram setpoint. A control room operator was in the process of taking the mode switch to shutdown when an automatic reactor scram signal initiated on low reactor water level.

The Reactor Protection System (RPS) [EIS Code: JC] response to the automatic scram was as expected and all control rods fully inserted. Following the reactor scram, reactor water level dropped to approximately -30 inches wide range. The Reactor Core Isolation Cooling (RCIC) [EIS Code: BN] system automatically initiated as expected. The 'A' RFP and RCIC restored level to within normal limits. An Alternate Rod Insertion Div 2 signal was received during the transient and was subsequently reset. Primary containment integrity was maintained during the event. An ENS notification (# 45866) was made to the NRC in accordance with 10 CFR 50.72(b)(2)(iv)(B) for an event or condition that resulted in the actuation of the RPS when the reactor was critical, and 10 CFR 50.72(b)(3)(iv)(A) due to a valid actuation of the RPS and RCIC.

Event 2 -

On May 14, 2010, at 2301 hours, SSES Unit 1 automatically scrammed from 66% power due to a main turbine trip on high reactor water level (+ 54 inches). As expected, all three RFPs tripped on high reactor water level. The high water level condition occurred during additional planned testing of the new digital ICS which involved a planned trip of one of the four condensate pumps. This test was performed as required by an Extended Power Uprate (EPU) license condition, to verify that a loss of all feedwater would not occur due to low feedwater pump suction pressure. As designed, this resulted in an automatic reactor recirculation [EIS Code: AD] pump run-back and a subsequent reactor water level transient. A larger than expected steam flow/feed flow mismatch developed due to insufficient gain on the master feedwater level controller (MFWLC), which resulted in steam flow dropping off at a much greater rate than feedwater flow. As a result, an aggregate vessel level rate of increase of 30 inches per minute was experienced. When the reactor water level exceeded the expected upper response range of the test, the operator placed the mode switch in shutdown. An automatic reactor scram signal initiated on a turbine trip due to high reactor water level occurring nearly simultaneously as the control room operators placed the mode switch in shutdown.

The RPS response to the automatic scram was as expected and all control rods fully inserted. Following the scram, reactor water level lowered to -30 inches wide range. RCIC was manually initiated at -24 inches and injected for level control. In accordance with plant procedures, the control room operator restored the 'B' reactor feed pump and RCIC

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Susquehanna Steam Electric Station Unit 1	05000387	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 5
		2010	-002-	00	

was secured. Reactor water level was restored to within normal limits. Primary containment integrity was maintained during the event. An ENS notification, (# 45930) was made to the NRC in accordance with 10 CFR 50.72(b)(2)(iv)(B) for an event or condition that resulted in the actuation of the RPS when the reactor was critical, and 10 CFR 50.72(b)(3)(iv)(A) due to a valid actuation of the RPS and RCIC.

In accordance with NUREG-1022, Rev. 2, Section 2.3, Reporting of Multiple Events, more than one failure or event may be reported in a single Licensee Event Report (LER) if; 1) the failures or events are related (i.e., they have the same general cause or consequences), and 2) they occurred during a single activity (e.g., a test program) over a reasonably short time (e.g., 60 days LER reporting). Since, both reactor scrams occurred during implementation of the ICS testing program and the events are related, one LER is being submitted for both events in accordance with 10 CFR 50.73(a)(2)(iv)(A) for an event that resulted in the manual or automatic actuation of the RPS and RCIC.

Because the root cause analysis for these events is not yet complete, the causes and corrective actions documented in this LER are considered preliminary. Upon completion and approval of the root cause analysis, a supplement to this LER will be submitted by August 1, 2010.

PRELIMINARY CAUSE(S) OF THE EVENT

Event 1 –

Performance characteristics of the mechanical equipment associated with the RFP turbine steam admission system were not well understood. As a result, the ICS system gains were inadequate for the low power and steam flow conditions that existed at the time of the test. In particular, there existed an unrecognized RFP turbine transition from low pressure (LP) to high pressure (HP) and HP to LP steam flow that decreases the response of the RFPs when operating at low power conditions with an increasing speed demand signal. It is believed that this non-responsiveness of the feedwater pumps was due to the lack of significant change in steam flow (i.e., motive force) to the feedwater pump turbine while the governor control valve position was moving through this transition zone. Because of this, manual control of the RFP turbines during this water level-transient was ineffective in preventing the low level condition. As such, the initial gain settings in ICS did not sufficiently account for system performance at low power conditions. While the transition zone still exists, the speed controller gain has been increased to make the speed control governor control valve open or close more (i.e., admit more steam or less steam) for a given demand within this transition zone.

In addition, the plant simulator, which was used to confirm these gain settings prior to performing the test, did not accurately model plant performance. As a result, the misunderstanding of the performance characteristics of the mechanical equipment was not identified prior to testing.

Event 2 –

The ICS MWLC was not originally configured with sufficient gain to handle a large transient such as the loss of a Condensate Pump. This conclusion is based on review of event data that showed that the MWLC demand to the 'A', 'B' and 'C' RFP turbine speed controllers did not decrease demand sufficiently to terminate the reactor vessel level increase following the condensate pump trip.

The MWLC demand did not decrease sufficiently to mitigate the transient because the original ICS gain parameters resulted in a relatively low flow gain. The original flow gain was selected during system tuning and implemented at lower power levels based on acceptable response for small flow upset events. The selection of these values did not anticipate the need for larger gains during transients that have larger flow and level impacts.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Susquehanna Steam Electric Station Unit 1	05000387	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 5
		2010	-002-	00	

The plant simulator was used prior to the condensate pump trip test to train the operators on expected plant response. The simulator did not react as the plant did due to a software error in the ICS controller function. Therefore, pre-site acceptance testing on the simulator and training for the Operators did not reveal the issue prior to the actual performance of the Unit 1 condensate pump trip test.

Combined Root Cause for Events 1 and 2

The preliminary root cause for both the April 22, 2010 and May 14, 2010 Unit 1 scram events was due to less than adequate engineering rigor being applied during the development and implementation of the ICS gain factors.

Because the root cause analysis for these events is not yet complete, the causes documented in this LER are considered preliminary. Upon completion and approval of the root cause analysis, a supplement to this LER will be submitted by August 1, 2010.

ANALYSIS/SAFETY SIGNIFICANCE

The ICS is a digital Distributed Control System (DCS) that includes three major control systems that are integrated into a single DCS architecture known as ICS. The ICS installation was deemed necessary to support plant operation at EPU power levels due to the need for additional condensate and feedwater flow and corresponding increased reliability of the overall feedwater system. At uprated conditions, the operators will be making more speed changes in order to maximize generation and address atmospheric impacts. The ICS system includes enhanced reactor recirculation system runbacks, feedwater margin (rundown) capability, eliminates single point failures, and provides the benefits of an integrated control system on a common platform. The ICS modifications included 1) the replacement of the obsolete RFP Turbine Speed Bailey Control system for all three RFP turbines, Feed Water Level Bailey Control system, and Reactor Recirculation Pump Speed Bailey Control system, and 2) the replacement of the manual control switches, indicators, and hard-wired controls on the control room panels with touch-screen digital controls and displays, for added system monitoring and stability, and enhanced user-interface and controls.

Actual Consequences

Event 1 -

Following the reactor scram all control rods fully inserted. RPS performance was as expected. Reactor water level lowered to -30 inches wide range following the scram signal due to void collapse in the core. RCIC automatically initiated and injected. RCIC and the 'A' RFP restored level to within normal limits. RCIC response to the automatic initiation was as expected.

The balance of plant response was not typical due to loss of one of the two 13.8 kV auxiliary buses caused by planned maintenance on one of the offsite feeder breakers. Auxiliary Bus 11A automatically transferred to an offsite source as expected. However, the offsite source to Auxiliary Bus 11B was unavailable and as a result this bus de-energized. This resulted in the loss of several large loads, including the 'B' Condensate Pump, 'B' Reactor Recirculation Pump, 'B' Circulating Water Pump, and the 'B' Service Water Pump. Consequently, the 'C' and 'B' RFPs tripped due to low suction pressure. After the trip of the second RFP (i.e., 'B'), suction pressure recovered such that the 'A' RFP remained in operation.

Due to loss of Auxiliary Bus 11B, six non-essential load centers lost power and were subsequently manually cross-tied to restore power to various load and motor control centers. Power to Auxiliary Bus 11B was subsequently restored at 1217 hours.

The main steam isolation valves (MSIVs) remained open during the transient and pressure was controlled via the main turbine bypass valves. No safety relief valve actuations occurred during this event. Primary containment integrity was

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Susquehanna Steam Electric Station Unit 1	05000387	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	5 OF 5
		2010	-002-	00	

maintained throughout the event. There were no diesel generator starts. The event was bounded by transients analyzed in Chapter 15 of the SSES Final Safety Analysis Report.

Event 2 -

Following the reactor scram all control rods fully inserted. RPS performance was as expected. Reactor water level lowered to -30 inches wide range following the scram signal due to void collapse in the core. RCIC was manually initiated at -24 inches and injected for level control. The 'B' RFP was restored and RCIC was secured. Level was restored to within normal limits. The lowest reactor water level reached was approximately -30 inches on wide range.

The MSIVs remained open during the transient and pressure was controlled via the main turbine bypass valves. There were no safety relief valve actuations during the event. Primary containment integrity was maintained throughout the event. There were no diesel generator starts. The event is bounded by transients analyzed in Chapter 15 of the SSES Final Safety Analysis Report.

Based upon the above discussion, the actual consequences of these events were minimal. There was no impact to the health and safety of the public.

Potential Consequences

None.

CORRECTIVE ACTIONS

Completed Actions:

Event 1 -

- Immediate corrective actions were taken to adjust the ICS speed controller gain and master feedwater level controller gain to compensate for the RFP non-responsiveness at low power conditions. The appropriate procedures were revised to reflect these changes.

Event 2 -

- The ICS design incorporates Flow Control, Level control (e.g., feed forward / cascade control), adaptive tuning techniques (e.g., different gains at various power levels), and "gap" control (i.e., higher / lower gains within a defined band) as well as dynamic system features that are intended to maximize reactor water level control stability. The corrective actions taken as a result of this event provided increased system gains for large transients on the ICS Level Controller and the Flow Controller.
- Adjustments were made that maintained the existing gains for small transients while increasing the gain for large transients. These changes provide a more aggressive control action response during large transients and keeps the current "as tuned" control response for smaller transients (i.e., normal expected operational occurrences).

Subsequent testing of ICS for both small and large transients, including the successful Unit 1 condensate pump trip test on May 30, 2010, indicated that the corrective actions were appropriate

Planned Corrective Actions:

The final root cause analysis will identify the planned corrective actions, including actions to prevent recurrence. Upon completion and approval of the root cause analysis, a supplement to this LER will be submitted by August 1, 2010.