# **ITS NRC Questions**

	-
Id	1471
NRC Question Number	ALK-009
Category	Editorial
ITS Section	3.0
ITS Number	3.0
DOC Number	A-2
JFD Number	
JFD Bases Number	
Page Number (s)	Vol. 5, pg 13 of 63
NRC Reviewer Supervisor	Rob Elliott
Technical Branch POC	Add Name
Conf Call Requested	Ν
NRC Question	Please verify if this is a typo that needs to (will) be corrected: Discussion of Changes for ITS 3.0, A02, first paragraph in 3 <sup>rd</sup> bullet: " upon discovery <i>or</i> failure to meet an LCO" should be " upon discovery <i>of</i> failure to meet an LCO"
Attach File 1	
Attach File 2	
Issue Date	1/11/2010
Added By	Audrey Klett
Date Modified	
Modified By	
Date Added	1/11/2010 11:54 AM
Notification	NRC/LICENSEE Supervision Audrey Klett

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 2 of 415

Id	1791
NRC Question Number	ALK-009
Select Application	Licensee Response
Response Date/Time	1/19/2010 7:55 AM
Closure Statement	
Response Statement	The NRC reviewer is correct in that the word "or" should be "of." A draft markup regarding this change is attached. This change will be reflected in the supplement to this section of the ITS conversion amendment.
Question Closure Date	
Attachment 1	ALK-009 Markup.pdf (699KB)
Attachment 2	
Notification	NRC/LICENSEE Supervision Jerry Jones Bryan Kays Audrey Klett Ray Schiele
Added By	Robert Hanley
Date Added	1/19/2010 7:54 AM
Modified By	
Date Modified	

## Attachment 1, Volume 5, Rev. 0, Page 13 of 63

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 3 of 415 DISCUSSION OF CHANGES ITS 3.0, LCO AND SR APPLICABILITY

#### ADMINISTRATIVE CHANGES

A01 In the conversion of the Kewaunee Power Station (KPS) Current Technical Specifications (CTS) to the plant specific Improved Technical Specifications (ITS), certain changes (wording preferences, editorial changes, reformatting, revised numbering, etc.) are made to obtain consistency with NUREG-1431, Rev. 3.0, "Standard Technical Specifications-Westinghouse Plants" (ISTS).

These changes are designated as administrative changes and are acceptable because they do not result in technical changes to the CTS.

- A02 CTS 3.0.a states, "Compliance with the LIMITING CONDITIONS FOR OPERATION contained in the succeeding TSs is required during the operational MODES or other conditions specified therein; except that upon failure to meet the LIMITING CONDITIONS FOR OPERATION, the associated ACTION requirements shall be met." ITS 3.0.1 states, "LCOs shall be met during the MODES or other specified conditions in the Applicability, except as provided in LCO 3.0.2, LCO 3.0.7, and LCO 3.0.8." This results in several changes to the CTS.
  - Certain phrases are revised to be consistent with the equivalent phrase used in the ITS. Specifically, "operational MODES or other conditions specified therein" is changed to "MODES or other specified conditions in the Applicability" to be consistent with the ITS definition of MODE and the terminology used in the ITS.

These changes are acceptable because they result in no change in the intent or application of the Technical Specifications, but merely reflect editorial preferences used in the ITS.

• The phrase "Compliance with the LIMITING CONDITIONS FOR OPERATION contained in the TS is required" is replaced with "LCOs shall be met." This change is made consistent with the ITS.

This change is acceptable because it is an editorial change that does not change the intent of the requirements.

 The phrase "except that upon failure to meet the LIMITING CONDITIONS FOR OPERATION, the associated ACTION requirements shall be met" is moved from CTS 3.0.a to ITS LCO 3.0.2, which states that upon discovery of failure to meet an LCO, the Required Actions of the associated Conditions shall be met.

The change is acceptable because moving this information within the Technical Specifications results in no change in the intent or application of ACTIONS.

• The phrase "except as provided in LCO 3.0.2, LCO 3.0.7, and LCO 3.0.8" is added in ITS LCO 3.0.1. ITS LCO 3.0.2 describes the appropriate actions to be taken when ITS LCO 3.0.1 is not met. ITS LCO 3.0.7 describes Test

Kewaunee Power Station

Page 1 of 13

Attachment 1, Volume 5, Rev. 0, Page 13 of 63

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 4 of 415

Id	1801
NRC Question Number	ALK-009
Select Application	NRC Question Closure
Response Date/Time	
Closure Statement	This question is closed, and no further information is required at this time to draft the Safety Evaluation.
Response Statement	
Question Closure Date	1/19/2010
Attachment 1	
Attachment 2	
Notification	NRC/LICENSEE Supervision
Added By	Audrey Klett
Date Added	1/19/2010 8:14 AM
Modified By	
Date Modified	

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 5 of 415

# **ITS NRC Questions**

_	
Id	1531
NRC Question Number	ALK-010
Category	Editorial
ITS Section	3.0
ITS Number	3.0
DOC Number	A-3
JFD Number	
JFD Bases Number	
Page Number (s)	Vol. 5, page 14 of 63
NRC Reviewer Supervisor	Rob Elliott
Technical Branch POC	Add Name
Conf Call Requested	Ν
NRC Question	Please verify that the addition of the word "not" in the quotation contained in the following statement is a typo that needs to (will) be corrected: Discussion of Changes for ITS 3.0, A03, first paragraph in $2^{nd}$ bullet: "The sentence is change, in ITS LCO 3.0.2, to state 'If the LCO is <i>not</i> [emphasis added] met or is no longer applicable prior to expiration of the specified Completion Time(s)"
Attach File 1	
Attach File 2	
Issue Date	1/22/2010
Added By	Audrey Klett
Date Modified	
Modified By	
Date Added	1/22/2010 7:51 AM
Notification	NRC/LICENSEE Supervision

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 6 of 415

# Licensee Response/NRC Response/NRC Question Closure

Id 1951 NRC Question ALK-010 Number Select Licensee Response Application Response 1/28/2010 8:50 AM Date/Time Closure Statement Response The NRC reviewer is correct in that the word "not" is a typo and is Statement incorrect. The sentence should not include the word and should read "If the LCO is met or is no longer applicable ... " Furthermore, KPS has noted that a typo exists in the same bullet and will also be corrected at this time. A draft markup regarding this change is attached. This change will be reflected in the supplement to this section of the ITS conversion amendment.

Question Closure Date Attachment ALK-010 Markup.pdf (699KB) 1 Attachment 2 Notification NRC/LICENSEE Supervision **Jerry Jones Bryan Kays Audrey Klett** Melissa Krcma **Ray Schiele** Added By Robert Hanley Date Added 1/28/2010 8:50 AM Modified By Date Modified

## Attachment 1, Volume 5, Rev. 0, Page 14 of 63

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 7 of 415 DISCUSSION OF CHANGES ITS 3.0, LCO AND SR APPLICABILITY

Exceptions LCOs, which are exceptions to other LCOs. ITS LCO 3.0.8 addresses snubber inoperabilities, which is also an exception to other LCOs.

This change is acceptable because adding the exceptions for LCO 3.0.2, LCO 3.0.7, and LCO 3.0.8 prevent a conflict within the Applicability section. This addition is needed for consistency in the ITS requirements and does not change the intent or application of the Technical Specifications.

These changes are designated administrative because they are editorial and result in no technical changes to the Technical Specifications.

- A03 CTS 3.0.b states, "Noncompliance with a TS shall exist when the requirements of the LIMITING CONDITIONS FOR OPERATION and associated ACTION requirements are not met within the specified time intervals. If the LIMITING CONDITIONS FOR OPERATION is restored prior to expiration of the specified time intervals, completion of the ACTION requirements is not required." ITS LCO 3.0.2 states "Upon discovery of a failure to meet an LCO, the Required Actions of the associated Conditions shall be met, except as provided in LCO 3.0.5 and LCO 3.0.6. If the LCO is met or is no longer applicable prior to expiration of the specified Completion Time(s), completion of the Required Action(s) is not required unless otherwise stated." This results in several changes to the CTS.
  - CTS 3.0.b is revised to include an exception for LCO 3.0.6. LCO 3.0.6 is a new allowance that takes exception to the ITS LCO 3.0.2 requirement to take the associated ACTION requirements when a LIMITING CONDITION FOR OPERATION is not met. This exception is included in LCO 3.0.2 to avoid conflict between the applicability requirements.

This change is acceptable because it includes a reference to a new item in the ITS and results in no change to the CTS. Changes resulting from the incorporation of LCO 3.0.6 are discussed in Discussion of Change (DOC) A08.

The second sentence of CTS LCO 3.0.b states, "If the LIMITING CONDITIONS FOR OPERATION is restored prior to expiration of the specified time intervals, completion of the ACTION requirements is not
 required." The sentence is change, in ITS LCO 3.0.2, to state "If the LCO is not-met or is no longer applicable prior to expiration of the specified Completion Time(s), completion of the Required Action(s) is not required unless otherwise stated."

This change is acceptable because, while worded differently, both the CTS and ITS state that ACTIONS do not have to be completed once the LCO is met or is no longer applicable. ITS LCO 3.0.2 also adds the phrase "unless otherwise stated." There are some ITS ACTIONS that must be completed, even if the LCO is met or is no longer applicable. This change is acceptable because it reflects a new feature in the ITS which does not exist in the CTS. The technical aspects of these changes are discussed in the appropriate ITS sections.

Kewaunee Power Station

Page 2 of 13

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 8 of 415

Id	1981
NRC Question Number	ALK-010
Select Application	NRC Question Closure
Response Date/Time	
Closure Statement	This question is closed, and no further information is required at this time to draft the Safety Evaluation.
Response Statement	
Question Closure Date	2/2/2010
Attachment 1	
Attachment 2	
Notification	NRC/LICENSEE Supervision
Added By	Audrey Klett
Date Added	2/2/2010 8:21 AM
Modified By	
Date Modified	

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 9 of 415

# **ITS NRC Questions**

Id	1651
NRC Question Number	ALK-011
Category	Technical
ITS Section	3.0
ITS Number	3.0
DOC Number	A-6
JFD Number	
JFD Bases Number	
Page Number(s)	Vol. 5, page 15 of 63
NRC Reviewer Supervisor	Rob Elliott
Technical Branch POC	Add Name
Conf Call Requested	Ν
NRC Question	DOC A06 for ITS 3.0 states, in part, "Certain CTS contain ACTIONS such as 'Declare the {supported system} inoperable and take the ACTIONS of {its Specification}.' In many cases, the supported system would likely already be considered inoperable. The implication of this presentation is that the ACTIONS of the inoperable supported system would not have been taken without the specific direction to do so."
	For each CTS that contains ACTIONS such as, "Declare the {supported system} inoperable and take the ACTIONS of {its Specification}", please clarify if adopting the STS LCO 3.0.6 would result in a less restrictive change for these TS. If it does, then please denote this change as less restrictive.
Attach File 1	
Attach File 2	
Jacua Data	1 /20 /2010

Issue Date 1/29/2010

Added By Audrey Klett

Date Modified

Modified By

Date Added 1/29/2010 2:27 PM

Notification NRC/LICENSEE Supervision Audrey Klett

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 10 of 415

# Licensee Response/NRC Response/NRC Question Closure

2181	Id
ALK-011	NRC Question Number
Licensee Response	Select Application
2/15/2010 3:50 PM	Response Date/Time
	Closure Statement
_	D

Response The statement in question is to clarify that the CTS wording means that Statement actions of supported systems do not have to be taken until directed by the support system actions, which is consistent with CTS use and application. In the ISTS, a similar approach is taken. That is, when a support system is inoperable, it may direct, either immediately or after some length of time, to cascade to the supported system Actions (i.e., take the actions in the support system). This change simply specifies that this CTS approach will be maintained in the ITS, thus the change is administrative. However, if the CTS does not allow a delay in the cascade requirement and the ITS does, then this delay is evaluated and justified in each individual Specification. For example, ITS 3.8.3 allows a delay in declaring the EDG inoperable when fuel oil or staring air requirements are not met. These less restrictive changes are justified in ITS 3.8.3 DOCs. KPS believes that each individual Specification adequately justifies any extension in declaring the support system inoperable and taking the Actions of the support system. Furthermore, this Discussion of Change is consistent with the DOCs used in other ITS conversions and approved by the NRC.

Question Closure Date Attachment 1 Attachment 2 Notification NRC/LICENSEE Supervision Jerry Jones **Bryan Kays** Audrey Klett **Ray Schiele** Added By Robert Hanley Date Added 2/15/2010 3:50 PM Modified By Date Modified

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 11 of 415

Id	2201
NRC Question Number	ALK-011
Select Application	NRC Question Closure
Response Date/Time	
Closure Statement	This question is closed, and no further information is required at this time to draft the Safety Evaluation.
Response Statement	
Question Closure Date	2/17/2010
Attachment 1	
Attachment 2	
Notification	NRC/LICENSEE Supervision Audrey Klett
Added By	Audrey Klett
Date Added	2/17/2010 10:06 AM
Modified By	
Date Modified	

# **ITS NRC Questions**

Id	1671
NRC Question Number	ALK-013
Category	Technical
ITS Section	3.0
ITS Number	3.0
DOC Number	L-1
JFD Number	
JFD Bases Number	
Page Number (s)	Att.1, v.5, pg 55 of 63
NRC Reviewer Supervisor	Rob Elliott
Technical Branch POC	Add Name
Conf Call Requested	Ν
NRC Question	The 10 CFR 50.92 evaluation for L01 in Attachment 1, Volume 5, page 55 of 63, discusses TSTF-359, Rev. 8; however, in Enclosure 3 to the ITS license amendment request letter, this TSTF is not listed to be adopted in whole or in part in the KPS ITS. Is it KPS's intention to fully adopt this TSTF?
Attach File 1	
Attach File 2	
Issue Date	2/18/2010
Added By	Audrey Klett
Date Modified	
Modified By	
Date Added	2/18/2010 9:53 AM
Notification	NRC/LICENSEE Supervision Audrey Klett

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 13 of 415

Id	2271
NRC Question Number	ALK-013
Select Application	Licensee Response
Response Date/Time	2/25/2010 10:20 AM
Closure Statement	
Response Statement	Enclosure 3 to the ITS Submittal includes only those TSTFs that are not already incorporated into NUREG-1431, Rev. 3.0. That is, it lists TSTFs that are to be incorporated into Revision 3.0 of NUREG-1431 (the latest issued revision of the NUREG). TSTF-359, Rev. 8 (and Rev. 9, which is the most current version of the TSTF) is already incorporated completely into NUREG-1431, Rev. 3.0, therefore, it is not listed in Enclosure 3. Kewaunee has incorporated this TSTF as typed into NUREG-1431, Rev. 3.0, as modified by minor changes identified in the ISTS Markup and justified by the applicable JFDs.
Question Closure Date	
Attachment 1	
Attachment 2	
Notification	NRC/LICENSEE Supervision Robert Hanley Jerry Jones Bryan Kays Audrey Klett
Added By	David Mielke
Date Added	2/25/2010 10:22 AM
Modified By	
Date Modified	

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 14 of 415

	2421
NRC Question Number	ALK-013
Select Application	NRC Question Closure
Response Date/Time	
Closure Statement	This question is closed, and no further information is required at this time to draft the Safety Evaluation.
Response Statement	
Question Closure Date	3/4/2010
Attachment 1	
Attachment 2	
Notification	NRC/LICENSEE Supervision Audrey Klett
Added By	Audrey Klett
Date Added	3/4/2010 7:47 AM
Modified By	
Date Modified	

Page 1 of 1

# **ITS NRC Questions**

Id	1681
NRC Question Number	ALK-014
Category	Technical
ITS Section	3.0
ITS Number	3.0
DOC Number	
JFD Number	
JFD Bases Number	9
Page Number (s)	att.1, v.5, pg 53 of 63
NRC Reviewer Supervisor	Rob Elliott
Technical Branch POC	Add Name
Conf Call Requested	Ν
NRC Question	Please clarify the WOG STS section and text for which JFD #9 for ITS 3.0 Bases (Volume 5, page 53 of 63) applies. The JFD 9 designator does not appear in the margins of the marked-up WOG STS Bases.
Attach File 1	
Attach File 2	
Issue Date	2/18/2010
Added By	Audrey Klett
Date Modified	
Modified By	
Date Added	2/18/2010 9:56 AM
Notification	NRC/LICENSEE Supervision Audrey Klett

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 16 of 415

Id	2281
NRC Question Number	ALK-014
Select Application	Licensee Response
Response Date/Time	2/25/2010 10:25 AM
Closure Statement	
Response Statement	Kewaunee has reviewed the ISTS Bases Markup and determined that JFD 9 is not used in the ITS submittal for this Section. The JFD will be deleted. A draft markup regarding this change is attached. This change will be reflected in the supplement to this section of the ITS conversion amendment.
Question Closure Date	
Attachment 1	ALK-014 Markup.pdf (703KB)
Attachment 2	
Notification	NRC/LICENSEE Supervision Robert Hanley Jerry Jones Bryan Kays Audrey Klett
Added By	David Mielke
Date Added	2/25/2010 10:28 AM
Modified By	
Date Modified	

## Attachment 1, Volume 5, Rev. 0, Page 53 of 63

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 17 of 415 JUSTIFICATION FOR DEVIATIONS ITS 3.0 BASES, LCO AND SR APPLICABILITY

- 8. This statement has been deleted since the Kewaunee Power Station ITS submittal does not state the snubbers do not meet the 10CFR50.36(c)(2)(ii) criteria. This is also consistent with the NRC SERs for DC Cook Units 1 and 2 and Monticello ITS amendments.
- Not used.
- This Reviewer's Note has been deleted. This information is for the NRC reviewer to be keyed in to what is needed to meet this requirement. This is not meant to be retained in the final version of the plant specific submittal.
- 10. These changes are made to be consistent with the wording of LCO 3.0.7.
- 11. The ITS SR 3.0.1 Bases allows credit to be taken for unplanned events that satisfy Surveillances. The Bases further states that this allowance also includes those SRs whose performance is normally precluded in a given MODE or other specified condition. This portion of the allowance has been deleted. As documented in Part 9900 of the NRC Inspection Manual, Technical Guidance Licensee Technical Specifications Interpretations, and in the Bases Control Program (ITS 5.5.12), neither the Technical Specifications Bases nor Licensee generated interpretations can be used to change the Technical Specification requirements. Thus, if the Technical Specifications preclude performance of an SR in certain MODES (as is the case for some SRs in ITS Section 3.8), the Bases cannot change the Technical Specifications requirement and allow the SR to be credited for being performed in the restricted MODES, even if the performance is unplanned.
- 12. Changes have been made for consistency with similar discussions/terminology in the Bases.
- 13. The ISTS SR 3.0.1 Bases provides two examples of when it is not possible to perform post maintenance testing in the current MODE or other specified conditions in the Applicability due to the necessary unit parameters not having been established. The second example is not valid for Kewaunee Power Station and therefore it has been deleted.
- 14. The proper LCO title and Applicability have been provided.
- 15. Changes are made to be consistent with changes made to the Specification.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 18 of 415

	2431
NRC Question Number	ALK-014
Select Application	NRC Question Closure
Response Date/Time	
Closure Statement	This question is closed, and no further information is required at this time to draft the Safety Evaluation.
Response Statement	
Question Closure Date	3/4/2010
Attachment 1	
Attachment 2	
Notification	NRC/LICENSEE Supervision Audrey Klett
Added By	Audrey Klett
Date Added	3/4/2010 7:48 AM
Modified By	
Date Modified	

# **ITS NRC Questions**

1751	Id
ALK-015	NRC Question Number
Technical	Category
3.0	ITS Section
3.0	ITS Number
M-1	DOC Number
	JFD Number
	JFD Bases Number
Att. 1, vol. 5, pg 19 of	Page Number(s)
Carl Schulten	NRC Reviewer Supervisor
Add Name	Technical Branch POC
Ν	Conf Call Requested
Attachment 1. Vo	NRC

63

<sup>NRC</sup> Attachment 1, Volume 5, page 19 of 63, DOC M01 discusses KPS's intent to incorporate LCO 3.0.8 into the KPS ITS. Please provide the following:

a. corrected pages that show the removal of CTS LCO 3.14.b as an "R" DOC (Relocated Specifications), and

b. a safety basis for why the 12-hour requirement in LCO 3.0.8b, as described in TSTF 372, Revision 4, and the NRC's model safety evaluation of this TSTF, cannot be met and therefore presents a hardship (e.g., operational challenges, reductions in safety, etc.) for KPS. Include in the response plant-specific design and licensing basis information, deterministic insights, and risk insights that justify the proposed time period for ITS LCO 3.0.8b. Describe the extent of the hardship as it applies to all KPS TS systems with snubbers. Also describe how the proposed 24-hour time allowance was derived from this safety basis analysis.

	Attach File 1
	Attach File 2
2/23/2010	Issue Date
Audrey Klett	Added By
	Date Modified
	Modified By

Date Added 2/23/2010 2:08 PM

Notification NRC/LICENSEE Supervision Audrey Klett Carl Schulten Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 21 of 415

## Licensee Response/NRC Response/NRC Question Closure

#### Id **2491**

NRC Question Number Select Application Response Date/Time Closure Statement

Statement As stated in the NRC Model Safety Evaluation for TSTF-372, Section 2.0, LCO 3.0.8 was added into the ISTS because of a difference of interpretation as to whether or not the 72 hour delay to enter the actions for the supported equipment in the old STS Snubber Technical Specification could be applied after the Snubber Technical Specification had been relocated to a licensee-controlled document as part of a licensee's conversion to the ISTS. The Safety Evaluation states that the NRC's position is that after relocation, the 72 hour delay cannot be used if the inoperable snubber also results in inoperability of the supported system. Thus, plants that had already converted to ISTS and had relocated the Snubber Technical Specification to a licensee-controlled document needed an allowance to delay entry into the supported systems when a required snubber is inoperable. TSTF-372 and the NRC CLIIP provided the requirements for these plants to adopt a new delay time for when a required snubber is inoperable. However, this CLIIP requirement on how to justify a new 72 hour delay time is only for plants that have already adopted the ISTS and relocated their old CTS Snubber Technical Specification.

> Kewaunee Power Station (KPS) currently has a 72 hour delay time in CTS 3.14. KPS has not, as yet, relocated the Snubber Technical Specification to a licensee-controlled document. Therefore, KPS does not believe that we have to re-justify the currently allowed 72 hour delay time for one train or the proposed 24 hour delay time for two trains to adopt LCO 3.0.8. The times and requirements of proposed LCO 3.0.8 are all equal to or more restrictive than the current actions provided in CTS 3.14 when a snubber is inoperable. KPS provided a More Restrictive DOC to justify the changes from the CTS to ITS LCO 3.0.8, with respect to the actions to take when a required snubber is inoperable. This More Restrictive DOC is consistent with a previously approved ITS conversion, specifically, Davis-Besse. The NRC approved the adoption of LCO 3.0.8 from their current Snubber LCO, which is similar to the KPS Snubber LCO (i.e., 72 hours is allowed for one or more snubbers to be OPERABLE). Furthermore, the NRC asked a similar question (i.e., requesting that Davis-Besse do the requirements, including the evaluations, listed in the CLIIP). Davis-Besse proposed to either maintain the DOC as an M DOC, but also incorporate the CLIIP Section 3.2 requirements (which include only the Tier 2 restrictions) or to maintain current licensing basis by not adopting the LCO 3.0.8 and including a

Page 2 of 3

Technical Specification identical to the CTS Snubber Specification, converted to ITS format.

The NRC accepted the first Davis-Besse option, which was to adopt LCO 3.0.8 but commit to the applicable Tier 2 requirements. A copy of the original RAI and all responses is attached (attachment 1). This RAI was docketed by Davis-Besse in a letter dated May 16, 2008 (ML081480464 and ML081480465). The Davis-Besse discussion of the two options is in the licensee response of 2/15/08 and the NRC acceptance of Option 1 is in the NRC reviewer response dated 4/1/2008. In addition, the NRC SER for the Davis-Besse ITS conversion, dated November 20, 2008 (ML082900600 and ML082910112), also stated that the change from the CTS Snubber Actions to adopting ITS LCO 3.0.8 was a more restrictive change. A copy of the applicable portions of the SER Table is attached (attachment 2).

In the KPS ITS submittal, KPS ensured that all the final requirements the NRC imposed on Davis-Besse as part of their Option 1 proposal were included in the more restrictive DOC. Furthermore, the commitments the NRC required of Davis-Besse are also included in the KPS submittal. These commitments are located in Attachment 5 to the ITS submittal cover letter, commitments 2 through 5. Based on the above, KPS believes that the ITS submittal, classifying the change as a more restrictive change, not requiring any CLIIP-related technical evaluations, and adopting the Tier 2 restrictions of the CLIIP (including the proposed commitments), is acceptable.

However, similar to Davis-Besse, KPS will provide the NRC the option of KPS maintaining the Current Licensing Basis of CTS 3.14. Specifically, this will require KPS to generate a new Technical Specification that is not currently in the ISTS, and not adopt LCO 3.0.8. The new Specification will maintain all the requirements of CTS 3.14 and CTS 4.14, in ISTS format. It should be noted that the current delay times and Action requirements are less restrictive than what is currently required by LCO 3.0.8.

Question<br/>Closure<br/>DateAttachmentAttachment 1 for ALK-015.pdf (454KB)Attachment<br/>2Attachment 2 for ALK-015.pdf (39KB)NotificationNRC/LICENSEE Supervision<br/>Jerry Jones<br/>Bryan Kays<br/>Audrey Klett<br/>Ray SchieleAdded ByRobert HanleyDate Added3/10/2010 7:02 AM

Kewaunee ITS Conversion Database

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 23 of 415

Date Modified

#### NRC ITS Tracking Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 24 of 415

# Return to View Menu Print Document RAI Screening Required: No Status: Approval Not Required This is a Non RAI Dialogue This document will not be relied upon by staff for disposition of the LAR This document has been reviewed and information in this question contains NO SUNSI sensitive material (the checkbox to the right must be selected before this Yes

Page 1 of 5

question can be submitted)

## NRC ITS TRACKING

## NRC Reviewer

ID	200712101502		Conference Call R	Conference Call Requested? No	
Category	In Scope				
ITS Information	ITS Section: 3.0 Carl Schult ITS Number: None	TB POC: cen <u>OSI:</u> None	JFD Number: None DOC Number: M.2	Page Number(s): 8 Bases JFD Number: None	
Comment	NoneM.2NoneSection 3.0Volume 5, Page 8 of 62 DOC M02LCO 3.0.8 is added to CTS per TSTF-372, Revision 4 by M02. Adopting the TSTF changesrequires submittal of the content of the CLIIP TSTF Model Application and Model SafetyEvaluation in accordance with Federal Register Notice (69 FR 68412, November 24, 2004)(ADAMS ML051160013) before these changes to CTS can be processed. To efficiently processthe incoming license amendment applications, the staff requests each licensee applying for thechanges addressed by TSTF-3372, Revision 4, as modified, using the CLIIP to include basesfor the proposed technical specification consistent with the bases proposed in the TSTF-372,Revision 4 as stated FRN. Identify and submit documentation for all differences between thecontent of DOC M02 and the content of a license application submittal required by the TSTF-372 CLIIP.				
Issue Date	ssue Date 12/10/2007				
Close Date 04/09/2008					
<b>Responses</b>					
Licensee Response by Jerry Jones on 01/04/2008		The CLIIP application is to TSTF-372, the ISTS di	based on a plant that has al d not include any snubber	ready adopted the ISTS. Prior requirements - they were to be	

to TSTF-372, the ISTS did not include any snubber requirements - they were to be relocated to a plant-controlled document. Thus, for an ITS plant to adopt TSTF-372, they would have to justify the allowances provided in ITS LCO 3.0.8. Furthermore, the CLIIP discussed this issue specifically, in that it stated that prior to ITS development, old CTS already had most of the allowances provided by ITS LCO 3.0.8, and that the TSTF was just adding them back into the ITS since they appeared to be lost when a plant adopted the ITS and relocated the old CTS requirements to plant controlled documents. Davis-Besse has not relocated the current snubber

http://www.excelservices.com/exceldbs/itstrack\_davisbesse.nsf/1fddcea10d3bdbb585256e85000138e4/77b3... 4/24/2008

## NRC ITS Tracking Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 25 of 415

	Techncial Specification, CTS 3.7.7, to a plant controlled document. Thus, in order to adopt the ITS LCO 3.0.8, Davis-Besse only has to justify the differences from the CTS requirements to the ITS requirements. The allowances provided in ITS LCO 3.0.8 are all more restrictive that what is allowed in CTS 3.7.7. Since the allowances provided in LCO 3.0.8 are all more restrictive than what is allowed by the Actions of CTS 3.7.7, Davis-Besse does not believe that a plant specific evaluation to justify the current 72 hour time (as is required by the CLIIP) is required. This manner of adopting LCO 3.0.8 is also consistent with a previously approved ITS conversion, Monticello, which adopted TSTF-372 as part of the conversion. Furthermore, the NRC asked a similar question, and did not require any changes to the more restrictive Discussion of Change submitted as part of the Monticello conversion. The question is still viewable on the EXCEL website (question 200512151125).
NRC Response by Carl Schulten on 01/30/2008	LCO 3.0.8 is a risk-informed TS. The three tiered approach for assessing the acccetability of risk-informed TS changes are dicussed in RG 1.177. The submittal information contained in the model application for TSTF-372 which follows the 3-tiered approach has not been provided to the NRR staff for review. There are conditions and speCific limitions to be met to adopt the allowances of TSTF-372. The shortest path to revising the Davis Besse licensing basis to incorporate LCO 3.0.8 risk-informed allowances is to submit the TSTF-372 CLIIP model application for staff review.
Licensee Response by Bryan Kays on 02/15/2008	As stated in the NRC Model Safety Evaluation for TSTF-372, Section 2.0, LCO 3.0.8 was added into the ISTS because of a difference of interpretation as to whether or not the 72 hour delay to enter the actions for the supported equipment in the old CTS Snubber Technical Specification could be applied after the Snubber Technical Specification to a licensee-controlled document as part of a licensee's conversion to the ISTS. The Safety Evaluation states that the NRC's position is that after relocation, the 72 hour delay cannot be used if the inoperable snubber also results in inoperability of the supported system. Thus, plants that had already converted to ISTS and had relocated the Snubber Technical Specification to a licensee-controlled document needed an allowance to delay entry into the supported systems when a required snubber is inoperable. TSTF-372 and the NRC CLIIP provided the requirements for these plants to adopt a new delay time for when a required snubber is inoperable. However, this CLIIP requirement on how to justify a new 72 hour delay time is only for plants that have already adopted the ISTS and relocated the old CTS Snubber Technical Specification. Davis-Bess currently has a 72 hour delay time in CTS 3.7.7. We have not, as yet, relocated the Snubber Technical Specification to a licensee-controlled document. Therefore, Davis-Besse does not believe that we have to re-justify the currently allowed 72 hour delay time to adopt LCO 3.0.8. The times and requirements of LCO 3.0.8 are all equal to or more restrictive than the current actions provided in CTS 3.7.7 when a snubber is inoperable. Davis-Besse provided a More Restrictive DOC to justify the changes from the CTS to ITS LCO 3.0.8, with respect to the actions to take when a required snubber is inoperable. This More Restrictive DOC to justify the changes from the CTS to ITS LCO 3.0.8, with respect to the actions to take when a required snubber is inoperable. This More Restrictive DOC to justify the Changes from the CTS to ITS LCO 3.0.8, with respect

## NRC ITS Tracking Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 26 of 415

	applicable to this change are provided as an attachment. Based on the above, Davis-Besse believes that one of the two options provided below are available to resolve this issue: 1. Davis-Besse will adopt LCO 3.0.8 using the NRC precedent set for Monticello. The currently provided M DOC will be sufficient to justify the adoption of LCO 3.0.8 and the adoption will not be considered a beyond scope issue. Furthermore, Davis-Besse has reviewed the additional provisions discussed in the CLIIP's Model Safety Evaluation, Section 3.2, and will commit to ensuring appropriate plant procedures and administrative controls will be used to implement the applicable Tier 2 Restrictions. Specifically: a) at least one EFW train (including a minimum set of supporting equipment required for its successful operation) not associated with the inoperable snubber(s) must be available when LCO 3.0.8.a is used; b) at least one EFW train (including a minimum set of supporting equipment required for its successful operation) not associated with the inoperable snubber(s), or some alternative means of core cooling must be available when LCO 3.0.8.b is used; and c) every time the provisions of LCO 3.0.8 are used, Davis-Besse will confirm that at least one train of systems supported by the inoperable snubbers would remain capable of performing their required safety or support functions for postulated design loads other than seismic loads. In addition, a record of the design function of the inoperable snubber (i.e., seismic vs. non-seismic), implementation of any applicable Tier 2 restrictions, and the associated plant configuration shall be available on a recoverable basis for NRC staff inspection. These Tier 2 Restrictions are also more restrictive than what is currently required by the Davis-Besse to generate a new TS that is not currently in the ISTS, and not adopt LCO 3.0.8. It should be noted that the current delay times and Action requirements are less restrictive than what is currently required by LCO 3.0.8.
	Based on further discussion with the NRC reviewer, Davis-Besse has modified Discussion of Change M02 (Volume 5, Pages 22 and 23) to include the information required from the CLIIP for this change. A draft markup regarding this change is attached. This change will be reflected in the supplement to this section of the ITS Conversion Amendment. Furthermore, Davis-Besse has reviewed the additional provisions discussed in the CLIIP's Model Safety Evaluation, Section 3.2, and will commit to ensuring appropriate plant procedures and administrative controls will be used to implement the applicable Tier 2 Restrictions. Specifically: a) at least one EFW train (including a minimum set of supporting equipment required for its successful operation) not associated with the inoperable snubber(s) must be available when LCO 3.0.8.a is used; b) at least one EFW train (including a minimum set of supporting equipment required for its successful operation) not associated with the inoperable snubber(s), or some alternative means of core cooling must be available when LCO 3.0.8.b is used; and c) every time the provisions of LCO 3.0.8 are used, Davis-Besse will confirm that at least one train of systems supported by the inoperable snubbers would remain capable of performing their required safety or support functions for postulated design loads other than seismic loads. In addition, a record of the design function of the inoperable snubber (i.e., seismic vs. non-seismic), implementation of any applicable Tier 2 restrictions, and the associated plant configuration shall be available on a recoverable basis for NRC staff inspection. These Tier 2 Restrictions are also more restrictive than what is currently required by the Davis-Besse CTS.
NRC Response by Carl Schulten	Your stated option 1 will be accceptable, provided the response to this comment

NRC Response by Carl Schulten Your stated option 1 will be acceptable, provided the response to this comment

# NRC ITS Tracking Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 27 of 415

on 04/01/2008	restates Option 1, in its entirety, as the Davis Besse ITS conversion commitment for incorporating LCO 3.0.8 and resolving ID 200712101502.
Licensee Response by Bryan Kays on 04/07/2008	Based on the NRC reviewer's posting on 4/1/2008, Option #1 from the Davis-Besse 2/15/2008 response is acceptable, provided it is restated in its entirety as the commitment for incorporating LCO 3.0.8. During a phone call with the NRC reviewer on 4/7/08, the NRC reviewer stated that the Tier 2 Restrictions should be stated in the Discussion of Change (DOC) as documentation of the commitment. The following response supersedes the Davis-Besse response and draft markup posted on 4/1/08: Davis-Besse will adopt LCO 3.0.8 using the NRC precedent set for Monticello. The currently provided DOC M02 (Volume 5, Pages 22 and 23) will be sufficient to justify the adoption of LCO 3.0.8 and the adoption will not be considered a beyond scope issue. Furthermore, Davis-Besse has reviewed the additional provisions discussed in the CLIIP's Model Safety Evaluation, Section 3.2, and will modify DOC M02 (Pages 22 and 23) to clearly state that the Tier 2 Restrictions will be complied with. DOC M02 will include a discussion that Davis-Besse will ensure appropriate plant procedures and administrative controls will be used to implement the applicable Tier 2 Restrictions. Specifically: a) at least one EFW train (including a minimum set of supporting equipment required for its successful operation) not associated with the inoperable snubber(s) must be available when LCO 3.0.8.b is used; and c) every time the provisions of LCO 3.0.8. are used, Davis-Besse will confirm that at least one train of systems supported by the inoperable snubbers would remain capable of performing their required safety or support functions for postulated design loads other than seismic loads. In addition, a record of the design function of the inoperable snubber (i.e., seismic vs. non-seismic), implementation of any applicable Tier 2 restrictions, and the associated plant configuration shall be available on a recoverable basis for NRC staff inspection. These Tier 2 Restrictions are also more restrictive than what is currently required by the Davis-Besse KIS. A draft
NRC Response by Carl Schulten on 04/09/2008	The response submitted 04/01/2008 stated Davis-Besse will commit to ensuring appropriate plant procedures and administrative controls will be used to implement the applicable Tier 2 Restrictions. The specific commitments given in the 04/01/2008 response to 200712101502 need to be added to DOC M.2 (Section 3.0) to complete the record of the commitment in the Davis-Besse ITS license amendment application and finalize the response to 200712101502. The text that should be added to DOC M.2, which is in the 04/01/2008 response, is as follows: "Davis-Besse has reviewed the additional provisions discussed in the CLIIPS Model Safety Evaluation, Section 3.2, and will commit to ensuring appropriate plant procedures and administrative controls will be used to implement the applicable Tier 2 Restrictions. Specifically: a) at least one EFW train (including a minimum set of supporting equipment required for its successful operation) not associated with the inoperable snubber(s) must be available when LCO 3.0.8.a is used; b) at least one EFW train (including a minimum set of supporting equipment required for its successful operation) not associated with the inoperable snubber(s) must be available when LCO 3.0.8.b is used; and c) every time the provisions of LCO 3.0.8 are used, Davis-Besse will confirm that at

I	least one train of gratering summaried by the increasely symbols would remain
	least one train of systems supported by the inoperable snubbers would remain
	capable of performing their required safety or support functions for postulated
-	design loads other than seismic loads. In addition, a record of the design function of
	the inoperable snubber (i.e., seismic vs. non-seismic), implementation of any
	applicable Tier 2 restrictions, and the associated plant configuration shall be
	available on a recoverable basis for NRC staff inspection."

Date Created: 12/10/2007 03:02 PM by Carl Schulten Last Modified: 04/09/2008 11:17 AM

ITS/CTS No.	Description of Change	ITS Requirement	CTS Requirement
and DOC No.			
3.0	CTS 3.7.7 Action a provides the actions for inoperable snubbers, and	LCO 3.0.8	3.7.7 Action a
M02	requires one of the following (1, 2, or 3) within 72 hours when one or		
	more snubbers are inoperable: 1) replace or restore the inoperable		
	snubber(s) to OPERABLE status; 2) verify system operability with the		
	snubber(s) inoperable by engineering evaluation; or 3) declare the		
	supported system inoperable and follow the appropriate ACTION		
	statement for that system. In the ITS, the actions for inoperable		
	snubbers are incorporated into ITS limiting condition for operation		
	(LCO) 3.0.8. When one or more required snubbers are unable to		
	perform their associated support function(s), any affected supported		
	LCO(s) are not required to be declared not met solely for this reason if		
	risk is assessed and managed, and either: a) the snubbers not able to		
	perform their associated support function(s) are associated with only		
	one train or subsystem of a multiple train or subsystem supported		
	system or are associated with a single train or subsystem supported		
	system and are able to perform their associated support function within		
	72 hours; or b) the snubbers not able to perform their associated		
	support function(s) are associated with more than one train or		
	subsystem of a multiple train or subsystem supported system and are		
	able to perform their associated support function within 12 hours. At the		
	end of the specified period (i.e., 12 hours or 72 hours) snubbers must		
	be able to perform their associated function(s), or the affected system		
	LCO(s) shall be declared not met. This changes the CTS by requiring		
	the risk associated with inoperable snubbers to be assessed and		
	managed and requires the snubbers to be restored to OPERABLE		
	status in all cases, and in certain cases within a more restrictive CT.		

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 30 of 415

# Licensee Response/NRC Response/NRC Question Closure

Id **2851** 

NRC<br/>Question<br/>Number**ALK-015**Select<br/>Application**Licensee Response**Response<br/>Date/Time**4/29/2010 7:05 AM**Closure<br/>StatementStatement

Response Statement

This response supplements the previous KPS response. The previous response was posted on 3/10/2010. Subsequent to posting this response, this issue has been informally discussed with the NRC. The NRC requested further information regarding the proposed 24 hour allowance when a snubber affecting both trains of a safety related system was found to be non-functional.

The following is additional information verbally discussed with the NRC on subsequent phone conversations:

Kewaunee Nuclear Power Plant, Individual Plant Examination of External Events Summary Report," Wisconsin Public Service Corporation, June 28, 1994 (docketed number NRC-94-079) provides earth quake frequency for Kewaunee. Table 3-1, Mean Seismic Hazard Curves for the Kewaunee Site (page 3-64) identifies that the Peak Ground Acceleration (g) of 0.11 has a Mean Annual Probability of Exceedence of 1.10E-04.

TSTF-372 provides a discussion and formula for assessing risk associated with the use of LCO 3.0.8.b. The formula uses earth quake frequency for Peak Ground Acceleration (g) of 0.1 and failure probability for insulators to determine a frequency for seismic-induced LOOP. The formula also includes a time period for repairing a snubber which is used to determine incremental core damage probability during the snubber repair.

Table 3-1 of IPEEE does not provide an earth quake frequency for 0.1 g. However the frequency for 0.11 g is 1.10E-04 and the frequency for 0.01 g is 2.10E-03. By interpolation on a logarithmic scale, the frequency for 0.1 g would be 1.5E-04.

Using the TSTF-372 formula, Kewaunee's earthquake frequency is 1.5E-04. Kewaunee's proposed snubber repair period is 24 hours. Therefore, the incremental core damage probability (ICDP) for a snubber repair would be:

(1.5E-04/yr)(5E-02) X <u>24 hours</u> = 2 E-08 8760 hours/yr Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 31 of 415

Using the same assumptions as TSTF-372, it can be conservatively assumed that the delta-large energy release frequency (LERF) values resulting from the snubber out of service would be at least an order of magnitude less than the delta-CDF and ICDP values, respectively. Therefore, the incremental LERF (ILERF) for Kewaunee would conservatively be 2 E-09.

For Kewaunee, the ICDP and ILERF are two orders of magnitude less than the risk assumed for normal work controls as identified in TSTF-372.

Therefore, Kewaunee considers the allowance of 24 hours to perform maintenance on a snubber associated with more than one train or subsystem of a multiple train or subsystem supported system to be acceptable for safe plant operation.

The NRC also questioned whether or not the change was properly classified as an M change, since the CTS required the affected system to be isolated after 72 hours in order to use the option of declaring the affected system inoperable. KPS believed that maintaining the system properly aligned during this additional time is actually safer with regard to operating the unit; therefore, we classified it as a more restrictive change. However, deleting this requirement could be considered as less restrictive, since KPS will not have to isolate the affected system when ITS LCO 3.0.8 is adopted. Therefore, KPS will reclassify the change as an overall L change (there remains a portion of the change that is more restrictive). A draft markup regarding this change is attached. This change will be reflected in the supplement to this section of the ITS conversion amendment.

Question Closure Date	
Attachment 1	ALK-015 Markup.pdf (845KB)
Attachment 2	ALK-015 KPS IPEEE.pdf (15MB)
Notification	NRC/LICENSEE Supervision Victor Cusumano Jerry Jones Bryan Kays Audrey Klett Ray Schiele Carl Schulten
Added By	Robert Hanley
Date Added	4/29/2010 7:17 AM
Modified By	
Date	

Kewaunee ITS Conversion Database

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 32 of 415

Modified

## Attachment 1, Volume 5, Rev. 0, Page 9 of 63

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 33 of 415



# INSERT 8

- LCO 3.0.8 When one or more required snubbers are unable to perform their associated support function(s), any affected supported LCO(s) are not required to be declared not met solely for this reason if risk is assessed and managed, and:
  - a. the snubbers not able to perform their associated support function(s) are associated with only one train or subsystem of a multiple train or subsystem supported system or are associated with a single train or subsystem supported system and are able to perform their associated support function within 72 hours; or
  - b. the snubbers not able to perform their associated support function(s) are associated with more than one train or subsystem of a multiple train or subsystem supported system and are able to perform their associated support function within 24 hours.

At the end of the specified period the required snubbers must be able to perform their associated support function(s), or the affected supported system LCO(s) shall be declared not met.

Insert Page TS 3.0-1d

Page 5 of 8

Attachment 1, Volume 5, Rev. 0, Page 12 of 63

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 34 of 415

ITS 3.0

## 3.14 SHOCK SUPPRESSORS (SNUBBERS)

## **APPLICABILITY**

Applies to the OPERABILITY of shock suppressors which are related to plant safety.

## **OBJECTIVE**

To ensure that shock suppressors, which are used to restrain safety-related piping under dynamic load conditions, are functional during reactor operation.

## **SPECIFICATION**

- a. The reactor shall not be made critical unless all safety-related shock suppressors are OPERABLE except as noted in 3.14.b.
- b. During power operation or recovery from inadvertent trip, if any safety-related shock suppressor is found inoperable one of the following actions shall be taken within 72 hours:
  - 1. The inoperable shock suppressor shall be restored to an OPERABLE condition or replaced with a spare shock suppressor of similar specifications; or
  - 2. The fluid line restrained by the inoperable shock suppressor shall, if feasible, be isolated from other safety-related systems if otherwise permitted by the TS and thereafter operation may continue subject to any limitations by the TS for that fluid line; or
  - 3. Actions shall be initiated to shut down the reactor and the reactor shall be in a HOT SHUTDOWN condition within 36 hours.



L04

See CTS 3.14

<u>ITS</u>

## Attachment 1, Volume 5, Rev. 0, Page 12 of 63

TS 3.14-1

12/21/95

Amendment No. 122

## Attachment 1, Volume 5, Rev. 0, Page 19 of 63

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 35 of 415 DISCUSSION OF CHANGES ITS 3.0, LCO AND SR APPLICABILITY

This change is designated as administrative as there is no change in the intent of the CTS and no additional flexibility is granted.

### MORE RESTRICTIVE CHANGES

Not used.

CTS 3.14.b provides the action for inoperable snubbers, and requires one of the M01 following (1, 2, or 3) within 72 hours when one or more snubbers are inoperable: 1) replace or restore the inoperable snubber; 2) isolate the fluid line restrained by the inoperable snubber from other safety related systems; or 3) shut down the unit to HOT SHUTDOWN within 36 hours. In the ITS, the actions for inoperable snubbers are incorporated into ITS LCO 3.0.8. When one or more require snubbers are unable to perform their associated support function(s), any affected supported LCO(s) are not required to be declared not met solely for this reason if risk is assessed and managed, and either: a) the snubbers not able to perform their associated support function(s) are associated with only one train or subsystem of a multiple train or subsystem supported system and are able to perform their associated function within 72 hours; or b) the snubbers not able to perform their associated support function(s) are associated with more than one train or subsystem of a multiple train or subsystem supported system and are able to perform their associated support function within 24 hours. At the end of the specified period (i.e., 24 hours or 72 hours) snubbers must be able to perform their associated function(s), or the affected support system LCO(s) shall be declared not met and the associated ACTIONS taken (which may include a unit shutdown). This changes the CTS by requiring the risk associated with inoperable snubbers to be restored to OPERABLE status in all cases, and in certain cases within a more restrictive Completion Time.

The purpose of CTS 3.14.b is to provide a short time (72 hours) prior to requiring the affected systems to be declared inoperable, to either restore or replace inoperable snubbers or to isolate the srubber from the safety related system. ITS LCO 3.0.8 requires the risk associated with inoperable required snubbers to be assessed and managed in all instances of snubber inoperability. ITS LCO 3.0.8 also requires all "required" inoperable snubbers to be restored to OPERABLE status within the specified Completion Times. ITS LCO 3.0.8.a allows 72 hours to restore the snubber(s) before declaring the supported system inoperable, provided only a single subsystem is affected. This 72 hour time is consistent with the CTS. However, ITS LCO 3.0.8.b applies when one or more snubbers are not capable of providing their associated support function(s) to more than one subsystem of a multiple subsystem supported system, and allows 24 hours to restore the snubber(s) before declaring the supported system inoperable. This  $\frac{2}{4}$  hour time is more restrictive than the CTS. The 24 hour Completion Time is acceptable based on the low probability of a seismic event concurrent with an event that would require operation of the supported system occurring while the snubber(s) are not capable of performing their associated support function. Furthermore, ITS LCO 3.0.8 requires that risk be assessed and managed. This risk assessment is not required in the CTS. The Bases for ITS LCO 3.0.8 provides guidance on how the risk must be assessed. Industry and NRC guidance on the implementation of 10 CFR 50.65(a)(4) (the Maintenance Rule) does not address seismic risk. However, use of ITS LCO 3.0.8 should be considered with respect to other plant maintenance activities, and integrated into

Kewaunee Power Station

Page 7 of 13

Attachment 1, Volume 5, Rev. 0, Page 19 of 63

## Attachment 1, Volume 5, Rev. 0, Page 20 of 63

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 36 of 415 DISCUSSION OF CHANGES ITS 3.0, LCO AND SR APPLICABILITY

the existing Maintenance Rule process to the extent possible so that maintenance on any unaffected train or subsystem is properly controlled, and emergent issues are properly addressed. The risk assessment need not be quantified, but may be qualitative awareness of the vulnerability of systems and components when one or more snubbers are not able to perform their associated support function. Furthermore, Kewaunee Power Station has reviewed the additional provisions discussed in the CLIIP's Model Safety Evaluation (in Federal Register Notice 69 FR 68412, November 24, 2004, Section 3.2, and will ensure appropriate plant procedures and administrative controls will be used to implement the applicable Tier 2 Restrictions. Specifically: a) at least one AFW train including a minimum set of supporting equipment required for its successful operation) not associated with the inoperable spubber(s) must be available when LCO 3.0.8.a is used; b) at least one AFW train (including a minimum set of supporting equipment required for its successful operation) not associated with the inoperable snubber(s), or some alternative means of core cooling must be available when LCO 3.0.8.b is used; and c) every time the provisions of LCO 3.0.8 are used, Kewaunee Power Station will confirm that at least one train of systems supported by the inoperable snubbers would remain capable of performing their required safety or support functions for postulated design loads other than seismic loads. In addition, a record of the design function of the inoperable snubber (i.e., seismic vs. non-seismic), implementation of any applicable Tier 2 restriction, and the associated plant configuration shall be available on a recoverable basis for NRC staff inspection. These Tier 2 Restrictions are also more restrictive than what is currently required by the Kewaunee Power Station CTS. This change is designated as more restrictive because inoperable snubbers must be restored to OPERABLE status under certain conditions within a more restrictive Completion Time and the risk associated with inoperable snubber must always be assessed and managed.

M02 CTS 4.0.b states, "Each surveillance requirement shall be performed within the specified surveillance interval with a maximum allowable extension not to exceed 25% of the specified surveillance interval." ITS SR 3.0.2 states "The specified Frequency for each SR is met if the Surveillance is performed within 1.25 times the interval specified in the Frequency, as measured from the previous performance or as measured from the time a specified condition of the frequency is met. For Frequencies specified as "once," the above interval extension does not apply. If a Completion Time requires periodic performance on a "once per ..." basis, the above Frequency extension applies to each performance after the initial performance. Exceptions to this Specification are stated in the individual Specifications." This changes the CTS by adding, "For Frequencies specified as "once," the above interval extension does not apply. The remaining changes to CTS 4.0.b are discussed in DOC A09 and DOC L03.

The purpose of the 1.25 extension allowance to Surveillance Frequencies is to allow for flexibility in scheduling tests. This change is acceptable because Frequencies specified as "once" are typically condition based Surveillances in which the first performance demonstrates the acceptability of the current condition. Such demonstrations should be accomplished within the specified Frequency without extension in order to avoid operation in unacceptable conditions. This change is designated as more restrictive because an allowance to extend Frequencies by 25% is eliminated in some Surveillances.

Kewaunee Power Station

Page 8 of 13

## Attachment 1, Volume 5, Rev. 0, Page 25 of 63

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 37 of 415 DISCUSSION OF CHANGES ITS 3.0, LCO AND SR APPLICABILITY

tripping an inoperable instrument channel. To allow the performance of Surveillance Requirements to demonstrate the OPERABILITY of the equipment being returned to service, or to demonstrate the OPERABILITY of other equipment or variable within limits, which otherwise could not be performed without returning the equipment to service, an exception to these Required Actions is necessary. ITS LCO 3.0.5 documents a formal allowance for accepted industry practices utilized in the restoration of inoperable equipment under CTS. Without this allowance, certain components could not be restored to OPERABLE status and plant shutdown would ensue. Clearly, it is not the intent or desire that the Technical Specifications preclude the return to service of a suspected OPERABLE component to confirm its OPERABILITY. This allowance is deemed to represent a more stable, safe operation than requiring a plant shutdown to complete the restoration and confirmatory testing. This change is designated as less restrictive because LCO 3.0.5 will allow the restoration of equipment to service under administrative controls when it has been removed from service or declared inoperable to comply with ACTIONS.

L03 CTS 4.0.b states, in part, "specific surveillance intervals with a maximum allowable extension not to exceed 25% of the specified interval." ITS SR 3.0.2 includes a similar requirement, but adds the following: "If a Completion Time requires periodic performance on a "once per..." basis, the above Frequency extension applies to each performance after the initial performance." This changes the CTS by adding an allowance that if a Required Action's Completion Time requires periodic performance on a "once per..." basis, the 25% Frequency extension applies to each performance after the initial performance.

This change is acceptable because the 25% Frequency extension given to provide scheduling flexibility for Surveillances is equally applicable to Required Actions that must be performed periodically. The initial performance is excluded because the first performance demonstrates the acceptability of the current condition. Such demonstrations should be accomplished within the specified Completion Time without extension in order to avoid operation in unacceptable conditions. This change is designated as less restrictive because additional time is provided to perform some periodic Required Actions.

INSERT L04

Kewaunee Power Station

Page 13 of 13

Attachment 1, Volume 5, Rev. 0, Page 25 of 63

L04 CTS 3.14.b provides the action for inoperable snubbers, and requires one of the following (1, 2, or 3) within 72 hours when one or more snubbers are inoperable: 1) replace or restore the inoperable snubber; 2) isolate the fluid line restrained by the inoperable snubber from other safety related systems; or 3) initiate action to shut down the unit to HOT SHUTDOWN within 36 hours. In the ITS, the actions for inoperable snubbers are incorporated into ITS LCO 3.0.8. When one or more required snubbers are unable to perform their associated support function(s), any affected supported LCO(s) are not required to be declared not met solely for this reason if risk is assessed and managed, and either: a) the snubbers not able to perform their associated support function(s) are associated with only one train or subsystem of a multiple train or subsystem supported system and are able to perform their associated function within 72 hours; or b) the snubbers not able to perform their associated support function(s) are associated with more than one train or subsystem of a multiple train or subsystem supported system and are able to perform their associated support function within 24 hours. At the end of the specified period (i.e., 24 hours or 72 hours) snubbers must be able to perform their associated function(s), or the affected support system LCO(s) shall be declared not met and the associated ACTIONS taken (which may include a unit shutdown). This changes the CTS by: a) requiring the risk associated with inoperable snubbers to be assessed and managed; b) allowing the associated safety related system to be declared inoperable yet remain unisolated, in lieu of requiring it to be isolated to use this option; c) deleting the option to shutdown the unit; and d) decreasing the amount of time allowed to perform one of the options if snubbers in both trains of a safety related system are affected.

The purpose of CTS 3.14.b is to provide a short time (72 hours) to either restore or replace inoperable snubbers prior to requiring the affected safety related system to be isolated from the inoperable and the affected safety realted system to be declared inoperable. If the safety related system cannot be isolated from the snubber, then the CTS requires the unit to be shutdown. ITS LCO 3.0.8 requires the risk associated with nonfunctional required snubbers to be assessed and managed in all instances of snubber nonfunctionality. ITS LCO 3.0.8 also requires all "required" nonfunctional snubbers to be restored to functional status within the specified Completion Times. ITS LCO 3.0.8.a allows 72 hours to restore the snubber(s) before declaring the supported system inoperable, provided only a single subsystem is affected. Furthermore, the ITS does not require the supported system to be isolated from the snubber. This 72 hour time is consistent with the CTS. However, ITS LCO 3.0.8.b applies when one or more snubbers are not capable of providing their associated support function(s) to more than one subsystem of a multiple subsystem supported system, and allows 24 hours to restore the snubber(s) before declaring the supported system inoperable. Again, the ITS does not require the supported system to be isolated from the snubber. This 24 hour time is more restrictive than the CTS. The 24 hour Completion Time is acceptable based on the low probability of a seismic event concurrent with an event that would require operation of the supported system occurring while the snubber(s) are not capable of performing their associated support function. Furthermore, ITS LCO 3.0.8 requires that risk be assessed and managed. This risk assessment is not required in the CTS. The Bases for ITS LCO 3.0.8 provides guidance on how the risk must be assessed. Industry and NRC guidance on the implementation of 10 CFR 50.65(a)(4) (the Maintenance Rule) does not address seismic risk. However, use of ITS LCO 3.0.8 should be considered with respect to other plant maintenance activities, and integrated into the existing Maintenance Rule process to the extent possible so that maintenance on any unaffected train or subsystem is properly controlled, and emergent issues are

properly addressed. The risk assessment need not be quantified, but may be qualitative awareness of the vulnerability of systems and components when one or more snubbers are not able to perform their associated support function. Furthermore, Kewaunee Power Station has reviewed the additional provisions discussed in the CLIIP's Model Safety Evaluation (in Federal Register Notice 69 FR 68412, November 24, 2004), Section 3.2, and will ensure appropriate plant procedures and administrative controls will be used to implement the applicable Tier 2 Restrictions. Specifically: a) at least one AFW train including a minimum set of supporting equipment required for its successful operation) not associated with the nonfunctional snubber(s) must be available when LCO 3.0.8.a is used; b) at least one AFW train (including a minimum set of supporting equipment required for its successful operation) not associated with the nonfunctional snubber(s), or some alternative means of core cooling must be available when LCO 3.0.8.b is used; and c) every time the provisions of LCO 3.0.8 are used, Kewaunee Power Station will confirm that at least one train of systems supported by the nonfunctional snubbers would remain capable of performing their required safety or support functions for postulated design loads other than seismic loads. In addition, a record of the design function of the nonfunctional snubber (i.e., seismic vs. non-seismic), implementation of any applicable Tier 2 restriction, and the associated plant configuration shall be available on a recoverable basis for NRC staff inspection. These Tier 2 Restrictions are also more restrictive than what is currently required by the Kewaunee Power Station CTS.

The deletion of the requirement to isolate the affected system is acceptable since it will allow the system to remain in service during the time the affected train is declared inoperable and the ACTION for the inoperable train is being taken. Thus, if an accident occurs in which the train is needed, it will function as assumed. This portion of the change could be considered as less restrictive, since the system is now not required to be isolated in order to use the CTS option to declare the train inoperable, in lieu of using the CTS shutdown option. Therefore, the change is designated overall as less restrictive. The remaining portions of this overall change are more restrictive because nonfunctional snubbers must be restored to functional status under certain conditions within a more restrictive Completion Time (24 hours versus 72 hours) and the risk associated with nonfunctional snubbers must always be assessed and managed.

## Attachment 1, Volume 5, Rev. 0, Page 63 of 63

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 40 of 415 DETERMINATION OF NO SIGNIFICANT HAZARDS CONSIDERATIONS ITS 3.0, LCO AND SR APPLICABILITY

Response: No.

The proposed change allows the Completion Time for periodic actions to be extended by 25 percent. This change will not physically alter the plant (no new or different type of equipment will be installed). Also, the change does not involve any new or revised operator actions. Therefore, the proposed change does not create the possibility of a new or different kind of accident from any previously evaluated.

# 3. Does the proposed change involve a significant reduction in a margin of safety?

Response: No.

The proposed change allows the Completion Time for periodic actions to be extended by 25 percent. The 25 percent extension allowance is provided for scheduling convenience and is not expected to have a significant effect on the average time between Required Actions. As a result, the Required Actions will continue to provide appropriate compensatory measures for the subject Condition. Therefore, the proposed change does not involve a significant reduction in a margin of safety.

Based on the above, it is concluded that the proposed change presents no significant hazards consideration under the standards set forth in 10 CFR 50.92(c), and, accordingly, there is a finding of "no significant hazards consideration."

INSERT NSHC L04

#### 10 CFR 50.92 EVALUATION FOR LESS RESTRICTIVE CHANGE L04

Kewaunee Power Station (KPS) is converting to the Improved Technical Specifications (ITS) as outlined in NUREG-1431, Rev. 3, "Standard Technical Specifications, Westinghouse Plants." The proposed change involves making the Current Technical Specifications (CTS) less restrictive. Below is the description of this less restrictive change and the determination of No Significant Hazards Considerations for conversion to NUREG-1431.

CTS 3.14.b provides the action for inoperable snubbers, and requires one of the following (1, 2, or 3) within 72 hours when one or more snubbers are inoperable: 1) replace or restore the inoperable snubber; 2) isolate the fluid line restrained by the inoperable snubber from other safety related systems; or 3) initiate action to shut down the unit to HOT SHUTDOWN within 36 hours. In the ITS, the actions for inoperable snubbers are incorporated into ITS LCO 3.0.8. When one or more required snubbers are unable to perform their associated support function(s), any affected supported LCO(s) are not required to be declared not met solely for this reason if risk is assessed and managed, and either: a) the snubbers not able to perform their associated support function(s) are associated with only one train or subsystem of a multiple train or subsystem supported system and are able to perform their associated function within 72 hours; or b) the snubbers not able to perform their associated support function(s) are associated with more than one train or subsystem of a multiple train or subsystem supported system and are able to perform their associated support function within 24 hours. At the end of the specified period (i.e., 24 hours or 72 hours) snubbers must be able to perform their associated function(s), or the affected support system LCO(s) shall be declared not met and the associated ACTIONS taken (which may include a unit shutdown). This changes the CTS by: a) requiring the risk associated with inoperable snubbers to be assessed and managed; b) allowing the associated safety related system to be declared inoperable yet remain unisolated, in lieu of requiring it to be isolated to use this option; c) deleting the option to shutdown the unit; and d) decreasing the amount of time allowed to perform one of the options if snubbers in both trains of a safety related system are affected.

The purpose of CTS 3.14.b is to provide a short time (72 hours) to either restore or replace inoperable snubbers prior to requiring the affected safety related system to be isolated from the inoperable and the affected safety realted system to be declared inoperable. If the safety related system cannot be isolated from the snubber, then the CTS requires the unit to be shutdown. ITS LCO 3.0.8 requires the risk associated with nonfunctional required snubbers to be assessed and managed in all instances of snubber nonfunctionality. ITS LCO 3.0.8 also requires all "required" nonfunctional snubbers to be restored to functional status within the specified Completion Times. ITS LCO 3.0.8.a allows 72 hours to restore the snubber(s) before declaring the supported system inoperable, provided only a single subsystem is affected. Furthermore, the ITS does not require the supported system to be isolated from the snubber. This 72 hour time is consistent with the CTS. However, ITS LCO 3.0.8.b applies when one or more snubbers are not capable of providing their associated support function(s) to more than one subsystem of a multiple subsystem supported system, and allows 24 hours to restore the snubber(s) before declaring the supported system inoperable. Again, the ITS does not require the supported system to be isolated from the snubber. This 24 hour

time is more restrictive than the CTS. The 24 hour Completion Time is acceptable based on the low probability of a seismic event concurrent with an event that would require operation of the supported system occurring while the snubber(s) are not capable of performing their associated support function. Furthermore, ITS LCO 3.0.8 requires that risk be assessed and managed. This risk assessment is not required in the CTS. The Bases for ITS LCO 3.0.8 provides guidance on how the risk must be assessed. Industry and NRC guidance on the implementation of 10 CFR 50.65(a)(4) (the Maintenance Rule) does not address seismic risk. However, use of ITS LCO 3.0.8 should be considered with respect to other plant maintenance activities, and integrated into the existing Maintenance Rule process to the extent possible so that maintenance on any unaffected train or subsystem is properly controlled, and emergent issues are properly addressed. The risk assessment need not be quantified, but may be qualitative awareness of the vulnerability of systems and components when one or more snubbers are not able to perform their associated support function. Furthermore, Kewaunee Power Station has reviewed the additional provisions discussed in the CLIIP's Model Safety Evaluation (in Federal Register Notice 69 FR 68412, November 24, 2004), Section 3.2, and will ensure appropriate plant procedures and administrative controls will be used to implement the applicable Tier 2 Restrictions. Specifically: a) at least one AFW train including a minimum set of supporting equipment required for its successful operation) not associated with the nonfunctional snubber(s) must be available when LCO 3.0.8.a is used; b) at least one AFW train (including a minimum set of supporting equipment required for its successful operation) not associated with the nonfunctional snubber(s), or some alternative means of core cooling must be available when LCO 3.0.8.b is used; and c) every time the provisions of LCO 3.0.8 are used. Kewaunee Power Station will confirm that at least one train of systems supported by the nonfunctional snubbers would remain capable of performing their required safety or support functions for postulated design loads other than seismic loads. In addition, a record of the design function of the nonfunctional snubber (i.e., seismic vs. non-seismic), implementation of any applicable Tier 2 restriction, and the associated plant configuration shall be available on a recoverable basis for NRC staff inspection. These Tier 2 Restrictions are also more restrictive than what is currently required by the Kewaunee Power Station CTS.

The deletion of the requirement to isolate the affected system is acceptable since it will allow the system to remain in service during the time the affected train is declared inoperable and the ACTION for the inoperable train is being taken. Thus, if an accident occurs in which the train is needed, it will function as assumed. This portion of the change could be considered as less restrictive, since the system is now not required to be isolated in order to use the CTS option to declare the train inoperable, in lieu of using the CTS shutdown option. Therefore, the change is designated overall as less restrictive. The remaining portions of this overall change are more restrictive because nonfunctional snubbers must be restored to functional status under certain conditions within a more restrictive Completion Time (24 hours versus 72 hours) and the risk associated with nonfunctional snubbers must always be assessed and managed.

An evaluation has been performed to determine whether or not a significant hazards consideration is involved with these proposed Technical Specification changes by focusing on the three standards set forth in 10 CFR 50.92, "Issuance of amendment," as discussed below:

# 1. Does the proposed change involve a significant increase in the probability or consequences of an accident previously evaluated?

Response: No.

The proposed change allows the affected train to be unisolated during the time provided to restore the affected train. Furthermore, this change decreases the amount of time allowed to restore an inoperable snubber. Not isolating the affected system or reducing the time allowed to restore a snubber is not an initiator of any accident previously evaluated. Consequenctly, the probability of an accident previously evaluated is not significantly increased. The consequences of any accident previously evaluated are the same during the Completion Time or during any reduction of the Completion Time. As a result, the consequences of any accident previously evaluated are not significantly increased. Therefore, the proposed change does not involve a significant increase in the probability or consequences of an accident previously evaluated.

# 2. Does the proposed change create the possibility of a new or different kind of accident from any accident previously evaluated?

Response: No.

The proposed change allows the affected train to be unisolated during the time provided to restore the affected train. Furthermore, this change decreases the amount of time allowed to restore an inoperable snubber. The proposed change does not involve a physical alteration of the plant (no new or different type of equipment will be installed) or a change in the methods governing normal plant operation. While the affected system is not required to be isolated from the inoperable snubber, normal plant operations are not affected. Thus, this change does not create the possibility of a new or different kind of accident from any accident previously evaluated.

# 3. Does the proposed change involve a significant reduction in a margin of safety?

Response: No.

The proposed change allows the affected train to be unisolated during the time provided to restore the affected train. Furthermore, this change decreases the amount of time allowed to restore an inoperable snubber. Maintaining the affected system unisolated during the system restoration time will allow the system to function as designed if an accident were to occur during this short restoration time. If the system were isolated, it would not be able to function. Furthermore, less time is now provided to restore the snubber if it affects both trains of a safety related system. Therefore, the proposed change does not involve a significant reduction in a margin of safety.

Based on the above, it is concluded that the proposed change presents no significant hazards consideration under the standards set forth in 10 CFR 50.92(c), and, accordingly, there is a finding of "no significant hazards consideration."

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 45 of 415

WPSC (414) 433-1599 TELECOPIER (414) 433-5544



ويتبر والمروا والمروا والحشار

NRC-94-079

WISCONSIN PUBLIC SERVICE CORPORATION

• Note A table ● FIC Bis 1902 ● Nate Bay A 5430 (900)

June 28, 1994

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555


Ladies/Gentlemen:

Docket 50-305 Operating License DPR-43 Kewaunee Nuclear Power Plant Response to Generic Letter 88-20, Supplement 4, Individual Plant Examination for External Events

- References: 1)
- ) Generic Letter 88-20, Supplement 4, "Individual Plant Examination of External Events" (IPEEE) For Severe Accident Vulnerabilities -10CFR50.54(f), dated June 28, 1991
  - 2) Letter from C. R. Steinhardt (WPSC) to NRC Document Control Desk, dated December 20, 1991
  - 3) Letter from C. R. Steinhardt (WPSC) to NRC Document Control Desk, dated September 18, 1992

Generic Letter 88-20, Supplement 4 (reference 1), requested that all licensees perform Individual Plant Examinations of External Events (IPEEE). Wisconsin Public Service Corporation (WPSC) submitted the response to Generic Letter 88-20, Supplement 4 for the Kewaunee Nuclear Power Plant in letters dated December 20, 1991, and September 18, 1992 (references 2 and 3). In reference 3, WPSC stated that the final results of the IPEEE for the Kewaunee Nuclear Power Plant would be submitted to the NRC by June 28, 1994. The enclosure with this letter provides the IPEEE submittal for Kewaunee.

The WPSC IPEEE submittal follows the format recommended in NUREG-1407, "Procedural and Submittal Guidance for the Individual Plant Examination of External Events (IPEEE) for Severe Accident Vulnerabilities." The report describes plant improvements already implemented, in the process of being implemented, or being considered as a result of the



Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 46 of 415

Document Control Desk June 28, 1994 Page 2

Kewaunee IPEEE project. This submittal completes WPSC's response to Generic Letter 88-20, Supplement 4, for the IPEEE. If there are any questions regarding this report, please contact a member of my staff.

Sincerely,

C.a. Schock for

C. R. Steinhardt Senior Vice President - Nuclear Power

FBS/cjt

Attach.

cc - US NRC Region III US NRC Senior Resident Inspector

Subscribed and Sworn to Before Mc This <u>234</u><sup>H</sup> Day

of funce 1994 PIMO J'Anna

Motary Public, State of Wisconsin

My Commission Expires:

LIC\NRC\20 WP

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 47 of 415

## ATTACHMENT 1

Letter From C. R. Steinhardt (WPSC)

То

Document Control Desk (NRC)

Laicu

June 28, 1994

•7

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 48 of 415

## **KEWAUNEE NUCLEAR POWER PLANT**

## INDIVIDUAL PLANT EXAMINATION OF EXTERNAL EVENTS SUMMARY REPORT

June 28, 1994

WISCONSIN PUBLIC SERVICE CORPORATION

1. S. 1. A. A. A. A.

9407010219 940628 PDR ADOCK 05000305 P PDR

# INDIVIDUAL PLANT EXAMINATION OF EXTERNAL EVENTS SUMMARY REPORT

# TABLE OF CONTENTS

# **SECTION**

## PAGE

1. Executive Summary	
1,1 Background and Objectives	1 - 1
1.2 Plant Familiarization	1-2
1.3 Overall Methodology	1-5
1.4 Summary of Major Findings	1-6
2. Examination Description	21
2.1 Introduction	
2.2 Conformance With Generic Letter and Supporting Material	
2.3 General Methodology	
2.4 Information Assembly	
3. Seismic Analysis	3-1
3.0 Methodology Selection	
3.1 Seismic PRA	
3.1.3 Analysis of Plant Systems and Structure Response	
3.1.4 Evaluation of Component Fragilities and Failure Modes	
3.1.5 Analysis of Plant Systems and Sequences	
3.1.6 Analysis of Containment Performance	
3.2 USI A-45, GI-131, and Other Seismic Safety Issues	
3.3 References	
<b>3.5 RUERING</b>	· ( • ~
4. Fire Hazards Analysis	4-1
4.0 Methodology Selection	
4.1 Fire Hazards Analysis	
4.1.1 Definitions and Assumptions	
4.1.2 Containment Fires	
4.1.3 Evaluation of Fire-Induced Initiating Events	
4.1.4 Screening Analysis	
4.1.5 Results of Screening	
4.2 Review of Plant Information and Walkdown	
4.3 Fire Growth and Propagation	
4.3.1 COMPBRN Runs	
4.4 Evaluation of Component Fragilities and Failure Modes	
4.5 Fire Detection and Suppression	
4.5.1 Automatic and Manual Fire Detection and Suppression 4	
$\pi_{0,2}$ , $\pi_{0,1}$ ,	÷.,

# INDIVIDUAL PLANT EXAMINATION OF EXTERNAL EVENTS SUMMARY REPORT

# TABLE OF CONTENTS (Cont'd)

# **SECTION**

# <u>PAGE</u>

4.6 Analysis of Plant Systems, Sequences, and Plant Responses	4-38
4.6.1 Identification of Components Affected by Fire	4-38
4.6.2 Determination of Initiating Event Frequency in Each Zone	
Requiring Quantification	4-38
4.6.3 Fire-Induced Core Damage Frequency Quantification	4-38
4.6.4 Dominant Fire-Induced Core Damage Sequences	4-41
4.7 Fire-Induced Containment Failures	
4.7.1 Containment Failure Frequency Quantification Procedure	4-44
4.7.2 Quantification Results	
4.8 Treatment of Fire Risk Scoping Study Issues	4-44
4.8.1 Dependency Between Control Room and Remote Shutdown	
Panel Circuitry	4-44
4.8.2 Cable Routing Verification	4-44
4.8.3 Suppression Agent Induced Damage	4-44
4.8.4 Fire Brigade Effectiveness	1-12
4.8.5 Seismic-Fire Interactions	4-45
4.8.6 Use of Plant Specific Data	
4.8.7 Consideration of Uncertainties	4-46
4.9 USI A-45 and ( ther Safety Issues	
4.10 Areas of Conservatism	4-50
4.11 Summary of Key Findings	4-51
4.12 References	4-52
5. Other External Events Analysis	. 5-1
5.0 High Winds, Floods, and Others	. 5-7
5.0.1 Introduction	. 5-7
5.0.2 General Methodology	. 5-7
5.0.3 Methodologies for Specific Events	5-11
5.0.4 Determination of Need to Analyze Additional Events	5 14
5.1 High Winds and Tornadoes	5 19
5.1.1 Severe Wind Source Screening	5-19
5.1.2 Screening Summary	5-14
5.1.3 Analysis	5-14
5.1.4 Results, Recommendations, and Conclusions	5-23

# INDIVIDUAL PLANT EXAMINATION OF EXTERNAL EVENTS SUMMARY RFPORT

# TABLE OF CONTENTS (Cont'd)

# **SECTION**

## PAGE

5.2 External Floods
5.2.1 External Flooding Source Screening
5.2.2 Screening Summary 5-24
5.2.3 Analysis
5.2.4 Results, Recommendations, and Conclusions
5.3 Transportation and Nearby Facility Accidents
5.3.1 Transportation and Nearby Facility Accidents Source Screening
5.3.2 Screening Summary
5.3.3 Analysis
5.3.4 Results, Recommendations and Conclusions
5.4 Hazardous Materials
<b>5.5 References</b>
6. Licensee Participation and Internal Review Team
6.1 IPEEE Program Organization 6-3
6.2 Composition of Independent Review Team
6.3 Areas of Review and Major Comments
6.4 Resolution of Comments
7. Plant Improvements and Unique Safety Features
7.1 Level 1 Unique Safety Features
7.2 Level 2 Unique Safety Features
7.3 Plant Improvements
8. Summary and Conclusions

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 52 of 415

## 1. Executive Summary

In November 1988, the U.S. Nuclear Regulatory Commission (NRC) staff issued Generic Letter 88-20, "Individual Plant Examination for Severe Accident Vulnerabilities - 10CFR50.54(f)," which established a formal request for utilities to perform an Individual Plant Examination (IPE). In addition to the performance of the IPE, this letter requested utilities to identify potential improvements to address the important contributors to plant risk and implement improvements that they believed were appropriate for their plant.

In June 1991, the NRC issued Supplement 4 to Generic Letter 88-20, "Individual Plant Examination of External Events (IPEEE) for Severe Accident Vulnerabilities - 10CFR50.54(f)," which was accompanied by NUREG-1407, "Procedural and Submittal Guidance for the Individual Plant Examination of External Events (IPEEE) for Severe Accident Vulnerabilities," which provided guidance for the information to be submitted to the NRC.

This report provides the requested information for the Kewaunee Nuclear Power Plant regarding external events, excluding internal flooding. The internal flooding analysis was included in the Kewaunee IPE.

### 1.1 Background and Objectives

In its Severe Accident Policy Statement (50FR43621), issued in 1985, the NRC concluded that operating nuclear plants pose no undue risk to the public health and safety and that there is no present basis for immediate action on any regulatory requirements for these plants. However, the Commission recognized, based on NRC and industry experience with plant-specific probabilistic risk assessments (PRAs), that systematic examinations are beneficial in identifying plant-specific vulnerabilities to severe accidents that could be removed with low-cost improvements. As a result, the Commission issued Generic Letter 88-20 in 1988, requesting that each licensee conduct an IPE for internally initiated events, including internal flooding.

In December 1987, an External Events Steering Group (EESG) was established by the NRC to make recommendations regarding the scope, methods and coordination of the IPEEE. Ultimately, Supplement 4 to Generic Letter 88-20 was issued regarding external events.

The objectives of the IPEEE, as outlined in NUREG-1407, are:

- 1. To satisfy the requirements of GL 88-20, Supplement 4.
- 2. To develop an appreciation of severe accident behavior.
- 3. To understand the most likely severe accident sequences that could occur under full power operating conditions.
- 4. To gain a qualitative understanding of the overall likelihood of core damage and fission product releases.

5. To identify potential improvements in the plant design and/or operation that will reduce the overall core damage frequency and/or the containment failure frequency.

Wisconsin Public Service Corporation (WPSC) has completed and documented the IPEEE for Kewaunee, which meets these objectives. This report, containing a summary of the methods, results, and conclusions, provides our response to the NRC request for information contained in Generic Letter 88-20, Supplement 4. In addition, the IPEEE was conducted according to the applicable sections of 10CFR50, Appendix B, "Quality Assurance Criteria for Nuclear Power Plants and Fuel Reprocessing Plants." WPSC has retained all supporting analyses, descriptions and files pertaining to the IPEEE. These are available at WPSC offices for NRC review as necessary.

## 1.2 Plant Familiarization

The WPSC IPEEE program for Kewaunee involved an extensive plant familiarization effort because the undertaking of a full-scope realistic IPEEE requires careful analysis of the as-built, as-operated plant. To the extent possible, information gained during the internal events IPE for Kewaunee is used for the IPEEE. Nevertheless, additional walkdowns of the plant were performed and documented for the seismic, fire and other external events analyses.

The Kewaunee Nuclear Power Plant is a 2-loop pressurized water reactor licensed at 1650 MW (thermal). It is located in Kewaunee County, Wisconsin, along Lake Michigan's western shoreline and is jointly owned by WPSC, Wisconsin Power and Light Company, and Madison Gas and Electric Company. Kewaunee is the only nuclear power plant operated by WPSC. The nuclear steam supply system was supplied by Westinghouse Electric Corporation as was the turbine-generator, which is rated at 535 MW (net electrical). The architect/engineer was Pioneer Service and Engineering. The operating license was granted on December 21, 1973. Initial criticality was achieved on March 7, 1974. Initial power generation was reached April 8, 1974. and the plant was declared commercial on June 16, 1974. As of May 31, 1994, Kewaunee has operated with an availability factor of 84.4%.

The following is a summary of some of the important design features at the Kewaunee plant.

- 1. High Pressure Injection
  - Two centrifugal safety injection (SI) pumps deliver flow if Reactor Coolant System (RCS) Pressure is less than 2200 psig.
  - Two SI accumulators each contain 1250 ft<sup>3</sup> of borated water and are ready to inject if reactor coolant system (RCS) pressure is less than 700 psig.
  - SI pumps require support from the component cooling water and service water systems.

- 2. Low Pressure Injection
  - Two residual heat removal (RHR) pumps deliver approximately 2000 gpm each when the RCS is depressurized.
  - RHR heat exchangers downstream of each pump provide recirculation heat removal.
  - Recirculation mode takes suction from containment sump B and discharges to the RCS, SI pump suction, and/or containment spray pump suction.
  - RHR pumps and heat exchangers require support from the component cooling water system.
  - RHR pump fan coil units are supplied by service water.
- 3. Auxiliary Feedwater
  - Two motor-driven and one turbine-driven auxiliary feedwater (AFW) pumps supply cooling water to the steam generators in the event of a loss of main feedwater. Each pump and associated lube oil is cooled by the fluid being pumped.
  - Pumps take suction through a single supply header from the condensate storage tanks.
  - An alternate supply of water to the AFW pumps is provided by the Service Water (SW) System. AFW pump A is supplied by service water train A. AFW pump B is supplied by service water train B. The turbine driven AFW pump can be supplied by either service water train. Each pump is equipped with a low discharge pressure trip, so that if its normal source, the condensate storage tank, is lost, the pump is not damaged but immediately trips.
- 4. Emergency Power System
  - Two 4160VAC buses feed two 480VAC buses each.
  - Two diesel generators provide power to the 4160VAC buses should off-site power become unavailable.
  - DC power is provided by four 8 hour station batteries and four battery chargers (2 vital and 2 non-vital).
  - Vital instrument power is provided to four instrument buses from the 480VAC buses by way of 480VAC/120VAC instrument bus transformers, or from the vital DC system by way of four instrument bus inverters.

- 5. Component Cooling
  - Consists of two pumps, two heat exchangers and one surge tank.
  - Cools reactor coolant pumps (RXCPs), RHR pumps, and SI pumps.
  - Component cooling heat exchangers are cooled by service water.
- 6. Service Water
  - Consists of two normally cross-connected headers with two pumps in each header. These two headers are isolated from each other by a SI signal and thereby made separate and independent.
  - Cools component cooling heat exchangers, containment fan coil units, SI pump lube oil heat exchanger and stuffing box, diesel generator coolers, and safeguard fan coil units, and provides the emergency water supply to the AFW pumps.
- 7. Containment
  - Containment is of the Westinghouse large dry type.
  - Primary containment consists of a low leakage steel vessel.
  - Secondary containment consists of a medium leakage concrete shield building surrounding the primary containment vessel.
  - Containment vessel free volume is 1.32x10<sup>6</sup> cubic feet.
  - The containment vessel design pressure is 46 psig and design temperature is 268°F.
- 8. Containment Spray
  - Two independent spray headers with one pump in each header deliver 1300 gpm each.
  - Water is supplied by the refueling water storage tank (RWST) and the sodium hydroxide tank initially. When the RWST is depleted recirculated fluid can be supplied to internal containment spray (ICS) pump suction from the RHR pumps.
- 9. Containment Fan Coil Units
  - Four containment fan coil units, two supplied by each service water header, cool the containment during normal and accident conditions.
  - Service water is supplied at maximum flow during accident conditions.

- 10. Chemical and Volume Control
  - Three positive displacement/air cooled charging pumps provide 60.5 gpm each for RCS makeup and RXCP seal injection.
  - One of the three charging pumps is provided with a variable DC drive for speed control and is therefore not dependent on instrument air for attaining maximum pump output.
  - Two boric acid transfer pumps provide the capability of supplying concentrated boric acid to the suction of the charging pumps for reactivity control.

## 1.3 Overall Methodology

In the IPEEE, standard systems analysis and external event assessment practices as outlined in NUREG-1407 are used. Seismic, internal fires and other external events (e.g., high winds, floods, etc.) are analyzed in the IPEEE using the following methodologies:

Seismic: The seismic IPEEE is a Level 1 effort with a qualitative and quantitative containment performance analyses. A seismic PRA (SPRA) approach using guidance described in NUREG/CR-4840, "Procedures for the External Event Core Damage Frequency Analysis for NUREG-1150" is used for Kewaunee. Both Electric Power Research Institute (EPRI) seismic hazard curves and hazard curves developed by the Lawrence Livermore National Laboratory (LLNL) are used in the analysis. The seismic accident event trees and plant system models are taken from the internal events IPE and modified as necessary for seismic events. The Westinghouse WLINK computer code is used for fault tree quantification. The J. R. Benjamin SHIP computer code is used to perform the core melt quantification and the plant damage state quantification. The plant damage state quantification serves as a link between the Level 1 SPRA and the containment performance analysis.

Internal Fires: The internal fires analysis of the IPEEE is performed for Kewaunee using a Level 1 PRA and a qualitative and quantitative containment performance evaluation. A screening study based on the plant walkdowns and the EPRI Fire-induced Vulnerability Examination (FIVE) Methodology is used to screen out the less important fire area, while a full PRA is performed for the remaining areas. This analysis is a new fire PRA and follows the guidance identified in NUREG-1407. The deficiencies of past fire PRAs identified in NUREG/CR-5088 "Fire Risk Scoping Study" are addressed in the Kewaunee Fire PRA. The Westinghouse WLINK code is used for fault tree and core melt quantification.

Other External Events: The other external events analysis of the IPEEE use a screening approach that meets the intent of that described in NUREG-1407.

Sensitivity studies were performed on the model to determine the variability in the core damage frequency as influenced by such factors as changes in the cutoffs, operator actions, rando: failures, etc. Importance analyses were performed to identify the important accident sequences, system failures, component failures, and operator errors that contribute to the core damage

frequency. Detailed notebooks were developed for each section of the Kewaunee IPEEE to provide documentation of the decisions and assumptions that served as input to the models and calculations.

One of the important steps in the Kewaunee IPEEE project was the reviews performed by the WPSC PRA staff, independent WPSC reviewers, and independent external reviewers. The PRA group members thoroughly reviewed the results of every iteration of the core melt quantification using their operations background to identify invalid cutsets. The models were reviewed to identify the problem or problems that caused the invalid cutset, and then the problems were corrected. An independent group of experienced Kewaunee plant staff members performed an extensive review of the different sections of the Kewaunee IPEEE, and identified numerous improvements that were then incorporated into the IPEEE.

### 1.4 Summary of Major Findings

This section summarizes the major findings of the Kewaunee IPEEE. First, the results of the core damage frequency quantification for each initiator are presented. Second, the dominant contributors leading to core damage for significant initiating events are described. Detailed discussion of these events can be found in their respective sections of this report.

The Kewaunee IPEEE does not deviate from the plant abnormal and emergency procedures. Therefore, there are no accident management actions modeled. By not taking credit for these actions, the results provided in this report are higher than they would  $b_{\rm ev}$  d credit been taken. The overall core damage frequency (CDF) for the Kewaunee Plant, considering both internal and external events is calculated to be 2.0E-04/year. This reflects the conservative approach taken by WPSC. Figure 1-1 provides a summary of the contribution to the overall core damage frequency due to external events other than fire and seismic events is at the screening value (1.0E-06/year). Figure 1-2 shows the Level 2 overall results by release categories. These release categories are defined in Table 1-1. The internal events portion of these figures represents not the IPE as submitted, but the present state of the Kewaunee internal events PRA which includes some revisions.

### Seismic

### Seismic Core Damage

In general, no significant seismic concerns were discovered in the SPRA. The CDF based upon the EPRI seismic hazard curve is 1.10E-05/year, whereas core damage frequency based upon the 1993 LLNL seismic hazard curve is 1.15E-05/year. Rankings of the dominant contributors to seismic CDF remain the same regardless of which seismic hazard curve is used. The following are the dominant basic events/component failures that contribute to seismic risk:

- Loss of off-site power,
- Surrogate component in the following systems: Containment or Steam Generator failure, Reactor Vessel or Building failures, SW, DC Power, and AC Power,
- Operator Error failure to shift AFW pumps from the condensate storage tanks (CST) to service water.

Kewaunee Seismic Core Damage Frequency Results - Approximately 93 percent of the CDF is determined by 6 accident sequences. A discussion of the dominant sequences is provided below.

Sequence SCSF - This sequence corresponds to failure of the containment structure or the SG. Failure of either of these components leads directly to core damage. These structures were screened using the first column in EPRI NP-6041, which corresponds approximately to a PGA HCLPF level of 0.30g. As a result, these structures are modeled by the surrogate component. The seismic CDF associated with this sequence is 3.6E-06 per year. This is conservative, since the surrogate component is a conservative representation of the capacity of components at the Kewaunee plant.

Sequence SSWS - This sequence corresponds to failure of the SW System. Failure of the SW System is dominated by failure of the intake structure, which is modeled using the surrogate component. The intake structure was screened based on a HCLPF level of 0.30g. All other components in the SW System have median capacities of 0.66g PGA or greater. The seismic risk associated with failure of the SW System is 1.99E-06 per year which is conservative, since the capacity of the SW System is dominated by the surrogate component.

Sequence SRVB - This sequence corresponds to failure of the screenhouse, the auxiliary building, turbine building or the reactor vessel. Failure of any of these components is assumed to lead directly to core damage. These structures were screened using the middle column in EPRI NP-6041, which corresponds approximately to a PGA HCLPF level of 0.30g.

As a result, these structures are modeled by the surrogate component. The seismic risk associated with this sequence is 1.74E-06 per year. This is conservative since the surrogate component is a conservative representation of the capacity of the struct res at the Kewaunee plant.

Sequence SLSP01 - This sequence corresponds to the loss of off-site power and failure of the AFW System. Failure of the AFW System is attributed to failure of the operator to shift AFW pumps from the CST to SW and failure of the surrogate element. The seismic risk associated with this sequence is 1.35E-06 per year.

Sequence SACP - This sequence corresponds to failure of emergency AC power system, including the diesel generators, and supporting mechanical and electrical equipment. All components in the AC power system have median capacities of 1.86g PGA or greater. As a

result, failure of AC power is dominated by failure of the surrogate component. The seismic risk associated with failure of the AC power system is 1.26E-06 per year. This is conservative, since the system capacity is dominated by the surrogate element.

Sequence SDCP - This sequence corresponds to failure of DC power system, including failure of the station batteries, battery chargers, cable trays and electrical support equipment. All components in the DC power system have median capacities of 1.10g PGA or greater. As a result, failure of DC power is dominated by failure of the surrogate component. The seismic risk associated with failure of the DC power system is 3.48E-07 per year. This is conservative, since the system capacity is dominated by the surrogate element.

In the Kewaunee SPRA, small, medium and large LOCA events are modeled. As part of the Kewaunee SPRA, reactor vessel failure and seismically initiated small, medium and large LOCA events are considered. The frequency of these events is:

Size	Frequency
1.5 - 3"	2.23E-07/Yr
3 - 6"	7.68E-09/Yr
> 6"	1.77E-07/Yr
Failure	1.74E-06/Yr
	1.5 - 3" 3 - 6"

Contribution of Ground Motions to Plant Risk - Approximately 76 percent of the CDF is contributed by PGA values in the range 0.25g to 0.65g.

## Summary

This section summarizes the results of the Kewaunee SPRA. The seismic CDF is 1.10E-05 which is considerably less than the internal events CDF (8.73E-05). The median capacity of the plant is 0.38g peak ground acceleration (PGA), which is greater than a factor three times that of the safe shutdown earthquake (SSE). The high confidence of a low probability of failure (HCLPF) acceleration for Kewaunee is 0.26g PGA or approximately two times the SSE. The HCLPF is based on an evaluation of seismic systems model for seismic failures only.

Based on sensitivity evaluations and a review of the SPRA results, the following conclusions are made:

- 1. There does not exist a single failure mode for Kewaunee that dominates the seismic CDF.
- 2. Failure of a surrogate component, which is a conservative measure of the capacity of components that are screened out, is for many systems the important mode of failure. Since the surrogate does not specifically model the failure of a particular component, this observation is a further reinforcement of the conclusion that there does not exist any component specific failure modes that dominate the seismic CDF.
- 3. Operator actions are not a major contributor to the seismic CDF or plant capacity.

- 4. Loss of off-site power is an important contributor to the seismic risk.
- 5. As a group, random failures and operator actions are an important part of the seismic CDF. In a relative sense, variation in the random failure probabilities produced the largest change in the seismic CDF (a range corresponding to a factor of 2.5).

#### Seismic Containment Performance

As part of the seismic containment walkdowns, containment mechanical penetrations and the containment isolation valves were analyzed for the ability to withstand seismic events. The penetrations and isolation valves from both inside and outside of containment were analyzed. Based upon these plant walkdowns, no significant seismic hazards were found to exist and it was determined that these components possess a high capability to withstand seismic events.

The seismic containment failure frequency is 6.24E-06 which is about the same as the containment failure frequency due to internal events (8.03E-06). The seismic containment failure frequency is 57% of the seismic core damage frequency. The containment failure median capacity and HCLPF for Kewaunee are 0.51 and 0.30g PGA, respectively. The median capacity is about four times the SSE and the HCLPF is two and a half times the SSE. The HCLPF is based on an evaluation of the seismic containment systems model that considers both random and seismic failures. No additional Level 2 vulnerabilities were discovered.

The results of the evaluations performed indicated that the containment as well as the systems designed to ensure containment integrity are seismically sound and no vulnerabilities could be identified.

#### Fire

#### Fire Core Damage

In general, no significant fire concerns were discovered in the Fire PRA. The core damage frequency due to fire is 9.8E-05/year. This is dominated by fires in the A and B auxiliary feedwater  $\sim TW$ ) pump rooms, which contribute 84% to the total fire core melt frequency. These areas each contain cabling for one train of safe shutdown equipment and cabling for numerous non-safety related equipment, such as transformers supplying offsite power. Kewaunee meets all the requirements of 10 CFR 50, Appendix R, (other than exemptions approved by the NRC) and an additional equipment failure or human error in addition to the fire is necessary for core melt to occur.

Due to manual actions necessary to respond to a fire, human error is an important contributor to fire core damage frequency, contributing 56% (based on Fussel Vesely importance) to the fire core damage frequency. Of these, the largest contributor is failure to locally establish power to the dedicated (A) train of safe shutdown equipment, contributing 17% to the fire core damage frequency.

Following is a description of each of the thirteen dominant sequences, which represent 99.95% of the total core melt frequency.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 61 of 415

Sequence #1 - AFW pump A oil fire followed by failures of AFW and bleed and feed. This results in a loss of heat sink and early core damage. The primary means by which heat sink is lost is a station blackout. Since offsite power and the A diesel generator are unavailable as a result of the fire, a failure of the B diesel generator or the B train of service water, which cools the diesel generator, results in a station blackout. Since the fire also disables control cabling for the turbine driven AFW pump, there is no heat sink and therefore core melt occurs. The primary human errors in this sequence are failure to manually establish electrical power from the B diesel generator and failure to locally restore instrument air for the pressurizer PORVs, used for bleed and feed. The frequency of this sequence is 4.21E-05 per year.

Sequence #2 - AFW pump B oil fire followed by failure of AFW. This results in a loss of heat sink and early core damage. Other means of removing heat, (main feedwater, condensate, bleed and feed) are unavailable due to the unavailability of offsite power and safety injection pumps from the dedicated shutdown panel (DSP). This sequence is dominated by human error. Failure to establish electrical power from the A diesel generator locally and failure to establish service water and AFW from the DSP are major contributors to this sequence. The frequency of this sequence is 2.91E-05 per year.

Sequence #3 - Oil fire in A AFW pump followed by failure of CCW. This results in a loss of cooling to the reactor coolant pump (RXCP) thermal barrier, which can result in a small LOCA due to RXCP seal failure. Since the safety injection (SI) and residual heat removal (RHR) pumps are cooled by component cooling water (CCW) and charging is not available because of cabling damaged by the fire, there is no way to get makeup flow to the RCS to replace that lost through the RXCP seals and late core damage results. The only human error in this sequence is the failure to manually restart CCW and this is a relatively minor contributor. The frequency of this sequence is 9.65E-06 per year.

Sequence #4 - Fire near motor control center (MCC) 62A in B diesel generator room followed by a failure of charging and CCW. This results in a loss of cooling to the RXCP seals and late core damage. The primary means of loss charging and CCW is loss of power to the emergency buses, buses 5 and 6. Human error is not important in this sequence. The frequency of this sequence is 4.50E-06 per year.

Sequence #5 - Oil fire in B diesel generator followed by a failure of charging and CCW. This results in a loss of cooling to the RXCP seals and late core damage. The primary contributor is a mechanical failure of CCW and operator error in establishing charging flow. The frequency of this sequence is 3.56E-06 per year.

Sequence #6 - Fire near safeguards 480V electrical buses 51 and 52 followed by a failure of CCW. This results in a loss of cooling to the RXCP seals and late core damage. Human errors in this sequence include failure to manually establish on-site power, service water and CCW. The frequency of this sequence is 3.13E-06 per year.

Sequence #7 - Oil fire in B diesel generator followed by failure of AFW and bleed and feed. This results in a loss of heat sink and early core damage. All B train equipment, powered by safeguards 4160V electrical bus 6, is unavailable due to the fire. Therefore, the primary means of failure is mechanical failure of the A motor driven and turbine driven auxiliary feedwater Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 62 of 415

(AFW) pumps followed by failures of the SI, CCW or Instrument Air Systems, all of which are needed for bleed and feed. Another means of failure is a failure of DC bus BRA-104, which is needed to start both the A motor driven and turbine driven AFW pumps, and the A SI pump. Human error, failure to establish bleed and feed, is a minor contributor to this sequence. The frequency of this sequence is 2.18E-06 per year.

Sequence #8 - Oil fire in B diesel generator f llowed by failure of AFW, success of bleed and feed, and failure of high pressure recirculation. This results in a loss of heat sink and late core damage. All B train equipment, powered by bus 6, is unavailable due to the fire. Therefore, the primary means of failure is mechanical failure of the A motor driven and turbine driven AFW pumps followed by failures of valves associated with switchover to containment sump recirculation. Human error, in this case failure to stop the A RHR pump to limit its time in miniflow, is a minor contributor to this sequence. The frequency of this sequence is 1.70E-06 per year.

Sequence #9 - Oil fire in A AFW pump followed by failure of AFW, success of bleed and feed, and failure of high pressure recirculation. This results in a loss of heat sink and late core damage. Since the fire destroys both the A AFW pump and control cabling for the turbine driven pump, the primary means of failure is a mechanical failure of the B AFW pump followed by failure of valves associated with switchover to containment sump recirculation. Human error is not important in this sequence. The frequency of this sequence is 9.83E-07 per year.

Sequence #10 - Oil fire in B AFW pump followed by failure of charging and CCW. This results in a loss of cooling to the RXCP seals and late core damage. Both CCW and charging must be established from the dedicated shutdown panel (DSP). This sequence is dominated by the combination of failure to establish CCW and failure to establish charging. In this case, moderate dependency is applied. The frequency of this sequence is 5.76E-07 per year.

Sequence #11 - Fire in the relay room followed by failure of AFW. This results in a loss of heat sink and early core damage. The dominant contributor to this sequence is human error. The A diesel generator must be started locally, and service water and either charging or CCW must be started from the DSP. The frequency of this sequence is 3.14E-07 per year.

Sequence #12 - Fire near buses 51 and 52 followed by failure of AFW and bleed and feed. This results in a loss of heat sink and early core damage. Since AFW, SI, and instrument air are all started locally, human error is the dominant contributor to this sequence. Of these human errors, the largest contributor is failure to establish AFW and instrument air. These are not modeled as dependent actions because AFW is started from the control room and the instrument air compressor is simultaneously started locally. The frequency of this sequence is 1.79E-07 per year.

Sequence #13 - Fire near MCC 62A in B diesel generator room followed by failure of AFW, main feedwater, and bleed and feed. This sequence consists mostly of mechanical failures of AFW followed by the operator failing to stop the RXCPs, in order to prevent the additional heat input into the Reactor Coolant System. The frequency of this sequence is 1.48E-07 per year.

Fire Containment Performance

Due to the robust design of Kewaunee's large dry containment, no containment failures due to overpressurization are produced by any fire-initiated core damage sequence within the 48 hour containment failure in time. The containment failure frequency of 3.64E-05/year is due exclusively to failure to isolate containment. No additional containment failure modes unique to internal fires were identified.

## Other External Events

This analysis examines all credible external events other than seismic events, internal floods, or internal fires. Specifically examined in the other external events analysis are external flooding, aircraft accidents, severe winds, ship impact accidents, off-site and on-site hazardous materials accidents, and external fires. No vulnerabilities are identified that require detailed quantification of any accident events. It is therefore concluded that the effects from any of the other external events described here are not a significant concern at Kewaunee. The results and conclusions are presented in summary as follows.

High Winds and Tornadoes

Due to the low frequency of high winds and tornadoes at the Kewaunee site, it is concluded that the contribution to plant risk from severe wind events is insignificant.

The severe wind protective measures and design features instituted at Kewaunee are consistent with a highly safe plant design with very low risk contribution. Therefore, no design changes are currently recommended to protect the plant from severe winds.

### External Floods

In view of the low frequencies and maximum flood levels, as well as the plant elevation, the topographical layout of the site, and the elevation of plant penetrations relative to safety-related equipment, it is concluded that the contribution to plant risk from external flooding is greatly de almated by other risk contributors.

An analysis was also performed to evaluate flooding based on the probable maximum precipitation (PMP) criterion. It is concluded that Kewaunee is not endangered by the flooding based on the PMP criteria.

In fact, in 1993 when flood levels across the Midwest were at all time highs, there were no problems experienced at Kewaunee.

The external flooding protective measures and design features instituted at Kewaunee are consistent with a highly safe plant design with very low risk contribution. Therefore, no design changes related to external flooding prevention are currently recommended.

## Transportation and Nearby Facility Accidents

Based on the location of Kewaunee with respect to the major roads, rail transportation, air traffic and nearby industrial facilities, there is no threat to the plant safety from any of these sources.

Unless flight patterns change, the air or ground traffic significantly increases, or any new industrial facility is opened in the vicinity of the plant, no design changes in plant are recommended due to these events.

#### Hazardous Materials

This analysis began with a review of the Updated Control Room Habitability Report (Reference 34), which was completed in 1989. This report was the result of a study performed in response to NUREG-0737 and includes an assessment of hazardous materials on-site as well as off-site.

A plant walkdown and a review of plant records was performed to verify that the control room habitability study assumptions were still valid. It was determined that the results and conclusions stated in the study are still valid, and that there is no threat to control room personnel from hazardous spills or releases.

The analysis was further expanded to consider the effects of a release of hazardous materials on safety-related equipment or the local operation of plant systems during emergencies. It was determined that a release of hazardous material would have no effect on safety related equipment, and furthermore, no hazardous materials were located near safety-related equipment. It was further determined that there are no credible hazardous material releases that would prevent an operator from locally operating plant equipment during plant emergencies.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 65 of 415


## TABLE 1-1


## **RFLEASE CATEGORY DEFINITIONS**

Release Category	Definition
A	No containment failure occurs with 48 hour mission time but failure could eventually occur without accident management action; noble gases and less than 0.1% volatiles released.
G	Containment failure prior to vessel failure with noble gases and up to 10% of the volatiles released (containment isolation impaired).
S	No containment failure (leakage only, successful maintenance of containment integrity; containment not bypassed; isciation successful).
Т	Containment bypassed with noble gases and more than 10% of the volitiles released.
U	Containment failure prior to vessel failure $a$ th noble gases and more than 10% of the volatiles released (containment isolation impaired).

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 66 of 415

# FIGURE 1-1 TOTAL CORE DAMAGE FREQUENCY FOR INTERNAL AND EXTERNAL EVENTS





## 2. Examination Description

## 2.1 Introduction

The Kewaunee Nuclear Power Plant Individual Plant Examination for External Events (IPEEE) has been performed to identify and resolve plant specific severe accident issues stemming from external events.

Wisconsin Public Service Corporation (WPSC) has conducted the IPEZE in full compliance with the requirements of the NRC Generic Letter 88-20, Supplement 4. WPSC's approach to the IPEEE has been to perform realistic evaluations of Kewaunee's capabilities to respond to external events.

The Kewaunee External Events program consisted of the following major tasks:

Project Management Data Collection and Analysis Initiating Event Analysis Event Tree Analysis Systems Analysis Human Reliability Analysis Systems Interaction Fault Tree and Accident Sequence Quantification Sensitivity Analysis Peer Reviews Training and Technology Transfer

The Kewaunee IPEEE Containment Performance Analysis is a qualitative as well as a quantitative analysis analogous to the internal events Level 2 analysis as appropriate.

The models developed in the IPEEE are drawn from the internal events analysis and modified as necessary for external events. These models represent the as-built, as-operated Kewaunee Nuclear Power Plant. Efforts were taken to ensure that only formal procedures that the operators are trained to use have been credited.

### 2.2 Conformance With Generic Letter and Supporting Material

Generic Letter 88-20, Supplement 4, which was issued on July 22, 1992, requested each utility to perform an IPEEE for the purpose of:

- (1) developing an appreciation of severe accident behavior,
- (2) understanding the most likely severe accident sequences that could occur at its plant,
- (3) gaining a more quantitative understanding of the overall probabilities of core damage and fission product releases, and if necessary,

(4) reducing the overall probabilities of core damage and fission product releases.

General requirements provided in the Generic Letter for fulfilling the stated purpose are:

- (1) The utility staff should be used to the maximum extent possible in the performance of the IPEEE to insure that they:
  - understand the plant procedures, design operation, maintenance and surveillance,
  - understand the quantification/evaluation of the expected sequence frequencies,
  - determine the leading contributors to core damage and unusually poor containment performance,
  - identify proposed plant improvements for prevention and mitigation,
  - examine each of the proposed improvements, and
  - identify which proposed improvements will be implemented and their schedule.
- (2) The method of examination should be as described (for each of the external events) in the Generic Letter using the guidance of NUREG-1407, "Procedural and Submittal Guidance for the Individual Plant Examination of External Events (IPEEE) for Severe Accident Vulnerabilities."
- (3) The utility should resolve Unresolved Safety Issue (USI) A-45, "Shutdown Decay Heat Removal Requirements," as impacted by external events in the IPEEE.
- (4) The utility should carefully examine the results of the IPEEE to determine if there are worthwhile prevention or mitigation measures that could be taken to reduce the frequency of core damage or improve containment performance.
- (5) The utility should report the results of the IPEEE to the NRC consistent with the criteria provided in the Generic Letter and subsequent guidance provided in NUREG-1407.
- (6) The utility should document the examination in a traceable manner and retain it for the duration of the license unless superseded.

In response to the Generic Letter, WPSC issued two letters dated December 20, 1991 and September 18, 1992 stating its intent to perform an IPEEE for Kewaunee in order to identify, evaluate, and resolve severe accident issues germane to the plant. The IPEEE addresses the requirements set forth in Supplement 4 to the Generic Letter.

WPSC has invested substantial personnel time in addition to financial resources for the efforts of contractors J. R. Benjamin & Associates, Westinghouse Electric Corporation and Stevenson & Associates in the performance of an IPEEE that meets or exceeds the NRC directives listed in Generic Letter 88-20, Supplement 4. A permanently assigned staff, knowledgeable in the

2-2

g wpfiles lis pro ipecesum wp

design and operation of Kewaunee and the IPE, has been involved in all aspects of the IPEEE. Other WPSC personnel have been involved in various aspects of the evaluation as needed. In addition, steps were taken to insure that WPSC personnel who had a need for understanding of the evaluation or parts thereof developed an appreciation for the risk significance of the results and the plant response as well as an understanding of the bases of the IPEEE.

#### 2.3 General Methodology

The Kewaunee IPEEE program, as previously identified, consisted of eleven major tasks. The IPEEE was conducted using standard systems analysis practices such as those mentioned in NUREG-1407. A comprehensive task breakdown was developed for the Kewaunee PRA in order to organize the work to be accomplished. An overview of each of the tasks is provided below. More specific information regarding each of the analyzed external events is found within the applicable sections of this report.

#### IPEEE Tasks

- (1) Project Management Development and monitoring of detailed project planning and scheduling provided necessary technical direction of project analyses and proper review of results.
- (2) Data Collection and Analysis Plant-specific information was collected through plant walkdowns, review of WPSC calculations and review of the history of external events at Kewaunee. This data was analyzed and formatted for input into the IPEEE.
- (3) Initiating Events Analysis The selection of accident initiating events for the Kewaunee IPEEE considered both actual plant data and results of previous studies and published NUREGs.
- (4) Event Tree Analysis Plant-specific event tree models were drawn from the internal events analysis and modified as necessary for external events. This task entailed reviewing accident progression as modeled within the internal event trees and modifying these event trees based upon equipment and operator availability following initiation of the external event.
- (5) Systems Analyses Similar to the event trees, the internal events system fault trees were modified as necessary to reflect plant system availability following initiation of the external event.
- (6) Human Reliability Analysis The human reliability analysis task established suitable models to represent the interaction of operators and other plant staff with plant systems and equipment during normal operation and during transient and accident conditions. For this task, those human tasks important to the analysis were identified, and the full range of plant procedures was examined to determine the types of human actions that are routinely performed and what kinds of actions operators are trained to take. All accident sequences and system failure modes developed in the event and fault tree models were

carefully evaluated to determine those areas where operator intervention can, should, and must occur. Finally, the kinds of errors in all identified human actions critical to the analysis of plant risk were assessed in the Kewaunee IPEEE.

After potentially important human errors were identified, detailed models were developed and were quantified so that their effects could be incorporated into the event and fault tree models. The Technique for Human Error Rate Prediction (THERP) methodology was used for the human reliability analysis.

- (7) Systems Interaction Possible system interactions due to external events were identified by conducting detailed system walkdowns.
- (8) Fault Tree and Accident Sequence Quantification The Kewaunee external events fault trees and event tree accident sequences were integrated and quantified to obtain accident sequence cutsets, frequencies for all accident sequences resulting in core damage, and to identify dominant accident sequences among all event tree results. The Westinghouse WLINK Code System was used to perform the initial fault tree quantification. The seismic IPEEE used the J. R. Benjamin SHIP code for system and accident sequence quantification. The internal fire analysis also employed the COMPBRN IIIe code to back up engineering evaluations. The other external events analysis employed a screening approach with engineering judgement as described in Generic Letter 88-20, Supplement 4.
- (9) Sensitivity and Importance Analyses The response of the core damage frequency to changes in input parameters and modeling assumptions was examined to identify important actions and equipment and to study the sensitivity to those assumptions.
- (10) Review Program In all stages of the Kewaunee PRA, numerous levels of review were performed to ensure accuracy and completeness. Extensive reviews were performed by the WPSC PRA staff, independent WPSC reviewers. The PRA group members thoroughly reviewed the results of every core melt quantification iteration using their operations background to identify invalid cutsets. The models were reviewed to identify the problem that caused the invalid cutset, and then the problems were corrected. A independent group of experienced Kewaunee plant staff members performed an extensive review of the different phases of the Kewaunee IPEEE, and identified numerous improvements that were made to the IPEEE.
- (11) Training and Technology Transfer Training was conducted by contractor employees for utility personnel to provide the in-house ability to understand, evaluate, modify, and update the IPEEE to reflect proposed or actual changes in the plant design, operation or to account for future industry updates impacting external event analyses.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 72 of 415

## 2.4 Information Assembly

A tremendous amount of information was needed to perform the detailed Kewaunee IPEEE study. The project team reviewed and assembled information from plant specific sources, similar plant studies, and generic sources. Plant walkdowns were key to the date collection effort. Walkdowns were specifically used to search for plant external event vulnerabilities and to group data into specific areas. This data was ultimately used to determine important initiating events, quantify their frequency and determine component and system failure rates or provide information for various screening analyses.

The Kewaunee IPEEE team modeled the plant condition as it currently exists. All major changes to plant operation or design to date have been identified and included in the PRA results. All information used in the project is available at the WPSC offices in Green Bay, Wisconsin. Copies of some information are also housed at the contractor offices previously mentioned.

Detailed IPEEE project notebooks were developed for seismic events, internal fires and other external events (external floods, winds, etc.). Information sources used to develop the IPEEE models are identified in the individual sections of this report. Both plant specific and generic sources identified were used to define component availabilities, initiating events and initiating event frequency, important accident sequences and potentially important modeling features. Subsequent sections of this report provide a more detailed discussion of the use of the information collected.

Plant walkdowns were conducted by IPE team members and contracted personnel who were responsible for the evaluation of specific external events. WPSC IPEEE analysts accompanied the walkdown team members so as to observe first hand any identified plant vulnerabilities and take part in the IPEEE from start-to-finish.

Walkdowns were conducted for the systems and plant environment of most concern to the IPEEE. These areas are contained primarily in the auxiliary building and the containment. Several other buildings or areas were examined, however, because important systems and components are located therein. The areas or buildings in which walkdowns were made are:

- Containment
- Auxiliary Building
- Turbine Building Basement
- Relay Room
- Screenhouse
- Battery Rooms
- Technical Support Center

- Control Room
- Administration Building Basement
- Outside Grounds Including Switchyards

General arrangement drawings of these areas are contained in the USAR. The individual external event walkdowns are described in more detail in subsequent sections of this report.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 74 of 415

# 3. Seismic Analysis

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 75 of 415 SECTION 3

# SEISMIC ANALYSIS

# **TABLE OF CONTENTS**

# **SECTION**

# PAGE

ar le Mai

1 🖤 -

*	
3. Seismic Analysis	3-1
3.0 Methodology Selection	3-6
3.1 Seismic PRA	3-6
3.1.1 Hazard Analysis	3-10
3.1.2 Review of Plant Information and Walkdown	. 3-11
3.1.2.1 Plant Information	. 3-11
3.1.2.2 Information Sources	. 3-11
3.1.2.3 Plant Walkdowns	. 3-12
3.1.3 Analysis of Plant Systems and Structure Response	. 3-13
3.1.3.1 Plant Frontline Systems Included in the SPRA	. 3-13
3.1.3.2 Mechanical and Electrical Support Systems Included in	
the SPRA	3-14
3.1.3.3 Supporting Components Included in the SPRA	
3.1.3.4 Site Buildings Included in the SPRA	. 3-16
3.1.3.5 Structural Response	. 3-17
3.1.3.6 Soil Properties and Soil Failure Analysis	. 3-17
3.1.4 Evaluation of Component Fragilities and Failure Mostes	. 3-18
3.1.4.1 Component Screening	. 3-18
3.1.4.2 Fragility Analysis Results	. 3-19
3.1.4.3 Detailed Fragilities	. 3-25
3.1.5 Analysis of Plant Systems and Sequences	. 3-25
3.1.5.1 Seismically Induced Initiating Event Analysis	. 3-26
3.1.5.2 Seismic Event Tree Analysis	
3.1.5.3 Seismic Fault Tree Analysis	
3.1.5.4 Seismic Risk Quantification and Results	
3.1.6 Analysis of Containment Performance	
3.1.6.1 Basis for Analysis Score	
3.1.6.2 Containmen: Structure and Components	
3.1.6.3 Containment Safeguaru Systems	
3.1.6.4 Quantification and Results	
3.1.6.5 Containment Analysis Summary	
3.2 USI A-45, GI-131, and Other Seismic Safety Issues	
3.3 References	. 3-62

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 76 of 415

# **SECTION 3**

# SEISMIC ANALYSIS

# LIST OF TABLES

- Table 3-1: EPRI and LLNL Seismic Hazard Results for Kewaunee
- Table 3-2:
   SPRA Equipment/Component List with Fragilities
- Table 3-3:
   SPRA Equipment/Component List-Screened at Surrogate Level
- Table 3-4: Equipment Outliers
- Table 3-5: Component and Structure List
- Table 3-6:
   Description of Seismic Event Tree Nodes
- Table 3-7: Kewaunee SPRA Results
- Table 3-8:
   Summary of Plant Level Fragility
- Table 3-9:
   Seismic Core Damage Frequency Results
- Table 3-10:Dominant Sequences
- Table 3-11: Sensitivity Analysis Results
- Table 3-12: CET End States and Frequencies
- Table 3-13
   SPRA Release Categories and Probabilities

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 77 of 415

# **SECTION 3**

# SEISMIC ANALYSIS

# LIST OF FIGURES

- Figure 3-1: EPRI Seismic Hazard Curve for Kewaunee
- Figure 3-2: LLNL (NUREG-1488) Seismic Hazard Curve for Kewaunee
- Figure 3-3: Small and Medium Break LOCA, NUREG/CR-4840, Figure 3.6
- Figure 3-4: Seismic Initiating Event Tree
- Figure 3-5: Seismic Large LOCA Event Tree
- Figure 3-6: Seismic Medium LOCA Event Tree
- Figure 3-7: Seismic Small LOCA Event Tree
- Figure 3-8: Seismic Loss of Off-Site Power Event Tree
- Figure 3-9: Seismic Steam Line Break Event Tree
- Figure 3-10: Flow Chart for SHIP Code
- Figure 3-11: Kewaunee Plant Fragility Curve
- Figure 3-12: Sequence Level Fragilities
- Figure 3-13: Sequence Level Fragilities
- Figure 3 14: System Fragilities
- Figure 3-15: System Fragilities
- Figure 3-16: System Fragilities
- Figure 3-17: System Fragilities
- Figure 3-18: Core Damage Frequency Results By Sequence

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 78 of 415

# **SECTION 3**

# SEISMIC ANALYSIS

# LIST OF FIGURES (Cont'd)

- Figure 3-19: Ground Motions Contribution to Plant Risk
- Figure 3-20: Plant Level Fragility Random/HRA Case
- Figure 3-21: Plant Level Fragility Surrogate Case
- Figure 3-22: CSG System Fragilities

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 79 of 415

## 3.0 Methodology Selection

The methodology applied in the Kewaunee Nuclear Power Plant seismic PRA (SPRA) is consistent with the methodology outlined in NUREG-1407 (Reference 1). A SPRA has not been previously performed for Kewaunee. Thus this is a new PRA study.

#### 3.1 Seismic PRA

The Kewaunee SPRA was performed using a methodology that allowed for the incorporation of the analysis that was performed in the Kewaunee Individual Plant Examination (IPE). Using such a methodology was beneficial for two reasons: first, since the basic structure of the internal events fault trees and event trees could be carried over into the seismic analysis, this saved the effort of creating all new logic models. Therefore, it was only necessary to make modifications to existing models. Second, by using the same logic model structure, for both the IPE and SPRA, the core damage contribution results could be compared on a common basis. Since the SPRA logic models were built by making modifications to the internal events logic models, the event tree and fault tree sections of this report only describe the modifications required to convert the IPE logic models into the SPRA logic models. The IPE submittal (Reference 2) provides the basis and description of the fault tree and event tree logic models.

The methodology used for the SPRA analysis is summarized below:

#### Hazard Analysis

The seismic hazard curve is a description of the probability that during a given period of time, one or more earthquakes will occur that results in a specific peak ground acceleration (PGA) level. As recommended in Generic Letter 88-20, Supplement 4, the site specific seismic hazard curves generated by both the Lawrence Livermore National Laboratory (LLNL) and the Electric Power Research Institute (EPRI) are analyzed in the Kewaunee SPRA. This is discussed further in Section 3.1.1.

#### Plant Walkdown

The Kewaunee SPRA plant walkdowns were conducted to take advantage of the overlapping requirements between the IPEEE and Unresolved Safety Issue (USI) A-46 examination programs. All equipment were treated as if they were USI A-46 items, even if they were designated as SPRA items with specific fragility levels assigned. Seismic walkdowns were also conducted to assess the primary site structures. The plant walkdowns are discussed in detail in Section 3.1.2.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 80 of 415

Fragility Analysis

In the SPRA, three types of basic events are considered in the plant logic model:

- component (i.e., structure or equipment item) failures that are initiated by a seismic event (seismic fragility)
- random (non-seismic) failures, and
- operator errors that occur following a seismic event.

Each basic event type is described below.

<u>Seismic Fragility</u> - The purpose of the seismic fragility analysis is to estimate the capacity of structures and equipment at Kewaunee in terms of peak ground acceleration (PGA). The seismic fragility of an individual component (structure or equipment item) is defined as the conditional probability of failure for levels of PGA. The assessment of the seismic fragility of a component is a function of its seismic design basis, safe shutdown earthquake (SSE), the factors of safety incorporated in the design process and the variability in earthquake ground motion and factors that influence structure response. As a result of these variabilities, the capacity of a component to withstand earthquake loading, as defined in terms of PGA, is a random variable. For a specified PGA level (a) the fragility (conditional probability of failure) of a component is:

 $f = P[A = a] \tag{3-1}$ 

The fragility of a component is modeled by a lognormal distribution. The lognormal distribution is defined by two parameters, the median capacity,  $A_m$ , and logarithmic standard deviation,  $\beta$ . The conditional probability of failure is calculated as:

$$f = \phi \left[ \frac{\ln(a/A_m)}{\beta_c} \right]$$
(3-2)

where  $(\phi)$  is the standard normal cumulative distribution function. For each component incorporated in the SPRA the median capacity,  $A_m$ , and logarithmic standard deviation,  $\beta_c$ , are determined.

The variability in the seismic capacity of a component is quantified by the logarithmic standard deviation which is divided in two parts, randomness and uncertainty. The logarithmic standard deviation for randomness,  $\beta_R$ , quantifies the inherent or natural variation in material properties and earthquake ground motion. The uncertainty in the assessment of the seismic capacity of a

component is attributed to limited data to determine the ground motion that causes failure and limitations of analytical methods. This logarithmic standard deviation for variability is denoted  $\beta_{U}$ .

The composite variability,  $\beta_C$ , is defined by:

$$\beta_c = \sqrt{\beta_R^2 + \beta_U^2}$$
(3-3)

In the Kewaunee SPRA the mean seismic fragility curve is used to quantify the plant risk. The mean conditional probability of failure is determined through the use of the median capacity,  $A_m$ , and the composite logarithmic standard deviation,  $\beta_c$ , in equation 3-2.

For a component, the ground motion (PGA) level for which there is a high confidence of a low probability of failure (HCLPF) is defined as:

$$HCLPF = A_m \exp(-1.65(\beta_k + \beta_U))$$
(3-4)

The HCLPF provides a measure of the seismic integrity of a component that accounts for the uncertainty in its capacity and randomness in response.

<u>Random (Non-Seismic) Failures</u> - As part of the Kewaunee SPRA, random or non-seismically initiated failure of equipment is considered. These random events are the same as those used in the IPE plant model.

<u>Operator Actions</u> - During a non-seismically initiated accident, the potential for operator error is related to the level of stress associated with the accident and the complexity of the operations that must be performed. Given the occurrence of an earthquake, stress conditions are amplified, leading to the greater chance for operator error. In addition, depending on the level of ground motion, the operator must contend with the disruption that may hypothetically occur in the control room (i.e., falling ceiling tiles, overturned bookcases, items falling off desks) as well as damage to the plant that may make access to critical areas difficult. In the Kewaunee SPRA, the increased likelihood of operator error with increasing levels of ground motion is considered. Operator error rates are defined for specified ground motion intervals. For low ground motions that are not likely to cause major damage to the plant, the operator error rates are the same as those used in the IPE. These rates are then increased for specified ground motion intervals. This is discussed further in Section 3.1.5.3.

Seismically Induced Initiating Events

To model the performance of the plant following the occurrence of a seismic event, the potential structure and equipment failures that could initiate an accident are considered. These events are modeled in a seismic event tree and fault trees. To develop the logic structure for seismically initiated accidents the following analysis procedure is used:

- 1. The system analysis identified the structures and equipment items that may be required to determine the status of the plant and to bring the plant to and maintain hot shutdown following a seismic event.
- 2. For the items identified in the previous step, a screening evaluation is performed to determine which components may be vulnerable to seismically initiated failure. (The screening procedure is described in Section 3.1.4.)
- 3. A seismic event tree is developed to model the sequence of seismically initiated failures in the plant. The initiating event is the occurrence of earthquake ground motion at Kewaunee. The top events in the tree correspond to seismically initiated structure and equipment failures, front line and support system failures, etc.
- 4. For each plant system, a seismic fault tree is developed to model the seismic and random failures that could lead to system failure. Included in the system model are operator actions required to mitigate an accident.
- 5. For structures and equipment items modeled in the seismic event and fault trees, fragility parameters are determined.
- 6. For operator actions that are modeled, seismic failure probabilities are estimated. (The estimation technique is described in Section 3.1.5.3.)

Seismically initiated accidents included in the SPRA are:

- Reactor Vessel rupture
- Large (> 6") LOCA
- Medium (3" 6") LOCA
- Small (1.5" 3") LOCA
- Transients
- Loss of Off-Site Power
- Steam Line Break

The logic model developed in the above steps is quantified using the Seismic Hazard Integration Package (SHIP) code (Reference 3) to determine the plant seismic risk. The seismic risk quantification process is described in Section 3.1.5.

## Seismic Event Trees

Seismic event trees are developed to model the event sequences that can follow the occurrence of an earthquake. The top events in the SPRA event trees define the frontline systems that need to be modeled in the seismic analysis and thus, the necessary support systems are defined by the frontline system requirements. Top events in the event tree include:

- Structure Failure
- Reactor Vessel Failure
- Support System Failure (i.e., electric power and cooling water)
- LOCAs
- Mitigation System Failure

A complete description of the methodology and assumptions used in the event tree development is found in Section 3.1.5.2.

#### Seismic Fault Trees

Seismic fault trees are developed using the Level 1 IPE analysis as the foundation for the fault trees in the SPRA. Once the systems needed for the SPRA analysis are defined, it is necessary to determine the components in these systems that could be adversely affected by seismic activity. The vulnerable components were identified during the seismic walkdown. A seismic fault tree is developed for each internal events fault tree that contains seismically vulnerable components. The seismic fault trees only contain the seismic failures of a system's components. After each system seismic fault tree is completed, it is linked with the internal events fault tree it supports. The resulting system fault tree cutset files contain both seismic and random failures. To simplify the system fault trees and more explicitly represent the intersystem dependencies, support systems such as AC power, DC power, and service water are removed from the system level analysis and placed into the sequence level analysis. A complete description of the methodology and modeling assumptions used in the fault tree development is found in Section 3.1.5.3.

## 3.1.1 Hazard Analysis

In the Kewaunee SPRA, the EPRI mean seismic hazard curve for PGA is used. Table 3-1 shows the EPRI hazard estimates for Kewaunee. The mean annual hazard curve defines the mean probability of exceedence of specified PGA levels at the plant site as determined in the EPRI seismic hazard study. The mean PGA hazard curve, which is defined to a maximum of 1.59g, is used in the seismic risk quantification. The EPRI mean annual seismic hazard curve for the Kewaunee site is presented in Figure 3-1.

The site specific seismic hazard curve generated by LLNL is used in performing sensitivity analyses as discussed in Section 3.1.5.4. The LLNL mean hazard estimates are presented in Table 3-1. The LLNL mean annual hazard curve is presented in Figure 3-2. These are the revised hazard estimates that are presented in NUREG-1488 (Reference 28) and endorsed by NRC Information. Notice 94-32 (Reference 23) as the best available information on seismic hazard estimates.

# 3.1.2 Review of Fiant Information and Walkdown

# 3.1.2.1 Plant Information

Kewaunee is designed to withstand the effects of unusual natural phenomena including earthquakes. The plant is designed to withstand a design basis earthquake (DBE) (also known as the SSE with a PGA of 0.12 g (12% of gravity). The operating basis earthquake (OBE) is one-half of the DBE event.

The Kewaunee site is a soil site with the safety-related power block structures founded on a clay-sand soil to an approximate depth to bedrock of 76 feet. The original building model is used in a nodal response analysis to obtain amplified floor response spectra (FRS) for the LLNL median ground spectral shape corresponding to the 10,000 year return period for the following buildings:

Containment Auxiliary Building Turbine Building Administration Building Technical Support Center

Since the screenhouse is entirely at or below grade (a deeply embedded structure) the ground spectrum is conservatively used as seismic demand for all elevations of the screenhouse. All safety-related systems and equipment are contained in the aforementioned power block structures.

Plant systems are chosen that were required to safely shut the plant down in the event of an earthquake. The list started as the Safe Shutdown Equipment List (SSEL) developed for the USI A-46 program. Since the USI A-46 program addresses mechanical and electrical equipment only, piping systems and plant structures were added to the list. Additionally, other equipment was added to the list to provide functions that are not addressed by the (USI) A-46 program.

## 3.1.2.2 Information Sources

As stated in the Kewaunee Updated Safety Analysis Report (USAR) (Reference 4), the plant buildings and systems are seismically designed. The USAR was used to obtain seismic design criteria for the DBE earthquake. The safety-related power block structures were evaluated by John A. Blume Associates, Engineers under contract to Pioneer Services, the Architect-Engineering firm responsible for the Kewaunee design. The Blume reports, (Reference 5) and (Reference 6), evaluate the seismic, dynamic response of the buildings providing amplified FRS for the DBE, and evaluate the seismic loads and stresses for the DBE, respectively.

The existing seismic evaluations of the safety-related piping and mechanical and electrical equipment were primarily found in the Kewaunee project engineering files originally developed by Pioneer Engineering, Inc. Safety-related piping was re-evaluated in accordance with requirements set forth in the IEB 79-14 piping seismic analysis program (Reference 7). This effort evaluated piping in the as-built configuration in accordance with current seismic-dynamic analysis procedures. Piping stress summaries and equipment stress analyses were obtained from these files. As-built and original installation drawings were used to obtain routing, equipment weights, and anchorage details.

Evaluation of site soil seismic adequacy and liquefaction potential was conducted by GEI Consultants, Inc. (Reference 8). Original site soil properties which formed the basis for the study were obtained from a geological study of Kewaunee performed in 1967 (Reference 9).

Much of the methodology of the seismic fragility program is based on the procedures prescribed in EPRI NP-6041 (Reference 10) which establishes bases for seismic "binning" and screening of nuclear power plant equipment, mechanical and electrical distribution systems, and power block structures. The basis for the procedures in EPRI NP-6041 use the same experience data as the Generic Implementation Procedures (GIP) (Reference 11) developed for resolution of the USI A-46 issue. Ancillary support documentation for the GIP and EPRI NP-6041 that are used in this study for Kewaunee include EPRI Reports NP-5228 (Reference 12) for anchorage issues, NP-7146 (Reference 13) for electrical cabinet amplification characteristics, and NP-7147 (Reference 14) for relay generic seismic ruggedness levels.

# 3.1.2.3 Plant Walkdowns

The Kewaunee SPRA takes advantage of the overlapping requirements between the IPEEE and A-46 examination programs. Seismic Review Teams (SRT) conducted the Kewaunee SPRA walkdowns following the walkdown procedures detailed in EPRI NP-6041. Each team consisted of two Seismic Capability Engineers trained by EPRI both in the USI A-46 walkdown requirements, and also in the IPEEE add-on requirements.

Wisconsin Public Service Corporation (WPSC), Stevenson & Associates (S&A), Jack R. Benjamin & Associates (JRBA) and RPK Structural Mechanics supplied the Seismic Capability Engineers. At least one WPSC engineer with systems expertise participated on each SRT throughout the plant walkdowns. The walkdowns were conducted between March 15 and April 2, 1993.

Walkdowns were conducted to evaluate plant equipment. For the sake of documentation, all equipment was treated as if it were an USI A-46 item, even if it was designated as SPRA equipment items only. As such, each equipment item has a Screening Evaluation Worksheet (SEWS) completed for it in accordance with GIP requirements as well as a fragility level assigned to it. Safety-related piping, electrical raceways and ductwork were walked down separately to assess fragility capabilities. Essential relays were evaluated based on seismic screening rules and then on circuit analyses. In accordance with GIP rules, spot checks of relays were made during walkdowns to confirm type (model number and manufacturer), location and installation adequacy. Structural screening walkdowns were conducted by Dr. John Reed of JRBA to assess the primary site structures and determine building fragilities.

#### Peer Review

An independent evaluation and peer review of the walkdown process was performed in accordance with the GIP by Dr. Paul Smith of The Readiness Operation on March 28 - March 30, 1993. As required, the review included an assessment of the walkdown and analyses by audit and sampling to identify any gross errors. Dr. Smith personally conducted two days of walkdowns with the SRTs and on his own to ascertain completeness and correctness of the SPRA and USI A-46 walkdown. His review included both comparing completed SEWS with equipment previously inspected by the SRTs and witnessing the SRTs performing actual evaluations in the field. Dr. Smith also reviewed the documentation packages the SRTs used to determine equipment design details that could not be readily determined by walkdown. Dr. Smith concluded that the walkdowns were being conducted competently and the findings made were appropriate. Documentation of Dr. Smith's peer review is provided in Reference 15.

# 3.1.3 Analysis of Plant Systems and Structure Response

This section discusses the development of the plant systems considered in the SPRA. The systems needed and the specific equipment comprising those systems are presented. Supporting systems such as electrical raceways are also presented. Structures containing these systems are identified and their seismic response characteristics are also discussed. Finally, site soil conditions and soil stability are presented in this section.

## 3.1.3.1 Plant Frontline Systems Included in the SPRA

## Low Pressure Safety Injection System

The Low Pressure Safety Injection (LPSI) System and the safety injection accumulators are subsystems of Kewaunee's Emergency Core Cooling System (ECCS). It can be operated in the low pressure injection (LPI) mode and the low pressure recirculation (LPR) mode. The LPSI System and the accumulators provide emergency core cooling in the event of a break in either the Reactor Coolant System (RCS) or the secondary system. The purpose of the injection mode of operation for the various accidents is to terminate any reactivity increase following the postulated accidents, cool the core, and replenish coolant lost from the RCS. Upon depletion of the refueling water storage tank (RWST), the recirculation mode of operation is initiated to provide long term heat removal by recirculating the water that accumulates in the containment sump.

## High Pressure Safety Injection System

The High Pressure Safety Injection (HPSI) System is a subsystem of Kewaunee's Emergency Core Cooling System (ECCS). It can be operated in the high pressure injection (HPI) mode, and the high pressure recirculation (HPR) mode. The HPSI system provides emergency core cooling in the event of a break in either the RCS or the secondary system. The purpose of the injection mode of operation is to terminate any reactivity increase following the postulated accidents, cool the core, and replenish coolant from the RCS.

Upon depletion of the RWST, the recirculation mode of operation may be initiated to provide long-term cooling by recirculating the water that accumulates in the containment sump by way of LPR.

## Auxiliary Feedwater System

The Auxiliary Feedwater (AFW) System is an engineered safeguard system designed to supply high pressure feedwater to the steam generators (SGs) following an interruption of the Main Feedwater (FW) System supply. Periods when the AFW System may be required for the removal of residual heat from the core include startup, safety injection, failure of the FW System and for long term decay heat removal. AFW System operation prevents the release of reactor coolant through the pressurizer safety valves and removes the residual heat from the reactor core by heat transfer in the SGs.

# 3.1.3.2 Mechanical and Electrical Support Systems Included in the SPRA

## Service Water System

The Service Water (SW) System is designed to provide redundant cooling water supplies to the diesel generators, safeguards compressors, safety injection pumps, containment fan coil units, turbine and auxiliary building safeguard fan coil units, control room air conditioners, component cooling heat exchangers, charcoal filter deluge for control room post accident recirculation, special zone ventilation, and shield building ventilation. The SW System provides an emergency supply of water to the Component Cooling Water (CCW) System, spent fuel pool and a backup source of water to the AFW System. The SW System also provides non-redundant cooling water supplies for balance of plant equipment.

## Component Cooling Water System

The CCW System is designed to remove sensible heat from the RCS via the Residual Heat Removal (RHR) System during plant cooldown, startup and shutdown. It also provides cooling of water taken from the containment sump during the recirculation phase of emergency core cooling. The CCW System cools the RCS letdown and reactor coolant pump (RXCP) seal leakoff flows to the Chemical and Volume Control System (CVCS). The CCW System provides cooling for the RXCPs, low head safety injection (RHR) pumps, high head safety injection (SI) pumps and the internal containment spray (ICS) pumps. The CCW System serves as an intermediate loop between systems processing or containing radioactive fluids and the SW System. The CCW System thereby minimizes the chance of contaminating the SW System with leakage from radioactive system coolers.

#### Electric Power System

The Electric Power System (EPS) provides a reliable source of power to all plant systems required during normal or emergency plant operation.

The primary functions of the EPS is to:

- Provide a reliable source of motive power to those components whose operation is necessary for the mitigation of any abnormal event affecting the reactor core, its heat removal systems, or systems that could effect the release of radioactivity to the environment.
- Provide a reliable source of control power for the operation of these systems and for the initiation of safeguards systems actuation signals.
- Provide a reliable source of power to instrumentation necessary for the monitoring of emergency system functions, for the monitoring of key plant parameters, and for inputs to safeguards systems actuation logic matrices.

#### **Reactor Protection System**

The protective actions initiated by the Reactor Protection System (RPS) are broadly classified into two major categories, reactor trips and actuations of engineered safety features. Therefore, the RPS protective functions are addressed from two functionally defined subsystems, the Reactor Trip System (RTS) and the Engineered Safety Features Actuation System (ESFAS). These two subsystems perform all of the safety-related actions associated with the RPS.

The overall RPS consists of: Foxboro process instrumentation, nuclear instrumentation system, reactor protection, and safeguards logic relay cabinets, SI sequencer, and reactor trip switchgear. For reactor trip and engineered safety features actuation, the safeguards and reactor protection logic relay cabinets each contain two redundant logic trains, A and B, that are physically and electrically independent. The logic relay cabinets receive inputs from process instrumentation, nuclear instrumentation, field contacts, and directly from main control board switches.

## 3.1.3.3 Supporting Components Included in the SPRA

#### Piping

As discussed in Section 3.1.3.1, numerous systems are identified as being considered in the SPRA. These systems are reviewed to ensure that the mechanical piping is seismically designed in all instances. Seismically designed piping is screened out at a relatively high PGA level as discussed in Section 3.1.4. As part of the IPEEE walkdown a candidate piping system was walked down from end to end to verify design adequacy. Piping inertial failure is not the issue. Inadequate piping system flexibility and excessive relative support deflections are more likely contributors to seismically induced failures. Specific items that could diminish seismic capacity include:

- threaded or Victualic connections
- cast iron pipe
- inflexibly attached branch line
- excessive nozzle loads
- proximity of valve operators to structures, components and other systems
- poor supports
- lack of flexibility across seismic gaps

The A train of the SW System was inspected at Kewaunee in detail to investigate for the aforementioned concerns. Also, in general, other piping systems were observed during the course of the walkdowns for these concerns.

# Electrical Raceways

A cable and conduit raceway review was conducted in accordance with Section 8 of the GIP in all safety-related areas of the plant. The raceway review consisted of: (1) a plant walkdown in which the raceways were evaluated against a set of walkdown guidelines, and (2) an analytical check of selected worst-case supports using a set of Limited Analytical Review Guidelines. The screening procedure for the raceways was based on earthquake experience and shake table test data. The plant walkdown focused on an inspection for design details and features that might result in poor seismic performance. The walkdowns were documented on Plant Area Summary Sheets (PASS). Representative, bounding support hangers were selected for ductility and load capacity evaluations for the worst-case Limited Analytical Reviews.

## **HVAC Ducting**

Ductwork was inspected throughout the site buildings. The major concern in these inspections were anchorage adequacy and support details, such as no missing bolts or connections. Particular attention was given to ducting inside containment supported along the steel shell and inside the battery rooms where collapse could short circuit the emergency station batteries.

## 3.1.3.4 Site Buildings Included in the SPRA

All buildings containing systems to be considered in the SPRA as well as support systems included in the SPRA were assessed. A site walkdown of the structures was performed by Dr. John Reed of JRBA and was presented in a report to Stevenson and Associates (Reference 31). Included in the building assessment walkdown were:

- Containment vessel (including the internal structures)
- Administration building basement (diesel generator rooms)
- Shield building
- Auxiliary building
- Screenhouse building
- Screenhouse tunnel
- Turbine building mezzanine (battery rooms)
- Turbine building basement (safeguards equipment alley)
- Technical support center

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 90 of 415

The evaluations were made in accordance with EPRI NP-6041, Table 2-3. Field walkdowns were supported by a thorough review of the USAR, seismic stress evaluations by Blume (Reference 5), and design calculations and drawings generated by the Archit st-Engineer, Pioneer/Fluor.

#### 3.1.3.5 Structural Response

2

The original DBE or SSE seismic analysis FRS at Kewaunee are based on simple dynamic models and soil springs, with peak input ground acceleration of 0.12g. The IPEEE seismic motion of interest for the SPRA is well in excess of the design basic PGA. Given the availability of advanced soil-structure interaction (SSI) analysis techniques, it is expected that the effects of radiation damping in the soil and kinematic interaction would result in floor response spectra that would be more realistic. Although this was considered, the cost of this benefit was determined to exceed the value, given the relatively low seismic hazard for this site. Therefore, the original building models and soil springs were used to generate amplified floor response spectra for the IPEEE SPRA study. The FRS are considered conservative. The original model is based on three-dimensional lumped mass models with elastic half-space springs to represent the soil properties. Soil damping is assumed to be 5% of critical damping.

Uniform hazard spectra are used for the seismic input. In accordance with the provisions of NUREG-1407, the median shape for the 10,000 year return period as provided by the <sup>1</sup>-awrence Livermore National Laboratory Eastern Seismicity Report (Reference 16) is used for this study. Structural damping for all modes is set to 7% in accordance with the recommendation of EPRI NP-6041.

## 3.1.3.6 Soil Properties and Soil Failure Analysis

NUREG 1407 specifically requires the consideration of soil failure effects in the seismic IPEEE. Soil failure effects are considered from two perspectives: 1) soil liquefaction potential; and, 2) differential soil displacements under seismic conditions, as an input to buried component fragilities.

The stratigraphy of Kewaunee consists of alternating layers of heavily overconsolidated glacial till and glacial lacustrine deposits underlain by very dense glacial outwash overlying dolomite bedrock. The glacial till and glacial lacustrine deposits consist of a clay matrix with varying amounts of sand and gravel included. The outwash consists of relatively clean sand and gravel.

In the Dames & Moore report (Reference 9), a shear wave geophysical refraction survey was conducted across the site, which indicates that the shear wave velocities of the glacial deposits and the bedrock are 2,500 fps and 11,500 fps, respectively. GEI estimates the shear wave velocities of the glacial clays and the outwash using empirical relationships by Hardin (Reference 17) and by Ohta and Goto (Reference 18), which range from 500 fps near the surface to 1050 fps at a depth of 62.5 ft. for the glacial clay. The outwash estimated shear wave velocity ranges from 1000 to 1300 fps bas d on the Hardin and Ohta, et al. empirical relationship, respectively. Based on these considerations, it is GEI's opinion that the actual shear wave velocities are bounded by the results obtained using the empirical correlations and those of the shear wave velocity survey. The soil failure analyses were conducted for both sets of shear wave velocities.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 91 of 415

The empirically obtained values are referred to as the stiff soil profile, and the geophysical survey results as the very stiff soil profile.

The results of the soil failure evaluation are provided in Section 3.1.4.2.

# 3.1.4 Evaluation of Component Fragilities and Failure Modes

The development of fragility values for equipment and structures in the Kewaunee SPRA proceeded through a three phase process: 1) component screening; 2) simplified fragility analysis; and, 3) detailed fragility analysis. This three phase consideration of the seismic ruggedness of plant equipment and structures efficiently concentrates attention on those items most significant to the overall assessment of seismic risk.

The potential for seismic interaction hazards results in specific seismic initiators within the system logic model. Thus the individual component fragilities represent the inherent seismic ruggedness of the components, independent of any seismic interaction hazards. The fragility of the interaction hazard, such as a masonry block wall, is applied to the hazard as an independent component with system logic linking the failure of the hazard to the failure of the affected components.

# 3.1.4.1 Component Screening

During the detailed plant walkdowns, the SRT engineers assigned a screening value to every component in the SPRA. EPRI NP-6041 supplied the framework for the screening decision making. Although the seismic margin procedure characterizes seismic ruggedness in terms of HCLPF level, the direct relationship between the HCLPF and median capacity supports the use of EPRI NP-6041 in performing SPRA component fragility screening. Followup anchorage chalysis verified inclusion at either the screening level, or produced a fragility value for individual components based upon anchorage capacity.

Application of the screening guidelines to SPRA items resulted in the following categories based on peak spectral acceleration capacity:

- Screened out at the 1.2g HCLPF screening level;
- Screened out at the 0.8g HCLPF screening level, but does not meet the 1.2g criterion
- Does not meet the 0.8g HCLPF screening criterion, but the item is also in the A-46 program and meets design basis.
- Does not meet the 0.8g HCLPF screening criterion, and the item is not in the A-46 program.

Based on the results of the walkdowns, the project selected the first screening column in Table 2-3 of EPRI NP-6041 for the Kewaunee SPRA. All components meeting this screening level are screened out, and the balance are explicitly considered within the SPRA. As discussed below, a single surrogate element in the SPRA represents the aggregate effect of the screened

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 92 of 415

out components. Engineering evaluations of anchorage capacities either validated the screening selection, or provided a simplified fragility value (second phase) on a component by component basis.

# The Surrogate Element

The SPRA includes a single surrogate element representing the conservative capacity of the weakest component screened out. The surrogate element appears as a basic event in each system with failure leading directly to system failure. The median capacity of the surrogate element translates the EPRI NP-6041 spectral acceleration of 0.8g from a HCLPF to a median fragility expressed as PGA. The median capacity of the surrogate element computes as a direct function of the site ground spectral shape, which for the IPEEE is the median spectral shape with a 10,000 year return period provided in NUREG/CR-5250. The use of the Kewaunee ground spectral shape resulted in a median capacity of 0.64g for the surrogate element. Following the recommendations of Drs. Kennedy and Reed (Reference 19), the surrogate element has an associated combined uncertainty ( $\beta_c$ ) of 0.3.

# 3.1.4.2 Fragility Analysis Results

The Kewaunee SPRA implements the concept of simplified fragility analysis as a means to bridge the gap between the summary level of the screening methodology and detailed fragility analysis. This approach improves on the use of industry generic fragilities by including plant specific analysis in the determination of component median seismic capacity values.

Simplified fragility analysis concentrates on determining the median seismic capacity taking actual plant specific conditions into consideration. All simplified fragilities use the same value for the combined variability ( $\beta_c$ ) = 0.46. Techniques used in simplified fragility analysis include:

- Detailed anchorage analysis;
- Factoring analysis;
- USI A-46 equivalency analysis; and,
- Detailed stress analysis.

Anchorage considerations rely heavily on the availability of detailed and bounding analyses performed for components also within the USI A-46 examination program. For cases in which the USI A-46 results are not available, the SPRA capacity assures that components minimally meet the USI A-46 requirements using equivalency analysis. The SPRA treats the USI A-46 values as equivalent to a HCLPF for purposes of estimating the median capacity.

Factoring analysis converts available design analysis results to median capacity values substituting the IPEEE in-structure floor spectra for the existing design spectra as applicable. Factoring separates out the seismic component from other design loads, such as dead load and live load, following the methodology outlined in EPRI NP-6041.

The availability of IPEEE in-structure floor spectra makes the simplified fragility analysis concept a productive intermediate step for this SPRA. Component capacity values come from one of the following sources:

- 1. Available calculations, or reports of previous seismic analysis;
- 2. Detailed anchorage analysis performed for the SPRA floor spectra;
- 3. Generic Equipment Ruggedness Spectra (used for relays);
- 4. Application of the lower EPRI NP-6041 screening lane (0.8g); or,
- 5. Equivalency to the minimum GIP demand (A-46 components only).

## Estimated Uncertainty for Simplified Fragility Analysis

The estimated fragilities couple an estimated median capacity  $(A_m)$  with an estimated logarithmic standard deviation,  $\beta_C$ , accounting for both randomness  $(\beta_R)$  and uncertainty  $(\beta_U)$ . Examination of east coast earthquake records suggest that an adjustment to the commonly selected value for  $\beta_C$  would be appropriate to account for a higher degree of variability in the peaks and valleys. This examination suggests that a more appropriate value for the  $\beta_R$  associated with the randomness of the peaks and valleys of seismic records is 0.29. This consideration results in the selection of  $\beta_C = 0.46$  for use with all but the detailed fragilities.

# Mechanical and Electrical Equipment

Tables 3-3 and 3-4 provide the equipment and components considered in the SPRA. The equipment was walked down during a two weck pre-walkdown in March of 1992. Final walkdowns were performed during a three week period in March and April of 1993. For the final walkdown, two SRTs participated during the first week and were comprised of Dr. R. P. Kennedy of RPK Consulting, Dr. J. D. Stevenson and W. Djordjevic of Stevenson & Associates, and P. Finnemore of WPSC. One SRT comprised of W. Djordjevic and P. Finnemore conducted the final two weeks of the walkdown.

The purpose of the walkdowns was to conduct a combined A-46 and IPEEE (screening) walkdown. As noted previously, all non A-46 items were treated as if they were A-46 items; therefore, complete SEWS exist for each of them as well.

All equipment was screened using the first column in Table 2-3 in EPRJ Report NP-6041. The screening approach uses the experience gained in performing seismic margin assessments (SMAs) to screen components out of a SPRA. Meeting the caveats for these components ensures that they may be represented by a surrogate element with a median peak 5-percent damped spectral acceleration capacity of 1.2g - which is equivalent to 0.64g PGA - with a combined logarithmic standard deviation,  $\beta_{C}$ , value of 0.30.

Items that were not screened out at the 0.64g PGA value were evaluated in detail to determine their specific seismic fragility. Section 3.1.4.3 discusses detailed fragilities.

# Relays

The clarifying note in Table 3.1 of NUREG-1407 classifies the Kewaunee plant as a focused-scope review for the purposes of performing relay chatter evaluation. Since the plant is included in the USI A-46 program, relays were evaluated in accordance with Section 6 of the GIP. A focused scope plant that is an A-46 plant thus needs only to conduct a "bad actor" relay review (see Reference 30 for list of bad actor relays) if such bad actors were found in the USI A-46 scope of review.

The USI A-46 review found 12 installations of the Westinghouse, Model SC relay in the 4160V switchgear. (Relays in Breakers 502 to 508 and 604 to 609.) The scope of the bad actor review was expanded to include the IPEEE equipment and no additional bad actor relays were identified.

WPS initiated Engineering Support Request (ESR) 94-005 proposing outright replacement of the 12 Westinghouse relays, or alternatively, a reworking of the system circuitry to exclude the Westinghouse relays after the emergency AC power system is initiated. As such, further consideration of the relay capacities in the SPRA model is not required. Details of the recommended solutions will be provided at a later date in the USI A-46 submittal.

# Masonry Block Walls

The availability of recent detailed calculations for masonry block walls developed under the IEB 80-11 program provided a ready reference for the determination of estimated fragilities. Conservatively, the block walls were assigned a HCLPF<sub>84</sub> capacity equal to the design basis peak ground acceleration. This value was then factored in accordance with the guidance in Reference 18 to obtain a median capacity with an associated  $\beta_{\rm C} = 0.46$ .

For the diesel generator day tank enclosures, which are formed with masonry block walls on three sides abutting a rear reinforced concrete wall, a HCLPF<sub>84</sub> value was calculated using the Conservative Deterministic Failure Margin (CDFM) methodology of EPRI NP-6041. The median capacity for this enclosure is 3.22g PGA with a  $\beta_{\rm C} = 0.46$ .

# **Building Structures**

The structures for the Kewaunee site considered in the SPRA are the reactor, auxiliary, and turbine buildings which are all founded on a single shallow mat foundation. The site is underlain by glacial till and lacustrine deposits as discussed in Section 3.1.3.6. These buildings are Category I structures except for the turbine building and the steel frame over the spent fuel handling area in the auxiliary building which are designated as Category III\* structures. Specific areas of the turbine building mezzanine (battery rooms) and Administration building basement (diesel generator rooms) are also classified as Category I. Category III\* indicates that the structure is not directly related to reactor operation or containment; however, it is designed to Class II seismic loads as prescribed by the 1967 Edition of the Uniform Building Code for Zone 1 areas (0.025g for K = 1.0).

All structures are screened using the first column in Table 2-3 in EPRI NP-6041. The screening approach uses the experience gained in performing seismic margin assessments (SMAs) to screen components out of a SPRA. Meeting the caveats for these structures ensures that the structures may be represented by a surrogate element with a median peak 5-percent damped spectral acceleration capacity of 1.2g with a combined logarithmic standard deviation,  $\beta_{C}$ , value of 0.30.

All caveats of Table 2-3 were dispositioned, including: the free standing steel containment's base mat shear keying, separations between structures, reinforcement detailing, and penetrations, including associated requisite piping flexibility. It was found that the steel structure over the spent fuel pool area and the turbine building have been designed to forces corresponding to the DBE ground response spectra (0.12g PGA). As such, they are also screened out of the SPRA.

The structures listed below are represented by the surrogate element in the SPRA with a median peak capacity of 1.2g, 5-percent damped spectral acceleration (which is equivalent to 0.64g PGA) with a composite logarithmic standard deviation,  $\beta_{\rm C}$  value of 0.30.

- Containment vessel (including the internal structures)
- Administration building basement (diesel generator rooms)
- Shield building
- Screenhouse building
- Screenhouse tunnel
- Turbine building mezzanine (battery rooms)
- Technical Support Center (basement)

# Reactor Vessel Internals and Control Rod Drive Housing and Mechanisms

The reactor vesse! internals simplified fragility analysis also applies factoring analysis using the results of the original stress analysis reported in the USAR. All of the vessel internals have median capacities in excess of the surrogate element capacity. Specific components evaluated as listed in the USAR are:

Upper Core Barrel, Upper Core Plate, Rod Control Cluster Guide Tubes, Fuel Assembly Thimbles, Lower Core Barrel, Barrel Flange, Fuel Assembly Top and Bottom Nozzle Plates, Upper Support Columns, Lower Radial Support.

The control rod drive housing has a lateral seismic support (Reference 20) and may thus be screened out and assigned the surrogate element capacity according to Table 2-4 of EPRI NP-6041.

## Soil Failure Analysis and Buried Piping

Soil stability and seismic displacements, both transient and permanent, along with permanent settlements were investigated for the Kewaunee site.

Due to the high factor of safety, the evaluations were conducted at 0.7g PGA using the SHAKE (Reference 21) computer program. The intake and discharge piping were also evaluated for the imposed displacements and settlements at 0.7g PGA.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 96 of 415

## Liquefaction

The results of the liquefaction stability analyses conducted for the power block and for the screenhouse structure give factors of safety equal to 9.1 and 2.0, respectively. These results indicate that a liquefaction instability failure of the critical structures at Kewaunee is very unlikely regardless of the earthquake magnitude or the value of PGA.

In addition, empirical correlations are used to assess the likelihood of significant pore pressure build-up in the soils. The results indicated that the likelihood of 100 % pore pressure development is remote, even for a peak ground acceleration of 0.7g. This is true for both the stiff and very stiff soil properties.

#### Transient and Permanent Horizontal Displacements and Settlements

The maximum transient horizontal displacements calculated at the ground surface for a PGA of 0.7g are 1.2 inches for the stiff soil profile and 0.16 inch for the very stiff soil profile. The differential displacement between a building and the surrounding ground can be conservatively taken to be uniformly distributed over a distance of about 25 feet from the foundation.

The permanent horizontal displacements for a PGA of 0.7g are estimated to be 0.14 inch for the stiff soil profile and about 0.5 inch for the very stiff soil profile. The differential displacement between the screenhouse and the intake crib approximately 1600 feet from the shoreline was evaluated.

The maximum calculated settlements at the ground surface range from 0.75 inch to less than 0.2 inch at 0.7g peak ground acceleration for the stiff and very stiff soil profiles, respectively.

Differential settlements can be expected within the foundation imprint of any one building and within the areas between buildings due to natural variability of the compressibility for the soil deposits. These can be taken equal to 50% of the total settlements and can be taken to occur over a distance of about 25 feet for structures on individual spread footings and for the areas between buildings. For structures founded on a continuous mat foundation, the differential displacement can be taken to occur over a distance of about 50 feet.

Differential settlements can also be expected between any one building and the ground and between adjacent buildings, such as those within the power block, due to the different thicknesses of the soil strata beneath the various structures and beneath the ground surface. Those between a building and the surrounding ground occur over a distance of only a few feet. The distance over which the differential settlements between adjacent buildings occurs is dependent on the interaction of the foundation mat with the foundation soil and can occur abruptly at construction or expansion joints between or within the buildings.

#### Buried Piping From Screenhouse and Intake Crib

The SPRA considers the influence of the displacements and settlements for the fragility analysis of intake and discharge piping from the screenhouse building and intake crib. At the imposed

0.7g PGA, the aforementioned steel and concrete piping do not exceed normal design allowables; thus, the buried piping is screened out of the SPRA and conservatively represented by the surrogate element.

# **Evaluation of Supporting Component Capacities**

# Piping

Piping was reviewed throughout the plant as part of the SPRA walkdown. All safety-related piping was re-evaluated using modern dynamic analysis procedures as part of the IEB 79-14 program. It was verified that no reliance on other than seismically designed piping systems was considered in the SPRA model.

Train A of the Service Water System was walked down from end to end to identify any anomalies as discussed in Section 3.1.3.3 during the first week in April, 1994. No design anomalies were found during this system walkdown.

The piping is represented by the surrogate element in the SPRA with a median peak capacity of 1.2g, 5-percent damped spectral acceleration (which is equivalent to 0.64g PGA) with a composite logarithmic standard deviation of 0.30.

Small bore piping was also reviewed during the walkdowns to consider any interaction effects that could result from such piping, for example, falling (collapsing) on equipment modeled in the SPRA. It was observed that piping supports would support more than three times an estimated dead weight and that support spacing was within two times that recommended by the ASME B.31.1 code for piping. Therefore, this issue is considered resolved and small bore piping may be considered to have the same capacity as the seismically designed large bore piping.

# HVAC

Ducting in all areas of the plant was reviewed with particular attention given to containment systems, and those in the control room and battery rooms. In general, the smaller size ducting is supported by sheet metal straps secured to the ceiling by expansion anchors. Larger duct cross-sections are supported by rod trapeze hangers anchored by Phillips shells. In containment, the ducts are supported off the steel containment shell by braced cantilever brackets. The duct is circular in cross-section and attached to the brackets by large threaded hoops.

The duct is supported in accordance with Sheet Metal and Air Conditioning National Association (SMACNA) (Reference 22) spacing rules, and the anchorage vertical capacities exceed three times dead weight. The ducting is represented by the surrogate element in the SPRA with a median peak capacity of 1.2g, 5-percent damped spectral acceleration (which is equivalent to 0.64g PGA) with a composite logarithmic standard deviation of 0.30.

# Electrical Raceways

The electrical raceways were walked down as part of the USI A-46 effort. All areas of the plant were surveyed and inspected against inclusion rules and caveats for raceways such as maximum spans, missing or broken hardware, and good design practices as presented in the GIP, Section 8. The results are documented in Plant Area Summary Sheets and will be presented at a later date in the USI A-46 submittal. In addition, bounding and representative supports were sclected for structural and seismic evaluations called Limited Analytic Reviews. (LAR). The LAR evaluations check dead load stresses, ductility, and vertical capacity.

No anomalies were found during the plant tour of the raceway systems. The LAR evaluations resulted in no outliers. In conclusion, the electrical raceways are represented by the surrogate element in the SPRA with a median peak capacity of 1.2g, 5-percent damped spectral acceleration (which is equivalent to 0.64g PGA) with a composite logarithmic standard deviation of 0.30.

# Seismically Induced Loss of Coolant Accidents

Figure 3-3 presents the relationship between increasing seismic levels, and the conditional probability of a small and medium break loss of coolant accidents. The data comes directly from NUREG/CR-4840 (Reference 24) and is included in the SPRA model.

# 3.1.4.3 Detailed Fragilities

Residual heat removal (RHR) heat exchanger A and B fragility is 0.63g PGA which is slightly less than the surrogate fragility. All detailed fragilities for other base mounted equipment exceed the surrogate fragility of 0.64g PGA.

Other components that require corrective action are screened at the surrogate level. These components are presented in summary on Table 3-4 and will be presented in detail at a later date in the USI A-46 submittal.

# 3.1.5 Analysis of Plant Systems and Sequences

The analysis of plant systems and sequences section is broken down into four sub-sections and is organized so that each sub-section discusses a step in the quantification process. The four sub-sections are as follows: seismic initiating events, seismic event trees, seismic fault trees, and seismic risk quantification and results including sensitivity analyses.

# 3.1.5.1 Seismically Induced Initiating Event Analysis

NUREG/CR-4840 recommends that the following events establish the basis for the seismic initiating event categories.

- Reactor Vessel Rupture
- LOCAs Large, Medium, and Small
- Transients

In addition NUREG/CR-4840 recommends that any site specific failures that could result in an initiating event should be considered. In order to properly account for all possible site specific initiators the following analysis methodology is employed:

- a. The structures and equipment that should be used to determine the plant status following a seismic event are determined.
- b. Given the failure of each of the items listed in step a, the plant status following a given earthquake is defined. Failures with similar results are grouped together (i.e. components whose failures resulted in a large LOCA are grouped into one "family").
- c. Fragility data representing each component "family" is developed.
- d. An event tree is then developed which contains, as its first node, the Kewaunee site specific seismic hazard analysis. The remaining top event nodes represent the structure and component "families" identified in steps a and b, which were developed to describe the plant status after an earthquake.

The items chosen in step a are plant specific, including major buildings and structures, RCS equipment and supports, switchyard ceramic insulators, and other plant specific items identified during the seismic walkdown. In addition, any other plant specific components the analyst determined to be capable of causing an initiating event are considered.

The structures and equipment that are used to define the seismically induced initiating events for the Kewaunee SPRA include:

<u>Structures</u> - Containment building, turbine building, auxiliary building, screenhouse, technical support center, reactor pressure vessel supports, steam generator supports, pressurizer supports, reactor coolant pump supports, reactor coolant system piping, and secondary piping and supports.

<u>Equipment</u> - Reactor pressure vessel, steam generators, pressurizer, reactor coolant pumps, control rod drive mechanism, and switchyard ceramic insulators.

It should be noted that the above list is not exhaustive, but rather includes a list of equipment and structures that would lead to initiating events considered to be "worst case" events. For example, failure of the containment shell structure is assumed to result in total collapse of the containment in such a way as to rupture the reactor pressure vessel; hence direct core damage with loss of containment is assumed.

From the above identified items, twelve failure groups are defined. The following paragraphs are a compilation and definition of these failure groups. The equipment and/or structures, along with their individual and combined fragilities, considered in these failure nodes are listed in Tables 3-2 and 3-3.

## (1) CONTAINMENT OR STEAM GENERATOR FAILURE - (CSF)

Containment structural failure is assumed to be a function of either the containment rebar or soil pressure fragilities. Failure is assumed to be structural collapse of the containment building. Damage to the RCS and the core cooling systems due to the containment collapse is hypothesized.

Steam generator (SG) integrity is assumed to be a function of the fragility of the SG and its supports. Both SGs are assumed to fail in such a way as to sever both RCS and secondary side piping (outside of containment).

Thus, either of these failures is assumed to cause direct seismically induced core damage with containment breech.

## (2) REACTOR VESSEL, RCS PIPING FAILURE, OR BUILDING FAILURE<sup>c</sup> - (RVB)

This failure is assumed to be a function of the fragility of the reactor pressure vessel (RPV), the RPV supports, the RCS piping, and any building failures that could render systems within the failed building unavailable. RPV or RPV support failure is assumed to lead to a vessel position that could not guarantee core cooling. RCS piping failure is assumed to be double guillotine breaks in all loops at a point that precludes emergency core cooling.

The building failures of major concern are the turbine building, auxiliary building, and the screenhouse. Failure of the screenhouse disables the SW System and thus, all of the systems that the SW System supports would consequently fail. Failure of the turbine and auxiliary buildings are assumed to fail all systems housed within these buildings. Examples of systems that are assumed to fail include the RHR System, diesel generators, AFW System, and it is assumed that this failure mode would sever all wires running through the failed buildings which would result in a loss of all power and indication.

In either case, since the core cooling function is not guaranteed, this failure is conservatively assumed to lead to direct core damage; no direct damage to the containment is assumed.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 101 of 415 (3) OFF-SITE POWER FAILURE - (OSP)

Off-site power availability is assumed to be a function of the switchyard ceramic insulators. Failure of these insulators is assumed to lead to a complete and unrecoverable loss of off-site power. Since the ceramic insulators have a very low seismic tolerance, any seismic activity that generates a seismically induced initiating event, will also result in the failure of the ceramic insulators and thus an unrecoverable loss of off-site power. Any seismic activity that does not cause a failure of the ceramic insulators, is assumed to be of such a small magnitude that it does not generate any other seismic initiating event and is therefore encompassed by the IPE. Therefore, the only structures or components considered in this node are the ceramic insulators. It should be noted that no credit is taken or assumed for off-site power recovery and that there is a strong reliance on the on-site AC Power System and components.

(4) AC POWER (ACP)

This failure is assumed to be a function of the combined fragilities for vital AC Power System components. The components considered include cable trays, switchgear and diesel generators. Equipment related to the diesel generator operation such as fuse panels, control cabinets, sequencer panels, fuel oil day tanks and fuel oil storage tanks were also included.

#### (5) SERVICE WATER SYSTEM (SWS)

This failure is assumed to be a function of the combined fragilities for the SW System. The components considered include air operated valves, check valves, motor control centers, motor valves, piping and pumps.

#### (6) DC POWER (DCP)

This failure is assumed to be a function of the combined fragilities for vital DC Power System components. The components considered include batteries, battery chargers, battery racks, cable trays, motor control centers, distribution cabinets and fuse panels.

#### (7) RCS COMPONENT FAILURE - (RCF)

This failure is assumed to be a function of the pressurizer, the pressurizer supports, the reactor coolant pump and supports. The failure of any of these components is assumed to lead to a large break (Pipe ID > 6") LOCA event. Neither emergency core cooling nor containment cooling functions are compromised as a direct result of these failures.

#### (8) CONTROL ROD INSERTION FAILURE - (ROD)

The ability to insert the control rods is assumed to be a function of the control rod drive mechanism fragility, as well as the fragilities of the reactor core upper internals, and the lower internals i.e., core barrel and thermal shield. All of these seismically induced

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 102 of 415

failures are postulated to fail in such a way as to either disable the control rod drive mechanism, or physically prevent rod insertion.

## (9) MEDIUM PRIMARY PIPE BREAK - (MPB)

This category of initiating events are based on failure of reactor coolant pipes and pipe combinations leading to medium break LOCA ( $3^{"}$  < Pipe ID <  $6^{"}$ ). NUREG/CR-4840 presents a statistical distribution (Figure 3-5), which is used to estimate the medium break LOCA initiating event in the Kewaunee SPRA. The use of this input to the SPRA precludes the need to model a surrogate element for medium breaks.

## (10) SMALL PRIMARY PIPE BREAK - (SPB)

This category of initiating events are based on failure of reactor coolant pipes and pipe combinations leading to small break LOCA (1.5" < Pipe ID < 3"). NUREG/CR-4840 presents a statistical distribution (Figure 3-5), which is used to estimate the small break LOCA initiating event in the Kewaunee SPRA. The use of this input to the SPRA precludes the need to model a surrogate element for small pipe breaks.

## (11) REACTOR COOLANT PUMP SEAL LOCA (SEAL)

Loss of RCS integrity is a functional failure that could result in a loss of coolant accident LOCA. Some of these failures were considered in nodes RVB, RCF, MPB and SPB. A small break LOCA could result from the failure of the RXCP seals. This failure is assumed to be a function of the fragility of the pump seals.

In addition, the RXCPs are assumed to fail in such a way as to damage the seals on both pumps. The resultant leakage is assumed to be equivalent to that required for small LOCA classification.

## (12) SECONDARY SIDE PIPE BREAK - (SSP)

The integrity of the secondary side piping is assumed to be a function of the fragility of the secondary side piping and its supports. Failure is assumed to lead to a steam line or feed line break. It is assumed that both SGs will be affected.

After the above equipment and structures are clearly defined, construction of the SPRA initiating event tree begins. There are several important rules that were followed while creating the SPRA initiating event trees. It is important that a proper hierarchy among the initiating events is developed. The order of the hierarchy is defined such that, if one initiating event occurs, the occurrence of other initiating events further down the hierarchy are of no significance in terms of plant response. Thus, for example, if a large break LOCA occurs, we are not concerned if a small break LOCA or transient occurs as the plant's response requirements are dictated by the need to mitigate the large break LOCA.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 103 of 415

Implicit in the defined hierarchy of the set of initiating events is the requirement that the basic events that define an initiating event cannot occur in the accident sequences corresponding to initiating events lower in the hierarchy. For example, loss of offsite power can occur as a basic event in any of the LOCA sequences, but not vice versa. The hierarchy used in the development of the Kewaunee seismic PRA is presented in Table 3-5.

The SPRA initiating event tree can be found in Figure 3-4. Once the SPRA initiating event tree is completed, the individual sequences of the event tree are then converted into logic equations that represent the seismically induced initiating events. Each end state of this event tree represents an initiating event category. The following five initiating event end states are not resolved at this stage of the quantification. The sequence logic equations that represent these end states are used as the initial input into the sequence analysis as described in Section 3.1.5.2.

- SLSP Loss of Off-site Power
- SSLB Steam Line Break
- SSLO Small LOCA
- SMLO Medium LOCA
- SLLO Large LOCA

There are six end states from the SPRA event tree that are not quantified beyond the SPRA initiating event tree. These end states are:

- CSF Containment or steam generator catastrophic failure
- RVB Reactor vessel or Reactor Coolant System piping or buildings catastrophic failure
- ACP AC power catastrophic failure
- SWS Service Water System catastrophic failure
- DCP DC power catastrophic failure
- RDF Control rod insertion failure

The first end state in the above list represents core damage with a failed containment. Therefore, for this end state there is a direct path for fission products to the atmosphere.

Since it is assumed, in this analysis, that any seismic activity results in an unrecoverable loss of off site power, the endstate STRS is not quantified. The end state STRS represents a transient with off-site power available.

## 3.1.5.2 Seismic Event Tree Analysis

Once the seismic initiators are defined, the seismic event trees are created from the applicable IPE event trees. To take advantage of the work done in the IPE, the foundation for the seismic event trees are the Level 1 IPE event trees. In order to differentiate between the normal and seismic Level 1 IPE event and fault trees, a naming convention for the seismic trees was developed. The seismic event trees are identified by a "S" prefix added to the internal event names, the seismic top event fault trees are identified by a "SX" prefix added to the internal

event name, and the seismic support system fault trees are identified by a "X" suffix added to the internal event names. The "X" suffix is also used to designate internal event fault trees in which it is necessary to add seismic failures. This was due to the fault tree structure or when basic assumptions are different in the SPRA versus the IPE.

Since the seismic failure probability associated with the ceramic insulators is high, all of the event trees are constructed and quantified assuming off-site power is not available. As can be seen in Figure 3-4, the third top event node OSP in the SPRA initiating event tree is the failure of the ceramic insulators. It can also be seen that the only endstate that does not occur after the failure of the ceramic insulators is the first endstate (STRS), which represents a transient initiating event with off-site AC power. Therefore, since this initiating event requires the availability of off-site power it is not included in the seismic analysis.

The second global assumption needed during event tree construction is that the instrument air system is unavailable after a seismic event. Since a portion of the instrument air system is non-seismic class I, the entire instrument air system is assumed to fail during a seismic event. As a result of this assumption, several top event and support systems are removed from the SPRA analysis. The most visible system to be removed, at the sequence level, are the pressurizer PORVs. Therefore, the ability for primary bleed and feed is lost. The steam generator PORVs are not removed from the seismic analysis because they have a seismically qualified air supply. This supply is a seismically qualified accumulator system that is used to actuate the PORVs in a loss of instrument air scenario. Therefore, the steam generator PORVs are available during and after a seismic event to provide secondary depressurization.

The results from the seismic initiating events analysis determine that there are five events that need to be quantified for the seismic analysis. These events included large break LOCA, medium break LOCA, small break LOCA, steam line break, and loss of off-site power.

As a result of the above discussion, it is necessary to make several changes to the Level 1 IPE event trees to transform them into seismic event trees. The following is an event tree by event tree description of the changes:

# • Seismic Large LOCA (SLLO)

The seismic large LOCA (SLLO) event tree is presented on Figure 3-5. The major assumptions included in the IPE event tree are the same for the seismic event tree. As previously discussed, support systems such as AC power, DC power, and SW are removed from the system level analysis and placed into the sequence level analysis as shown on the seismic initiating event tree (Figure 3-6). For the large break LOCA event tree, two other support systems, CCW and the RPS are quantified at the sequence level. It is assumed that the failure of either CCW or RPS leads to core damage.

# • Seismic Medium LOCA (SMLO)

The seismic medium LOCA (SMLO) event tree is presented on Figure 3-6. One major assumption changes as compared to the IPE event tree. Top event OMO is removed. This node represents the Main Feedwater System, which is assumed to be lost as a result of the loss of off-site power due to the seismic initiator. Support system modeling discussed for the large LOCA event tree also applies here. An additional top event (RST) is included and represents the failure of the refueling water storage tank. Failure of RST is assumed to lead to core damage.

## • Seismic Small LOCA (SSLO)

The seismic small LOCA (SSLO) event tree is presented on Figure 3-7. Three major assumptions changed as compared to the IPE event tree.

- 1. Top event OM0 is removed. This node represents the Main Feedwater System, which is assumed to be lost as a result of the loss of off-site power due to the seismic initiator.
- 2. Top event OB1 is removed. This node represents the operator action and the associated hardware necessary for primary bleed and feed. This node was removed because of the loss of instrument air, which is assumed to fail due to the seismic initiator.
- 3. Top event ES1 is removed. This node represents the operator action and the associated hardware necessary to cool down and depressurize the RCS for charging flow. This node like the OB1 node is dependent on instrument air for success and is removed for the same reason.

Support system modeling including the refueling water storage tank (RST) discussed for the medium LOCA event tree also applies here.

## • Seismic Loss of Off Site Power (SLSP)

The loss of off-site power on all SPRA event trees is accounted for in the quantification of the event trees through the choice of mitigating systems. Any system dependent on off-site power was eliminated from the event tree when the seismic event tree logic was constructed. The value for seismic fragility for loss of off-site power is based on values used in recent PRA evaluations based on a discussion with Dr. R. P. Kennedy (Reference 25).

The seismic loss of off site power (SLSP) event tree is presented on Figure 3-8. Two major assumptions change as compared to the IPE event tree.

1. Top event OSP is removed. This node represents the availability of on site power. This is addressed in the seismic initiating event tree node ACP (Figure 3-2).

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 106 of 415

2. Top events OB1 and HR1 are removed. The OB1 node represents the operator action and the associated hardware necessary for primary bleed and feed. This node is removed because of the loss of instrument air, which is assumed to fail due to the seismic event. Node HR1 is only addressed after the success of OB1. Since OB1 is assumed to fail, HR1 does not need to be addressed.

Support system modeling discussed for the large LOCA event tree also apply here.

## • Steam Line Break (SSLB)

The seismic steam line break (SSLB) event tree is presented on Figure 3-9. Two major assumptions changed as compared to the IPE event tree.

- 1. Top events OM1 and OB4 are removed. These nodes are the same as OM0 and OB1 previously described and are removed for the same reasons.
- 2. Top event HR1 is removed. This node represents the high pressure safety injection lined up in the recirculation mode. This node is only addressed after the success of OB4. Since OB4 is assumed to fail, HR1 does not need to be addressed.

Support system modeling discussed for the large LOCA event tree also applies here.

# 3.1.5.3 Seismic Fault Tree Analysis

Once the seismic event trees are developed, the seismic fault trees are created. The seismic fault trees are defined by the seismic event tree top events and those support systems that require a fault tree. Note that some event tree top events do not require a seismic fault tree since the event does not model any components that could fail seismically.

The first step in creating the seismic fault trees is to identify which components are adversely affected by a seismic event. The components expected to experience seismic failures were identified during the seismic walkdown and are discussed in Section 3.1.4. The list of components includes system pumps, tanks, valves and electrical equipment. The components described in Section 3.1.4 are used to construct seismic fault trees for each system of interest.

The selection of components to be modeled is the result of a screening process by which seismically rugged structures and components are screened out. Using this methodology presents a special problem in that all failure modes cannot be accurately defined. To account for these failure modes a surrogate element is modeled. The surrogate element is discussed in Section 3.1.4.1. The surrogate element is intended to represent the conservative capacity for the weakest component screened out. A surrogate element is modeled as a basic event in each system fault tree in series with the cutsets for the top event. The results of a seismic quantification using this methodology are somewhat conservative but has the advantage of providing added flexibility to evaluate sensitivity.

The seismic fault trees are then quantified and linked to the corresponding IPE fault trees (e.g., seismic fault tree SXLR1 is linked to IPE fault tree LR1). By combining these trees together,

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 107 of 415

both seismic and non-seismic failures are considered in the event tree accident sequence quantification. Thus, the IPE fault tree component random failures, human errors, and test and maintenance unavailabilities are all considered in the seismic PRA. The fault trees are quantified in a manner that ensures all seismic events modeled in the SPRA are present in the final cutsets used in sequence quantification. Table 3-6 lists the top events and support systems that require a fault tree.

The seismic fault trees are constructed based upon the following assumptions:

- 1. In order to remove some of the complexity involved with seismic quantification, it is assumed that analogous components in close proximity, simultaneously fail with a probability equal to that of one component. For example, if one pump in a two pump system seismically fails, its redundant partner fails without a decrease in the failure probability. This assumption, which is analogous to using a common cause  $\beta$  factor of 1.0, conservatively removes train redundancy while simplifying the seismic fault trees.
- 2. In an attempt to accurately model operator actions, it is assumed that the probability of the operator failing to perform specific actions is a function of ground motion level. Operator actions are modeled by a non-lognormal fragility curve by which the conditional probability of failure as a function of ground motion level is defined in terms of a discrete function. For low ground motions, up to and including the SSE (0.12g), the operator error rates are assumed to be the same as those used in the IPE. For ground motions greater than the SSE, the operator error rates increase in a linear manner to three times the SSE (0.36g). It is assumed that the operator error rates would increase by a factor of ten at three times the SSE. Operator actions performed at ground motions greater than 0.36g are conservatively assumed to fail (failure probability of 1.0).
- 3. Systems not classified as Seismic Class I are conservatively assumed to fail at any seismic activity level. That is, the failure probability is 1.0. This assumption applies to the loss of the station and instrument air system, which in turn removes all pressurizer PORVs and therefore, the possibility for bleed and feed operations. Like the Station and Instrument Air System, the Feedwater and Condensate Systems are also not Seismic Class I. Because of this assumption, it is convenient to remove top events that either rely on instrument air or whose success is dependent upon the success of a previous event that depends on instrument air.

The SW and AFW Systems rely on instrument air. However, the AFW air operated valves fail to a predetermined position upon loss of instrument air to permit continued operation. The SW System needs instrument air for automatic backwashing of traveling screens and pump strainers. This failure is not however, a major contributor to system unavailability and these components are addressed in the seismic quantification. Thus, failure of the station and instrument air system does not directly fail the SW and AFW Systems.

4. The condensate storage tank (CST), which supplies water to the AFW pumps, is not classified as Seismic Class I and is assumed to fail at any seismic activity level. The CST is therefore removed from the AFW fault trees. With the failure of the CST, the operators

are required to transfer over to the SW System as the source of water to the AFW pumps. This operator action was modeled consistent with assumption 2 above.

- 5. It is assumed that failure of plant structures destroys everything within the structure confines. The electrical wires that run through structure walls are also sheared. Each structure failure is assumed to be independent of other structure failures.
- 6. Failure of off site power is assumed to have a duration of 24 hours. Thus, the diesel generators have a defined mission time of 24 hours.
- 7. Seismic failure of the pressurizer safety valves is not modeled since these valves are normally closed and it is expected that they would fail closed due to seismic activity.

## 3.1.5.4 Seismic Risk Quantification and Results

This section describes the procedure used to perform the seismic risk quantification and presents the results of the Kewaunee SPRA and the findings of sensitivity analyses that were performed.

## Quantification Procedure

The Kewaunee SPRA is quantified using the SHIP code. SHIP was developed by Jack R. Benjamin and Associates, Inc. specifically to perform the computations required to estimate seismic risk.

Input to SHIP includes:

- discretized seismic hazard at a site (i.e., annual probability of exceeding specified levels of ground motion),
- component (e.g., structure or equipment item) fragility data defined in terms of the median capacity and logarithmic standard deviation, which are used in SHIP to define a lognormal fragility curve,
- component random failure probabilities,
- operator error probabilities, and
- seismic system logic model.

The seismic system logic model is input to SHIP in the form of:

- event tree sequence logic, and/or
- fault tree cutsets.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 109 of 415

The seismic event tree is input for each sequence in terms of the combination of top event failures and successes. System fault trees are input to SHIP by means of the cutset files produced by the Westinghouse system analysis software, WLINK (Reference 26), which was also used in the IPE. In the Kewaunee SPRA, SHIP perform, the seismic risk quantification in three steps.

- 1. Systems Evaluation For each top event in the seismic event trees, SHIP evaluates the corresponding fault tree<sup>1</sup> to determine the conditional probability of the top event over a specified range of ground motions. To solve for the conditional probability of the top event (for each PGA interval), SHIP uses the SIGPI algorithm (Reference 27). SHIP combines individual component conditional failure probabilities, according to the system logic, to determine the system level conditional probability of failure (fragility). This evaluation is repeated for each ground motion interval to produce a fragility curve for each system or top event.
- 2. Event Tree Quantification In this step, sequence level fragility curves are computed. For each accident sequence defined in the seismic event tree, SHIP combines the top event failures and successes according to the sequence logic. This evaluation is performed for each ground motion interval to produce a sequence level fragility curve. The set of sequence level fragility curves is combined to produce the plant level or core damage fragility. The plant fragility curve has the same characteristic shape as the fragility curve for a component.
- 3. Risk Quantification The seismic core damage frequency (CDF) is estimated by combining the plant level fragility with the mean seismic hazard curve for the site. In addition, the frequency of each accident sequence is also estimated by combining the site hazard curve with the sequence fragility.

Figure 3-10 shows the input and output involved in a SHIP application.

### Quantification Results

The Kewaunee SPRA is quantified by evaluating the 47 sequences defined in the seismic event trees (Figures 3-4 through 3-9). Table 3-7 presents the results of the Kewaunee SPRA in terms of the mean CDF, the plant median capacity and HCLPF level. The Kewaunee plant fragility provides a measure of the seismic capacity of the plant in terms of the level of earthquake loading. It is a composite measure of seismic integrity, accounting for the seismic design of structures and equipment, redundancy in the plant safety system design, and the role of operators in mitigating an accident. In the following, the SPRA fragility and CDF results are discussed.

<sup>&</sup>lt;sup>1</sup>Note in some cases a top event in the event tree may be a single basic event.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 110 of 415

## Kewaunee Fragility Results

The seismic capacity of the plant is presented in terms of the:

- plant-level fragility,
- sequence fragility curves, and
- system (or top event) fragility curves.

**Plant Fragility** - Figure 3-11 shows the Kewaunee plant fragility curve. The plant fragility is derived from a quantification of the seismic systems logic model, component seismic fragility data, random failure probabilities, and operator error probabilities. As indicated in Figure 3-11, the median capacity of the plant is 0.38g PGA, which is approximately a factor of three times the Safe Shutdown Earthquake level of 0.12g.

In the Kewaunee SPRA, the mean plant fragility is calculated. Although an uncertainty analysis is not performed, an estimate of the plant HCLPF can be made. Assuming the plant fragility curve is lognormally distributed, the HCLPF corresponds to the ground motion that has a 0.01 conditional probability of failure. (Note, if a full uncertainty analysis was performed, the HCLPF would correspond to the ground motion level for which there is 95 percent confidence that the probability of failure is 0.05 or lower.) Table 3-8 summarizes the plant level fragility at various failure fractions. For Kewaunee the HCLPF is 0.23g. As discussed below, this is a conservative estimate of the HCLPF, due to the fact that the plant fragility includes the effects of random (non-seismic) failures and operator actions.

The purpose of a HCLPF is to provide a measure of the seismic structural integrity of structures and equipment items. As noted in NUREG-1407, the plant HCLPF determined in a SPRA is different from the result that would be obtained in a seismic margin assessment (SMA). In the SPRA, random failures and operator actions are included in the quantification of the plant systems. The contribution of these basic events to the plant fragility is greatest at low ground motions where the conditional probabilities of failure are small ( in the lower tail of the fragility curve). Therefore, with the addition of random failures and operator errors, the likelihood of failure at low ground motions is higher. As a result, the conditional probability of failure of 0.01 is reached at a ground motion that is lower than it would otherwise be if only seismic failures were considered. In order to determine a measure of the plant HCLPF based only on the seismic structural integrity of the plant, the random failures and operator actions should be removed from the model. In the Sensitivity Analysis section, the sensitivity of the plant HCLPF to the random failures and operator errors is considered.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 111 of 415

Sequence Fragility - Figure 3-12 shows the plant fragility with the sequence level fragility curves for the dominant seismic sequences. Figure 3-13 shows the fragility curves for the remaining sequences in the seismic event trees. Based on their contribution to the plant fragility, the following seismic sequences are the primary contributors:

- Failure of the containment structure or the steam generator (SCSF)
- Failure of the emergency AC power system (SACP)
- Failure of the screenhouse, the auxiliary building, turbine building or the reactor vessel (SRVB)
- Failure of the Service Water System (SSWS)
- Loss of off-site power (SLSP01)
- Failure of emergency DC power system (SDCP)

The sequence fragility curves initially increase and then fall off with increasing ground motion. This is due to the combination of system (top event) failures and successes that are involved in a sequence. With increasing ground motion, the probability of a system not failing (success) decreases from a conditional probability of 1.0 at low ground motions to 0 at high ground motions.

System (Top Event) Fragility - The fragility of individual plant systems or top events are presented in terms of system level fragility curves. The following lists the figures and system/top event fragility curves that are presented:

### Figure No.

## Systems/Top Events

- 3-14 Charging System (SXCHG), Reactor Protection System (SXRPS), Steam Line Isolation (SXIS1) Auxiliary Feedwater System (SXAF1, SXAF3), Service Water System (SXSWS)
- 3-15 Low Pressure Recirculation (SXLR1, SXLR2, SXLR4), Low Pressure Injection (SXL11, SXL12,) High Pressure Injection (SXH10, SXH12, SXH13), Component Cooling Water (SXCCW)
- 3-16 Accumulator Injection (SXACC), Emergency AC Power (SXACP), Cool Down and Depressurization (SXOP1, SXOP2)
- 3-17 Reactor Vessel and Buildings (SXRVB), Medium Pipe Break (MPB), Control Rod (SYROD), Small Pipe Break (SPB), Secondary System Pipe Break (SYSSP), DC Power (SXDCP).

The fragility curves in Figures 3-14 through 3-17 can be used to make comparisons of the seismic  $ca_i$  city of individual systems (top events).

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 112 of 415

Based on a review of the system fragility curves, the following systems (top events) are ranked by their contribution to the plant fragility.

- Low pressure recirculation (SXLR1, SXLR2, SXLR4)
- Low pressure safety injection (SXL12)
- Auxiliary Feedwater System (SXAF1, SXAF3)
- Charging System (SXCHG)
- Cooldown and depressurization (SXOP1, SXOP2)
- Service Water System (SXSWS)

There are a number of systems whose median capacity is determined by the capacity of the surrogate component as indicated by the group of fragility curves whose median is 0.64g.

**Dominant Events** - The following are the dominant basic events/component failures that contribute to seismic risk:

- Loss of off-site power,
- Surrogate component in the following systems: CSF, RVB, SWS, DCP and ACP,
- Operator Error failure to shift AFW pumps from CST to SWS.

Kewaunee Seismic Cere Damage Frequency Results - All sequences in the Kewaunee SPRA have been quantified. Table 3-9 lists in rank order, the CDF for each seismic sequence and their total. Approximately 93 percent of the CDF is determined by 6 accident sequences. Figure 3-18 shows the contribution of individual accident sequences to the plant seismic CDF. Table 3-10 summarizes for the dominant sequences the system failures and the important basic events in these sequences. A discussion of the dominant sequences is provided below.

Sequence SCSF - This sequence corresponds to failure of the containment structure or the SG. Failure of either of these components leads directly to core damage. These structures were screened using the first column in EPRI NP-6041, which corresponds approximately to a PGA HCLPF level of 0.30g. As a result, these structures are modeled by the surrogate component. The seismic CDF associated with this sequence is 3.6E-06 per year. This is conservative, since the surrogate component is a conservative representation of the capacity of components at the Kewaunee plant.

Sequence SSWS - This sequence corresponds to failure of the SW System. Failure of the SW System is dominated by failure of the intake structure, which is modeled using the surrogate component. The intake structure was screened based on a HCLPF level of 0.30g. All other components in the SW System have median capacities of 0.66g PGA or greater. The seismic

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 113 of 415

risk associated with failure of the SW System is 1.99E-06 per year which is conservative, since the capacity of the SW System is dominated by the surrogate component.

Sequence SRVB - This sequence corresponds to failure of the screenhouse, the auxiliary building, turbine building or the reactor vessel. Failure of any of these components is assumed to lead directly to core damage. These structures were screened using the middle column in EPRI NP-6041, which corresponds approximately to a PGA HCLPF level of 0.30g.

As a result, these structures are modeled by the surrogate component. The seismic risk associated with this sequence is 1.74E-06 per year. This is conservative, since the surrogate component is a conservative representation of the capacity of the structures at the Kewaunee plant.

Sequence SLSP01 - This sequence corresponds to the loss of off-site power and failure of the AFW System. Failure of the AFW System is attributed to failure of the operator to shift AFW pumps from the CST to SWS and failure of the surrogate element. The seismic risk associated with this sequence is 1.35E-06 per year.

Sequence SACP - This sequence corresponds to failure of emergency AC power system, including the diesel generators, and supporting mechanical and electrical equipment. All components in the AC power system have median capacities of 1.86g PGA or greater. As a result, failure of AC power is dominated by failure of the surrogate component. The seismic risk associated with failure of the AC power system is 1.26E-06 per year. This is conservative, since the system capacity is dominated by the surrogate element.

Sequence SDCP - This sequence corresponds to failure of DC power system, including failure of the station batteries, battery chargers, cable trays and electrical support equipment. All components in the DC power system have median capacities of 1.10g PGA or greater. As a result, failure of DC power is dominated by failure of the surrogate component. The seismic risk associated with failure of the DC power system is 3.48E-07 per year. This is conservative, since the system capacity is dominated by the surrogate element.

In the Kewaunee SPRA, small, medium and large LOCA events are modeled. As part of the Kewaunee SPRA, reactor vessel failure and seismically initiated small, medium and large LOCA events are considered. The frequency of these events is:

LOCA	Frequency
Small	2.23E-07/yr
Medium	7.68E-09/yr
Large	1.77E-07/yr
Reactor Vessel	1.74E-06/yr

**Contribution of Ground Motions to Plant Risk** - Figure 3-19 shows the relative contribution of PGA intervals to the seismic CDF. Approximately 76 percent of the CDF is contributed by PGA values in the range 0.25g to 0.65g.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 114 of 415

## Sensitivity Analysis

This section presents sensitivity analyses that were performed to examine the importance of individual factors to the Kewaunee SPRA results. The results of the Kewaunee SPRA, described in the previous section, are referred to as the Base Case. The results of the sensitivity evaluation are summarized in Table 3-11. The following sensitivity cases are evaluated:

No.	Case	Description
1	Seismic Hazard Input	The Lawrence Livermore National Laboratory (LLNL) mean seismic hazard curves are used to estimate the seismic CDF.
2	Non-Seismic (Random) Failures and Operator Errors	<ul> <li>The purpose of this sensitivity evaluation is:</li> <li>1) assess the significance of non-seismic (random) failures and operator actions in the SPRA,</li> <li>2) determine the plant HCLPF based on the seismic capacity of structures and equipment.</li> </ul>
3	Non-Seismic (Random) Failures	The purpose of this sensitivity evaluation is to assess the significance of random failures in the SPRA independent of other failures.
4	Operator Errors	The purpose of this sensitivity evaluation is to assess the significance of operator actions in the SPRA independent of other failures.
5	Surrogate Component	The contribution of the surrogate component to plant risk is determined by increasing the median capacity of the surrogate to 2.0g.
6	Operator action - Shift AFW from CST to SWS	The contribution of this operator action to plant risk is determined by assuming that this action is successful.
7	Seismic failure of SW System screens	The contribution of this component to plant risk is determined by increasing the medium capacity for the SW System screens to 3.0g.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 115 of 415

**Case 1:** Seismic Hazard Input - To consider the sensitivity of the risk results to the seismic hazard input, the mean LLNL PGA hazard curves are used. The purpose of this evaluation is to assess the sensitivity of the ranking of the seismic sequences and their relative importance to plant risk. Since the LLNL mean PGA hazard curves are higher, as compared to the EPRI hazard, the seismic CDF based on the LLNL hazard is higher (1.15E-05). However, since the shape of the EPRI and LLNL mean PGA hazard results are not significantly different, the ranking of seismic sequences and the importance of individual components is the same.

There is one major difference between the EPRI and the LLNL hazard curves that needs to be addressed. The CDF estimate using the EPRI curve (Figure 3-1) considers ground motion up to 1.6g PGA whereas the LLNL hazard input (Figure 3-2) examines ground motion up to 1.0g PGA. The error induced by not specifically examining the effect of ground motion greater than 1.0g PGA would result in an estimated CDF of 1.32E-05, a 15% increase.

Case 2: Random (Non-Seismic) Failures and Operator Errors - This case examines the contribution of non-seismic failures and operator errors to the assessment of the seismic structural integrity of the plant and the CDF. To do this the random failure and operator error probabilities are set to 0.0. By eliminating these basic events, an estimate of the plant HCLPF based on the seismic integrity of structures and equipment is determined.

Figure 3-20 shows the plant level fragility curves for the Base Case and this case. In this case the plant HCLPF has increased to 0.26g, a relatively small change. This is attributed to the fact that random failures and operator errors contribute very little to the plant level fragility at ground motions less than 0.30g. There is a 10% change in the plant median capacity, from 0.38 to 0.43g PGA. This sensitivity evaluation also resulted in a reordering of sequences. The CDF for sequences SLSP01 and SACP decreases by 81% and 31%, respectively.

The CDF based on scismic failures is 9.27E-06. From this it is concluded that the random failures and operator error events in the SPRA make a 16% contribution to the plant CDF. The major contributor is the operator action to align SW System to the AFW pumps.

Case 3: Random (Non-Seismic) Failures - In this case two calculations are made to examine the contribution of non-seismic failures. The random failure probabilities are increased and then reduced by an order of magnitude (an overall change of a factor of 100). In the first calculation, when the random failure probabilities are increased by an order of magnitude, the CDF has increased by approximately a factor of 2 and the plant median capacity has decreased to 0.35g from 0.38g. By increasing the random failure probabilities by an order of magnitude, the HCLPF hs decreased to 0.10g. With the increase in the random failure probabilities, the HCLPF probability level of 0.01 is reached at a much lower ground motion level.

In the second calculation in this case in which the random failure probabilities are reduced by an order of magnitude, there is very little difference when compared to the base case. The CDF is reduced to 1.06E-05 from 1.10E-05 and the median capacity is unchanged. As a result of the lower random failure probabilities, the HCLPF increases slightly to 0.25g.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 116 of 415

**Case 4: Operator Errors** - This case examines the contribution of operator errors to the seismic CDF. Two sets of calculations are performed in which the operator error probabilities are increased and then reduced by an order of magnitude (an overall change of a factor of 100). This adjustment applies to ground motions less than 0.36g. The results are nearly the same in both cases. When the operator error probabilities are decreased by one order of magnitude, the CDF, plant median capacity and HCLPF have not changed from the base case. Increasing the operator error probabilities by one order of magnitude results in a slightly higher CDF (5%), and a HCLPF that has reduced to 0.20g. The results of these sensitivity evaluations indicate the seismic risk results are relatively insensitive to the operator error probabilities.

**Case 5:** Surrogate Component - As described in Section 3.1.4, the surrogate component is used to model components in the plant that have been screened out. The parameters of the surrogate component, the median capacity and logarithmic standard deviation, are conservatively defined to represent those components not explicitly included in the SPRA. This sensitivity analysis considers the dependence of the SPRA results on the parameters of the surrogate components.

The median capacity of 0.64g PGA for the surrogate component is based on the use of the middle column in the EPRI seismic margins report, NP-6041. Using the middle column, components are screened out that have a HCLPF greater than approximately 0.30g PGA.

In this sensitivity analysis, the median capacity of the surrogate is set to 2.0g, making the surrogate a much stronger component and thus less likely to fail. Figure 3-21 shows a comparison of the Base Case plant level fragility and the plant fragility assuming the higher capacity for the surrogate component.

Given the higher median capacity for the surrogate, the CDF is 9.66E-06. However, the plant median capacity has remained at 0.38g. As described in Section 3.1.4, the parameters of the surrogate component are conservative. In addition, the use of the surrogate component on a system specific basis is an additional conservatism. The results of the Base Case and the sensitivity evaluation provide a bound on the SPRA results that accounts for the approach used to screen components.

Case 6: Operator Action to Transfer AFW from the CST to the SW System - In the event that the CST fails, the operator must transfer to the SW System as the source of water for the AFW pumps. To examine the importance of this operator action, the corresponding error probability is set to 0.0. The CDF is 9.95E-06 which represents a 9.5% reduction. There is a 10% change in the plant median capacity, from 0.38 to 0.42g PGA and the HCLPF is unchanged.

**Case 7:** SW System Screens - In the base case, failure of the SW System contributes 18% to the total seismic CDF In this case, the median capacity of the SW System screens is increased to 3.0g. The CDF is 1.07E-05 which represents a 3% reduction and the plant median capacity remains at 0.38g PGA The relatively small change in the CDF suggests that failure of the SW System may occur as a result of failure of one or more other components.

## Summary

This section summarizes the results of the Kewaunee SPRA. The seismic CDF is 1.10E-05 which is considerably less than the internal events CDF (8.74E-05). The median capacity of the plant is 0.38g PGA, which is greater than a factor three times the SSE. The HCLPF for Kewaune is 0.26g PGA or approximately two times the SSE. The HCLPF is based on an evaluation of seismic systems model for seismic failures only.

Based on sensitivity evaluations and a review of the SPRA results, the following conclusions are made:

- 1. There does not exist a single failure mode for Kewaunee that dominates the seismic CDF.
- 2. Failure of a surrogate component, which is a conservative measure of the capacity of components that were screened out, is for many systems the important mode of failure. Since the surrogate does not specifically model the failure of a particular component, this observation is a further reinforcement of the conclusion that there does not exist any component specific failure modes that dominate the seismic CDF.
- 3. Operator actions are not a major contributor to the seismic CDF or plant capacity.
- 4. Loss of off-site power is an important contributor to the seismic risk.
- 5. As a group random failures and operator actions are an important part of the seismic CDF. In a relative sense, variation in the random failure probabilities produced the largest change in the seismic CDF (a range corresponding to a factor of 2.5).

## 3.1.6 Analysis of Containment Performance

As stated in NUREG-1407, the purpose of this evaluation is to identify vulnerabilities that involve early failure of containment functions. The following sub-sections present the details of the evaluations that were performed including the results.

### 3.1.6.1 Basis for Analysis Scope

The scope of this analysis is based upon a review of the Level 2 analysis that was performed for the IPE as well as the specific issues presented in Section 3.2.6 of NUREG-1407.

### 3.1.6.2 Containment Structure and Components

The plant walkdown included a review of all penetrations and hatches, all isolation valves, the free standing steel containment, and the piping and conduit flexibility between the concrete containment wall and steel shell as well as either side of wall and shell and found everything to be within the screening criteria. Thus, all were assigned the surrogate element value for the analysis of containment performance.

## 3.1.6.3 Containment Safeguard Systems

## A. Containment Safeguard Systems Included in the SPRA

The systems evaluated in the IPE and the IPEEE that are classified as containment safeguard systems (CSG) are described as follows.

#### 1. Internal Containment Spray

The Internal Containment Spray (ICS) System is designed to spray cool water into the containment atmosphere following a design basis accident (DBA). The spray provides sufficient heat removal capability to maintain the post-accident containment pressure below its design value. In addition, the spray is effective in scrubbing fission products from the containment atmosphere. Sodium Hydroxide (NaOH) is added to the spray solution for pH adjustment. The resulting alkaline pH of the spray fluid enhances its ability to scavenge iodine fission products from the containment atmosphere and precludes the possibility of stress corrosion cracking of the stainless steel components that are exposed to the containment sump fluid.

#### 2. Containment Air Cooling

The Containment Air Cooling (CAC) System is a subsystem of the Reactor Building Ventilation (RBV) System. The RBV System consists of several subsystems that operate together to cool and circulate containment air during all modes of plant operation; provide containment purge and vent capabilities; provide containment vacuum protection and post-LOCA hydrogen control.

During normal plant operation the CAC System provides the majority of air cooling and circulation in order to maintain containment air temperatures below 120°F. Post-LOCA, the CAC System is designed to remove sufficient heat from the containment vessel, following the initial pressure transient, to keep containment pressure from exceeding the design value of 46 psig at 268°F (100% relative humidity).

#### 3. Containment Isolation

The design of Kewaunee includes three barriers to prevent the release of fission products to the environment: the fuel rod cladding, the Reactor Coolant System, and the containment. The capability of the containment to provide third barrier protection in the event of an accident in which one or both of the other two barriers is not maintained requires that containment integrity be established and maintained so as to limit the leakage of fission products to a low value.

Any flow of fluids that may contain fission products from the containment following an accident may be from one of the two sources: leakage from the containment structure and leakage through containment penetrations. The function of the Containment Isolation (CI) System is to provide for the automatic isolation of all fluid lines not required for accident mitigation.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 119 of 415 **B. Systems Analysis**

The containment safeguard systems were included in the plant walkdowns described in Section 3.1.2.3. The components associated with these systems were evaluated and specific fragilities assigned as described in Section 3.2.4.

Seismic fault trees for the containment safeguard systems are developed and quantified in the same manner as described in Section 3.1.5. These fault trees are as follows.

SXICS -	Internal Containment Spray
SXFCH -	Containment Air Cooling
SXCI -	Containment Isolation

#### C. Analysis of Specific Issues

#### Backup Air Systems

The containment, containment penetrations and the containment safeguard systems do not rely or any backup air systems for proper operation. Also a key assumption in the SPRA, which is presented in Section 3.1.5.3, is that the Station and Instrument Air System (IAS), which is not classified as Seismic Class I, is assumed to fail at any seismic level. Loss of IAS causes all air operated valves in the CSG systems to fail in the safe position.

#### **Relay Chatter**

A relay evaluation was performed based on the guidance provided in NUREG-1407. The evaluation included relays associated with the actuation signals for the CSG systems and the emergency core cooling systems. The results of this evaluation are presented in Section 3.1.4.

#### 3.1.6.4 Quantification and Results

This section describes the procedure used to perform the seismic Level 2 risk quantification and presents the results of the Kewaunee Level 2 SPRA.

#### Quantification Procedure

The same procedure is used for Level 1 and Level 2 analysis. The Level 1 procedure is described in Section 3.1.5.4. Of the 47 sequences defined in the seismic event trees (Figures 3-4 through 3.9), those with frequencies greater than 1.0E-07 are quantified in the Level 2 portion. These sequences represent over 96% of the total seismic core damage frequency.

For each of these sequences, the availability of the containment safeguards systems discussed in Section 3.1.6.3 is determined. In addition, availability of low pressure recirculation is also considered. In some cases, such as loss of AC power, one or more containment safeguards systems is considered unavailable due to failure of support systems. For the containment structure failure sequence (SCSF<sub>1</sub>, containment safeguards are not considered at all. All other Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 120 of 415

sequences are divided into several sequences based on containment safeguards system availability. This is the same method that was employed in the IPE and is presented in Section 4 of the IPE submittal (Reference 2).

Since each sequence corresponds to an IPE sequence, the containment analysis developed for the IPE is assumed to be applicable to the seismic analysis. The only exception to this is the SCSF sequence, which is considered a worst case containment failure, i.e., greater than 10% of volatile fission products released. The frequencies of each containment event tree end state are presented in Table 3-12. As in the IPE, a 48 hour mission time is used.

### Quantification Results

System Fragilities - The fragility of the individual containment systems are presented in terms of system level fragility curves. The CSG systems, Containment Isolation (SXCI), Containment Air Cooling (SXFCH) and Internal Containment Spray (SXICS) are presented on Figure 3-22.

Table 3-13 shows the frequency of each release category due to seismic events. The seismic containment failure frequency is 6.24E-06 which is about the same as the containment failure frequency due to internal events (8.03E-06). The seismic containment failure frequency is 57% of the seismic core damage frequency. The containment failure median capacity and HCLPF for Kewaunee are 0.51 and 0.30g PGA, respectively. The median capacity is about four times the SSE and the HCLPF is two and a half times the SSE. The HCLPF is based on an evaluation of the seismic containment systems model that considers both random and seismic failures. No additional Level 2 vulnerabilities were discovered.

### 3.1.6.5 Containment Analysis Summary

The results of the evaluations performed indicated that the containment as well as the systems designed to ensure containment integrity are seismically sound and no vulnerabilities could be identified.

### 3.2 USI A-45, GI-131, and Other Seismic Safety Issues

### GI-131 Flux Mapping Cart

This generic issue deals with mobile flux mapping carts designed by Westinghouse Electric Corporation that could roll off their guide rails during a seismic event. This issue is not directly applicable to Kewaunee. Although the cart is a Westinghouse design, it is not a moveable table as discussed in GI-131. The so-called ten path flux mapping frame at Kewaunee is stationary. As part of the issue, the lateral seismic capability of the ten path frame was investigated to ensure it could withstand seismic forces without lateral restraints. The dynamic analysis shows that the frame would easily sustain seismic forces without the aid of lateral restraints. This issue is thus considered resolved.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 121 of 415 An overhead I-beam rail supporting a chain-fall is located directly above the 10-path assembly. The I-beam is cantilevered by a hinged support from a concrete wall. Administrative controls were implemented to restrain the hoist at the fixed end of the crane rail when not in use. This eliminates any interaction hazards to the ten path assembly.

## Charleston Earthquake Issue

The NRC states in Generic Letter 88-20, supplement 4 that the Charleston Earthquake issue is subsumed in the IPEEE. WPSC has performed a seismic PRA for Kewaunee using the current LLNL and EPRI seismic hazard estimates. WPSC considers that it has fulfilled the requirements for this issue.

## USI A-45 Shutdown Decay Heat Removal Requirements

Generic Letter 88-20, discusses resolution of USI A-45, "Shutdown Decay Heat Removal Requirements." The IPE submittal for Kewaunee (Reference 2) indicates that a complete evaluation of the decay heat removal capability as well as the possible resolution of the USI A-45 will be considered as part of the IPE for external events. This section outlines the analysis of the Kewaunee decay heat removal (DHR) capability, as required by the generic letter.

The Kewaunee IPE and IPEEE are an integrated look at core damage risk from all internal and external events including loss of decay heat removal. These examinations use a systematic approach to evaluate plant systems and components looking for vulnerabilities to severe accidents. Inherent to this approach is an evaluation of the potential for loss of decay heat removal capability.

NUREG-1289, "Unresolved Safety Issue A-45, Shutdown Decay Heat Removal Requirements," Section 1.1, lists two criteria that must be met by systems used to remove decay heat. These criteria are (1) to maintain sufficient water inventory in the RCS to ensue adequate cooling of the fuel and (2) to provide the means for transferring decay heat from the RCS to an ultimate heat sink.

Systems Available for Decay Heat Removal

There are four possible methods by which decay heat can be removed from the reactor core:

- Secondary cooling through the steam generators with main feedwater or auxiliary feedwater providing the steam generator makeup.
- Bleed and feed cooling using the high-head SI pumps and pressurizer PORVs.
- ECCS injection and recirculation as provided by the SI and RHR Systems.
- Shutdown cooling mode of RHR operation after the RCS has been cooled down and depressurized to RHR conditions.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 122 of 415

## 1. Secondary Cooling

Heat removal through the steam generators is the primary and preferred method of removing decay heat until the RHR System is placed in service. Effective heat removal using the steam generators requires circulation of primary coolant through the core with energy removal from the steam generators by use of steam relief to the condenser or atmosphere and steam generator makeup. Steam relief is not generally modeled for Kewaunee because of the many diverse means of steam removal. Following a reactor trip, steam is relieved to the condenser through four air-operated relief valves or to the atmosphere through four air-operated valves. If the MSIVs should fail closed, steam relief is possible through an air-operated POR' for each steam generator or through five safety valves on each steam generator, all of which are upstream of the MSIVs. In the event of loss of air, DC control power or instrument power, steam relief is assured through the five safety valves for each steam generator as they are not dependent on any support systems. With these many and diverse means of steam relief, it is assumed that the main reason for loss of steam generator cooling would be through loss of makeup capability. Two means of makeup to the steam generators were modeled: auxiliary feedwater (AFW) and main feedwater (MFW). A description of both of these systems follows:

#### Auxiliary Feedwater System

The AFW System consists of three completely redundant trains, each capable of feeding both steam generators. One train consists of a turbine-driven pump and the other two trains each consist of a motor-driven pump. Any one of the three pumps can supply adequate flow to meet the decay heat removal needs following any transient event. The normal water supply to the AFW System is the condensate storage tanks. These are backed up by the Service Water (SW) System. Valves in the AFW flow paths that have the potential to reduce AFW flow have their positions administratively controlled to prevent inadvertent valve misalignments after system maintenance.

Failure of the AFW pumps to start and run is minimized by ensuring the reliability of the pump driver. The off-site power supplies to the motor-driven pumps are backed up by emergency diesel generators to ensure reliability. The steam supply to the turbine-driven pump is from the Main Steam System upstream of the MSIVs. The motor valves on the steam supply lines are normally open and have indication in the control room that would alert the operators if the valves were misaligned. The steam supply valve that isolates steam from the turbine-driven AFW pump is a motor operated valve powered from the station battery and is not dependent on AC power.

Kewaunee performed a reliability study using PRA techniques to identify potential improvements to the AFW System. The study, completed in October 1987, had several recommendations that were implemented and increased the reliability of the system. This included an increased awareness of the importance of the AFW System resulting in additional improvements to maximize system availability.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 123 of 415

The following is a discussion of the major contributors to the AFW System reliability as derived from the IPE fault trees.

Initiating Event	AFW Failure Probability
Transients and LOCAs	2.7E-04
Tube rupture/steam line break	4.4E-03
Station blackout	1.1E-01

The failure probability of the AFW System varies for the spectrum of initiating events. Its support systems include only AC and DC power with SW providing a backup suction source in the event the condensate storage tanks are depleted. In the event that a station blackout occurs causing loss of the motor-driven AFW pumps, the turbine-driven pump is the only means for feedwater addition to the steam generators. The turbine-driven AFW pump is not dependent on AC power, as the steam admission valve to the pump requires DC power.

Important Hardware Failures:

- Random failure of turbine-driven AFW pump to run.
- Random failure of motor-driven AFW pumps to run.

Random failures of the turbine-driven auxiliary feedwater pump to run appear in a large portion of the results. Even through it is not dependent on AC power, the turbine-driven pump is not as reliable as the motor-driven pumps. Common cause events between the AFW pumps are not large contributors because of the diversity of the AFW pump drivers, one turbine-driven and two motor-driven pumps, and the redundancy provided by three pumps, all of which must fail to disable the AFW System.

Valve failures are not large contributors to the AFW System failure as the only valve required to change state is the steam admission valve to the turbine-driven AFW pump. All other valves required for system operation are in their required positions during normal operations or fail in their required positions on loss of support system.

Important Operator Actions:

In a station blackout or loss of instrument air, it is necessary to manually isolate the line connecting the condensate storage tanks and the condenser in order to prevent the draining of the condensate storage tanks. This is a very conservative assumption because a recent study shows that this draining is a very slow process, and the operator has ample warning before the tanks are drained.

## Main Feedwater System

The MFW System is the primary source of makeup to the steam generator during normal operation. Following a reactor trip, feedwater is automatically isolated to the steam generators in order to prevent a rapid RCS cooldown. Feedwater can be easily recovered from the control room for initiating events that do not generate an SI signal by opening the feedwater regulating bypass valves. If an SI signal has been generated, MFW restoration is somewhat more complicated in that the MFW pumps must be restarted, the SI, containment isolation and feedwater isolation signals must be reset, the MFW containment isolation valves must be opened and the MFW bypass valves must then be opened.

The MFW System consists of two redundant pumps that can supply feedwater to both steam generators. Each pump is capable of supplying all of the necessary flow to remove decay heat after any transient event. The pump suction is supplied from the Condensate System. The discharge of the pumps is cross-connected and then flows through two parallel feedwater heater trains. The flow is again combined before it is split to flow through the feedwater regulating valves to the steam generators.

Initiating Event MFW Failure Probabi	
Transients	2.8E-03
LOCAs	6.1E-03
Tube rupture	1.5E-02
Steam line break	1.5E-02

The following is a discussion of the major contributors to the MFW System reliability as derived from the IPE fault tree.

Since MFW is not a safeguards system, the pumps are not powered from a diesel backed bus and therefore are unavailable during a loss of off-site power. Loss of service water causes loss of lube oil cooling to the MFW and condensate pumps causing eventual failure of the pumps. Since the feedwater regulating and bypass valves are air-operated fail closed valves, loss of DC power and loss of instrument air both cause closure of all of the feedwater valves, failing feedwater. Local operation of the MFW valves is proceduralized for loss of heat sink. The different MFW System failure probabilities for initiating events that do fail feedwater and those initiating events that caused an SI signal to be generated is the difference in recoveries that the control room operators must perform to recover MFW as explained above. Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 125 of 415

Important hardware failures:

- Common cause failure of MFW System.
- Random failure of feedwater isolation valve.

Important operator actions:

The important operator action is the restoration of MFW for events in which it is isolated as a result of the initiating event but is still available. The actions associated with MFW restoration for those initiating events that do and do not generate an SI signal have been described above. Restoration of MFW is a relatively simple proceduralized action that is performed in the control room.

#### 2. Bleed and Feed

Transients resulting in reactor trip employ secondary cooling as the primary mechanism for core heat removal. For accident scenarios in which secondary cooling cannot be established or maintained, decay heat is absorbed by the primary system causing RCS temperature and pressure to rise. In these accidents, the emergency procedures direct the operator to initiate bleed and feed cooling.

To perform decay heat removal via bleed and feed, the operators inject cool water to the RCS with the SI System and relieve steam from the RCS through the pressurizer PORVs. In this cooling mode, primary coolant is released through the PORVs into the pressurizer relief tank (PRT) resulting in RCS pressure reduction and decay heat removal. An evaluation was performed that indicates that only one PORV is required for successful bleed and feed operations at Kewaunee. SI injection in this mode maintains adequate RCS inventory as well as providing decay heat removal. A short description of the pressurizer PORVs and SI System follows.

The pressurizer PORVs are air-operated fail-closed valves that are used to prevent overpressure in the RCS. For bleed and feed operation, they are manually opened from the control room to allow flow from the pressurizer to the PRT.

Since the PORVs are air operated valves, they are dependent on instrument air and DC power to operate. The instrument air supply to containment passes through one air operated fail open containment isolation valve. A failure of this valve or the associated control circuit will cause the valve to close and isolate instrument air to containment, which results in the loss of continuous bleed and feed capability. The PORVs have air accumulators to allow limited valve operation in the event of a loss of instrument air, but for conservatism it is assumed that they do not have sufficient capacity to allow valve operation for the duration of the bleed and feed operation. Therefore, the PORVs are assumed to fail on a loss of instrument air event.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 126 of 415 Safety Injection System

The SI System is used to inject water from the refueling water storage tank (RWST) into the RCS when the RCS pressure is greater than the shutoff head of the RHR pumps. The SI System consists of two redundant trains containing a pump and its associated valves.

The SI pump motors are powered from safeguards buses, which are backed up by diesel generators for reliability. The motor-operated valves that must operate to align the system for injection are also powered from safeguards power supplies. Motor-operated valves in the injection lines to the RCS cold legs are normally open with the breaker locked open to prevent inadvertent valve misalignment. The SI pump discharge is cross-connected such that either pump can supply cold leg injection or reactor vessel injection.

The SI pumps draw a suction off the boric acid tank (BAT) for the first few minutes of the injection phase of an event and then switch to the RWST when the lo-lo level alarm is reached on the BAT. When the RWST low level alarm setpoint is reached, the operators are instructed to begin the transfer from injection to recirculation mode.

The following is a discussion of the major contributors to bleed and feed reliability as derived from the IPE fault trees.

Initiating Event	Bleed and Feed Failure Probability
Loss of off-site power	2.7E-02
Transients	6.1E-03
Loss of one DC bus	6.3E-02
Steam line break	6.3E-03
Small LOCA	3.7E-03

As shown above, the availability of bleed and feed cooling is highly dependent on the initiating event. During normal transient events, bleed and feed is relatively reliable and its operation is principally dependent on operator action to initiate bleed and feed. For events involving loss of DC power or instrument air, the pressurizer PORVS fail closed, failing bleed and feed.

Loss of component cooling water (CCW) is assumed to fail the SI System as the SI pumps rely on CCW for lube oil cooling. Loss of SW has the same effect as loss of CCW as loss of SW results in loss of CCW.

Important hardware failures:

- Common cause failure of high pressure injection.
- Common cause failure of BAT interlock.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 127 of 415

Important operator actions:

Hardware failures are insignificant contributors to the bleed and feed failure probability as most of the failure probability is from human error. The operator actions to initiate bleed and feed differ as to whether an SI signal has been generated by the initiating event. If an SI signal has not been generated, the operator must manually start the SI pumps and open the pressurizer PORVs, while if an SI signal has been generated, he must only verify an SI pump is running and then open the pressurizer PORVs.

The most important operator actions for bleed and feed are manually stopping the reactor coolant pumps (RXCPs) and manually establishing bleed and feed. Manually stopping the RXCPs is modeled based on the very conservative assumption that the heat input from the RXCPs is sufficient to speed up drying of the steam generators to the point at which there is insufficient time for manual initiation of bleed and feed. Manually establishing bleed and feed consists of opening the PORVs, 7 ad if they are not running already, starting the SI pumps.

### 3. ECCS Injection and Recirculation

During LOCA events, decay heat is removed from the RCS by the Emergency Core Coolant Systems (ECCS). The two systems from the ECCS that provide RCS inventory control are the SI and RHR Systems. Each system has two modes of operation. During the initial phase of injection, both systems inject into the RCS from the RWST. The SI pumps are high head low capacity pumps that inject into the RCS when the RCS pressure remains above the shutoff head of the RHR pumps. The RHR pumps are low head high capacity pumps that are used to prevent core damage for a design basis LOCA.

When low level in the RWST is reached, the operators are instructed to switch to the recirculation mode of ECCS. In recirculation, the RHR pump suction is shifted to the containment sump. Water is drawn from the containment, cooled in the RHR heat exchangers and discharged either back into the RCS or to the suction of the SI pumps depending on whether RCS pressure is above or below the shutoff head of the RHR pumps.

For high head recirculation, when RCS pressure is above RHR pump shutoff head, the RHR pump discharge is directed to the SI pump suction. The SI pumps then pump the water back into the RCS at high pressure. For low head recirculation, when the RCS pressure is below the RHR pump shutoff head, the RHR pumps discharge directly into the reactor vessel. Since the SI System is discussed under bleed and feed, it is not discussed here.

### High Head Injection and Recirculation

The following is a discussion of the major contributors to high head injection and recirculation system reliability.

## High Head Injection

The reliability of high head injection does not vary for the spectrum of initiating events considered in the IPE.

Initiating Event	HPSI Failure Probability	
Interfacing system LOCA	1.29E-03	
Other events	3.0E-03	

Important hardware failures:

- Common cause failure of system.
- Common cause failure of BAT interlock.

The two largest contributors to the high head SI System failure probabilities ar. the suction valves from the BAT and RWST failing to open due to common cause. At Kewaunee, the SI pumps first draw suction from the BAT and then switch over to the RWST on low BAT level. If the BAT or RWST suction valves fail to open, a small 2-inch passive suction line from the RWST provides some limited protection for the SI pumps.

Important operator actions:

The only operator action is associated with system restoration after test and maintenance. This action contributes less then 3 percent to system reliability.

#### High Head Recirculation

The reliability of high head recirculation does not vary appreciably except for the loss of a DC bus, in which one complete train of safeguard systems fail.

Initiating Event HPR Failure Probabil	
Loss of a DC bus	1.0E-01
Other events	6.0E-03

Loss of CCW is assumed to fail high head recirculation as the SI pumps rely on CCW for hube oil cooling and the RHR heat exchangers use CCW for their heat sink. Loss of SW has the same effect as loss of CCW as loss of SW results in loss of CCW. Important hardware failures:

- Common case failure of high head recirculation.
- Common case failure of low head recirculation.
- Common case failure of low head injection.
- Plugging of the containment sump strainers.
- Random failure of CCW, RHR, and SI motor valves required during recirculation.

Important operator actions:

The single most important operator action is the failure of the operator to stop the RHR pumps when RCS pressure is above the RHR pump head. It is assumed that failure of this action within 30 minutes results in the failure of the RHR pumps.

### Low Head Injection and Recirculation

The low head SI (RHR) System is used to inject water from the RWST or the containment sump into the RCS when the RCS pressure is low. The RMR System consists of two redundant trains each containing a pump and heat exchanger. The heat load from the heat exchangers is transferred to the CCW System. Each RHR train is capable of providing the necessary injection flow to prevent core damage for a design basis LOCA.

The RHR pump motors are powered from safeguards buses which are backed up by diesel generators for reliability. The motor-operated valves that operate to align the system for recirculation are also powered from safeguards power supplies. The RHR flow control valves downstream of the heat exchangers are air-operated and are dependent on instrument air, but they fail open on a loss of air and therefore do not fail their associated train. Since the RHR pumps are located in pits in the auxiliary building, it is assumed that room cooling is required for successful RHR pump operation.

#### Low Head Injection

The reliability of low head injection does not vary appreciably for the spectrum of events considered based on the IPE fault trees.

Initiating Events	LPSI Failure Probability
Large LOCA	6.9 <b>E</b> -04
Small and medium LOCA	4.3E-04

Important hardware failures:

- Common cause failure of both RHR pumps.
- Common cause failure of actuation signals.

The largest contributors to RHR injection failure are common cause failures of the two RHR pumps to start and run. Since the only support systems that the RHR System requires during the injection mode of operation is AC and DC power, support system failures are not large contributors to system failure Valve failures do not contribute to system failure as there are no valves required to change state for successful RHR injection as the RHR vessel injection valves are open because of pressure locking/thermal binding concerns.

Important operator actions:

There are no significant operator actions associated with low head injection.

#### Low Head Recirculation

The reliability of low head recirculation used for small, medium, and large LOCA events is 2.8E-03.

Important hardware failures:

- Common cause failure of both RHR pumps.
- Plugging of the containment sump screen.
- Random and common cause failure of the CCW valves for the RHR heat exchangers.
- Random and common cause failure of the containment sump valves.

The largest hardware failures that contributes to low head recirculation failure is the common cause failure to open of the CCW supply valves to the RHR heat exchangers and the containment sump valves. Failure of the CCW valves causes loss of heat sink for the RHR heat exchangers, which is assumed to cause failure of recirculation as heat cannot be removed from the RCS. Failure of the sump valves prevents flow from being established from the sump to the RHR System and thus failing recirculation. Area cooling failures contribute to low head recirculation failure as it has been assumed that the RHR pumps require room cooling during the recirculation mode of operation.

Important operator actions:

The single most important operator action is the failure of the operator to stop the RHR pumps for small and medium LOCA events where RCS pressure remains above RHR discharge pressure. It is assumed that failure of this action results in the failure of the RHR pumps due to excessive time in minimum flow conditions.

### 4. Residual Heat Removal Shutdown Cooling

The RHR System is discussed above in the injection and recirculation modes of operation. This section describes the RHR shutdown cooling mode of operation. In this mode of operation, the RHR pumps draw suction from the A and B RCS hot legs and discharge the coolant through the RHR heat exchangers and back to B RCS cold leg. The heat load of the coolant is transferred to the CCW System from the RHR heat exchangers. This mode Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 131 of 415

of RHR operation can only be entered after the RCS has been cooled and depressurized to 350°F and 425 psig.

The initiating events for which RHR is modeled, namely small LOCA and SGTR, have no affect on the RHR System, therefore only hardware failures and human error contribute to the system failure probability of 9.4E-03.

Important hardware failures:

- Random failure of RHR return valve to open.
- RHR System common cause failures.

The largest hardware contribution to RHR failure is the failure of the single RHR loop return valve to open. Since this is the single return valve, failure of this valve to open fails both trains of RHR. It was conservatively assumed that RHR could not be established through the low head injection valves to the reactor vessel.

Important operator actions:

The only significant operator action is the stopping of the RHR pumps that was discussed previously. This event contributes approximately 4.5 percent to system reliability.

#### **Containment Cooling Considerations**

There are four fan coil units (FCUs) inside the containment that draw air from around the unit and pass it through cooling coils to cool the air and condense any steam in the air, returning the condensate to a containment sump. They then discharge the cooled air to various areas in the containment. The fan motors are powered from a safeguards power supply that is backed up by an emergency diesel generator. The normal cooling medium for the FCU cooling coils is from the safeguards SW System.

The Internal Containment Spray (ICS) System consists of two pumps that are able to draw a suction from the RWST and a caustic standpipe to deliver a borated water-sodium hydroxide mixture to spray ring headers located in the containment dome. The ICS System operation consists of two phases: an injection and a recirculation phase. During the injection phase, the pumps draw a suction from the RWST and the caustic standpipe and deliver the mixture to spray rings in the containment dome. During the recirculation phase of operation, water is supplied to the suction of the ICS pumps from the RHR pumps, which draw their suction from the containment sump.

In all of the Kewaunee containment event trees, success or failure of recirculation is addressed before FCU or ICS success or failure. Credit is not taken for the FCUs removing decay heat from containment and condensing the water to return it to the containment sump. In the case of recirculation, failure of the RHR heat exchanger is assumed to result in failure of recirculation even though the RHR pumps could recirculate the water through containment where the heat could be removed by the FCUs. If recirculation fails, it is assumed that core damage occurs.

## **External Event Considerations**

This section evaluates the effect of the external events considered in the IPEEE on the DHR capability at Kewaunee.

#### Seismic

#### Important SPRA Assumptions

The following are the major assumptions used in developing the SPRA models as discussed in Section 3.1 that have an impact on the DHR capability at Kewaunee.

- Offsite power is lost at low ground motion.
- The condensate storage tanks (CST) fail at low ground motion.
- The Instument Air System fails at low ground motion.

#### Secondary Cooling

#### Auxiliary Feedwater

In the seismic analysis AFW success is highly dependent on the diesel generators for support due to the loss of offsite power.

The CSTs are the primary supply of water to the AFW pumps. The CSTs are assumed to fail, requiring the operator to switch to the SW supply. This operator action plays a more important role in AFW success. This is, however, a simple task accomplished from the control room.

Main Feedwater System

The MFW System is not available due to the loss of offsite power to backup the AFW system in providing secondary cooling. The buses that provide power to the feedwater pumps are not backed up by diesel generators. Therefore, no credit is taken for MFW in the SPRA.

#### Bleed and Feed

In the seismic analysis, the Instrument Air System is assumed to fail at low ground motions. As discussed previously, bleed and feed requires the pressurizer PORVs, which are dependent on instrument air. Therefore, no credit is taken in the SPRA for bleed and feed. This is a conservative assumption in that a seismically qualified air supply would be available. It is uncertain, however, whether there would be sufficient capacity for the duration of the bleed and feed operation.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 133 of 415

#### ECCS Injection and Recirculation

The only significant finding associated with the ECCS Systems (SI and RHR) is the seismic capacity of the RHR heat exchangers (0.63g PGA), which is below the value for the surrogate (0.64g PGA). A sensitivity evaluation for this component provided results that were the same as the base case.

#### Fire

Kewaunee meets all the requirements of 10 CFR 50, Appendix R, other than exemptions approved by the NRC. This includes assuring that no fire can prevent operators from safely shutting down the plant. This includes the decay heat removal function.

For successful decay heat removal, it is necessary to have sufficient RCS inventory and, since steam generators are used to remove decay heat, sufficient steam generator inventory and relief capability. After cooldown to cold shutdown, it is necessary to have another means of long-term decay heat removal. Each of these is specifically addressed in the WPSC response to Appendix R.

#### **RCS** Inventory

The dedicated means of providing RCS inventory is the C charging pump. The alternate means is the B SI pump.

#### Steam Generator Relief

The primary means of steam relief is the A steam generator PORV. The alternate means is the B steam generator PORV.

#### Steam Generator Inventory

The dedicated means of providing steam generator inventory is the A AFW pump. The alternate means is the B AFW pump.

#### Long-Term Decay Heat Removal

The dedicated means of long-term heat removal is RHR train A. The alternate means is RHR train B.

Other decay heat removal options (MFW, bleed and feed, recirculation) are not credited for Appendix R purposes. They may be available however, depending on the location of the fire. Section 4 of this report provides a detailed description of which of these additional systems is available in which fire scenarios.

Support systems are also divided by train. In general, the same support systems are needed for fire events as for internal events. The A train supports dedicated train equipment and the B train supports alternate train equipment.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 134 of 415

### Other

A review of the analysis for the other external event indicated that none of the analyzed events had any impact on the DHR capability at Kewaunee.

#### **Conclusions**

In NUREG-1289, the two DHR requirements listed are:

- a. Maintain sufficient water inventory in the Reactor Coolant System to ensure adequate cooling of the fuel.
- b. Provide the means for transferring heat from the Reactor Coolant System to an ultimate heat sink.

With this definition in mind, loss of DHR becomes synonymous with core damage as there are no core damage sequences that do not involve loss of either one or both of the two requirements listed above. As identified above, there are many redundant and diverse means for DHR at Kewaunee. Several of the DHR systems and operator actions have to fail in combination to have an impact on the DHR capability at Kewaunee. With the performance of the IPE/IPEEE and the resultant overall CDF being acceptably low, WPSC considers that it has fulfilled the requirements of USI A-45.

#### **USI A-17 Systems Interactions**

The walkdowns explicitly considered USI A-17 interactions. Therefore USI A-17 is subsumed in the USI A-46 program. The seismic, fire, and flooding examinations for this IPEEE report incorporate the walkdown findings for USI A-17 related items. This will be presented in detail at a later date in the USI A-46 submittal.

#### USI A-40 Seismic Design Criteria, a Short Term Program

The one remaining element of USI A-40 concerns the evaluation of tanks. The IPEEE seismic evaluation does not explicitly evaluate large tanks. The USI A-46 assessments, however, do evaluate tanks for the concerns raised in USI A-40. Evaluation techniques incorporated the considerations established for the Seismic Margins Program thereby resolving the analytical concerns raised in USI A-40. The evaluation results will be presented at a later date in the USI A-46 submittal.

#### USI A-46 Verification of Seismic Adequacy of Equipment

The IPEEE project team performed the seismic PRA jointly with the USI A-46 evaluations. The selection of SPRA systems and components sought to retain commonality with the USI A-46 SSEL to the extent practical. Seismic walkdown teams gathered data for both evaluations simultaneously. The evaluation results are presented in Section 3.1.4 and Table 3-4 of this report. A more detailed report will be presented at a later date in the USI A-46 submittal.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 135 of 415

## **3.3 References**

- 1. NUREG-1407, "Procedural and Submittal Guidance for the Individual Plant Examination of External Events (IPEEE) for Severe Accident Vulnerabilities", June 1991
- 2. Kewaunee IPE Submittal Report, December 1, 1992
- 3. Jack R. Benjamin and Associates, Inc., "Ship User's Manual," Version 1.0 (Proprietary), Mountain View, California, 1994
- 4. Kewaunee USAR, Revision July 1, 1993
- 5. John A. Blume & Associates, Engineers, "Kewaunee Nuclear Power Plant Earthquake Analysis of the Reactor - Auxiliary - Turbine Building," JAB-PS-01, February 16, 1971
- 6. John A. Blume & Associates, Engineers, "Kewaunee Nuclear Power Plant Earthquake Analysis: Reactor - Auxiliary - Turbine Building Response Acceleration Spectra," JAB-PS-03, February 16, 1971
- 7. Kewaunee Calculation in Report files for IE Bulletin No. 79-14, "Seismic Analyses for As-Built Safety Related Piping Systems," July 2, 1979
- 8. GEI Consultants, Inc., Soil Failure Report for the Kewaunee IPEEE, March, 1994
- 9. Dames & Moore, "Report of Geological and Seismological Environmental Studies. Proposed Nuclear Power Plant, Kewaunee, Wisconsin, for the Wisconsin Public Service Company," May 12, 1967
- 10. EPRI NP-6041-SL, "A Methodology for Assessment of Nuclear Power Plant Seismic Margin" Revision 1, August 1991
- 11. Seismic Qualification Utility Group (SQUG), "Generic Implementation Procedure (GIP) for Seismic Verification of Nuclear Plant Equipment," Revision 2, February 14, 1992.
- 12. EPRI NP-5228-SL, Revision 1, Volume 1. "Seismic Verification of Nuclear Plant Equipment Anchorage (Revision 1)," June, 1991
- 13. EPRI NP-7146-SL. "Guidelines for Development of In-Cabinet Amplified Response Spectra for Electrical Benchboards and Panels," December, 1990
- 14. EPRI NP-7147-SL. "Seismic Ruggedness of Relays," August, 1991
- 15. Letter from Paul Smith (TRO) to Walter Djordjevic (S&A), April 2, 1993
- 16. NUREG/CR-5250, "Seismic Hazard Characterization of 69 Nuclear Power Plant Sites East of the Rocky Mountains", Vols. 1-8, January 1989
- 17. Hardin, B.O. "The Nature of Stress-Strain Behavior for Soils," Proceedings of the Conference on Earthquake Engineering and Soil Dynamics, ASCE, Geotechnical Engineering Division, Pasadena, CA, pp. 3-90. 1978
- Sykora, D.W. "Examination of Existing Shear Wave Velocity and Shear Modulus Correlations in Soils," Waterways Experiment Station, U.S. Army Corps of Engineers, 1987
- EPRI draft report, "Methodology for Developing Seismic Fragilities" by J.W. Reed and R.P. Kennedy, draft version of EPRI document dated August 1993
- 20. WPS Letter on Seismic Restraint of CRD Housing from WPSC to S&A, September 10, 1993
- Schnabel, P.B.; Lysmer, J.; and Seed, H.B. "SHAKE, A Computer Program for Earthquake Response Analysis of Horizontally Layered Sites," Report No. EERC 72-12, University of California, Berkeley, 1972
- 22. Rectangular Industrial Duct Construction Standards, Sheet Metal and Air Conditioning National Association, Inc. (SMACNA), Vienna, VA. 1980

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 136 of 415

3.3 References (Cont'd)

- 23. NRC Information Notice 94-32, "Revised Seismic Hazard Estimates," April 29, 1994
- 24. NUREG/CR-4840, "Procedures for the External Event Core Damage Frequency Analysis for NUREG-1150, " November 1990
- 25. Conversation between R. P. Kennedy and W. Djordjevic, June 11, 1993
- 26. Westinghouse Corporation, "WLINK User Manual," Version 3.11, 1992
- 27. Patenaude, C. J., "SIGPI: A User's Manual for Fast Computation of the Probabilistic Performance of Complex Systems," prepared by Lawrence Livermore National Laboratory, prepared for U.S. Nuclear Regulatory Commission, NUREG/CR-4800, UCID-20679, September, 1986
- 28. NUREG-1488, Revised Livermore Seismic hazard Estimates for 69 Nuclear Power Plant Sites East of the Rocky Mountains," Draft Report for Comment, October 1993
- 29. EPRI NP-6395-D, "Probabilistic Seismic Hazard Evaluations at Nuclear Plant Sites in the Central and Eastern United States: Resolution of the Charleston Earthquake Issue," April 1989
- 30. EPRI Report NP-7148-SL. "Procedure for Evaluation Nuclear Power Plant Relay Seismic Functionality," December, 1990
- 31. Report from John Reed of JRB to W. Dejordjevic of S&A, April 4, 1994

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 137 of 415

## Table 3-1

## Mean Seismic Hazard Curves for the Kewaunee Site

EPRI HAZARD CURVE	
Peak Ground Acceleration (g)	Mean Annual Probability of Exceedence
0.01	2.10E-03
0.11	1.10E-04
0.22	3.8E-05
0.50	5.90E-06
0.85	9.60E-07
1.12	2.70E-07
1.59	6.20E-08

LLNL HAZARD CURVE (NUREG-1488)	
Peak Ground Acceleration (g)	Mean Annual Probability of Exceedence
0.05	3.04E-04
0.07	1.77E-04
0.15	6.42E-05
0.25	2.75E-05
0.30	1.98E-05
0.40	1.14E-05
0.50	7.21E-06
0.66	4.04E-06
0.81	2.47E-06
1.02	1.41E-06

Table 3-2           SPRA Equipment/Component Fragilities		
Component Description	Median PGA	β <sub>c</sub>
Off-site Power	0.35	0.55
Reactor Internals	5.22	0.30
Diesel Generator Day Tank Block Walls	3.22	0.46
Circulating Water Intake and Discharge Piping	1.05	0.46
120/208V DISTRIBUTION PANEL	1.51	0.46
120/208V DISTRIBUTION PANEL	1.51	0.46
4160V SWGR	3.57	0.46
AC DISTR. CAB BRB-105	1.10	0.46
AC DISTR. CAB BRB-113(EXT)	3.45	0.46
AC DISTRIB CAB BRA-113 EXT	3.60	0.46
AC FUSE PANEL SD-100	3.20	0.46
ACCUMULATOR-ACCUMULATOR 1A	1.44	0.46
ACCUMULATOR-ACCUMULATOR IB	1.44	0.46
BATTERY-SAFEGUARDS STATION BATTERY A	2.74	0.46
BATTERY-SAFEGUARDS STATION BATTERY B	2.74	0.46
BORIC ACID TANK 1A	1.16	0.46
BORIC ACID TANK 1B	1.16	0.46
BUS 1-51	3.47	0.46
BUS 1-52	3.47	0.46
BUS 1-61	3.47	0.46
BUS 1-62	3.47	0.46
BRA127 - 120/128VAC DISTR. CAB.	3.45	0.46
BRA113 118VAC DISTR. CAB.	1.51	0.46
BRA114 118VAC DISTR. CAB.	3.45	0.46
BRB102 125VDC MAIN DISTR. CAB.	1.10	0.46
BRB104 125VDC DISTR. CAB.	1.10	0.46
BRB113 118VAC DICTR. CAB.	3.45	0.46
BRB114 118VAC DISTR. CAB.	3.45	0.46
CABINET-DR102-LOGIC PANEL 1A 4KV	3.60	0.46
CABINET-DR103-LOGIC PANEL 1A 480V	3.60	0.46
CABINET DR104-SEQ LOADING 1A PANEL	3.60	0.46
CABINET DR105-SEQ LOADING 1A PANEL	3.60	0.46
CABINET DR106-SEQ LOADING 1A PANEL	3.60	0.46
CABINET-DR112-LOGIC PANEL 1B 4KV	3.60	0.46
CABINET-DR113-LOGIC PANEL 1B 480 V	3.60	0.46
CABINET-DR114 SEQ LOADING 1B PANEL	3.60	0.46
CABINET-DR115-SEQ LOADING 1B PANEL	3.60	0.45
CABINET-DR116-SEQ LOADING 1B PANEL	3.60	0.46
CHARGER-BATTERY CHARGER BRA108 125 VDC	3.45	0.46
CHARGER-BATTERY CHARGER BRB108 125 VDC	3.45	0.46

Table 3-2 SPRA Equipment/Component Fragilities		
Component Description	Median PGA	β <sub>c</sub>
CONTAINMENT FAN COIL UNIT IA	2.85	0.46
CONTAINMENT FAN COIL UNIT 1B	2.85	0.46
CONTAINMENT FAN COIL UNIT 1C	2.85	0.46
CONTAINMENT FAN COIL UNIT ID	2.85	0.46
COOLER-PUMP 1A GLAND SEAL COOLER	1.50	0.46
COOLER-PUMP IB GLAND SEAL COOLER	1.50	0.46
DAMPER-OUTSIDE AIR INLET DAMPER TO DG ROOM 1A	1.46	0.46
DAMPER-OUTSIDE AIR INLET DAMPER TO DG ROOM 1B	1.46	0.46
DC FUSE PANEL SD-101	3.20	0.46
DG FUEL OIL DAY TANK 1A1	1.86	0.46
DG FUEL OIL DAY TANK 1A2	1.86	0.46
DG FUEL OIL DAY TANK IBI	1.86	0.46
DG FUEL OIL DAY TANK 1B2	1.86	0.46
DIESEL AUX RELAY PANEL	1.57	0.46
DIESEL AUX RELAY PANEL	1.57	0.46
DIESEL GENERATOR 1A	3.67	0.46
DIESEL GENERATOR 1B	3.67	0.46
EDG-EXCITER CAB DR-101	2.22	0.46
EDG-EXCITER CAB DR-111	2.22	0.46
BRA101N FUSE CAB. (NEG)	3.45	0.46
BRA101P FUSE CAB. (POS)	3.45	0.46
BRA102 125VDC MAIN DISTR. CAB.	1.10	0.46
BRA104 125VDC DISTR. CAB.	1.10	0.46
BRB101N FUSE CAB. (NEG)	3.45	0.46
BRB101P FUSE CAB. (POS)	3.45	0.46
MIN. INTERRUPT. BUS 120/208 VAC DISTR. CAB.	1.10	0.46
FAN COIL UNIT-AUX BLDG BSMT FAN COIL IC	1.51	0.46
FAN COIL UNIT-AUX DG BSMT FAN COIL UNIT 1D	3.47	0.46
FAN COIL UNIT-AU RY BLDG BSMT 1A	1.45	0.46
FAN COIL UNIT-AUXILIARY BLDG BSMT 1B	1.45	0.46
FAN COIL UNIT-RESIDUAL HEAT PUMP PIT 1A	1.43	0.46
FAN COIL UNIT-RESIDUAL HEAT PUMP PIT 1B	1.43	0.46
HEAT EXCHANGER-RESIDUAL HEAT EXCHANGER 1A	0.63	0.46
HEAT EXCHANGER-RESIDUAL HEAT EXCHANGER 1B	0.63	0.46
INSTRUMENT BUS SUB-DIST CABINET IBSD-2	3.46	0.46
INSTRUMENT BUS SUB-DIST CABINET IBSD-4	3.46	0.46
INSTRUMENT BUS TRANSFORMER	3.41	0.46
INSTRUMENT BUS TRANSFORMER	3.41	0.46
INVERTER BRB-111 (INSTRUMENT BUS II)	3.45	0.46
INVERTER-BRAIII (INSTRUMENT BUS I)	3.45	0.46

Table 3-2 SPRA Equipment/Component Fragilities		
Component Description	Median PGA	β <sub>c</sub>
INVERTER-BRAII2 (INSTRUMENT BUS IV)	3.45	0.46
INVERTER-BRBIIZ (INSTRUMENT BUS III)	3.45	0.46
MCC 1-52F (EXT)	3.48	0.46
MCC 1-52A	2.84	0.46
MCC 1-52B	1.87	0.46
MCC 1-52B (EXT)	3.34	0.46
MCC 1-52D	1.59	0.46
MCC 1-62C	2.67	0.46
MCC 1-62D	1.59	0.46
MCC 1-3352	3.34	0.46
MCC 1-62G	2.95	0.46
MCC 1-5262	2.84	0.46
MCC 1-52C	2.67	0.46
MCC 1-52E	2.94	0.46
MCC 1-52F	3.00	0.46
MCC 1-62A	2.84	0.46
MCC 1-62B	2.93	0.46
MCC 1-62BE	3.34	0.46
MCC 1-62E	1.87	0.46
MCC 1-62H	3.38	0.46
MCC 1-62J	1.08	0.46
Motor Starter - AFW10A/MV32027 AFW Train A X-over Valve	1.54	0.46
Motor Starter - AFW10B/MV32028 AFW Train B X-over Valve	1.54	0.46
Motor Starter - Turb Dvn AFW Pump Aux Lube Oil Pump	1.54	0.46
Motor Starter - BT3A/MV32078 SG A Blowdown Isol Valve A2	1.58	0.46
Motor Starter - BT3B/MV32080 SG B Blowdown Isol Valve B2	1.58	0.46
Motor Starter - MS102/32040 T/D AFW Pump Main Steam Isol	1.54	0.46
Motor Starter - SW502/MV32031 SW to Turb Dvn Aux FWP	1.54	0.46
PUMP-AUXILIARY FEEDWATER PUMP 1A	1.55	0.46
PUMP-AUXILIARY FEEDWATER PUMP 1B	1.55	0.46
PUMP-CHARGING PUMP 1A	1.51	0.46
PUMP-CHARGING PUMP 1B	1.51	0.46
PUMP-CHARGING PUMP IC	1.51	0.46
PUMP-COMPONENT COOLING PUMP 1A	1.49	0.46
PUMP-COMPONENT COOLING PUMP 1B	1.49	0.46
PUMP-CONTAINMENT SPRAY PUMP 1A	1.51	0.46
PUMP-CONTAINMENT SPRAY PUMP IB	1.51	0.46
PUMP-TURB DRIVEN-AUXILIARY FEEDWATER PUMP IC	1.57	0.46
REACTOR TRIP BREAKERS RTA AND RTB - RD106	3.48	0.46
Relay Rack - RR121-RR125 Reactor Protection Train 'B' (1C165)	3.46	0.46

Table 3-2		
SPRA Equipment/Component Fragilities Component Description	Median PGA	β <sub>c</sub>
	3.46	0.46
Relay Rack RR126 - Engineered Safeguard Train B	3.46	0.46
Relay Rack - RR127 - Engineered Safeguard Train B Relay Rack - RR128 - Engineered Safeguard Train B	3.40	0.40
Relay Rack - RR128 - Engineered Safeguard Train B Relay Rack - RR129 - Engineered Safeguard Train A	3.46	0.40
	3.46	0.46
Relay Rack - RR130-RR134 Reactor Protection Train 'A'	3.46	0.40
Relay Rack - RR142 - Aux Relay Rack A Relay Rack - RR143 - Aux Relay Rack Train A	3.46	0.40
• •	3.46	0.40
Relay Rack - RR144 - Aux Relay Rack Train B	3.46	0.40
Relay Rack - RR147 - Aux Relay Rack B	1.11	0.40
Relay Rack - RR170-RR171 - Sub Distr AC Fuse Panel		0.46
Relay Rack - RR172 - Sub Distr AC Fuse Panel	1.11	
Relay Rack - RR173 - Sub Distr AC Fuse Panel Normal	1.11	0.46
Relay Rack - RR174 - Sub Distr DC Fuse Panel Normal	1.11	0.46
Relay Rack - RR175 - Sub Distr AC Fuse Panel Train 'B'	1.11	0.46
Relay Rack - RR176 - Sub Distr DC Fuse Panel Train 'B'	1.11	0.46
RELAY-ELECT-BRA107 AUTOMATIC TRANSFER SWITCH	3.45	0.46
RELAY-ELECT-BRB107 AUTOMATIC TRANSFER SWITCH	3.45	0.46
RHR Pump 1A	1.51	0.46
RHR Pump 1B	1.51	0.46
RR101 - RR109/1E-0200-0208	3.46	0.46
SI PUMP 1A	1.51	0.46
SI PUMP 1B	1.51	0.46
SW PUMP IAI	1.45	0.46
SW PUMP 1A2	1.45	0.46
SW PUMP 1B1	1.45	0.46
SW PUMP 1B2	1.45	0.46
SWITCHGEAR 4160V SWITCHGEAR BUS 6	3.57	0.46
Tank - Volume Control Tank	1.43	0.46
Transducer panel	1.57	0.46
Transducer panel	1.57	0.46
Transducer panci	1.57	0.46
Transducer panel	3.60	0.46
TRANSFORMER-STATION SERVICE TRANSFORMER 51	3.57	0.46
TRANSFORMER-STATION SERVICE TRANSFORMER 52	3.57	0.46
TRANSFORMER-STATION SERVICE TRANSFORMER 61	3.57	0.46
TRANSFORMER-STATION SERVICE TRANSFORMER 62	3.57	0.46
TURBINE BLDG FAN COIL IB	1.42	0.46
FURBINE BLDG. FAN COIL 1A	1.42	0.46

Table 3-3
SPRA Equipment/Component List-Screened at Surrogate Level
Component Description
145-661/SW-AUX FW PMP 1A AUX LUBE OIL PMP CONT PS
155-031/SWITCH-RESIDUAL HT PMP PIT FAN COIL UNIT IA TS
155-032/SWITCH-RESIDUAL HT PMP PIT FAN COIL UNIT 1B TS
155-101/ SWITCH-AUX BLDG BSMT FAN COIL UNIT 1A TS
155-102/ SWITCH-AUX BLDG BSMT FAN COIL UNIT 1B TS
155-111/SWITCH-AUX BLDG MEZZ FAN COIL UNIT IA TS
155-112/SWITCH-AUX BLDG MEZZ FAN COIL UNIT 1B TS
155-211/SWITCH-BATTERY RM FAN COIL UNIT 1A DSCH AIR TS
155-3117 SWITCH-AUX BLDG BSMT FAN COIL UNIT IC TS
155-312/ SWITCH-AUX BLDG BSMT FAN COIL UNIT 1D TS
Accumulator - Service Water Turb Bldg Hdr 1A CV Accumulator
Accumulator - Service Water Turb Bldg Hdr 1B CV Accumulator
ACT- PRZR POWER RELIEF CV 1B SOL VLV
Actuator - ACC3A/MD32397 CRPA Recirc Damper A
Actuator - ACC3B/MD32371 CRPA Recirc Damper B
Actuator - ACC4/MD32374 Control Rm A/C Normal Recirc Dmpr
Actuator - Reactor Clnt Pmp 1A Seal Water Isol SV
Actuator - Reactor Clnt Pmp 1B Seal Water Isol SV
Actuator - Seal Wtr Return by - Pass Block CV
ACTUATOR SW TO CCW
ACTUATOR-ACC1A/MV32367 CONT ROOM FRESH AIR INLET DAMPER A
ACTUATOR-ACC1B/MV32368 CONT ROOM FRESH AIR INLET DAMPER B
ACTUATOR-ACC5/CD34007 NON-ACCIDENT FRESH AIR DAMPER
ACTUATOR-AFW PMP 1A DISCH CV SV ACTUATOR-AFW PMP 1A FAN COIL UNIT COOLING VLV SV
ACTUATOR-AFW PMP TA FAN COIL UNIT COOLING VLV SV
ACTUATOR-AFW PUMP IA DICHO ACTUATOR-AUX FW PMP IA OIL COOLER COOLING WTR INLET SV
ACTUATOR-AUX FW PMP TA OIL COOLER COOLING WIR INLET SV ACTUATOR-AUX FW PMP 1B OIL COOLER COOLING WIR INLET SV
ACTUATOR-BATT RM FAN COIL UNIT IB SV
ACTUATOR-BATT RM FAN COOL UNIT 16 SV
ACTUATOR-CC610A/CV31127 RXCP A THERMAL BARR CC RETURN
ACTUATOR-CC610A/CV31127 RXCP A THERMAL BARR CC RETURN
ACTUATOR-CC610B/CV31128 RXCP B THERMAL BARR CC RETURN
ACTUATOR-CHG LINE TO AUX SPRAY/CVC15/33039
ACTUATOR-CHG LINE TO REGEN HX SV
ACTUATOR-CHG. LINE TO COLD LEG LOOP B STOP SV
ACTUATOR-COND MAKE-UP CV
ACTUATOR-D/G RM 1A INLET DMPR SV 1A1
ACTUATOR-D/G RM 1A INLET DMPR SV 1A2
ACTUATOR-D/G RM 1A OUTLET DMPR SV 1A1

Table 3-3
SPRA Equipment/Component List-Screened at Surrogate Level
Component Description
ACTUATOR-D/G RM 1A OUTLET DMPR SV 1A1
ACTUATOR-D/G RM 1B INLET AND RECIRC DMPR SV 1B1
ACTUATOR-D/G RM 1B INLET AND RECIRC DMPR SV 1B2
ACTUATOR-DG 1A OIL CLR WTR OUTL CV
ACTUATOR-DG RM 1B OUTLET DAMPER SV 1E1
ACTUATOR-DG RM 1B OUTLET DAMPER SV 1B2
ACTUATOR-DGIB OIL CLR WTR OUTLET SV
ACTUATOR-DIESEL GEN 1A OIL CLR WTR OUT SV
ACTUATOR-EXCESS LETDOWN HX INLET SV
ACTUATOR-FAN COIL UNIT IB
ACTUATOR-HEADER IA SHROUD CLG COIL A/B BYPASS SV
ACTUATOR-HEADER IB SHROUD CLG COIL A/B BYPASS SV
ACTUATOR-HEADER IC SHROUD CLG COIL C/D BYPASS SV
ACTUATOR-HEADER 1D SHROUD CLG COIL C/D BYPASS SV
ACTUATOR-HS2203A/MV32143 CONT ROOM AC UNIT A 3-WAY MIXING
ACTUATOR-HS2203B/MV32144 CONT ROOM AC UNIT B 3-WAY MIXING
ACTUATOR-LETDOWN & SEAL WTR BY-PASS BLOCK 1B SV
ACTUATOR-LETDOWN AND SEAL WATER
ACTUATOR-LTDN AND SEAL WTR BYPASS BLOCK SV
ACTUATOR-LTDN AND SL WTR BYPASS ELOCK 1A SV
ACTUATOR-LTDN AND SL WTR BYPASS DIVERT 1A SV
ACTUATOR-MN STM HDR 1A ISOL VLV AIR RELEASE SV 1A6
ACTUATOR-MN STM HDR IA ISOL VLV AIR RELEASE SV 1A7
ACTUATOR-MN STM HDR 1A ISOL VLV AIR SPLY SV 1A1
ACTUATOR-MN STM HDR 1A ISOL VLV AIR SPLY SV 1A2
ACTUATOR-MN STM HDR 1B ISOL VLV AIR RELEASE SV 1B6
ACTUATOR-MN STM HDR 1B ISOL VLV AIR RELEASE SV 1B7
ACTUATOR-MN STM HDR 1B ISOL VLV AIR SPLY SV 1B2
ACTUATOR-MN STM HDT IB ISOL VLV AIR RELEASE SV IBI
ACTUATOR-PRZR PWR RLF PRESS SV 1A
ACTUATOR-PRZR PWR RLF PRESS SV 1B
ACTUATOR RCTR HEAD VENT TO CNTNMT SV 49
ACTUATOR-RCTR HEAD VENT TRAIN A SV 33A ACTUATOR-RCTR HEAD VENT TRAIN A SV 45A
ACTUATOR-RETR HEAD VENT TRAIN A SV 45A ACTUATOR-RETR HEAD VENT TRAIN B SV 33B
ACTUATOR-RETR HEAD VENT TRAIN B SV 33B
ACTUATOR-RCTR HEAD VENT TRAIN B SV 45B
ACTUATOR-REAC CLNT CLD LEG LOOP B LTDN CV 1A
ACTUATOR-REAC CLNT COLD LEG LOOP B LIDN CV TA
ACTUATOR-RELAY RM ISOL INLET DMPR
ACTUATUR RELAT RM ISUL INLET DMPR

Table 3-3
SPRA Equipment/Component List-Screened at Surrogate Level
Component Description
ACTUATOR-RELAY RM ISOL OUTLET DMPR
ACTUATOR-RELAY ROOM SPLY AND EXH DMPR SLND
ACTUATOR-SCRNHSE EXH FAN 1A DISCH DMPR TRAIN A SV
ACTUATOR-SCR WHSE EXH FAN IB DISCH DMPR TRAIN B SV
ACTUATOR-SW AND RX BLDG 1A
ACTUATOR-SW PUMP HDR ISOL SV 1A
ACTUATOR-SW PUMP HDR ISOL SV 1B
ACTUATOR-SW TURB BLDG HDR 1A SV
ACTUATOR-SW TURE BLDG HDR 1B SV
ACTUATOR-SW1006C/CV31746 AUX BLDG BSMT FN COIL UNIT C INLT
ACTUATOR-SW1006D/CV31747 AUX BLDG BSMT FN COIL UNIT 1D INLT
ACTUATOR-SW1041A/CV31129 CR A/C CDSR A SW RTRN
ACTUATOR-SW1041B/CV31130 CR A/C CDSR B SW RTRN
ACTUATOR-SW1211A/SV33303 RHR PUMP PIT FAN COIL UNIT A INLET
ACTUATOR-SW1211B/SV33304 RHR PMP PIT FAN COIL UNIT B INLET
ACTUATOR-SW1221A/SV33307 AUX BLDG MEZZ FAN CL UNIT A INLET
ACTUATOR-SW1221B/SV33308 AUX BLDG MEZZ FAN COLL UNIT B INLET
ACTUATOR-SW1261/SV33778 CC PMP B FAN COIL COOLING WTR
ACTUATOR-SW802A/SV33313 AUX BLDG BSMT FAN COIL UNIT A INLET
ACTUATOR-SW802B/SV33302 AUX BLDG BSMT FN CL UNIT B INLET
ACTUATOR-TURB BLDG FAN COIL UNIT 1A CLG WTR SV
ACTUATOR-TURB BLDG FAN COIL UNIT IB CLG WTR SV
ACTUATOR-TURB DRIVEN AFW PMP OIL COOLER SV
All Cable Tray and Conduit Raceways
All Piping System
CABINET-CR108 N.I.S. RACK NO.4
CABINET-CR109 N.I.S. RACK NO.3
CABINET-CR110 N.I.S. RACK NO.2
CABINET-CR111 N.I.S. RACK NO.1
CABINET-CR112 I.T.S. RACK NO. 4
CABINET-CR113 I.T.S. RACK NO. 3
CABINFT-CRI14 I.T.S. RACK NO. 2
CABINET-CRI15 I.T.S. RACK NO. 1
CABINET-CR116 I.T.S. RACK NO. 2
CABINET-CR117 I.T.S. RACK NO. 1
CABINET-CR118 I.T.S. RACK NO.
CCW SURGE TANK
Control Room Ventilation Panel
Controller - Control Rm A/C Unit IA Cooling Wtr TC
Controller - Control Rm A/C Unit 1B Cooling Wtr TC

Table 3-3
SPRA Equipment/Component List-Screened at Surrogate Level
Component Description
CONTROLLER BRC ACID TNK IA HEATER TC
CONTROLLER-BRC ACID TNK IA HEATER TU
CONTROLLER-BRC ACID TNK IB HEATER TC
CONTROLLER-BRC ACID TNK 1B HEATER TC
CONTROLLER-COMP CLG PUMPS 1A/1B DSCH PC
CR107 MECHANICAL VERT PNL B
CV-CNTMT CLG SW RETURN HEADER IC MV
DAMPER TAV 63A
DAMPER-CNTMT FAN COIL IC EMERG DSCH DMPR
DAMPER-DG ROOM RECIRC SUPPLY FAN 1A DAMPER
DAMPER-DG ROOM RECIRC SUPPLY FAN 1B DAMPER
DAMPER-RBV150A/CD34131 CNTMT FAN COIL UNITB EMERG DISCH DMPR
DAMPER-RBV150B/CD34131 CNTMT FAN COIL 1B EMERG DISCH DMPR
DAMPER-RBV150D/CD34133 CNTMT FAN COIL UNIT D EMERG DISCH DMP
Detector - Neutron Flux Monitoring Detector Assg, Channel 2
Detector - Neutron Flux Monitoring Detector Assg, Channel 2
DG FUEL OIL STORAGE TANK IA
DG FUEL OIL STORAGE TANK 1B
DG FUEL OIL TRANSFER PUMP 1A
DG FUEL OIL TRANSFER PUMP 1B
DIESEL GI B FIRE DAMPER TAV60B
DIESEL GEN 1 IB FIRE DAMPER TAV61A
Elec Equip - FR104 Steam Exclusion Protection Rack
Elec Equip - FR105 Steam Exclusion Protection Rack
Elec Equip - FR106 Steam Exclusion Protection Rack
Fan - Control RM Post Accid Recirc Fan 1A
Fan - Control RM Post Accid Recirc Fan 1B
FCU - Component Cooling Pump 1B
HEAT EXCHANGER-COMPONENT COOLING HEAT EXCHANGER 1A
HEAT EXCHANGER-COMPONENT COOLING HEAT EXCHANGER IB
INSTRUMENT-AFW PUMP IB DISCHARGE PRESSURE
INSTRUMENT-AFW PUMP IB DISCHARGE PRESSURE (P-21024)
INSTRUMENT-MN STM HDR 1A CONTROLLED RLF SV
INSTRUMENT-MN STM HDR IB CONTROLLED RLF SV
ISOL V-AUX BLDG SW HEADER B ISOLATION
Isolation Devices - Neutron Flux Monitoring Optical Isolator
Junction Box - Neutron Flux Monitoring Junction Brk Assg.
Junction Box - Neutron Flux Monitoring Junction Brk Assg.
JUNCTION BOX FOR STAION & INSTRUMENT AIR COMP. 1A TIMING RELAY
LD-2 CVC LETDOWN ISO (LCV-427)

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 146 of 415

Table 3-3
SPRA Equipment/Component List-Screened at Surrogate Level
Component Description
LD-3 CVC LETDOWN ISO (LCV-428)
LD-300 CVC EXCESS LETDOWN/33172
MS HDR 1A CONTROLLED RELIEF CV SD3A ACCUMULATOR
MS HDR IB CONTROLLED RELIEF CV SD3B ACCUMULATOR
PANEL-CARDOX CONT PNL DGA
PANEL-CARDOX CONT PNL DGB
POSITIONER - 31305
Positioner for 31103
Positioner for 31170
Positioner for 34072
Positioner for 34073
PRZR LEVEL TRANS 24031
PRZR RELIEF TANK
PUMP-AUX FEEDWATER PUMP 1A AUX LUBE OIL PUMP
PUMP-AUXILIARY FEEDWATER PUMP IB AUXILIARY LUBE OIL PUMP
PUMP-CONTROL ROOM A/C CHILLER PUMP 1A
PUMP-CONTROL ROOM A/C CHILLER PUMP 1B
PUMP-TDAFW PMP AUX LUBE OIL PMP
Regulator - 1A for 31103
Regulator - 1A for 31103
REGULATOR-IA FOR 31109
REGULATOR-LA FOR 31110
REGULATOR-IA FOR 33875
REGULATOR-IA FOR 33876
REGULATOR-IA FOR 33877
REGULATOR-IA FOR 33878
REGULATOR-IA FOR 34072
REGULATOR-IA FOR 34073
REGULATOR-SCRN HSE EXH FAN IA DISCH DMPR
Relay Rack - RR186 - ICCMS Train B
Relay Rack - RR187 - ICCMS Train A
RELIEF VLV-SAFETY TO ATMOS-STEAM GEN 1A
RELIEF VLV-SEAL WTR RETURN LINE TO PRESS. RLF TANK
RTD-REACTOR COOLANT LOOP A COLD LEG RTD
RTD-REACTOR COOLANT LOOP A HOT LEG RTD
RTD-REACTOR COOLANT LOOP B COLD LEG RTD

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 147 of 415

SPRA Equipment/Component List-Screened at Surrogate Level Component Description TD-REACTOR COOLANT PMP 1A THERM BARRIER RTD TD-REACTOR COOLANT PMP 1B THERM BARRIER RTD B1B PRESS. TRANS 21097 CREEN-TRAVELING WTR SCRN 1A1 CREEN-TRAVELING WTR SCRN 1A2 CREEN-TRAVELING WTR SCRN 1B2 CREENHOUSE EXH. FAN 1A IGNAL CNVTR-CHARGING LINE TO REGEN HT EXGR CV SOL VLV ignal Converter - Neutron Flux Monitoring Wide Range Amplifie ignal Converter - Neutron Flux Monitoring Wide Range Amplifie URGE TK LEVEL TRANSMITTER 24041 V FOR LD2 V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1B1 W STRAINER 1B1 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUXE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B LUBE OIL PERMISSIVE PS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW PMP LABE OIL PERS PERMIPS witch - REAC CINT PMP LABE OIL TS witch - REAC CINT PMP LACEG WTR RTRN FC
RTD-REACTOR COOLANT PMP 1A THERM BARRIER RTD RTD-REACTOR COOLANT PMP 1B THERM BARRIER RTD B1B PRESS. TRANS 21097 CREEN-TRAVELING WTR SCRN 1A1 CREEN-TRAVELING WTR SCRN 1A2 CREENHOUSE EXH. FAN 1A IGNAL CNVTR-CHARGING LINE TO REGEN HT EXGR CV SOL VLV ignal Converter - Neutron Flux Monitoring Wide Range Amplifie ignal Converter - Neutron Flux Monitoring Wide Range Amplifie URGE TK LEVEL TRANSMI FTER 24041 V FOR LD2 V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1A2 W STRAINER 1B1 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OI
RTD-REACTOR COOLANT PMP 1B THERM BARRIER RTD         B1B PRESS. TRANS 21097         CREEN-TRAVELING WTR SCRN 1A1         CREEN-TRAVELING WTR SCRN 1B2         URGE TK LEVEL TRANSMITTER 24041         V FOR LD2         V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV         W PMP HEADER 1A ISO CV         W STRAINER 1A1         W STRAINER 1A2         W STRAINER 1A2         W STRAINER 1B1         W AUX FW PMP 1A LUBE OIL PERMISSIVE PS         W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS         W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS         W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS         W-TD FW PMP AUX LUBE OIL PERMISSIVE PS         W-TD FW PMP AUX LUBE OIL PERMISSIVE PS         witch - AFW PMP 1A Lube Oil Perm PS         witch - AFW PMP 1B Lube Oil Perm PS
BIB PRESS. TRANS 21097 CREEN-TRAVELING WTR SCRN 1A1 CREEN-TRAVELING WTR SCRN 1B2 CREENHOUSE EXH. FAN 1A IGNAL CNVTR-CHARGING LINE TO REGEN HT EXGR CV SOL VLV ignal Converter - Neutron Flux Monitoring Wide Range Amplifie ignal Converter - Neutron Flux Monitoring Wide Range Amplifie URGE TK LEVEL TRANSMI FTER 24041 V FOR LD2 V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1B1 W AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS witch - AFW PMP 1B LUBE OIL PERMIPS witch - AFW PMP 1B LUBE OIL PERMIPS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW PMP LUBE OIL PRES PERM PS witch - Reac Clat Pmp 1B Clg Wtr Rtm FC WTTCH-AFW PUMP 1A FAN COIL TS
CREEN-TRAVELING WTR SCRN 1A1 CREEN-TRAVELING WTR SCRN 1B2 CREENHOUSE EXH. FAN 1A IGNAL CNVTR-CHARGING LINE TO REGEN HT EXGR CV SOL VLV ignal Converter - Neutron Flux Monitoring Wide Range Amplifie ignal Converter - Neutron Flux Monitoring Wide Range Amplifie URGE TK LEVEL TRANSMITTER 24041 V FOR LD2 V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS Witch - AFW PMP 1B LUBE OIL PERMISSIVE PS Witch - AFW PMP 1A LUBE OIL PERMISSIVE PS Witch - AFW PMP 1B LUBE OIL PERMISSIVE PS Witch - AFW PMP 1A LUBE OIL PERMISSIVE PS Witch - AFW PMP 1A LUBE OIL PERMISSIVE PS Witch - AFW PMP 1A LUBE OIL PERMISSIVE PS Witch - MN Stm Hdr 1A CONTROLED RELIEF PS Witch - MN Stm Hdr 1A CONTROLED RELIEF PS Witch - TDAFW PMP LUBE OIL PERS PERM PS Witch - Reac Clut PMP 1A FAN COIL TS
CREEN-TRAVELING WTR SCRN 1B2 CREENHOUSE EXH. FAN 1A IGNAL CNVTR-CHARGING LINE TO REGEN HT EXGR CV SOL VLV ignal Converter - Neutron Flux Monitoring Wide Range Amplifie ignal Converter - Neutron Flux Monitoring Wide Range Amplifie URGE TK LEVEL TRANSMITTER 24041 V FOR LD2 V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1B1 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B LUBE OIL PERMISSIVE PS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW PMP Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clint Pmp 1B Clg Wtr Rtm FC WTCH-AFW PUMP 1A FAN COIL TS
CREENHOUSE EXH. FAN 1A IGNAL CNVTR-CHARGING LINE TO REGEN HT EXGR CV SOL VLV ignal Converter - Neutron Flux Monitoring Wide Range Amplifie ignal Converter - Neutron Flux Monitoring Wide Range Amplifie URGE TK LEVEL TRANSMI PTER 24041 V FOR LD2 V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1B1 W AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS witch - AFW PMP 1A LUBE OIL PERMISSIVE PS witch - AFW PMP 1B LUBE OIL PERMISSIVE PS witch - AFW PMP 1B LUBE OIL PERMISSIVE PS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW PMP Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clnt Pmp 1B Clg Wtr Rtm FC WTCH-AFW PUMP 1A FAN COIL TS
IGNAL CNVTR-CHARGING LINE TO REGEN HT EXGR CV SOL VLV ignal Converter - Neutron Flux Monitoring Wide Range Amplifie ignal Converter - Neutron Flux Monitoring Wide Range Amplifie URGE TK LEVEL TRANSMITTER 24041 V FOR LD2 V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1B1 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS witch - AFW PMP 1A LUBE OIL PERMISSIVE PS witch - AFW PMP 1B LUBE OIL PERMISSIVE PS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW PMP Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clnt Pmp 1B Clg Wtr Rtm FC WITCH-AFW PUMP 1A FAN COIL TS
ignal Converter - Neutron Flux Monitoring Wide Range Amplifie ignal Converter - Neutron Flux Monitoring Wide Range Amplifie URGE TK LEVEL TRANSMITTER 24041 V FOR LD2 V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1B1 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rin FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW PMP Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clint Pmp 1B Clg Wtr Rtm FC WITCH-AFW PUMP 1A FAN COIL TS
ignal Converter - Neutron Flux Monitoring Wide Pange Amplifie URGE TK LEVEL TRANSMITTER 24041 V FOR LD2 V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1A2 W STRAINER IB2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PMP CONT PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS witch - AFW PMP 1A LUBE OIL PERMISSIVE PS witch - AFW PMP 1B LUBE OIL PERMISSIVE PS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW PMP Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clnt Pmp 1B Clg Wtr Rtm FC WTTCH-AFW PUMP 1A FAN COIL TS
URGE TK LEVEL TRANSMITTER 24041 V FOR LD2 V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PMP CONT PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rn FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW PMP Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clnt Pmp 1B Clg Wtr Rtm FC WTTCH-AFW PUMP 1A FAN COIL TS
V FOR LD2 V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1A2 W STRAINER 1B1 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PMP CONT PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW PMP Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clnt Pmp 1B Clg Wtr Rtm FC WITCH-AFW PUMP 1A FAN COIL TS
V: ACTUATOR-CHARGING LINE AUX SPRAY TO PRZR STOP SV W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PMP CONT PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PERMISSIVE PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW PMP Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clnt Pmp 1B Clg Wtr Rtm FC WITCH-AFW PUMP 1A FAN COIL TS
W PMP HEADER 1A ISO CV W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1A2 W STRAINER 1B1 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PMP CONT PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PMP CONT PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rin FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clint Pmp 1B Clg Wtr Rtm FC WITCH-AFW PUMP 1A FAN COIL TS
W STRAINER 1A1 W STRAINER 1A2 W STRAINER 1B1 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PMP CONT PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PMP CONT PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rin FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW PMP Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clint Pmp 1B Clg Wtr Rtrn FC WITCH-AFW PUMP 1A FAN COIL TS
W STRAINER 1A2 W STRAINER 1B1 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PMP CONT PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PMP CONT PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rin FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clnt Pmp 1B Clg Wtr Rtm FC WITCH-AFW PUMP 1A FAN COIL TS
W STRAINER 1B1 W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PMP CONT PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PMP CONT PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rin FCU 1B discharge Air TS witch - Battery Rin FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clint Pmp 1B Clg Wtr Rtm FC WITCH-AFW PUMP 1A FAN COIL TS
W STRAINER 1B2 W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PMP CONT PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PMP CONT PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rm FCU 1B discharge Air TS witch - Battery Rm FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clnt Pmp 1B Clg Wtr Rtm FC WITCH-AFW PUMP 1A FAN COIL TS
W-AUX FW PMP 1A LUBE OIL PERMISSIVE PS W-AUX FW PMP 1B AUX LUBE OIL PMP CONT PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PMP CONT PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rin FCU 1B discharge Air TS witch - Battery Rin FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clnt Pmp 1B Clg Wtr Rtrn FC WITCH-AFW PUMP 1A FAN COIL TS
W-AUX FW PMP 1B AUX LUBE OIL PMP CONT PS W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PMP CONT PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rin FCU 1B discharge Air TS witch - Battery Rin FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clnt Pmp 1B Clg Wtr Rtm FC WITCH-AFW PUMP 1A FAN COIL TS
W-AUX FW PMP 1B LUBE OIL PERMISSIVE PS W-TD FW PMP AUX LUBE OIL PMP CONT PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rin FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch- Reac Clnt Pmp 1B Clg Wtr Rtrn FC WITCH-AFW PUMP 1A FAN COIL TS
W-TD FW PMP AUX LUBE OIL PMP CONT PS witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rm FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch - Reac Clnt Pmp 1B Clg Wtr Rtrn FC WITCH-AFW PUMP 1A FAN COIL TS
witch - AFW PMP 1A Lube Oil Perm PS witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rin FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch- Reac Clnt Pmp 1B Clg Wtr Rtrn FC WITCH-AFW PUMP 1A FAN COIL TS
witch - AFW PMP 1B Lube Oil Perm PS witch - Battery Rm FCU 1B discharge Air TS witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch- Reac Clnt Pmp 1B Clg Wtr Rtrn FC WITCH-AFW PUMP 1A FAN COIL TS
witch - Battery Rin FCU IB discharge Air TS witch - MN Stm Hdr IA Controlled Relief PS witch - MN Stm Hdr IB Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch- Reac Clnt Pmp IB Clg Wtr Rtm FC WITCH-AFW PUMP IA FAN COIL TS
witch - MN Stm Hdr 1A Controlled Relief PS witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch- Reac Clnt Pmp 1B Clg Wtr Rtrn FC WITCH-AFW PUMP 1A FAN COIL TS
witch - MN Stm Hdr 1B Controlled Relief PS witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch- Reac Clnt Pmp 1B Clg Wtr Rtm FC WITCH-AFW PUMP 1A FAN COIL TS
witch - TDAFW Pmp Lube Oil Press Perm PS witch - TDAFW PMP Lube Oil Press Perm PS witch- Reac Clnt Pmp 1B Clg Wtr Rtrn FC WITCH-AFW PUMP 1A FAN COIL TS
witch - TDAFW PMP Lube Oil Press Perm PS witch- Reac Clnt Pmp 1B Clg Wtr Rtm FC WITCH-AFW PUMP 1A FAN COIL TS
witch- Reac Clnt Pmp IB Clg Wtr Rtm FC WITCH-AFW PUMP IA FAN COIL TS
WITCH-AFW PUMP 1A FAN COIL TS
WITCH-REAC CLNT PMP IA CLG WTR RTRN FC
WITCH-TURB BLDG FAN COIL UNIT IA TS
WITCH-TURB BLDG FAN COIL UNIT 1B TS
ANK REFUELING WATER STORAGE TANK
ERM BOX FOR CNTMT COOLING TRN A LOCKOUT RELAY
ERM BOX FOR CNTMT COOLING TRN B LOCKOUT RELAY
ERM BOX-TB1279 TB AUX RELAY BOX FOR SWITCHGEAR BUS 1-3
ERM BOX-TB1371-TB FOR SV33261, SV33270 FUTURE
erminal Box - TB1282 - Aux Relay Box for Switchgear Bus 1-61
RANSMITTER - CC PUMP DISCH PRESS XMTR

Table 3-3
SPRA Equipment/Component List-Screened at Surrogate Level
Component Description
TRANSMITTER - RXCP A SEAL WATER HI RANGE FLOW XMTR
TRANSMITTER - RXCP A SEAL WATER LO RANGE FLOW XMTR
TRANSMITTER - RXCP B SEAL WATER HI RANGE FLOW XMTR
TRANSMITTER - RXCP B SEAL WATER LO RANGE XMTR
TRANSMITTER - SG IA LVL IND XMTR
Transmitter - SG 1A LVL Ind XMTR
TRANSMITTER - SG IB LVL IND XMTR
Transmitter - SG IB LVL Ind XMTR
Transmitter - Vol Cont Tank Ref Line P Xmtr
TRANSMITTER-BORIC ACID TANK IA L XMTR
TRANSMITTER-BORIC ACID TANK IA L XMTR
TRANSMITTER-BORIC ACID TANK IA L XMTR
TRANSMITTER-BORIC ACID TANK IA L XMTR
TRANSMITTER-BORIC ACID TANK 1A L XMTR
TRANSMITTER-BORIC ACID TANK 1A L XMTR
TRANSMITTER-BORIC ACID TANK IA L XMTR
TRANSMITTER-BORIC ACID TANK IB L XMTR
TRANSMITTER-CHG PMPS DSCH TO REGEN HT EXGR F XMTR
TRANSMITTER-CNTMT PRESSURE NO 1A1 DIFF P XMTR
TRANSMITTER-CNTMT PRESSURE NO 1A2 DIFF P XMTR
TRANSMITTER-CNTMT PRESSURE NO 1A3 DIFF P XMTR
TRANSMITTER-CNTMT PRESSURE NO 1B1 DIFF P XMTR
TRANSMITTER-CNTMT PRESSURE NO 1B2 DIFF P XMTR
TRANSMITTER-CNTMT PRESSURE NO 1B3 DIFF P XMTR
TRANSMITTER-PRESS. TRANSMITTER P-21006
TRANSMITTER PRESSURE TRANSMITTER P-21005 SW TRAIN A DISCH PRES
TRANSMITTER-PRESSURE TRANSMITTER PT-922 (INJECTION LINE A)
TRANSMITTER-PRESSURE TRANSMITTER PT-923 (INJECTION LINE B)
TRANSMITTER-PRESSURE TRANSMITTER SGIA PT-460
TRANSMITTER-PRESSURE TRANSMITTER SGIA PT-468
TRANSMITTER-PRESSURE TRANSMITTER SGIA PT-482
TRANSMITTER-PRESSURE TRANSMITTER SGIB PT-479
TRANSMITTER-PRESSURE TRANSMITTER SGIB PT-483
TRANSMITTER-PRESSURE TRANSMITTER WIDE RANGE RCS LOOP A (PT-419
TRANSMITTER-PRESSURE TRANSMITTER WIDE RANGE RCS LOOP A (PT-420
TRANSMITTER-PRESSURIZER RELIEF TANK PRESSURE TRANSMITTER PT-44
TRANSMITTER PRZR LEVEL XMTR
TRANSMITTER-PRZR LEVEL XMTR IA
TRANSMITTER-PRZR PRESSURE XMTR 1A
IRANSMITTER-PRZR PRESSURE XMTR 1B

Table 3-3
SPRA Equipment/Component List-Screened at Surrogate Level
Component Description
TRANSMITTER-PRZR PRESSURE XMTR 1C
TRANSMITTER-PRZR RELIEF TANK LVL XMTR
TRANSMITTER-RESID HT REML PMP 1A DSCH P XMTR
TRANSMITTER-RESID HT REML PMP 1B DSCH P XMTR
TRANSMITTER-RWST LVL XMTR
TRANSMITTER-RWST LVL XMTR
TRANSMITTER-RXCP A NO. 1 SEAL INS. FLOW XMTR
TRANSMITTER-RXCP B NO. 1 SEAL INS. FLOW XMTR
TRANSMITTER-SFTY INJ PMP IA DISH F XMTR
TRANSMITTER-STM GEN 1A L XMTR
TRANSMITTER-STM GEN 1A L XMTR
TRANSMITTER-STM GEN 1A L XMTR (LT-461)
TRANSMITTER-STM GEN 1B L XMTR
TRANSMITTER-STM GEN 1B L XMTR
TRANSMITTER-STM GEN 1B L XMTR 1 T-471)
TRANSMITTER-TEMP XMTR COLD LEG CS LOOP (TE-450B)
TRANSMITTER-VOL CONTROL TANK LVL
TRANSMITTER-VOL CONTROL TANK LVL
Turbine Oil Storage Tank
VALVE- MTR OPER-COMPONENT COOLING HX IA INLET
VALVE- SG A MSIV BYPASS
VALVE-CHECK-MAIN STEAM ISOLATION VALVE ASSEMBLY-GEN 1A
VALVE-CHECK-MAIN STEAM ISOLATION VALVE ASSEMBLY-GEN 1B
VALVE-CONTROL-AUX FEEDWATER PUMP 1B FLOW CONTROL VALVE VALVE-CONTROL-CC610A/CV31127 RXCP A THERMAL BARRIER
VALVE-CONTROL-CC610B/CV31128 RXCP B THERMAL BARR COMP CLG RT VALVE-CONTROL-CNTMT CLG SW RETURN HEADER 1A MV
VALVE-CONTROL-CNTMT CLG SW RETURN HEADER 1D MV VALVE-CONTROL-CONDENSATE EMERGENCY MAKE-UP CONTROL STATION
VALVE-CONTROL-CONDENSATE EMERGENCY MARE-UP CONTROL STATION
VALVE-CONTROL-CONTAINMENT SUMP TO DH NO.1
VALVE-CONTROL-CONTAINMENT SUMP TO DH NO.T
VALVE-CONTROL-HEADER IA SHROUD COOLING COIL C/D BYPASS
VALVE-CONTROL-HEADER TA SHROUD COOLING COIL A/B BIPASS
VALVE-CONTROL-HEADER ID SHROUD COOLING COIL A/B BIPASS
VALVE-CONTROL-HEADER 1D SHROOD COOLING COIL C/D BIPASS
VALVE-CONTROL-ICS207/CV31273 ICS RECIRCULATION TO RWST
VALVE-CONTROL-LOCA100B/CV31725 POST LOCA H2 TO RECOMBINER B
VALVE-CONTROL-LOCA201B/CV31727 POST LOCA H2 TO RECOMBINER B
VALVE-CONTROL-MAIN STM CONTROLED RELIEF VALVE STM HDR 1B
AT A D COMPRODUMENT OF ME COMPRODED ALLER AND A D OTHER TONE IN TO

Table 3-3
SPRA Equipment/Component List-Screened at Surrogate Level
Component Description
VALVE-CONTROL-MAIN STM CONTROLLED RELIEF VALVE STM HDR IA
VALVE-CONTROL-PRESSURIZER TO PRESSURIZER RELIEF TANK
VALVE CONTROL-PRESSURIZER TO PRESSURIZER RELIEF TANK
VALVE-CONTROL-REAC COOLANT TO DH NO.1
VALVE-CONTROL-REAC COOLANT TO DH NO.1
VALVE-CONTROL-REACTOR COOLANT PUMP 1A SEAL WATER OUTLET
VALVE-CONTROL-REACTOR COOLANT PUMP IB SEAL WATER OUTLET
VALVE-CONTROL-REGEN. HEAT EXCH. CHARGING LINE
VALVE-CONTROL-RHR8A/CV31114 RHR HEAT EXGR A FLOW CV
VALVE-CONTROL-RHR8B/CV31115 RHR HEAT EXGR B FLOW CV
VALVE-CONTROL-SA7003B/MV32148 HYDROGEN DILUTION TO CONTAINMN
VALVE-CONTROL-SEAL WTR INJECTION BYPASS BLOCK CV
VALVE-CONTROL-SERVICE WATER FROM DIESEL GEN, OIL COOLER
VALVE-CONTROL-SERVICE WATER HEADER ISOLATION
VALVE-CONTROL-SERVICE WATER TO TURBINE BUILDING
VALVE-CONTROL-SERVICE WATER TO TURBINE BUILDING
VALVE-CONTROL-SI101A/CV31247 SI PUMP MAKEUP TO ACCUMUL A
VALVE-CONTROL-SI101B/CV31248 SI PUMP MAKEUP TO ACCUM B
VALVE-MTR OPER-AFW10B/MV32028 AFW TRAIN B CROSSOVER VALVE
VALVE-MTR OPER-AUX FEEDWATER PUMP 1A
VALVE-MTR OPER-AUX FEEDWATER PUMP 1B
VALVE-MTR OPER-AUX FW PUMP 1A DISCH X-OVER MV
VALVE-MTR OPER-BORIC ACID FILTER (STA. 1)
VALVE-MTR OPER-BT2A/MV32077 S/9 A BLOWDOWN ISOL VALVE A1
VALVE-MTR OPER-BT2B/MV32079 S/G B SLOWDOWN ISOL VALVE BI
VALVE-MTR OPER-BT3A/MV32078 S/G A BLOWDOWN ISOL VALVE A2
VALVE-MTR OPER-BT3B/MV32080 S/G B BLOWDOWN ISOL VALVE B2
VALVE-MTR OPER-CC400A/MV 32119 COMP COOLING TO RHR HT EXCH A
VALVE-MTR OPER-CC400B/MV32120 COMP COOLING TO RHR HT EXCH B
VALVE-MTR OPER-CC600/MV32088 CC TO RXCPS AND EXCHS LD HX
VALVE-MTR OPER-CC601A/MV32084 COMP COOLING TO RXCP A
VALVE-MTR OPER-CC601B/MV32085 COMP COOLING TO RXCP B
VALVE-MTR OPER-CC612A/MV32086 RXCP A COMP CLG RETURN ISOL
VALVE-MTR OPER-CC612B/MV32087 RXCP B CC RETURN ISOL
VALVE-MTR OPER-CC6A/MV 32121 COMP COOLING HT EXCH A OUTLET
VALVE-MTR OPER-CC6B/MV32122 COMP COOLING HT EXCH B OUTLET
VALVE-MTR OPER-CVC211/MV32124 RXCP SEAL WTR RETURN ISOLATION
VALVE-MTR OPER-ICS2A/MV32406 CNTMT SPRAY PMP A SUCT FRM RWST
VALVE-MTR OPER-ICS2B/MV32407 CNTMT SPRAY PMP B SUCT FRM RWST
VALVE-MTR OPER-ICS5A/MV32066 CNTMT SPRAY PMP A DISCH ISOL

Table 3-3
SPRA Equipment/Component List-Screened at Surrogate Level
Component Description
VALVE-MTR OPER-ICS5B/MV32068 CNTMT SPRAY PMP B DISCH ISOL
VALVE-MTR OPER-ICS6A/MV32067 CNTMT SPRAY PMP A DISCH ISOL
VALVE-MTR OPER-ICS6B/MV32069 CNTMT SPRAY PMP B DISCH ISOL
VALVE-MTR OPER-MS100A/MV32038 S/G A STM SPLY TO T/D AFW PUMP
VALVE-MTR OPER-MS100B/MV32039 S/G STM SUPPLY TO T/D AFW PMP
VALVE-MTR OPER-MS102/MV32040 T/D AFW PUMP MAIN SIM ISOL
VALVE-MTR OPER-MS2B/32008 S/G MSIV BYPASS VALVE
VALVE-MTR OPER-PEN. NO. 14 N EL. 616'-11 15/16 INCH
VALVE-MTR OPER-PRIA/MV32089 PRESSURIZER PORV BLOCK VALVE
VALVE-MTR OPER-PRIB/MV32090 PRESSURIZER PORV BLOCK VALVE
VALVE-MTR OPER-R.W. INLET AT CHARGING PUMP
VALVE-MTR OPER-RHR11/MV32118 RHR DISCHARGE TO RCS LOOP B
VALVE-MTR OPER-RHRIA/MV32116 RCS LOOP A SUPPLY TO RHR PUMPS
VALVE-MTR OPER-RHRIB/MV32132 RCS LOOP B SUPPLY TO RHR PUMPS
VALVE-MTR OPER-RHR2A/MV32117 RCS LOOP A SUPPLY TO RHR PUMPS
VALVE-MTR OPER-RHR2E/MV32133 RCS LOOP B SUPPLY TO RHR PUMPS
VALVE-MTR OPEP-RHR300A/MV32134 RHR PMP A SUPPLY TO SI PMP A
VALVE-MTR OPER-RHR300B/MV32135 RHR PMPB SUPPLY TO SI PMP B
VALVE-MTR OPER-RHR400A/MV32125 RHR PMP A SUPPLY TO ICS PMP A
VALVE-MTR OPER-RHR400B/MV32126 RHR PMP B SUPPLY TO ICS PMP B
VALVE-MTR OPER-SI208/MV32131 SI RECIRCULATION TO RWST
VALVE-MTR OPER-SI209/MV32130 SI RECIRCULATION TO RWST
VALVE-MTR OPER-SI2A/MV32104 BORIC ACID TANK OUTLET ISOLATION
VALVE-MTR OPER-SI2B/MV32105 BORIC ACID TANK OUTLET ISOLATION
VALVE-MTR OPER-SI300A/MV32111 RWST SUPPLY TO RHR PUMP A
VALVE-MTR OPER-SI300B/MV32112 RWST SUPPLY TO RHR PUMP B
VALVE-MTR OPER-SI302B/MV32101 RHR PUMP B INJN TO REAC VESSEL
VALVE-MTR OPER-SI350A/MV32102 CNTMT SUMP B SPLY TO RHR PMP A
VALVE-MTR OPER-SI350B/MV32103 CNTMT SUMP B SPLY TO RHR PMP B
VALVE-MTR OPER-SI351A/MV32113 CNTMT SUMP B SPLY TO RHR PMP A
VALVE-MTR OPER-SI4A/MV32109 RWST SUPPLY SI PUMPS
VALVE-MTR OPER-SI4B/MV32110 RWST SUPPLY TO SI PUMPS
VALVE-MTR OPER-SI5A/MV32107 SI PUMP A SUCTION ISOLATION
VALVE-MTR OPER-SI5B/MV32108 SI PUMP B SUCTION ISOLATION
VALVE-MTR OPER-TURBINE DRIVEN AUX. FEEDWATER PUMP
VALVE-MTR OPER-VOLUME CONTROL TANK - OUTLET
VALVE-RELIEF-CHARGING PUMP 1A DISCH RELIEF
VALVE-RELIEF-CHARGING PUMP IB DISCH RELIEF
VALVE-RELIEF-CHARGING PUMP IC DISCH RELIEF
VALVE-RELIEF-PRESSURIZER SAFETY RELIEF TO PRSZR RELIEF TANK

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 152 of 415

Table 3-3
SPRA Equipment/Component List-Screened at Surrogate Level
Composent Description
VALVE-RELIEF-PRESSURIZER SAFETY RELIEF TO PRSZR RLF TNK
VALVE-RELIEF-SAFETY TO ATMOS-STEAM GEN 1B
VALVE-SI302A/MV32100 RHR PUMP A INJECTION TO REACTOR VESSEL
VALVE-SI351B/MV32114 CNTMT SUMP B SUPPLY TO RHR PUMP B
VALVE-SOLENOID-DG RM 1A DMPR CONTROL SV 1A3
VALVE-SOLENOID-DG RM 1A DMPR CONTROL SV 1A4
VALVE-SOLENOID-DG RM 1B DMPR CONTROL SV 1B3
VALVE-SOLENOID-DG RM 1B DMPR CONTROL SV 1B4
XMITTER-AUX FW TO STM GEN 1A F XMTR
XMITTER-AUX FW TO STM GEN 1B F XMTR

Table 3-4         EQUIPMENT OUTLIERS         IPEEE WALKDOWN RESULTS			
EQUIPMENT DESCRIPTION	FINDING	RESOLUTION	
Motor Control Centers MCC52F & MCC52FEXT.	Adjacent MCC's not bolted together, which may pose an interaction hazard based on relay chatter concerns.	Cabinet displacements during a design basis seismic event were determined. The evaluation concluded that the cabinets will not impact.	
Diesel Generator Excitation & Control Cabinets DR101 & DR111.	Several fasteners on cast-in-place anchors were found missing. An overhead emergency light posed an interaction hazard to DR101.	Missing fasteners were replaced during the 1992 refueling outage and restraint installed on emergency light during 1993 outage.	
Station Service Transformers 51, 52, 61 & 62.	Transformer cabinets were found anchored to the floor with friction clips, which are considered undesirable according to A-46 walkdown guidelines.	A design change was initiated to have the transformer cabinet bases welded to embedded floor channels. Transformers 51 and 52 were modified during the 1994 refueling outage. Transformers 61 and 62 are scheduled for modification during a later refueling outage.	
Relay Racks RR186 & RR187.	The relay racks are not bolted to adjacent panels, which may pose an interaction hazard based on relay chatter concerns.	An engineering support request was initiated to have the racks bolted together to eliminate the concern. A schedule for completion has not been determined.	
Reactor Trip Breaker Cabinet RD106.	Several anchor bolts which connect cabinet to embedded channel were found missing.	A design change was initiated to have the cabinet sections welded to the embedded channel in lieu of installing bolts. Work was completed during the 1993 refueling outage.	

Table 3-4 EQUIPMENT OUTLIERS IPEEE WALKDOWN RESULTS		
EQUIPMENT DESCRIPTION	FINDING	RESOLUTION
SI Pump B Suction Isolation Valve SI5B.	One leg of a Unistrut frame is within 1/2" of the valve motor, which may present an interaction hazard.	IE Bulletin 79-14 pipe stress evaluation determined that displacement of the pipe and valve is approximately 1/8". Issue considered resolved.
Main Steam Header 1A Controlled Relief Valve SD3A.	Valve actuator and yoke are independently braced.	An analysis was performed to qualify support configuration as-is.
SI Pump Makeup Valve SI101B to Accumulator.	Actuator and yoke are independently braced.	An analysis was performed to qualify support configuration as-is.
Aux Feedwater Pump Lube Oil Pressure Switches 16016, 16019 & 16085.	All three switches identified as Mercoids, which are considered outliers for the A-46 program.	A design modification was previously initiated to have the switches replaced for other reasons. Modification completed in 1993.
Flux Mapping Transfer Cart (GI-131 Issue).	Two concerns identified; (1) lateral restraints for the 10-path assembly frame were never installed, and (2) chain hoist on overhead rail identified as a possible interaction hazard to 10-path assembly.	It was determined by analysis that lateral restraints are not required to support 10-path assembly under seismic loads. Administrative controls were implemented to restrain hoist at the fixed end of crane rail and required to be functional when not in use.
Overhead Fluorescent Lights.	Generic problem throughout safety-related areas of the plant. S-hooks on the chains supporting the lights are not closed, presenting a possible interaction hazard to equipment below.	A plant walkdown was conducted during the 1994 refueling outage to pinch the S-hooks closed.

Table 3-4 EQUIPMENT OUTLIERS IPEEE WALKDOWN RESULTS		
EQUIPMENT DESCRIPTION	FE	RESOLUTION
Emergency Lights.	Some of the lights were found to not have seismic restraints installed, presenting a possible interaction hazard to equipment below.	Lights and battery units strapped to supports as required during 1994 refueling outage.
480V Switchgear Bus 62.	An empty spare breaker cabinet was used for parts storage, presenting a possible interaction hazard on the basis of relay chatter concerns.	Maintenance department notified of problem. Spare parts were removed and all other spare breaker cabinets were inspected for similar problems during 1993 refueling outage.
Control Room Ceiling.	Aluminum ceiling diffuser panels were considered as a possible hazard to operators if the diffusers were to dislodge from T-bar supports.	An engineering support request was initiated to have the diffuser panels tie-wrapped to the T-bar supports. A schedule for completion has not been determined.
Control Room Vertical Panel C.	Rear doors on panel could not be latched shut due to interference with cables which extend from rear of cabinet. Unlatched doors present possible interaction hazard on basis of relay chatter.	It was determined that the cables were temporarily in place to support radiation monitoring modifications. Doors could not impact with cabinet because of cable interference. Operations department agreed to latch doors shut following completion of work during 1994 refueling outage.
All Equipment	Possible interaction hazards due to loose or unrestrained portable equipment.	Plant procedure GNP 1.31.1 drafted to provide guidelines for control of portable equipment. Full implementation occurred June 1, 1994.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 156 of 415

----

TABLE 3-5 COMPONENTS AND STRUCTURES USED TO DETERMINE PLANT STATUS FOLLOWING A SEISMIC EVENT	
Containment Building	
Reactor Pressure Vessel	
Reactor Pressure Vessel Supports	
Switchyard Ceramic Insulators	
Auxiliary Building	
Turbine Building	
Screenhouse	
Steam Generators	
Steam Generator Supports	
Pressurizer	
Pressurizer Supports	
Reactor Coolant Pumps	
Reactor Coolant Pump Supports	
Control Rod Drive Mechanism	
Reactor Core Upper Internals	
Reactor Coolant System Piping	
Reactor Coolant Pump Seals	
Secondary Side Piping and Supports	

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 157 of 415

TABLE 3-6 DESCRIPTION OF SEISMIC EVENT TREE NODES							
FRONTLINE SYSTEMS							
EVENT TREE NODE	DESCRIPTION						
SXACC	Safety Injection Accumulators						
SXLI1, SXLI2	Low Pressure Injection System						
SXLR1, SXLR2, SXLR3	Low Pressure Recirculation System						
SXHIO, SXHI2, SXHI3	High Pressure Injection System						
SXAFI, SXAF3	Auxiliary Feedwater System						
SXCHG	Chemical and Volume Control System						
SXISI	Main Stream Isolation						
SXOP1, SXOP2	Operator Cooldown and Depressurize RCS						
SUPP	ORT SYSTEMS						
SXRPS	Engineered Safeguards Actuation System Including 120V AC Instrument Power						
SXCCW	Component Cooling Water System						
SXSWS**	Service Water System						
SXDCP**	125V DC Electrical System						
SXACP**	4160V AC Electrical System, 480V AC Electrical System, Emergency Diesel Generators						

\*\* Fault trees used in the seismic initiating events tree Figure 3.4

#### Table 3-7

### Kewaunee SPRA Results

Result	Value
Seismic Core Damage Frequency	1.10E-05
Plant Median Capacity (PGA(g))	0.38g
Plant High Confidence of a Low Probability of Failure (HCLPF) (PGA(g))	0.23

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 159 of 415

#### Table 3-8

Summary	of	the	Plant	Level	Fragility
---------	----	-----	-------	-------	-----------

Conditional Probability of Failure	PGA (g)
0.05	0.293
0.15	0.344
0.25	0.364
0.50	0.377
0.75	0.452
0.85	0.512
0.95	0.611
HCLPF <sup>1</sup>	0.228

Assuming the plant fragility curve is lognormal, the HCLPF corresponds to a 0.011% probability of failure

## Table 3-9

Seismic Sequence <sup>1</sup>	Mean Annual Core Damage Frequency	Percent
SCSF	3.60E-06	32.70
SSWS	1.99 <b>E</b> -06	18.08
SRVB	1.74E-06	15.76
SLSP01	1.35E-05	12.25
SACP	1.26 <b>E</b> -06	11.40
SDCP	3.48E-07	3.16
SRDF	2.09E-07	1.90
SSLB06	1.08 <b>E</b> -07	0.98
SLLO04	9.34E-08	0.85
SLLO19	7.65E-08	0.69
SSLO09	4.90E-08	0.44
SLLO01	4.04E-08	0.37
SLLO02	C €0E-08	0.24
SSLO11	08	0.21
SLL()()3	· 4E-08	0.16
SSL012	1.58E-08	0.14
SSL014	1.46E-08	0.13
SSL(0)1	1.35 <b>E</b> -08	0.12
SSL(0)2	9.17 <b>E</b> -09	0.08
SSL004	8.15E-09	0.07
<b>SSL</b> O10	6.77 <b>E</b> -09	0.06
SSLO20	5.03E-09	0.05
SML009	<b>4</b> .70 <b>E</b> -09	0.04
SLSP02	3.25E-09	0.03
SSLB05	2.91E-09	0.03

#### Table 3-9 (cont.)

#### Contribution of Individual Accident Sequences Towards the Total Plant Risk

Seismic Sequence <sup>1</sup>	Mean Annual Core Damage Frequency	Percent
SMLO01	1.29E-09	0.01
SSLB04	1.08 <b>E</b> -09	0.01
SMLO02	8.68 <b>E</b> -10	0.01
SMLO05	6.35E-10	0.01
SSLO13	4.03E-10	0.00
SSLB01	3.40E-10	0.00
SSLO03	2.34E-10	0.00
SSLB02	2.28E-10	0.00
SSLB03	2.28E-10	0.00
SSLO08	1.77 <b>E-</b> 10	0.00
SSLO18	1.53 <b>E</b> -10	0.00
SMLO04	1.48E-10	0.00
SSLO07	6.57E-11	0.00
SSLO17	5.90E-11	0.00
SSLO06	4.44E-11	0.00
SSLO05	4.38E-11	0.00
SSLO16	4.08E-11	0.00
SSLO15	4.07E-11	0.00
SML003	2.22E-11	0.00
SMLO08	1.30E-11	0.00
SMLO06	4.20E-12	0.00
SMLO07	3.24E-12	0.00
Total	1.10E-05	100.00

<sup>1</sup> See the seismic event trees in Figures 3-4 through 3-9.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 162 of 415 Dominant Sequences

Sequence	Description	Important Components
SCSF	Failure of the Containment or Steam Generator. These components have been screened out and are modeled by the surrogate element.	Surrogate Component
SSWS	Failure of the service water system occurs due to failure of the Intake Structure valves (air or motor operated, check valves, pumps, etc.)	Intake Structure (Surrogate Component). All other components have a median capacity of 0.95g or greater.
SRVB	Failure of the Screenhouse, Auxiliary Building, Turbine Building, or Reactor Vessel. These structures have been screened out and are modeled by the surrogate element.	Surrogate Component
SLSP01	Loss of off-site power, and the Auxiliary Feedwater System.	Operator Error Surrogate Component
SACP	Failure of the emergency AC power system occurs, which includes the diesel generators and supporting equipment.	Surrogate Component All components have a median capacity of 1.05g and higher.
SDCP	DC power system fails which includes the station batteries, diesel generators, cable trays, etc.	Surrogate Component All components have a median capacity of 1.05g and higher.

#### Table 3-11

Case	Description	Core Damage Frequency	Plant Median (g)	HCLPF (g)
Base Case	EPRI Seismic Hazard Curve Used to Estimate CDF	1.10E-05	0.38	0.23
1	LLNL (NUREG-1488) <sup>1</sup> Seismic Hazard Curve Used to Estimate CDF	1.15E-05	0.38	0.23
2	Random Failure and Operator Action Probabilities Set to 0.0	9.27 <b>E</b> -06	0.43	0.26
3	Random Failure Probabilites Increased By an Order of Magnitude	2.35E-05	0.35	0.10 <sup>2</sup>
	Random Failure Probabilities Reduced By an Order of Magnitude	1.06 <b>E</b> -05	0.38	0.25
4	Operator Action Probabilities Increased By an Order of Magnitude	1.15 <b>E</b> -05	0.38	0.20
	Operator Action Probabilities Reduced By an Order of Magnitude	1.10 <b>E</b> -05	0.38	0.25
5	Surrogate Component Capacity Set to 2.0g	9.66 <b>E</b> -06	0.38	0.23
6	Operator action - Shift AFW from CST to SWS probability set to 0.0	9.95 <b>E</b> -06	0.42	0.23
7	SW System screen capacity set to 3.0g	1.07E-05	0.38	0.24

#### Summary of Kewaunee SPRA Sensitivity Analysis Results

<sup>&</sup>lt;sup>1</sup>Plant model is the same is the base case.

<sup>&</sup>lt;sup>2</sup>See text for a discussion of this HCLPF estimate.

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 164 of 415

#### Table 3-12

#### CET **End State** Release **End State** Catagory Frequency HAAAA 1.68E-07 S S HAAFA 3.96E-09 S HAFAA 8.76E-09 HAFFA 1.68E-10 S S **HFFAA** 1.16E-06 HFFFA 3.03E-06 Α G HAAAF 4.86E-09 HAFAF G 2.51E-10 **HFFAF** 1.42E-07 G HFFFF 7.48E-07 G U LFFFF 5.34E-06

#### **CET End States and Frequencies**

#### Notes:

1. End States are given the following identifier:

PLIFC Where:

P = H for high pressure (>400 Psia) reactor vessel failure,

L for low pressure vessel failure.

- L = A if low pressure recirculation is available, F if it has failed.
- I = -A if containment spray is available, F if it has failed.

F = A if containment fan coil units are available, F if they have failed.

- C = A if containment is isolated, F if isolation has failed.
- 2. Release catagories are defined in Table 3-13.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 165 of 415

#### **TABLE 3-13**


#### **KEWAUNEE NUCLEAR PLANT SPRA** AIRBORNE RELEASE CATEGORIES AND PROBABILITIES


Release Category	Definition	Frequency	Conditional Probability <sup>1,2</sup>
S	No containment failure (leakage only, successful maintenance of containment integrity; containment not bypassed; isolation successful)	1.35E-06	0.13
U	Containment failure prior to vessel failure with noble gases and more than 10% of the volatiles released (containment isolation impaired)	5.34E-06	0.50
G	Containment failure prior to vessel failure with noble gases and up to 10% of the volatiles released (containment isolation impaired)	8.96E-07	0.08
A	No containment failure within 48 hr mission time, but failure could eventually occur without accident management action; noble gases and less than 0.01% volatiles released	3.03E-06	0.29

#### NOTES:


6. <sup>3°</sup>

- Conditional probability of release category given core damage.
   Core damage frequency for Level 2 = 1.06x10<sup>-5</sup>/yr.






3-93




Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 168 of 415 Figure 3-3 Small and Medium E 2ak LOCA (Figure 3.6 - NUREG/CR-4840)



## Enclosure - 0% Attachment 1 Volume 05 (Section 3.0) Page 169 of 415

														<b>.</b>		••••••••••••••••••••••••••••••••••••••					
	-	1.04	· · · · ·				- 1	f *		$1 \mathbf{i} \mathbf{c}$		117		· · · · · · · · · · · · · · · · · · ·	1 mm	· · · · · · · · · · · · · · · · · · ·			·		1
					1			1				11	1	11 1		11 . i	11	[] ]		1	1
1	SD	- 11	CSI		1.	8 VB		1	OSP	111	ACP	11	SWS	DCP	RCF	ROD	I MOPIO I	SPB	SEAL	SSP	1
1		- 11	:							111		11		11 1					· · · · · · · · · · · · · · · · · · ·		4
1.4		. 11	1 _	:	1		- 1			յլե	·	1-		j L J	i	L	Luna merenada	has a second	he		1
					1.				COLUMN 117 MIL	- <b>-</b> -	THE R P. LEWIS CO., Name of Street, or other		mentanes were and	A					and the second second second	and the second se	




\*\* With Off Sim Awer Not Explicitly Modeled

· Sequence Continues On Associated Seismic Erent True


Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 170 of 415

#### FIGURE 3-5 SEISMIC LARGE LOCA EVENT TREE

SLLO	sxccw	SXRPS	SXLII	SXLRA



# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 171 of 415



## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 172 of 415









FIGURE 3-8 SEISMIC LOSS OF OFF SITE POWER EVENT TREE




# Enclosure - Q&A to Attachment 1. Volume 05 (Section 3.0) Page 174 of 415




#### Figure 3-10 Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 175 of 415 SHIP FLOW CHART




CD5 Care Dumage Frequency





Enclosure - Q&A to Attachment 10 Volume 05 (Section 3.0) Page 177 of 415





Enclosure - Q&A to Attachment divolume 05 (Section 3.0) Page 178 of 415














Enclosure - Q&A to Attachmented Volume 05 (Section 3.0) Page 182 of 415







Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 185 of 415



Enclosure - Q&A to Attachment Volume 05 (Section 3.0) Page 186 of 415



3-113



Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 188 of 415

٠

# 4. Fire Hazards Analysis

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 189 of 415

# **SECTION 4**

# FIRE HAZARDS ANALYSIS

### TABLE OF CONTENTS

# **SECTION**

4. Fire Hazards Analysis	
4.0 Methodology Selection	
4.1 Fire Hazards Analysis	
4.1.1 Definitions and Assumptions	
4.1.2 Containment Fires	
4.1.3 Evaluation of Fire-Induced Initiating Events	
4.1.4 Screening Analysis	
4.1.4.1 Zones containing components required for	
mitigation of fire-induced events	
4.1.4.2 Postulated fires in fire zones	
4.1.4.2.a Fire in dedicated zones	
4.1.4.2.b Fire in alternate zones	
4.1.5 Results of Screening	
4.2 Review of Plant Information and Walkdown	
4.3 Fire Growth and Propagation	
4.3.1 COMPBRN Runs	
4.3.1.1 TU-95A, Switchgear room 5B	
4.3.1.1a Scenario: fire near safeguards 480 V electrical	
bus 52	
4.3.1.2 TU-97, Battery room A (room 129)	. 4-29
4.3.1.2a Scenario: fire near distribution cabinets	
4.3.1.2b Scenario: fire near batteries	. 4-29
4.3.1.3 TU-98, Battery room B (room 130)	. 4-29
4.3.1.3a Scenario: fire near distribution cabinets	
4.3.1.3b Scenario: fire near batteries	. 4-29
4.3.1.4 AX-23A, Auxiliary building (RWST area)	. 4-30
4.3.1.4a Scenario: fire near MCC 35E/45E in fan room	. 4-30
4.3.1.4b Scenario: fire in corridor near MCC 62J	. 4-30
4.3.1.4c Scenario: fire near bottled gas storage at	
elevation 657'-6"	. 4-30
4.3.1.4d Scenario: SI pump oil fire	. 4-30
4.3.1.5 AX-23B, Auxiliary building (reactor auxiliaries	
north center)	. 4-30
4.3.1.5a Scenario: fire near flammable liquid storage	
cabinet at elevation 586'-0"	. 4-30
4.3.1.5b Scenario: fire near bottled gas storage at	
elevation 586'-0"	. 4-31

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 190 of 415

# **SECTION 4**

# FIRE HAZARDS ANALYSIS

### TABLE OF CONTENTS

**SECTION** 

4.3.1.6 TU-90, Diesel generator room A	4-31
4.3.1.6a Scenario: fire near safeguards 4160 V electrical	
bus 5	. 4-31
4.3.1.6b Scenario: fire near MCC 52A	
4.3.1.6c Scenario: diesel engine oil fire	4-32
4.3.1.7 TU-92, Diesel generator room B	
4.3.1.7a Scenario: fire near MCC 62A	
4.3.1.7b Scenario: fire near safeguards 4160 V electrical	
bus 6	4-32
4.3.1.7c Scenario: diesel engine oil fire	
4.3.1.7d Scenario: trash can fire located beneath cable	
travs at north end of room	4-33
4.3.1.8 SC-70A, Screenhouse	
4.3.1.8a Scenario: fire near MCC 35C/45C	
4 3.1.9 AX-30, Relay room	
4.3.1.9a Scenario: fire near vertical cable trays	
4.3.1.9b Scenario: fire near four cabinets	
4.3.1.10 TU-95C, AFW pump A room	
4.3.1.10a Scenario: AFW pump A oil fire	
4.3.1.11 AX-32, Service rooms	
4.3.1.11a Scenario: fire near MCC 62B	
4.3.1.11b Scenario: fire near MCC 62B extension	4-34
4.3.1.11c Scenario: fire in cable spreading area	
4.3.1.12 AX-23D: Component cooling water pump B	
room	4-34
4.3.1.12a Scenario: Component cooling water pun.p B oil	
fire	4-34
4.3.1.13 TU-94: Air compressor A room	4-35
4.3.1.13a Scenario: fire in air compressor A	4-35
4.3.1.13b Scenario: fire beneath cable trays	4-35
4.3.1.14 TU-95B: AFW pump B room and 480 V swgr	
buses 61 and 62 room	4-35
4.3.1.14a Scenario: AFW pump B oil fire	
4.3.1.14b Scenario: fire beneath cable trays north of	
safeguards 480 V electrical bus 62	4-35
4.3.1.14c Scenario: fire between safeguards 480 V	
electrical buses 61 and 62	4-36

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 191 of 415

# **SECTION 4**

# FIRE HAZARDS ANALYSIS

### TABLE OF CONTENTS

# **SECTION**

4.3.1.15 AX-21: 4160 V switchgear room	. 4-36
4.3.1.15a Scenario: fire near non-safeguards 4160 V	
electrical buses 1 and 2	. 4-36
4.4 Evaluation of Component Fragilities and Failure Modes	. 4-37
4.5 Fire Detection and Suppression	
4.5.1 Automatic and Manual Fire Detection and Suppression	4-37
4.6 Analysis of Plant Systems, Sequences, and Plant Responses	. 4-38
4.6.1 Identification of Components Affected by Fire	. 4-38
4.6.2 Determination of Initiating Event Frequency in Each Zone	
Requiring Quantification	. 4-38
4.6.3 Fire-Induced Core Damage Frequency Quantification	4-38
4.6.3.1 FI1: Fire near MCC 62J in AX-23A	4-39
4.6.3.2 FI2: Fire near MCC 62A in TU-92	4-39
4.6.3.3 FI3: Fire in AX-21, near non-safeguards 4160 V	
electrical buses 1 and 2	. 4-39
4.6.3.4 FI4: Diesel fire in TU-92	4-39
4.6.3.5 FI5: Fire in relay room near vertical cable	
trays	
4.6.3.6 FI6: AFW pump A oil fire	
4.6.3.7 FI7: AFW pump B oil fire	4-40
4.6.3.8 FI8: Fire near safeguards 480 V electrical buses	
51 and 52	
4.6.3.9 Core damage timing	
4.6.4 Dominant Fire-Induced Core Damage Sequences	
4.7 Fire-Induced Containment Failures	
4.7.1 Containment Failure Frequency Quantification Procedure	
4.7.2 Quantification Results	
4.8 Treatment of Fire Risk Scoping Study Issues	4-44
4.8.1 Dependency Between Control Room and Remote Shutdown	
Panel Circuitry	4-44
4.8.2 Cable Routing Verification	4-44
4.8.3 Suppression Agent Induced Damage	4-44
4.8.4 Fire Brigade Effectiveness	
4.8.5 Seismic-Fire Interactions	4-45
4.8.5.1 Seismically induced fires	
4.8.5.2 Seismic degradation of fire suppression	
capabilities	4-45

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 192 of 415

# **SECTION 4**

# FIRE HAZARDS ANALYSIS

# TABLE OF CONTENTS

# **SECTION**

4.8.5.3 Inadvertent actuation of fire suppression
systems
4.8.6 Use of Plant Specific Data
4.8.7 Consideration of Uncertainties
4.8.7.1 Uncertainty in generation of fire initiation
frequencies
4.8.7.2 Judgement of fire propagation
4.8.7.3 Fire suppression probabilities
4.8.7.4 Human error calculations
4.8.7.5 COMPBRN calculations
<b>4.8.7.6 Barrier failure</b>
4.8.7.7 Random failure probabilities
4.9 USI A-45 and Other Safety Issues
4.10 Areas of Conservatism
4.11 Summary of Key Findings
4.12 References

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 193 of 415

#### **SECTION 4**

### FIRE HAZARDS ANALYSIS

### LIST OF TABLES

- Table 4-1: Kewaunee Nuclear Power Plant Fire Initiation Frequencies
- Table 4-2: Screening Results, Dedicated and Alternate Zones
- Table 4-3: Area of Influence and Room Area for Each Damage Scenario
- Table 4-4: Fault Tree Identifiers of Damaged Cables and Components
- Table 4-5: Fire Sequences and Their Core Damage Frequencies
- Table 4-6: Airborne Release Cata; pries and Frequencies
- Table 4-7: FI1 Dominant Cutsets
- Table 4-8: FI2 Dominant Cutsets
- Table 4-9: FI3 Dominant Cutsets
- Table 4-10: FI4 Dominant Cutsets
- Table 4-11: FI5 Dominant Cutsets
- Table 4-12: FI6 Dominant Cutsets
- Table 4-13: FI7 Dominant Cutsets
- Table 4-14: FI8 Dominant Cutsets

Table 4-15: Dominant Sequences

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 194 of 415

### **SECTION 4**

#### FIRE HAZARDS ANALYSIS

#### LIST OF FIGURES

- Figure 4-1: AX-23A (FI1) Initiating Event Frequency
- Figure 4-2: TU-92 (FI2) Initiating Event Frequency (MCC 62A Scenario)
- Figure 4-3: AX-21 (FI3) Initiating Event Frequency
- Figure 4-4: TU-92 (FI4) Initiating Event Frequency (Diesel Generator B Scenario)
- Figure 4-5: AX-30 (FI5) Initiating Event Frequency
- Figure 4-6: TU-95C (FI6) Initiating Event Frequency
- Figure 4-7: TU-95B (FI7) Initiating Event Frequency
- Figure 4-8: TU-95A (FI8) Initiating Event Frequency
- Figure 4-9: Transients With Main Feedwater Available Event Tree
- Figure 4-10: Transients Without Main Feedwater Event Tree
- Figure 4-11: Loss of Offsite Power Event Tree
- Figure 4-12: Dedicated Shutdown System Event Tree
- Figure 4-13: Alternate Shutdown System Event Tree

#### 4.0 Methodology Selection

A combination of the Fire Induced Vulnerability Evaluation (FIVE) and a fire probabilistic risk assessment (PRA) was selected as the method to satisfy the NRC request described in GL 88-20, Supplement 4 (Reference 1).

Data and information pertinent to this analysis were collected. This included the Kewaunee Appendix R documentation (References 2 and 3), plant-specific information pertaining to fire events (Reference 4), fire-related procedures (Reference 5), transient combustible control procedures (Reference 6), fire brigade performance (References 7, 8, and 9). Locations of each of the components and their cable routes in the fire zones were determined using general arrangement drawings (Reference 10) and Appendix R information.

Possible fire-induced initiating events were identified in each fire zone based on disabling all components and cabling in the zone.

A screening analysis was then done. A fire destroying everything in each fire zone was postulated. If the fire endangered components modeled in the PRA and required for mitigation of the event initiated by the fire, the zone was retained for further analysis; otherwise it was not considered further in the analysis. A second screening analysis was then done, assuming that the contents of a room or zone would be destroyed, given a fire. Fire ignition frequency was calculated for each of the remaining zones and the contents (components and cables) identified. The ignition frequency was calculated using the method described in the EPRI FIVE methodology (Reference 11). The applicable accident sequences were identified for each zone, based on the supposition that a fire destroyed the contents of the room. The accident sequences were modified using the Westinghouse WALT code (Reference 12), and the core damage frequencies recalculated. The initiating event frequency was changed to the fire ignition frequency, and the failure probabilities of all components or cables located in that room or zone were changed from their random values to 1.0. If the fire-induced core damage frequency did not exceed 1E-06/yr, then that zone was screened from further analysis. 1E-06/yr was selected as the cutoff frequency because this is the value used in FIVE and the EPRI fire PRA methodology for screening purposes. If the core damage frequency exceeded the screening value, then that fire zone was retained for further analysis. The likelihood of fire propagation was also assessed, and affected zones were re-screened.

In conjunction with the frequency of fire initiation, the failure probability of automatic suppression was then factored into development of the initiating event frequency. Remaining zones were then modeled with the COMPBRN IIIe code (Reference 13) to determine heat transfer characteristics and the likelihood of certain components or cables in the zone being damaged, given a fire of a certain size and in a certain location. In order to gather the necessary data for this modeling, the plant was walked down in October of 1992. The following tasks were accomplished:

- Information used in this analysis was verified, and assumptions used in the analysis were confirmed.
- Fire propagation potential was determined and barrier integrity was verified.
- Layout of components and cable trays was verified.

- Three dimensional location information for components and cable trays in each compartment retained for further analysis was obtained. This was used to model fire damage to components and cables using COMPBRN.
- Interviews with plant personnel took place, and the information obtained included suppression system capabilities, likely transient combustibles in zones, and fire brigade training.
- Possible suppression agent induced damage to equipment was identified.
- The potential for interactions between control room and remote shutdown capabilities was examined.
- Possible seismic-fire interactions were identified.

COMPBRN was then run for those zones that remained after the screening analysis to determine if a certain component would be damaged, given a fire of a certain magnitude and in a certain location. Each of the zones was partitioned further into compartments, dependent on spatial separation or heat transfer barriers, to facilitate modeling. The three dimensional measurements of components and cables in the compartment were used to model heat transfer, given a fire, and determine if a component or cable tray would be damaged, given a fire in a certain location. Use of COMPBRN allowed determination of the extent and timing of damage. This made possible reductions in the initiating event frequency, by partitioning the "area of influence" over the compartment or zone area, and allowed credit of manual suppression efforts, if they could occur prior to damage.

COMPBRN was also needed to identify components and cables that would be affected by a postulated fire.

The internal event models were then modified to reflect the fire-induced initiating event frequency and the fire-damaged components. These changes allowed quantification of fire-induced damage in conjunction with random failures, resulting in fire-induced core damage frequency. Each fire scenario was quantified using the WLINK fault tree linking code (Reference 12) to get its own fire-induced core damage frequency. These frequencies were then summed to obtain total fire-induced core damage frequency.

#### 4.1 Fire Hazards Analysis

#### 4.1.1 Definitions and Assumptions

Following are the definitions of some terms used in the Kewaunee Appendix R effort.

- Fire Area. An area segregated from neighboring areas by three hour fire barriers. A fire area delineates the plant locations using the alternate and dedicated methods of safe shutdown available at the Kewaunee Nuclear Power Plant.
- Fire Zone: Fire zones are combined into fire areas. The fire zones at Kewaunee separate safety-related equipment from combustibles, and identify areas having similar fire protection characteristics.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 197 of 415

Fire Compartment:	Fire compartments are contained within fire zones, and are delineated by physical characteristics such as spatial separation or heat transfer barriers such as components. Fire compartments are defined for ease of modeling.
Area of Influence:	Area over which a fire can damage certain components or cables, given

The following assumptions are used in this analysis:

a fire.

- 1. It is assumed that a reactor trip would be generated (either automatically or manually) upon significant fire initiation in zones housing components and cabling required for safe shutdown.
- 2. A 24-hour period is assumed as the base mission time for this analysis. This time is consistent with the internal events analysis and is based on NUREG-1335 (Reference 13).
- 3. Fire-induced disabling of the control room heating ventilation and cooling (HVAC) is not assumed to result in control room uninhabitability. The control room is constantly manned, and a heating or cooling failure would be noticed, and corrective action taken, according to the applicable procedure, in a timely manner.
- 4. It is assumed that fire barriers remain intact for fires of less than rated duration. For instance, it is assumed that a 3-hour fire barrier could withstand a 2-hour fire.
- 5. Motor control centers (MCCs) and other metal-enclosed components are not considered to be vulnerable to a low-intensity external exposure fire. However, unprotected cables entering and exiting the metal-enclosed component are considered to be vulnerable. Low intensity fires internal to the cabinet are assumed to be confined to that cabinet.
- 6. The delineations and boundaries employed in the Appendix R analyses are used in this analysis. They are, however, examined to ensure applicability to this analysis.
- 1. It is assumed that all automatic five suppression systems are sized to effectively mitigate a maximum sized fire.
- 8. It is assumed that the fire brigade failure probabilities account for any fire-induced access difficulties. Fire brigade response times are compared with damage times prior to assigning credit.
- 9. It is assumed that successful automatic suppression is initiated instantaneously upon successful fire detection.
- 10. Cables in conduit are assumed to be protected from thermal damage for a period of one hour. Conduit dissipates radiative heat. If a fire is of greater than 60 minutes in duration, cables in conduit are assumed to be vulnerable to damage.

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 198 of 415

- 11. Instrumentation and control cables at Kewaunee are qualified to IEEE-383 standards. For this analysis, it is assumed that all cables of interest have polyethylene (PE) insulation.
- 12. Information obtained from Appendix R documentation is assumed to be current and valid. A Wisconsin Public Service Corporation internal audit of all this documentation was completed in 1991.
- 13. Appendix R fire barriers are assumed to remain intact under rated fire conditions. Fire loading for all zones was reviewed, and most zones do not contain sufficient combustibles to sustain a fire of duration long enough to challenge the barriers. For those zones with high combustible loadings (e.g., diesel fuel oil day tank rooms, turbine lube oil room), barrier failure and potential propagation is considered.

Where a 20 ft. separation is used to separate zones within the same fire area, it is assumed that this is adequate spatial separation to prevent inter-zonal propagation, if intervening combustibles are not present. The presence, or lack of, intervening combustibles which could allow fire propagation, was determined during the walkdown. It was found that transient combustibles are limited, reducing the chance of inter-zonal propagation.

14. Power cabling throughout Kewaunee is armored, and in trays that are separate from instrumentation and control cabling. This was verified during the walkdown.

#### 4.1.2 Containment Fires

A fire in containment could have severe consequences. However, a damaging hot gas layer resulting from the fire is unlikely to form in most areas of containment due to the large volume inside containment. Vulnerable equipment and cables are located on the lower elevations, where a hot gas layer which could damage cables is not likely to form. Redundant trains of equipment were also found to be segregated such that a single fire plume or hot gas layer would not threaten both trains of equipment.

A large percentage of past fires in nuclear reactor containments have been reactor coolant pump (RXCP) oil fires. These are not likely at Kewaunee due to the installation of the RXCP oil collection system. As described in the Appendix R Design Description, the RXCP lube oil collection system poses no threat to components or cables within containment.

In addition, the combustible loading for containment is low. During maintenance activities, the combustible loading may increase, but Kewaunee has administrative controls to restrict the amount of transient combustibles.

For these reasons, containment fires are concluded to pose no significant threat at Kewaunee.

#### 4.1.3 Evaluation of Fire-Induced Initiating Events

Initiating events that may theoretically be induced by a fire include the following:

small break loss of coolant accident (LOCA)

- inadvertent opening of pressurizer power operated relief valves (PORVs) leading to small LOCA
- loss of charging and component cooling water leading to RXCP seal LOCA
- interfacing systems LOCA
- transients with main feedwater available
- transients without main feedwater available
- loss of offsite power
- anticipated transient without SCRAM
- loss of station and instrument air system
- loss of a 125 V DC bus
- loss of service water
- loss of component cooling water

Each is examined and described below:

• Small Break LOCA - inadvertent opening of pressurizer PORVs leading to small LOCA

Prolonged opening of pressurizer PORVs could lead to a small LOCA. Fire-induced LOCAs are described in the Appendix R Design Description, Sections 2.1.1. and 2.1.2. The PORVs are air-operated, and controlled by solenoid valves. The solenoid valves have their fuses removed in procedure E-0-06 and E-0-67. This ensures closure of the PORVs, preventing a LOCA.

Pressurizer PORVs are located in containment. As described in Section 4.2, containment fires are not considered to present hazards to components or cabling. Pressurizer PORV cabling is routed outside of containment, on its way from containment to the control room. Fire effects in the zones outside of containment through which pressurizer PORV cables pass are assessed in this report.

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 200 of 415

• Small Break LOCA - loss of charging and component cooling water leading to a RXCP seal LOCA

RXCP seals at Kewaunee are maintained by charging and by component cooling water (CCW). The primary method of maintaining the integrity of the RXCP seals is with seal injection from the positive displacement charging pumps. If seal injection is lost, the seals are cooled with reactor coolant, which passes through the RXCP thermal barriers. These thermal barriers are cooled by CCW. A RXCP seal LOCA is highly unlikely unless both charging and CCW capabilities are lost. CCW pumps are segregated, precluding fire-induced loss of both CCW pumps due to the same fire. Cables are separated, precluding fire-induced loss of cabling for both trains. Sections 2.1.1 and 2.1.2 of the Appendix R Design Description, describe Kewaunee's defense-in-depth strategy to prevent fire-induced LOCAs.

• Interfacing systems LOCA

A fire-induced interfacing systems LOCA is not a credible event at Kewaunee. A fire could not initiate this event. Fire-induced interfacing systems LOCA: are not considered further in this analysis.

• Transients with main feedwater available

A fire could induce a transient with main feedwater available. This is the response that is most likely for most fires.

• Transients without main feedwater available

A fire could disable main feedwater functions, resulting in a transient without main feedwater available.

• Loss of offsite power

A fire-induced loss of offsite power would occur if a fire were to disable the main transformer, the main auxiliary transformer, the tertiary auxiliary transformer, and the reserve auxiliary transformer. These are separated from each other by three hour barriers, and are located outside the plant. The control cables for these transformers, however, are located in the plant in non-safeguards cable trays. A loss of offsite power could therefore occur as a result of fire damage to these trays. Even if the trays are not damaged, procedures E-0-06, Fire in an Alternate Zone, and E-0-07, Fire in a Dedicated Zone, require manual isolation of offsite power, thus creating a loss of offsite power.

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 201 of 415 Anticipated transient without SCRAM (ATWS)

ATWS could occur if the reactor trip function were disabled. An ATWS due to a fire is not credible at Kewaunee, due to the "fail-safe" design of the Reactor Protection System (RPS), and adequate separation. Possible failure modes, such as stuck rods, are not fire-induced. The control rods drop unless energized. A fire, therefore, would not disable the reactor trip function. It is far more likely to initiate a trip. This event is not considered further in this analysis.

• Loss of station and instrument air

While safeguards station and instrument air compressors were located and their cables traced in compliance with Appendix R requirements, non-safeguards air compressors and cables were not. A loss of air only occurs when both safeguards and non-safeguards air compressors are disabled. The three non-safeguards air compressors are located in the turbine building basement. The safeguards air compressors and their cabling are located in separate fire areas, such that a single fire cannot disable all air compressors. Calculation performed for the Appendix R effort also showed that a fire cannot damage the station and instrument air piping. A fire-induced loss of air is not a credible event at Kewaunee.

• Loss of a 125 V DC bus

125 V DC components and cables were located for the Appendix R effort. The two trains of 125 V DC components and cables are separated by three hour fire barriers, preventing a loss of 125 V DC capability, since the DC buses can be supplied by MCCs 52C, 62C, 52E, 62E, or batteries A or B. Due to this diversity and separation that would prevent a single fire from destroying 125 V DC capability, a fire-induced loss of 125 V DC capability is not considered further in this analysis. However, loss of a single 125 V DC bus is considered in this analysis.

• Loss of service water

A loss of service water could result if a fire were to disable cabling for service water components. Redundant service water components are located in two separate fire areas. Service water cabling was traced as part of the Appendix R effort. It is separated by train such that a single fire could not disable service water functionality. This event is concluded to be incredible at Kewaunee. This event is not considered further in this analysis.

• Loss of component cooling water

A loss of CCW could result if a fire were to disable cabling for CCW components. Redundant CCW components that are susceptible to fire damage are located in two separate fire areas. CCW cabling was traced as part of the Appendix R effort. It is separated by train such that a single fire could not disable component cooling water functionality. This event is concluded to be incredible at Kewaunee. This event is not considered further in this analysis.

As part of discussions for fire zones, discussion of applicable initiating events is included.

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 202 of 415 4.1.4 Screening Analysis

#### 4.1.4.1 Zones containing components required for mitigation of fire-induced events

All zones designated for the Appendix R analysis containing components required for mitigation of fire-induced events are defined as follows:

Dedicated Fire Zone:	Those zones containing dedicated shutdown components. Should a fire in a dedicated zone occur, safe shutdown is accomplished with alternate components.
Alternate Fire Zone:	Those zones containing alternate shutdown components. Should a fire in an alternate zone occur, safe shutdown is accomplished with dedicated components.
Designated Fire Zone:	Those zones containing both dedicated and alternate system components that are not easily segregated.
Nondesignated Fire Zones:	Those zones containing equipment not specifically related to achieving safe shutdown.

Designated fire zones include SB-65 (shield building), RC-60 (containment) and TU-99 (diesel generator fuel tanks). Nondesignated fire zones are not listed. A fire in a nondesignated fire zone is not analyzed further, unless it contains important components modeled in the Individual Plant Examination (IPE) (Reference 15). Following is a list of each zone by category.

\*:

DEDICATED FIRE ZONES		IATE FIKE INES	DESIGNATED FIRE ZONES		IGNATED ZONES
AX-23B	AX-21	SC-70B	SB-65	AD-10	MS-52
AX-24	AX-22	TU-22	RC-60	AT-15	MS-53
AX-33	AX-23A	TU-92	TU-99	AX-20	MS-54
SC-70A	AX-23C	TU-93		AX-25	MS-55
<b>TU-9</b> 0	AX-23D	TU-94		AX-26	MS-56
TU-91	AX-30	TU-95 <b>B</b>		AX-27	MS-57
TU-95A	AX-32	TU-98		AX-31	<b>TR-80</b>
TU-95C	AX-34	TC-102		AX-36	TR-81
TU-97	AX-35			AX-39	TR-82
TC-1()()	AX-37			AX-41	TR-83
<b>TC</b> -101	AX-40			MS-50	TR-84
				MS-51	TR-85
				TU-96	TR-86

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 203 of 415

For the initial screening, a fire in each dedicated and alternate fire zone that destroys its contents is postulated. Fires in the nondesignated zones are discussed only if they contain components or cables credited in the IPE. Fires in designated zone SB-65 are not discussed because it is a narrow area in which personnel rarely enter during operation, and so transient combustibles, the only credible source of a fire, are kept to a minimum. Designated zone RC-60 is ruled out as discussed in Section 4.1.2. Fires in designated zone TU-99 would not affect the operability of diesel- for 8 hours and could not spread to other areas, due to the below ground location of the fuel tanks.

#### 4.1.4.2 Postulated fires in fire zones

#### 4.1.4.2.a Fire in dedicated zones

AX-23B: AX 23B, the "Reactor Auxiliaries North Central", contains components and cabling for many systems required to achieve safe shutdown: Reactor Coolant (RC), Residual Heat Removal (RHR), Safety Injection (SI), Chemical and Volume Control (CVC), Main Steam (MS), CCW, Service Water (SW), Low Voltage Electrical (ELV), Reactor Building Ventilation (RBV), Auxiliary Building Ventilation (ACA), and Nuclear Instrumentation (NI). All these systems are modeled in the IPE. Rooms contained in AX-23B are listed below: Elevation 566'-6": 14B-5, 14B-7, 14B-9 Elevation 586'-0": 8B-1, 8B-2, 8B-3, 8B-4, 12B-1, 12B-2, 12B-3, 14B, 14B-1, 14B-2, 14B-3 Elevation 606'-0": 153, 153-1, 156, 156-1, 156-2, 156-4, 157, 160, 166, 167

Separation between identified safety-related trains prevents a complete loss of function for most events. For instance, either charging or safety injection is necessary for reactor makeup. Although charging capability could be lost because all charging pumps are in zone AX-23B, safety injection pumps are in a separate fire zone, AX-23A, which is also in a separate fire area (alternate). So total loss of Reactor Coolant System makeup would not occur due to a fire in zone AX-23B.

Reference 7 describes design features that prevent fire-induced LOCAs. LOCA paths were identified, and necessary human actions, such as fuse removal, were incorporated in procedures.

If a fire is postulated in AX-23B, a transient could occur. This zone is retained for further analysis.

<u>AX-24</u>; AX-24, the "Fuel Handling Rooms" contains no equipment modeled in the IPE, with the exception of main steam cabling in 0.75" conduit. The main steam cabling passing through this area is for steam generator A level and pressure transmitters. According to assumption 10, cables in conduit are not vulnerable to the effects of fires of less than one hour in duration. The combustible loading for this zone, AX-24, would produce a fire of 8 minutes duration (Reference 8). This is not long enough to produce enough heat to damage cables within conduit. Because these cables and the other equipment in the fire zone are not vulnerable to fire-induced damage, or are not modeled in the Kewaunee IPE, this zone is not considered further in this analysis.

<u>AX-33</u>: AX-33, "Condensate and reactor makeup water tank room" contains components not vulnerable to fire effects. The only cabling for Appendix R systems in this zone is for the condensate storage tank level indication, which is not absolutely necessary for plant shutdown. Cabling for non-Appendix R systems does not pass through this fire zone, since it is located in the far southern end of the auxiliary building. This zone was inspected during the walkdown to verify that no important components which were credited in the IPE were located in this zone. Due to its large volume and the lack of vulnerable components or cabling in this fire zone, this zone is not considered further in this analysis.

<u>SC-70A</u>: SC-70A, "Screenhouse North", contains components and cabling for the SW, ELV, Turbine Building Ventilation (TAV), and Fire Protection (FP) Systems. A complete loss of service water is not a credible event due to adequate separation between trains. Likewise, a complete loss of ELV, TAV and FP are not credible due to train separation into separate fire areas. A fire in this zone could generate a transient. Therefore, this zone is retained for further analysis.

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 205 of 415

<u>TU-90</u>; TU-90, "Diesel Generator A Room", contains the A diesel generator, motor control center (MCC) 52A, and safeguards 4160 V electrical bus 5. This zone also contains cabling for many systems: RHR, Auxiliary Feedwater (AFW), SW, Diesel Generator Electric (DGE), High Voltage Electrical (EHV), ELV, TAV, ACA, FP, and the Station and Instrument Air (AS) Systems. Fire-induced disabling of these components could initiate a transient. This zone is retained for further analysis.

<u>TU-91</u>: TU-91, "Diesel Generator A Day Tank Room", contains the day tanks for diesel generator A. The day tanks are not explicitly modeled in the IPE. They are separated from TU-90 by a reinforced concrete barrier with vent holes held open by fusible links. It would take a very large explosive-type fire to damage the barrier. There is enough fuel in the day tanks to accomplish this (750 gallons in each of two tanks), but since they are enclosed and there are no active components, the likelihood is small enough to be considered insignificant compared to the fire initiation frequency of TU-90. A small, leak-type fire would not propagate further. Therefore, this room is not considered further in this analysis.

<u>TU-95A</u>; TU-95A, "Dedicated Shutdown Panel Room", contains safeguards 480 V electrical buses 51 and 52, turbine building basement fan coil unit A, the dedicated shutdown panel, station and instrument air compressor C, diesel start-up air compressor A, as well as cabling for the RC, RHR, SI, CVC, AFW, MS, CCW, SW, Diesel Generator Electric (DGE), EHV, ELV, Emergency AC and DC (EDC), RBV, TAV, ACA, FP, NI, and the Dedicated Analog Control System. A fire in this room that destroys all of its contents would generate a transient. This zone is retained for further analysis.

<u>TU-95C</u>; TU-95C, "Auxiliary Feedwater Pump A Room", contains auxiliary feedwater pump A, and cables for the RC, AFW, MS, SW, DGE, EHV, ELV, EDC, TAV, NI, and the Dedicated Analog Control Systems. A fire in this room would not initiate a complete loss of AFW, since motor driven AFW pump B and the turbine driven AFW pump are in separate fire zones, and protected by appropriate fire barriers. Likewise, fire-induced failure of cabling would not result in a complete loss of function, since redundant trains are in other fire zones. A significant fire in TU-95C could result in a transient. This zone is retained for further analysis.

<u>TU-97</u>: TU-97, "Battery Room A", contains 125 V battery B, 5.0 and 7.5 kVA inverters, MCC 52C, and DC distribution cabinets. Cables for the following systems pass through this room: RC, AFW, MS, DGE, SW, ELV, EDC, TAV, and NI. Adequate separation between TU-97 and areas housing redundant trains of the same systems prevents a complete loss of function for the systems. A fire destroying the contents of this room would initiate a transient or the loss of one 125 V DC train. This zone is retained for further analysis.

<u>TC 100:</u> TC  $\pm$ 00, "Technical Support Center, elevation 586'-0"", contains no components required for safe shutdown, but does contain cabling for the RC, RHR, SI, CVC, AFW, MS, CCW, SW, DGE, EHV, ELV, EDC, RBV, TAV, ACA, and NI. The cables are located above a false ceiling. Below the ceiling is the technical support center (TSC) used in emergency. The TSC contains no significant mechanical equipment, only chairs, tables, computers, and other office furniture. It is also a very open area. Therefore, there are no significant transient combustibles of the type considered in the other analyses (i.e., oily rags, etc.). There are

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 206 of 415

quartzoid bulb activated sprinklers that would operate in the event of a fire. Due to the lack of significant flammable materials, this zone is not considered further in this analysis.

<u>TC-101</u>: TC-101. Technical Support Center, elevation 606'-0", contains no safe shutdown components, but does contain cabling for the EDC system, for the non-vital batteries. It is unlikely that a trip resulting from a fire in zone TC-101 would be any worse than a normal transient. Since it is bounded by the IPE, this zone is not considered further in this analysis.

#### 4.1.4.2.b Fire in alternate zones

<u>AX-21</u>: AX-21, "4160 V Switchgear Room", contains 4160 V components for non-safeguards electrical buses 1 and 2, and cables for the EHV and RBV Systems. Adequate separation between areas prevents the possibility of loss of function, whether due to component or cable loss in this room. Significant fire initiation in this room could result in loss of buses 1 or 2, or both, which would cause a reactor trip. The main feedwater pumps are powered from these buses, and are modeled in the IPE. Likewise, the RXCPs are powered from these buses, and their loss would cause a loss of flow, initiating a reactor trip. A significant fire in this room could initiate a transient. This room is retained for further analysis.

<u>AX-22</u>; AX-22, "Machine Shop, Tank and Pump Rooms", contains cabling for the RC, SW, and Control Room Air Conditioning (ACC) Systems. Due to adequate separation, a fire in this zone would not result in a complete loss of function for the above systems. Significant fire initiation could result in a transient. This zone is retained for further analysis.

<u>AX-23A</u>; AX-23A, Refueling Water Storage Tank Area, contains components and cabling for the following systems: RC, RHR, SI, CVC, AFW, MS, CCW, SW, DGE, EHV, ELV, EDC, RBV, ACA, FP, and Internal Containment Spray (ICS), as well as cables for control room lighting. Rooms contained in AX-23A are listed below:

Elevation 586'-0": 8B Elevation 606'-0": 156-5 Elevation 626'-0": 238, 239, 313 Elevation 642'-3": 304A, 305, 306, 307A, 308, 309, 310 Elevation 657'-6": 403

If a fire is postulated in AX-23A, a transient could occur. Other events are prevented due to adequate separation between trains of components which, if both trains were disabled, could cause a loss of function, and initiate other events. This zone is retained for further analysis.

AX-23C: AX-23C, "RHR Pump B Pit", is room 14B-6 on elevation 566'-6", and contains RHR pump B, and ACA cables. A loss of RHR function is not credible since redundant components are separated by three hour fire barriers. An automatic trip would not occur upon disabling of the contents of this room. This room is retained for further analysis.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 207 of 415

<u>AX-23D</u>: AX-23D, "Component Cooling Water Pump B Room", contains CCW water pump B, and ELV and ACA cables. A complete loss of component cooling due to fire is not credible, since CCW pump A is in a separate fire area. If a significant fire were to occur in AX-23D, a transient could occur. This room is retained for further analysis.

<u>AX-30</u>: AX-30, "Relay Room", contains equipment needed for the primary safe shutdown method (via the control room). The remote shutdown panel is used in the event of AX-30 or AX-35 being disabled. If a significant fire were to be initiated in AX-30, a number of events could be initiated if a function were to be disabled: loss of service water, loss of 125 V DC, loss of air, or a transient. This room is retained for further analysis.

AX-32: Rooms located in AX-32, "Service Rooms", are listed below:

Elevation 6061-0":	137, 139, 140, 141, 142, 143, 144, 145, 146, 150, 166, 167, 168, 219
Elevation 626'-0":	230, 230A, 231, 232, 236, 244, 251

These rooms contain no components modeled in the IPE, but they do contain cables for the RC, RIIR, SI, CVC, MS, CCW, SW, ELV, EDC, TAV, ACA, ACC, and NI Systems, and for control room lighting. A complete loss of function is not likely, due to adequate separation between trains of redundant components. It is assumed that a transient would be initiated if a fire damaged the aforementioned cabling. This zone is retained for further analysis.

<u>AX-34</u>: AX-34, "Stairwell B", contains no safe shutdown components or cabling. This area is not considered further in this analysis.

<u>AX-35</u>; AX-35, "Control Room and A/C Equipment Room", contains control and indication circuitry for all plant functions controlled and monitored from the control room. A fire in the control room could generate many events: loss of service water, loss of 125 V DC, loss of air, or a transient. This room is retained for further analysis.

<u>AX-37</u>: AX-37, "Control Rod Drive Equipment Room", contains the reactor trip breakers, control rod drive equipment, pressurizer heater components and RC cabling. A fire in this room destroying its contents would initiate a reactor trip. This room is retained for further analysis.

<u>AX-40</u>: AX-40, "Records Storage Room", contains no components or cables modeled in the IPE. For this reason, this room is not considered further in this analysis.

<u>SC-70B</u>: SC-70B, "Screenhouse South", contains components and cables modeled in the IPE: SW, EHV, ELV, TAV, and FP. Although one train of service water and fire protection pumps is located in SC-70B, a complete loss of service water or fire protection (fire pumps) capability is not considered credible, as adequate separation (3-hour fire barriers) exists between trains. A loss of other components in the room could initiate a transient. This room is retained for further analysis.

<u>TU-22</u>; TU-22, "Turbine Room" contains many components credited in the IPE: main feedwater components, non-vital air compressors, MCCs powered from non-safeguards buses, non-safeguards 480 volt and 4160 volt buses, 125 volt non-safeguards DC buses, and condensate pumps. Rooms contained in TU-22 are listed below:

Elevation 586'-0": 6B Elevation 606'-0": 120, 121, 122, 123, 124, 125, 126, 127, 128 Elevation 626'-0": 199, 200

Failure of components located in these rooms could initiate a transient. This zone is retained for further analysis.

<u>TU-92</u>: TU-92, "Diesel Generator B", contains diesel generator B, safeguards 4160 V electrical bus 6, MCC 62A, and cables for the SW, EHV, ELV, RBV, TAV, ACA, ACC, FP, and ICS Systems. Due to separation between trains, a fire destroying the contents of this room would not cause a complete loss of function. A transient could be initiated. This room is retained for further analysis.

<u>TU-93</u>; TU-93, "Diesel Generator B Day Tank Room", contains the day tanks for diesel generator B. The day tanks are not explicitly modeled in the IPE. They are separated from TU-92 by a reinforced concrete barrier with vent holes held open by fusible links. It would take a very large explosive-type fire to damage the barrier. There is enough fuel in the day tanks to accomplish this (750 gallons in each of two tanks), but since they are enclosed and there are no active components, the likelihood is small enough to be considered insignificant compared to the fire initiation frequency of TU-92. A small, leak-type fire would not propagate further. Therefore, this room is not considered further in this analysis.

<u>TU-94</u>: TU-94, "CO<sub>2</sub> Tank Room", contains air compressor A, and cabling for the RC, RHR, SI, AFW, MS, CC, SW, DGE, EHV, ELV, RBV, TAV, ACA, ACC, FP, AS, and ICS Systems. Adequate separation between TU-94 and areas housing redundant trains of the same systems, prevents a complete loss of function for the systems. A fire destroying the contents of this room could initiate a transient. This zone is retained for further analysis.

<u>TU-95B</u>: TU-95B, "Safeguards Alley" contains safeguards 480 volt electrical buses 61 and 62, auxiliary feedwater pump B, turbine building basement fan coil unit B and the turbine driven auxiliary feedwater pump. Cables cc tained in this zone belong to the RC, RHR, SI, AFW, MS, CCW, SW, DGE, EHV, ELV, EDC, TAV, ACA, ACC, FP, AS, and ICS Systems. Cables passing through the turbine-driven AFW pump room are located above a steam exclusion ceiling. Adequate separation between TU-95B and areas housing redundant trains of the same systems, prevents a complete loss of function for the systems. A fire destroying the contents of this zone could initiate a transient. This zone is retained for further analysis.

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 209 of 415

<u>TU-98</u>; TU-98, "Battery Room B", contains 125 volt battery B, 5.0 and 7.5 kVA inverters, MCC 62C, and DC distribution cabinets. Cables for the following systems pass through this room: RC, AFW, MS, SW, DGE, EHV, ELV, TAV, TSC Ventilation (TCV), ACA, ACC, and NI. Adequate separation between TU-98 and areas housing redundant trains of the same systems prevents a complete loss of function for the systems. A fire destroying the contents of this room would initiate a transient, or the loss of one 125 volt DC train. This zone is retained for further analysis.

<u>TC-102</u>; TC-102, "TSC Non Safeguards Battery and Electrical Equipment Room", contains the non safeguards batteries and associated electrical equipment (BRC-108 and BRD-108). The cables for the TCV system pass through this zone. An automatic trip could possibly be generated from a fire occurring in this zone, due to loss of main feedwater control or other non-safety related equipment/cables in this zone. This type of trip is bounded by the IPE (transient without main feedwater). Fire-induced losses of components and cabling in zone TC-102 are not considered further in this analysis, since they were examined in the IPE.

# 4.1.5 Results of Screening

The first screening results in nine zones being eliminated from further analysis. The following table summarizes the first screening:

Zones that are eliminated	Reason for elimination	Remaining Dedicated Zones	Remaining Alternate Zones
AX-24	Cables/components not vulnerable to fire damage	AX-23B SC-70A	AX-21 AX-22
AX 33	Large volume of room, no components or cabling credited in PRA	TU-90 TU-95A TU-95C TU-97	AX-23A AX-23C AX-23D AX-30
TU 91	Zone does not contain components that were credited in PRA, Concrete barriers prevent propagation		AX-32 AX-35 AX-37 SC-70B
TC 100	No significant combustibles		TU-22 TU-92
TC 101	IPE transients analysis bounds worst case fire		TU-94 TU-95B
AX 34	No components or cables which were credited in PRA		TU-98
<b>AX</b> 40	No components or cables which were credited in PRA		
TU 93	Zone does not contain components that were credited in PRA, Concrete barriers prevent propagation		
TC 102	IPE transients analysis bounds worst case fire		

The next screening step is to conservatively calculate core damage frequency assuming the entire contents of the zone are damaged, given a fire, and to determine if that zone's core damage frequency is below the screening value of 1E-06/yr. To do this, the fire initiation frequency is determined for each screened zone, and an inventory of the zone (components and cables) is made. The fire initiation frequency is determined by the EPRI method which allocates the likelihood of a fire based on the room's location in the plant, and the number and type of components in the zone. Both fixed and transient combustibles are considered in this step. The fire initiation frequency is set as the initiating event frequency. The contents of each zone are determined by reviewing the Appendix R documentation, in conjunction with general arrangement drawings, and verified during the walkdown. The fire frequency calculations are documented in Table 4-1. It is postulated that a fire in a certain zone would destroy the contents of that zone. To model this scenario, the Westinghouse WALT code (Reference 13) is used to recalculate core damage frequency. Changes are made to the loss-of-offsite power sequence, assuming total zonal fire-induced damage. The loss-of-offsite power sequence is selected because non-vital loads from buses 1, 2, 3, 4, 32, 35, 42, and 45 were not traced for Appendix R. Appendix R documentation is used at this stage of the analysis. The cables of the non-vital loads, which are not credited, are assumed to be in any of the zones, and vulnerable to fire-induced damage. The results of this screening are documented in Reference 14. As a result of the screening, the following zone is not considered further in the analysis: AX-37. Table 4-1 documents calculation of the fire initiation frequency. Results of the screening are presented in Table 4-2.

The following remaining zones are considered further in the analysis:

DEDICATED	ALTERNATE	
AX-23B	AX-21	SC-70B
SC-70A	AX-22	TU-22
TU 90	AX-23A	TU-92
TU-95A	AX-23C	TU-94
TU-95C	AY 3D	TU-95B
TU-97	<b>Αλ-3</b> 0	TU-98
	AX-32	
	AX-35	

The next screening step is to more realistically consider and model fire damage, rather than assume total zonal damage in the event of a fire. To do this, the walkdown was conducted, and measurements required to run COMPBRN were obtained. COMPBRN allows determination of extent and timing of damage, given a fire of a certain size in a certain location.

#### 4.2 Review of Plant Information and Walkdown

Data and information pertinent to this analysis were collected in the plant walkdown. This included the Kewaunee Appendix R documentation, plant specific information pertaining to fire events, fire related procedures, transient combustible control procedures, fire brigade

performance and cable routing information. Locations of components and their cables were determined.

The walkdown occurred October 27, 28 and 29, 1992, when the plant was at 100% power. The walkdown team consisted of four WPSC employees and two Westinghouse employees with the following expertise:

Job Title and Company	Expertise
Senior Risk Assessment Engineer - WPSC	PRA modeling of plant systems
Senior Nuclear Engineer - WPSC	1-1/2 years of fire engineering at another utility
Fire Protection Operations Supervisor - WPSC	In charge of fire protection at Kewaunee
Quality Assurance Auditor WPSC	9 years as Fire Protection Operations Supervisor
Senior Engineer Westinghouse	Fire PRA modeling
Associate Engineer - Westinghouse	PRA modeling of plant systems

In general, the plant was found to be very clean, and transient combustibles were limited. Except for containment, which was screened from further analysis earlier, the entire plant was inspected. All zones which were retained for further analysis were examined in detail.

Some zones were excluded from further analysis based on walkdown findings. The following paragraphs discuss these exclusions.

<u>Cable Spreading Area of AX-32</u>: All cables in this area are located in trays. There are numerous ionization detectors in this area. Wet pipe sprinklers of the quartzoid bulb design are located close to the cable trays, aimed at the cable trays. This area is under strict administrative control. No transient combustibles are stored in or near the zone. If maintenance such as cable pulling were to occur, it would be done during shutdown conditions. This analysis is limited to at-power conditions. There is a 480 V/120 V transformer in one corner of the room. A transformer fire is unlikely, especially with the relatively low voltages involved. There are cable trays located about six feet from the transformer. If it were to occur, a transformer fire would be of short duration. Because of the 'ow voltages involved, and the short duration of a postulated fire, it is assumed that insufficient energy would be released to cause damage to the cables which are a minimum of six feet away. For the above reasons, this area is not considered further in this analysis.

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 213 of 415

<u>Auxiliary Building (AX-23A and AX-23B)</u>: The controlled part of the auxiliary building is large and open. Formation of a hot gas layer is unlikely, since there are no confined spaces. Scenarios that could contain vulnerabilities are examined in detail, but most of the auxiliary building is not considered further in this analysis due to the large open layout.

<u>Control Room (AX-35)</u>: The control room is continually manned. Cabinets in the control room have smoke detectors inside the cabinets. Studies have shown (Reference 16) that cabinet fires are confined to cabinets where the fire originated. Circuitry within these cabinets operate at low voltages. Although a fire in the control room is unlikely, the plant can still be safely shut down from the dedicated shutdown panel. The control room and the dedicated shutdown panel are in separate fire areas, so that a single fire could not disable both areas. Procedures E-0-06 and E-0-07 describe actions that must be taken in the event of a fire which causes loss of monitoring or control function (e.g., control room fire). Control room fires are not considered further in this analysis.

<u>Turbine Building (TU-22)</u>: Due to its large area and volume, and lack of components and cabling .equired for safe shutdown, fires in the turbine building are not analyzed, except for individual scenarios in which a fire could damage components or cabling credited in the PRA.

#### Screenhouse (SC-70A and SC-70B):

SC-70A was chosen as being representative of SC-70B. The two zones are normally open to each other, and can be isolated by roll-up fire doors held open by fusible links. Each zone has a large exhaust fan (50,000 cfm) located near the vital MCCs (MCC 52D, MCC 62D). It is not feasible that a damaging hot gas layer would form near these MCCs, as any hot gases would be exhausted outdoors by the fans. Radiative damage is not credible, due to the spatial separations involved. The non-vital MCCs (MCC 35C and MCC 45C) are located in SC-70A, away from the exhaust fans. A fire near these MCCs in SC-70A is analyzed.

The most likely lize of pilot fire was discussed with Kewaunee fire safety professionals. It was concluded that a trash can fire equivalent to combustion of 3 kg of heptane, or a fire resulting from a lube oil spill, are the most likely fire initiators.

#### 4.3 Fire Growth and Propagation

Propagation from adjacent zones is considered. In accordance with assumption 13, Appendix R barriers are assumed to remain intact, and inter-zonal propagation is not found to present a hazard. Zonal boundaries and intervening combustibles were examined during the walkdown. Combustibles were found to be evenly distributed in the zones. Combustible loadings presented in Reference 8 were found to be applicable to this analysis.

Fire growth was modeled with COMPBRN, which is documented in Reference 16.

### 4.3.1 COMPBRN Runs

Following is a list of COMPBRN runs that were made, to determine extent and timing of damage.

• AX-23B

Scenario 1 Cable trays near flammable liquid storage cabinet, 586' elevation Scenario 2: Cable trays near bottled gas storage, 586' elevation

• AX-23A

Scenario 1: Cable trays above SI pumps Scenario 2: Cable trays near bottled gas storage, 657'-6" elevation Scenario 3: Cable trays near MCC-35E, -45E

• TU-95A

Scenario 1: Cable trays above Bus 52

• TU 95C

Scenario 1. Cable trays above AFW Pump A

• TU-95B

Scenario 1: Cable trays above Bus 61 Scenario 2: Cable trays north of Bus 62 Scenario 3: Cable trays (2 trains) in AFW pump B room

• TU-90

Scenario 1: Cable trays above Bus 5 Scenario 2: Cable trays above MCC 52A Scenario 3: Other cable trays in room

• TU-92

Scenario 1: Cable trays above Bus 6 Scenario 2: Cable trays above MCC 62A Scenario 3: Other cable trays in room

• SC 70A

Scenar.0 1: Cable trays above MCC 35C and MCC 45C

• TU-97

Scenario 1: Cable trays above distribution cabinets Scenario 2: Cable trays above batteries

• TU-98

Scenario 1. Cable trays above distribution cabinets Scenario 2: Cable trays above batteries

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 215 of 415

- AX-30 Scenario 1: Fire near vertical cable trays
  - Scenario 2: Fire near cabinets (cables exposed on top of cabinets)
- AX-32

Scenario 1: Cables leading to MCC 62B

- AX-23D Scenario 1: Cables near CCW pump
- TU-94 Scenario I: Cable trays near air compressor A
- AX-21 Scenario 1: Cable tray above buses 1 and 2

#### 4.3.1.1 TU-95A, Switchgear room 5B

#### 4.3.1.1a Scenario: fire near safeguards 480 V electrical bus 52

A trash can fire is modeled by a 3 kg pool of heptane. TU-95A is modeled two ways--with ventilation and without ventilation. The case with ventilation yields no damage to any of the cable travs located directly above the heptane pool. The case without ventilation yields similar results. Both of these cases model a heptane pool at floor level. When the heptane pool is raised to 0.5 meters above floor level (estimated height of full trash can), both models yield damage to cable tray 1TT5S5 within one minute. Other cable trays and the adjacent MCC are not damaged. Both cases (with and without ventilation) with the heptane pool raised 0.5 m from the floor yield damage to cable tray 1TT5S5. The fusible link closure temperature on the fire dampers is 160 deg. F or 341 deg. K. The fire that is modeled (3 kg of heptane) causes closure of the dampers for the case with ventilation and without ventilation, since the hot gas layer of 5.6 m reaches a mean temperature of 385 deg. K without ventilation and 335 deg. K (close to 341 deg. K) with ventilation. The more conservative case with no ventilation is considered. Cable tray 1TT555 is affected with a fuel size of 3 kg heptane located 0.5 meters above the floor. Other cable trays ITTIS5, ITTIN, ITTI2N, ITTI1N and ITTI3N are not affected by the postulated fire. Ladder trays 1TL53S5, 1TL1S8, 1TL1N and 1TL14N are not considered in the analysis, since they contain power cables, and all power cables are enclosed in conduit, which is not considered to be vulnerable to heat damage for fires of less than one hour duration. The other train of cables, 1TT5S6, 1TT1S6, 1TT6N, and 1TT16N are routed above an Appendix R false ceiling, and are not considered to be vulnerable to damage.

It is concluded that a fire of 3 kg of heptane with no ventilation may damage cable tray 1TT5S5.

#### 4.3.1.2 TU-97, Battery room A (room 129)

#### 4.3.1.2a Scenario: fire near distribution cabinets

This room contains many cables, but most are power cables in conduit. Cables in conduit are not considered to be vulnerable to fires of less than one hour duration. There also are many distribution cabinets in the room. Cables entering the cabinets are considered to be vulnerable to fire damage. This room is modeled with and without ventilation. The room ambient temperature exceeds the temperature at which the fusible links in the dampers actuate in both cases, so the cases with no ventilation are considered. Three (3) kg of heptane located near the distribution cabinets, at floor level, and elevated 0.5 m yield no damage to the distribution cabinet or the overhead cable trays. However, if the amount of fuel was increased to 30 kg of heptane (not realistic), damage occurs to the distribution cabinet and the overhead cable trays. Thirty (30) kg of heptane, representing a large trash can, was determined by the Kewaunee fire safety professionals to be an unrealistic amount of fuel. Note that there were no transient combustibles located in TU-97 during the walkdown, and the plant fire protection safety professionals confirmed that there are none in this room during operations.

#### 4.3.1.2b Scenario: fire near batteries

Where a 3 kg heptane pool elevated 0.5 m from floor level is modeled near the batteries, no damage to either the batteries or the overhead cable trays occurs. When the 3 kg heptane pool is replaced with a 30 kg pool, no damage to the batteries occurs, but cable tray 1TT132N is damaged. As described earlier, 30 kg of heptane is an unrealistic amount of fuel.

It is concluded that a fire of realistic magnitude (represented by 3 kg of heptane) in the battery room poses no threat to components or cables in the room.

#### 4.3.1.3 TU-98, Battery room B (room 130)

#### 4.3.1.3a Scenario: fire nerr distribution cabinets

Like battery room A, battery room B has many cables passing through it. Most cables are power cables in conduit. Ventilation and no ventilation are modeled, and in both cases the room ambient temperature exceeds the damper closure temperature of 341 deg. K. The case with no ventilation represents the battery room under fire conditions. Three (3) kg of heptane elevated 0.5 m from floor level, located near the distribution cabinets, yields no damage to the distribution cabinets or the overhead trays. When 30 kg of heptane in the same location is modeled as the fuel source, damage does occur to the distribution cabinet and to the overhead cable trays. However, 30 kg of heptane is an unrealistic amount of fuel.

#### 4.3.1.3b Scenario: fire near batteries

When the fire is modeled near the batteries, a 3 kg pool of heptane elevated 0.5 m from the floor yields no damage to the batteries or the overhead cable trays. However, a 30 kg pool of heptane in the same location does cause damage to both the batteries and overhead cable trays. As described above, 30 kg of heptane is an unrealistic amount of fuel.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 217 of 415

It is concluded that a fire of realistic magnitude (represented by 3 kg of heptane) in the battery room poses no threat to components or cables in the room.

#### 4.3.1.4 AX-23A, Auxiliary building (RWST area)

#### 4.3.1.4a Scenario: fire near MCC 35E/45E in fan room

The fan room is a large area, and this fire scenario is modeled as an open room. Three (3) kg of heptane located 0.5 m from floor level is modeled as the fuel source. This fire causes no damage to the MCCs or the overhead cable trays. It is concluded that a fire poses no threat to the MCCs or to the overhead cable trays.

#### 4.3.1.4b Scenario: fire in corridor near MCC 62J

This corridor is small, and is modeled as a closed room with no ventilation. A postulated fire of 3 kg of heptane causes damage to MCC 62J, and cable trays 1FT6S6 and 1FX4S6. Note that in reality, it is very unlikely that transient combustibles would be in this corridor, as it is too small to permit trash storage and personnel traffic. However, for the purpose of this analysis, this fire is considered.

#### 4.3.1.4c Scenario: fire near bottled gas storage at elevation 657'-6"

The bottled gas storage area at elevation 657'-6" is modeled as an open area with a fire of 3 kg of heptane, elevated 1.5 m above the floor to represent a bottled gas leak. Damage to overhead cable tray 1FT10N occurs.

#### 4.3.1.4d Scenario: SI pump oil fire

A lubricating oil leak from a SI pump is postulated, to determine if the resulting fire endangers overhead cable trays. The SI pumps are not in a closed room, so an open area was modeled. The fuel that was modeled is engine oil, representing lubricating oil, at floor level, with the SI pump between the oil pool and the overhead cable trays. No damage to the overhead cable trays resulted.

#### 4.3.1.5 AX-23B, Auxiliary building (reactor auxiliaries north center)

#### 4.3.1.5a Scenario: fire near flammable liquid storage cabinet at elevation 586'-0"

A fire in the flammable liquid storage cabinet at elevation 586'-0" is modeled by a 3 kg heptane pool. The flammable liquid storage cabinet is in an open corridor, so this scenario is modeled as an open area. No damage to overhead cable trays 1AT3S5 or 1AT33N results. The flammable liquid storage cabinet, however, has been moved to a site in same compartment but farther from the cable trays.

When a 30 kg heptane fire is modeled, damage to the two cable trays results. It is unlikely that combustibles equivalent to 30 kg of heptane would reside in an open flammable liquid storage cabinet. The scenario with 3 kg of heptane is more realistic, and is considered.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 218 of 415

#### 4.3.1.5b Scenario: fire near bottled gas storage at elevation 586'-0"

3 kg of heptane elevated 1.58 m (to represent the height of a bottled gas cylinder) is used to model a fire in which a hose breaks loose from its bottle, and the leaking gas ignites. The bottled gas cylinders are located in an open hallway, so this scenario is modeled as an open area. Four cable trays, 1AT1N, 1AT23N, 1AT53N, and 1AT4S5 are located near the gas cylinders. No damage to these cable trays results.

A 30 kg heptane fire is modeled, and damage to two of the four cable trays results. However, it is unlikely that a fire equivalent to 30 kg of heptane would be initiated, with the strict transient combustible controls at Kewaunee. The 3 kg scenario is considered in this analysis.

#### 4.3.1.6 TU-90, Diesel generator room A

Note that this room has a  $CO_2$  flooding system, which is actuated by heat detectors in the room, or manually.

#### 4.3.1.6a { enario: fire near safeguards 4160 V electrical bus 5

Three (3) kg of heptane elevated 0.5 m and situated near safeguards 4160 V electrical bus 5 is postulated to model a trash can fire, and to determine if such a fire harms bus 5 or the overhead cable trays. Because the fire dampers close on high temperature (160 deg. F), and on  $CO_2$  and thermal detector actuation, it is postulated that there is no ventilation if a fire occurs. Hence, TU-90 is modeled as a closed room. Neither the bus nor the overhead cable trays are damaged in this scenario.

Even when a large (and unrealistic) 30 kg heptane fire is modeled, no damage to either the bus or the overhead cable trays results, due to the large volume of the room.

#### 4.3.1.6b Scenario: fire near MCC 52A

Three (3) kg of heptane located near the MCC is modeled to represent a trash can fire. A closed room is modeled in this scenario. No damage to the MCC or the overhead cable trays results.

However, a 30 kg heptane fire located near the MCC does cause damage to the MCC and the  $\frac{4}{3}$  overhead cable trays. Upon review of transient combustible controls at Kewaunee, it was determined that a 30 kg heptane fire representing a full 55 gallon trash can was unrealistic. Hence this scenario was ruled out.

It is concluded that a fire near MCC 52A does not damage the MCC or the overhead cable trays.

#### 4.3.1.6c Scenario: diesel engine oil fire

For this scenario, a 300 gallon engine oil fire below the diesel generator is postulated. As above, a closed room scenario is modeled. 300 gallons of engine oil (the entire inventory) is postulated to burn. The two overhead cable trays 1DT3S5 and 1DT4S5 are not damaged.

It is concluded that a diesel engine oil fire does not damage the overhead cable trays.

#### 4.3.1.7 TU-92, Diesel generator room B

Similar to TU-90, this room has a total flooding  $CO_2$  system, actuated manually or by heat detectors.

#### 4.3.1.7a Scenario: fire near MCC 62A

Three (3) kg of heptane located near the MCC is selected to represent a trash can fire. A closed room is modeled in this scenario. Damage to MCC 62A results, and COMPBRN shows a .495 probability of cable tray 1DT3S6 being damaged. For this analysis, it is assumed that the MCC and cable tray 1DT3S6 are damaged if a trash can fire occurs near the MCC.

When a large (and unrealistic) 30 kg fire is modeled, both the MCC and the overhead cable tray are damaged.

This scenario yields damage while the scenario for MCC 52A does not, due primarily to the different geometries of TU-90 and TU-92.

# 4.3.1.7b Scenario: fire near safeguards 4160 V electrical bus 6

A 3 kg heptane fire elevated 0.5 m from the floor is modeled near safeguards 4160 electrical bus 6. As above, a closed room scenario is modeled. No damage to the bus or the overhead cable trays results. However, a 30 kg heptane fire elevated 0.5 m from the floor does cause damage to the bus and overhead cable tray 1DT4S6.

Upon review of transient combustible controls at Kewaunee, it was determined that a 30 kg heptane fire representing a full 55 gallon trash can is unrealistic. Hence this scenario is ruled out. It can be concluded that a fire near bus 6 does not damage it or the overhead cable trays.

#### 4.3.1.7c Scenario: diesel engine oil fire

For this scenario, 300 gallons of engine oil below the diesel generator is postulated to burn. As above, a closed room scenario is modeled. Overhead cable tray 1DT8N is damaged.

Å

Ŀ,

#### 4.3.1.7d Scenario: trash can fire located beneath cable trays at north end of room

Thirty (30) kg of heptane located beneath cable trays is modeled to represent a very large trash can fire. A closed room scenario is modeled. The overhead cable trays show no damage, due to the large volume of the room.

#### 4.3.1.8 SC-70A, Screenhouse

#### 4.3.1.8a Scenario: fire near MCC 35C/45C

Three (3) kg of heptane elevated 0.5 m from the floor, and located near MCC 35C/45C and overhead cable tray 1ST3N produces a fire yielding no damage to either the MCC or the cable tray. However, a 30 kg fire in the same location damages both the MCC and cable tray 1ST3N. Upon review of transient combustible controls at Kewaunee, it was determined that a 30 kg heptane fire representing a full 55 gallon trash can is unrealistic. Hence this scenario is ruled out.

It is concluded that a fire near the MCCs does not damage it or the overhead cable trays.

#### 4.3.1.9 AX-30, Relay room

#### 4.3.1.9a Scenario: fire near vertical cable trays

Three (3) kg of heptane located near vertical cable trays 1AT3N, 1AT4N, 1RT62S6, 1AT12S6, and 1AT13S6 is modeled. This is modeled with ventilation, since the hot gas layer temperature does not exceed the damper closure temperature with a fuel source of 3 kg of heptane. It is a large room. All these cable runs are Flameastic coated from floor level to 4 ft high. Therefore the first vulnerable section of cable is considered to be 4 ft high. Damage to cable trays 1RT62S6, 1AT12S6, and 1AT13S6 results.

#### 4.3.1.9b Scenario: fire near four cabinets

Three (3) kg of heptane elevated 0.5 m from the floor, representing a trash can, is modeled 0.5 m from four cabinets. As in the above scenario, the hot gas layer temperature does not exceed the fire damper closure temperature, so ventilation is modeled. No damage to the cabinets or the overhead cable trays results. When this same scenario is modeled with 30 kg of heptane as the fuel source, still no damage results.

#### 4.3.1.10 TU-95C, AFW pump A room

#### 4.3.1.10a Scenario: AFW pump A oil fire

Fifteen (15) kg of engine oil is modeled at floor level below AFW pump A to simulate a lubricating oil leak to determine if this causes damage to the overhead cable trays. The pump is located in a small room, and the ambient temperature in the simulation for two cases - with and without ventilation - exceeds the damper closure temperature of 341 deg. K. There is

uncertainty associated with the damage computation and COMPBRN shows a probability of damage to all cable trays to be 0.52. For this analysis, damage to all cable trays in the room (1TT8S5, 1TT4S5, 1TT4N, 1TT15N, and 1TT106S5) is assumed.

#### 4.3.1.11 AX-32, Service rooms

#### 4.3.1.11a Scenario: fire near MCC 62B

Three (3) kg of heptane located near MCC 62B, elevated 0.5 m from the floor is modeled to represent a full trash can. No damage to the MCC or the overhead cable trays results, due to the open area of AX-32.

#### 4.3.1.11b Scenario: fire near MCC 62B extension

Three (3) kg of heptane located near MCC 62B extension, elevated 0.5 m from the floor is modeled to represent a full trash can. No damage to the MCC results, due to the open area of AX-32.

#### 4.3.1.11c Scenario: fire in cable spreading area

There are limited transients combustibles allowed in this area. All power cables are armored. There are numerous ionization detectors located in this area, and wet pipe sprinklers (actuated by a quartzoid bulb) aimed at the numerous cable trays in this area. There is one 480/120 V transformer in the area, which could be a potential ignition source, but there are no combustibles located nearby. In addition, a transformer fire is not likely. A transformer fire is short and intense, but it is assumed that there would be insufficient energy released to damage the nearby (6 ft. away) cable trays. The main steam and feedwater lines pass through this area, but they are insulated and jacketed, minimizing heat release. There is no maintenance in this area during power operations. For these above reasons, it is concluded that a fire in the cable spreading area during power operations is not credible.

#### 4.3.1.12 AX-23D: Component cooling water pump B room

#### 4.3.1.12a Scenario: Component cooling water pump B oil fire

Fifteen (15) kg (approximately 5 gallons) of lubricating oil is modeled at floor level to represent an oil spill, the most probable fire initiator in the room. Within 14 minutes, damage occurs to cable tray 1AT20N. Moving the lubricating oil spill around to determine the area of influence over which it causes damage has no effect, because the damage occurs only due the hot gas layer. For this analysis, it is assumed that, given a fire in this room, everything in the room is lost.

#### 4.3.1.13 TU-94: Air compressor A room

#### 4.3.1.13a Scenario: fire in air compressor A

When 15 kg of lube oil is modeled beneath air compressor A, no damage to the air compressor or the overhead cable trays results. The average hot gas layer temperature is 411 deg. K, not high enough to cause damage.

#### 4.3.1.13b Scenario: fire beneath cable trays

Three (3) kg of heptane, representing a trash can fire, located near air compressor A and beneath cable trays 1DT6S6, 1DT7S6 and 1TT5N results in no damage. When the size of the fuel source is increased to a 60 kg heptane fire (not realistic), still no damage results. The hot gas layer temperature does not exceed the cable damage threshold, due to the large volume of the room. The average temperature during the simulation was 397 deg. K for the 3 kg heptane case, and 444 deg. K for the 60 kg heptane case. Neither temperature exceeds the cable damage threshold, hence no damage occurs.

#### 4.3.1.14 TU-95B: AFW pump B room and 480 V swgr buses 61 and 62 room

#### 4.3.1.14a Scenario: AFW pump B oil fire

Fifteen (15) kg (5 gallons) of engine oil located beneath AFW pump B at floor level is modeled to represent a lubricating oil leak. The hot gas layer temperature exceeds the damper closure temperature of 341 deg. K for two cases - with and without ventilation. The mean hot gas layer temperature for the case with no ventilation is 665 deg. K, and 5.60 m in thickness. This temperature exceeds the damage threshold temperature of the cables, 500 dig. K, and indicates damage to all cables in the room. There is uncertainty associated with the damage computation, and COMPBRN shows a probability of damage to all cable trays in the room to be 0.05. For this analysis, damage to all the cable trays in the room (1TT8S5, 1TT4S5, 1TT4N, 1TT15N, 1TT8S6, 1TT4S6, 1TT10N, and 1TT20N) is assumed.

#### 4.3.1.14b Scenario: fire beneath cable trays north of safeguards 480 V electrical bus 62

Three (3) kg of heptane is modeled 0.5 m from the floor to simulate a full trash can located directly beneath the train B cable trays (1TT7S5, 1TT3S5, 1TT3N, 1TT14N). The hot gas layer temperature exceeded the damper closure temperature of 341 deg. K for two cases - with and without ventilation. The case with no ventilation is the one considered. The mean hot gas layer temperature is 402 deg. K, below the damage threshold temperature of the cables. There is no damage to the cable trays.

#### 4.3.1.14c Scenario: fire between safeguards 480 V electrical buses 61 and 62

Three (3) kg of heptane are modeled 0.5 m from the floor to simulate a full trash can located between safeguards 480 V electrical buses 61 and 62. The hot gas layer temperature exceeds the damper closure temperature of 341 deg. K for two cases - with and without ventilation. The case with no ventilation is considered. The mean hot gas layer temperature is 402 deg. K, below the damage threshold temperature of the cables. As a result, no damage to the cable trays results.

#### 4.3.1.15 AX-21: 4160 V switchgear room

n .....

#### 4.3.1.15a Scenario: fire near non-safeguards 4160 V electrical buses 1 and 2

Three (3) kg of heptane are modeled 0.5 m from the floor to simulate a full trash can located between non-safeguards 4160 V electrical buses 1 and 2. The hot gas layer temperature does not exceed the damper closure temperature of 341 deg. K, so the case with ventilation is considered. The mean hot gas layer temperature is 321 deg. K, below the cable damage threshold temperature. However, cable tray 1AT9N shows damage within the first minute, due to radiant heat exposure.

The results from these COMPBRN runs are summarized below, and are also shown in Table 4-3.

Demand Cable Trave/Commonste

Room	Damaged Cable Trays/Components
TU-95A	177555
TU-97	no damage
TU-98	no damage
AX-23A:	-
- MCC 35E/45E	no damage
- MCC 62J	1FT6S6, 1FX4S6
- bottled gas, el. 657'	IFT10N
- SI pump	no damage
AX-23B:	0
- flammable liquid storage cab	no damage
- bottled gas, el. 586'	no damage
TU 90:	ee-
- bus 5	no damage
MCC 52A	no damage
- diesel fire	no damage
TU 92:	ing duringe
MCC 62A	1DT4S6, MCC 62A
- bus 6	no damage
diesel fire	1DT8N
SC-70A	
AX 30	no damage
fire near vertical trays	1RT62S6, 1AT12S6, 1AT13S6
······································	

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 224 of 415

fire near cabinet	no damage
TU-95C	1TT8S5, 1TT4S5, 1TT4N, 1TT5N, 1TT106S5
AX-32:	
- MCC 62B	no damage
$MC \subset C2B$ ext	no damage
- cable spreading area	not modeled*
AX-35	not modeled*
AX-23D	1AT20N
TU-94:	
- air comp A fire	no damage
- beneath cable trays	no damage
TU-95B:	
- cable trays above bus 61	no damage
- cable trays north of bus 62	no damage
- cable trays in AFW B room	1TT8S5, 1TT4S5, 1TT4N, 1TT15N, 1TT8S6, 1TT4S6, 1TT10N, 1TT20N
- turbine-driven AFW pump room	not modeled**

AX-21

1A19N

\* Neither the cable spreading area nor the control room are modeled. These rooms are discussed in Section 4.2.

\*\* All cable trays are located above the steam exclusion ceiling.

The area of influence for the fires causing damage is determined by iterating the COMPBRN runs while moving the fire source around. Table 4-3 shows the area of influence for each scenario.

Those scenarios showing no damage are not analyzed further.

#### 4.4 Evaluation of Component Fragilities and Failure Modes

If a component or cable is determined to be damaged by fire, then it is assumed to fail with a probability of 1.0. In the case of the AFW pump rooms, darlage to the cable trays in the room is estimated by COMPBRN to occur with a probability of 0.52 for the A pump room and 0.05 for the B pump room. This figure is factored in the initiating event frequency calculation for the AFW pump B room.

#### 4.5 Fire Detection and Suppression

#### 4.5.1 Automatic and Manual Fire Detection and Suppression

Manual fire detection is based upon room occupancy. All rooms except the control room are assumed to be unoccupied. Manual fire detection elsewhere is based upon maximum patrol interval, which is determined to be two hours.

Manual fire suppression capability is demonstrated by plant-specific documentation, which documents fire brigade drills from 1988 to 1991. It is concluded that the response time from alarm initiation to assembly of the fully turned out brigade is 6.0 minutes for the turbine building and screenhouse, and 6.4 minutes for the auxiliary building.

Automatic fire detection is accomplished by ionization detectors, which are described in the NFPA Handbook (Reference 17). Thermal detectors also exist in the diesel generator rooms.

In the initiating event frequency calculations, automatic fire suppression is listed for each scenario. Automatic suppression is assumed to be initiated instantaneously upon successful fire detection.

#### 4.6 Analysis of Plant Systems, Sequences, and Plant Responses

#### 4.6.1 Identification of Components Affected by Fire

After the vulnerable cable trays are identified, their contents are determined. Table 4-4 lists the contents of the cable trays that were found to be vulnerable to damage in the postulated fire scenarios. This table also lists the fault tree identifiers for the damaged cables/components, and the fault trees in which the identifiers appear.

When determining the contents of cable trays that had been identified as vulnerable to damage, a number of cable trays were found to contain only cables for components that are not modeled in the IPE. As a result, a number of scenarios are not analyzed in detail. The cable trays that contain only cables for components that are not modeled in the IPE are listed below:

Cable tray	Room in which cable tray resides
1AT20N	AX-35
1FX4S6	AX-23A, near MCC 62J
IFT10N	AX-23A, near bottled gas at elevation 657'-0"

#### 4.6.2 Determination of Initiating Event Frequency in Each Zone Requiring Quantification

Figures 4-1 through 4-8 show the derivation of the initiating event frequency for each scenario. The transient with main feedwater, transient without main feedwater or loss of offsite power event sequence was used depending on the scenario.

#### 4.6.3 Fire-Induced Core Damage Frequency Quantification

Core damage frequencies are computed for each fire scenario. Table 4-5 shows results from the eight scenarios that require quantification of core damage frequency (CDF). The fire CDF is 9.81E-05, which is about the same as the internal events CDF (8.74E-95). Tables 4-7 through 4-14 show the results for each scenario. Following is a discussion of the results from quantification of core damage frequency for each fire scenario.

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 226 of 415

Results show that fires in the AFW pump rooms (Scenarios FI6 and FI7) dominate all the scenarios requiring quantification.

#### 4.6.3.1 FI1: Fire near MCC 62J in AX-23A

A fire near this MCC, which is located in a closed corridor. has a small impact on the plant. Table 4-7 lists the top 50 dominant cutsets for this scenario. The transient with main feedwater available event tree (Figure 4-9) is used in this scenario.

Since this fire does not prohibit the operation of safe shutdown equipment from the control room, it is assumed operators do not use procedure E-0-06, Fire in Alternate Zone, which requires manual isolation of offsite power and evacuation of the control room.

#### 4.6.3.2 FI2: Fire near MCC 62A in TU-92

A fire near this MCC, which is located in the B diesel generator room, is postulated. Cable tray 1DT4S6 and the MCC are affected. Table 4-8 shows the top 50 dominant cutsets for this scenario. The transient with main feedwater available event tree (Figure 4-9) is used in this scenario.

Since this fire does not prohibit the operation of safe shutdown equipment from the control room, it is assumed operators do not use procedure E-0-06, Fire in Alternate Zone, which requires manual isolation of offsite power and evacuation of the control room.

#### 4.6.3.3 FI3: Fire in AX-21, near non-safeguards 4160 V electrical buses 1 and 2

A postulated fire near non-safeguards 4160 V electrical buses 1 and 2 damages cable tray 1AT9N, containing main feedwater cabling. The cabling leading to the buses is not damaged. Table 4-9 shows the top 50 dominant cutsets for this scenario. The transient without main feedwater event tree (Figure 4-10) is used in this scenario.

Since this fire does not prohibit the operation of safe shutdown equipment from the control room, it is assumed operators do not use procedure E-0-06, Fire in Alternate Zone, which requires manual isolation of offsite power and evacuation of the control room.

#### 4.6.3.4 FI4: Diesel fire in TU-92

Cable tray 1DT8N is damaged in this postulated fire scenario. Table 4-10 shows the top 50 dominant cutsets for this scenario. Due to the loss of the RAT, which supplies power to buses 1 through 4, a modified loss of offsite power sequence (Figure 4-11), which allows the TAT to supply bus 5, is used in this scenario.

Since this fire does not prohibit the operation of safe shutdown equipment from the control room, it is assumed operators do not use procedure E-0-06, Fire in Alternate Zone, which requires manual isolation of offsite power and evacuation of the control room.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 227 of 415

#### 4.6.3.5 FI5: Fire in relay room near vertical cable trays

Safeguards 4160 V electrical bus 6 and cable trays 1RT62S6, 1AT12S6, and 1AT13S6 are disabled in this postulated fire scenario. Table 4-11 shows the dominant cutsets for this scenario. The dedicated shutdown system event tree (Figure 4-12) is used in this scenario.

Due to the proximity of the relay room to the control room and the chance of the fire spreading and affecting safe shutdown capability from the control room, it is assumed that the operators evacuate the control room and go to the dedicated shutdown panel using procedure E-0-06, Fire in Alternate Zone. Therefore, it is assumed that offsite power is not available and that operators manually restore power to safeguards 4160 V electrical bus 5.

#### 4.6.3.6 FI6: AFW pump A oil fire

This scenario is still analyzed, despite the 0.48 probability of no damage to the cable trays. All cable trays in this room and the AFW pump A are assumed damaged. Table 4-12 shows the top 50 dominant cutsets for this scenario. The alternate shutdown system event tree (Figure 4-13) is used for this scenario. Fire-induced disabling of the vulnerable cable trays causes damage to cables that control components vital to safe shutdown, giving rise to a high core damage frequency.

Operators are instructed to use procedure E-0-07, Fire in Dedicated Zone, which requires manual isolation of offsite power, when train A equipment is not available. Since this is the case for this fire, it is assumed that offsite power is not available and that operators manually restore power to safeguards 4160 V electrical bus 6.

#### 4.6.3.7 FI7: AFW pump B oil fire

This scenario is still analyzed, despite the 0.95 probability of no damage to the cable trays. All of the following cable trays show susceptibility to damage: 1TT8S5, 1TT4S5, 1TT4N, 1TT8S6, 1TT4S6, 1TT10N, and 1TT20N. Electrical buses 3, 4, and 6 are disabled due to damage to the contents of these trays. Table 4-13 shows the top 50 dominant cutsets for this scenario. The dedicated shutdown system event tree (Figure 4-12) is used for this scenario.

Fire-induced disabling of the vulnerable cable trays causes damage to cables that control components vital to safe shutdown, giving rise to a high core damage frequency. Failure of safeguards 4160 V electrical bus 6 is assumed because the cables for the source breakers for these components are vulnerable to fire-induced damage.

Since this fire renders operation of equipment from the control room impossible, it is assumed that the operators evacuate the control room and go to the dedicated shutdown panel using procedure E-0.06, Fire in Alternate Zone. Therefore, it is assumed that offsite power is not available and that operators manually restore power to safeguards 4160 V electrical bus 5.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 228 of 415

#### 4.6.3.8 FI8: Fire near safeguards 480 V electrical buses 51 and 52

Cable tray 1TT5S5 and the source breaker cabling for safeguards 4160 V electrical bus 5 are damaged in this scenario. Table 4-14 shows the dominant cutsets for this scenario. The alternate shutdown system event tree (Figure 4-13) is used in this scenario.

Operators are instructed to use procedure E-0-07, Fire in Dedicated Zone, which requires manual isolation of offsite power, when train A equipment is not available. Since this is the case for this fire, it is assumed that offsite power is not available and that operators manually restore power to safeguards 4160 V electrical bus 6.

#### 4.6.3.9 Core damage timing

Because the accident sequences induced by a fire are similar to those analyzed for the internal events analysis, fire-induced core damage timing is similar to that determined for the internal events analysis. The core damage timing for fire induced events is shown in Tables 4-9 through 4-13.

#### 4.6.4 Dominant Fire-Induced Core Damage Sequences

Table 4-15 lists the 22 systemic core damage sequences of the Fire PRA. Of these, 13 are dominant according to the definition provided in NUREG-1335. These sequences represent 99.95% of the total core melt frequency. Following is a description of each of these dominant sequences. The frequency and percent contribution of each sequence is given in Table 4.B-9.

#### • Sequence #1 - AFW pump A oil fire followed by failures of AFW and bleed and feed.

This results in a loss of heat sink and early core damage. The primary means by which heat sink is lost is a station blackout. Since offsite power and the A diesel generator are unavailable as a result of the fire, a failure of the B diesel generator or the B train of service water, which cools the diesel generator, results in a station blackout. Since the fire also disables control cabling for the turbine driven AFW pump, there is no heat sink and therefore core melt occurs. The primary human errors in this sequence are failure to manually establish electrical power from the B diesel generator and failure to locally restore instrument air for the pressurizer PORVs, used for bleed and feed.

#### • Sequence #2 - AFW pump B oil fire followed by failure of AFW.

This results in a loss of heat sink and early core damage. Other means of removing heat, (main feedwater, condensate, bleed and feed) are unavailable due to the unavailability of offsite power and safety injection pumps from the DSP. This sequence is dominated by human error. Failure to establish electrical power from the A diesel generator locally and failure to establish service water and AFW from the DSP are major contributors to this sequence.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 229 of 415

Sequence #3 - AFW pump A oil fire followed by failure of CCW.

This results in a loss of cooling to the RXCP thermal barrier, which can result in a small LOCA due to RXCP seal failure. Since SI and RHR pumps are cooled by CCW and charging is not available because of cabling damaged by the fire, there is no way to get makeup flow to the Reactor Coolant System to replace that lost through the RXCP seals and late core damage results. The only human error in this sequence is the failure to manually restart CCW and this is a relatively minor contributor.

• Sequence #4 Fire near MCC 62A in B diesel generator room followed by a failure of charging and CCW.

This results in a loss of cooling to the RXCP seals and late core damage. The primary means of loss charging and CCW is loss of power to the emergency buses, buses 5 and 6. Human error is not important in this sequence.

• Sequence #5 - Oil fire in B diesel generator followed by a failure of charging and CCW.

This results in loss of cooling to the RXCP seals and late core damage. The primary contributor is a mechanical failure of CCW and operator error in establishing charging flow.

• Sequence #6 - Fire near safeguard 480 V electrical buses 51 and 52 followed by a failure of CCW.

This results in a loss of cooling to the RXCP seals and late core damage. Human errors in this sequence include failures to manually establish on-site power, service water and CCW.

• Sequence #7 - Oil fire in B diesel generator followed by failure of AFW and bleed and feed.

This results in a loss of heat sink and early core damage. All B train equipment, powered by safeguards 4160 V electrical bus 6, is unavailable due to the fire. Therefore, the primary means of failure is mechanical failure of the A motor driven and turbine driven AFW pumps followed by failures of the SI, CCW or Instrument Air Systems, all of which are needed for bleed and feed. And her means of failure is a failure of DC bus BRA-104, which is needed to start both the A motor driven and turbine driven AFW pumps, and the A SI pump. Human error, the failure to establish bleed and feed, is a minor contributor to this sequence.

• Sequence #8 - Oil fire in B diesel generator followed by failure of AFW, success of bleed and feed, and failure of high pressure recirculation.

This results in a loss of heat sink and late core damage. All B train equipment, powered by bus 6, is unavailable due to the fire. Therefore, the primary means of failure is mechanical failure of the A motor driven and turbine driven AFW pumps followed by

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 230 of 415

failures of valves associated with switchover to containment sump recirculation. Human error, in this case failure to stop the A RHR pump to limit its time in miniflow, is a minor contributor to this sequence.

# • Sequence #9 - Oil fire in A AFW pump followed by failure of AFW, success of bleed and feed, and failure of high pressure recirculation.

This results in a loss of heat sink and late core damage. Since the fire destroys both the A AFW pump and control cabling for the turbine driven pump, the primary means of failure is a mechanical failure of the B AFW pump followed by failure of valves associated with switchover to containment sump recirculation. Human error is not important in this sequence.

#### • Sequence #10 - Oil fire in B AFW pump followed by failure of charging and CCW.

This results in a loss of cooling to the RXCP seals and late core damage. Both CCW and charging must be established from the DSP. This sequence is dominated by the combination of failure to establish CCW and failure to establish charging. In this case, moderate dependency is applied, as stated in Section 4.8.7.4.

#### • Sequence #11 - Fire in the relay room followed by failure of AFW.

This results in a loss of heat sink and early core damage The dominant contributor to this sequence is human error. The A diesel generator must be started locally, and service water and either charging or CCW must be started from the DSP.

# • Sequence #12 - Fire near buses 51 and 52 followed by failure of AFW and bleed and feed.

This results in a loss of heat sink and early core damage. Since AFW, SI, and instrument air are all started locally, human error is the dominant contributor to this sequence. Of these human errors, the largest contributor is failure to establish AFW and instrument air. These are not modeled as dependent actions because AFW is started from the control room and the instrument air compressor is simultaneously started locally.

# • Sequence #13 - Fire near MCC 62A in B diesel generator room followed by failure of AFW, main feedwater, and bleed and feed.

This sequence consists mostly of mechanical failures of AFW followed by the operator failing to stop the RXCPs, in order to prevent the additional heat input into the Reactor Coolant System.

#### 4.7 Fire-Induced Containment Failures

#### 4.7.1 Containment Failure Frequency Quantification Procedure

As in the IPE, the core damage sequences are coupled with the containment safeguards systems in order to determine which systems would be available after core damage. The containment safeguards systems used are containment isolation (CI), containment fan coil units, ICS and low pressure SI recirculation. Fire-induced failures of these systems are accounted for in the same way as those systems used in the core melt frequency determination. The containment event tree (CET) is identical to that used for the IPE and is therefore not reproduced in this report. The frequencies of each CET end state are presented in Table 4-6. The phenomenological studies performed for the IPE are bounding for the fire PRA as well, because no additional vulnerabilities were discovered in the fire PRA. As in the IPE, a 48 hour mission time is used.

#### 4.7.2 Quantification Results

Table 4-7 shows the results of the Level 2 fire analysis. The fire-induced containment failure frequency is 3.64E-05 which is considerably larger than the internal events containment failure frequency (8.03E-06) but not out of line with containment failure frequency values from other PRAs in the industry. The fire-induced containment failure frequency is 31% of fire-induced CDF.

#### 4.8 Treatment of Fire Risk Scoping Study Issues

#### 4.8.1 Dependency Between Control Room and Remote Shutdown Panel Circuitry

The remote shutdown panel and the control room are in two separate fire areas. There is segregation between the two areas, and the cables contained in each area. Shutdown functions in dedicated and alternate fire areas are separated. Dependency between the control room and the remote shutdown panel is not credible at Kewaunee.

#### 4.8.2 Cable Routing Verification

Cable routing was verified for the 1990 WPSC internal audit of fire documentation. Updated cable tracing information is used in this analysis.

#### 4.8.3 Suppression Agent Induced Damage

Page 6-14 of the Kewaunee Fire Protection Program Analysis states, "In the use of Halon 1301 and  $CO_2$ , toxicity, thermal shock, concentration and soak times and overpressurization have all been considered in the initial design." Insufficient data exists to quantitatively analyze potential Halon and  $CO_2$  damage. During the walkdown, obvious potential hazards for  $CO_2$  and Halon damage were identified and have been addressed in this report.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 232 of 415

Water damage from fire suppression activities could disable components. Damage due to fire effects or suppression activities is assumed to fail affected components. Many safety-related areas have no automatic suppression systems, so inadvertent automatic system actuation is impossible. The fire brigade is trained to avoid spraying energized electrical components.

Kewaunee Operations Experience Assessment 83-78 (Reference 18) addresses suppression agent induced damage at Kewaunee and concludes that it is not a significant issue.

#### 4.8.4 Fire Brigade Effectiveness

Reference 7 documents fire brigade drills from 1988 to 1991. Fire brigade response times were determined for anywhere in the auxiliary building, and anywhere in the turbine building (including the screenhouse). Response times are 6.0 minutes for anywhere in the turbine building, and 6.4 minutes for anywhere in the auxiliary building.

Reference 8 documents the responses of Kewaunee to a fire brigade survey described in the Fire Risk Scoping Study (Reference 19). According to the survey, Kewaunee has a comprehensive fire brigade.

The fire brigade is trained and drilled, as described in Fire Brigade Training Procedures.

#### 4.8.5 Seismic-Fire Interactions

#### 4.8.5.1 Seismically induced fires

Pumps that contain lube oil could be vulnerable to lube oil spillage, and possibly initiate a fire. At Kewaunee, all safety-related pumps are also seismic class I, which means they can survive a design basis earthquake. Non-safety related pumps such as the main feedwater pumps are not seismically anchored. However, non-safety related pumps are not co-located with safety related components. The turbine lube oil storage tank was evaluated by a Seismic Qualification Utility Group (SQUG) Seismic Review Team during the unresolved safety issue (USI) A-46 walkdowns conducted in March and April, 1993. Stevenson and Associates performed an anchorage evaluation of the tank, and determined that the tank was seismically adequate. Diesel generator day tanks and gas bottles are also seismically anchored. It is concluded that seismically induced fires that threaten safety related components are not credible at Kewaunee.

#### 4.8.5.2 Seismic degradation of fire suppression capabilities

Fire suppression capabilities in the safeguards areas at Kewaunee include fire water from class I service water and  $CO_2$ . The two fire pumps at Kewaunee are qualified according to the USI A-46 program. Table B.2-1 of the Kewaunee Updated Safety Analysis Peport (USAR) states that the fire protection systems serving class I equipment are classified as class I. The water sprinkler piping and the sprinkler heads in non-safeguards areas are not seismically anchored. The  $CO_2$  tank is seismically anchored. Seismically induced actuation of the ulesel generator Cardox system was examined (Reference 20), and concluded not to present a hazard. A seismic event could damage fire water capability, but damage to the  $CO_2$  system is not credible.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 233 of 415

Mercury switches are a special concern, because they can spuriously operate during even a minor seismic event. The following switches were determined from the seismic walkdown to be mercury switches:

A and B fire pumps, jockey pump switches

The malfunction of these switches could cause the pumps to not operate on demand, or to operate spuriously. If the pumps were to operate spuriously, they would pressurize the line. This could result in damage to the pumps by dead heading, but it could not result in spurious actuation of the sprinklers. Therefore, the worst case is the unavailability of the pumps.

Cardox pressure switch

This switch operates the compressor that controls  $CO_2$  pressure in the Cardox system. A malfunction of this switch could cause the compressor to not operate on demand, or to operate spuriously. If the compressor failed to operate on demand, it would cause the relief valve to open, venting  $CO_2$  out the roof of the turbine building. If it were to operate spuriously, the pressure could get too low, also causing the system to be inoperable. Neither failure of the switch could cause the Cardox system to spuriously operate.

A failure of any or all of the above switches could result in the unavailability of the fire protection system when needed. The fire and seismic walkdowns assessed the possibility of a seismically induced fire, and none were found. The probability of an independent fire concurrent with a seismic event is negligible.

#### 4.8.5.3 Inadvertent actuation of fire suppression systems

A seismic event could actuate charged fire water sprinkler systems. Because charged suppression systems are not located in safety-critical areas at Kewaunee, the impact of inadvertent actuations is minimized.

#### 4.8.6 Use of Plant Specific Data

After reviewing fire Licensee Event Reports and Kewaunee reports, it was concluded that insufficient data exists to update generic fire data with plant specific data.

#### 4.8.7 Consideration of Uncertainties

Sources of uncertainty in a fire PRA include the following:

- Fire initiation frequencies
- Judgement of fire propagation
- Fire suppression probabilities
- Human error calculations

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 234 of 415

- COMPBRN IIIe code calculations
- Barrier failure
- Random failure probabilities

#### 4.8.7.1 Uncertainty in generation of fire initiation frequencies

The most current database is employed in deriving the fire initiation frequencies. In addition, the method used to derive these frequencies is comprehensive, and accounts for both fixed and transient combustibles.

#### 4.8.7.2 Judgement of fire propagation

Judgement of whether a fire could propagate to an adjacent area or zone is based on Appendix R documentation (barrier construction, combustible loading, and door fire ratings), and general arrangement drawings. These were verified during walkdown inspection. In addition, during the walkdown, control of transient combustibles that could lead to fire propagation was verified.

#### 4.8.7.3 Fire suppression probabilities

Fire suppression system unavailabilities were obtained from the FIVE Methodology. Effectiveness of the fire suppression was determined by the following:

- Time to damage of components/cables is oetermined using the COMPBRN IIIe code.
- Time to actuate detection devices is determined using the COMPBRN IIIe code.

- If  $t_{damage}$  is less than  $t_{detector actuation}$ , then credit for fire suppression is not granted. If  $t_{damage}$  exceeds  $t_{detector actuation}$ , then the unavailabilities of detector and suppression systems are factored into development of the initiating event frequency.

#### 4.8.7.4 Human error calculations

The human actions required during a fire-induced transient (with the exception of fighting the fire which is described in section 4.8.4) are similar to those actions described in the IPE. There are, however, three differences that need to be addressed.

- a) Additional stress is put on the operators due to the fire and the resulting loss of equipment and instrumentation.
- b) Local actions may be hampered by the presence of the fire.
- c) A severe fire results in entry to procedures E-0-06, Fire in Alternate Zone, or E-0-07, Fire in Dedicated Zone. These procedures have many additional steps, such as removing fuses and isolating offsite power. In addition, E-0-06 requires evacuation of the control room and activation of the dedicated shutdown panel (DSP).

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 235 of 415

For events in which E-0-06 and E-0-07 are not necessary, the additional stress is accounted for by assuming that moderate stress, as defined by the IPE, becomes high stress in a fire situation. This results in a multiplier of 5 (high stress) placed on both the action and the recovery, replacing a multiplier of 2 (medium stress). Since the action is multiplied by the recovery, the net effect is to place a multiplier of  $(5/2)^2$  or 6.25 on each medium stress action. For simplicity and conservatism, a factor of 10 is applied to all actions with two exceptions. The exceptions are 1) those actions taken before the event that result in returning a piece of equipment to service after test and maintenance, and 2) those actions taken late in the accident, such as switchover to containment sump recirculation, after which the initial stress due to the fire has died down.

Only one local action is modeled for the fire analysis. This action is opening valves SW-1300A and SW-1300B to provide additional service water flow to cool the component cooling heat exchangers in the event that these valves do not open automatically. This action does not take place in any of the fire zones that were not screened out, nor are any of those zones traversed by the operator on the way to these valves. This action is not necessary until after the switchover to containment sump recirculation (at least 3.5 hours), so the auxiliary operator has ample time to perform it, even if he was involved in the fire-fighting effort. Therefore, no additional penalty, other than the factor of 10 discussed above, is taken for this action.

In a fire that causes the inability to monitor or control major plant parameters from the control room, operators are instructed to enter E-0-06. This procedure instructs the operators to evacuate the control room, isolate alternate (train B), and nonsafeguards equipment including offsite power, manually restore power from the A diesel generator and shut the plant down from the DSP. Bleed and feed, which is used in the IPE in case AFW and main feedwater fails, is not available from the DSP and is therefore not considered in this analysis. Since the operator actions are very different from any scenario in the IPE, they have been evaluated separately using the same methodology employed in the IPE. Following are all operator actions in E-0-06 that appear in the fire PRA and their human error probabilities (HEPs):

ACTION	HEP
Isolate nonessential equipment and restore power to electrical bus 5	2.69E-01
Establish service water from the DSP	8.06E-02
Establish AFW from the DSP	5.19E-02
Establish charging from the DSP	1.03E-01
Establish CCW to the RXCP thermal barriers	3.08E-02

One operator error dependency exists - charging is only necessary if CCW fails. Therefore, according to the dependency rules used in the IPE, moderate dependency is applied. This results in a human error probability of 2.31E-01 for establishing charging when CCW has failed due to operator error.

These values are used for scenarios FI5 and FI7.

In a fire that causes the inability to monitor or control dedicated equipment and instrumentation from the control room, operators are instructed to enter E-0-07. This procedure is similar to E-0-06, except that the operators continue to occupy the control room. Charging is isolated in

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 236 of 415

E-0-07 since all three charging pumps are in a dedicated zone so their ability to provide cooling to the RXCP seals is not considered. Since the operator actions are very different from any scenario in the IPE, they have been evaluated separately using the same methodology employed in the IPE. Following are all operator actions that appear in E-0-07 and their HEPs:

ACTION	HEP
Isolate nonessential equipment and restore power to electrical bus 6	7.87E-03
Establish service water manually	1.72E-03
Establish AFW manually	3.18E-03
Establish CCW to the RXCP thermal barriers	1.59E-03
Establish safety injection	5.57E-03
Establish instrument air	3.98E-01

One operator error dependency exists - safety injection is only necessary if AFW fails. Therefore, according to the dependency rules used in the IPE, moderate dependency is applied. This results in a human error probability of 1.50E-01 for establishing safety injection when AFW has failed due to operator error.

These values are used for scenarios FI6 and FI8. Since the control room and control room alarms and indications are available, operators can perform other tasks while in E-0-07. The HEP values for these tasks are values used for the IPE with a factor of 10 applied due to additional stress as explained above.

#### 4.8.7.5 COMPBRN calculations

The uncertainty option in COMPBRN was run to gauge the uncertainty in the COMPBRN calculations and these results are discussed along with the discussion of the base case COMPBRN runs.

#### 4.8.7.6 Barrier failure

Ratings from the NFPA Handbook (Reference 21) for fire resistance of barriers were used, and compared with the combustible loadings of fixed and transient combustibles. Combustible loadings were verified during the walkdown by observing combustibles in each zone.

#### 4.8.7.7 Random failure probabilities

In the IPE, sensitivity studies were performed to determine the effects of varying certain parameters on the core damage frequencies. Sources of uncertainty for random failure probabilities were identified in the IPE. There are no failure modes unique to the fire analysis that generate new random failure uncertainties. Random failure uncertainties are dominated by other sources of uncertainty in fire analysis.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 237 of 415

### 4.9 USI A-45 and Other Safety Issues

Unresolved Safety Issue A-45, Shutdown Decay Heat Removal Requirements, as it pertains to the fire analysis, is discussed in detail in Section 3.2 of this report.

The Kewaunee response to NRC Bulletin 92-01, regarding Thermo-Lag 330-1 Fire Barriers, states that there is no Thermo-Lag material at Kewaunee. The response is documented in Reference 22.

The concerns raised in GI-57, "Effects of Fire Protection System Actuation on Safety-Related Equipment," (Reference 23) were investigated qualitatively. This includes examination of inadvertent and advertent actuations of fire protection systems, and seismic-fire interactions. It is concluded that since automatic fire protection systems are minimally present in areas where safety-critical equipment resides, there is minimal impact if fire protection systems were to actuate. Likewise, seismic-fire interactions are minimized due to the absence of automatic fire protection systems in critical areas, and adequate anchoring of ignition sources (i.e., fuel tanks) in safeguards areas. Additional discussion of seismic-fire interactions is present in sections 4.6.5.1 through 4.6.5.3 of this report.

#### 4.10 Areas of Conservatism

The following areas of conservatism are inherent in this analysis:

a. Total damage is assumed for any component or cable found to be vulnerable to fire damage using COMPBRN. The conservatisms present in COMPBRN are described in the COMPBRN manual. Exceptions to assuming total damage are found in the modeling of a fire in the AFW pump rooms. COMPBRN indicates that the probability of damage, given a fire is only 0.52 in the A pump room and 0.05 in the B pump room. This probability is factored in calculation of the initiating event frequency for this scenario.

b. Although strict transient combustible controls exist at Kewaunee, all trash cans are equipped with lids held open by fusible links, and administrative controls are adhered to, it is postulated in this analysis that a fire may be started by violation of administrative controls and that transient combustibles would fuel the fire.

c. Although most fires historically have either been detected and extinguished by personnel prior to damage or have been self-extinguishing, credit is not taken for this in this analysis.

d. In the evaluation of the cable trays to determine what equipment is affected by damage to a given cable tray, it is assumed in many cases that if a cable is associated with a given piece of equipment, then damage to that cable renders the piece of equipment inoperable.

#### 4.11 Summary of Key Findings

AFW pump A and B oil fires give rise to high core damage frequencies, 5.27E-5/yr for AFW pump A, and 2.97E-5/yr for AFW pump B. The sum of these two core damage frequencies accounts for 84% of the total fire induced core damage frequency. All other scenarios yield lower core damage frequencies Three other scenarios produce reportable core damage frequencies: scenarios, FI4 (diesel generator B oil fire - 7.44E-06/year), FI2 (MCC 62A Scenario - 4.65E-06/year), and FI8 (fire near MCCs 51 and 52 - 3.33E-06/year). Neither of the AFW pump rooms has automatic suppression in the room, so credit is not taken for automatic suppression. Conservative assumptions are made in calculating the initiating event frequency, and when determining the contents of the cable trays passing through these rooms.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 239 of 415

#### 4.12 References

- 1. GL 88 20, Supplement 4, "Individual Plant Examination of External Events (IPEEE) for Severe Accident Vulnerabilities 10CFR50.54(f), June 1991.
- 2. Appendix R Design Description, Wisconsin Public Service Corporation, 1990.
- 3. "Fire Protection Program Analysis, Kewaunee Nuclear Power Plant," Volumes 1 & 2, Wisconsin Public Service Corporation, Revision 3, February 1991.
- 4 Licensee Event Reports for fire events at the Kewaunee Nuclear Power Plant.
- 5 Procedures for shutdown given a fire in Alternate and Dedicated Zones:

E-0-06, "Fire in Alternate Fire Zone", November 6, 1990.

E-0-07, "Fire in Dedicated Fire Zone", November 6, 1990.

- 6 FPP 08-8, "Control of Transient Combustibles", WPSC KNPP Fire Plan Procedure, November 19, 1991.
- 7. Fire brigade response times compiled from fire drills during 1988 to 1991.
- 8. Fire Brigade Survey for Kewaunee Nuclear Power Plant, 1992.
- 9. Procedures for Fire Brigade Training:

T FBT-L.P. 08-2 T-FBT-L.P. 08-3 T-FBT-L.P. 08-4 T-FBT-L.P. 08-5 T-FBT-L.P. 08-6 T-FBT-L.P. 08-7 T-FBT-L.P. 08-8 T-FBT-L.P. 08-9 T-FBT-L.P. 08-10 T-FBT-L.P. 08-11 T-FBT-L.P. 08-12 T-FBT-L.P. 08-13 T-FBT-L.P. 08-14 T FBT-L.P. 08-15 T-FBT-L.P. 08-16 T-FBT-L.F 08-17 T-FBT-L.P. 08-18 T-FBT-L.P. 08-19 T-FBT-L.P. 08-20 T-F3T-L.P. 08-21

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 240 of 415

- 10. Fire Area Strategies, Kewaunee Nuclear Power Plant, 1990.
- 11. "Fire Induced Vulnerability Evaluation Methodology (FIVE) Plant Screening Guide," Prepared by Professional Loss Control for EPRI under Contract No. RP 3000-41, December 1991.
- 12. WALT and WLINK codes, WLINK Code System, Version 3.11, July 1992.
- 13. "COMPBRN IIIe: An Interactive Computer Code for Fire Risk Analysis," University of California at Les Angeles, EPRI NP-7282, May 1991.
- 14. WALT files used for screening, November 1992.
- 15. Kewaunee Nuclear Power Plant Individual Plant Examination, December 1992.
- 16. EPRI/NUMARC fire workshop, June 1992, Baltimore, Maryland.
- 17. Fire Protection Handbook, 17th edition, NFPA, 1991.
- 18. Operational Experience Assessment #83-78, "Actuation of Fire Suppression System Causing Inoperability of Safety-Related Equipment (IE IN 83-41)," WPS, June 30, 1983.
- 19. NUREG/CR-5088, "Fire Risk Scoping Study: Investigation of Nuclear Power Plant Fire Risk, Including Previously Unaddressed Issues, January 1989.
- 20. Letter from Walter Djordjevic of Stevenson Associates to Greg Ridder of Wisconsin Public Service Corporation, April 15, 1992.
- 21. Fire Protection Handbook, Seventeenth Edition, NFPA, 1991.
- 22. Letter from C.R. Steinhardt of WPSC to U.S. Nuclear Regulatory Commission, re: NRC Bulletin 92-01, July 27, 1992.
- 23. NUREG/CR-5580, Volume 1, "Evaluation of Generic Issue 57: Effects of Fire Protection System Actuation on Safety-Related Equipment," Lambright, J. A. et. al., December 1992.

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 241 of 415

### Table 4-1: Kewaunee Fire Initiation Frequencies

### \*\*\* KEWAUNEE FIRE INITIATION FREQUENCIES \*\*\*

a - number of ignition sources in compartment

 $b \gg total number of ignition sources in selected plant location$ 

 $c \in total number of ignition sources compartments in plant$ 

Fife = fire ignition frequency by location and source

ignation source trequency (Fift) = WF(L) x WF(LS) x Fift)

compartment tire frequency  $|F(l) \cap sum(F(if)_{\ell})|$ 

#### DEDICATED ZONES

AX 23B	SELECTED PLANT LOCATION	AUXILIARY BLDG					
	LOCATION WEIGHTING FACTOR	VF(L)	1	T			1
	COMPONENT IGNITION SOURCES		•	Ь	WF(LS) = a/b	F(f)	F(if)
	ELECTRICAL CABINETS		24	72	0.33333333333	0.019	0 006333
	PUMPS		6	16	0 375	0 019	0.007125
	PLANT-WIDE IGNITION SOURCES		+	c	WF(LS) = a/c	F(f)	F(if)
	TRANSIENTS		3	25	0 12	0 0013	0.000156
	TRANSFORMERS	- <u></u>	2	21	0.0952380952	0.0079	0.000752
1	VENTILATION SYSTEMS		2	21	0 0952380952	0 0095	0 000904

SC 70A	SELECTED PLANT LOCATION	INTAKE STRUCTURE					
	LOCATION WEIGHTING FACTOR - V	VF(L)	1				
	COMPONENT IGNITION SOURCES		4	b	WF(LS) = a/b	<b>F</b> (r)	F(if)
	ELECTRICAL CABINETS		4	6	0 6666666667	0.0024	0 0016
	FIRE PUMPS		1	2	05	0 004	0.002
	SW PUMPS		2	4	0.5	0 0032	0 0016
	PLANT WIDE IGNITION SOURCES			c	WF(LS) = a/c	F(f)	F(if)
	VENTILATION SYSTEMS		1	21	0 0476190476	0.0095	0.000452
	FIRE PROTECTION PANELS		1	2	0.5	0.0024	0 0012
		COMPARTMENT FIRE	FRE	UENC	$(\mathbf{Y} \cdot \mathbf{F}(1)) = \mathbf{sum}\{\mathbf{I}\}$	F(if)] =	0 006852

TT: 90	SELECTED PLANT LOCATION	DIESEL ROOM A					
	LOCATION WEIGHTING FACTOR WE	F(L)	1	T	1	Τ	T
	COMPONENT IGNITION SOURCES	<u> </u>	8	b	WF(LS) = a/b	F(f)	Frif)
	DIESEL GENERATOR A		1	3	0 3333333333	0 026	0 008666
	4160V BUS 5, MCC 52A		1-3	31	0 4516129032	0 0024	0 001083
	PLANT WIDE IGNTHON SOURCES.		•	c	WF(LS) = e/c	F(f)	F(if)
	TRANSIENTS		1	25	0 04	0 0013	0 000052
	VENTILATION SYSTEMS		1	21	0 0476190476	0 0095	0 000452
		COMPARTMENT FIR	E FREQ	UENCY	$f \cdot F(l) = sum[F_l]$	(if)] =	0 010253

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 242 of 415

TU 95A	SELECTED PLANT LOCATION	SWGR DEDICATED SHUTDOWN PANEL ROOM					
	LOCATION WEIGHTING FACTOR W	F(L)	0 25			I	
	COMPONENT IGNITION SOURCES			b	WF(LS) = a.b	F(f)	Fiif)
	ELECTRICAL CABINETS		10	71	0 1408450704	0.0	0 000528
	PLANT WIDE IGNITION SOURCES			с	WF(LS) = a/c	F(f)	F(if)
	VENTILATION SYSTEMS		1	21	0 0476190476	0 0095	0.000452
	AIR COMPRESSOR		1	6	0.1666666667	0 0047	0.000783
•		COMPARTME	T FREQUEN	CY	F(1) = sum[F(if)]	÷	0.001764

TU 95C	SELECTED PLANT LOCATION	AFW PUMP A ROOM					
	LOCATION WEIGHTING FACTOR W	/F(L)	I	T	1	T	
	COMPONENT IGNITION SOURCES			b	WF(LS) = a/b	F(f)	F(if)
	PUMP IA	······································	1	8	0 125	0.0063	0.000787
	PLANT WIDE IGNITION SOURCES		•	c	WF(LS) = s/c	F(f)	F(if)
	VENTILATION SYSTEMS		1	21	0.0476190476	0 0095	0 000452
		COMPARTMENT FIRE	FREQ	UENCY	$(\cdot F(1) = sum (F)$	(if)] =	0.001239

TU 97	SELECTED PLANT LOCATION	BATTERY ROOM (ROOM 129)					
	LOCATION WEIGHTING FACTOR - WF(	L) 0 3333333333	Τ				
	COMPONENT IGNITION SOURCES.	4	h	WF(LS) = a/b	F(f)	F(if)	
	BATTERIES	1	3	0 3333333333	0 0032	0.000355	
	ELECTRICAL CABINETS	14	31	0 4516129032	0 019	0 002860	
	PLANT WIDE IGNITION SOURCES	a	c	WF(LS) = a/c	F(f)	Fát)	
	TRANSFORMERS	1	26	0.0384615385	0 0079	0 000303	
	VENTILATION SYSTEMS	2	21	0.0952380952	0.0095	0.000904	
	BATTERY CHARGERS	1	4	0 25	0.004	0 001	
		COMPARTMENT FREQUE	NCY - I	F(1) = sum[F(if)]	=	0.005424	

#### ALTERNATE ZONES

ZONE

AX 2.	SELECTED PLANT LOCATION	SWGR (ROOM 16B)					
	LOCATION WEIGHTING FACTOR - 1	WF(L)	0 25			T	
	COMPONENT IGNITION SOURCES			b	WF(LS) = a/b	F(f)	1
	ELECTRICAL CABINETS		8	71	0 1126760563	0 015	0 000422
	PLANT WIDE IGNITION SOURCES		•	c	WF(LS) = a/c	F(f)	Fat
	VENTILATION SYSTEMS		1	21	0 0476190476	0 0095	0 000452
		COMPARTMENT FIRI	E FREQU	ENC	Y - F(1) = sum   F	(in)  =	0.000875

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 243 of 415

AX 22	SELECTED PLANT LOCATION	CONDENSATE	STORAGE TA	NK RO	ЮМ		
	LOCATION WEIGHTING FACTOR	VF(L)	1	T			
	COMPONENT IGNITION SOURCES		•	ь	WH(LS) = a/b	F(f)	F(if)
	ELECTRICAL CABINETS		17	72	0 236111111	0.019	0 004486
	PLANT WIDE IGNITION SOURCES			c	$\Psi F(LS) = a/c$	F(f)	F(if)
	TRANSIENTS		3	25	0.12	0 0013	0.000156
	ELEVATOR MOTOR		1	3	0 33333333333	0 0063	0.0021
	GRINDING CUTTING	, « ا م برد	1	2	05	0.031	0.0155
	· · · · · · · · · · · · · · · · · · ·	COMPARTMEN	IT FIRE FREQ	UENC	$Y \cdot F(l) = sum{F}$	(if)] =	0 022242

AX 23A	SELECTED PLANT LOCATION	MCC 62J ROOM, E	L 642'				
	LOCATION WEIGHTING FACTOR - W	/F(L)	1	Ţ			
	COMPONENT IGNITION SOURCES			ь	WF(LS) = a/b	F(f)	Füf)
	ELECTRICAL CABINETS		1	72	0.0138888889	0 019	0 000263
	PLANT WIDE IGNITION SOURCES			c	WF(LS) = a/c	F(f)	Füß
							·
		COMPARTMENT F	IRE FREQ	UENCY	$' \cdot F(l) = \operatorname{sum}(F)$	(if)] =	0 000263

AX 23A	SELECTED PLANT LOCATION	AUXILIARY BLDG	GAS BO	TTLE S	TORAGE AREA,	EL 657')	
	LOCATION WEIGHTING FACTOR - WF	L)	1	T			
	COMPONENT IGNITION SOURCES		1.	Ь	WF(LS) = a/b	F(f)	F(if)
	ELECTRICAL CABINETS		2	72	0.0277777778	0 019	0 000527
	PLANT WIDE IGNITION SOURCES			c	WF(LS) = a/c	F(f)F(f)	F(if)
	VENTILATION SYSTEMS		2	21	0.0952380952	0 0095	0 000904
	BOTTLED GAS		1	2	0.5	0 0032	0 0016
		COMPARTMENT FIR	E FREQ	UENC	$Y - F(1) = sum \{F$	(if)] =	0.003032

AX 23C	SELECTED PLANT LOCATION	RHR PUMP B PIT					
	LOCATION WEIGHTING FACTOR	VF(L)	1	T		1	T
	COMPONENT IGNITION SOURCES		8	b	WF(LS) = a/b	F(f)	F(if)
	RHR PUMP		1	16	0 0625	0.019	0 001187
	PLANT WIDE IGNITION SOURCES	<u>,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	•	c	WF(LS) = a/c	F(f)	F(if)
	VENTILATION SYSTEMS		1	21	0 0476190476	0 0095	0 000452
		COMPARTMENT F	REQUE	NCY	F(1) = sum[F(if)]		0 00163

AX 23D	SFLECTED PLANT LOCATION	CCW PUMP B ROOM					
	LOCATION WEIGHTING FACTOR WE	(L)	1		1	[	T
	COMPONENT IGNITION SOURCES			h	WF(LS) = a/b	F(1)	Fub
	CCW PUMP		1	16	0.0625	0 019	0 001187
	PEANT WIDE IGNITION SOURCES		R	с с	$WF(LS) = \pi/c$	Fiñ	F(if)
	VENTILATION SYSTEMS		1	21	0 0476190476	0 0095	0 000452
		COMPARTMENT FIRE	EREQ	UENCY	Fdi sun F	(f)] =	0 001639

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 244 of 415

AX 30	SELECTED PLANT LOCATION	CABLE SPREADIN	G ROOM	RELA	( ROOM)		
	LUCATION WEIGHTING FACTOR WE	Ĺ)	1	T	1	T	1
	COMPONENT IGNITION SOURCES	······································		b	WF(LS) = a/b	F(f)	F(if)
	FLECTRICAL CABINETS		69	69	1	0 0032	0.0032
			-	1			1
	PLANT WIDE IGNITION SOURCES	······································	•	c	WF(LS) = ec	Fit	F(if)
					-	-	
		COMPARTMEN	FREQUE	NCY -	$F(l) \approx sum(F(it))$		0 00

AX 32	SELECTED PLANT LOCATION	AUXILIARY	BLDG (SERVICI	E ROON	4S)		
	LOCATION WEIGHTING FACTOR - V	NF(L)	1			T	
	COMPONENT IGNITION SOURCES	<u></u>		b	WF(LS) = a/b	F(f)	F(if)
	DRYER (FOR HP CLOTHING)		3	3	1	0.0087	0 0087
	PLANT WIDE IGNITION SOURCES			c	WF(LS) = a/c	F(f)	F(if)
	TRANSIENTS		3	23	0 12	0.0013	0.000156
		COMPARTME	NT FIRE FREQ	UENCI	(·F(1) = sum[F	(if)] =	0.008856

AX 15	SELECTED PLANT LOCATION	AUXILIARY BLD	O (SERVIC	e roof	AS)		
	LOCATION WEIGHTING FACTOR - W	F(L)	1				
	COMPONENT IGNITION SOURCES	<u></u>	4	b	WF(LS) = a/b	F(f)	F(if)
	ELECTRICAL CABINETS		15	15	1	0 0095	0 0095
	PLANT WIDE IGNITION SOURCES		•	c	WF(1.S) = o/c	F(f)	F(if)
	TRANSIENTS		1	25	0.04	0 0013	0 000052
		COMPARTMENT FI	RE FREQU	ENCY	F(1) = sum[F(i	î)] =	0 00955

SELECTED PLANT LOCATION	AUXILIARY BLDO	(SERVIC)	E ROOM	4S)		
OCATION WEIGHTING FACTOR - WF(	L)	1		T		
OMPONENT IGNITION SOURCES			b	WF(LS) = a/b	F(f)	F(if)
ELECTRICAL CABINETS		15	15	1	0 0095	0 0095
PLANT WIDE IGNITION SOURCES		- <del> </del> -	c	WF(LS) = a/c	F(f)	F(if)
TRANSIENTS		1	25	0.04	0 0013	0 000052
VENTILATION STSTEMS		2	21	0 0952380952	0 0795	0.000904
	OCATION WEIGHTING FACTOR - WF OMPONENT IGNITION SOURCES ELECTRICAL CADINETS LANT WIDE IGNITION SOURCES TRANSIENTS	OCATION WEIGHTING FACTOR - WF(L) COMPONENT IGNITION SOURCES ELECTRICAL CAGINETS CLANT WIDE IGNITION SOURCES TRANSIENTS	.OCATION WEIGHTING FACTOR - WF(L)       1         TOMPONENT IGNITION SOURCES       4         ELECTRICAL CALINETS       15         CLANT WIDE IGNITION SOURCES       4         TRANSIENTS       1	.OCATION WEIGHTING FACTOR · WF(L)       1         .OMPONENT IGNITION SOURCES       a         ELECTRICAL CAGINETS       15	OCATION WEIGHTING FACTOR · WF(L)       1         OMPONENT IGNITION SOURCES       a       b       WF(LS) = a/b         ELECTRICAL CADINETS       15       15       1         VLANT WIDE IGNITION SOURCES       a       c       WF(LS) = a/c         TRANSIENTS       1       25       0.04	OCATION WEIGHTING FACTOR · WF(L)       1       1         OMPONENT IGNITION SOURCES       •       b       WF(LS) = a/b       F(f)         ELECTRICAL CACINETS       15       15       1       0 0095         LANT WIDE IGNITION SOURCES       •       c       WF(LS) = a/c       F(f)         TRANSIENTS       1       25       0.04       0 0013

AX 37	SELECTED PLANT LOCATION	SWGR ROOM					
	LOCATION WEIGHTING FACTOR	WF(L)	0 25		T		
	COMPONENT IGNITION SOURCES			h	WF(LS) = a/b	Fin	F(if)
	SWOR, C. D.		8	75	0 1066666667	0 015	0 00040
	PLANT WIDE IGNITION GOURCES			c	WF(LS) = a/c	F(f)	F(if)
	RPS MG SETS		2	2	1	0 0055	0 0055
		COMPARTMENT	FIRE FREQ	IT FNC	$(\mathbf{Y} \cdot \mathbf{F}(\mathbf{i}) = \mathbf{sum}$	F.(f)] =	0 0059

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 245 of 415

SC 70B	SELECTED PLANT LOCATION	INTAKE STRUCTURE					
	LOCATION WEIGHTING FACTOR	WF(L)	1	T			
	COMPONENT IGNITION SOURCES			b	WF(LS) = a/b	F(f)	F(if)
	ELECTRICAL CABINETS		2	6	0 3333333333	0.0024	0.0008
	FIRE PUMPS		1	2	0.5	0.004	0.002
	SERVICE WATER PUMPS		2	4	0.5	0.0032	0.0016
	PLANT WIDE IGNITION SOUPCES			c	WF(LS) = a/c	F(f)	F(if)
	VENTILATION SYSTEMS		1	21	0.0476190476	0.0095	0.000452
	FIRE PROTECTION CABINETS		1	2	0.5	0 0024	0.0012
		COMPARTMENT FIRE	FREQ	UENCI	( - F(1) = sum   F	(if)] =	0.006052

TU 22	SELECTED PLANT LOCATION	TURBINE BLDG					
	LOCATION WEIGHTING FACTOR WE	L)	i	Τ	1	T	
	COMPONENT IGNITION SOURCES		1.	b	WF(LS) = a/b	F(f)	F(if)
	ELECTRICAL CABINETS		26	26	1	0.013	0.013
	T/G EXCITOR		1	1	1	0.004	0.004
	T/G HYDROGEN		4	4	1	0 0055	0 0055
	T/G OIL		5	5	1	0 013	0.013
	MAIN FEED PUMPS		2	2	1	0.004	0 004
	OTHER PUMPS		4	4	1	0 0063	0 0063
	PLANT WIDE IGNITION SOURCES	· · · · · · · · · · · · · · · · · · ·	•	c	WF(LS) = a/c	F(f)	F(if)
	TRANSIENTS		10	25	04	0 0013	0 00052
	TRANSFORMERS	<u> </u>	5	21	0 2380952381	0 0079	0.001880
	VENTILATION SYSTEMS	· · · ·	2	21	0 0952380952	0.0095	0.000904
	AIR COMPRESSORS		3	6	0.5	0 0047	0 00235
		COMPARTMENT FIR	E FREQ	UENCI	$f \cdot \mathbf{F}(\mathbf{I}) = \operatorname{sum}[\mathbf{F}(\mathbf{I})]$	(if)] =	0.051455

TU 92	SELECTED PLANT LOCATION	DIESEL ROOM B	DIESEL ROOM B					
	LOCATION WEIGHTING FACTOR WF(L)					I		
	COMPONENT IGNITION SOURCES		•	ь	WF(LS) = a/b	F(f)	F(if)	
	BUS 6, MCC 62A		14	31	0.4516129032	0.0024	0.001084	
	DIESEL GENERATOR		1	3	0 3333333333	0.026	0.008666	
	PLANT WIDE IGNITION SOURCES		•	c	$WF(LS) \simeq a/c$	F(f)	F(if)	
	TRANSIENTS		1	25	0.04	0.0013	0.000052	
	VENTILATION SYSTEMS		1	21	0 0476190476	0.0095	0 000452	
		COMPARTMENT FIR	E FREQ	. <u> </u>			0.010	

TU 94	SELECTED PLANT LOCATION	LECTED PLANT LOCATION CO <sub>2</sub> STORAGE TANK ROOM		ROOM 4B				
	LOCATION WEIGHTING FACTOR WE	1.)	1	T	T	T		
	COMPONENT IGNITION SOURCES		h	WF(LS) = e/b	F(f)	Fift		
					<b> </b>	- <b> </b>		
	PLANT WIDE IGNITION SOURCES		c	WF(LS) = a/c	F(f)	Fiif)		
	VENTILATION SYSTEMS	1	21	0 0476190476	0 0095	0 000452		
	AIR COMPRESSOR A	1	6	0 1666666667	0 0047	0 000783		
		COMPARTMENT FIRE FREQ	UENC	Y F(l) = sum[F	uf)  =	0.001_35		

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 246 of 415

TU-95B	SELECTED PLANT LOCATION	AFW PUMP B ROOM					
	LOCATION WEIGHTING FACTOR - WF	(L)	1	T			
	COMPONENT IGNITION SOURCES			b	WF(LS) = a/b	F(f)	F(if)
	AFW PUMP B		1	8	0 125	0.0063	0.000781
	PLANT WIDE IGNITION SOURCES			c	WF(LS) = a/c	F(f)	F(if)
	VENTIL ATION SYSTEMS		1	21	0 0476190476	0.0095	0.000452
		COMPARTMENT FIRE	FREQ	UENCY	-F(l) = sum(F)	(if)] =	0.00124

TU 95B	SELECTED PLANT LOCATION	SWGR ROOM (B	USES 61 & 62	)			
	LOCATION WEIGHTING FACTOR - W	'F(L)	0.25		1	1	
	COMPONENT IGNITION SOURCES		4	b	$WF(LS) \approx a/b$	F(f)	F(if)
	ELECTRICAL CABINETS		9	71	0.1267605634	0.015	0.000475
	PLANT WIDE IGNITION SOURCES		•	c	WF(LS) = a/c	F(f)	F(if)
	AIR COMPRESSOR B	····· ··· ··· ··· ··· ··· ··· ··· ···	í	6	0 1666666667	0.0047	0.000783
	INSTR AIR DRYERS		2	2	1	0.0087	0.0087
		COMPARTMENT	FIRE FREQU	ENC	$\mathbf{Y} \cdot \mathbf{F}(\mathbf{I}) = \mathbf{sum} \mathbf{F}$	(if)) =	0.009958

TU 98	SELECTED PLANT LOCATION	BATTERY ROOM (RM 130)				
	LOCATION WEIGHTING FACTOR - WF(I	L) 0 33333333333		1	[	
	COMPONENT IGNITION SOURCES		b	WF(LS) = a/b	F(f)	F(if)
	BATTERIES	1	3	0 3333333333	0 0032	0.000355
	ELECTRICAL CABINETS	14	31	0.4516129032	0 019	0 002860
	PLANT WIDE IGNITION SOURCES	4	c	WF(LS) = a/c	F(f)	F(if)
	TRANSFORMERS	1	26	0 0384615385	0 0079	0.000303
	VENTILATION SYSTEMS	2	21	0.0952380952	0 0095	0.000904
	BATTERY CHARGER	1	4	0.25	0.004	0 001
[		COMPARTMENT FIRE FREQU	ENCY	-F(1) = sum[F]	(if)] =	0 005424

-

Alternate Zone	Fire-induced Core Damage Frequency (/yr)	Dedicated Zone	Fire-induced Core Damage Frequency (/yr)
AX-21	7.001E-5	AX-23B	1.094E-3
AX-22	2.719E-6	SC-70A	7.650E-6
AX-23A	1.038E-3	TU-90	5.501E-4
AX-23C	1.097E-6	TU-95A	2.187E-4
AX-23D	3.326E-6	TU-95C	5.725E-5
AX-30	3.920E 7	TJ-97	2.289E-4
AX-32	8.079E-4		
AX-35	2.450E-6		
AX-37	7.129E-7		
SC-70B	1.584E-6		
TU-22	6.716E-6		
TU-92	1.582E-3		
TU-94	1.470E-4		
TU-95B	1.193E-2		
TU-98	5.092E-4		

Table 4-2: Screening Results, Dedicated and Alternate Zones

NOTE: These core damage frequencies were calculated for screening purposes only, and do not realistically reflect the scenario.

Table 4-3: AREA OF INFLUENCE & ROOM AREA FOR EACH DAMAGE SCENARIO (Sheet 1 of 3)							
Fire Zone	Damage Scenario	Danage Time	Area of Influence	Room Area	(Infl.Area):(Room_Area)		
AX-21	Buses 1 and 2 Room	l min	$(0.9 \text{ m})^{\bullet}(13.75 \text{ m}) = 12.775 \text{ m}^2$	114.07 m <sup>2</sup>	0 108		
	MCC 35E/45E	no damage			· .		
	MCC 62J	2 <b>m</b> in.	entire contents of room damaged	· · · · · ·	1		
AX-23A	Bottled Gas, El: 657'	l min.	$(5.5 \text{ m})^*(0.5 \text{ m}) = 2.75 \text{ m}^2$	$(7.01 \text{ m})^*(13.1 \text{ m}) = 91.9 \text{ m}^2$	2 99E-02		
	SI Pump	no dame ge					
	Flammable Liq.Cab	no damage					
AX-23B	Bottled Gas, EL 5861	no damage					
AX-23D	CCW Pump B Room	14 min.	entire contents of room destroyed		1		
AX 30	Fire Near Vertical Trays	2 min.	$(1/2)(\pi)(1.5 \text{ m})^2 = 3.53 \text{ m}^2$	$(16.2 \text{ m}) * (16.8 \text{ m}) = 270.8 \text{ m}^2$	1-31E-02		
	Fire Near Cabinets	no <b>damag</b> e			•••		
	MCC 62B	no damage					
AX-32	MCC 62B Ext	no dama <sub>b</sub> e					
	Cable Spreading Area	not modeled					
AX-35	Control Room	not modeled					
SC-70A	Screenhouse	no damage					

4-61

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 249 of 415

	Table 4-3: AREA OF INFLUENCE & ROOM AREA FOR EACH DAMAGE SCENARIO (Sheet 2 of 3)								
Fire Zone	Damage Scenario	Damage Time	Area of Influence	Room Area	(Infl. Area)/(Room Area)				
TU-90	Bus S	no damage							
	MCC 52A	no damage							
	Diesel Fire	3 min							
TU-92	MCC 62A	3 min.							
	Bus 6	no damage							
	Diesel Fire	3 min.							
TU-94	Air Comp. A Fire	no damage	•••						
	Beneath Cable Trays	no damage							
TU-95A	Switchgear Room 5B	2 min.	$(0.2 \text{ m})(13 \text{ m}) = 2.6 \text{ m}^2$	98.65 m <sup>2</sup>	2.64E-02				

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 250 of 415

	Table 4-3: AREA OF INFLUENCE & ROOM AREA FOR EACH DAMAGE SCENARIO (Sheet 3 of 3)								
Fire Zone	Damage Scenario	Damage Time	Area of Influence	Room Area	(Infl. Area)/(Room Area)				
TT-95B	Cable Trays Above Bus 61	no damage							
	Cable Trays North of Bus 62	10 Cath 5 .							
	Cable Trays in AFW B Room	3 .nm.	entire contents of room damaged						
	Turbine-Driven AFW Pump Room	not modeled (steam exclusion ceiling protects cables)	 						
TU-95C	AFW Pump A Room	l min	entire contents of room damaged		l				
TU-97	Battery Room A	ne damage							
T11-98	Battery Room B	no dama <sub>i</sub> ;e							

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 251 of 415

	Table 4-4: FAULT TREE IDENTIFIERS OF DAMAGED CABLES/COMPONENTS								
Scenario, Fire Zone	Damaged Cable Tray or Component	Contents of Cable Tray	Corresponding Fault Tree Identifier	Fault Trees in which Identifier Appears					
FII: AX-23A, MCC 62J scenario	<ol> <li>Cable tray 1FT686</li> <li>Cable tray 1FX486</li> </ol>	a) valve BT 2B b) valve MS 10013 Affected cables coi trol components which are not modeled in PRA.	07-MVBT2B-OO 06-MV-MS100B-OC	AF3 AF3					
1 1. AX-23A, MCC 62J scentilio	Composents	МСС 62Ј	40-38-MCC62J-SG	AF3					
FI2: TU-92, DG B room, MCC 62A scenario	Cable tray 1DT4S6 Breaker 610 to MAT not modeled	<ul> <li>a) AFW pump B</li> <li>b) Air compressor E</li> <li>c) Breaker 611</li> <li>d) DG 1B</li> <li>e) MCC 62A</li> <li>f) RHR pump B - <ul> <li>injection</li> <li>g) S1 pump B -</li> <li>injection</li> </ul> </li> </ul>	05BPMAFW1B-PS 01-PM-SIAC1B-PS 39-CB-1-611FC 10-GE-DG1BPS 40-BS-MCC62A-SG 341PMRHR1B-PS 331PMSI1B-PS	AF3 IAS, IAST, IASTA, IASTB BUS6 DGB IAS, IAST, IASTA, IASTB RHRB HPI, HR1					
F12: TU-92, DG B room, MCC 62A scenario	Cable tray 1DT4S6	<ul> <li>h) SW pump B1</li> <li>i) SW pump B2</li> <li>j) SW strainer B1</li> <li>k) TAT</li> <li>q) SW valve B</li> <li>r) AFW pump B</li> <li>s) Air compressor B</li> <li>t) Breaker 607</li> </ul>	02-PM-SW1B1PR 02-PM-SW1B2PR 02-FL-1B1PL 39-TR-TATSG 02-MV'-SW10BOC 05BPM -AFW1B-PS 01-PM-SIAC1B-PS 39-CB1-607-CO	SWB, SWT SWB, SWT SWB, SWT, BUS5, BUS6 SWB, AF3 IAS, IASP, IASF., IAST, IASTA, IASTB BRB104T, BUS61, BUS62, IASTB					
F12: TU-9?, DG B room, MCC 62A scenario	Components	a) MCC 62A	40-BS-MCC 62A-SG	IAS, IAST, IASTA, IASTB					

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 252 of 415

	Table 4-4: FAULT 1	REE IDENTIFIERS OF	DAMAGED CABLES/CO	MPONENTS
Scenario, Fire Zone	Damaged Cable Tray or Component	Contents of Cable Tray	Corresponding Fault Tree Identifier	Fault Trees in which Identifier Appears
FI3 AX 21, Room 16B, Fire between buses 1 and 2	Cable tray 1AT9N	a) MFW pump A b) MFW pump B	05APMFWP1A-PR 05APMFWP1B-PR	ОМ2 ОМ2
FI4: TU-92, DG B dieset fire	Cable tray 1D18N Breaker 301 not modeled	в) RAT	39-TR-RATSG	BUS1, BUS2, BUS3, BUS4, BUS5 BUS6
FI4. TU-92, DG B dieset fire	Components	a) DG B	10-GF-DG1BPS	DGB
F15: AX-30, Relay room Fire near vertical trays, cable trays 1AT12S6, 1AT13S6 and 1RT62S6 damaged	Damage disables all potential source breakers for bus 6. Components dependent on bus 6 (directly or indirectly) are also disabled (starred components). Valve CC400B not modeled AFW pump 1B lut 1 pump not modeled	a) TAT b) Valve BT3A c) Valve FW10A d) Valve FW7A e) Valve SI208 f) Valve CC400B	39-TR-TATSG 07-MVBT3A-OO 05A-AV-FW10A-CC 05A-AV-FW7ACC 33RMV-S1208FC 34RMV-CC400B-CC	BUS5, BUS6 AF3 OM2 OM2 RHPA, RHRB RHRB
Fl6: Fire in TU-95C, AFW pump A room (multiple cable trays affected)	Cable tray 1TT106S5 AFW pump A aux lube oil pump not modeled	a) Valve AFW10A	05BMV-AFW10A-OC	AF3

LIC\PRA\IPEEE-4.WP

4-65

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 253 of 415

Table 4-4: FAULT TREE IDENTIFIERS OF DAMAGED CABLES/COMPONENTS								
Scenario, Fire Zone	Damaged Cable Tray or Component	Contents of Cable Tray	Corresponding Fault Tree Identifier	Fault Trees in which Identifier Appears				
FI6: Fire in TU-95C. AFW pump A rowin Starred components already disabled	Cable tray 1TT15N Breakers 301, 305, 307, 308, 309, and 407 are not modeled	<ul> <li>a) Breaker 13201</li> <li>b) Breaker 13242</li> <li>c) Breaker 14201</li> <li>d) Breaker 303</li> <li>e) CDP A*</li> <li>f) RAT</li> </ul>	40-CB13201-CO 40-CB13242-FC 40-CB14201-CO 39-CB1-303-CO 03-PMCDP1A-PR 39-TR-RATSG	BUS32 BUS32, BUS42 BUS42, BUS42T BUS32 OM2 BUS1, BUS2, BUS3, BUS4, BUS5, BUS6				
Fl5: Fire in TU-95C, AFW pump A room	Cable tray 1TT4N Breaker 511 is not modeled	a) CDP A* b) TAT	03-PMCDP1A-PR 39-TR-TATSG	OM2 BUS5, BUS6				
Fl6: Fire in TU-95C, AFW pump A room	6: Fire in TU-95C, 4) Cable tray 1TT4S5		01-PM-SIAC1A-PR 35-PM-CHGP1C-PR 05APMFWP1A-PR 05APMFWP1B-PR	IAS, IAST, IASTA, IASTB CHG OM2 OM2				
Fl6: Fire in TU-95C, AFW pump A room	5) Cable tray 1TT8S5	a) SI pump A c) AFW pump C lube oil pump d) TAT e) Valve SW502 f) Breaker 501 g) Breaker 503 h) Breaker 505	331PMSi1A-PS 05BPM-ALOP1C-PS 39-TR-TATSG 02-MV-SW502CC 39-CB-1-501CO 39-CB-1-503FC 30-CB-1-505FO	HPI, HR1, AF3 BUS5, BUS6 AF3 BUS5 BUS5 BRA104T, BUS51, BUS52, IASTA				

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 254 of 415

	Table 4-4: FAULT TREE IDENTIFIERS OF DAMAGED CABLES/COMPONENTS								
Scenario, Fire Zone	Damaged Cable Tray or Component	Contents of Cable Tray	Corresponding Fault Tree Identifier	Fault Trees in which Identifier Appears					
H6. Fire in TU 95C AFW pump A room	Components	a) AFW pump A	05BPMAFW1A-PS	AF3					
FI7 <sup>1</sup> Fire in AFW Pump B Room, TU-95B	Components	a) AFW pump B b) TBB FCU B	05BPMAFW1B-PS 17-FN-TBB1BPS	AF3 IAS, IAST, IASTA, IASTB					
HI7: Fire in AFW Pump B Room, TU-95B	Cable tray 1TT10N Breaker 610 to MAT not modeled Note that a fire in this area disables buses 1, 2, 3, 4 and 6. All components which are supplied by buses 1, 2, 3, 4, and 6 are starred.	a) CCW Pump B FCU* b) Breaker 611* c) Breaker 601* d) Valve SV 33778*	17-FN-CCWP1B-PS 39-CB-1-611FC 39-CB-1-601CO 17-SVSV33778-CC	CCW BUS6 BUS6 CCW					
F17: Fire in AFW Pump B Room, TU-95B	Cable tray 1TT15N Breakers 301, 305, 307, 308, 309, and 407 are not modeled Note that a fire in this area disables buses 1, 2, 3, 4 and 6. All components which are supplied by buses 1, 2, 3, 4 and 6 are starred.	<ul> <li>a) Breaker 13201*</li> <li>b) Breaker 13242*</li> <li>c) Breaker 14201*</li> <li>d) Breaker 303*</li> <li>e) CDP A*</li> <li>f) RAT</li> </ul>	40-CB13201-CO 40-CB13242-FC 40-CB14201-CO 39-CB1-303-CO 03-PMCDP1A-PR 39-TR-RATSG	BUS32 BUS32, BUS42 BUS42, BUS42T BUS32 OM2 BUS1, BUS2, BUS3, BUS4, BUS5, BUS6					

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 255 of 415

Table 4-4: FAULT TREE IDENTIFIERS OF DAMAGED CABLES/COMPONENTS								
Scenario, Fire Zone	Damaged Cable Tray or Component	Contents of Cable Tray	Corresponding Fault Tree Identifier	Fault Trees in which Identifier Appears				
F17 Fire in AFW Pump B Room. TU 95B	Cable Liay 17120N Breakers 401 and 402 are not modeled Bus BRD 103 not modeled Note that a fire in this area disables buses 1, 2, 3, 4 and 6. All components which are supplied by buses 1, 2, 3, 4, and 6 are starred.	a) Breaker 13501* b) Breaker 13545* c) Breaker 14501* d) Breaker 407* e) Breaker 405* f) Breaker 406* g) Distribution bus BRA-127 h) Distribution bus BRB-127 i) Condensate pump B* j) FW pump A* k) FW pump B*	40-CB13501-CO 40-CB13545-FC 40-CB14501-CO 39-CB-1-407FC 39-CB1-405-CO 39-CB1-406-CO 381BS-BRA127-SG 381BS-BRB127-SG 03-PMCDP1B-PR 05APMFWP1A-PR 05APMFWP1B-PR	BUS35 BUS35, BI S45 BUS45, BUS45T BUS45, BUS45T BUS42, BUS42T BRA127 BRB127, BRD115 OM2 OM2 OM2				
FI7. Fire in AFW Pump B Room, TU-95B	Cable Tray 1TT4N Note that a fire in this area disables buses 1, 2, 3, 4 and 6. All components which are supplied by buses 1, 2, 3, 4, and 6 are starred.	a) CDP A* b) TAT	03-PMCDPIA-PR 39-TR-TATSG	OM2 BUS5, BUS6				

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 256 of 415

	Table 4-4: FAULT 1	KEE IDENTIFIERS OF	DAMAGED CABLES/CU	IMPUNENTS
Scenario, Fite Zonc	Damaged Cable Tray or Component	Contents of Cable Tray	Corresponding Fauit Tree Identifier	Fault Trees in which Identifier Appears
<ul> <li>F17 Fire in AFW</li> <li>Puin: B Room,</li> <li>FU-98B</li> <li>Note that a fire in this area disables buses 1.</li> <li>2. 3, 4 and 6. A.,</li> <li>components which are supplied by buses 1.</li> <li>3, 4, and 6 are starred.</li> </ul>	Cable tray 1 FF485 Control room control of AFW pump A - not modeled in PRA Control room control of FCU A and B, and DGA - not modeled in PRA Control room control or SW pumps A1 and A2, train A ESF Signals, valves SI2A, SI3, SI302, SW1300A, SW903A, and SW903B - not modeled in PRA	a) Air compressor A b) Charging pump C* c) MFW pump A* d) MFW pump B*	01-PM-SIAC1A-PR 35-PM-CHGP1C-PR 05APMFWP1A-PR 05APMFWP1B-PR	IAS. IAST, IASTA, IASTB CHG OM2 OM2
F17: Fire in AFW Pump B Room, TU-95B	Cable tray 1TT855 Note that a fire in this area disables buses 1, 2, 3, 4 and 6. All components which are supplied by buses 1, 2, 3, 4, and 6 are starred.	a) SI pump B* b) AFW pump C lube oil pump c) TAT d) Valve SW502	331PMS11B-PS 33RPMS111B-PS 05BPM-ALOP1C-PS 39-TR-TATSG 02-MV-SW502CC	HPI, HRI HRI AF3 BUS5, BUS6 AF3

### Table 4-4: FAULT TREE IDENTIFIERS OF DAMAGED CABLES/COMPONENTS

	Table 4-4: FAULT TREE IDENTIFIERS OF DAMAGED CABLES/COMPONENTS							
Scenario, Lire Zone	Damaged Cable Tray or Component	Contents of Cable Tray	Corresponding Fault Tree Identifier	Fault Trees in which Identifier Appears				
F17: Fire in AFW Pump B Room, TU-95B	Cable tray 11T4S6 AFW Pump B aux lube oil pump not modeled Note that a fire in this area disables buses 1, 2, 3, 4 and 6. All components which are supplied by buses 1, 2, 3, 4, and 6 are starred.	<ul> <li>a) AFW pump B*</li> <li>b) Air compressor B*</li> <li>c) DG B*</li> <li>d) FW pump A*</li> <li>e) FW pump B*</li> <li>f) Valve AFW 10B</li> <li>g) Valve SW10B*</li> <li>j) Valve SW601B*</li> </ul>	05BPMAFW1B-PS 01-PM-SIAC1B-PS 10-GE-DG1BPS 05APMFWP1A-PR 05APMFWP1B-PR 05BMV-AFW10B-OC 02-MV-SW10BOC 02-MV-SW601B-CC	AF3 IAS, IAST, IASTA, IASTB DGB OM2 OM2 AF3 SWB AF3				
HI7: Fire in AFW Pump B Room. TU-95B	Cable tray 1TT8S6 AFW Pump B aux lube oil pump not modeled Valve SW903C not modeled Damage disables all potential source breakers for bus 6. Note that a fire in this area also disables buses 1, 2, 3, and 4. All components which are supplied by buses 1, 2, 3, 4, and 6 are starred.	<ul> <li>a) AFW pump B*</li> <li>b) Breaker 16201*</li> <li>c) Breaker 601*</li> <li>d) Breaker 601*</li> <li>d) Breaker 607*</li> <li>f) CW pump B*</li> <li>g) DG B*</li> <li>h) RHR pump B -</li> <li>mjection*</li> <li>i) RHR pump B -</li> <li>recirc.*</li> <li>j) Pump pit B FCU*</li> <li>k) SI pump B*</li> <li>l) SW pump B1*</li> <li>m) SW pump B2*</li> <li>n) TAT</li> <li>o) Valve BT2B*</li> <li>p) Valve BT3A</li> <li>q) Valve SW10B*</li> </ul>	05BPMAFW1B-PS 40-CB16201-CO 39-CB-1-601CO 39-CB-1-611FC 39-CB-1-607-CO 31-PM-CCW1BPS 10-GE-DG1BPS 34IPMRHR1B-PS 34RPMRHR1B-PS 34RFNPMPPITB-PS 33IPMS11B-PS 33IPMS11B-PS 33RPMS11B-PS 02-PM-SW1B1PR 02-PM-SW1B1PR 02-PM-SW1B2PR 39-TR-TATSG 07-MVBT2B-OO 07-MVBT3A-OO 02-MV-SW10BOC	AF3 BRB104T, BUS62, 1ASTB BUS6 BUS6 BRB104T, BUS61, BUS62, IASTB, CCW DGB LPI, RHRB LR1, RHRB RHRB HPI, HR1 HR1 SWB,SWT SWB, SWT BUS5, BUS6 AF3 AF3 SWB				

4-70

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 257 of 415

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 258 of 415

Table 4-4: FAULT TREE IDENTIFIERS OF DAMAGED CABLES/COMPONENTS								
Scenario, Fire Zone	Damaged Cable Tray or Component	Contents of Cable Tray	Corresponding Fault Tree Identifier	Fault Trees in which Identifier Appears				
F18 Fire near buses 51 and 52 in T1 95A	Cable (ray 1TT555 Note that domage to this cable tray disables all potential source breakers for bus 5. All affected components are starred.	<ul> <li>a) AFW Pump A*</li> <li>b) IA Compressor C*</li> <li>c) Breaker 15101*</li> <li>d) Breaker 15201*</li> <li>e) Breaker 15203*</li> <li>f) Breaker 501*</li> <li>g) Breaker 503*</li> <li>h) Breaker 505*</li> <li>i) Bus 51*</li> <li>j) Bus 52*</li> <li>k) Chg pump A*</li> <li>l) CCW pump A*</li> <li>m) DG A*</li> <li>n) TAT</li> <li>n) MCC 5262</li> </ul>	05BPMAFW1A- <sup>p</sup> S 01-PM-SIAC1C-PS 40-CB15101-CO 40-CB15201-CO 40-CB-15203-CO 39-CB-1-501CO 39-CB-1-503FC 39-CB-1-503CO 39-CB-1-505FO 40-BS-BUS51SG 40-BS-BUS52SG 35-PM-CHGP1A-PR 31-PM-CCW1APR 10-GE-DG1APS 39-TR-TATSG 40-BS-MCC5262SG	AF3 IAS, IAST, IASTA, IASTB BUS51 BRA104T, BUS52, IASTA CHG BUS5 BUS5 BRA104T, BUS51, BUS52, IASTA, BUS51 BRA104T, BUS52, IASTA CHG CCW DGA BUS5, BUS6 IAS, IAST, IASTA, IASTB				
F18: Fire near buses 51 and 52 in TU-95A	Cable tray 1TT5S5 Note that damage to this cable tray disables all potential source breakers for bus 5. All affected components are starred.	<ul> <li>o) RHR pump A*</li> <li>p)RHR pump pit A</li> <li>Fan*</li> <li>q) SI pump A*</li> <li>r) SW pump A1*</li> <li>s) SW pump A2*</li> <li>t) Valve BT2A</li> <li>u) Valve BT3B*</li> <li>v) Valve SWI0A*</li> </ul>	341PMRHR1A-PS 34RPMRHR1A-PS 34RFNPMPPITA-PS 331PMS11A-PS 33RPMS11A-1 02-PM-SW1A1PS 02-PM-SW1A2PR 07-MVBT2A-OO 07-MVBT3B-OO 02-MV-SW10AOC	RHRA RHRA RHRA HPI, HR1 HR1 SWA SWT SWA, SWT AF3 AF3 SWA				

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 259 of 415

Table 4-5: FIRE SEQUENCES AND THEIR CORE DAMAGE FREQUENCIES							
Sequence Fire Zone		Scenario Description	Core Damage Frequency				
FII	AX-23A	MCC 62J scenario	2.81E-9/yr				
F12	TU-92	MCC 624 scenario	4.65E-6/yr				
F13	AX-21	Fire between buses 1 and 2, beneath cable tray 1AT9N	1.41E-9/yr				
FI4	TU-92	Diesel B oil fire	7.44E-6/yr				
F15	AX-30	Fire in relay room	3.21E-7/yr				
F16	TU-95C	AFW pump A oil fire	5.27E-5/yr				
F17	TU-95B	AFW pump B oil fire	2 97E-5/yr				
F18	ГU-95А	Fire near buses 51 and 52	3.33E-6/yr				
Total Fire-induced	9.80E-5/yr						

CET END STATE	FRFQUENCY	RELEASE CATEGORY
НАААА	9.68E-06	S
HAAFA	1.29E-06	S
Наћаа	1.18E-06	S
HAFFA	2.90E-07	S
НЕААА	1.67E-09	S
HFFAA	1.85E-05	S
HFFFA	4.57E-05	A
ΙΔΑΑΑ	7.66E-07	S
LAAFA	4.23E-08	S
LAFAA	2.91E-07	S
LAFFA	L.70E-08	S
LFAAA	3.65E-10	S
LFFAA	1.76E-06	A
LFFFA	5.09E-08	А
Чалағ	1.49E-06	G
HAAFF	2.20E-07	G
HAFAF	1.86E-07	G
HAFFF	2 48E-08	G
HFFAF	2.82E-06	G
HFFFF	3.15E-05	G
LAAAF	4 86E-08	G
LAAFF	6.41E-09	G
1 AFAF	1 73E-08	G
I AFFF	1-71E-09	G
LIFAF	1.05E-07	G
1 +++1-	1.40E-08	G

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 260 of 415 Table 4-6: CET END STATES AND FREQUENCIES

Notes

1 Ind States are given the following identifier:

PLHC Where

- Р H for high pressure (>400 Psia) reactor vessel failure. I for low pressure vessel failure.
  - A if low pressure recirculation is available, F if it has failed
- I A 'f containment spray is available. F if it has failed
- ŀ A if containment fan coil units are available, F if they have failed
- C A if containment is isolated, F if isolation has failed
- Retease catagories are defined in Fable 4-7 2

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 261 of 415 Table 4-7: AIRBORNE RELEASE CATEGORIES AND FREQUENCIES

Release Category	Definition	Frequency	Conditional Probability <sup>1,2</sup>
S	No containment failure (leakage only, successful maintenance of containment integrity; containment not hypassed; isolation successful)	3.21E-05	0.28
G	Containment failure prior to vessel failure with noble gases and up to 10% of the volatiles released (containment isolation impaired)	3.64E-05	0.31
Α	No containment failure within 48 hr mission time, but failure could eventually occur without accident management action; noble gases and less than 0.01% volatiles released	4.75E-05	0.41

#### NOTES:

- 1 = Conditional probability of release category given core damage.
- 2 Core damage frequency for Level 2 < 1.16E-04/yr. This is larger than the Level 1 core damage frequency because success probabilities are not considered.

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 262 of 415

TABLE 4-7 FIT

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: Z

2.13E 2 13 SE-DG1A-- +5

Title: F11: MCC 62J Scenario File: F1RE1.WLK ( File created by linking F1RE1.IN WLINK \*\* Ver. 3.11 \*\*) Reduced Sum of Cutsets: 2.8140E-09

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
			DIESEL GENERATOR	1B	FAILURE TO STAR	T AND RUN	2.13E-02	10-GE-DG1P -PS
10	2.80E-11	1.00	FIRE NEAR MCC	621 CLCURS			2.63E-04	IEV-FI1
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			DIESEL GENERATOR	1 🖌	FAILURE TO START	AND RUN	2.13E-02	10-GE-DG1APS
			FEEDER BREAKERS	ON 4160V BUS 6	FAIL TO OPEN		4.20E-02	39-CB-BUS6FB-FO
11	2.74E 11	.97	FIRE NEAR MCC	621 OCCURS			2.63E-04	IEV-FI1
			EQUIPMENT FAILS	DUE TO FIRE			1.00F+00	FIRE-DAMAGE
			SOV AFW-111A	FAILS TO OPEN			2.00E · 03	058SVAFW111A-CC
			AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PHAFW18-PS
			TURBINE DRIVEN	AFW PUMP 10	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E · 02	36-RXCP-STOP-HE
12	2.74E 11	.97	FIRE NEAR MCC	621 OCCURS			2.63E-04	IEV-FI1
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICA	FAILURE		1.63E-02	058PMAFW1A-PS
			SOV AFW-111B	FAILS TO " EN			2.00E-03	058SVAFW1118-CC
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PT AFW1C-PS
			UPERATOR FAILS	TO STOP	REACTOR COOLANT	PURPS	2.33E-02	36-RXCP-STOP-HE
13	2.46E 11	.87	FIRE NEAR MCC	621 OCCURS			2.63E · 04	1EV-FI1
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+90	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PHAFW1A-PS
			AFW PUMP 1B	UNAVAILABLE	DUE TO TEST OR	MAINTENANCE	1 805-03	058PMAFW18-TM
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			OPEPATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
14	2.28E-11	.81	FIRE NEAR MCC	621 OCCURS			2.63E-04	IEV-FI1
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E 04	LOSP-24
			NO SERVICE WATER	DUE TO	COMMON CAUSE	FAILURES	7.30E-04	02SWSCM
15	1.04E-11	. <del>6</del> 5	FIRE NEAR MUC	621 OUCURS			2.63E-04	IEV-FI1
			FOUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			LOSS OF CONTROL	STUNAL TO MU-3A	VALVE FAILS OPEN		3.00E-06	03-AS-HTEVEC-OP
			OPERATOR FALLS	10 STUP	REACTOR COOLANT	PUMPS	2.33E-02	35-RXCP-STOP-HE
S.e.	1 23E 11	•, ,	FIRE NEAR MCC	620 OCCURS			2.63E-04	IEV-FI1
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE DAMAGE
			AFW PUMP TA	UNAVALLABEE	DUE TO TEST OR	MAINTENANCE	1.34E-03	058PM-+AFW1A-TH
			AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PMArw18-PS
			TORBINE DR N	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			OPERATOR FAILS	t() (\$*))P	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP HE
, <i>i</i>	1 4.E 11	ι.	FIRE NEAR MCC	620 - Keinings			2.63E-04	IEV-FI1
			· HILDMENT FATUS	CLE 10 FIRE			1.00E+00	FIRE-DAMAGE
			NSS OF ALL	ୋଲ୍ଲାର୍ମ୍ୟେଲ୍ଲାରେକ୍ଟେଲ୍	DURING 24 HOURS		1 19E 04	LOSP - 24

There is new an the second search and RUN

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 263 of 415 Page

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

1

39 CB BUSSEB FO

- 80E 02

EVENT PROB. IDENTIFIER

TABLE 4-7 FI1

Title: FI1: MCC 623 Scenario File: FIRE1.WLK ( File created by linking FIRE1.IN Reduced Sum of Cutsets: 2.8140E 09

WE[NK \*\* Ver. 3.1% \*\*)

#### NUMBER CUISET PROB PERCENT BASIC EVENT NAME . IEV-FI1 2.63E-04 46.20 FIRE NEAR MCC 623 OCCURS 1 366 09 1 FIRL DAMAGE 1.00E+00 DUE TO FIRE EQUIPMENT FAILS 058--AFH----CN 2.12E-04 AFW SYSTEM FAILURES OF COMMON CAUSE 36-RXCP-STOP-HE 2.33E-02 REACTOR COOLANT PUMPS IN STOP OPERATOR FAILS 2.63E-04 IEV-FI1 621 OCCURS 21.78 FIRE NEAR MCC 6.158 10 2 1.00E+00 FIPT-DAMAGE EQUIPMENT FAILS DUE TO FIRE 1.00E-04 27-CV-MU301--F0 FAILS TO OPEN CHECK VALVE MH-301 2.33E-02 36-RXCP-STOP-HE REACTOR COOLANT PUMPS OPERATOR FAILS TO STOP 5.63E.04 IEV-FI1 621 OCCURS 2 92 FIPE NEAR MCC. 2.236 10 3 FIRE-DAMAGE 1.00E+00 EQUIPMENT FAILS DUE TO FIRE 058PM--AFW1A-PS 1.63E-02 MECHANICAL FAILURE AFW PUMP 1A GSBPM--AFW18-PS 1.63E-02 FAILURE MECHANICAL AFW PUMP 18 058PT -- AFW1C-PS 1.37E-01 FAL. JRE AFW PUMP 1C MECHANICAL TURBINE DRIVEN 36-RXCP-STOP-HE 2.33E-02 REACTOR COOLANT PUMPS TO STOP OPERATOR FAILS IEV-FI1 2.43E-04 2.61 FERE NEAR MCC 621 OCCURS 7.35E 11 FIRE - DAMAGE 1 00F+00 EQUIPMENT FAILS DUE TO FIRE 1.20E-05 03-AV--MU38--CO TRANSFERS OPEN AOV MU-38 36-RXCP-STOP-HE REACTOR COOLANT PUMPS 2.33E-02 GERATOR FAILS TO STOP 16V-611 2.63E · 04 621 OCCURS 2 61 FIRE NEAR MCC . 35E 11 FIRE-DAMAGE 1.00E+00 EQUIPMENT FALLS DUE TO FIRE 03-AV--HU3A--CO 1.20E-05 TRANSFERS OPEN AOV MU-SA 36-RXCP-STOP-HE 2.33E-02 REACTOR COOLANT PUMPS OPERATOR FAILS TO STOP IEV-EI1 2.63E 04 2.24 FIRE NEAR MCC 621 OF CURS A 31E 11 FIRE -DAMAGE 1.00E+00 EQUIPMENT FAILS DUE TO FIRE LOSP-24 1.19E-04 POWER FROM GRID DURING 24 HOURS LOSS OF ALL 39-C8-BUS5F8-F0 4 80E-02 FEEDER BREAKERS ON 4160V BUS 5 FAIL TO OPEN 4.20E-02 39-C8-BUS6F8-F0 FEEDER BREAKERS ON 4160V BUS 6 FAIL TO OPEN IEV-FI1 2.636.04 1.12 FIRE NEAR MCC 621 OCCURS 6.1 E 11 FIRE-DAMAGE 1.00E+00 FUUIPMENT FAILS DUE TO FIRE LOSP-24 1.19E-04 FOWER FROM GRID DURING 24 HOURS OSS OF ALL 10 GE-DGA8- -CM 1,97E 03 GENERATORS MMON CAUSE FAILUPE OF BOTH DIESEL 2.63E-04 IEV-FI1 621 OCCURS 1 14 FIRE NEAR MCC 3.325 11 в FIRE-DAMAGE 1.00E+00 SUE TO FIRE EQUIPMENT FALLS 2.12E-04 058--AFW---- CM AFW SYSTEM FAILURES OF MMIN AUSE 054--0H2-0H4 HE 1.19E-03 MAIN FEEDWATER FERA R FALLS TO ESTABLISH 5.00E-01 36-0820850860HE BLEED AND FEED FERATOR FALLS TO ESTABLISH 1EV-F11 2.63E 04 ALL DECORS. TT. FIRE NEAR MUL 5 JE 11 1.00E+00 FIRE-DAMAGE 1. SHENT FALLS SE TO FIRE LOSP 24 1.19E-04 FINER FROM GRID DURING 24 HOURS 55 × A.

FALL TO OPEN

IN THE BALARERS I A WATE A B .

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 264 of 41.5

Title: F[1: NCC 62] Scenario File: F[RE1.WLK ( File created by Linking F[RE1.IN Reduced Sum of Cutsets: 2.8140E-09

WLINK \*\* Ver. 3.11 \*\*)

.

NUMBER	CUTSE1	PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
				DIESEL GENERATOR	1B	FAILURE TO START	ANU RUN	2.13E-02	10-GE-DG1BPS
	4 . 7 . 7 .							2.63E-04	IEV-F11
18	1.22E	11	.43	FIRE NEAR MCC	62J OCCURS			1.00E+00	FIRE-DAMAGE
				EQUIPMENT FAILS		FAILURE		1.63E-02	058PMAFW1A-PS
				AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PMAFW18-PS
				AFW PUMP 1B	MECHANICAL FAILS TO OPEN	ALCONC.		7.50E-03	06-MVMS102-CC
				MOV MS-102		REACTOR COOLANT	PLIMPS	2.33E-02	36-RXCP-STOP HE
				OPERATOR FAILS	TO STOP	KENCTOR CODENNI			
19	7.498	1./	28	FIRE NEAR MCC	62J OCCURS			2.63E-04	IEV-FI1
. •	1.000	12		EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
				LOSS OF ALL		DURING 24 HOURS		1.19E-04	LOSP-24
				FEEDER BREAKERS		FALL TO OPEN		4.80E-02	39-CB-BUS5FB-FO
				AOV SW-3018	FAILS TO OPEN			5.32E-0 <b>3</b>	02-AV-SW3018-CC
20	6.99E	12	25	FIRE NEAR MCC	621 OCCURS			2.63E-04	IEV-FI1
. ,				EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
				LOSS OF ALL		DURING 24 HOURS		1.19E-04	LOSP-24
				AOV SH-301A	FAILS TO OPEN			5.32E-03	02-AV-SW301A-CC
				FEEDER BREAKERS	ON 4160V BUS 6	FAIL TO OPEN		4.20E-02	39-CB-BUS6FB-FO
23	6	12	22	FIRE NEAR MCC	621 OCCURS			2.6 <b>3E</b> -04	IEV-F11
•		c		EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PM AFW1A - PS
				AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PMAFW18-PS
				AFW PUMP 1C	AUX LUBE OIL	PUMP MECHANICAL	FAILURE	3.72E-03	05BPM-ALOP1C-PS
				OF RATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
è i	5 *:)E	12	. 20	FIRE NEAR MCC	62.1 OCCURS			2.63E-04	1EV-F11
•				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PMAFW1A-PS
				AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PMAFW18-PS
				TURBINE DRIVEN	AFW PUMP TC	MECHANICAL	FAILURE	1.37E-01	05BPTAFW1C-PS
				OPERATOR FAILS	TO ESTABLISH	MAIN FEEDWATER		1.19E-03	054- 0H2-0H4-HE
				OPERATOR FALLS	TO ESTABLISH	BLEED AND FEED		5 00E-01	36-0820850860HE
23	5 59E	•2	.20	FIRE NEAR MCC	525 OLCURS			2.6 <b>3E</b> -04	IEV-FI1
				EQUIPMENT FAILS	DUE TO FIRE			1.00 <b>E+</b> 00	FIRE-DAMAGE
				LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1, 19E-04	LOSP-24
				FLEDER BREAKERS	ON 4160V BUS 5	FALL TO OPEN		4.80E-02	39-C6 BUS5FB-FO
				RAVELING WATER	SCREEN 182	MECHANICAL	FAILURE	3.72E-03	02+FLT-TW1B2+PS
		12	• ;	FIRE NEAR MCC	621 OCCURS			2.63E-04	IEV FI1
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				S OF ALL	POWER FROM GRID	ULRING 24 HOURS		1.19E-04	LOSP-24
				RAVELING WATER		MECHANICAL	FAILURE	3.72E-03	02-FLT-TWIAT PS
				FFEJER BREAKERS	UN 416UV BUS 6	FALL TO OPEN		4 20E-02	39-08-805658-50
	• ••••		۰.	·, RE NEAR MIC	N/2 DCC. RS			2.63E 04	1EV-FIT
	-			EULISMENT FALLS				1.00E+00	FIRE DAMAGE

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 265 of 415 Pare: 4

TABLE 4 7 FIT

Title: FIT: MCC 623 Scenario File: FIRE1.WEK ( File created by Linking FIRE1.IN Reduced Sum of Cutsets: 2.8140E-09

WEINK \*\* Ver. 3.11 \*\*)

.

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
••••			AFN PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PMAFW1A-PS
			AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PMAFW18-PS
			AFW PUMP 1C	UNAVAILABLE	DUE TO TEST OR	MAINTENANCE	3.00E-03	058PMAFW1C-TH
				TO STOP	REACTOR COOLANT	PUMPS	2. <b>33</b> E-02	36-RXCP-STOP-HE
26	4.51E-12	16	FIRE MEAR MCC	621 OCCURS			2.63E-04	IEV-FI1
20	4.916 16	.10	EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			LOSS OF ALL		DURING 24 HOURS		1.19E-04	LOSP-24
			FEEDER BREAKERS		FAIL TO OPEN		4.80E-02	39-CB-BUS5F8-F0
			BREAKER FROM	NCC-62D	FAILS TO CLOSE		3.000-03	40-CB-62D/A6-FC
21	4.51F 12	. 16	FIRE NEAR MCC	62J OCCURS			2.63E-04	1EV-F11
	4.7.4		EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			LOSS OF ALL		DURING 24 HOURS		1.19E-04	LOSP-24
			FEEDER BREAKERS	ON 4160V BUS 5	FAIL TO OPEN		4.80E-02	39-CB-BUS5FB-FO
			BREAKER 1-601	FAILS TO OPEN			3.00E-03	39-C9-1-601F0
28	4 S1E 12	. 16	FIRE NEAR MCC	62J OCCURS			2.63E-04	IEV-FI1
.0			EQUIPMENT FALLS	DUE TO FIRE			1.00E+C0	/ IRE-DAMAGE
			LOSS OF ALL		DURIN' 24 HOURS		1.19E-04	LOSP-24
			FEEDER BREAKERS	ON 4160V BUS 5	FALL TO OPEN		4.80E-02	39-CB-BUS5FB-FO
			BREAKER 1 603	FAILS TO CLOSE			3.00E-03	39-C8-1-603FC
29	3.94E - 12	. 14	FIRE NEAR MCC	621 OCCURS			2.63E-04	IEV FI1
Ľý			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			LOSS OF AL'	POWER TROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			BREAKER FROM	MCC - 520	FAILS TO CLOSE		3.00E-03	40-C8-52D/A6-FC
			FEEL & BREAKERS	ON 4160V BUS 6	FALL TO OPEN		4.20E-02	39-C8-8US6F8-FC
311	5 94E 12	. <b>* .</b> .	FIRE NEAR MCC	621 OCLURS			2.63E-04	LEV-FI1
-			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			BREAKER 1-501	FAILS TO OPEN			3.00E-03	39-CB-1-501FO
			FEDER BREAKERS	ON 4160V BUS 6	FAIL TO OPEN		4.20E-02	39-CB-BUS6F8-F0
۲,	5 week 12	14	FIRE NEAR MCC	62J OCCURS			2.6 <b>3</b> E-04	IEV-FI1
			EQUIPMENT FAILS	OUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BREAKER 1-509	FA: J TO CLOSE			3.00E-03	39-C8-1-509FC
			LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			FEFDER BREAKERS	ON 4160V BUS 6	FALL TO OPEN		4.20E-02	39-C8-BUS6F8-F0
52	3 546 12	: 3	FIRE NEAR MCC	621 OCCURS			2.63E-04	IEV-FI1
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			DIESEL GENERATOR	1A	FAILURE TO START	AND RUN	2.13E 02	10-GE-DG1A- PS
			AOV SW-501B	FAILS TO OPEN			5.32E-03	02-AV-SW3018-CC
<b>.</b> ۲,	Co.4 12	. • 3	FIRE NEAR MCC	521 OCCURS			2.63E-04	IEV-FI1
				OUE TI FIRE			1.00 <b>E+</b> 00	FIRE-DAMAGE
			355 (* ALC	- SWEE FROM URID	CURING 24 HOURS		1 198 D4	LUSP- →

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 266 of 415

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

.

Page:

5

TABLE 4-2 FIT

Title: F11: MCC 62J Scenario File: F1RE1.WLK ( File created by Linking F1RE1.IN Reduced Sum of Cutsets: 2.8140E-09

WLINK \*\* Ver. 3.11 \*\*)

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
			AOV SW-301A	FAILS TO OPEN			5.32E-03	02-AV-SW301A-CC
			DIESEL GENERATOR	18	FAILURE TO START	AND RUN	2.13E-02	10-GE-DG18PS
<b>1</b> .	3.47E · 12	12	FIRE NEAR MCC	62J OCCURS			2.63E-04	IEV-FI1
54	J.471 10		EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			COMMON CAUSE	FAILURES OF	AFW SYSTEM		2.12E-04	058AFWCN
			NO SERVICE WATER	DUE TO	COMMON CAUSE	FAILURES	6.22E-05	02SWCM
35	3.36E 12	. 12	FIRE NEAR MCC	62J OCCURS			2.63E-04	1EV-F11
	31700	-	EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			SOV AFW-111A	FAILS TO OPEN			2.00E-03	05BSVAFW111A-CC
			SOV AFW-1118	FAILS TO OPEN			2.00E-03	0585VAFW1118-CC
			TURBINE DRIVEN	AFW PUMP TC	MECHANICAL	FAILURE	1.37E-01	05BPTAFW1C-PS
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
36	3.26E 12	12	FIRE NEAR MCC	62J OCCURS			2.6 <b>3</b> E-04	1EV-F11
30	5.200 .2		EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.638-02	058PHAFW1A-PS
			AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PMAFW18-PS
			SOV AFW-111C	FAILS TO OPEN			2.00E-03	05BSVAFW111C-CC
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
37	3-02E-12	11	FIRE NEAR MCC	621 OCCURS			2.63E-94	IEV-FI1
, ر	5 022 72	• •	EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			SOV AFW-111A	FAILS TO OPEN			2.00E-03	05BSVAFW111A-CC
			AFW PUMP 18	UNAVAILABLE	DUE TO TEST OR	MAINTENANCE	1.80E-03	058PMAFW18-TM
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	05BPTAFW1C-PS
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2. <b>33E</b> -02	36-RXCP-STOP-HE
14	2 9.4 12	. 10	FIRE NEAR MCC	621 OCCURS			2.63E-04	IEV-FI1
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			CHECK VALVE	AFU-GA	FAILS TO OPEN		1.00E-04	05BCVAFW4A-FO
			MOV BT 38	FAILS TO CLOSE			4.77E-03	07-MVB138-00
			PERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
5.4	2 481 12	<b>Q</b> 1	FIRE NEAR MCC	62, OCCURS			2.63E-04	IEV-FI1
			EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			LOSS OF ATL		DURING 24 HOURS		×r · 04	LOSP-24
			DIESEL GENERATOR	18	FAILURE TO START	AND RUN	۰۰02	10-GE-DG1APS
			TRAVELING WATER	SCREEN 182	MECHANILAL	FAILURE	3.72E-03	02-FLT-TW182-PS
	2 488 12		FIRE NEAR MCC	523 OCCURS			2.63E-04	1 E V - F I 1
			EDUTEMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			OSS OF ALL		DURING 24 HOURS		1.19E-04	LOSP-24
			TRAVELING WATER		MECHANICAL	FAILURE	3.72E-03	02-FLT-TWIA1-PS
			DIESEL GENERATOR	.8	FAILURE TO START	AND RUN	2.13E-02	10-GE-DG18PS
·4 *	2 4 6 12	Ŷ	FIRE NEAR MCC	H2J OCCURS			2.63E-04	IEV-F11
.4			FOULTHENT FATUS				1.008+00	FIRE - DAMAGE
			AFW PUMP 18	MECHANICA.	FALLURE		1.638-02	058PMAFW18-PS

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 267 of 415

TABLE 4-7 FIT

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

WLINK \*\* Ver. 3.11 \*\*)

Page: 6

Title: FI1: MCC 62J Scenario File: FIRE1.WLK ( File created by linking FIRE1.IN Reduced Sum of Cutsets; 2.8140E-09

NUMBER CUTSET PROB PERCENT BASIC EVENT NAME EVENT PROB. IDENTIFIER .... BREAKER FROM BUS BRA-102 TO BUS BRA-104 TRANSFERS OPEN 2.40E-05 38-CBA102-04-CO OPERATOR FALLS TO STOP REACTOR COOLANT PUMPS 2.33E-02 36-RXCP-STOP-HE 2 63E-04 (EV-E11 42 2.25E 12 .08 FIRE MEAR MCC 62.J. OCCURS EQUIPMENT FAILS DUE TO FIRE 1.00E+00 FIRE-DAMAGE 1.34E-03 058PH--AFW1A-TH DUE TO TEST OR MAINTENANCE AF& PUMP TA UNAVAILABLE SOV AFW-1118 FAILS TO OPEN 2.00E-03 0585VAFW1118-CC 058PT--AFW1C-PS 1 37E-01 TURBINE ORIVEN AFU PUMP 1C MECHANICAL FALLURE REACTOR COOLANT PUMPS 2.33E-02 36-RXCP-STOP-HE OPERATOR FAILS TO STOP .07 FIRE NEAR MCC 2.63E-04 IEV-FI1 43 2.028-12 621 OCCURS EQUIPMENT FAILS DUE TO FIRE 1.00E+00 FIRE-DAMAGE 1.34E-03 05RPM--AFW1A-TH AFW PUMP 1A UNAVAILABLE DUE TO TEST OR MAINTENANCE MAINTENANCE 1.80E-03 AFW PUMP 18 UNAVA1LABLE DUE TO TEST OR 058PH -- AFW18-TH 058PT--AFW1C-PS TURBINE DRIVEN AFW "'MP 1C MECHANICAL FAILURE 1.37E-01 OPERATOR FAILS TO STOP REACTOR COOLANT PUMPS 2.33E-02 36-RXCP-STOP-HE 44 2.00E-12 .07 FIRE NEAR MCC 62.1 OCCURS 2.63E-04 1EV-611 EQUIPMENT FAILS DUE TO FIRE 1.00E+00 FIRE-DAMAGE LOSS OF ALL POWER FROM GRID DURING 24 HOURS 1.19E-04 1 OSP-24 DIESEL GENERATOR 2.13E-02 10-GE-DG1A---PS 14 FAILURE TO START AND RUN BREAKER FROM MCC-62D FAILS TO CLOSE 3.00E-03 40-CB-62D/A6-FC 2.00E 12 .07 FIRE NEAR MCC 621 OCCURS 2.63E-04 1EV-F11 45 1.00E+00 FIRE-DAMAGE EQUIPMENT FAILS DUE TO FIRE POWER FROM GRID DURING 24 HOURS 1.19E-04 LOSP-24 LOSS OF ALL FAILURE TO START 2.13E-02 10-GE-DG1A---PS DIESEL GENERATOR 14 AND RUN 3.00E-03 39-C8-1-601--FO BREAKER 1-601 FALLS TO OPEN 40 2.00E 12 .07 FIRE NEAR MCC 62J OCCURS 2.63E-04 IEV FI1 FIRE-DAMAGE EQUIPMENT FAILS DUE TO FIRE 1.00E+00 POWER FROM GRID DURING 24 HOURS 1.198-04 LOSP-24 1055 OF ALL DIESEL GENERATOR 1A FAILURE TO START AND RUN 2.13E-02 10-GE-DG1A---PS BREAKER 1-603 FALLS TO CLOSE 3.00E-03 39-CB-1-603--FC ., .\* 2.018 12 IEV-FI1 7 FIRE NEAR MCC 62J OCCURS 2 63E-04 EQUIPMENT FALLS DUE TO FIRE 1.00€+00 FIRE-DAMAGE POWER FROM URID DURING 24 HOURS ISS OF ALL 1.19E-04 LOSP-24 BREAKER FROM MCC 520 FAILS TO CLOSE 3.00E-03 40-CB-520/A6-FC 10-GE-DG18---PS DIESEL GENERATOR 19 FAILURE TO START AND RUN 2.13E-02 T FORE NEAR MEE ...8 2 - 6 12 621 OCC .RS 2.63E-04 1EV-F11 FOULFMENT FAILS DUE TO FIRE 1.00E+00 FIRE - DAMAGE USS OF ALL FOWER FROM GRID DURING 24 HOURS 1.19E-04 LOSP-24 BREAKER 1 501 FAILS TO OPEN 3.00E-03 39-08-1-501--+0 DIESEL GENERATOR ۱Β FAILURE TO START AND RUN 2.13E-02 10-GE-0G18---PS

 --2
 2
 5.12
 1.17
 FTRE NEAR MCC
 620
 OCCURS
 2.63E-04
 1EV-F11

 EUDIFMENT
 FALLS
 DUE TO FTRE
 1.00E+00
 FTRE-DAMAGE

 HRFAKER 1
 5.9
 FALLS
 TO CLOSE
 3.00E
 03
 39+CB-1+509++FC

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 268 of 415

TABLE 4-7 FIT	***** DOMINANT CUTSETS *****	Page:	7
Title: F11: MCC 62J Scenario ile: F1RE1.WLK ( File created by linking F1RE1.IN Reduced Sum of Cutsets: 2.8140E-09	WLINK ** Ver. 3.11 **)		

<b>VUMBE</b> R	CUISET PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
-			LOSS OF ALL DIESEL GENERATOR	POWER FROM GRID	DURING 24 HOURS	AND PIIN	1.19E-04 2.13E 02	L <b>OSP-24</b> 10-GE-DC18PS
50	1.04E 12	. U <b>O</b>		62J OCCURS DUE TO FIRE MU-301 DUE TO	FAILS TO OPEN COMMON CAUSE	FAILURES	2.63E-04 1.00E+00 1.00E-04 6.22E-05	1EV-FI1 FIRE-DAMAGE 27-CV-MU301FO 02SWCM

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 269 of 415

TABLE 4	-8 F12				*** DONINANT CUTS	-		Page: 1
Istle.	F12: MCC 62	Scenaru	n					
				E2.IN WLINK	** Ver. 3.11 **)			
	d Sum of Cuts							
NJMBER	CUISET PROB	PERCENT	BASIC EVENT NAM	£			EVENT PROB.	IDENTIFIER
				•••••				
1	4.02E-06	R6 51	FIRE NEAR MCC	624 IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	1EV-F12
		0.077	EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			BREAKER 1-501	FAILS TO OPEN			3.00E-03	39-C8-1-501F0
2	1.93E-07	4.15	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-FI2
			EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BREAKER 1-503	FAILS TO CLOSE			3.00E-03	39-CB-1-503FC
			FEEDER BREAKERS	ON 4160V BUS 5	FAIL TO OPEN		4.80E-02	39-C8-BU\$5F8-F0
5	8.56E-08	1 84	FIRE NEAR MCC	674 IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	1EV-F12
,	0.502 00	1.04	EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			BREAKER 1-503	FAILS TO CLOSE			3.00E-03	39-CB-1-503FC
			DIESEL GENERATOR		FAILURE TO START	AND RUN	2.13E-02	10-GE-DG1APS
	6.97E-08	1.50	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-F12
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.636-02	058PNAFW1A-PS
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.3 <b>3</b> E-02	36-RXCP-STOP-HE
5	5.22E-08	. 69	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	1EV-F12
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE - DAMAGE
			BREAKER FROM	BUS BRA-102 TO	BUS BRA-104	TRANSFERS OPEN	2.40E-05	38-08A102-04-00
	3.22E-08	40		62A IN B DIESEL	CENERATOR DOOM	OCCURS	1.34E-03	IEV-F12
6	0.22r 08	.07	FIRE NEAR MCC		UENERATOR ROOM	OLCOR3	1.00E+00	FIRE-DAMAGE
			EQUIPMENT FAILS	TRANSFERS OPEN			2.408-05	40-0815201-00
			BREAKER 15201	IRANSPERS OPEN			2,402.03	40-08-15201-00
7	3 226 98	. 69	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-F12
			EQUIPMENT FAILS	DUE TO FIRE			1,00€+00	FIRE-DAMAGE
			TRANSFORMER	SUPPLY BREAKER	1 - 505	TRANSFERS OPEN	2.40E-05	39-CB1-505-CO
5	2.6/E8	.56	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-F12
			EQUIPMENT FAILS				1.008+00	FIRE - DANAGE
			TRANSFORMER	1-52	FAILURE		1.94E-05	40-181-52SG
							4 717 67	
4	3. <b>1</b> 4 8		TIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-F12
			EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			BREAKER 1 503	FAILS TO CLOSE			3.00E-03	39-CB-1-503FC
			ACV SW 301A	FATUS TO OPEN			5.32E-03	02-AV-SW301A-CC
•-1	1.5∂€ ∂8	. 32	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	1EV-F12
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BREAKER 1-503	FAILS TO CLOSE			3.00E-03	39-C8-1-503FC
			TRAVELING WATER	SCREEN 1A1	MECHANICAL	FALLURE	3.72E-03	02-FLT-TW1A1-PS
• •			FIRE NEAR MCC	62A IN B DIESEL	SENERATOR ROOM	DECURS	1.34E-03	1EV-F12
	• · · · · · · · · · · · · · · · · · · ·	L 6.1	EDULEMENT FALLS		JUNCKATUR RUUM	26,610,000	1.00E+00	FIRE-DAMAGE
			2 W 2 1 P 2 N 2 N 2 N 2 D	000 - 10 Fint			1.000700	THE VARAUE

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 270 of 415

TABLE 4 8 FIZ

\*\*\*\*\* DONINANT CUTSEIS \*\*\*\*\*

Page: 2

Title: 712: MCC 62A Scenario File: FIRE2.WLK ( File created by linking FIRE2.IN Reduced Sum of Cutiets: 4.6470E-06

WEINK \*\* Ver. 3.11 \*\*)

NUMBER	CUTSET	PROB	PERCENT	BASIC EVENT HAM	E			EVENT PROB.	IDENTIFIER
				BREAKER 1 503 BREAKER FROM	FAILS TO CLOSE MCC-52D	FAILS TO CLOSE		3.00E-03 3.00E-03	39-C8-1-503FC 40-C8-52D/A6-FC
• 2	1 216	08	. 26	FIRE NEAR NCC EQUIPMENT FAILS BREAKER 1-509 BREAKER 1-503		GENERATOR ROOM	OCCURS	1.34E-03 1.00E+00 3.00E-03 3.00E-03	IEV-F12 FIRE-DAMAGE 39-CB-1-509FC 39-CB-1-503FC
15	1.⊎ZE	98	. 23	FIRE NEAR NCC EQUIPMENT FAILS BREAKER BRA-104	62A IN B DIESEL DUE TO FIRE CIRCUIT 7	GENERATOR ROOM	OCCURS	1.34E-03 1.00E+00 8.00E-06	1EV-F12 FIRE-DAMAGE 38-CBA104-07-CO
14	8.55E	0 <b>9</b>	. 18	FIRE NEAR NGC EQUIPMENT FAILS SOV AFW-111A TURBINE DRIVEN OPERATOR FAILS	62A IN B DIESEL DUE TO FIRE FAILS TO OPEN AFW PUMP 1C TO STOP	GENERATOR ROOM MECHANICAL REACTOR COOLANT	OCCURS FATLURE DUMPS	1 . 34E - 03 1 . 00E + 00 2 . 00E - 03 1 . 37E - 01 2 . 33E - 02	IEV-F12 FIRE-DAMAGE OSBSVAFW111A-CC OSBPTAFW1C-PS 36-RXCP-STOP-HE
15	√.92E	<b>99</b>	. 17	FIRE NEAR MCC EQUIPMENT FAILS BREAKER 1-503 COMMON CAUSE	62A IN B DIESEL DUE TO FIRE FAILS TO CLOSE FAILURE OF BOTH		OCCURS	1.34E-03 1.00E+00 3.00E-03 1.97E-03	IEV-FI2 FIRE-DAMAGE 39-CB-1-503FC 10-GE-DGABCM
16	7 55E	09	. 16	FIRE NEAR MCC EQUIPMENT FAILS LOSS OF ALL FEEDER BREAKERS	62A IN B DIESEL DUE TO FIRE POWER FROM GRID ON 4160V BUS 5	GENERATOR ROOM DURING 24 HOURS FAIL TO OPEN	OCCURS	1.34E-03 1.00E+00 1.19E-04 4.80E-02	IEV-FIZ FIRE-DAMAGE LOSP-24 39-CB-BUS5FB-FO
. 7	6.02F	99	. 14	FIRE NEAR MCC EQUIPMENT FAILS COMMON JAUSE OPERATOR FAILS	62A IN B DIESEL DUE TO FIRE FAILURES OF TO STOP	GENERATOR ROOM AFW SYSTEM REACTOR COOLANT	OCCURS PUMPS	1.34E-03 1.00E+00 2.12E-04 2.33E-02	1EV-F12 FIRE-DANAGE 05BAFWCM 36-RJ_P-STOP-HE
18	5 73E	οQ	. 12	FIRE NEAR MCC EQUIPMENT FAILS AFW PUMP 14 TURBINE DRIVEN OPERATOR FAILS	62A IN B DIESEL DUE TO FIRE UNAVATLABLE AFW PUMP 1C TO STOP	GENERATOR ROOM DUE TO TEST OR MECHANICAL REACTOR COULANT	OCCURS MAINTENANCE FAILURE PUMPS	1.34E-03 1.00E+00 1.34E-03 1.37E-01 2.33E-02	1EV-F12 FIRE-DAMAGE OSBPMAFW1A-TM OSBPTAFW1C-PS 36-RXCP-STOP-HE
۰ پ	3.82£	J9		FIRE NEAR MCC EQUIPMENT FAILS AFW PUMP 1A MOV MS 102 DPERATOR FAILS	62A IN B DIESEL DUE TO FIRE MECHANICAL FAILS TO GPEN TO STOP	GENERATOR ROOM FAILURE REACTOF: COOLANT	OCCURS PUMPS	1.34E-03 1.00E+00 1.63E-02 7.50E-03 2.33E-02	1EV-F12 FIRE-DAMAGE USBPMAFW1A-PS 06-MVMS102-CC 36-RXCP-STOP-HE
ل ا	\$ - <sup>5</sup> E	<sup>r</sup> ic,		FIRE NEAR MCC EQUIPMENT FAILS UDSS TF ALL TIESEL SHERATOR	624 IN B DIESEL DUE TO FIRE FOWER FROM GRID 'A	GENERATOR ROOM DURING 24 HOURS FAILURE TO START	OCCURS AND RUN	1.34E-03 1.00E+00 1.19E-04 2.13E-02	1EV-F12 FTRE-DAMAGE LOSP-24 10-GE-DGTA FS

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 271 of 415

TABLE	E 4-8	F12	
-------	-------	-----	--

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 3

EVENT PROB. IDENTIFIER

3.00E-03 058PM--AFW1C-TH

2.33E-02 36-RXCP-STOP HE

Title: F12: MCC 62A Scenario File: F1RE2.WLK ( File created by linking F1RE2.IN WLINK \*\* Ver. 3.11 \*\*) Reduced Sum of Cutsets: 4.6470E 06

#### NUMBER CUISET PROB PEPCENT BASIC EVENT NAME

				-				
	•••••		•••••					····
21	3.22E-09	.07	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-F12
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			125VDC BUS	BRA-104	FAILURE		2.40E-06	38-85-8RA104-SG
22	3.22E 09	07	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.346-03	IEV-FIZ
			EQUIPMENT FAILS				1.002+00	FIRE-DAMAGE
			125VDC BUS	BRA-102	FAILURE		2.40E-06	38-85-8RA102-5G
3	5.22E U9	07	FIRE NEAR MCC	ADA IN A DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	1EV-F12
. ,	J.LLE UJ		EQUIPMENT FAILS		denetrifick koder	000000	1.00E+00	FIRE-DAMAGE
			BUS 5	FALLURE			2.40E-06	39-BS-BUS5SG
			603 7	GILORE			2.402 00	57 65 6637 54
24	3.22E 09	.07	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-FI2
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+C0	FIRE-DAMAGE
			BUS 52	FAILURE			2.40E-06	40-85-80552SG
25	3.12E-09	_n <b>7</b>	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-FI2
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			CHECK VALVE	MU-301	FAILS TO OPEN		1.00E-04	27-CV-MU301F0
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
56	S183E 08	.06	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-FI2
			EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			BREAKER 1-503	FAILS TO CLOSE			3.00E-03	39-CB-1-503FC
			NO SERVICE WATER	DUE TO	COMMON CAUSE	FAILURES	7.30E-04	02SWSCM
27	2.77E-09	.06	FIRE NEAR MCC	62A IN B !ESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-F12
			EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			RESERVE AUX	TRANSFORMER	FAILURE		4.30E-05	39-TR-RAT5G
			FEEDER BREAKERS	ON 4160V BUS 5	FALL TO OPEN		4.80E-02	39-CB-BUS5FB-FO
.48	1 898 -89	:)4	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	1EV-F12
			EQUIPMENT FAILS	DUE TO FIRE			1.00E-00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PMAFW1A-PS
			AFW PUMP 1C	AUX LUBE OIL	PUMP MECHANICAL	FAILURE	3.72E-03	058PM-ALOP1C-PS
			OPERA OR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
<u>.</u>	1.78E-09		FIRE NEAR MCC	62A IN B DIESEL	CENERATOR BOOM	OCCURS	1.34E-03	1EV-F12
. *	1. F (AC 1. F T		EQUIPMENT FAILS	DUE TO FIRE	UCHERRIOR ROOM	OCCORS	1.00E+00	FIRE-DAMAGE
			AF# FUMP 1A	MECHANICAL	FAILURE		1.632-02	058PM AFW1A-PS
			AND FORP A	AFW FUMP 1C	MECHANICAL	FALLURE	1.37E-01	058PTAFW1C-PS
			OFERATOR FAILS	TO ESTABLISH	MAIN FEEDWATER	ALUNE	1.19E-03	05AOM2-OM4-HE
			OPERATOR FAILS	TO ESTABLISH	BLEED AND FEED		5.00E-01	36-0820850860HE
			UPLERIUE FAILS	I COMPLISH	DIELO AND FELJ		3.00E-01	ως σείσο μασημε
<b>i</b> .;	1.53£ .09	3	FIRE NEAR MCC	02A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-F12
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FALLURE		1.63E 02	USBPMAFW1A-PS

a a composite

OF LITOR FAILS TO STOP

UNAVAILABLE DUE TO TEST OR MAINTENANCE

REACTOR CUDLANT PUMPS

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 272 of 415

TABLE 4-8 FIZ

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page:

4

#### Title: FI2: MCC 62A Scenario File: FIRE2.WLK ( File created by Linking FIRE2.IN WLINK \*\* Ver. 3.11 \*\*) Reduced Sum of Cutsets: 4.6470E-06

#### NUMBER CUTSET PROB PERCENT BASIC EVENT NAME

#### EVENT PROB. IDENTIFIER .....

31	1,238-09	.03	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	168-612
-			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			RESERVE AUX	TRANSFORMER	FAILURE		4.30E-05	39-TR-RATSG
			DIESEL GENERATOR		FAILURE TO START	AND RUN	2.13E-02	10-GE-DG1APS
	1 435 00					000000	1 7/5 07	151/ 513
32	1.02E 09	.02	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-FIZ
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAKAGE
			AFW PUMP TA	MECHANICAL	FAILURE		1.63E-02	058PHAFW1A-PS
			SOV AF#-111C	FAILS TO OPEN	DEACTOR CODIANT	DUMDE	2.00E-03 2.33E-02	05BSVAFW111C-CC 36-RXCP-STOP-HE
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PURP 3	2.335.02	JO-RACE-STOP-HE
53	8.48E-10	.02	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-FI2
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			AOV SW-301A	FAILS TO OPEN			5.32E-03	02-AV-SW301A-CC
34	7.88E-10	.02	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-FI2
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BREAMER 1-503	FAILS TO CLOSE			3.00E-03	39-CB-1-503FC
			SW PUMP 1A1	MECHANICAL	FAILURE		1.40E-02	02-PM-SW1A1PS
			SW PUMP 1A2	MECHANICAL	FAILURE		1.40E-02	02-PM-SW1A2PS
35	5.93E-10	<b>01</b>	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-F12
				DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			TRAVELING WATER		MECHANICAL	FAILURE	3.72E-03	02-FLT-TW1A1-PS
50	4.78E 10	01	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-FI2
10	4.700 10			DUE TO FIRE	demention noon	000000	1.00E+00	FIRE-DAMAGE
			LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			BREAKER FROM	MCC-52D	FAILS TO CLOSE		3.00E-03	40-C8-520/A6-FC
37	~.78£ 10	.)1	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCLURS	1.34E-03	IEV-FI2
<b>3</b> 1	4,100 10		EQUIPMENT FAILS		DERENATOR ROOM	OCLORD	1.00E+00	FIRE-DAMAGE
			BREAKER 1 509	FAILS TO CLOSE			3.00E-03	39-C8-1-509FC
			OSS OF ALL	POWER FROM GRID	DUPTNG 24 HOURS		1.19E-04	LOSP-24
			1033 / ACC		DURING 24 HOURS		1.172 04	
43	4.58E 10				GENERATOR ROOM	OCCURS	5.34E-03	1E/-FI2
			EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
				FALS TO OPEN			2.00E-03	05BSVAFW111A-CC
			MAY MS 102				7.5UE-03	06-MVMS102-CC
			DERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36 RXCP-STOP-HE
39	4 28E 10	01	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	LEV-F12
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			CHECK VALVE	AFW-TA	FALLS TO OPEN		1.00E-04	05BCVAFW1A-FO
			TURBINE DRIVEN	AFW PUMP TC	MECHANICAL	FAILURE	1.37E-01	058PT - AFW1C-PS
			SPERATOR FALLS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
•••	- 198 - IV		F. RE NEAR MCC	524 IN 8 DIESEL	SENERATOR ROOM	OCCURS	1.34E-03	164-615

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 273 of 415

WLINK \*\* Ver. 3.11 \*\*)

TABLE 4-8 FI2

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 5

#### Title: F12: MuC 62A Scenario File: FIRE2.WLK ( File created by Linking FIRE2.IN Reduced Sum of Cutsets: 4.6470E-06

Coursent Fails         De to File Check Vavie         No.511A Defeator Fails         Fails To OPH Fails To OPH Reactor Count Fuels         1.000-04 Distribution         OSEC+HUSTIA-FOILS           41         3.751-10         Of File Near NCC Defeator Fails         Color No         Ary Dup TC Teasters Fails         Fails To OPH Recover Color No         Fails To OPH Recover Color No         1.000-04 Distribution         OSEC+HUSTIA-FFIC-PE Distribution           41         3.751-10         Of File Near NCC Defeator Fails         Color No         OCA IN 8 DIESEL Defeator Fails         Geleator Room Recover Color No         Tele Near NCC Distribution         Tele Near NCC Distribution         Color Na Distribution         Tele Near NCC Distribution         Color Na Distribution         Tele Near NCC Distribution         Color Na Distribution         Tele Near Na Distribution           42         5.751-10         Of File Near NCC Distribution         Color Na Distribution         Color Na Distribution         Color Na Distribution         Tele Na Distribution         Color Na Distribution         Tele Na Distribution           42         5.761-10         Of File	NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAM	Ę			EVENT PROB.	IDENTIFIER
OPERATOR FAILS         TO STOP         REACTOR COOLACT         PARPS         2.33E-02         SA-RXCP-STOP-HE           4.1         3.75E-10         0.01         FIRE MAR MCC         S2A         M III 00 IOESEL         GENERATOR ROOM         OCCURS         1.34E-03         FIRE-DAMAGE           4.2         3.75E-10         0.01         FIRE MAR MCC         S2A III III 00 IOESEL         GENERATOR ROOM         OCCURS         1.34E-03         FER-FIRE           4.2         3.75E-10         0.01         FIRE MAR MCC         S2A III III 00 IOESEL         GENERATOR ROOM         OCCURS         1.34E-03         FER-FIRE           4.2         3.75E-10         0.01         FIRE MAR MCC         S2A IIII 00 IOESEL         GENERATOR ROOM         OCCURS         1.34E-03         FER-FIRE           4.3         3.14E-10         0.01         FIRE MAR MCC         S2A IIII 00 IOESEL         GENERATOR ROOM         OCCURS         1.34E-03         FER-FIRE           4.4         5.14E-10         0.01         FIRE MAR MCC         S2A IIIII 00 IOESEL         GENERATOR ROOM         OCCURS         1.34E-03         FER-FIRE           4.5         5.14E-10         0.01         FIRE MARGE         S2A IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	· · · ·			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAKAGE
IDENTIFY				CHECK VALVE	HU-311A	FAILS TO OPEN		1.00E-04	058CV-HU311A-FO
4.1         3.75E-10         0.1         FIRE NAM PCC EQUIPMENT FALLS EQUIPMENT FALLS EQUIPM				OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
1000F000         FIRE-DAMAGE ADV HU-3B         INAMSFERS UPEN TRANSFERS UPEN TRANSFER				TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
1000F000         FIRE-DAMAGE ADV HU-3B         INAMSFERS UPEN TRANSFERS UPEN TRANSFER	41	3 75E-10	01	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34. 03	1EV-F12
AOV HU: 38         FRANSFERS OPEN OPERATOR HALLS         FRANSFERS OPEN IS STOP         REACTOR COOLANT         PUMPS         1.20E-05         03-AVMU3E-CD 30-BKCP-STOP-HE           42         5.75E-10         .01         FIRE HARA MCC         62A IN B DIESEL OPERATOR FAILS         GENERATOR ROON         OCURS         1.34E-03         1.20E-05         03-AVMU3E-CD 30-BKCP-STOP-HE           43         5.14E-10         .01         FIRE HARA MCC         62A IN B DIESEL OPERATOR FAILS         GENERATOR ROON         OCURS         1.34E-03         120E-05         03-AVMU3E-CD 03-AVMU3E-CD           44         5.14E-10         .01         FIRE HARA MCC         62A IN B DIESEL OPERATOR ROOR         GENERATOR ROON         OCURS         1.34E-03         120E-06-07         FIRE-POMAGE 1.05F-24           44         5.14E-10         .01         FIRE HARA MCC         62A IN B DIESEL OPERATOR ROOR         GENERATOR ROOR         OCURS         1.34E-03         120E-04 1.05F-24           44         5.14E-10         .01         FIRE HARA MCC         62A IN B DIESEL OPERATOR ROOR         GENERATOR ROOR         OCURS         1.34E-03         120E-04 1.05E-04A0CE           44         .01         FIRE HARA MCC         62A IN B DIESEL OPERATOR FACINE ROOM         GENERATOR ROOM         OCURS         1.34E-03         120E-04 1.05E-04         120E-04		311.21							
OPERATOR FAILS         TO STOP         REACTOR COOLANT         PUMPS         2.33E-02         36-RKCP-STOP-HE           42         3.75E 10         .01         FIRE MEAR MCC BOUTHMENT FAILS OPERATOR FAILS         G2A IN B DIESEL OPERATOR FAILS         GENERATOR ROOM OPERATOR FAILS         GENERATOR ROOM OPERATOR FAILS         0CURS FIRE-DAMAGE OPERATOR FAILS         1.34E-03 OPERATOR FAILS         IEV-FI2 FIRE-DAMAGE COMMON CAUSE         IEV-FI2 OPERATOR FAILS         IEV-FI2 OPERATOR FAI								1.20E-05	
EQUIPMENT FAILS ADV MO-3A         DUE TO FIRE TRANSFERS OPEN ADV MO-3A         REACTOR COCLANT         PLAPS         1.000-00 1.000-00         FIRE-DAMAGE 03-AVMU3ACO 00-EV-AVMU3ACO 00-EV-AVMU3ACO 00-EV-AVMU3ACO 00-EV-AVMU3ACO 00-EV-AVMU3ACO 00-EV-AVMU3ACO 00-EV-AVMU3ACO 1.00E-00         FIRE-DAMAGE 1.00E-00           44         3.14E-10         1.01         FIRE-MARCE EQUIPMENT FAILS DUE TO FIRE AFW PUMP 1A HOW R5-102         GENERATOR ROOM DUE TO EST OR AFW PUMP 1A HAVATIABLE DUE TO FIRE AFW PUMP 1A HAVES TO OPEN         DECOLINS 1.34E-03         IEV-FI2 FIRE-DAMAGE FIRE-DAMAGE           4-0         2.75E-10         .01         FIRE-MARCE FAILS TO OPEN         GENERATOR ROOM REACTOR COOLANT         DUE TO FIRE FAILURE         DUE TO FIRE FAILURE         DUE TO FIRE FAILURE         IEV-FI2 SO-FRAC-3         IEV-FI2 SO-FRAC-3           4-0         2.75E-10         .01         FIRE-MARCE FAILS         GENERATOR ROOM COCURS         I.34E-03         IEV-FI2 SO-FRAC-50           4-0         FIRE-MARCE FAILS         CO-FIC        GENERATOR ROOM COCURS						REACTOR COOLANT	PUMPS		
EQUIPMENT FAILS ADV MU-3A         DUE TO FIRE TRANSFERS OPEN TRANSFERS OPEN ADV MU-3A         REACTOR COCLANT         PUMPS         1.000-00 1.200-05         FIRE-DAMAGE 03-AVX-MU3A-CD 03-AVX-MU3A-CD 03-AVX-MU3A-CD 03-AVX-MU3A-CD 03-AVX-MU3A-CD 03-AVX-MU3A-CD 03-AVX-MU3A-CD 03-AVX-MU3A-CD 03-AVX-MU3A-CD 03-AVX-MU3A-CD 03-AVX-MU3A-CD 00FERATOR FAILS         FIRE-DAMAGE CDUPMENT FAILS         1.000-00 DUE TO FIRE EQUIPMENT FAILS         FIRE-DAMAGE CDUPMENT FAILS         1.000-00 DUE TO FIRE FAILURE OF BOTH DIESEL         GENERATOR ROOM CCURS         0.000-00 T.000-00         FIRE-DAMAGE TI.000-00           44         3.14(-10)         .01         FIRE-MARCE COMMON CAUSE         FAILURE OF BOTH DIESEL         GENERATOR ROOM DUE TO FIRE COMMON CAUSE         GENERATORS         1.346-03         IEV-FI2 FIRE-DAMAGE           44         3.14(-10)         .01         FIRE-MARCE COMMON CAUSE         GENERATOR ROOM OUFING ZA HOURS         0.346-03         IEV-FI2 FIRE-DAMAGE           44         3.14(-10)         .01         FIRE-MARCE COMMON CAUSE         GENERATOR ROOM OUFING ZA HOURS         1.346-03         IEV-FI2 FIRE-DAMAGE           44         3.14(-10)         .01         FIRE-MARCE FAILURE         DUE TO FIRE DUE TO FIRE FIRE-DAMAGE         DUE TO FIRE FIRE-DAMAGE         1.346-03         IEV-F12 FIRE-DAMAGE           455         .02/F10         .01         FIRE-MARCE FAILURE         DUE TO FIRE FIRE-DAMAGE         DUE TO FIRE FIRE-DAMAGE         DUE TO FIRE FIRE-	, ,	7 75 1 11	01	EIDE NEAD MCC			0001185	1 346-03	164-612
AOV HQ-3A OPERATOR FAILS         TRANSFERS OPEN TO STOP         REACTOR COLLANT         PURPS         1.20E-05 2.35E-02         07-AVHU3ACD 36-RECP-STOP-HE           4.3         5.14E-10         L01         FIRE HEAR MCC EQUIPHENT FAILS COMMON CAUSE         620 ILB B DIESEL EQUIPHENT FAILS COMMON CAUSE         GENERATOR ROOM FIRE -DAMAGE         0.00E+00 1.09E-04         FIRE-DAMAGE LOSP-24           4.4         3.14E-10         L01         FIRE HEAR MCC EQUIPHENT FAILS DUE TO FIRE DUE TO FIRE EDUIPHENT FAILS DUE TO FIRE DUE TO FIRE DUE TO FIRE DUE TO FIRE DUE TO FIRE DUE TO FIRE DUE TO FIRE OFENATOR ROOM         0CCURS         1.34E-03 1.97E-03         IEV-FI2 FIRE-DAMAGE           4.4         3.14E-10         L01         FIRE HEAR MCC EQUIPHENT FAILS DUE TO FIRE DUE TO FIRE DUE TO FIRE FAILS TO OPEN REACTOR COLLANT         0CCURS         1.34E-03 1.97E-03         IEV-FI2 FIRE-DAMAGE           4.5         5.07E-10         .01         FIRE HEAR MCC EQUIPHENT FAILS DUE TO FIRE FAILS TO OPEN REACTOR COLLANT         0CCURS         1.34E-03 1.00E+00         IEV-FI2 FIRE-DAMAGE           4.5         0.75E-10         .01         FIRE HEAR MCC EQUIPHENT FAILS DUE TO FIRE FAILURE         62A IN B DIESEL FAILURE         GENERATOR ROOM CCURS         1.34E-03 1.00E+00 FIRE-DAMAGE           4.5         0.75E-10         .01         FIRE HAAR MCC EQUIPHENT FAILS DUE TO FIRE FAILURE         62A IN B DIESEL FAILURE         GENERATOR ROOM FIRE-DAMAGE         1.00E+00 FIRE-DAMAG	42	J./JE 10	.01			UCREARIOR ROOM	UCCORS		
OPERATOR FAILS         TO STOP         REACTOR COCLAMI         PUMPS         2.33E-02         36-RKCP-STOP-HE           -43         5.14E-10         .01         FIRE HEAR MCC EQUIPMENT FAILS COMMON CAUSE         62A IN B DIESEL COMMON CAUSE         GENERATOR ROOM DURING 24 HOURS         0.00E+00         FIRE-DAMAGE 1.00E+00         FIRE-DAMAGE 1.00E+00         FIRE-DAMAGE 1.00E+00           44         3.14F-10         .01         FIRE HEAR MCC EQUIPMENT FAILS         62A IN B DIESEL UNAVAILABLE         GENERATOR ROOM DURING 24 HOURS         GENERATORS         1.34E-03         IEV-FI2 INOPE-04         IEV-FI2 LOS-24           44         3.14F-10         .01         FIRE HEAR MCC EQUIPMENT FAILS         62A IN B DIESEL         GENERATOR ROOM DUE TO TEST OR HAINTENANCE         1.34E-03         IEV-FI2 INOPE-04         IEV-FI2 INOPE-04           45         5.07E-10         .01         FIRE HEAR MCC POLIPMENT FAILS         62A IN B DIESEL UNAVAILABLE         GENERATOR ROOM PEACTOR COLLANT         OCCURS         1.34E-03         IEV-FI2 INOPH-04           45         5.07E-10         .01         FIRE HEAR MCC POLIPMENT FAILS         62A IN B DIESEL         GENERATOR ROOM PEACTOR COLLANT         OCCURS         1.34E-03         IEV-FI2 INOPH-0           46         2.75E-10         .01         FIRE HEAR MCC POLIPMENT FAILS         62A IN B DIESEL PEACTOR COLLANT         GENERATOR ROOM P									
EQUIPMENT FAILS       DUE TO FIRE LOSS OF ALL COMMON CAUSE       FORE FROM GRID DURING 24 HOURS FAILURE OF BOTH DIESEL       1.00E+00 GENERATORS       FIRE-DAMAGE LOSP-24 LOSP-25 LOSP-24 LOSP-24 LOSP-25 LOSP-24 LOSP-24 LOSP-25						REACTOR COOLANT	PUMPS		
EQUIPMENT FAILS       DUE TO FIRE LOSS OF ALL COMMON CAUSE       FORE FROM GRID DURING 24 HOURS FAILURE OF BOTH DIESEL       1.00E+00 GENERATORS       FIRE-DAMAGE LOSP-24 LOSP-25 LOSP-24 LOSP-24 LOSP-25 LOSP-24 LOSP-24 LOSP-25									
LOSS OF ALL COMMON CAUSE       POMER FROM CRID COMMON CAUSE       POMER FROM CRID FAILURE OF BOTH DIESEL       OURING 24 HOURS GENERATORS       1.19E-04 1.97E-03       LOSP-24 10-GE-DGABCH         44       3.14E-10       .01       FIRE NEAR MCC EQUIPMENT FAILS DUE TO FIRE UNAVAILABLE DUE TO TEST OR OPERATOR FAILS       GENERATOR ROOM TO TEST OR DUE TO TEST OR DUE TO TEST OR DUE TO TEST OR HAINTENANCE       0.2000 1.34E-03 0.560-03 0.500-00       FIRE-DAMAGE FIRE-DAMAGE FIRE-DAMAGE FIRE-DAMAGE DUE TO TEST OR DUE TO TEST OR DUE TO TEST OR DUE TO TEST OR DUE TO TEST OR HAINTENANCE       1.34E-03 0.560-03 0.500-00       IEV-FI2 FIRE-DAMAGE F	-3	3.14E 10	.ú1			GENERATOR ROOM	OCCURS		
сонном слизе         FAILURE OF BOTH DIESEL         GENERATORS         1.97E-03         10-GE-0GABCH           44         3.14E-10         .01         FIRE NEAR MCC EQUIPMENT FAILS         62A IN B DIESEL OUE TO FIRE         GENERATOR ROOM OCCURS         1.34E-03         FEV-FI2 FIRE-DAMAGE FIRE-DAMAGE           45         5.97E-10         .01         FIRE NEAR MCC OPERATOR FAILS         62A IN B DIESEL TO STOP         GENERATOR ROOM PEACTOR COOLANT         PUMPS         1.34E-03         IEV-FI2 FIRE-DAMAGE           45         5.97E-10         .01         FIRE NEAR MCC FUJIPMENT FAILS         62A IN B DIESEL OUE TO FIRE TRANSFORMER         GENERATOR ROOM FAILS         OCCURS         1.34E-03         IEV-FI2 FIRE-DAMAGE           46         2.75E-10         .01         FIRE NEAR MCC EQUIPMENT FAILS         62A IN B DIESEL OUE TO FIRE TRANSFORMER         GENERATOR ROOM FAILS         OCCURS         1.34E-03 FIRE-DAMAGE         IEV-FI2 FIRE-DAMAGE           46         2.75E-10         .01         FIRE NEAR MCC EQUIPMENT FAILS         62A IN B DIESEL DUE TO TEST OR FAILS         GENERATOR ROOM FIRE-DAMAGE         OCCURS         1.34E-03 FIRE-DAMAGE         IEV-FI2 FIRE-DAMAGE           47         .020         FIRE NEAR MCC EQUIPMENT FAILS         62A IN B DIESEL DUE TO TEST OR MOV MS-102         GENERATOR ROOM PUMPS         OCCURS         1.34E-03 FIRE-DAMAGE           47									
44       3.14E+10       101       FIRE NEAR NCC EQUIPMENT FAILS AFU PUMP 1A NOV NS-102       62A 1N B DIESEL DUE TO FIRE UNAVAILABLE FAILS TO OPEN PEATOR FAILS       GENERATOR ROOM DUE TO TEST OR FAILS TO OPEN REACTOR COOLANT       OCCURS       1.34E+03 1.00E+00       IEV-FI2 FIRE-DAMAGE 7.50E+03         45       5.97E+10       .01       FIRE NEAR MCC FUUIPMENT FAILS       62A IN B DIESEL DUE TO TEST OR FAILS TO OPEN       GENERATOR ROOM REACTOR COOLANT       OCCURS       1.34E+03 7.50E+03       IEV-FI2 FIRE-DAMAGE 1.00E+00         45       5.97E+10       .01       FIRE NEAR MCC FUUIPMENT FAILS       62A IN B DIESEL DUE TO FIRE TRANSFORMER FAILURE       GENERATOR ROOM FAILURE       OCCURS       1.34E+03 1.00E+00       IEV-FI2 FIRE-DAMAGE 4.30E+03         46       2.75E+10       .01       FIRE NEAR MCC FOUIPMENT FAILS       62A IN B DIESEL UNAVAILABLE DUE TO FIRE FAILURE       GENERATOR ROOM FIRE-DAMAGE FAILURE       OCCURS       1.34E+03 1.00E+00       IEV-FI2 FIRE-DAMAGE 5.40E+04         47       2.75E+10       .01       FIRE NEAR MCC FOUIPMENT FAILS       62A IN B DIESEL UNAVAILABLE DUE TO TEST OR FAILURE       OCCURS       1.34E+03 1.00E+00       IEV-FI2 FIRE-DAMAGE 5.40E+04       OSEPNAFW1A-PS 0.54E+07         48       2.35E+102       .03       FAILS TO OPEN AFAILS       OCCURS       1.34E+03 1.00E+00       FIRE-DAMAGE 5.40E+04       OCEURS       1.34E+03 1.00E+00       FIRE-DAMAGE 1.00E+00       FIRE-DAMA									
EQUIPMENT FAILS AFW PUMP 1A NOV MS-102DUE TO FIRE HAINTENANCE1.00E+00 1.34E+03FIRE-DAMAGE OSBPMAFV1A-TM 0.50FWAFV1A-TM 0.60FWMS102-CC 3.6+NXC-PSTOP-HE455.97E+10.01FIRE NEAR MCC FULLENCE AUX ADV SW-301A624 IN B DIESEL FAILS TO OPENGENERATOR ROOM FAILS TO OPEN REACTOR COOLANT FUMPSOCCURS1.34E+03 1.34E+03IEV-FI2 FIRE-DAMAGE FIRE-DAMAGE FIRE-DAMAGE462.75E+10.01FIRE NEAR MCC FULLENCE AUX ADV SW-301A624 IN B DIESEL FAILS TO OPENGENERATOR ROOM FAILS TO OPENOCCURS1.34E+03 1.00E+00IEV-FI2 FIRE-DAMAGE FIRE-DAMAGE462.75E+10.01FIRE NEAR MCC FULLENCE AUX ADV SW-301A624 IN B DIESEL FAILS TO OPENGENERATOR ROOM FAILS TO OPENOCCURS1.34E+03 1.00E+00IEV-FI2 FIRE-DAMAGE462.75E+10.01FIRE NEAR MCC FULLENCE ADV SW-301A624 IN B DIESEL FAILS TO OPENGENERATOR ROOM FAILS TO OPENOCCURS1.34E+03 1.00E+00IEV-FI2 FIRE-DAMAGE462.75E+10.01FIRE NEAR MCC FAILS624 IN B DIESEL TO STOPGENERATOR ROOM REACTOR COLLANT PUMPSOCCURS1.34E+03 1.34E+03IEV-FI2 FIRE-DAMAGE47.0.35E+17.01FIRE NEAR MCC FAILS624 IN B DIESEL TO STOPGENERATOR ROOM REACTOR COLLANT PUMPSOCCURS1.34E+03 1.34E+03IEV-FI2 FIRE-DAMAGE482.35E+17.01FIRE NEAR MCC FAILS624 IN B DIESEL FAILSGENERATOR ROOM REACTOR COLLANT PUMPSOCCURS <t< td=""><td></td><td></td><td></td><td>COMMON CAUSE</td><td>FAILURE OF BOTH</td><td>DIESEL</td><td>GENERATORS</td><td>1.97E-03</td><td>10-GE-DGABCM</td></t<>				COMMON CAUSE	FAILURE OF BOTH	DIESEL	GENERATORS	1.97E-03	10-GE-DGABCM
AFW PUMP 1A NOV MS-102 OPERATOR FAILSUNAVAILABLE FAILS TO OPEN TO STOPDUE TO TEST OR REACTOR COOLANT PUMPS1.34E-03 2.33E-0205BPHAFVIA-TM 06-NVMS102-CC 36RXCP-STOP-HE455.97E-10.01FTHE NEAR NCC FUUIPMENT FAILS AOV SW-301A62A TN B DIESEL UE TO FIRE RESERVE AUX AOV SW-301AGENERATOR ROOM FAILS TO OPENOCCURS1.34E-03 1.00E+00TEV-F12 FIRE-DAMAGE 4.30E-05462.75E-10.01FTRE NEAR NCC FUUIPMENT FAILS AOV SW-301A62A TN B DIESEL TRANSFORMER FAILS TO OPENGENERATOR ROOM FAILS TO OPENOCCURS1.34E-03 1.00E+00TEV-F12 FIRE-DAMAGE462.75E-10.01FTRE NEAR NCC FUUIPMENT FAILS DUE TO FIRE HECHANICAL OVERATOR FAILS62A TN B DIESEL DUE TO FIRE FAILUREGENERATOR ROOM FAILUREOCCURS1.34E-03 1.00E+00TEV-F12 FIRE-DAMAGE472.35E-17.01FTRE NEAR NCC PUMP TA NECHANICAL OPERATOR FAILS62A TN B DIESEL TO STOPGENERATOR ROOM REACTOR COOLANT PUMPSOCCURS1.34E-03 1.34E-03TEV-F12 FIRE-DAMAGE472.35E-17.03FTRE-NEAR NCC PUMP TC AFW PUMP TC DERATOR FAILS62A TN B DIESEL FAILS TO OPEN AFW TOPH AFW DUMP MECHANICAL FAILS TO OPEN AFW PUMP TC DERATOR FAILS0.02 TO FIRE FAILS TO OPEN AFW DUMP MECHANICAL FAILS TO OPEN AFW PUMP TC DERATOR FAILS0.20 TO FIRE FAILS TO OPEN AFW TOPH TO TO STOP0.020081.34E-03 TEV-F12TEV-F12 TO STOP-HE482.13E-10.030FTRE-NARA MCC PUMP TO DERATOR FAILS	í. í.	3.14E - 10	.01	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-FI2
NOV MS-102 OPERATOR FAILSFAILS TO OPEN TO STOPREACTOR COOLANT PLANPSPUMPS7.50E-03 2.33E-0206-NVMS102-CC 36-RXCP-STOP-HE455.97E-101.01FIRE NEAR NCC FUUIPMENT FAILS62A IN B DIESEL DUE TO FIRE TRANSFORMER FAILS TO OPENGENERATOR ROOM FAILS TO OPENOCCURS1.34E-03 1.00E+00IEV-FI2 FIRE-DAMAGE462.75E-10.01FIRE NEAR NCC FOUIPMENT FAILS62A IN B DIESEL DUE TO FIRE FAILS TO OPENGENERATOR ROOM FAILS TO OPENOCCURS1.34E-03 1.00E+00IEV-FI2 FIRE-DAMAGE462.75E-10.01FIRE NEAR NCC FOUIPMENT FAILS62A IN B DIESEL DUE TO FIRE MECHANICAL UNAVAILABLEGENERATOR ROOM FAILS TO OPENOCCURS1.34E-03 1.00E+00IEV-FI2 FIRE-DAMAGE462.75E-10.01FIRE NEAR NCC FOUIPMENT FAILS62A IN B DIESEL DUE TO FIRE MECHANICAL UNAVAILABLEGENERATOR ROOM FIRE-DAMAGEOCCURS1.34E-03 1.00E+00IEV-FI2 FIRE-DAMAGE472.33E-10.00FIRE NEAR MCC FOUIFMENT FAILS62A IN B DIESEL DUE TO FIRE FAILS TO OPENGENERATOR ROOM ACCURSOCCURS1.34E-03 1.34E-03IEV-FI2 FIRE-DAMAGE482.33E-10.00FIRE NEAR MCC FOUIFMENT FAILS62A IN B DIESEL DUE TO FIRE FAILS TO OPENGENERATOR ROOM REACTOR COOLANTOCCURS1.34E-03 SIEV-FI2IEV-FI2 SIGENAAGE49.00FIRE NEAR MCC FOUIFMENT FAILS62A IN B DIESEL FOUIFMENT FAILSGENERATOR ROOM FIRE ODAMAGEOCCURS1.34E-03 SIEV-FI2				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
OPERATORFAILSTOSTOPREACTORCOLANTPUMPS2.33E-0236-RXCP-STOP-HE455.07E-10.01FIRE NEAR NCC FULIPNENT FAILS AOV SW-301A62A IN B DIESEL TRANSFORMER FAILS TO OPENGENERATOR ROOM FAILUREOCCURS1.34E-03 1.00E+00IEV-FI2 FIRE-DAMAGE462.75E-10.01FIRE NEAR MCC FOULPMENT FAILS AOV SW-301A62A IN B DIESEL FAILS TO OPENGENERATOR ROOM FAILUREOCCURS1.34E-03 1.34E-03IEV-FI2 FEV-FI2462.75E-10.01FIRE NEAR MCC FOULPMENT FAILS AFW PUMP 1A MOV MS-102 OPERATOR FAILS62A IN B DIESEL TO STOPGENERATOR ROOM FAILUREOCCURS1.34E-03 1.34E-03IEV-FI2 FER-DAMAGE470.35E-170FIRE NEAR MCC FOULPMENT FAILS OPERATOR FAILS62A IN B DIESEL TO STOPGENERATOR ROOM REACTOR COOLANTOCCURS1.34E-03 FIRE-DAMAGE482.35E-170FIRE NEAR MCC FOULPMENT FAILS OPERATOR FAILS62A IN B DIESEL DUE TO FIRE FAILS TO OPEN AFW 111A AFW PUMP 1C ADX LUBE OIL PUMP MECHANICAL PUMP MECHANICAL FAILURE7.34E-03 FAILUREIEV-FI2 FOULPMENT FAILS SO SBRAFH111A-CC SO SBRAFH111A-CC ADX LUBE OIL PUMP MECHANICAL PUMP MECHANICAL FAILURE7.34E-03 FAILUREIEV-FI2 FAILURE482.138-10.00FIRE-DAMAGE FAILS TO STOP62A IN B DIESEL FAILS TO OPEN ADX LUBE OIL PUMP MECHANICAL PUMPS2.33E-0236-RXCP-STOP-HE482.138-10.00FIRE-NEAR MCC FAILS TO STOP62A IN B DIESEL				AFW PUMP 1A	UNAVAILABLE	DUE TO TEST OR	MAINTENANCE	1.34E-03	058PHAFW1A-TH
45       \$197E-10       101       FIRE NEAR INCC FULIDMENT FAILS AGV SW-301A       62A IN BIDIESEL UE TO FIRE RESERVE AUX AGV SW-301A       GENERATOR ROOM FAILS TO OPEN       OCCURS       1.34E-03 1.00E+00       IEV-FI2 FIRE-DAMAGE 5.32E-03         46       2.75E-10       .01       FIRE NEAR INCC EQUIDMENT FAILS AGV SW-301A       62A IN BIDIESEL EQUIDMENT FAILS AGV SW-301A       GENERATOR ROOM FAILS TO OPEN       OCCURS       1.34E-03 1.00E+00       IEV-FI2 FIRE-DAMAGE 1.00E+00         46       2.75E-10       .01       FIRE NEAR INCC EQUIDMENT FAILS AFW PUMP 1A WOV INS-102       62A IN BIDIESEL UNAVAILABLE DUE TO FIRE AFW PUMP 1C       GENERATOR ROOM WAXILABLE DUE TO FIRE DUE TO FIRE AFW PUMP 1C       0.00E+00 FIRE-DAMAGE 5.40E+00       IEV-FI2 0.66HWAFW12-FM 1.00E+00         47       2.32E-17       1.3       FIRE NEAR INCC EQUIPMENT FAILS TO STOP       62A IN BIDIESEL GENERATOR ROOM       OCCURS       1.34E+03 1.34E+03 1.00E+00       IEV-FI2 36-RXCP-STOP-HE         47       2.32E-17       1.3       FIRE NEAR INCC EQUIPMENT FAILS SOV AFW-111A AFW PUMP 1C OPERATOR FAILS       62A IN BIDIESEL GENERATOR ROOM       OCCURS       1.34E+03 1.00E+00 FIRE-DAMAGE 2.00E+03       IEV-FI2 36-RXCP-STOP-HE         48       2.13E-10       .02       FIRE NEAR INCC EQUIPMENT FAILS SOV AFW-111A AEW PUMP 1C OPERATOR FAILS       62A IN BIDIESEL GENERATOR ROOM       OCCURS       1.34E+03 1.00E+00 FIRE-DAMAGE 2.00E+03       IEV-FI2 36-RXCP-STOP-HE         48 </td <td></td> <td></td> <td></td> <td>MOV MS-102</td> <td>FAILS TO OPEN</td> <td></td> <td></td> <td>7.50E-03</td> <td>06-MVMS102-CC</td>				MOV MS-102	FAILS TO OPEN			7.50E-03	06-MVMS102-CC
402.75E-10.01FIRE NEAR MCC FOULDMENT FAILS62A IN B DIESEL DUE TO FIRE FAILS TO OPENGENERATOR ROOM FAILSOCCURS1.34E-03 1.00E+00IEV-FI2 FIRE-DAMAGE402.75E-10.01FIRE NEAR MCC FOULDMENT FAILS62A IN B DIESEL DUE TO FIRE HECHANICAL OPERATOR FAILSGENERATOR ROOM FAILUREOCCURS1.34E-03 1.00E+00IEV-FI2 FIRE-DAMAGE402.75E-10.01FIRE NEAR MCC FOULDMENT FAILS62A IN B DIESEL UNAVAILABLE TO STOPGENERATOR ROOM FAILUREOCCURS1.34E-03 1.00E+00IEV-FI2 FIRE-DAMAGE422.33E-10.03FIRE NEAR MCC FOULDMENT FAILS62A IN B DIESEL UNAVAILABLE TO STOPGENERATOR ROOM REACTOR COOLANT PUMPSOCCURS1.34E-03 1.34E-03IEV-FI2 FIRE-DAMAGE432.33E-10.03FIRE NEAR MCC FOULDMENT FAILS62A IN B DIESEL DUE TO FIRE GOV AFW-111A AFK PUMP 1C ADX LUBE OIL DUE TO FIRE FAILS TO OPEN AFW-111A TO STOPOCCURS1.34E-03 FAILUREIEV-FI2 FIRE-DAMAGE 2.00E-034482.18E-10.040FIRE-MARK FAILS62A IN B DIESEL TO STOPGENERATOR ROOM PUMP MECHANICAL REACTOR COOLANT PUMPSOCCURS1.34E-03 FIRE-DAMAGE 2.00E-03IEV-FI2 SOBBM-ALOP1C-PS 3.35E-024482.18E-10.040FIRE-MARK FAILS62A IN B DIESEL TO STOPGENERATOR ROOM REACTOR COOLANT PUMP MECHANICAL FAILURE1.34E-03 FAILUREIEV-FI2 FIRE-DAMAGE 2.00E-034482.18E-10.040FIRE-MARK FAILS62A I				OPERATOR FALLS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
RESERVE AUX AOV SW-301ATRANSFORMER FAILS TO OPENFAILURE4.30E-05 S.32E-0339-TR-RATSG 02-AV-SW301A-CC462.75E-10.01FIRE NEAR MCC EQUIPMENT FAILS62A IN B DIESEL DUE TO FIREGENERATOR ROON FAILUREOCCURS1.34E-03 1.63E-02IEV-F12 FIRE-DAMAGE462.75E-10.01FIRE NEAR MCC EQUIPMENT FAILS62A IN B DIESEL UNAVAILABLEGENERATOR ROON DUE TO FIREOCCURS1.34E-03 1.63E-02IEV-F12 OSBPMAFVIA-PS470.32E-10.03FIRE NEAR MCC EQUIPMENT FAILS62A IN B DIESEL DUE TO FIREGENERATOR ROON REACTOR COOLANT PUMPSOCCURS1.34E-03 1.34E-03IEV-F12 FIRE-DAMAGE470.32E-10.03FIRE NEAR MCC EQUIPMENT FAILS62A IN B DIESEL DUE TO FIREGENERATOR ROON PUMP SOCCURS1.34E-03 1.00E+00IEV-F12 FIRE-DAMAGE482.38E-10.03FIRE NEAR MCC EQUIPMENT FAILS62A IN B DIESEL DUE TO FIREGENERATOR ROON PUMP NECHANICAL NERATOR FAILSOCCURS1.34E-03 1.00E+00IEV-F12 FIRE-DAMAGE482.38E-10.030FIRE NEAR MCC EQUIPMENT FAILS62A IN B DIESEL DUE TO FIREGENERATOR ROON PUMP NECHANICAL NEACTOR COOLANT PUMPS2.33E-0236-RXCP-STOP-HE482.38E-10.030FIRE NEAR MCC EQUIPMENT FAILS62A IN B DIESEL DUE TO FIREGENERATOR ROON PUMP SOCCURS1.34E-03 1.00E+00IEV-F12 FIRE-DAMAGE482.38E-10.030FIRE NEAR MCC EQUIPMENT FAILS62A IN B DIESEL <td>45</td> <td>5-07E+10</td> <td>.01</td> <td>FIRE NEAR MCC</td> <td>62A IN B DIESEL</td> <td>GENERATOR ROOM</td> <td>OCCURS</td> <td>1.34E-03</td> <td>IEV-FI2</td>	45	5-07E+10	.01	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-FI2
AOV SW-301AFAILS TO OPEN5.32E-0302-AV-SW301A-CC462.75E+10.01FIRE NEAR NCC EQUIPMENT FAILS62A IN B DIESEL DUE TO FIRE AFW PUMP 1A MOV MS-102GENERATOR ROOM FAILURE0CCURS1.34E+03 1.00E+00IEV-F12 FIRE-DAMAGE402.32E-10.01FIRE NEAR MCC POPERATOR FAILS62A IN B DIESEL DUE TO FIRE HECHANICAL TO STOPGENERATOR ROOM FAILURE0CCURS1.34E+03 1.63E-02IEV-F12 FIRE-DAMAGE400.32E-10.03FIRE NEAR MCC EQUIPMENT FAILS62A IN B DIESEL DUE TO FIRE DUE TO FIRE SOV AFW 111A AFW PUMP 1C DUE TO FIRE SOV AFW 111A62A IN B DIESEL DUE TO FIRE DUE TO FIRE SOV AFW 111A AFW PUMP 1C DUE TO FIRE SOV AFW 111A AFW PUMP 1C DUETO TO FIRE FOULTERED TO STOP0CCURS1.34E-03 1.00E+00 2.00E-03IEV-F12 FIRE-DAMAGE 2.00E-03482.18E 10.00FIRE NEAR MCC PUMP 1C DUETO FIRE FOULTERED TO FIRE SOV AFW 111A DUETO FIRE FAILURE62A IN B DIESEL FOULTERED FOULTERED TO FIRE REACTOR COOLANT PUMP NECHANICAL REACTOR COOLANT PUMPS0CCURS1.34E-03 SOESVAFW111A-CC SOESVAFW111A-CC SOESVAFW111A-CC SOE AFW-111A TURBINE DRIVEN DUE TO FIRE FAILUS TO OPEN TURBINE DRIVEN DEFATOR FAILS62A IN B DIESEL FOULTERED FAILS TO OPEN AFW PUMP 1C AFW PUMP 1C AFW PUMP 1C DEFATOR FAILS DE STABLISH0CCURS1.34E-03 FAILUREIEV-F12 SOECOS SOESVAFW111A-CC SOESVAFW111A-CC SOESVAFW111A-CC SOESVAFW111A-CC SOESVAFW111A-CC SOESVAFW111A-CC SOESVAFW111A-CC SOESVAFW111A-CC SOESVAFW111A-CC SOESVAFW111A-CC SOESVAFW11				FUUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
46       2,75E-10       .01       FIRE NEAR MCC EQUIPMENT FAILS       62A IN B DIESEL UNE TO FIRE AFW PUMP 1A MOV MS: 102 UNAVAILABLE TO STOP       GENERATOR ROOM FAILURE UNAVAILABLE DUE TO TEST OR REACTOR COOLANT       MAINTENANCE PUMPS       1.34E-03 1.63E-02       IEV-FI2 05BPHAFW1A-PS 06-NVHS102-TH 2.33E-02         40       0.30E-10       C.3       FIRE NEAR MCC EQUIPMENT FAILS       62A IN B DIESEL UNAVAILABLE TO STOP       GENERATOR ROOM REACTOR COOLANT       OCCURS       1.34E-03 1.63E-02       IEV-FI2 06-NVHS102-TH 2.33E-02         40       C.30E-10       C.3       FIRE NEAR MCC EQUIPMENT FAILS       62A IN B DIESEL UNAVAILABLE TO STOP       GENERATOR ROOM REACTOR COOLANT       OCCURS       1.34E-03 1.00E+00       IEV-FI2 FIRE-DAMAGE         40       C.30E-10       C.3       FIRE NEAR MCC EQUIPMENT FAILS       62A IN B DIESEL UNAVAILABLE       GENERATOR ROOM AFW PUMP IC UNAVAILABLE       OCCURS       1.34E-03 1.00E+00       IEV-FI2 7.2E-03 05BPM-ALOPIC-PS 3.6FRCP-STOP-HE         48       C.13E-10       L00       FIRE NEAR MCC UNERAFOR FAILS       62A IN B DIESEL UNAVAILABLE       GENERATOR ROOM UNAVAILABLE       OCCURS       1.34E-03 1.00E+00       IEV-FI2 7.2E-03 05BPM-ALOPIC-PS 3.6FRCP-STOP-HE         48       C.13E-10       L00       FAILS TO OPEN AFW PUMP IC UNAVAILABLE       GENERATOR ROOM AFW PUMPS       OCCURS       1.34E-03 1.00E+00       IEV-FI2 1.00E+00         48       C.13E-10 </td <td></td> <td></td> <td></td> <td>RESERVE AUX</td> <td>TRANSFORMER</td> <td>FATLURE</td> <td></td> <td>4.30E-05</td> <td>39-TR-RATSG</td>				RESERVE AUX	TRANSFORMER	FATLURE		4.30E-05	39-TR-RATSG
Bit of the bound of the bo				AOV SW-301A	FALLS TO OPEN			5.32£-0 <b>3</b>	02-AV-SW301A-CC
AFW PUMP 1A MOV MS-102 OPERATOR FAILSHECHANICAL UNAVAILABLE TO STOPFAILURE LUE TO TEST OR REACTOR COOLANTHAINTENANCE1.63E-02 5.40E-04 2.33E-02058PHAFW1A-PS 06-MVMS102-TH 36-RXCP-STOP-HE4.72.32E-171.3FIRE NEAR MCC EQUIPMENT FAILS62A IN B DIESEL DUE TO FIRE SQV AFW-111A AFW PUMP 1C AFW PUMP 1CGENERATOR ROOM AUX LUBE OIL PUMP MECHANICAL FAILS TO OPEN REACTOR COOLANTOCCURS1.34E-03 1.00E+00IEV-FI2 FIRE-DAMAGE 2.00E-03482.18E-10	46	2.758-10	.01	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	UCCURS	1.34E-03	IEV-F12
MOV MS-102 OPERATOR FAILSUNAVAILABLE TO STOPDUE TO TEST DR REACTOR COOLANTMAINTENANCE PUMPS5.40E-04 2.33E-02O6-HVMS102-TH 36-RXCP-STOP-HE4.70.32E 101.3FIRE NEAR MCC EQUIFMENT FAILS62A IN B DIESEL DUE TO FIREGENERATOR ROOM COEURSOCCURS1.34E-03 1.00E+00IEV-FI2 FIRE-DAMAGE4.82.38E 10				EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
OPERATOR FAILSTO STOPREACTOR COOLANTPUMPS2.33E-0236-RXCP-STOP-HE4.72.32E-101.3FIRE NEAR MCC62A IN B DIESELGENERATOR ROOMOCCURS1.34E-03IEV-FI24.82.02E-03OSBVAFW111AFAILSDGE TO FIREDGE TO FIRE2.00E-03OSBVAFW111A-CCAFW PUMP 1CAUX LUBE OILPUMP MECHANICALFAILURE3.72E-03OSBPM-ALOP1C-PS30ERATOR FAILSTO STOPKEACTOR COOLAMTPUMPS2.33E-0236-RXCP-STOP-HE482.18E-10.00FIRE NEAR MCC62A IN B DIESELGENERATOR ROOMOCCURS1.34E-03IEV-FI2482.18E-10.00FIRE NEAR MCC62A IN B DIESELGENERATOR ROOMOCCURS1.34E-03IEV-FI2482.18E-10.00FIRE NEAR MCC62A IN B DIESELGENERATOR ROOMOCCURS1.34E-03IEV-FI2492.18E-10.00FIRE DAMAGEDUE TO FIREDUE TO FIRE2.00E-03OSBSVAFW111A-CC50V AFW-111AFAILS TO OPENFAILS TO OPEN2.00E-03OSBSVAFW111A-CC2.00E-03OSBSVAFW111A-CC50V AFW-111AFAILS TO OPENMECHANICALFAILUREI.37E-01OSBSVAFW111A-CC50V AFW-111AFAILS TO OPENMECHANICALFAILURE1.37E-01OSBSVAFW111A-CC50V AFW-111AFAILS TO OPENMECHANICALFAILURE1.37E-01OSBSVAFW111A-CC50V AFW-10FWAFW PUMP 1CMECHANICALFAILURE1.19E-03OSA-OM2-OM4-HE50V AFW-111A<				AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PHAFW1A-PS
<ul> <li>4.7 2.32E 30</li> <li>4.8 2.32E 30</li> <li>4.9 FIRE NEAR MCC 62A IN B DIESEL GENERATOR ROOM OCCURS</li> <li>4.1 34E-03 IEV-FI2</li> <li>4.00E+00 FIRE-DAMAGE</li> <li>4.00E+03 O5BSVAFW111A-CC</li> <li>4.00E+03 O5BSVAFW111A-CC</li> <li>4.00E+04 FAILS 10 OPEN</li> <li>4.00E+04 FAILS 10 STOP</li> <li>4.00E+</li></ul>				MOV MS-102	UNAVAILABLE	DUE TO TEST OR	MAINTENANCE	5.40E-04	06-MVNS102-TM
Harring Point Fails       DUE TO FIRE       1.00E+00       FIRE-DANAGE         SOV AFW-111A       FAILS TO OPEN       2.00E-03       05BSVAFW111A-CC         AFW POMP 1C       AUX LUBE OIL       PUMP MECHANICAL       FAILURE       3.72E-03       05BPM-ALOP1C-PS         OPERATOR FAILS       TO STOP       REACTOR COOLAMT       PUMPS       2.33E-02       36-RXCP-STOP-HE         VB       2.18E-10       IOP       FIRE NEAR MCC       62A IN B DIESEL       GENERATOR ROOM       OCCURS       1.34E-03       IEV-F12         VB       2.18E-10       IOP       FIRE DIESEL       GENERATOR ROOM       OCCURS       1.00E+00       FIRE-DANAGE         VB       2.18E-10       IOP       FAILS TO OPEN       2.00E-03       05BSVAFW111A-CC         VB       IOP       FAILS TO OPEN       2.00E-03       05BSVAFW111A-CC         VB       IOP       FAILS TO OPEN       2.00E-03       05BSVAFW111A-CC         VB       SOV AFW-111A       FAILS TO OPEN       2.00E-03       05BSVAFW111A-CC         VB       SOV AFW-111A       FAILS TO OPEN       2.00E-03       05BSVAFW111A-CC         VB       VERATOR FAILS       IO ESTABLISH       MAIN FEEDWATER       FAILURE       1.37E-01       05BPTAFW1C-PS         <				OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
SOV AFW-111A       FAILS TO OPEN       2,00E-03       05BSVAFW111A-CC         AFW PUMP 1C       AUX_LUBE OIL       PUMP_MECHANICAL       FAILURE       3,72E-03       05BPM-ALOP1C-PS         OPERATOR FAILS       TO STOP       REACTOR COOLAPT       PUMPS       2,33E-02       36-RXCP-STOP-HE         OPERATOR FAILS       TO STOP       REACTOR COOLAPT       PUMPS       0CCURS       1,34E-03       1EV-F12         OPERATOR FAILS       DUE TO FIRE       SOV AFW-111A       FAILS TO OPEN       2,00E-03       05BSVAFW111A-CC         SOV AFW-111A       FAILS TO OPEN       SOV AFW-111A       FAILS TO OPEN       2,00E-03       05BSVAFW111A-CC         TURBINE DRIVEN       AFW PUMP 1C       MECHANICAL       FAILURE       1,37E-01       05BPTAFW1C-PS         OPERATOR FAILS       10 ESTABLISH       MAIN FEEDWATER       1,19E-03       05A0H2-0M4-HE	-+ , <sup>*</sup>	2.326.10	. J	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-FI2
AFW PUMP 1C AUX LUBE OIL PUMP MECHANICAL FAILURE 3.72E-03 058PM-ALOP1C-PS DEERATOR FAILS TO STOP REACTOR COOLAFT PUMPS 2.33E-02 36-RXCP-STOP-HE COULTMENT FAILS DUE TO / TRE SOV AFW-111A FAILS TO OPEN FAILS TO OPEN TURBINE DRIVEN AFW PUMP 1C MECHANICAL FAILURE 1.37E-01 058PTAFW1C-PS DEERATOR FAILS 10 ESTABLISH MAIN FEEDWATER 1.19E-03 05AOH2-OH4-HE				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
UPERATOR FAILS TO STOP REACTOR COOLART PUMPS 2.33E-02 36-RXCP-STOP-HE 48 2.18E 10 .00 FIRE NEAR MCC 62A IN B DIESEL GENERATOR ROOM OCCURS 1.34E-03 IEV-F12 EDULPMENT FAILS DUE TO / IRE SOV AFW-111A FAILS TO OPEN TURBINE DRIVEN AFW PUMP 1C MECHANICAL FAILURE 1.37E-01 058PTAFW1C-PS DPERATOR FAILS 10 ESTABLISH MAIN FEEDWATER 1.19E-03 05AON2-ON4-HE				SOV AFE-111A	FALLS TO OPEN			2.00E-03	05BSVAFW111A-CC
48       2.18E 10       100       FIRE NEAR MCC       62A IN BIDIESEL GENERATOR ROOM       OCCURS       1.34E-03       1EV-F12         2012PMENT FAILS       DUE TO FIRE       1.00E+00       FIRE-DAMAGE         SOV AFW-111A       FAILS TO OPEN       2.00E-03       05BsVAFW111A-CC         TURBINE DRIVEN       AFW PUMP 1C       MECHANICAL       FAILURE       1.37E+01       05BpTAFW1C-PS         DPERATOR FAILS       10 ESTABLISH       MAIN FEEDWATER       1.19E+03       05A+-0N2-0M4+HE				AFW PUMP 1C	AUX LUBE OIL	PUMP MECHANICAL	FAILURE	3.72E-03	058PM-ALOP1C-PS
EQUIPMENT FAILS       DUE TO FIRE       1.00E+00       FIRE-DAMAGE         SOV_AFW-111A       FAILS_TO_OPEN       2.00E-03       05BSVAFW111A-CC         TURBINE DRIVEN       AFW_PUMP_1C       MECHANICAL       FAILURE       1.37E-01       05BPTAFW1C-PS         DPERATOR_FAILS       10 ESTABULSH       MAIN_FEEDWATER       1.19E-03       05A0N2-0N4-HE				OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
EQUIPMENT FAILS       DUE TO FIRE       1.00E+00       FIRE-DAMAGE         SOV_AFW-111A       FAILS_TO_OPEN       2.00E-03       0585VAFW111A-CC         TURBINE DRIVEN       AFW_PUMP_1C       MECHANICAL       FAILURE       1.37E-01       058PTAFW1C-PS         DPERATOR_FAILS       10 ESTABULSH       MAIN_FEEDWATER       1.19E-03       05A0N2-0N4-HE	<b>-</b> B	2.18E-10	. da	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	1EV-F12
SOV AFW-111A FAILS TO OPEN 2.00E-03 0585VAFW111A-OC TURBINE DRIVEN AFW PUMP IC MECHANICAL FAILURE 1.37E-01 058PTAFW1C-PS OPERATOR FAILS 10 ESTABLISH MAIN FEEDWATER 1.19E-03 05A0N2-0N4-HE					DUE TO FIRE				
TURBINE DRIVEN AFW PUMP 1C MECHANICAL FAILURE 1.37E-01 058PTAFW1C-PS OPERATOR FAILS 10 ESTABLISH MAIN FEEDWATER 1.19E-03 05AON2-ON4-HE									058SVAFW111A-CC
				TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	05BPTAFW1C-PS
OPERATIR FATUS TO ESTABLISH BLEED AND FEED 5.00E-01 36-0820850860HE				OPERATOR FAILS	10 ESTABLISH	MAIN FEEDWATER		1.19E-03	05A0H2-0H4-HE
				CHERAT R FATES	TO ESTABLISH	BLEED AND FEED		5.00E-01	36-0820850860 HE

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 274 of 415

TABLE 4-8 F12

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 6

EVENT PROB. IDENTIFIER

Title: FI2: MCC 62A Scenario File: FIRE2.WLK ( File created by linking FIRE2.IN WLINK \*\* Ver. 3.11 \*\*) Reduced Sum of Cutsets: 4.6470E-06

#### NUMBER CUISET PROB PERCENT BASIC EVENT NAME

	• • • • • •	- •	• • • • • • • • • • • • • • • • • • • •	· · · · · · · · · · · · · · · · · · ·			· · · · <b>· · · · · · · ·</b>	
49	2.14E-10	.00	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	1EV-F12
			EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			RESERVE AUX	TRANSFORMER	FAILURE		4.30E-05	39-TR-RATSG
			TRAVELING WATER	SCREEN 1A1	HECHANICAL	FAILURE	3.72E-03	02-FLT-TW1A1-PS
50	2.09E+10	.00	FIRE NEAR NCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	1.34E-03	IEV-FI2
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BREAKER 1.503	FAILS TO CLOSE			3.00E-03	39-CB-1-503FC
			SW PUMP 1A1	MECHANICAL	FAILURE		1.40E-02	02-PN-SW1A1PS
			ROTATING	STRAINER 1A2	MECHANICAL	FAILURE	3.72E-03	02-FLR-RS1A2-PS

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 275 of 415

TABLE 4-9 F13

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 1

Title: FI3: Fine Between Buses 1 and 2 File: FIRE3.WLK ( File created by linking FIRE3.IN Reduced Sum of Cutsets: 1.4090E-09

WLINK \*\* Ver. 3.11 \*\*)

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
1	4, <b>69</b> 8 - 10	53.29	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-FI3
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			COMMON CAUSE	FAILURES OF	AFW SYSTEM		2.12E-04	058AFWCH
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
2	2.21E-10	15.68	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	1EV-F13
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-CAMAGE
			CHECK VALVE	MU-301	FAILS TO OPEN		1.00E-04	27-C1/-HU301FO
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUNPS	2.33E-02	36 RXCP-STOP-HE
3	8.52E 11	6.05	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-FI3
			EQUIPMEN: FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			COMMON CAUSE	FAILURES OF	AFW SYSTEM		2 12E-04	058AFWCM
			OPERATOR FAILS	TO STOP BOTH	RHR PUMPS		23E U3	341-RHR-STOP-HE
4	8.06E 11	5.72	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-FI3
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PMAFW1A-PS
			AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PMAFW18-PS
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
5	7.81E-11	5.54	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9,50E-05	IEV-F13
			EQUIPMENT FAILS	OUE TO FIRE			1.00E+00	FIRE-DAMAGE
			COMMON CAUSE	FAILURES OF	AFW SYSTEM		2.12E-04	058AFWCH
			OPERATOR FAILS	TO ESTABLISH	BLEED AND FEED		3.88E-03	36-082085086-HE
5	3.28E+11	2.33	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-FI3
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			COMMON CAUSE	FAILURES OF	AFW SYSTEM		2.12E-04	05BAFWCM
			COMMON MODE	FAILURE OF TRAIN	A AND B BAT TO	RWST SWITCHOVER	1.63E-03	55SYBATAB-CM
7	2.66E-11	1,99	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-FI3
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AOV MU-38	TRANSFERS OPEN			1.20E-05	03-AVMU3BCO
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
8	2,645-11	1.89	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-F13
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AOV MU-34	TRANSFERS OPEN			1.20E-05	03-AVMU3ACO
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
Ŷ	2.286-11	1.62	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-FI3
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			FEEDER BREAKERS	JN +160V BUS 5	FAIL TO OPEN		<b>→</b> . 80£ - 02	39-C8-BUS5F8-F0
			FEFOER BREAKERS	ON 4160V BUS 6	FAIL TO OPEN		4.20E-02	39-C8-BUS6F8 F0

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 276 of 415

4-9 F13	***** DOMINANT CUTSETS *****	Page:

Title: F13: Fire Between Buses 1 and 2 File: F1RE3.WLK ( File created by linking F1RE3.IN Reduced Sum of Cutsets: 1.4090E-09

TABLE

WEINK \*\* Ver. 3.11 \*\*)

Z

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAM	E			EVENT PROB.	IDENTIFIER
10	2.23E-11	158	FIRE IN BUS 1	AND BUS 2' ROOM	OCCURS		9.50E-05	1EV-F13
	6.6.96		EQUIPMENT FAILS		0000.10		1.00E+00	FIRE-DAMAGE
			LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			COMMON CAUSE	FAILURE OF BOTH		GENERATORS	1.97E-03	10-GE-DGABCM
11	1.97E-11	1.40	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-FI3
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			COMMON CAUSE	FAILURES OF	AFW SYSTEM		2.12E-04	058AFWCN
			COMMON CAUSE	FAILURE OF RHR			9.79E-04	34RHRCri
2	1,64E 11	1.16	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-FI3
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			COMMON CAUSE	FAILURES OF	AFW SYSTEM		2.12E-04	058AFWCN
			HPR UNAVAILABLE	DUE TO COMMON	CAUSE		8.14E-04	33RHPRCM
15	1.52E-11	1.08	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		2.50E-05	[EV-F13
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			CONHON CAUSE	FAILURES OF	AFW SYSTEM		2.12E-04	058AFWCM
			HPI UNAVAILABLE	DUE TO COMMON	CAUSE		7.56E-04	331HPSI-CM
14	1.46E 11	1.04	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-F13
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PMAFW1A-PS
			AFW PUMP 18	MECHANICAL	FATLURE		1.63E-02	058PNAFW18-PS
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			OPERATU: FAILS	TO STOP BOTH	RHR PUMPS		4.23E-03	341-RHR-STOP-HE
15	1.45E 11	1.03	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		. 50E - 05	IEV-FI3
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			COMMON CAUSE	FAILURES OF	AFW SYSTEM		2.12E-04	05BAFWCM
			CONTAINMENT	SUMP STRAINERS	PLUGGED		7.20E-04	34RFLSUMP-PL
15	1.34E 11	. 95	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	1EV-F13
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PHAFW1A-PS
			AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PMAFW18-PS
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	05BPTAFW1C-PS
			OPER'TOR FAILS	TO ESTABLISH	BLEED AND FEED		3.88E-03	36-082085086-HE
17	1.16E-11		FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-FI3
			EQUIPMENT FAILS		5-151-16-24 (SUDD		1.00E+00	FIRE-DAMAGE
				FOWER FROM GRID			1.19E-04	LOSP-24
			FEEDER BREAKERS		FAIL TO OPEN		4.80E.02	39-CB-BUS5FB-FO
			DIESEL GENERATOR	18	FAILURE TO START	AND RUN	2.13E-02	10-66-DG18P3
13	1,016-11		FIRE IN BUS 1		ÜCCURS		9.50E-05	IEV-F13
			EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
				FINER FROM GRID			1.19E-04	LOSP-24
			CIESEL SENERATOR		FAILURE TO START	AND RUN	2.13E-02	10-GE-DG1APS
			FELLE BRIARINS	CN 41607 805 5	THIL OUDERN		₩.20E 02	39-08-8056F8-F0

	Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 277 of 415											
TABLE 4	9 F13			••		ETS ****		Page: 3				
File: F	TRE3.WLK (	e Between Bu ( File creat utsets: 1.40	ed by Linking FIR	E3.IN WLINK	: ** Ver. 3.11 **)							
NUMBER	CUTSET PR	OB PERCENT	BASIC EVENT NAN	E			EVENT PROB.	IDENTIFIER				
19	9.89E 12	2 . 70	FIRE IN BUS 1 EQUIPMENT FAILS SOV AFW-111A AFW PUMP 1B TURBINE DRIVEN	AND BUS 2 ROOM DUE TO FIRE FAILS TO OPEN MECHANICAL AFW PUMP 1C	OCCURS FAILURE MECHANICAL	FAILURE	9.50E-05 1.00E+00 2.00E-03 1.63E-02 1.37E-01	IEV-FI3 FIRE-DAMAGE 0585VAFW111A-CC 058PMAFW18-PS 058PTAFW1C-PS				
			OPERATOR FAILS	TO STOP	REACTOR CODLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE				
50	9.89E 12	. 70	FIRE IN BUS 1 EQUIPMENT FAILS AFW PUMP 1A SOV AFW-111B TURBINE DRIVEN OPERATOR FAILS	AND BUS 2 ROOM DUE TO FIRE MECHANICAL FAILS TO OPEN AFW PUMP 1C TO STOP	OCCURS FAILURE MECHANICAL REACTOR COOLANT	FAILURE PUMPS	9.50E-05 1.00E+00 1.63E-02 2.00E-03 1.37E-01 2.33E-02	IEV-FI3 FIRE-DAMAGE O5BPMAFW1A-PS O5BSVAFW1118-CC O5BPTAFW1C-PS 36-RXCP-STOP-HE				
21	8.90( - 12	.63	FIRE IN BUS 1 EQUIPMENT FAILS AFW PUMP 1A AFW PUMP 1B TURBINE DRIVEN OPERATOR FAILS	AND BUS 2 ROOM DUE TO FIRE MECHANICAL UNAVAILABLE AFW PUMP 1C TO STOP	OCCURS FAILURE DUE TO TEST OR MECHANICAL REACTOR COOLANT	MAINTENANCE FAILURE PUMPS	9.50E-05 1.00E+00 1.63E-02 1.80E-03 1.37E-01 2.33E-02	IEV-FI3 FIRE-DANAGE OSBPNAFW1A-PS OSBPNAFW1B-TM OSBPTAFW1C-PS 36-RXCP-STOP-HE				
22	8.48E+12	.60	FIRE IN BUS 1 EQUIPMENT FAILS COMMON CAUSE COMMON CAUSE	AND BUS 2 ROOM DUE TO FIRE FAILURES OF FAILURE OF BOTH	OCCURS AFW SYSTEM LPI TRAINS		9.50E-05 1.00E+00 2.12E-04 4.21E-04	1EV-F13 F1RE-DAMAGE 05BAFWCM 341LP1CM				
23	8.25E 12	.59	FIRE IN BUS 1 EQUIPMENT FAILS LOSS OF ALL NO SERVICE WATER	POWER FROM GRID	OCCURS DURING 24 HOURS COMMON CAUSE	FAILURES	9.50E-05 1.00E+00 1.19E-04 7.30E-04	1EV-F13 F1RE-DAMAGE LOSP-24 02SWSCM				
24	6.64E 12	.47	FIRE IN BUS 1 EQUIPMENT FAILS LOSS OF CONTROL OPERATOR FAILS	AND BUS 2 ROOM DUE TO FIRE SIGNAL TO MU-3A TO STOP	OCCURS VALVE FAILS OPEN REACTOR CODLANT	PUMPS	9.50E-05 1.00E+00 3.00E-06 2.53E-02	IEV-F13 FIRE-DAMAGE 03-AS-HTLVLC-OP 36-RXCP-STOP-HE				
.">	5.82E *2		FIRE IN BUS 1 EQUIPMENT FAILS AFW PUMP 1A AFW PUMP 16 "URBINE DRIVEN OPERATOR FAILS	AND BUS 2 ROOM DUE TO FIPE UNAVAILABLE MECHANICAL AFW PUMP 1C TO STOP	OCCURS DUE TO TEST OR FAILURE MECHANICAL REACTOR COOLANT	MAINTENANCE FAILURE PUMPS	9.50E-05 1.00E+00 1.34E-03 1.63E-02 1.37E-01 2.33E-02	IEV-FI3 FIRE-DAMAGE C5BPMAFW1A-TM O5BPMAFW1B-PS 05BPTAFW1C-PS 36-RXCP-STOF HE				
25	5 fire 12	. 40	FIRE IN BUS 1 EQUIPMENT FAILS AFW PUMP 1A	AND BUS 2 ROOM OUE TO FIRE MECHANICAL	GCCURS		9.50E-05 1.00E+00 1.63E-02	IEV-FI3 FIRE-DAMAGE 058PMAFW1A-PS				

FAILURE

MECHANICAL FAILURE

FALLERE OF TRAIN A AND B BAT TO RWST SWITCHOVER 1.63E-03 55--SY--BATAB-CM

1.63E-02 058PH--AFW18-PS

1,37E-01 058PT--AFW1C-PS

MECHANICAL

.

LABINE ORIVEN AFW PUMP 10

AFW PUMP 18

OMMON MODE

Enclo	osure - Q8	&A to Attach	nment 1 Vol	ume 05 (Se	ction 3.0) Pa	age 278 c	of 415
TABLE 4-9 FI3			***	*** DOMINANT CUTS	ETS ****		Page: 4
File: FIRE3.WL	are Between Bu K ( File creat Cutsets: 1.40	ed by Linking F1R	E3.IN WLINK	** Ver. 3.11 **)			
NUMBER CUTSET	PROB PERCENT	BASIC EVENT NAMI	E			EVENT PROB.	IDENTIFIER
27 5.56E	12 . 38	FIRE IN BUS 1 EQUIPMENT FAILS COMMON CAUSE AUXILIARY BLDG	AND BUS 2 ROOM DUE TO FIRE FAILURES OF BASEMENT COOLING	OCCURS AFW SYSTEM 5 FAILS DUE TO	N CAUSE	9.50E-05 1.00E+00 2.12E-04 2.66E-04	IEV-F13 F1RE-DAMAGE 05BAFWCM 17-SY-ABBCCM
28 5.13E	12 .36	FIRE IN BUS 1 EQUIPMENT FAILS LOSS OF ALL DIESEL GENERATOR DIESEL GENERATOR	POWER FROM GRID	OCCURS DURING 24 HOURS FAILURE TO START FAILURE TO START		9.50E-05 1.00E+00 1.19E-04 2.13E-02 2.13E-02	IEV-F13 FIRE-DAMAGE LOSP-24 10-GE-DG1APS 10-GE-DU18PS
29 4.41E	12 .31	FIRE IN BUS 1 EQUIPMENT FAILS AFW PUMP 1A AFW PUMP 1B MOV MS 102 OPERATOR FAILS	AND BUS 2 ROOM DUE TO FIRE MECHANICAL MECHANICAL FAILS TO OPEN TO STOP	OCCURS FAILURE FAILURE REACTOR COOLANT	PUMPS	9.50E-05 1.00E+00 1.63E-02 1.63E-02 7.50E-03 2.33E-02	1EV-F13 F1RE-DAMAGE 05BPHAFW1A-PS 05BPHAFW1B-PS 06-HVMS102-CC 36-RXCP-STOP-HE
30 5.67E -	12 .26	FIRE IN BUS 1 EQUIPMENT FAILS COMMON CAUSE BLEED AND FEED	AND BUS 2 ROOM DUE TO FIRE FAILURES OF FAILS DUE TO	OCCURS AFM SYSTEM COMMON CAUSE	FAILURES	9.50E-05 1.00E+00 2.12E-04 1.82E-04	IEV-FI3 FIRE-DAMAGE 058AFWCM 36082CM
3 5. SVE	12 .24	FIRE IN BUS 1 EQUIPMENT FAILS AFW PUMP 1A AFW PUMP 1B TURBINE DRIVEN COMMON CAUSE	AND BUS 2 ROOM DUE TO FIRE MECHANICAL MECHANICAL AFW PUMP 1C FAILURE OF RHR	OCCURS FAILURE FAILURE MECHANICAL	FAILURE	9.50E - 05 1.00E + 00 1.63E - 02 1.63E - 02 1.37E - 01 9.79E - 04	1EV-F13 FIRE-DAMAGE OSBPMAFW1A-PS OSBPMAFW1B-PS OSBPTAFW1C-PS 34RHRCM
32 5.04F	12 .72	FIRE IN BUS 1 EQUIPMENT FAILS COMMON CAUSE COMMON MLOE	AND BUS 2 ROOM DUE TO FIRE FAILURES OF FAILURE OF TRAIN	OECURS AFW SYSTEM A AND TRAIN B		9,50E-05 1.00E+00 2.12E-04 1.51E-04	1EV-F13 F1RE-DANAGE U5BAFWCM 55SYS1AB-CM
33 2 PVE	12 - S	FIRE IN BUS 1 EQUIPMENT FAILS LOSS OF ALL FEEDER BREAKERS ADV SW 3018	POWER FROM GRID	OCCURS UURING 24 HOURS FAIL TO OPEN		9.50E-05 1.00E+00 1.19E-04 4.80E-02 5.32E-03	IEV-F13 F1RE-DAMAGE LOSP-24 39-CB-BUS5FB-F0 02-AV-SWI01B-CC
54 2 Bit	12 .20	FIRE IN BUS 1 EQUIPMENT FAILS AFW PUMP 1A AFW PUMP 1B TURBINE DRIVEN HPR UNAVAILABLE	MECHANICAL MECHANICAL AIW PUMP IC	OCCURS FAILURE FAILURE MECHANICAL CAUSE	FAILURE	9.50E-05 1.00E+00 1.63E-02 1.63E-02 1.37E-01 8.14E-94	IEV-FL3 FIRE-DANAGE 058PMAFW1A-PS 058PMAFW18-PS 058PTAFW1C-PS 33RHPRCM
35 2.616	.5 <i>1</i> 9	FIRE IN BUS 1 EQUIPMENT FAILS		OCCURS		♀.50E÷05 1.00E+00	IEV-FI3 FIRE-DAMAGE

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 279 of 415

TABLE 4-9 FT3

q

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

WLINK \*\* Ver. 3.11 \*\*,

Page: 5

Title: F13: Fire	Between Buses	
File: F.HE3.WLK (	File created by	, FIRE3.IN
Reduced Sum of Cu	tsets: 1.4090E-09	

NUMBER	CUTSET PROB	PERCENT	BASIC	EVENT N	IAME

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAM	E			TVENT PROB.	IDENTIFIER
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PNAFW1A-PS
			AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PMAFW18-PS
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			HPI UNAVAILABLE	DUE TO COMMON	CAUSE		7.56E-04	331HPSI-CM
. 36	2.53E-12	. 18	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-FI3
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			AOV SH-301A	FAILS TO OPEN			5.32E-03	02-AV-SW301A-CC
			FEEDER BREAKERS	ON 4160V BUS 6	FAIL TO OPEN		4.20E-02	39-CB-BUS6FB-FO
37	2.498-12	. 18	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-FI3
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	05BPHAFW1A-PS
			AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	05BPNAFW18-PS
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			CONTAINMENT	SUMP STRAINERS	PLUGGED		7.20E-04	34RFLSUMP-PL
58	2.19E-12	. 16	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	1EV-F13
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURF		1.63E-02	058PMAFW1A-PS
			AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PMAFW18-PS
			AFW PUMP 1C	AUX LUBE OIL	PUMP MECHANICAL	FAILURE	3.72E-03	058PN-ALOP1C-PS
			OPERATOR FAILS	TO STOP	REACTOR COOLANT	PUMPS	2.33E-02	36-RXCP-STOP-HE
39	2.02E-12	. 14	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	1EV-F13
			EL'HEPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			LOSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			FEEDER BREAKERS	GN 4160V BUS 5	FAIL TO OPEN		4.80E-02	39-CB-BUS5FB-FÖ
			TRAVELING WATER	SCREEN 182	MECHANICAL	FAILURE	3.72E-03	02-FLT-TW182-PS
чU	1.79E-12	. 13	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	1EV-F13
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			SL- AFW-111A	FAILS TO OPEN			2.00E-03	D5BSVAFW111A-CC
			AF# PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PHAFW18-PS
				AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			OPERATOR FATUS	TO STOP BOTH	RHR PUMPS		4.23E-03	341 - RHR - STOP - HE
1	1.796-12	• 3	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	LEV-F13
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MÉCHANICA	FAILURE		1.63E-02	058PMAFW1A-PS
			50V AFW-1118	FAILS TO OPEN			2.00E-03	0585VAFW1118-CC
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PT AFUIC-PS
			OPERATOR FAILS	TO STOP BOTH	RHR PUMPS		4.23E-03	341-RHR-STOP-HE
42	1.77E 12	.13	FIRE IN BUS 1	AND BUS 2 ROOM	OCCURS		9.50E-05	IEV-F13
			EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			:055 OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
			TRAVELLIG WATER		RECHANICAL	FAILURE	3.72E-03	02-FLT-TW1A1-PS
			FEESER BREAKERS	ON 4160V BUS 6	FAIL TO OPEN		4.20E-02	39-CB-BUS6FB-FO

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 280 of 415

TABLE 4-9 FI3

Title: FI3: Fire Between Buses 1 and 2

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 6

File: FIRE3.WLK ( File created by linking FIRE3.1W WLINK \*\* Ver. 3.11 \*\*) Reduced Sum of Cutsets: 1,4090E-09 EVENT PROB. IDENTIFIER NUMBER CUTSET PROB PERCENT BASIC EVENT NAME . . . . . . . . . . . . . . . . . 1EV-F13 9.50E-05 AND BUS 2 ROOM OCCURS 1.75E-12 12 FIRE IN BUS 1 43 1.00E+00 FIRE-DAMAGE FOULPMENT FALLS DUE TO FIRE 05RPM--AFU1A-PS 1.63E-02 FAILURE MECHANICAL AFU PUMP 1A 058PH--AFW18-PS 1.638-02 AFM PUMP 18 MECHANICAL FAILURE 058PH--AFW1C-TH 3.00E-03 DUE TO TEST OR MAINTENANCE UNAVAILABLE AFW PUMP 1C 2.33E-02 36-RXCP-STOP-HE PUMPS REACTOR COOLANT TO STOP OPERATOR FAILS IEV-FI3 9.50E-05 OCCURS 12 FIRE IN BUS 1 AND BUS 2 ROOM 1.65E-12 es la FIRE-DAMAGE 1.00E+00 FOUIPMENT FAILS DUE TO FIRE 05BSVAFW111A-CC 2.00E-03 FALLS TO OPEN SOV AFM-111A 1.63E-02 058PM--AFW18-PS FAILURE AFM PUMP 18 MECHANICAL 1.37E-01 058PT--AFW1C-PS FAILURE MECHANICAL AFH PLIMP 1C TURBINE DRIVEN 36-082085086-HE 3.88E-03 BLEED AND FEED OPERATOR FAILS TO EST SLISH 9 50F-05 1EV-F13 12 FIRE IN BUS 1 AND BUS 2 ROOM OCCURS 45 1.65E-12 FIRE-DAMAGE 1 00E+00 EQUIPMENT FAILS DUE TO FIRE 1.63E-02 058PH--AFW1A-PS FAILURE AFU PUMP 1A MECHANICAL 05RSVAEW1118-CC 2.00E-03 FAILS TO OPEN SOV AFW-1118 056PT--AFW1C-PS 1.37E-01 **MECHANICAL** FAILURE AFW PUMP 1C TURBINE DRIVEN 36-082085086-HE 3.888-03 BLEED AND FEED TO ESTABLISH OPERATOR FAILS JEV-FI3 9.50E-05 OCCUPS. AND BUS 2 ROOM 1 638-12 12 FIRE IN BUS 1 46 1 00F+00 FIRE-DAMAGE DUE TO EIRE EQUIPMENT FAILS 1.19E-04 1058-24 DURING 24 HOURS POWER FROM GRID LOSS OF ALL 39-CB-BUS5FB-FO 4.80E-02 FEEDER BREAKERS ON 4160V BUS 5 FAIL TO OPEN 40-C8-620/A6-FC 3.00E-03 FAILS TO CLOSE BREAKER FROM MCC-620 9.50E-05 1EV-F13 12 FIRE IN BUS 1 AND BUS & ROOM OCCURS 1.53E 12 41 1.00E+00 FIRE-DAMAGE FOULPMENT FAILS DUE TO FIRE LOSP-24 1.19E-04 POWER FROM GRID DURING 24 HOURS LOSS OF ALL 39-CB-BUS5FB-FO 4.80E-02 FAIL TO OPEN FEEDER BREAKERS ON 4160V BUS 5 39-C8-1-601--FC 3.00E-03 FALLS TO OPEN BREAKER 1-601 1EV-F13 9.50E-05 OCCURS AND BUS 2 ROOM 48 1.63E-12 12 FIRE IN BUS 1 1.00E+00 FIRE-DAMAGE FOULPMENT FAILS DUE TO FIRE 105P-74 DURING 24 HOURS 1.19E-04 POWER FROM GRID LOSS OF ALL 4.80E-02 39-CB-BUS5FB-FO FEEDER BREAKERS ON 160V BUS 5 FAIL TO OPEN 39-CB-1-603--FC 3.00E-03 BREAKER 1-603 FAILS TO CLOSE 9.50E-05 1EV-F13 AND BUS 2 ROOM OCCURS . 1 FIRE IN BUS 1 1.628-12 49 FIRE-DAMAGE 1.00E+00 EQUIPMENT FAILS DUE TO FIRE 058PH--AFW1A-PS 1.63E-02 AFW PUMP TA MECHANICAL FATLURE 058PN -- AFW18 - TH 1.80E-03 DUE TO TEST OR MAINTENANCE AFW PUMP 18 UNAVAILABLE 058PT -- AFW1C-PS 1.378-01 FAILURE AFW PUMP 1C MECHANICAL TURBINE DRIVEN 341-RHR-STOP-HE RHR PUMPS 4.23E-03 TO STOP BOT OPERATOR FAILS 9.50E-05 1EV-F13 11 FIRE IN BUS 1 AND BUS 2 ROOM OCCURS 50 1 4BE 12 FIRE-DAMAGE 1.00E+00 DUE TO FIRE EQUIPMENT FAILS 356PH -- AFWIA-PS 1.638-02 AFW PUMP 1A MECHANICAL FALLURE 1.80F-03 058PH--AFW18-TH DUE TO TEST OR MAINTENANCE AFH PIMP 15 UNAVAILABLE

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 281 of 415

ABLE 4-9 FI3		*	**** DOMINANT CUT	SETS ****		Page: 7		
Title: FJ3: Fire Between Buses 1 and 2 File: FJRE3.WLK ( File created by linking FIRE3.IN WLINK ** Ver. 3.11 **) Reduced Sum of Cutsets: 1,4090E-09								
NUMBER CUTSET PROB PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER		
	TURBINE DRIVEN OPERATOR FAILS	AFW PUMP 1C TO ESTABLISH	MECHANICAL BLEED AND FEED	FAILURE	1.37E-01 3.88E-03	058PTAFW1 36-082085084		

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 282 of 415

TABLE 4-10 F14

Title: FI4: Diesel B Fire

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Parje: 1

JMBE R	CUTSET PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
							8.92E-03	IEV-FI4
1	1.11E-06	14.91	B DIESEL	GENERATOR OIL	FIRE OCCURS		1,00E+00	FIRE-DAMAGE
			EQUIPMENT FAILS				1.21E-02	35CHPH
			OPERATOR FAILS	TO START ONE	CHARGING PUMP		1.03E-02	31-PNCCW1A-F
			CCW PUMP A	MECHANICAL	FAILURE		1.052 02	•••••
2	4.028 07	5 60	B DIESEL	GENERATOR OIL	FIRE OCCURS		8,925-03	1EV-F14
٤	4.022 01	2.10	EQUIPMENT FAILS				1,00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO START ONE	CHARGING PUNP		1.21E-02	35CHPI
			TRAVELING WATER	SCREEN 1A1	MECHANICAL	FAILURE	3.72E-03	02-FLT-TW1A1-1
,	7 3/1 07	/ 75	B DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	IEV-FI4
3	3.24E 07	4.00	EQUIPMENT FAILS		71R2 000000		1,00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO START ONE	CHARGING PUMP		1.21E-02	35CHPI
			BREAKER FROM	MCC-52D	FAILS TO CLOSE		3.00E-03	40-CB-520/A6-
							8.92E-03	1EV-514
4	2.14E-07	2.87	8 DIESEL EQUIPMENT FAILS	GENERATOR OIL	FIRE OCCURS		1.00E+00	FIRE-DAMAGE
			BREAKER FROM	BUS BRA-102 TO	BUS BRA-104	TRANSFERS OPEN	2.40E-05	38-CBA102-04-
							0.025-03	IEV-FI4
5	2.14E-07	2,87	B DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03 1.00E+00	FIRE-DAMAGE
			EQUIPMENT FAILS BREAKER 15201	DUE TO FIRE TRANSFERS OPEN			2.40E-05	40-CB15201-
			DREARER TIEV					
6	2.14E-07	2.87	B DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	IEV-FI4
			QUIPMENT FAILS				1.00E+00	FIRE-DAMAGE 39-CB1-505-
			TRANSFORMER	SUPPLY BREAKER	1-505	TRANSFERS OPEN	2.406-05	JF CD   909 .
7	2.052 17	2.75	8 DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	IEV-FI4
			EQUIPMENT FAILS	DUE TO FIRE			1.002:00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PHAFW1A-I
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-
			CCW PUMP A	MECHANICAL	FAILURE		1.03E-02	31-PH-+CCW1A-I
8	1.73E-07	2 32	B DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	IEV-FI4
0	1,132 01	6.90	EQUIPMENT FAILS				1,00E+00	FIRE-DAMAGE
			TRANSFORMER	1-52	FAILURE		1.94£ 05	40-TR1-52
	1 00 07	a .a		GENERATOR OIL	FIRE OCCURS		8.92E-03	IEV-FI4
Ŷ	1,49E 07	¢11	B DIESEL EQUIPMENT FAILS		The occord		1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.638-02	058PMAFW1A-I
			LRBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-I
			M V SI GA	FAILS TO OPEN			7.50E-03	331NVSI4A-1
• •	و د مر ا	<b>1</b> 00		UENERATOR OIL	FIRE OCCURS		8.92E 03	IEV-FI4
۰'	1.49E 07	2,00	B DIESEL FOUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1,63E-02	OSBPHAFW1A-
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-I
			MOV REAL	FALLS TO OPEN			7,508-03	331HVS12A-

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 283 of 415

TABLE 4-10 F14

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 2

Title: FI4: Diesel & Fire File: FIRE4.WEK ( File created by Linking FIRE4.IN Reduced Sum of Cutsets: 7.4440E-06

WLINK \*\* Ver. 3.11 \*\*)

NUMBE R	CUISET PRO	B PERCENT	BASIC EVENT NAM	E			EVENT PROB.	IDENTIFIER
			· · · · · · · · · · · · · · · · · · ·	• • • • • • • • • • • • • • • • • • • •		••••••••	· · · · · · · · · · · · · · · · · · ·	
11	1 49E 07	2.00	8 DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	1EV-F14
			EQUIPMENT FAILS	DUE TO FIRE			1.J0E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PHAFW1A-PS
			FURBLNE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			MOV ST-350A	FAILS TO OPEN			7.50E-03	34RMV-\$1350A-CC
12	1.49E 07	2.00	B DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	IEV-FI4
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP TA	MEUHANICAL	FAILURE		1.63E-02	058PMAFW1A-PS
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			MOV SE 351A	FAILS TO OPEN			7.50E-03	34RMV-S1351A-CC
13	1.49E 07	2.00	B DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	IEV-FI4
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PMAFW1A-PS
			TURBINE DRIVEN	AFW PUMP 1C	HECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			MOV CC 400A	FALLS TO OPEN			7.50E-03	34RHV-CC400A-CC
34	1.49E 07	2.00	B DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	IEV-FI4
			FQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FALLURE		1.63E-02	058PHAFW1A-PS
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			MOV RHR 300A	FAILS TO OPEN			7.50E-03	33RMVRHR300A-FO
15	1.42E-07	1,91	B DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	1EV-F14
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PMAFW1A-PS
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			COMPRESSOR 1A	MECHANICAL	FAILURE		8.44E-02	01-PM-SIAC1A-PS
			COMPRESSOR 1C	MECHANICAL	FAILURE		8.44E-02	01-PN-SIACIC-PS
16	9.74E-08	۰.31	8 DIFSEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	1EV-F14
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			NO CHARGING FLOW	DUE TO	COMMON CAUSE	FAILURES	1.06E-03	35СНРСМ
			CCW PUMP A	MECHANICAL	FAILURE		1.03E-02	31-PMCCW1A-PS
۰.	2 LHE 68	1 27	B DIESEL	SENERATOR OIL	FIRE OCCURS		8.928-03	IEV-F14
			EQUIPMENT FAILS	CLAE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW HUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PMAFW1A-PS
			TURBINE DRIVEN	AFW PUMP 10	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			M-17 53 5A	FAILS TO CLOSE			⊶.76E-03	33RMV\$15A-FC
18	8 -3E 08	1.15	8 DILJEL	GENERATOR OLL	FIRE OCCURS		8.92E-03	IEV FI4
			EQUIPMENT FALLS				1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PMAFW1A-PS
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FALLURE	1.37E-01	058PTAFW1C-PS
			SPERATOR FALLS	12 STOP BOTH	RHR PUMPS		4.23E 03	341-RHR-STOP-HE
۰,	* 38E+38		8-01626	JENERATOR OIL	FIRE OCCURS		8.928-03	IEV-F14
			EOFTENENT ENTRES	CIE TO FIRE			1.00F+00	FIRE DAMAGE

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 284 of 415 \*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\* TABLE 4-10 F14 Page: 3 Title: FI4: Diesel 8 Fire File: FIRE4.WLK ( F - - created by linking FIRE4.IN WLINK \*\* Ver. 3.11 \*\*) Reduced Sum of Cutsets: 7.4440E-06 NUMBER CUISET PROB PERCENT BASIC EVENT NAME EVENT PROB. IDENTIFIER ......... . . . . . . . 35--CHP-----HE OPERATOR FAILS TO START ONE CHARGING PUMP 1.21E-02 02----SWS----CM NO SERVICE WATER DUE TO COMMON CAUSE FAILURES 7.30E-04 20 7.73E-08 1.04 B DJESEL GENERATOR OIL FIRE OCCURS 8.92E-03 IEV-FI4 EQUIPMENT FAILS DUE TO FIRE 1.00E+00 FIRE-DAMAGE AFM PUMP TA MECHANICAL AL URE 1.63E-02 058PM--AFW1A-PS MECHANICAL FAILURE 1.37E-01 058PT -- AFW1C-PS TURBINE DRIVEN AFM PUMP 1C 36-082085086-HE OPERATOR FAILS TO ESTABLISH BLEED AND FEED 3.88E-03 IEV-FI4 21 7.41E 08 1.00 B DIESEL GENERATOR OIL FIRE OCCURS 8.92E-03 OUE TO FIRE 1.00E+00 FIRE-DAMAGE EQUIPMENT FAILS AFW PUMP 1A FAILURE 1.63E-02 058PM--AFW1A-PS MECHANICAL AFW PUMP 1C 1.37E-01 058PT--AFW1C-PS TURBINE DRIVEN MECHANICAL FAILURE 02-FLT-TW1A1-PS TRAVELING WATER SCREEN 1A1 MECHANICAL FAILURE 3.72E-03 22 5.98E-08 .80 B DIESEL GENERATOR OIL FIRE OCCURS 8.92E-03 1EV-F14 EQUIPMENT FAILS DUE TO FIRE 1.00E+00 FIRE-DAMAGE AFW PUMP 1A MECHANICAL FAILURE 1.63E-02 058PM--AFWIA-PS 1.37E-01 058PT--AFW1C-PS TURBINE DRIVEN AFW PUMP 1C MECHANICAL FAILURE BREAKER FROM MCC-52D FAILS TO CLOSE 3.00 -03 40-C8-52D/A6-FC GENERATOR OIL FIRE OCCURS 8.92E-03 IEV-F14 23 5.84E-08 .78 B DIESEL EQUIPMENT FAILS DUE TO FIRE 1.00E+00 FIRE-DAMAGE AFY PUMP 1A MECHANICAL FAILURE 1.63E-02 J58PH--AFW1A-PS 1.37E-01 058PT--AFW1C-PS TURBINE DRIVEN AFW PUMP 1C MECHANICAL FAILURE -NOT-TRAIN B UNAVAILABLE DUE TO TEST OR MAINTENANCE 2.94E-03 -55--SY-ESFTRB-TM TRAIN A UNAVAILABLE DUE TO TEST OR MAINTENANCE 2.946-03 55--SY-ESFTRA-TH 24 5.10E-08 .69 8 DIESEL GENERATOR OIL FIRE OCCURS 8.92F-03 1EV-F14 EQUIPMENT FAILS 1.00E+00 FIRE-DAMAGE DUE TO FIRE POWER FROM GRID LOSS OF ALL DURING 24 HOURS 1.19E-04 LOSP-24 FEEDER BREAKERS ON 4160V BUS 5 FAIL TO OPEN 4.80E-02 39-CB-BUS5FB-FO 25 4 86E 08 .65 B DIESEL GENERATOR OLL FIRE OCCURS 8.92E-03 **IEV-F14** 1.00E+00 FIRE-DAMAGE EQUIPMENT FAILS DUE TO FIRE AFW PUMP TA MECHANICAL FAILURE 1.63E-02 OSBPE--AFW1A-PS TURBINE CRIVEN AFW PUMP 10 MECHANICAL FAILURE 1.37E-01 058PT--AFW1C-PS AIR COMPRESSORS FAIL DUE TO COMMON CAUSE 2.44E-03 01-PM-TASP---CN 4.79E 08 GENERATOR OIL FIRE OCCURS 8.92E-03 1EV-F14 26 .6- B DIESEL EQUIPMENT FAILS DUE TO FIRE 1.00E+00 FIRE-DAMAGE OPERATOR FAILS TO START ONE CHARGING PUMP 1.21E-02 35--CHP----HE 55--RE-TOBS85-RF FAILURE OF TIME DELAY RELAY TDR-BLS/85 4.44E-04 27 4.12E\_08 .55 B DIESEL GENERATOR OIL FIRE OCCURS 8.92E-03 IEV-FI4 EQUIPMENT FAILS DUE TO FIRE 1.00E+00 FIRE-DAMAGE AFU PLIMP 1A MECHANICAL FAILURE 1.63E-02 058PM--AFW1A-PS TURBINE DRIVEN AFW PUMP 1C MECHANICAL FAILURE 1.37E-01 058PT--AFW1C-PS

AND RUN

2.07E-03

338PH --- SI \* A-PS

FAILS TO START

ST PHAR TA

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 285 of 415

TABLE 4-10 F14

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 4

#### 

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
		· • • • •	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·				
			D. D. C.C.	GENERATOR OIL	FIRE OCCURS		8.92E-03	1EV-F14
28	3.98E-08	در.	B DIESEL		THE OCCORD		1.00E+00	FIRE-DAMAGE
			EQU. PMENT FAILS	NECHANICAL	FAILURE		1.63E-02	058PMAFW1A-PS
			AFW PUMP TA	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			TURBINE ORIVEN		FAILS TO OPEN		2.00E-03	17-AVCV31746-CC
			SW CONTROL VALVE	AUY 31740	TRIES TO OFEN			
29	3.98E-08	53	B DIESEL	GENERATOR OIL	FIRE OCCURS		8,92E-03	IEV-FI4
<i>C</i> <b>?</b>	)		EUUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	NECHANICAL	FAILURE		1.63E-02	058PMAFW1A-PS
			TURBINE DRIVEN	AFW PUMP 1C	NECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			SW CONTROL VALVE		FAILS TO OPEN		2.00E-03	17-SVSV33313-CC
					CIDE OCCURS		8,92E-03	IEV-FI4
30	3.98E US	.53	B DIESEL	GENERATOR OIL	FIRE OCCURS		1.00E+00	FIRE-DAMAGE
			EQUIPMENT FAILS		C 4 2 4 10 F		1.63E-02	058PNAFU1A-PS
			AFW PUMP 1A	NECHANICAL	FAILURE	FAILURE	1.37E-01	058PTAFW1C-PS
			FURBINE DRIVEN	AFW PUMP TC	MECHANICAL	A SCORE	2.00E-03	3485VSW1211A-CC
			SOV SW-1211A	FAILS TO OPEN			2.000 00	
		. 0		GENERATOR OLL	FIRE OCCURS		8.92E-03	1EV-F14
51	5.56E-08	. +0	B DIESEL EQUIPMENT FAILS				1,00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO START ONE	CHARGING PUMP		1,21E-02	35CHPHE
			BOTH CCW PUMPS	FAIL DUE TO	LOSS OF OFFSITE	POWER	3.30E-04	31-PM-CCW1AB-CH
			BOTH CCW FORFS					
52	3.52E 08	.47	B DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	IEV-FI4
26	J. J.C. 00	• • •	EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			NO CHARGING FLOW		CONMON CAUSE	FAILURES	1.06E-03	35CHPCM
			TRAVELING WATER		MECHANICAL	FAILURE	3.72E-03	02-FLT-TW1A1-PS
		. 5	0.015551	GENERATOR OIL	FIRE OCCURS		8.92E-03	IEV-F14
53	3.33E 08	.45	B DIESEL		THE OUGOND		1.00E+00	FIRE-DAMAGE
			EQUIPMENT FAILS		FAILURE		1.63E-02	058PHAFW1A-PS
			AFW PUMP 1A	MECHANICAL AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
			TURBINE DRIVEN RHR PUMP 1A	FALLS TO START	AND RUN		1.67E-03	34RPMRHR1A-PS
								· ··· · · · · · · ·
5	5.25E 08	4	8 DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	IEV-FI4
			EQUIPMENT FALL.	QUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANECAL	FAILURE		1.63E-02	058PMAFW1A-PS
			TURBINE DRIVEN	AFV PUMP 1C	MECHANICAL	FAILURE	1,37E-01	058PTAFW1C-PS
			COMMON MODE	FAILURE OF TRAIN	A AND B BAT TO	RWST SWITCHOVER	1.63E-03	55SYBATAB-CM
34.	3 11E 08	· ·	8 DIESEL	JENERATOR OIL	FIRE OCCURS		8.926-03	IEV-FI4
) ·	3 <b>L</b> . ()	••	EUGIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			AFW PUMP TA	MECHANICAL	FAILURE		1.63E-02	058PHAFW1A-PS
			T. REINE ORLVEN	AFW PUMP 1C	MECHANICAL	FATLURE	1.37E-01	058PTAFW1C-PS
			SI FUMP 14	FAILS TO START	AND RUN		1.56E-03	331PHSI1A-PS
		3.3	9 DITCC:	CLARDATOD OT	FIRE OCCURS		8.92E-03	1EV-F14
35	2 - 31 - 48		B DIFSEL For ifment fails	GENERATOR OIL	the bocons		1,00E+00	FIRE-DAMAGE
			REALER 15206	TRANSFERS OPEN			2.40E-05	40-CB15206-CO
			TURBENE ORIVEN	AFW PUMP 10	MECHANICAL	FALLURE	1.37E 01	058PT-AFW1C-PS
			CADINE CARES	an mar an				

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 286 of 415

LEGLE 4-10 FI4

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

WLINK \*\* Ver. 3.11 \*\*)

Page:

5

Title: FI4: Diesel B Fire File: FIRE4.WLK ( File created by Linking FIRE4.IN Reduced Sum of Cutsets: 7.4440E-06

NUMBER	CUTSET	PR08	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
					GENERATOR OIL	FIRE OCCURS		8.92E-03	1EV-F14
37	2.84E	98	. 58	B DIESEL EQUIPMENT FAILS		THE OCCORD		1.00E+00	FIRE-DAMAGE
				NO CHARGING FLOW		COMMON CAUSE	FAILURES	1.06E-03	35CHPCM
				BREAKER FROM	HCC-52D	FAILS TO CLOSE		3.00E-03	40-CB-52D/A6-FC
58	2.83F	ú.Я	38	8 DIESEL	GENERATOR DIL	FIRE OCCURS		8.92E-03	1EV-F14
,,,	2.03			EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				AFW PUMP TA	MECHANICAL	FAILURE		1.63E-02	058PM- AFW1A-PS
				URBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
				RHR PUMP 1A	FAILS TO START	AND RUN		1.42E-03	341PMRHR1A-PS
39	2.52E-	08	. 54	B DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	1EV-F14
				EQUIPMENT FALLS	DUE TO FIRE			1 00E+00	FIRE-DAMAGE
				SUV AFN 111A	FALLS TO OPEN		-	2.00E-03	05BSVAFW111A-CC
				TURBINE ORIVEN	AFW PUMP 1C	MECHANICAL	F#**LURE	1.37E-01	058PTAFW1C-PS
				CCW FUMP A	MECHANICAL	FAILURE		1.0 <b>3E</b> -02	31-PHCCW1A-PS
				0.015-5	CENERATOR OU	FIRE OCCURS		8.92F-03	1EV-F14
46	) - F	-, <b>8</b>	52	8 DIESEL	GENERATOR OIL	FIRE OLCURS		1.00E+00	FIRE-DAM*GE
				TOUTPMENT FAILS RECIEF VALVE	CVC-101A	FAILS TO CLOSE		1.608-02	35-AMCVC101A-FC
				RELIEF VALVE	CVC-101C	FALLS TO CLOSE		1.60E-02	35-ANCVC101C FC
				CCW PUMP A	MECHANICAL	FALLURE		1.03E-02	31-PNCCW1A-PS
	2.26E	. a	₹/)	e diesel	GENERATOR OIL	FIRE OCCURS		8.92E-03	IE FI4
41	7.700	11.5		EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
				OSS OF ALL	POWER FROM GRID	DURING 24 HOURS		1.19E-04	LOSP-24
				DIESEL GENERATOR	1.4	FAILURE TO START	AND RUN	2.13E-02	10-GE-DG1APS
-2	2.17F	.18	.29	B DIESEL	GENERATOR OIL	FIRE OCCURS		8.92E-03	IEV-F14
••		-		EGETEMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				AFW PUMP TA	MECHANICAL	FATLURE		1.036-02	058PM-TAR#IA PS
				" RBINE GRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	05BPTAFW1C-PS
				RHR TRAIN A IN	TESTUMAINTENANCE			1.09E-03	341 - RHRTRNA-TH
	i th€	~ <u>8</u>	. 'Q	8 UTESEL	UENERATOR 01.	FIRE OCCURS		8.92E 03	1EV-F14
.,				FOULPMENT FALLS	JE TO HIRE			1.CJE+00	FIRE-DAMAGE
				AFW PUMP 1A	MECHANICAL	FATUURE		1.63E-02	058PMAFW1A-PS
				1 WHINE RIVEN	AFW PUMP 10	MECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
				MI LWA ' N	AL 528 FALLS			1.088-03	55ADPC628-FA
مه او	2 1.4	28	14	5 Get sta	LARATOR CLL	FILE OCCURS		8.92E-03	IEV FI4
				MENT HALLS	CUE TO FIRE			1.00E+00	FIRE-DAMAGE
				1,542 - 455	BRA-104	FAILURE		2.49E-06	38-85 BRA104-SG
ч <sup>1</sup> 1	2 Set	9.	29	8 minste	JENERATOR OUT	FIRE OCCURS		5.92E-03	IEV-FI4
				EQUIPMENT FAILS	DUE TO FIRE			•.00E+00	FIRE-DAMAGE
				125x1. BUS	BRA 102	FAL: RE		2.40E-06	38-85-8RA102-5G
42	€	.8	<b>`</b> \$	B. MERE	ENERATOR OL.	FIRE DECLAS		9.92E-03	LEV-F14
	-			ELECTIMENT FALLS				1.90E+00	FIRE-DAMAGE

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 287 of 415

#### TABLE 4-10 FI4

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

NUMBER	CUTSET	PROB	PERCENT	BASIC EVENT NAME	:		EVENT PROB.	IDENTIFIER
				805 5	FAILURE		2.40E · UU	39-85-8US5SG
ц. <sup>*</sup>	2.14E	68	. 29	B DIESE:	GENERATOR OIL	FIRE OCCURS	8.92E-03	IEV-FI4
				EQUIPMENT FAILS	DUE TO FIRE		1,006+00	FIRE-DAMAGE
				8US 52	FAILURE		2.40E-06	40- <b>85-80552</b> 5G
48	2.14E	68	.29	B DIESEL	GENERATOR OIL	FIRE OCCURS	8.92E-03	1EV-F14
				FOUIPMENT FAILS	DUE TO FIRE		1.00E+00	FIRE-DAMAGE
				OPERATOR FAILS	TO START ONE	CHARGENG PUMP	1.21E-02	35CHPHE
				FAILURE OF	SEQUENCER RELAY	BL S/85	1.98E-04	55REBLSBS RF
41	2 14F	6 <b>8</b>	.29	B DIESEL	GENERATOR OIL	FIRE OCCURS	S 92E+03	IEV-F14
				EQUIPMENT FAILS	DUE TO FIRE		1.00E+00	FIRE-DAMAGE
				PERATOR FALLS	TO START ONE	CHARGING PUMP	1.21E-02	35СНРНЕ
				FALCURE OF	SEQUENCER RELAY	85/85 TO OPERATE	1.98E-04	55REBSB5-KF
<b>ч</b>	2 148	<b>8</b> 0	29	B DIESEL	GENERATOR OIL	FIRE OCCURS	8.928-03	1EV-F14
				EQUIPMENT FALLS	DUE TO FIRE		1.00E+00	FIRE-DAMAGE
				OPERATOR FAILS	TO START ONE	CHARGING PUMP	1.21F-02	35СНРНЕ
				RELAY REX/85	FAILS TO OPERATE		1.98E_04	55REBLXB5-RF

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 288 of 415

TABLE 4 11 F15

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page:

1

Title: FI5: Fire in Relay Room near Vertical Trays File: FIRE5.WLK ( File created by Linking FIRE5.IN Reduced Sum of Cutsets: 3.2110E-07

WEINK \*\* Ver. 3.11 \*\*)

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
						<u>.</u>	• • • • • • • • • • •	,
,	1,82E-07	56 68	FIRE IN RELAT	ROOM OCCURS			6.78E-07	1EV-F15
1	TODE OF	70.00	EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO START AND	LGAD DIESEL	FROM DSP	2.69E-01	42-DGA-DSPHE
	e er i P	<b>17</b> 60	FIRE IN RELAY	ROOM OCCURS			6.78E-07	1EV-F15
2	5 4AE 08		EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO ESTABLISH	SERVICE WATER	FROM DSP	8.06E-02	02-SWA-DSPHE
5	5 44 18	1, 76	FIRE IN RELAY	ROOM OCCURS			6.78E-07	1EV-F15
			FOULPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO ESTABLISH	AFW FLOW FROM	DSP	5,19E-02	058AF3 DSP - HE
	the B	ь <b>с</b> . Р	EIRE IN RELAY	ROOM OCCURS			6.78E 07	1EV-F15
٤.		4 40	EQUIPMENT FAILS	DUE TO FIRE			1.00 <b>E+00</b>	FIRE-DAMAGE
			DIESEL GENERATOR	!A	FALLURE TO START	AND RUN	2.13E 02	10 GE-DG1A PS
				ROOM OCCURS			6.78E-07	1EV-F15
1,	<u>, 11( ,8</u>	5 447	ETRE IN RELAY EJUEPMENT FAILS				1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.53E 02	058PMAFW1A-PS
٠,	5.838	· ·.	FIRE IN H LAY	ROOM OCCURS			6.78E-07	IEV-FIS
			EQUIPMEN FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AHV 5W 301A	FALLS TO OPEN			5.32E-03	02-AV-SW301A-CC
	5 548 1.4	1 5	FIRE IN RELAT	RUDM OF "JRS			6.78E-07	1EV-F15
	3 348 YY		FULTEMENT FATUS	DUE TO FIRE			1 00E+00	FIRE-DAMAGE
			OFERATOR FAILS	TO ESTABLISH	CUMPONENT	ODE ING FROM DSP	3.08E 02	31-CCL-DSP HE
			PERATOR FALLS	O ESTABLISH	CHARGING USING	OSP	1.60E 01	35-CHP-DSPDHE
							6.78E-07	1EV-F15
5	<i>.</i> ** <i>*</i>	.8	FIRE IN RELAY	ROOM JCEURS			1,006+00	FIRE-DAMAGE
			EUGERMENT FALLS TRAVELING WATER	DUE TO FIRE SCREEN TAT	MECHANICAL	FAILURE	3.72E-03	02-FLT-TWIAT PS
			HAVELING WAICH	JUNCIN 15				
			- HE IN RELAT	RUKOM CLEURS			5.78E 07	IEV-F15
			FULLIMENT FALLS	LE TO FIRE			1.u0E+00	FIRE-DAMAGE
			DEERATOR FALLS	10 ESTABLISH	CHARGING USING		1.03E 01	35-CHP-DSPHE
			HERAT HERATIS	т. Е́́́\^А́₿.:≦н	MPONENT	LOOLENG FROM DSP	3 088 - 02	31-CCL-DSP HE
	<b>7</b>		THE IN REAM	RUDM OFCURS			6.78E-07	1Ev-F15
1 1	1, V	. }	E DE MENT FALLS				1.00 <b>E+0</b> 0	FIRE-DAMAGE
			5 46 € R₩	MCC 520	+AILS TO CLOSE		3 00E-03	40-CB-520/A6-FC
				D			6.78E-07	1EV-F15
• •	, SE ¥	.+3	FIRE IN HE AF	ROOM OCCURS			1.00 <b>E+0</b> 0	FIRE-DAMAGE
			FOULPMENT FAILS	POE TO FIRE FAILS TO CLOSE			3.CUE-03	39-C8-1-509FC
			HREAKER + SHO	- наса о сторг				
· .	Ş : <b>Q</b> ⊨Ş	3	FILE IN RELAT	KUMM COLLES			J. 78£ 07	IEV-F15
•	· ·		OUT MENT FAILS	044 10 4186			* 00E+00	FTRE-CAMAGE

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 289 of 415

ABLE 4 11 F15

\*\*\*\*\* DOMINANT CUISETS \*\*\*\*\*

Page:

2

Title: F15: Fine in Relay Room near Vertical Trays - Le - F18ES.WLK ( File cleated by Linking F1RE5.1N Meduced Sum of Sutsets: 3.2110E-07

NUMBER	Cu	! SE 1	PROB	PERCENT	BASIC EVENT NAME	E 			EVENT PROB.	IDENTIFIER
					BREAKER 1 501	FAILS TO OPEN			3.00E-03	39-CB-1-501FO
• ,	;	306	.9	. 42	FIRE IN RELAT	ROOM OCCURS			6.78E-07	IEV-F15
					EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
					SOV AFW-111A	FAILS TO OPEN			2.00E-03	058SVAFW111A-CC
١.,	1	34ê	69	. 42	FIRE IN RELAY	ROOM OCCURS			6.78E-07	1EV-F15
					EQUIPMENT FAILS	DUE TO FIRE			1.005+06	FIRE-DAMAGE
					COMMON CAUSE	FAILURE OF BOTH	DIESEL	GENERATORS	1.97E-03	10-GE-DGABCM
1%	9	9 <b>9</b> F	10	. 28	FIRE IN RELA.	ROOM OCCURS			6.78E-07	1EV-F15
					EQUIPMENT FATUS	DUE TO FIRE			1.00E+00	FIRE-CAMAGE
					AFW FUMP 1A	UNAVAILABLE	DUE TO TEST OR	MAINEMANCE	1.348 03	058PHAFWIA TH
٠,	,	: 9F	16	22	FIRE IN RELAY	ROOM OCCURS			6.78E 07	1EV-F15
					EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
					OPERATOR FAILS	TO ESTABLISH	CHARGING USING	OSP	1.03E-01	35-СНР-Ф\$РнЕ
					<pre>//w PUMP A</pre>	MECHANICAL	FAILURE		1.03E-02	31-PHCCW1A PS
• !	4	25E	•	15	FIRE IN RELAY	ROOM OCCURS			5.78E-07	1EV-F15
					EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-CAMAGE
					NO SERVICE WATER	DUE TO	COMMON CAUSE	FATLURES	7.30E-04	02CM
• 13		·• •• I	<b>x</b> 1.	14	FIRE IN RELAY	ROUM OCCURS			6.78E-07	IEV-FI5
					FUUTPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
					COMMON CAUSE	FAILURES OF	AFW SYSTEM		2.128 04	058AFWCM
	•	134	,	• 64	FIRE IN RELAY	FORM OCCURS			6.78E-07	IEV-F15
					E JULFMENT FAILS	QUE TO FIRE			1,00 <b>F+</b> 00	FIREDAMAGE
					′∋ш Р⊎НР ≛≜1	MECHANICAL	FALLURE		1.40E-02	02-PM-SW1A1PS
					un Phimp 142	MECHANICAL	FAILINE		1,40E-02	02-PM-SW1A2- PS
	r	•4	• •	·	FRE IN RELAT	ROOM OCCURS			6.78E 07	1EV-F15
					FULLEMENT FALLS	WE TO FIRE			1 008+00	FIKE DAMAGE
					HELLK VAL VE	AFW 1A	PAS'S IU OPFN		1.00E-04	058CVAFW*A-FO
. 1		·''t	••		•	ROOM DECURS			6.78E 07	LEV FIS
					ELCOMEN' + 4, S	CLE THE FERE			1 UUE+00	FIRE FAMAGE
					HE'R VALUE	₩E 531A	FAILS TO OPEN		1. DOE 04	058 - MU311A-FO
• •			• •		- HE N HELAS	ROOM ROLLARS			6.78E 07	1±√ F15
					- L DEMENT FAL	2 E TO FIRE			1 006+00	FIRE-DAMAGE
					47 K 44,48	Mi 3.71	FALLS OF OPEN		1.00E 04	27 CV MU301- 50
ş	ب	- 52	• •		ELBE LA RECTA	R.KM JC. JRS			6.78E 37	IEV 15
					ED TOMENT FAILS	THE TO FIRE			1.008+00	FIRE-DARAGE
					lw shiMs 1A1	MECHANICAL	FALLURE		1.4 ±-02	02-PM SWIAT- PS
					N. 141. N.S.	STRAINER 142	MECHANICAL	FALLURE	3.7 ¥-03	02-FLR-R51A2 45
. •	<b>ξ</b> .	٩Ļ	· ·		· Les N Recan	ROUM SHE RS			6 18E 07	LEV FIS

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 290 of 415

TABLE 4 11 FIS

---- DOMINANT CUTSETS -----

Page: 3

Fite: FLS: Fire in Relay Room near Ventical Travs Fire: FLRES.WLK ( File created by Linking FLRES.IN Reduced Sum of Sutsets: 3.2110E 07

NUMBER	CUTSET PRO	B PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
			· · · · ·	the side			1 00E+00	FIRE-DAMAGE
			EQUIPMENT FALLS		MECHANICAL	FAILURE	3.72E-03	02-FLR-RS1A1-PS
			ROTATING SW PUMP 1A2	STRAINER 1A1 MECHANICAL	FAILURE		1.40E-02	02-PM-SW1A2PS
		<i></i>	CIDE IN DELAY	ROOM OCCURS			6.7 <b>8E</b> -07	IEV-F15
<i>`</i> ,	21.85£ 11	() L	FIRE IN RELAY FOULPMENT FAILS				1.00E+00	FIRE-DAMAGE
				MECHANICAL	FAILURE		1.40E-02	02-PH-SW1A1PS
			SW PUMP 1A1 BREAKER FRUM	MCC-52D	FAILS TO CLOSE		3.00E-03	40-C8-520/A5-FC
		<i></i>		ROOM OCCURS			6.78E-07	IEV-FI5
76	2 85E 11	اين.	FIRE IN PELAY	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			ED PMENT FAILS	NCC 529	FAILS TO CLUSE		3 00E-03	40-C8-520/A4-FC
			BREAKER FROM SW PUMP 1A2	MECHANICAL	FAILURE		1.40E-02	02-PM-SW1A2PS
				ROOM OLCURS			6,7 <b>8E</b> -07	IEV-FI5
21	2 75E 11	.01	FIRE IN RELAT				1,00E+00	FIRE-DAMAGE
			EQUIPMENT FALLS SW PUMP 1A1	JNAVAILABLE	DUE TO TEST OR	MAINTENANCE	2.90E-03	02-PH-SWP1A1-TH
			SW PUMP 1A2	MECHANICAL	FAILURE		1.⊶0E÷02	02-PM-SW1A2PS
				DOM DOCUES			6.78E-07	IEV-F15
78	2.30F 11	41	FIRE IN RELAT	ROOM OCCURS DUE IN FIRE			1.00E+00	FIRE-DAMAGE
			EQUIPMENT FAILS	U ESTABLISH	CHARGING USING	DSP	1.03E 11	35-CHP-DSPHE
			DERATOR FAILS BOTH CCW PUMPS	FATE DUE TO	LCS OF OFFSITE	POWER	3.30E-04	31-PM-CCW1AB-CM
			1111 IN DC AN	ROUM OCCURS			6.78E-07	1EV-F15
5.4	2.21E 11	j1	FIRE IN RELAY EQUIPMENT FALLS				1,00 <b>E+00</b>	FIRE-DAMAGE
			NO CHARGING FLOW		COMMON CAUSE	FAILURES	1,06E-03	35CHPCM
			OPERATUR FALLS	TO ESTABLISH	COMPONENT	COCLING FROM DSP	3.08E-02	31-CCL-DSPHE
	1 ASE 11	11	FIRE IN RELAY	ROUM OCCURS			6.78E-07	1EV-F15
3.1	1.001	() ·	EULIPHENT FAILS				1.00E+00	FIRE DAMAGE
			BREAKER FROM	565 BRA 102 TO	BUS BRA 104	TRANSFERS OPEN	2 40E 05	38 CBA102-04-CO
••			FIRE IN RELAY	ROOM OCCURS			6.78E-07	1EV-F15
3.	1,638-11		EQUIPMENT FALLS				1,00+300,1	FIRE-DAMAGE
			BREAKER 15208	TRANSFERS SPEN			2.40E-05	40 CB 15208 CO
	· 731 · ·		FIRE IN RELAT	u XM skCluRS			6.78E-07	1EV-F15
э.	(C)1		EQUIPMENT FALLS				1.00E+00	FIRE-DAMAGE
			BREAKER 152 1	TRANSFERS OPEN			2.40E 05	40 0815201 10
ε <b>λ</b>	1 + 3[ - 13	,	FINE IN RELAT	ROOM OFCURS			6.78E-07	1EV-F15
	т. <del>И</del> т.		FULLEMENT FAILS				1.00E+00	FIRE-DAMAGE
			TRANSF JEMER	SUPPLY BREAKER	1.5.5	TRANSFERS OPEN	2,40E-05	39-081-505-00
š.,			→ TRE , No RELAY	κ.)λ₩. UL JURS			6.78E-07	1EV-F15
·••	·1		+ DE TPMENT + ALLS				1.00E+00	FIRE-DAMAGE
			GREAKER 15206	TRANSFERS OPEN			2.40E-05	40-CB15206-CO
;	1 h.e. (1		· FIRE N RELAT	KUOM JOCURS			e.78E-07	1EV-F15

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 291 of 415

### 1ABLE 4 11 F15

\*\*\*\*\* DUNINANT CUTSETS \*\*\*\*\*

Page:

4

Fitle: FIS: Fire in Relay Room near Ventical Trays File: FIRES.WLK ( File created by Linking FIRES.IN Reduced Sum of Cutsets: 3.2110E 07

NUMBER	CUTSET	PROB		BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				TRANSFORMER	1 - 52	FAILURE		1.94E 05	40-TR1-52SG
36	9-38E	12	. 00	FIRE IN RELAY	ROOM OCCURS			6.78E-07	1EV-F15
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				ROTATING	STRAINER 1A1	MECHANICAL	FATLURE	3.72E·03	02-FLR-RS1A1-PS
				ROTATING	STRAINER 1A2	MECHANICAL	FAILURE	3.72E-03	02-FLR-RS1A2-PS
57	8.141	12	90	FIRE IN RELAY	RUON OCCURS			6.78E-07	1EV-F15
				EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				AOV HU 3B	TRANSFERS OPEN			1.20E-05	03-AVMJ38CO
[ \s	9 )4F	12	. 00	FIRE IN RELAT	ROOM OCCURS			6.78E-07	1EV-F15
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				AOV HU SA	TRANSFERS OPEN			1.20E-05	03-AVMU3ACO
3.2	7.57E	12	(j{)	FIRE IN RELAY	ROOM OCCURS			6.78E-07	IEV-FIS
				FOUTPMENT FAILS	DUE TO FIRE			1 E+0C	FIRE DAMAGE
				BREAKER FROM	MCC 520	FAILS TO CLOSE		3. JUE-03	40-C8-52D/A4-FC
				ROTATING	STRAINER 1A2	MECHANICAL	FAILURE	3.72E-03	02-FLR-R\$1A2-P\$
••U	7 57E	12	90	FIRE IN RELAY	ROOM OCCURS			6.78E-07	1EV-F15
				ED IPMENT FALLS	OUE TO FIRE			1.00E+00	FIRE-DAMAGE
				ROTATING	STRAINER 1A1	MECHANICAL	FAILURE	3.72E-03	02-FLR-RS1A1-PS
				BREAKER FROM	MCC 520	FAILS TO CLOSE		3.00E-03	40-C8-520/A5-FC
<u>د</u> ۲	7 4 4	12	.10	FIRE IN RELAY	ROOM DECURS			6.78E-07	IEV-F15
				EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				NO CHARLING FLOW	DUE TO	COMMON CAUSE	FATLURES	1.06E-03	35CHPCM
				1.0W MPA	MECHANICAL	FAILURE		1.03E 02	31-PHCCW1A-PS
ч.`	7.51E	12	÷μ,	·. WE '. RELAY	ROOM OCCURS			6.78E-07	1EV-F15
				FOUTPMENT FALLS	DUE TO FIRE			1.00E+00	FIREDAMAGE
				SW POMP TAT	UNAVATLABLE	DHE TO TEST OR	MAINTENANCE	2.90E 03	02-PH-SWP1A1-TH
				NO. AFEND	STRAINER 142	MECHANICAL	FALLURE	3.72E-03	02-FLR-RS1A2-PS
. 1	1 . HE	•	-1	FIRE IN RELAY	ROOM OCCURS			6.78E 07	1EV-F15
				EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE - DAMAGE
				HERATOR FALLS	10 ESTABLISH	CHARGING USING	DSP	1.03E 01	35-CHP-DSP- HE
				HELK VALVE	CC 3A	FALLS TO OPEN		1.00E-04	31-CVCC3A-FO
·• *•	n HSE	12		τ, έ.Ν.⊬ξ <b>.Δγ</b>	REX MILLING S			6.78E 07	1EV-F15
				HULL MENT FALLS	.JE 19 FIRE			1.00E+00	FIRE DAMAGE
				√a ,MP 1A1	MECHANICAL	FAILURE		1.40E-02	02 PM-SW1A1 PS
				W STRAINER 142	P. Oost D			7.20E 04	02 FL-1A2 PL
-• 5	5 Nat	12	у.	N RELAY	RUXMOLOURS			6.78E-07	1EV-F15
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				HREAKEN FROM	MCC 520	FAILS TO CLOSE		3.00E 03	40-C8 520/44 FC
				REFER PROM	ML. 420	ATES TO CLOSE		3.00E U <b>3</b>	40 CB 520/#5 FC

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 292 of 415

### TABLE 4 11 F15

\*\*\*\*\* DOMINANT CUISETS \*\*\*\*\*

Page: 5

Title: >15. Fire in Relay Room near Vertical ...ays File; FIRES.WLK ( File created by linking FIRES.IN Feduced Sum of Cutsets: 3.2110E-07

NUMBER	CULSET PROR	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
M 20101 P								
	5 VOE 12	<u>^</u>	FIRE IN PELAY	ROOM OCCURS			6.78E-07	IEV-FI5
•1	) #12 IF	.,	EQUIPMENT FALLS	QUE TO FIRE			1.00E+00	FIRE-DAMAGE
			SW PUMP 1A1	UNAVAILABLE	DUE TO TEST OR	MAINTENANCE	2.90E-03	02-PH-SWP1A1-TN
			BREAKER FROM	MCC 52D	FAILS TO CLOSE		3.00E-03	40-C8-520/A5-FC
		116	FIRE IN RELAT	ROOM OCCURS			6.78E-07	1EV-F15
	5 428 12	.40	EQUIPMENT FATLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BREAKER BRA 104	CIRCUIT 7	TRANSFERS OPEN		8.00E-06	38-CBA104-07-CO
				hoom of clifte			6.78E-07	12V-F15
/ 9	1 35E 12	10	FIRE IN RELAT	ROOM OCCURS			1.00E+00	FIRE-DAMAGE
			EQUIPMENT FAILS	DUE TO FIRE	FAILS TO CLOSE		1.60E-02	35-AMEVE101A FC
			RELIEF VALVE	CV1 1013	FAILS TO CLOSE		1.60E-02	35-AHCVC101C-FC
			RELIEF VALVE OPERATOR FAILS	CVC 101C TO ESTABLISH	COMPONENT	COOLING FROM DSP	3.08E 02	31-CCL-DSPHE
							6.78E-07	1EV-\$15
49	2.63E.12	20	FIRE IN RELAY	RIJOM OCCURS			1.00E+00	FIRE-DAMAGE
			EQUIPMENT FAILS	DUE TO FIRE				03-AS-HTEVLC-OP
			1555 OF TONTROL	SIGNAL TO MU JA	VALVE FAILS OPEN		3.00E 06	USTASTRIEVEC OF
50	1 216 12	<i>;</i> 0	FIRE IN RELAY	RIVOM OCCURS			6.78E 07	IEV-F15
			CHULFMENT FALLS	SUL TO FLAF			1.00 <b>E+</b> 00	FIRE-DAMAGE
			THERATOR FALLS	TO ESTABLISH	CHARGING USING	DSP	1.03E-01	35 CHP-DSPHE
			CCW HEAT	FXCHANGER 14	SHEEL LEAK		2.74E 05	31-HE- CCWIA HS

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 293 of 415

TABLE 4-12 F16

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 1

Title: F16. AFW Pump A Scenario (TU 950) File: FIRE6.WLK ( File created by linking FIRE6.IN WLINK \*\* Ver. 3.11 \*\*) Reduced Sum of Cutsets: 5.2700E-05

NUMBER	CUTSET	PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
								6.45E-04	1EV-F16
1	1 37E	05	26.00	AUXILIARY		OIL FIRE OLLORS		1.00E+00	FIRE-DAMAGE
				EQUIPMENT FAILS		FAILURE TO START	AND RUN	2.13E-02	10-GE-DG1BPS
				DIESEL GENERATOR	16	FALLURE TO START			
	4.415		12 60	AUXILIARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	1EV-F16
2	6.64E	.)()	12.00	EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
				CCW PUMP 8		FAILURE		1.03E-02	31-PHCCW18-PS
3	58E	06	9 64	AUXILIARY	FEEDWATER FUMP A	OIL FIRE OCCURS		6.45E-04	IEV-FI6
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				OPERATOR FAILS	TO START AND	LOAD DIESEL	MANUALLY	7.87E-03	42-DG8-MANHE
			- 0.			OIL FIRE OCCURS		6.45E-04	1EV-F16
4	4 18E	36	7.95	AUXILIARY		OIE FIRE OCCURS		1.00E+00	FIRE-DAMAGE
				EQUIPMENT FAILS		FAILURE		1.63E-02	05BPMAFW1B-PS
				OPERATOR FAILS		ESTABLISH	INSTRUMENT AIR	3.98E-01	OT-TAS-MANHE
c,	5.43E	06	6.51	AUXILIARY	FEEDWATER PUMP	OI' FIRE OCCURS		6.45E-04	1EV-F16
-				EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				AOV SW 3018	FAILS TO OPEN			5.32E-0?	02-AV-SW301B-CC
								6.45E-04	IEV-FI6
6	2 -49E	06	w.55	AUXILIARY		OI FIRE OCCURS		1.00E+00	FIRE-DAMAGE
				EQUIPMENT FAILS TRAVELING WATER		MECHANICAL	FAILURE	3.72E-03	02-FLT-TW182-PS
				RAAFFING MATER	SCREEN IDE	HECHN- CHE			
	* +++		5 68	AUXILIARY	F FOWATER PUMP A	OIL FIRE OCCURS		6.45E-04	IEV-FI6
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				BREAKER FROM	MCC 620	FAILS TO CLOSE		3.00E-03	40-CB-62D/A6-FC
								6.45E-04	IEV-FI6
Ą		•	5.68	AURTLARY		OIL FIRE OCCURS		1,00E+00	FIRE-DAMAGE
				EWUIPMENT FAILS BREAKER 1 603	FALLS TO CLOSE			3.00E-03	39-CB-1-603FC
				BREAKTR 1 (NO)	values to crose				
	·	t	5 42	AUXILIARY	FEEDWA'ER PUMP	DIE FIRE OCCURS		6.45E-04	IEV-FI6
				EDUTPMENT FALLS				1,00E+00	FIRE-DAMAGE
				BREAKER 501	FALLS TO OPEN			3.00E · 03	39-CB-1-601FO
								6 45E-04	1EV-F16
•	- · 58	л.	•	AUXI, IARY	-	OIL FIRE OCCURS		1.00E+00	FIRE-DAMAGE
				DUTEMENT FALLS		DUE TO TEST OR	MATHTENANCE	2,37E-03	31-PHCCW18-TH
				₩ ► MP 18	NAVALLABLE	502 (0 (ES) 5K		275 2 05	
, ,	1 . <b>`</b> *E	-16	<u>,</u>	4. x [ ARY	FEEDWATER FUMP	A DIL FIRE OCCURS		6.45E-04	IEV-FIG
			·	EQUIFMENT FALLS				1.00E+00	FIRE-DAMAGE
				COMMON CAUSE	FALLURE OF BOTH	DIESEL	GENERATORS	1,97E-03	10-GE-DGA8CM
					THE ALL A DUMP			6.45E 04	LEV-F16
12		99		AUXILIART		A DIE FIRE OCCURS		1.00E+00	FIRE-DAMAGE
				EWELEMENT FALL"		SERVICE WATER	MANUALLY	1.72E-03	02-SWB-MAN HE
				OPERATOR FALLS	O COMOLION	ACTIVE AND UN			

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 294 of 415

148LE 4-12 FIG

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 2

NUMBER	COTSE!	PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
				• • • • • •			· · · · · · · · · · · · · · · · · · ·		
13	1.0 <b>3</b> 8	06	1,95	AUXILIARY	FEEDWATER PUMP	CIL FIRE OCCURS		6.45E-04	JEV-FI6
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				OPERATOR FAILS	TO ESTABLISH CON	MANUALLY		1.5 <b>9E-03</b>	31-CCL-MANHE
14	8.87F	07	1.68	AUXILIARY	FEEDWATER PUNP	OIL FIRE OCCURS		6.45E-04	IEV-FI6
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				AFW PUMP 16	MECHANICAL	FAILURE		1.63E-02	058PMAFW18-PS
				COMPRESSOR 18	MECHANICAL	FAILURE		8.44E-02	01-PM-SIAC1B-PS
15	8 !6E	<i>u</i> 7	1.55	AUXILIARY	FEEDWATER PUNP A	OIL FIRE OCCURS		6.45E-04	1EV-F16
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				OPERATOR FALLS	TO ESTABLISH	AFW FLOW	MANUALLY	3.18E-03	05BAF3-MANHE
				OPERATOR FAILS	TO LOCALLY	ESTABLISH	INSTRUMENT AIR	3.98E-01	01-1AS-MANHE
16	5.13E	07	.97	AUXILIARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	1EV-F16
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				SOV AFW 1118	FAILS TO OPEN			2.00E-03	058SVAFW1118-CC
				OPERATOR FAILS	TO LOCALLY	ESTABLISH	INSTRUMENT AIR	3.98E-01	01-[AS-MANHE
. ,	<ul> <li>∠1E</li> </ul>	.)7	9 <b>9</b>	AUXILIARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E.04	IEV-F16
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				NO SERVICE WATER	DUE TO	COMMON CAUSE	FATLURES	7.30E-04	02SWSCM
18	4 62E	0Z	. 88	AUXILIARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	IEV-FI6
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				AFW PUMP 1B	UNAVAILABLE	DUE TO TEST OR	MAINTENANCE	1.80E-03	058PHAFW18-TM
				OPERATOR FAILS	TO LOCALLY	ESTABLISH	INSTRUMENT AIR	3.98E-01	01-IAS-MANHE
۰ <i>۰</i>	3,⊐BE	7	.58	AHXILLARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	IEV-FI6
				EQUIPMENT FAILS	DUE TO FIFE			1.00E+00	FIRE-DAMAGE
				OPERATOR FAILS	TO ESTAR ICH	AFW FLOW	MANUALLY	3.18E-03	058AF3-MANHE
				OPERATOR FAILS	TO ESTA LISH	SAFETY INJECTION	MANUALLY	1.50E-01	33-HPI-MANDHE
	2 13E	37 1	ust,	AUXILIARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E.04	IEV-FI6
				EQUIPMENT FAILS	DUE TO FIRE			1.00 <b>E+</b> 00	FIRE-DAMAGE
				BOTH ((@ PUMPS	FALL OUE TO	LOSS OF OFFSITE	POWER	3.30E 04	31-PH-CCW1AB-CM
. •	1. 13t	•	53	AURTELARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.4 <sup>5</sup> E 04	IEV-FI6
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				FERATOR FALLS	TO ESTABLISH	ASW FLOW	MANUALLY	3.18E-03	C3BAF3-MANHE
				UMPRESSOR 18	MECHANICAL	FALLURE		8.44E-02	01-PM-SIAC1B-PS
ċ,	1 .'6t	17	. 24	AURTELARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	1EV-F16
				EQUIPMENT FAILS	OUE TO FIRE			1.00E+00	FIRE-DAMAGE
				SW PUMP 181	MECHANICAL	FAILURE		1.40E-02	02-PM-SW181PS
				SW PUMP 102	MECHANICAL	FAILURE		1.406-02	02-P4-SU182PS
33	1 1 SE	07	.21	AUXILIARY	FEEDWATER PLIMP &	OLL FIRE GCCURS		≜.45E÷04	IEV-F16
				EQUIPMENT FALLS	OUE TO FIRE			1.00E+00	FIRE DAMAGE
				DIESEL JENERATOR	18 UNAVAILABLE	DUE TO TEST OR	MAINTENANCE	1.75E-04	10-GE-DG1B- TM

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 295 of 415

TABLE 4-12 F16

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 3

Title: F16: AFW Pump A Scenario (10.950) File: F1RE6.WLK ( File created by Linking FIRE6.IN WLINK \*\* Ver. 3.11 \*\*) Reduced Sum of Cutsets: 5.2700E-05

...

#### NUMBER CUISET PROB PERFENT BASIC EVENT NAME

EVENT PROB. IDENTIFIER

24         1.121.07         21         AUX11AFT         FEEDUATER POMP A OIL FIRE OCCUPS COUPERT FAILS         6.455-04         FEV-FIG FIRE-DAMAGE           25         1.104.07         21         AVX11AFT         FEEDUATER POMP A OIL FIRE OCCUPS COUPERT FAILS         0.457-04         FEV-FIG FIRE-DAMAGE           25         1.104.07         21         AVX11AFT         FEEDUATER POMP A OIL FIRE OCCUPS COUPERT FAILS         0.457-04         FEV-FIG FIRE-DAMAGE           26         1.104.07         21         AVX11AFT         FEEDUATER POMP A OIL FIRE OCCUPS         0.457-04         FEV-FIG FIRE-DAMAGE           26         0.104.08         10         AUX11AFT         FEEDUATER POMP A OIL FIRE OCCUPS         6.456-04         FEV-FIG FIRE-DAMAGE           26         0.104.08         10         AUX11AFT         FEEDUATER POMP A OIL FIRE OCCUPS         6.456-04         FEV-FIG FIRE-DAMAGE           27         7.001.08         15         AUX11AFT         FEEDUATER POMP A OIL FIRE OCCUPS         6.456-04         FEV-FIG FIRE-DAMAGE           27         7.001.08         15         AUX11AFT         FEEDUATER POMP A OIL FIRE OCCUPS         6.456-04         FEV-FIG FIRE-DAMAGE           27         7.001.08         15         AUX11AFT         FEEDUATER POMP A OIL FIRE OCCUPS         6.456-04         FEV-FIG FIRE-DAMAGE </th <th></th> <th></th> <th></th> <th></th> <th>•• •••</th> <th></th> <th></th> <th>···· · · · · · · · · · · · · · · · · ·</th> <th></th> <th></th>					•• •••			···· · · · · · · · · · · · · · · · · ·		
COM HEAT EXCLUTE QUAVAILAGE         DUE TO TEST OF HALFFERANCE         1.75E-04         31-HE-COMESTIN           75         3.000-117         21         ANXILLARY ISOUTHERT FAILS OUE TO THE SOUTHERT FAILS OUE TO THE ATURE         3.45E-04         1EV-T16 FAILS TO OPEN SOUTHERT FAILS OUE TO THE SOUTHERT FAILS OUE TO THE ATURE         1.000-00         5.45E-04         1EV-T16 FAILS TO OBBS/ATUTIS_CC           76         V.R0L.08         10         AUXILLARY AUXILLARY ATURES OUE TO THE ATURE         FAILURE         0.0000 FAILS TO THE ATURE         1.000-00 FAILS TO OBBP/A-ATVIS_THE BLOCK         0.45E 04 FAILS TO OBBP/A-ATVIS_THE BLOCK         1.000-00 FAILS TO OBBP/A-ATVIS_THE FAILS TO OPEN         0.45E 04 FAILS TO OPEN         1.000-00 FAILS TO OBBP/A-ATVIS_THE FAILS TO OPEN         0.45E 04 FAILS TO OPEN         0.	24	1 12E	07	.21	AUXILIARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	1EV-F16
25         1.091-07         21         ANXELTARY         FEEDWATER PLANP A DEL FIRE OCCURS         0.451-04         IEV-FI6           20         2.001-03         0.001-04         1.001-04         2.001-03         0.451-04         FIRE-DAMAGE           20         2.001-03         0.001-05         0.001-06         FIRE-DAMAGE         2.001-03         0.455-04         FIRE-DAMAGE           20         9.701-08         1.0         AUXELTARY         FEEDWATER PLANP A DEL FIRE OCCURS         0.455-04         FEV-FI6           20         0.001-09         1.001-09         1.001-09         FIRE-DAMAGE         0.001-00         FIRE-DAMAGE           27         7.001-08         1.5         AUXELTARY         FEEDWATER PLANP A DEL FIRE OCCURS         0.455-04         FEV-FI6           27         7.001-08         1.5         AUXELTARY         FEEDWATER PLANP A DEL FIRE OCCURS         0.455-04         FEV-FI6           27         7.001-08         1.5         AUXELTARY         FEEDWATER PLANP A DEL FIRE OCCURS         0.455-04         FEV-FI6           27         7.001-08         1.5         AUXELTARY         FEEDWATER PLANP A DEL FIRE OCCURS         0.455-04         FEV-FI6           27         7.001-08         1.5         AUXELTARY         FEEDWATER PLAN					EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
FOULTMENT FACES         OUE TO FIRE SON ATLI 1118         FOULTMENT FALLS         OUE TO FIRE FALL         FALLURE         1.0/E-00         FIRE-DAMAGE SUB-ATLI118-CC           26         V. MOL-105         1.19         AUXELTARY EQUIPMENT FALLS         FEEDATER PUMP A OLL FIRE OCCURS         6.45E-34         FES-FIE           26         V. MOL-105         1.19         AUXELTARY EQUIPMENT FALLS         DUE TO FIRE UNAVAILABLE         DUE TO TEST OR MATHETENANCE         1.00E-00         FIRE-DAMAGE           27         7. MOL-105         1.5         AUXELTARY EQUIPMENT FALLS         FEEDUATER PUMP A OLL FIRE OCCURS         6.45E-04         FEV-FI6           27         7. MOL-105         1.5         AUXELTARY EQUIPMENT FALLS         FEEDUATER PUMP A OLL FIRE OCCURS         6.45E-04         FEV-FI6           27         7. MOL-106         1.5         AUXELTARY EQUIPMENT FALLS         FEEDUATER PUMP A OLL FIRE OCCURS         6.45E-04         FEV-FI6           28         7. MOL-108         1.5         AUXELTARY EQUIPMENT FALLS         FEEDUATER PUMP A OLL FIRE OCCURS         6.45E-04         FEV-FI6           29         7. MOL-108         1.5         AUXELTARY EQUIPMENT FALLS         FEEDUATER PUMP A OLL FIRE OCCURS         6.45E-04         FEV-FI6           20         7. MOL-108         AUXELTARY EQUIPMENT FALLS         FEEDUATER					CCW HEAT EXCH TO	UNAVATLABL?	DUE TO TEST OR	MAINTENANCE	1.73E-04	31-HECCW10-TM
SQU AFX 1119         FAILS TO OPEN TOPPRESSON TO TOPPRESSON TO TOPPRESSON TOPPRESSON TO TOPPRESSON TO TOPPRESS	25	1.09E	9 <b>7</b>	21	ADDELIARY	FEEDWATER PUHP A	OIL FIRE OCCURS		6.45E-04	1EV-F16
ICOMPRESSON 19         MECHANICAL         FAILURE         8.44E 02         01-PM-SIAC18-PS           26         V. RUL 08         19         AUXISTART COUTMENT FAILS DUE TO FIRE AUXIACLA         FEEDWATER POMP A OIL FIRE OCCURS FAILURE         6.45E-04 1.00E-00         FEE-DAAGE FRE-DAAGE           27         7. RVE 18         15         AUXISTART COUTMENT FAILS AUXISTART         FEEDWATER POMP A OIL FIRE OUX TO FIRE AUXISTART         FAILURE         0.01 FIRE FAILURE         6.45E-04 FIRE-DAAGE         FEEDWATER B.44E-02         FEED					EQUIPMENT FAILS	OUE TO FIRE			1.6CE+00	FIRE-DAMAGE
20         M. Rul, 108         .19         Auticitant         FEEDWATER PUMP A OLL FIRE OCCURS         6.45E-04         IEV-FI6           27         M. Rul, 108         .19         Auticitant         Tational and transmission of the fire         1.00 + 00         FIRE-DAMAGE           27         7. RVH 108         15         Auticitant         TEEDWATER PUMP A OLL FIRE OCCURS         6.45E -04         1.00 + 00         FIRE-DAMAGE           27         7. RVH 108         15         Auticitant         TEEDWATER PUMP A OLL FIRE OCCURS         6.45E -04         1.00 + 00         FIRE-DAMAGE           27         7. RVH 108         15         Auticitant         TEEDWATER PUMP A OLL FIRE OCCURS         6.45E -04         1.00 + 00         FIRE-DAMAGE           27         7. RVH 108         15         Auticitant         FEEDWATER PUMP A OLL FIRE OCCURS         6.45E -04         1.00 + 00         FIRE-DAMAGE           28         7. RVH 108         15         Auticitant         FEEDWATER PUMP A OLL FIRE OCCURS         6.45E -04         1.00 + 04         FIRE-DAMAGE           29         7. RVH 108         .15         Auticitant         FEEDWATER PUMP A OLL FIRE OCCURS         6.45E -04         1.00 + 04         FIRE-DAMAGE           29         7. RVH 108         .15         Auticitant					SOV AFM 1118	FAILS TO OPEN			2.00£-03	05BSVAFW1118-CC
COLUMENT FAILS         DUE TO FIRE AND FUND         DUE TO FIRE UNAVAILABLE         DUE TO TEST OR FAILURE         MAINTENANCE         1.00E-00 1.00E-00         FIRE-DAMAGE OSBMANTHE '''           V7         7 MVE 108         35         AUXITLARY FOULIMENT FAILS         VECTO FIRE NECHANTCAL         FAILURE         0.6.45E 04         FEV-FIG           V7         7 MVE 108         35         AUXITLARY FOULIMENT FAILS         VECTO FIRE NECHANTCAL         FAILURE         0.6.45E 04         FEV-FIG           V8         AUXITLARY FOULIMENT FAILS         OUL TO FIRE AUX DUPL TR         FAILURE         1.05E 02         05BMF-AUXIEPS           V8         AUXITLARY FOULIMENT FAILS         OUL TO FIRE AUX DUPL TR         FAILURE         1.05E 02         05BMF-AUXIEPS           V8         7 DUPL TR         AUXITLARY FOULIMENT FAILS         FEEDWARE PUMP A OIL FIRE OCCURS         6.45E 04         FEV-FIG           V9         7 RVE 108         .15 AUXITLARY FOULIMENT FAILS         FEEDWARE PUMP A OIL FIRE OCCURS         6.45E 04         FEV-FIG           V9         7 RVE 108         .15 AUXITLARY FOULIMENT FAILS         FEEDWARE PUMP A OIL FIRE OCCURS         6.45E 04         FEV-FIG           V9         7 RVE 108         .15 AUXITLARY FOULTHENT FAILS TO OPEN         FIGE OCCURS         6.45E 04         FEV-FIG           V9 <td></td> <td></td> <td></td> <td></td> <td>COMPRESSOR 19</td> <td>MECHANICAL</td> <td>FAILURE</td> <td></td> <td>8.44E 02</td> <td>01-PH-SIAC1B-PS</td>					COMPRESSOR 19	MECHANICAL	FAILURE		8.44E 02	01-PH-SIAC1B-PS
ATM PUMP 18 CEMPRESSOR 18         UNAVAILABLE RECHARICAL         DUE TO TEST OR FAILURE         MAINTENANCE         1.60E-03 B.4.4E-02         05BPH - ATM 18 /m OT-PH-STATE           77         7 RVE 08         15         AUXILLARY FOULPMENT TAILS AUXILLARY FOULPMENT TAILS AUXILLARY FOULPMENT TAILS AUXILLARY FOULPMENT TAILS AUXILLARY         FEEDWATER PUMP A OLL FIRE OCCURS TAILORE         6.45E 04         1EV-F16           78         7 RVE 08         15         AUXILLARY FOULPMENT TAILS AUX PUMP 18         FEEDWATER PUMP A OLL FIRE OCCURS TAILORE         6.45E 04         1EV-F16           78         7 RVE 08         15         AUXILLARY AUX PUMP 18         FEEDWATER PUMP A OLL FIRE OCCURS TAILORE         6.45E 04         1EV-F16           78         7 RVE 08         15         AUXILLARY AUX PUMP 18         FEEDWATER PUMP A OLL FIRE OCCURS TAILORE         6.45E 04         1EV-F16           79         7 RVE 08         15         AUXILLARY AUX PUMP 18         FEEDWATER PUMP A OLL FIRE OCCURS TAILORE         6.45E 04         1EV-F16           700         7 RVE 08         15         AUXILLARY AUXIL PUMP 18         FEEDWATER PUMP A OLL FIRE OCCURS TAILORE         6.45E 04         1EV-F16           75 00         150         AUXILLARY AUXIL PUMP 18         FEEDWATER PUMP A OLL FIRE OCCURS TAILORE         6.45E 04         1EV-F16           75 00         150         AUX	26	9 80E	9 <b>8</b>	. 19	AUXILIARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	1EV-F16
1/2         1/2         0.1464-03         0.11         NUCLANTCA         FAILURE         8.446-02         01-PM-SIAC18-PS           1/2         1/2         1/2         1/2         1/2         1/2         1/2         0.000-10         1/2         0.000-10         1/2         1/2         0.000-10         1/2         1/2         0.000-00         F100-00AGE         0.000-00         F100-0AGE         0.000-00         F100-0AGE         0.000-00         F100-0AGE         0.000-00         F100-0AGE         0.000-00         F100-0AGE					EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
27       7       894-108       15       AUXELTARY       TETOWER POMP A OLE FIRE OCCURS       6.45E-04       TEV-FI6         28       7       894-108       15       AUXELTARY       TETOWER FALLS       FAILURE       1.65E-02       OSUBH - AFUE-PS         28       7       894-108       15       AUXELTARY       TETOWER FALLS       FAILURE       1.65E-02       OSUBH - AFUE-PS         28       7       894-108       15       AUXELTARY       TETOWER FALLS       FAILURE       1.00E-00       FIRE-DAMAGE         29       7       894-108       15       AUXELTARY       FEEDWATER PUMP A OLE FIRE OCCURS       6.45E-04       TEV-FI6         29       7       894-108       15       AUXELTARY       FEEDWATER PUMP A OLE FIRE OCCURS       6.45E-04       TEV-FI6         29       7       894-108       15       AUXELTARY       FEEDWATER PUMP A OLE FIRE OCCURS       6.45E-04       TEV-FI6         2001 108       15       AUXELTARY       FEEDWATER PUMP A OLE FIRE OCCURS       6.45E-04       TEV-FI6         30       7.00E-08       1.00E-00       FIRE-DAMAGE       1.00E-00       FIRE-DAMAGE         31       1.00E-00       FIRE-DAMAGE       1.00E-00       FIRE-DAMAGE         <					AFW PUMP 1B	UNAVATLABLE	DUE TO TEST OR	MAINTENANCE	1.80E-03	058PM- AFW18 'H
FOULDMENT FAILS     DUE TO FIRE ATM FORE TB     FAILURE HICHARICAL     FAILURE     1.000+00     FIRE DAMAGE 1.05E 02     0504PHAFVIB-PS       2/8     7 8VE 08     1.1     ALSE LAAV FOULPMENT FAILS     FEEDWATER PUMP A OIL FIRE OCCUPS     6.45E 04     16V-FIG       2/8     7 8VE 08     1.1     ALSE LAAV FOULPMENT FAILS     FEEDWATER PUMP A OIL FIRE OCCUPS     6.45E 04     16V-FIG       2/8     7 8VE 08     .15     ALKELLAAV     FAILURE     1.03E-02     058PHAFVIB PS       2/9     7 8VE 08     .15     ALKELLAAV     FEEDWATER PUMP A OIL FIRE OCCUPS     6.45E 04     16V-FIG       2/9     7 8VE 08     .15     ALKELLAAV     FEEDWATER PUMP A OIL FIRE OCCUPS     6.45E 04     16V-FIG       2/9     7 8VE 08     .15     ALKELLAAV     FEEDWATER PUMP A OIL FIRE OCCUPS     6.45E 04     16V-FIG       3/1     1/100+00     FIRE-DAMAGE     FAILURE     1.00E+00     FIRE-DAMAGE       3/1     1/100+10     1/100+00     FIRE-DAMAGE     1.00E+00     FIRE-DAMAGE       3/1     1/100+10     1/100+10     FIRE-DAMAGE     1.00E+00     FIRE-DAMAGE       3/1     1/100+10     1/100+10     FIRE-DAMAGE     1.00E+00     FIRE-DAMAGE       3/1     1/100+10     1/100+10     FIRE-DAMAGE     1.00E+00     <					COMPRESSOR 18	MECHANICA	FAILURE		8.44E-02	01-PM-SIAC1B-PS
ATM PUMP 18       HECKARICAL       FAILURE       1.65E 02       058PH - AFM18 -PS         10       7.89E 78       .15       AUX 11APY       FAILURE       FAILURE       1.00E 00       FIRE DAMAGE         10       7.89E 78       .15       AUX 11APY       FEDUATER PUMP A OIL FIRE OCCURS       6.45E 04       FEV-FI6         10       AUX 10000 18       HERMAICAL       FAILURE       FAILURE       1.00E+00       FIRE DAMAGE         AUX 10000 18       HERMAICAL       FAILURE       FAILURE       1.00E+00       FIRE DAMAGE         AUX 10000 18       HERMAICAL       FAILURE       FAILURE       1.00E+00       FIRE DAMAGE         AUX 10000 18       HERMAICAL       FAILURE       1.00E+00       FIRE DAMAGE         AUX 10000 18       HERMAIR ALLINE       FAI	27	7 89E	08	15	AUKILIARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E 04	1EV-F16
HIV S1 48       TATIS TO OPEN       7.50E-03       \$\$147\$148-CC         1/8       7.8VE-1/8       1.15       AUXILIARY       FEEDWATER PUMP A OLL FIRE OCCURS       6.45E-04       FEV-FI6         1/9       7.8VE-1/8       1.15       AUXILIARY       FEEDWATER PUMP A OLL FIRE OCCURS       6.45E-04       FEV-FI6         1/9       7.8VE-1/8       1.15       AUXILIARY       FEEDWATER PUMP A OLL FIRE OCCURS       6.45E-04       FEV-FI6         1/9       7.8VE-1/8       1.15       AUXILIARY       FEEDWATER PUMP A OLL FIRE OCCURS       6.45E-04       FEV-FI6         1/9       7.8VE-1/8       1.5       AUXILIARY       FEEDWATER PUMP A OLL FIRE OCCURS       6.45E-04       FEV-FI6         1/9       1.5       AUXILIARY       FEEDWATER PUMP A OLL FIRE OCCURS       6.45E-04       FEV-FI6         1/9       1.6       AUXILIARY       FEEDWATER PUMP A OLL FIRE OCCURS       6.45E-04       FEV-FI6         1/9       1.5       AUXILIARY       FEEDWATER PUMP A OLL FIRE OCCURS       6.45E-04       FEV-FI6         1/9       1.5       AUXILIARY       FEEDWATER PUMP A OLL FIRE OCCURS       6.45E-04       FEV-FI6         1/9       1.5       AUXILIARY       FEEDWATER PUMP A OLL FIRE OCCURS       6.45E-04       FEV-FI6 <tr< td=""><td></td><td></td><td></td><td></td><td>EQUIPMENT FAILS</td><td>DUE TO FIRE</td><td></td><td></td><td>1.00<b>E+00</b></td><td>FIRE-DAMAGE</td></tr<>					EQUIPMENT FAILS	DUE TO FIRE			1.00 <b>E+00</b>	FIRE-DAMAGE
28       7       BVE 7/R       .15       AUXELLARY       FEEDUATER PUMP A OTL FIRE OCCURS       6.45E 04       FEV-FI6         100E+00       FIRE DAMAGE       DUE TO FIRE       FAILURE       1.00E+00       FIRE DAMAGE         100       7       RVE 1/R       .15       AUXELTARY       FEEDUATER PUMP A OTL FIRE       FAILURE       1.00E+00       FIRE DAMAGE         100       7       RVE 1/R       .15       AUXELTARY       FEEDUATER PUMP A OTL FIRE       FAILURE       1.00E+00       FIRE DAMAGE         100       7       RVE 1/R       .15       AUXELTARY       FEEDUATER PUMP A OTL FIRE       ALURE       1.00E+00       FIRE DAMAGE         100       FIRE       AUXELTARY       FEEDUATER PUMP A OTL FIRE       ALURE       1.00E+00       FIRE DAMAGE         115       AUXELTARY       FEEDUATER PUMP A OTL FIRE       FAILURE       1.00E+00       FIRE DAMAGE         115       AUXELTARY       FEEDUATER PUMP A OTL FIRE       CCURS       0.45E+04       FEV-FI6         115       AUXELTARY       FEEDUATER PUMP A OTL FIRE       1.00E+00       FIRE DAMAGE         116       AUXELTARY       FEEDUATER PUMP A OTL FIRE       1.00E+00       FIRE DAMAGE         116       AUXELTARY       FEEDUATER PUMP A OTL					AFW FUMP 18	MECHANECAL	FAILURE		1.63E 02	058PHAFW18-PS
FQUIPHENT FAILS       DUE TO FIPE       1.00E+00       FTRE-DANAGE         AFW PUMP 18       MECHANICAL       FAILURE       1.03E+02       058PMAFV18 PS         MOV ST 3508       FAILS TO OPFN       7.50E 03       34RMV-ST3508-CC         P9       7.0VE-08       .15       AUXITI TARY       FEEDWATER PUMP A OIL FIRE OCCURS       6.45E 04       1EV-FIG         AFW PUMP 18       HECHANICAL       FAILURE       1.00E+00       FIRE-DANAGE         AFW PUMP 18       HECHANICAL       FAILURE       1.00E+00       FIRE-DANAGE         AFW PUMP 18       HECHANICAL       FAILURE       1.00E+00       FIRE-DANAGE         MIN ST 3518       FAILS TO OPEN       7.50E 03       34RMV-ST3518 CC         S       7.50E 03       SARMV-ST3518       FAILS TO OPEN       7.50E 03       34RMV-ST3518 CC         S       7.50E 03       MECHANICAL       FAILURE       1.00E+00       FIRE-DANAGE         S       7.50E 03       SARMV-ST3518       FAILS TO OPEN       7.50E 03       34RMV-ST3518 CC         S       7.50E 03       MECHANICAL       FAILURE       1.00E+00       FIRE-DANAGE         S       7.50E 03       SARMV-ST3518       FEEDWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV-FI6					MERV SE 48	FAILS TO OPEN			7.50E-03	551MV++-\$140-CC
ATM PORP 18 HOV KL 1508         HECHANICAL FAILURE         FAILURE         1.63E-02 7.50E 03         05BPH-AFW18 PS 34RMV-515508-CC          99         7. RVE 08        15         AUX11 LARY FOUDIMENT FAILS MOV SL 1518         FEEDWATER PUMP A OTL FIRE OCCURS MOV SL 1518         6.45E 04 FIRE DAMAGE         FEEDWATER PUMP A OTL FIRE OCCURS FOUDIMENT FAILS MOV SL 1518         6.45E 04 FIRE DAMAGE         FEEDWATER PUMP A OTL FIRE OCCURS FAILURE         6.45E 04 FIRE DAMAGE         FEEVATURE FIRE DAMAGE           1         7. SVE 08         15         AUX11 LARY FOUDIMENT FAILS MOV SL 1518         FEEDWATER PUMP A OTL FIRE OCCURS FAILS TO OPEN         6.45E 04 FIRE DAMAGE         FEEVATIB FIRE DAMAGE           1         7. SVE 08         15         AUX11 LARY FOUDIMENT FAILS HOW SC 4008         FEEDWATER PUMP A OTL FIRE OCCURS FAILS TO OPEN         6.45E-04 FIRE DAMAGE         FEV FI6 FIRE DAMAGE           1         7. 99E 08         15         AUX11 LARY FAILS TO OPEN         FAILURE FAILS TO OPEN         FAILURE FAILS TO OPEN         5.00E-00 FIRE DAMAGE           10         5.99E 08         15         AUX11 LARY FAILS TO OPEN         FAILURE FAILS TO OPEN         FAILURE FAILS TO OPEN         5.00E-00 FIRE DAMAGE           11         5.99E 08         15         AUX11 LARY FAILS TO OPEN         FILE DAMAGE         1.00E-00 FIRE DAMAGE         FILE DAMAGE           12         5.99E 08         13 <td><b>.</b> B</td> <td>7 89F /</td> <td>18</td> <td>. 15</td> <td>AUXILLARY</td> <td>FEEDWATER PUMP A</td> <td>OIL FIRE OCCURS</td> <td></td> <td>6.45E 04</td> <td>1EV-F16</td>	<b>.</b> B	7 89F /	18	. 15	AUXILLARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E 04	1EV-F16
HOU ST 1500         FALS TO OPEN         7.50E 03         34RHY-S13500-CC           199         7.89E 08         .15         AUXILIARY         FEEDWATER PUMP A OLL FIRE OCCURS         6.45E 04         FEV-FI6           199         7.89E 08         .15         AUXILIARY         FEEDWATER PUMP A OLL FIRE OCCURS         6.45E 04         FEV-FI6           1         6.0019MENT FAILS         DUE TO FIRE         FAILURE         1.63E 02         05BPH-AFW18-VS           1         7.50F 03         34RHY-S13518 CC         FAILS TO OPEN         7.50F 03         34RHY-S13518 CC           1         7.50F 03         MIXELIARY         FEEDWATER PUMP A OLL FIRE OCCURS         6.45E-04         FEV-F16           1         FAULDINE AT FAILS         DUE TO FIRE         FAILURE         1.05E 02         05BPH-AFW18 PS           1         7.99F 198         15         AUXILIARY         FEEDWATER PUMP A OLL FIRE OCCURS         6.45E-04         FEV-F16           1         199F 198         15         AUXILIARY         FEEDWATER PUMP A OLL FIRE OCCURS         6.45E-04         FEV-F16           1         199F 198         15         AUXILIARY         FEEDWATER PUMP A OLL FIRE OCCURS         6.45E-04         FEV-F16           1         199F 198         15         AUXILI					EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FTRE-DAMAGE
19       7.89E-08       .15       AUXT1 (ARY HOUTHENT FAILS AND PUMP 18       FEEDWATER PUMP A OLE FIRE OCCURS OUF TO FIRE       0.45E-04       FEV-FI6 FIRE-DAMAGE         1       .15       AUXT1 (ARY HOW ST 351R       FEEDWATER PUMP A OLE FIRE OCCURS HOW ST 351R       0.45E-04       FEV-FI6 FIRE-DAMAGE         1       .15       AUXT1 (ARY HOW ST 351R       FEEDWATER PUMP A OLE FIRE OCCURS HOW ST 351R       0.45E-04       FEV-FI6         1       .15       AUXT1 (ARY HOW ST 351R       FEEDWATER PUMP A OLE FIRE OCCURS HOW SC 4008       0.45E-04       FEV-FI6         1       .15       AUXT1 (ARY HOW ST 351R       FEEDWATER PUMP A OLE FIRE OCCURS HOW SC 4008       0.45E-04       FEV-FI6         1       .15       AUXT1 (ARY HOW SC 4008       FEEDWATER PUMP A OLE FIRE OCCURS HOW SC 4008       0.45E-04       FEV-FI6         1       .15       AUXT1 (ARY HOW SC 4008       FEEDWATER PUMP A OLE FIRE OCCURS HOW SC 4008       6.45E-04       FEV FI6         1       .15       AUXT1 (ARY HOW ST 3018       FEEDWATER PUMP A OLE FIRE OCCURS HOW HOW ST 3378       6.45E-04       FEV FI6         1       .15       AUXT1 (ARY HOW A OLE FIRE HOW FIRE DAMAGE       FEEDWATER PUMP A OLE FIRE OCCURS HOW HAR 3008-FO       6.45E-04       FEV FI6         10       .15       .15       .16       .16       .16       .16					AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PMAFW18 PS
FOUDTMENT FAILS AFW PUMP 18 HIV SC 3518OUE TO FARE HECHANICAL FAILS TO OPENFAILURE1.00E+00 FAILS FOFIRE-DAMAGE OSBPNAFW18-PS S4RHV-SI3518 CC115AUX1LIARY FOUDPMENT FAILS HUV CC WORBFEIDWATER PUMP A OLL FIRE OCCURS FAILS TO OPEN6.45E-04 1.00E+00FEW-FIG FIRE DAMAGE 1.00E+00115AUX1LIARY FOUDPMENT FAILS HUV CC WORBFEIDWATER PUMP A OLL FIRE OCCURS FAILS TO OPEN6.45E-04 1.00E+00FEW-FIG FIRE DAMAGE 1.00E+0051199E-118 HUV CC WORB15AUX1LIARY FEIDWATER PUMP A OLL FIRE OCCURS HECHANICAL FAILS TO OPEN6.45E-04 1.00E+00FEW-FIG FIRE DAMAGE 1.00E+0051199E-118 HUV RHR 500B HUV RHR 500B16FAILS TO OPEN7.50E-03 3.35PMVPH300B+50100-VE-0811AUX1LIARY HECHANICAL HUV RHR 500BFEEDWATER PUMP A OLL FIRE OCCURS HECHANICAL HIV RHR 500B6.45E-04 1.00E+00FEEDWATER PUMP A FEEDWATER PUMP A OLL FIRE OCCURS FIRE DAMAGE HIV RHR 500B6.45E-04 1.00E+00FEEDWATER PUMP A FIRE-DAMAGE110-VE-0811AUX1LIARY FEEDWATER PUMP A OLL FIRE OCCURS HIV RHR 500B6.45E-04 1.00E+00FEEDWATER FIRE-DAMAGE120-VE-0811AUX1LIARY FEEDWATER PUMP A OLL FIRE OCCURS HIV RHR 500B6.45E-04 1.00E+00FERE-DAMAGE13AUX1LIARY FUNDH 18 RECHANICAL RECHANICAL FEEDWATER PUMP A SEERATOR FAILSFEEDWATER PUMP A SEERATOR FAILS6.45E-04 1.00E+00FEEDWATER FEEDWATER PU					NOV 51 3508	FALLS TO OPEN			7.50E 03	34RMV-\$13508-CC
AFW PUMP 18 MIN KT 3518MECHANICAL FAILS TO OPENFAILURE1 63E 02 7 50E 03058PMAFW18-PS 34RMV-S13518 CC521 EVE 1815AUXELIANT EUDIPMENT FAILS ATM PUMP 16FEEDWATER PUMP A OIL FIRE OCCURS6.45E-04 1.00E+00FEE DAMAGE FEE DAMAGE521 EVE 1815AUXELIANT EUDIPMENT FAILS ATM PUMP 18 EUDIPMENT FAILSFEEDWATER PUMP A OIL FIRE OCCURS6.45E-04 1.05E 02 0.5BPMAFW18 PS 7.50E 036.45E-04 1.00E+00FEE DAMAGE FEE DAMAGE511 199E 19815AUXELIANT EUDIPMENT FAILS AUXELIANT EUDIPMENT FAILS AUXELIANT FAILS 10 OPENFOIL FIRE OCCURS6.45E-04 1.00E+00FEE DAMAGE FEE DAMAGE 1.00E+00511 199E 19815AUXELIANT FEEDWATER PUMP A OIL FIRE OCCURS FAILS 10 OPEN6.45E-04 1.00E+00FEE DAMAGE FEE DAMAGE 1.00E+005251 199E 19815AUXELIANT FEEDWATER PUMP A OIL FIRE OCCURS FAILS 10 OPEN6.45E-04 1.00E+00FEE DAMAGE FEE DAMAGE 1.00E+005351 199E 19811AUXELIANT FEEDWATER PUMP A OIL FIRE OCCURS FUE TO FIRE FEEDWATER PUMP A OIL FIRE OCCURS 1.00E+006.45E-04 FIRE-DAMAGE 1.00E+00FEEDWATER PUMP A FIRE-DAMAGE 1.00E+00FEEDWATER PUMP A FIRE-DAMAGE 1.00E+00FEEDWATE	.9	7 B9E :	8	. 15	AUX 11 ARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E 04	1EV-F16
HIV K1 351B       FALLS TO OPEN       7 50E 03       3ARMY-SI351B CC         5       7 80F 98       15       AUX1LIARY       FLECWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV:FI6         5       7 80F 98       15       AUX1LIARY       FLECWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV:FI6         5       7 80F 98       15       AUX1LIARY       FLECWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV:FI6         51       7 90F 98       15       AUX1LIARY       FLECWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV:FI6         51       7 90F 98       15       AUX1LIARY       FLECWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV FI6         51       7 90F 98       15       AUX1LIARY       FLECWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV FI6         51       7 90F 98       15       AUX1LIARY       FLECWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV FI6         51       7 90F 98       15       AUX1LIARY       FLECWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV FI6         52       5 90 98       17 AUX1LIARY       FLECWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV FI6         53       1001PMENT FAILS       500 F0 FIRE       FUMP A OIL FIRE OCCURS <td< td=""><td></td><td></td><td></td><td></td><td>FOUTPMENT FALLS</td><td>OUE TO FIRE</td><td></td><td></td><td>1.00E+00</td><td>FIRE-DAMAGE</td></td<>					FOUTPMENT FALLS	OUE TO FIRE			1.00E+00	FIRE-DAMAGE
3       7       EVENDB       35       ADXELIARY       FEEDWATER PUMP A OIL FIRE OCCURS       6.45E-04       TEV-FT6         4       EQUIPMENT FAILS       DUE TO FIRE       FAILURE       1.00E+00       FTRE DANAGE         4       MOVICE GOOB       FAILS TO OPEN       FAILS TO OPEN       7.50E-03       34RNV-CC400B CC         51       7       MOVICE GOOB       FAILS TO OPEN       FAILS TO OPEN       7.50E-03       34RNV-CC400B CC         51       7       MOVICE GOOB       FAILS TO OPEN       FAILS TO OPEN       7.50E-03       34RNV-CC400B CC         51       7       MOVICE GOOB       FAILS TO OPEN       FAILS TO OPEN       7.50E-03       34RNV-CC400B CC         51       7       MOVICE GOOB       FAILS TO OPEN       FAILS TO OPEN       7.50E-03       34RNV-CC400B CC         51       7       MOVIDE       MECHANICAL       FAILS TO OPEN       7.50E-03       33FNVRH30DB-FO         50       5       MOVIDE       FAILS TO OPEN       FAILS TO OPEN       7.50E-03       33FNVRH30DB-FO         50       5       MOVIDE       FAILS TO OPEN       FAILS TO OPEN       7.50E-03       33FNVRH30DB-FO         50       5       MOVIDE       FAILS TO OPEN       FAILS TO OPEN       7.50E-					AFW PUMP 18	MECHANICAL	FAILURE		1 63E 02	058PHAFW18-PS
EUCLEMENT FAILS ALW POMP 18 MOVIC 4008DUE TO FIRE MECHANICAL FAILS 10 OPENFAILURE1.00E+00 FAILS FAILS FAILS 10 OPENFIRE DAMAGE FAILS 10 OPENS11.99E 19815AUXILIARY EQUIPMENT FAILS ALW POMP 18 MECHANICAL FAILS 10 OPENFAILS COLCURS FAILS 10 OPEN6.45E-04 1.00E+00FIRE DAMAGE FIRE DAMAGE 1.00E+00S11.99E 19815AUXILIARY EQUIPMENT FAILS ALW POMP 18 MECHANICAL FAILS 10 OPENFAILS COLCURS FAILS 10 OPEN6.45E-04 1.00E+00FIRE DAMAGE FIRE DAMAGE 1.00E+00S20.5604122ALKIDIARY FUDIPMENT FAILS DUE 10 FIRE HELK 24LVEFEEDWATER PUMP A OIL FIRE OCCURS FUILS TO OPEN6.45E-04 1.00E+00FEEV FIG FIRE DAMAGE FIRE DAMAGE FUILS TO OPENS35.10E 10811ALKIDIARY FUDIPMENT FAILS DUE 10 FIRE HELK 24LVEFEEDWATER PUMP A OIL FIRE OCCURS FUILS TO OPEN6.45E-04 1.00E+00FEV FIG FIRE DAMAGE 1.00E+00S35.10E 10811ALKIDIARY FEEDWATER PUMP A OIL FIRE OCCURS FULDEMENT FAILS DUE 10 FIRE HELK 24LVEFEEDWATER PUMP A OIL FIRE OCCURS 1.00E+006.45E-04 1.00E+00FEV FIG FIRE DAMAGE 1.00E+00S45.10E 10811ALKIDIARY FEEDWATER PUMP A OIL FIRE OCCURS FULDEMENT FAILS DUE 10 FIRE HELK 24LVEFEEDWATER PUMP A OIL FIRE OCCURS 1.00E+006.45E-04 FIRE DAMAGE 1.00E+00S55.10E 10811ALKIDIARY FEEDWATER PUMP A OIL FIRE OCCURS FULDEMENT FAILS DEFENTION FAILS S5.57E 035.57E 03 S35PM-FIRE S35PM-FIRE S5.57E 03S45					MOV S; 351B	FALLS TO OPEN			7 SOE 03	34RMV-\$13518 CC
ATM PUMP 18 HOV CC 4008       MECHANICAL FAILS 10 OPEN       FAILURE       1.63E 02 7.50E 03       058PHAFM18 PS 34RMY-CC400B CC         S1       1.99E 1/8       MS       AUXILIARY EQUIPMENT FAILS AFM PUMP 18 HEV FAILS 10 OPEN       +EEDWATER PUMP A OIL FIRE OCCURS       6.45E-04 1.00E+00       FEV FI6 FIRE DAMAGE         S1       1.99E 1/8       MECHANICAL EQUIPMENT FAILS AFM PUMP 18 HEV FIRE DAMAGE       +EEDWATER PUMP A OIL FIRE OCCURS       6.45E-04 1.00E+00       FEV FI6 FIRE DAMAGE         S2       5.44E 1/8       1/2       ALXICIARY FUDIPMENT FAILS       FEFDWATER PUMP A OIL FIRE OCCURS HEV FIRE DAMAGE       6.45E 04 1.00E+00       FEV FI6 FIRE DAMAGE         S2       5.44E 1/8       11       ALXICIARY FUDIPMENT FAILS       FEFDWATER PUMP A OIL FIRE OCCURS HEV FIG       6.45E 04 1.00E+00       FEV FIG FIRE DAMAGE         S3       5.5 1/00 L-88       11       ALXICIARY FEEDWATER PUMP A OIL FIRE OCCURS AFW PUMP 18 HEV FIG       FEEDWATER PUMP A OIL FIRE OCCURS AFW PUMP 18 HEV FIG       6.45E-04 1.00E+00       FIRE DAMAGE 1.63E 02 058PM-AFW18 PS 333 HP1-MAN- HE         S4       5.5 1/00 L-88       .11       ALXILIARY FEEDWATER PUMP A OIL FIRE OCCURS AFW PUMP 18 HEV FIG       FEEDWATER PUMP A OIL FIRE OCCURS AFW PUMP 18 HEV FIG       6.45E 1/4       IEV FIG	\$	1 EVE 1	·8	15	AUXILIANY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	IEV-F16
HOVICE GOOB       FAILS TO OPEN       7.50E 03       34RMY-CC400B CC         51       1.59E 148       15       AUXILIARY       FEEDMATER PUMP A OIL FIRE OCCURS       6.45E-04       FEV FI6         51       1.59E 148       15       AUXILIARY       FEEDMATER PUMP A OIL FIRE OCCURS       6.45E-04       FEV FI6         60/000       FIRE-DAMAGE       1.63E 02       05BPH - AFWIR PS       335PMVRHR300B-FO         61       1.63E 02       05BPH - AFWIR PS       7.50E 03       335PMVRHR300B-FO         61       1.63E 02       05BPH - AFWIR PS       7.50E 03       335PMVRHR300B-FO         61       1.00E +00       FIRE-DAMAGE       1.00E+00       FIRE-DAMAGE         61       1.00E +04       12/2       ALKIT TART       FEEDWATER PUMP A OIL FIRE OCCURS       6.45E 04       IEV FI6         61       1.00E +04       11/2       ALKIT TART       FEEDWATER PUMP A OIL FIRE OCCURS       6.45E 04       IEV FI6         63       1.5       10       10/2       10/2       10/2       10/2       10/2         63       1.5       1.5       10/2       11/2       11/2       10/2       11/2         63       1.5       10       11/2       11/2       11/2       11/2       1					EQUIPMENT FALLS	DUE TO FIRE			1.00 <b>E+0</b> 0	FIRE DAMAGE
S1       1.99E-198       1.5       AUXILIARY       FLEDWATER PUMP A OIL FIRE DECURS       6.45E-04       IEV-FI6         S1       1.99E-198       1.5       AUXILIARY       FLEDWATER PUMP A OIL FIRE DECURS       6.45E-04       IEV-FI6         S1       1.99E-198       1.6       AUXILIARY       FLEDWATER PUMP A OIL FIRE DECURS       1.00E+00       FIRE-DAMAGE         S1       0.44       1.6       AUXILIARY       FLEDWATER PUMP A OIL FIRE DECURS       0.45E-04       IEV-FI6         S2       0.44       1.2       AUXILIARY       FLEDWATER PUMP A OIL FIRE DECURS       0.45E-04       IEV-FI6         S2       0.44       1.2       AUXILIARY       FLEDWATER PUMP A OIL FIRE DECURS       0.45E-04       IEV-FI6         S3       1.0012040401       FAILS       DUE-10-FIRE       1.00E+00       FIRE-DAMAGE         HERE 24.74E       0.738       FAILS       DUE-10-FIRE       1.00E+00       FIRE-DAMAGE         S5       1.00E+08       11       AUXILIARY       FLEDWATER PUMP A OIL FIRE OCCURS       0.45E-04       IEV-FI6         S5       1.00E+08       11       AUXILIARY       FLEDWATER PUMP A OIL FIRE OCCURS       0.45E-04       IEV-FI6         S5       1.00E+08       11       AUXILIARY       FLEDWAT					AFM PUMP 18	MECHANICAL	FAILURE		1.63E 02	058PMAFV18 PS
EQUIPMENT FAILS       DUE TO FIRE AFM PUNP 18       FAILURE       1.00E+00       FIRE-DAMAGE         NO       AFM PUNP 18       MECHANICAL       FAILURE       1.63E 02       05BPM - AFW18 PS         NO       AFM PUNP 18       MECHANICAL       FAILURE       1.00E+00       FIRE-DAMAGE         NO       AFM PUNP 18       MECHANICAL       FAILURE       1.00E       05BPM - AFW18 PS         NO       AFM PUNP 18       FEEDWATER PUMP A OIL FIRE OCCURS       61.45E 04       IEV FIG         FUELWATER       UE TO FIRE       FFILS TO OPEN       1.00E 04       FIRE-DAMAGE         NO       AFM PUNP 18       FEEDWATER PUNP A OIL FIRE OCCURS       61.45E 04       IEV FIG         NO       NOE 048       11       AFM PUNP 18       FEEDWATER PUNP A OIL FIRE OCCURS       61.45E 04       IEV FIG         NO       NOE 048       11       AFM PUNP 18       FEEDWATER PUNP A OIL FIRE OCCURS       61.45E 04       IEV FIG         SUE TO FIRE       UE TO FIRE       FAILURE       FAILURE       1.00E 400       FIRE DAMAGE         SUE TO FIRE       UE TO FIRE       FAILURE       FAILURE       50.57E 03       53.5HM1-AFW1B PS         SUE TO FIRE       MECHANICAL       FAILURE       FAILURE       50.57E 03       53.5HM1-AFW1					HOV CC 4008	FAILS TO OPEN			7.50E 03	34RMV-CC400B CC
AFW PUMP 18       MECHANITAL       FAILURE       1.63E 02       058PM - AFWT8 PS         N/       V       HEV FHR 3008       FAILS TO OPEN       7.50E 03       33PMVRHR3008-F0         N/       S. VIE-08       N/       ALKELLARY       FEEDWATER POMP A OIL FIRE OCCURS       6.45E 04       IEV FI6         N/       S. VIE-08       N/       ALKELLARY       FEEDWATER POMP A OIL FIRE OCCURS       6.45E 04       IEV FI6         N/       ALKELLARY       FEEDWATER POMP A OIL FIRE OCCURS       6.45E 04       IEV FI6         N/       VIE       10       FIRE       1.00E 04       31-CV CC3B F0         N/       ALKELLARY       FEEDWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV FI6         N/       N/       ALKELLARY       FEEDWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV FI6         N/       N/       ALKELLARY       FEEDWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV FI6         N/       N/       ALKELLARY       FEEDWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV FI6         N/       N/       ALKELLARY       FEEDWATER PUMP A OIL FIRE OCCURS       6.45E-04       IEV FI6         N/       N/       N/       N/       N/       ALKELARY       FEEDWATER PUMP A OIL	51	• 99£ 1	·8	.,	AUXILIARY	HEEDWATER PUMP A	OIL FIRE DECURS		6.45E-04	IEV-FI6
HEY RHR 3018       FAILS TO OPEN       7 50E 03       33FMVRHR3008-F0         30       5 45E 04       12       ALKETTARY       FEEDWATER PUMP A OLE FIRE OCCURS       5.45E 04       IEV FIG         30       5 45E 04       12       ALKETTARY       FEEDWATER PUMP A OLE FIRE OCCURS       5.45E 04       IEV FIG         50       5 45E 04       11       ALKETTARY       FEEDWATER PUMP A OLE FIRE OCCURS       5.45E 04       IEV FIG         55       5 46E 08       11       ALKETTARY       FEEDWATER PUMP A OLE FIRE OCCURS       6.45E 04       IEV FIG         55       5 46E 08       11       ALKETTARY       FEEDWATER PUMP A OLE FIRE OCCURS       6.45E 04       IEV FIG         55       5 46E 08       11       ALKETTARY       FEEDWATER PUMP A OLE FIRE OCCURS       6.45E 04       IEV FIG         55       5 46E 08       11       ALKETTARY       FEEDWATER PUMP A OLE FIRE OCCURS       6.45E 04       IEV FIG         54       5 50E 08       11       ALKETTARY       FEEDWATER PUMP A OLE FIRE OCCURS       5.57E 03       33 HP1-MAN- HE         54       5 50E 08       11       ALKETTARY       FEEDWATER PUMP A OLE FIRE OCCURS       6.45E 04       IEV FIG					EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
No       Solve Her       No       Alkiniary       FEEDwater Pump A OIL FIRE OCCURS       6.45E 04       IEV FI6         Fu01PMENT FAILS       OUE TO FIRE       1.00E+00       FIRE-DAMAGE         HER VALVE       10 30       FFILS TO OPEN       1.00E+00       FIRE-DAMAGE         SS       5 MoE+08       11       Alexticary       FEEDwater Pump A OIL FIRE OCCURS       6.45E+04       IEV FI6         SS       5 MoE+08       11       Alexticary       FEEDwater Pump A OIL FIRE OCCURS       6.45E+04       IEV FI6         Fullipment Fails       20E to FIRE       Alexticary       FEEDwater Pump A OIL FIRE OCCURS       6.45E+04       IEV FI6         SS       5 MoE+08       11       Alexticary       FEEDwater Pump A OIL FIRE OCCURS       6.45E+04       IEV FI6         SS       5 MoE+08       11       Alexticary       FEEDwater Pump A OIL FIRE OCCURS       5.57E+03       33 HP1+MAN+         SS       5 SVE-08       11       Auxticary       FEEDwater Pump A CIL FIRE OCCUPS       6.45E+04       IEV-FI6					AFW PUMP 18	MECHANICAL	FATLURE		1.63E 02	058PH - AFW18 PS
FU01PMENT FAILS       DUE TO FIRE       1.09E+00       FIRE-DAMAGE         HERK VALVE       UC 38       FFILS TO OPEN       1.09E+00       31-CV CC38 F0         SS       S 16E-08       31       A-HILLIANY       FEEDWATER PUMP A DIL FIRE OCCURS       6.45E-04       IEV FI6         FULIPMENT FAILS       DUE TO FIRE       A-HILLIANY       FEEDWATER PUMP A DIL FIRE OCCURS       6.45E-04       IEV FI6         SS       S 10E-00       FIRE DAMAGE       1.00E+00       FIRE DAMAGE         ALM PUMP 18       MECHANICAL       FAILURE       1.63E-02       05BPMAFW1B-PS         SFERATOR FAILS       TO ESTABLISH       SAFETY INJECTION MANUALLY       5.57E-03       33 HPI-MAN-         Subscript       Stype-08       .11       AUXILIANY       FEEDWATER PUMP A DIL FIRE OCCURS       6.45E-04       IEV-FI6					MEY RHR SOUB	FALLS TO OPEN			7 50€ 0 <b>3</b>	33FMVRHR3008-FO
HERK VALVE UP 38 FFILS TO OPEN 1.00E.04 31-CV CC3B F0 55 5 5556-08 31 A-HELTARY FEEDWATER PUMP A DIL FIRE OCCURS 6.45E-04 IEV FT6 FULTPMENT PAILS DUE TO FIRE 1.00E+00 FIRE DAMAGE AFW PUMP 18 MECHANICAL FAILURE 1.63E-02 05BPMAFW1B PS 3FERATOR FAILS TO ESTABLISH SAFETY INJECTION MANUALLY 5.57E-03 33 HPT-MAN- HE 54 5 59E-08 .11 AURILIARY FEEDWATER PUMP A DIL FIRE OCCURS 6.45E-04 IEV-F16	ł.,	a she o	स	'ړ'	A .KI [ABT	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E 04	IEV FIG
55     51     55     51     54     51     APRILIARY     FEEDWATER PUMP A DIL FIRE OCCURS     6.45E-04     IEV FI6       FULTPMENT FAILS     DUE TO FIRE     1     00E+00     FIRE DAMAGE       AFW PUMP 18     MECHANICAL     FAILURE     1.63E-02     05BPMAFW1B PS       BERATOR FAILS     TO ESTABLISH     SAFETY INJECTION MANUALLY     5.57E-03     33       54     5     54E     11     AUXILIARY     FEEDWATER PUMP A D'L FIRE OCCURS     6.45E-04     IEV-FI6					FUOIPMENT FALLS	DUE TO FIRE			1,09 <b>E+0</b> 0	FIRE-DAMAGE
FULTPMENT FAILS DUE TO FIRE       1.00E+00       FIRE DAMAGE         AFW PUMP 18       MECHANICAL       FAILURE       1.63E-02       05BPMAFW18 PS         OFERATOR FAILS       TO ESTABLISH       SAFETY INJECTION MANUALLY       5.57E-03       33 HPI-MAN- HE         Subscription       SUBSCRIPTION       FEEDWALER PUMP A CIL FIRE OCCURS       6.45E-04       1EV-FI6					HEIK JALVE	50 BB	FFILS TO OPEN		1,00E 04	31-CV CC38 FO
AFW PUMP 18 MECHANICAL FAILURE 1,63E 02 058PMAFW18 PS GERATOR FAILS TO ESTABLISH SAFETY INJECTION MANUALLY 5,57E 03 33 HPI-MAN- HE GUINN SVE 08 11 AUXILIARY FEEDWALER PUMP A CILIFIRE OCCUPS 6,45E (14 1EV-F16	55	5 36E	8	11	A	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45F-04	1EV F16
SPERATOR FAILS TO ESTABLISH SAFETY INJECTION MANUALLY 5.57E-03 33 HPT-MAN- HE S4 5 59E-08 .11 AURILIAEY FEEDWALER PUMP A CIL FIRE OCCURS 6.45E-04 1EV-F16					FULTPMENT FAILS	DOF TO FIRE			1 00E+00	FIRE DAMAGE
S4 S SVE 08 .11 AUXILIARY FEEDWARER PUMP A D'U FIRE OCCURS 6.45E 04 IEV-FI6					AFW PUMP 18	MECHANICAL	FAILURE		1.63E 02	058PMAFW18 PS
					PERATOR FAILS	TO ESTABLISH	SAFETY INJECTION	MANUALLY	5.57E-03	33 HP1-MAN- HE
EUCLEMENT FAILS FOR TO FIRE 1.00E+00 FIRE 1.00E+00 FIRE	¢.,	N NVE G	8	. 11	AUNIL LAFY	FEEDWALER PUMP A	T'U FIRE OCCURS		6.45E /14	1EV-F16
					EDELEMENT FALLS	COE TO FIRE			1.00 <b>F+</b> 00	FIRE-DAMAGE

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 296 of 415

Title: F16: AFW Pump A Scenario (TU-95C) File: F18E6.WLK ( File created by Linking F1RE6.IN Reduced Sum of Cutsets: 5.2700E-05

WLINK \*\* Ver. 3.11 \*\*)

4

NUMBER	CUTSET PROP	B PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
·			KEN DOMES 10	MECHANICAL	FAILURE		1.63E-02	OSBPHAFW18-PS
			AFW PUMP 18 AOV SW 4208	MECHANICAL FAILS TO OPEN	ALCONC.		5.32E-03	02 - AV - SW4208 - FO
					ALL FIRE OCCURE		6.45E-04	1EV-F16
55	5.44E 08	. 10	AUXILIARY		OIL FIRE OCCURS		1,000+00	FIRE-DAMAGE
			EQUIPMENT FAILS		AFW SYSTEM		2,12E-04	056AFWCN
			COMMON CAUSE	FAILURES OF TO LOCALLY	ESTABLISH	INSTRUMENT AIR	3,98E-01	01-1AS-MANHE
							1 (FC D)	151-514
56	5,00# 08	.09	AUXILIARY		OIL FIRE OCCURS		6.45E-04	IEV-FIG FIRE-DAMAGE
			EQUIPMENT FAILS				1.00E+00	058PMAFW18-PS
			AFW PUMP 18	HECHANICAL	FAILURE		1.63E 02	33RMV SISB-FC
			MOV 51 58	FAILS TO CLOSE			4.76E+03	JJANY - 3138 (C
37	4 451 08	. 6 <b>8</b>	AUXICIARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	1EA-E19
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE DAMAGE
			AFW PUMP 18	MECHANICAL	FATLURE		1.63E-02	058PMAFW18-PS
			OPERATOR /AILS	TO STOP BOTH	RHR PUMPS		4,23E-03	341-RHR-STOP-HE
58	4.08E-08	.08	AUXILIARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	IEV-FI6
70	4 <b>x</b>		EQUIPMENT FAILS				1.00E+00	F1RE-DAMAGE
			AFW PUMP 18	MECHANICAL	FAILUNE		1.63E-02	058PMAFW18-PS
			OPERATOR FAILS	TO ESTABLISH	BLEED AND FEED		3,88E-03	36-082085086-HE
10	3.368-08	ίι <b>κ</b>	AUKILIARY	FFEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	IEV-FI6
30	3.306.00	. 50	EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			SW PUMP 181	MECHANICAL	FAILURE		1,40E-02	02-PH-SW181PS
			ROTATING	STRAINER 182	MECHANICAL	FAILURE	3.72E-03	02-FLR-RS182-PS
		04	AUXILIARY		OIL FIRE OCCURS		6.45E-04	1EV-F16
4I)	3 36E 08	.,0	EQUIPMENT FAILS		••••		1.00E+00	FIRE-DAMAGE
			ROTATING	STRAINER 181	MECHANICAL	FAILURE	3,725-03	02-FLR-R\$181-P\$
			SW PUMP 182	MECHANICAL	FAILURE		1,40E 02	02-PH-SW182PS
				CCEDUATED DUMD &	OIL FIRE OCCURS		6.45E-04	IEV-FI6
	3 15E 08	, O	AUXILIARY EQUIPMENT FAILS		OIL TIME OCCORD		1,00E+00	FIRE-DAMAGE
			AFE PUMP 18	MECHANICAL	FAILURE		1.63E.02	058PMAFW18-PS
			BREAKER FRIM	MEC 52A	FAILS TO CLOSE		3.00E-03	40-CB-62A/A5-FC
					Stering Occurs		6.45E-04	1EV-F16
·•.'	2 214 38		А.)¥1.1Ай¥ - холона т. с.н.т. с.		DIL FIRE OCCURS		1,00E+00	FIRE DAMAGE
			EQUIPMENT FAILS		FALLURE		1.40E-02	02-PH-SW181PS
			JW PUMP 181 BREAKER FROM	MECHANICAL MCC+6L7	FAILS TO GLOSE		3.00E-03	40-C8-620/A5-FC
- 3	2 /1E 68	۰.۲	AUXI. LARY	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	IEV-FI6
			EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BREAKER FROM	MCC 620	FAILS TO CLOSE		3.00E-03	40-CB-62D/A4-FC
			SW POMP 182	MECHANICAL	FAILURE		1,40E-02	02-PM-\$¥182PS
~ 4	2.571-08	5	AUXIFIART	FEEDWATER PUMP A	OIL FIRE OCCURS		6.45E-04	1EV-F16
<b>-</b>			EQUIFMENT FAILS				1_00E+00	FIRE-DAMAGE

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 297 of 415

TABLE 4 12 FI6

\*\*\*\*\* DONINANT CUISEIS \*\*\*\*\*

Page: 5

Title: F16: AFW Pump A Scenario (19955) File: F1RE6.WEK ( File created by Inking (FRE6.1) Reduced Sum of Cutsets: 5.2700E-05

NUMBER	CUTSET PR	OB PERCENT	BASIC EVENT NAME					EVENT PROB.	IDENTIFIER
			CHECK VALVE	AFW- 48				1.00E-04	05BCVAFW4B-FO
				TO LOCALLY		INSTRUMENT	AIR	3.98E-01	01-IAS-MANHE
. 5	3 5 26 08	05	AUXILIARY	FEEDWATER PUNP A	OIL FIRE OCCURS			6.45E-04	1EV-F16
45	6.116.10	,,	EQUIPMENT FAILS					1.00E+00	FIRE-DAMAGE
			CHECK VALVE		FAILS TO OPEN			1.00E-04	05BCVAFW1B-FO
				TO LOCALLY	ESTABLISH	INSTRUMENT	AIR	3.98E-01	01-IAS-MANHE
40	2.57E-08	u 05	AUXILIARY	FEEDWATER PUMP A	OIL FIRE OCCURS			6.45E-04	IEV-FI6
41)	2.071.00		EQUIPMENT FAILS					1.00E+00	FIRE-DAMAGE
			AFW PUMP 18	MECHANICAL	FAILURE			1.63E-02	058PMAFW18-PS
			ALR COMPRESSORS		COMMON CAUSE			2.44E-03	01-PM-1ASPCM
. 1	> t1r (.9		AUXILIARY	FEEDWATER PUMP A	OIL FIRE OCCURS			6.45E-04	1EV-F16
47	7,518-00		EQUIPMENT FAILS					1.00E+00	FIRE-DAMAGE
			AFW PUMP 16	MECHANICAL	FAILTRE			1.63E-02	OSBPHAFW18-PS
				TO LOCALLY OPEN				2.20E-03	31-LO-SW1300-HE
	> .aa	()4	AUXILIARY	FEEDWATER PUNP A	OIL FIRE OCCURS			6.45E-04	1EV-F16
4時	2 18E 08	, · · )44	EQUIPMENT FAILS					1.00E+00	FIRE-DAMAGE
			AFW PUMP 18	MECHANICAL	FALLURE			1.638-02	058PM AFW18-PS
			SI PUMP 18					2.07E-03	33RPM5118-PS
			A 191. 1409	FEEDWATER PUNP A				6.45E-04	1EV-F16
	2 YOE 08	مەر.	AUKILIARY		OIC THE OCCORD			1,00E+00	FTRE-DAMAGE
			EQUIPMENT FAILS	MECHANICAL	FALLINF			1.63E 02	058PMAFW18-PS
			AFW PUMP 18 SOV SW 4028	FAILS TO OPEN	· MILLONE			2.00E-03	02-5V-5W4028-FO
				FEEDWATER PUMP A	OT FIRE OCCUPS			6.45E-04	1EV-F16
۴,	2 H 38	1)4 <sub>0</sub>	AUXILIARY		OIL TIME GLOOMS			1.00E+00	FIRE DAMAGE
			EUULPHENT FAILS	MECHANICAL	SATE UPF			1.63E-02	0580H- AFW18-PS
			AFW PUMP 18 17 33113					2.00E-03	36-5V-33113FO

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 298 of 415

WLINK \*\* Ver. 3.11 \*\*)

TABLE 4 13 FL7

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 1

EVENT PROB. IDENTIFIER

Title: F17: AFW Pump B Fire File: FIRE7.WLK ( File created by linking FIRE7.IN Reduced Sum of Cutsets: 2.9670E-05

NUMBER CU	TSET PRO	B PERCENT	BASIC	EVENT	NAME
-----------	----------	-----------	-------	-------	------

ROMOCH	GO BET FROM	- <u>(</u> <b>N</b> ) ( <b>H</b> )	UNDIC LICHT NAME	•			CTCHT TRODI	IVENITIES.
	•		<u>.</u>		• ••• •••••	· · · · · · · · · · · · · · · · · · ·		·····
۱	1.67E-05	50.29	AUXILIARY	FEEDWATER PUMP E	OIL FIRE OCCURS		6.20E-05	1EV-F17
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO START AND	LOAD DIESEL	FROM DSP	2.69E-01	42-DGA-DSPHE
S	5.00E-06	16.35	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO ESTABLISH	SERVICE WATER	FROM DSP	8.06E·02	02-SWA-DSPHE
3	5.22E 06	10. <b>85</b>	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	IEV-FI7
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO ESTABLISH	AFW FLOW FROM	DSP	5.19E-02	058AF3-DSPHE
**	1 52E 06	4.45	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	JEV-F17
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			DIESEL GENERATOR	1.4	FAILURE TO START	AND RUN	2.13E-02	10-GE-DG1APS
5	1-)1E-06	5.40	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	IEV-F17
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 1A	MECHANICAL	FAILURE		1.63E-02	058PH- AFW1A-PS
ð	5 308 07	1, 11	AUXILIARY	FEEDWATER PUMP 8	OIL FIRE OCCURS		6.20E-05	1EV-F17
			EQUIPMENT FAILS				1.00 <b>E+00</b>	FIRE-DAMAGE
			AOV SU 301A	FALLS TO OPEN			5.32E-03	02-AV-SW301A-CC
,	5.06E 07	1 03	AUXILIARY	HEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	IEV-FI7
			EQUIPMENT FALLS				1.00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO ESTABLISH	COMPONENT	COOLING FROM DSP	3.08E-02	31-CCL-DSPHE
			OPERATOR FALLS	TO ESTABLISH	CHARGING USING	DSP	1.60E-01	35-CHP-DSPDHE
8	2 908 07	1.00	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
			FUUEPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			MOV BI ZA	FAILS TO CLOSE			4.77E-03	07-NVBT2A-00
ų,	2.516 07	. 78	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
			EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			TRAVELING WATER	CREEN 1A1	MECHANICAL	FAILURE	3.72E-03	02-FLT-TWIAT PS
1.1	1 97E 07	56	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
			EQUIFMENT FAILS				1 00E+00	FIRE-DAMAGE
			FERATOR FALLS	10 ESTABLESH	CHARGING USING	OSP	. ಚ <b>3E</b> - 01	35-CHP-DSP HE
			-FERATOR FALLS	TO ESTABLISH	COMPONENT	CODLING FROM DSP	3.08E-02	31-CCL-DSPHE
			A	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
; :	1 86r 07	. 63						
<b>!</b> !	1 Bor 97		EQUINMENT FALLS	DUE TO FIRE			1.00E+00	FIREDAMAGE
<u>•</u> •	1 BOF 07		EQUINMENT FALLS		FAILS TO CLOSE		1.00E+00 3.00E+03	FIRE-DAMAGE 40-CB-52D/A6-FC
11	1 86E 07		EQUINMENT FAILS RREAKER FROM					

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 299 of 415

TABLE 4-15 F17

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 2

Title: F17: AFW Pump 8 Fire File: F1RE7.WLK ( File created by linking F1RE7.IN WEINK \*\* Ver. 3.11 \*\*) Reduced Sum of Cutsets: 2.9670E-05

NUMBER	CUTSE	PROB	PERCENT	BASIC EVENT NAME	E			EVENT PROB.	IDENTIFIER
		•		BREAKER 1 509	FAILS TO CLOSE			3.00E-03	39-CB-1-509FC
13	). 86E	07	.63	AUXILIARY	FEEDWATER PUMP E	OIL FIRE OCCURS		6.20E-05	LEV-FL7
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				BREAKER 1-501	FAILS TO OPEN			3.00E-03	39-CB-1-501FO
1 4	1.24E	-07	. 42	AUXILIARY	FEEDWATER PUNP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
				EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				SOV AFW-111A	FAILS TO OPEN			2.00E-03	05BSVAFW111A-CC
15	1.228	07	.41	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	IEV-FI7
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				COMMON CAUSE	FAILURE OF BOTH	DIESEL	GENERATORS	1.97E-03	10-GE-DGABCH
16	8.31E	0 <b>8</b>	. 28	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				AFY PUMP 1A	UNAVAILARLE	DUE TO TEST OR	MAINTENANCE	1,34E+03	058PN AFW1A- TH
17	8 5af	0 <b>8</b>	22	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	IEV-FI7
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				OPERATOR FAILS	TO ESTABLISH	CHARGING USING	DSP	1.03E-01	35-CHP-DSPHE
				CCW PUMP A	MECHANICAL	FAILURE		1.03E-02	31-PNCCW1A-PS
18	4 53E	0 <b>8</b>	. 15	AUXILIARY	FEEDWATER PUHP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
				EQUIPMENT FAILS	DUE TO FIRE			1.00E-00	FIRE-DAMAGE
				NO SERVICE WATER	DUE TO	COMMON CAUSE	FAILURES	7.30E-G4	02SWSCM
19	1.51E	98	04	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	IEV-F17
				EQUIPMENT FAILS	OUE TO FIRE			1.00E+00	FIRE-DAMAGE
				CUMMON CAUSE	FAILURES OF	AFW SYSTEM		2.12E-04	058AFWCM
20	1-226	<b>'8</b>	. 14	ACTELIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
				EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				Sw PUNP 1A1	MECHANICAL	FAILURE		1.40E-02	02-PM-SW1A1PS
				SW PUMP TA2	MECHANICAL	FAILURE		1.40E-02	02-PM-SW1A2PS
2.	820E	γ <b>y</b>	12	AUXILIARY	FEEDWATER PUMP 8	OIL FIRE OCCURS		6.20E-05	1EV-F17
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE - DAMAGE
				CHECK VALVE	MU 301	FAILS TO OPEN		1.00E-04	27-CV-MU301FO
22	6 29E	.; <b>9</b>		A. RTI CAPY	FEEDWATER PUMP 8	OIL FIRE OCCURS		5 20E-05	1EV-F17
				EURIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				HELK VALVE	AFW 4 <b>A</b>	FAILS TO OPEN		1.00E-04	USBCV- AFW4A - FO
23	6 20E	U <b>V</b>	02	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-0'	LEV-FI7
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				CHELK VALVE	AFW IA	FAILS TO OPEN		1.00E-04	058CVAFW1A-FO
24	કરમ	άΨ	.92	AUXILIAHY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
				EQUIEMENT FAILS	NUE TO FIRE			1.00E+00	FIRE DAMAGE

TABLE 4 13 F17

\*\*\*\*\* DONINANT CUTSETS \*\*\*\*\*

Page:

3

Title: F17: AFW Pump B Fire File: F1RE7.WLK ( File created by linking F1RE7.1N Reduced Sum of Cutsets: 2.9670F-05

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
			CHECK VALVE	MU-311A	FALLS TO OPEN		1.00E-04	058CV-MU311A-FO
15	3.23E 09	01	AUXILIARY	FEEDWATER PUMP B	OTI FIRE OCCURS		6.20E-05	1EV-F17
25	3.236 04	.01	EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			SU PUMP' 1A1	MECHANICAL	FAILURE		1.40E-02	02-PN-SWIA1PS
			ROTATING	STRAINER 142	HECHANICAL	FAILURE	3.72E-03	02-FLR-RS1A2-PS
26	\$ 238 09	11	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.208-05	1EV-F17
10			EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			ROTATING	STRAINER 1A1	NECHANICAL	FAILURE	3.72E-03	02-FLR-RS1A1-PS
			SW PUMP 1A2	MECHANICAL	FAILURE		1.40E-02	02-PH-SW1A2PS
27	2 601 19	.01	AUXILIARY	FEEDWATER PUMP 8	OTH FIRE OCCURS		6.20E-05	1EV-F17
•			EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			SH PUMP 1A1	MECHANICAL	FALLURE		1.40E-02	02-PM-SW1A1PS
			BREAKER FROM	MCC-52D	FAILS TO CLOSE		3.00E-03	40 · C8 · 520/A5 · FC
28	2 608 119	01	AUXILIARY	FEEDWATER PUNP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
10				DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BREAKER FROM	MCC 520	FAILS TO CLOSE		3.00E-03	40-CB-52D/A4-FC
			SU PUMP 1A2	MECHANICAL	FAILURE		1.40E-02	02-PN-SW1A2PS
29	2 526 09	61	AUXILIARY	FEEDWATER	OIL FIRE OCCURS		6.20Ł-05	1EV-F17
	• /20 /2		EQUIPMENT FAILS	OUE TO FIRE			1.00E+00	FUPE-DAMAGE
			SW PUMP 1A1	UNAVATLABLE	DUE TO TEST OR	MAINTENANCE	2.90E-03	02-PN-SWP1A1-TH
			SW PUMP 1A2	MECHANICAL	FALLURE		1.40E-02	02-PH-SW1A2PS
5.;	2 116 39	.01	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	IEV-FI7
2.7			EQUIPMENT FALLS	OUE TO FIRE			1.00E+00	FIRE-DAMAGE
			OPERATOR FALLS	TO ESTABLISH	CHARGING USING	OSP	1.03E-01	35-CHP-DSPHE
			BOTH COW PUMPS	FAIL DUE 10	LOSS OF OFFSITE	POWER	3.30E-04	31-PM-CCWTAB-CM
31	2.026-69	11	AUX JE LARY	FEEDWALER PUMP 6	OIL FIRE OCCURS		6.20E-05	IEV-FI7
1	••••		EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			NO CHARGING FLOW		COMMON CAUSE	FAILURES	1.06E-03	35CHP M
				TO ESTABLISH	COMPONENT	COCLING FROM DSP	3.08E-02	31-CCL-DSP- HE
32	1 - 9F - 9A	1()	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	LEV-F17
			EQUIPMENT FALLS	DUE TO FIRE			1,00E+00	FIRE-DANAGE
			BREAKER FROM	BUS BRA 102 TO	BUS BRA-104	TRANSFERS OPEN	2.40E.05	38-CBA102-04-CO
55	1 498 99		AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
			EQUIPMENT FAILS	DIE TO FIRE			1.00E+00	FIRE-DANAGE
			BREAKER 15208	TRANSFERS OPEN			2.40E-05	40-C815208 CO
54	1.496 39	បា	AUXILIA6 Y	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	JEV-F17
			EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			BREAKER 15201	TRANSFERS OPEN			2.40E-05	40- <b>CB15</b> 201-CO
\$5	1 49E -79	.0 <b>1</b>	AUKILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6 20E CS	IEV FI7

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 301 of 415

TABLE 4-13 F17

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page:

4

#### Title: FI7: AFW Pump B Fire File: FIRE7.WLK ( File created by Linking FIRE7.IN WLINK \*\* Ver. 3.11 \*\*) Reduced Sum of Cutsets: 2 9670E-05

NUMBER	CUISET	PROS	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
				EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
				TRANSFORMER	SUPPLY BREAKER	1-50 <b>5</b>	TRANSFERS OPEN	2.40E-05	39-CB1-505-CO
56	1.495	ng	01	AUXILIARY	FEEDWATER PUMP	B DIL FIRE OCCURS		6.20E-05	1EV-F17
<b>J</b> U	1.40	•		FQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				BREAKER 15206	TRANSFERS OPEN			2 40E-05	40-CB15206-CO
37	1.20E	04	.00	AUXILIARY	FEEDWATER PUMP	B OIL FIRE OCCURS		6.20E-05	IEV-F17
· ·				EQUIPMENT FALLS	DL TO FIRE			1.00E+00	FIRE-DAMAGE
				TRANSFORMER	1-52	FAILURE		1,94E-05	40-TR1-52SG
38	8.58E	ŧú	.00	AUXILTARY	FEEDWATER PUMP	B OIL FIRE OCCURS		6.20E-05	IEV-FL7
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				ROTATING	STRAINER JAT	MECHANICAL	FAILURE	3.72E-03	02-FLR-RS1A1-PS
				ROTATING	STRAINER 142	MECHANICAL	FAILURE	3.72E-03	02-FLR-RS1A2-PS
39	1 44E	10	.00	AUXILIARY	FEEDWATER PUMP	B OIL FIRE OCCURS		6.20£-05	1EV-F17
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE - DANAGE
				ADV MU-38	TRANSFERS OPEN			1.20E-05	03-AVMU38CO
4()	7 44E	10	. 00	AUXILIARY	FEEDWATER PUNP	B OIL FIRE OCCURS		6.20E-05	1EV-F17
				EQUIPMENT FALLS	DUE TO FIRE			1.0UE+00	FIRE-DAMAGE
				AUV MU SA	TRANSFERS OPEN			1.20E-05	03-AVMU3A -CO
41	6.92E	10	.00	AUXILIARY	FEEDWATER PUMP	B OIL FIRE OCCURS		6.20E-05	1EV-F17
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				BREAKER FROM	MCC 52D	FALLS TO CLOSE		3.00E-03	40-C8-520/A4-FC
				ROTATING	STRAINER 1A2	MECHANICAL	FAILURE	3.72E-03	02-FLR-RS1A2-PS
42	6 92E	10	.00	AUXILIANT	FEEDWATER PUMP	B OIL FIRE OCCURS		6.20E-05	IEV-F17
-				EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAKAGE
				ROTATING	STRAINER 1A1	MECHANICAL	FAILURE	3,72E-03	02-FLR-RS1A1-PS
				BREAKER FROM	NCC-520	FAILS TO CLOSE		3.00E-03	40-CB-520/A5-FC
45	6.77E	- 10	.00	AUXILIARY	FEEDWATER PUMP	B OIL FIRE OCCURS		6.20E-05	1EV-F17
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE DAMAGE
				NO CHARGING FLOW	DUE TO	COMMON CAUSE	FAILURES	1.06E-03	35CHP CM
				CCW PUMP A	MECHANICAL	FALLURE		1.03E+02	31 - PH JCH1A - PS
4a 44	6.6¥8	10	. 50	AUKILIARY	FEEDWATER PUMP	B OIL FIRE OCCURS		6.20E 05	1EV-FI7
				E-JUIEPMENT FALLS	OUE TO FIRE			1.00E+00	FIRE-DAMAGE
				SW POMP 1A1	UNAVALLABLE	DUE TO FEST OR	MAINTENANCE	2.90E-03	02-PH-SWP*A1 TH
				ROFATING	STRAINER 142	MECHANICAL	FAILURE	3.72E-03	02-FLR-RS1A2 PS
45	6.39E	10	.00	AUNTELANY	FEEDWATER PUMP	B OIL FIRE OCCURS		6.20E 05	TEV-F17
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE DAMAGE
				OPERATOR FAILS	TO ESTABLISH	CHARGING USING	DSP	1.03E-01	35-CHP-DSP HE
				CHECK VALVE	CC 3A	FAILS TO OPEN		1,00E-04	31 CVCC3A-FO
<b>م</b> و	8.25E	- 10	.00	AUXILIARY	FEEDWATER PUMP	B OIL FIRE OCCURS		6.20E-05	IEV-F17

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 302 of 415

TABLE 4-13 F17

\*\*\*\*\* DONINANT CUTSETS \*\*\*\*\*

Page: 5

#### Title: F17: AFW Pump B Fire File: FIRE7.WLK ( File created by Linking FIRE7.IN WLINK \*\* Ver. 3.11 \*\*) Reduced Sum of Cutsets: 2.9670E-05

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAME	i.			EVENT PROB.	IDENTIFIER
	· · ·		EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			SW PUMP 1A1	MECHANICAL	FAILURE		1.40E-02	02-PM-SW1A1PS
			SW STRAINER 142				7.20E-04	02-FL-1A2PL
47	5,58E 10	ΩĐ	AUXILIARY	FEEDWATER PUHP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
47	1,106 10	.00	EQUIPMENT FAILS				1.00E+00	FIRE-DANAGE
			BREAKER FROM	MCC - 520	FAILS TO CLOSE		3.00E-03	40 C8-520/A4-FC
			BREAKER FROM	NCC-52D	FAILS TO CLOSE		3.00E-03	40-C8-52D/A5-FC
48	5.39E 10	00	AUXILIARY	FEEDWATER PUNP B	DIL FIRE OCCURS		6,20E-05	IEV-FI7
40	). JAC 10	.00	EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			SH PUMP 1A1	UNAVAILABLE	DUE TO TEST OR	MAINTENANCE	2.90E-03	02-PH-SUP1A1-TH
			BREAKER FROM	MCC-52D	FAILS TO CLOSE		3.00E-03	40-08-520/A5-FC
49	4.96E 10	00	AUXILIARY	FEEDWATER PUMP B	OIL FIRE OCCURS		6.20E-05	1EV-F17
4 <del>7</del>	4, YOE IV		EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			BREAKER BRA- 104		TRANSFERS OPEN		8.00E-06	38-CBA104-07-CO
		00	AUXILIARY	FE JWATER PUMP B			6.20E-05	1FV-F17
50	4.89E 10	.00	EQUIPMENT FAILS		0.0		1.00E+00	FIRE-DAMAGE
			RELIEF VALVE		FAILS TO CLOSE		1.60E-02	35-ANCVC101A-FC
			RELIEF VALVE	CVC-101C	FAILS TO CLOSE		1.60E-02	35-AMCVC101C-FC
			OPERATOR FALLS	TO ESTABLISH	COMPONEN?	COOLING FROM DSP	3.08E-02	31-CCL-DSPHE

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 303 of 415

TABLE 4-14 FI8

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page:

1

Title: F18: Fire in TU-95A Between Buses 51 and 52 File: F1RE8.WLK ( File created by Linking F1RE8.IN Reduced Sum of Cutsets: 3.3300E-06

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
• • • •								
1	9.90E-07	20 78	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-F18
T	9.90E-07	29.13	EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			DIESEL GENERATOR		FALLURE TO START	AND RUN	2.13E-02	10-GE-DG18PS
							/ AFF-05	IEV-FI8
2	4. <b>79E</b> -07	14.38	FIRE NEAR BUSES				4.65E-05	FIRE-DAMAGE
			EQUIPMENT FAILS				1.00E+00	31-PMCCW1B-PS
			CCW PUMP B	MECHANICAL	FAILURE		1.03E-02	21*PH- CCM18-P3
5	5.66E-07	10,99	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-FI8
-			EQUIPHENT FALLS				1.00E+00	FIRE-DAMAGE
				TO START AND	LOAD DIESEL	MANUALLY	7.87E-03	42-DG8-MANHE
	o. 10 √.7	• .,		51 AND 52 OCCURS			4.65E-05	IEV-FI8
4	2.47E 07	1.42	FIRE NEAR QUSES				1,00E+00	FIRE-DAMAGE
							5.32E-03	02-AV-SW3018-CC
			AOV S₩-3018	PATES TO OPEN				
5	1 738 07	5.20	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	ILV-FI8
,			EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
				SCREEN 182	MECHANICAL	FAILURE	3.72E-03	02-FLT-TW182-PS
				ST AND ST OF CIDE			4.65E-05	1EV-F18
6	1 4116 117	4 20	FIRE NEAR BUSES				1.00E+00	FIRE-DAMAGE
				MCC 62D	FAILS TO CLOSE		3.00E-03	40-C8-62D/A6-FC
7	1.4°E 07	4.20	FIRE NEAR " SES	51 AND 52 OCCURS			4.65E-0*	1EV F18
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			EREAKER 1-603	FAILS TO CLOSE			3.00E - 03	39-C8-1-603FC
8	1.40£ 07	<b>4</b> 2.7	FIRE NEAR BUSES	51 AND 52 OCCURS			4 65E-05	IEV-F18
0	1,402 0		EQUIPMENT FALLS				1.JOE+00	FIRE-DAMAGE
			HALAKER 1 601				3.)0E-03	39-C8-1-601F0
							4.65E-05	IEV-FIB
Ş	1,10E 07	2.30	-IRE NEAR BUSES				1.00E+00	FIRE-WAMAGE
				UNAVATLABLE	NE TO TEST OR	HATHTENANCE	2.37E-03	31-PHCCW18-TH
			C(A NOWN 18	CHRYMICADLC	SE TO FEST ON			_
•	2 168 3	्र •९	FIRE NEAR DUSES	51 AND 52 OCCURS			4.65E-05	IEV-F18
			EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			COMMENCIAUSE	FALCHRE OF BOTH	DIESEL	GENERATORS	1,97E-03	10-GE-DGA8CM
; 1	8 996 98	۰. م	FIRE NEAR BUSES	51 AND 52 DECURS			4.65E-05	IEV-FI8
			- FMENT FALLS				1.00E+00	FIRE-DAMAGE
				TO ESTABLISH	SERVICE WATER	MANUALLY	1.72E.03	02-SWB-MANHE
				Et AUD ED SOCIOS			4.65E.05	IEV-FI8
1,3	7 39E 18	0.20	FIRE NEAR BUSES				1.00E+00	FIRE-DAMAGE
			EQUIPMENT FAILS		MANHALLY		1,598-03	31-CCL-MAN HE
			"HERBUCK FRE'S	TO ESTABLISH COW	THINKLL !			

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 304 of 415

TABLE 4-14 F18

Title: F18: Fire in TU 95A Between Buses 51 and 52 File: F1RE8.WLK ( File created by Linking F1RE8.1N Reduced Sum of Cutsets: 3.3300E-06

WLINK \*\* Ver. 3.11 \*\*)

Z

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
15	5.89E-0 <b>8</b>	1 77	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-FI8
( <sup>,</sup>	).04E 90			DUE TO FIRE			1,00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO ESTABLISH	AFW FLOW	MANUALLY	3,18E-03	05BAF3-MANHE
			OPERATOR FAILS	TO LOCALLY	ESTABLISH	INSTRUMENT AIR	3,98E-01	01-IAS-MANHE
14	4.13E 08	1.24	FIRE NEAR BUSES	51 AND 52 OCCUPS			4.65E-05	1EV-F18
-			EQUIPMENT FAILS	JE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 18	HECHANICAL	FAILURE		1.63E-02	058PMAFW18-P\$
			TURBINE DRIVEN	AFW PUMP 1C	NECHANICAL	FAILURE	1.372-01	058PTAFW1C-PS
			OPERATOR FAILS	TO LOCALLY	ESTABLISH	INSTRUMENT AIR	3,98E-01	01-1AS-MANHE
15	3.39E-08	1.02	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-FI8
			EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			NO SERVICE WATER	DUE TO	COMMON CAUSE	FAILURES	7,3)E-04	02SWSCM
16	2.22E-08	.67	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	LEV-F18
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO ESTABLISH	AFW FLOW	MANUALLY	3.18E-03	05BAF3-MANHE
			OPERATOR FAILS	TO ESTABLISH	SAFETY INJECTION	MANUALLY	1,50E-01	33-HPI-MANDHE
17	1.538 08	.46	FIRE NEAR BUSES	ST AND 52 OCCURS			4.65E-05	IEV-FI8
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BOTH COW PUMPS	FAIL DUE TO	LOSS OF OF TE	POWER	3.30E-04	31-PM-CCW1AB-CH
18	1.25E-08	. 38	FIRE NEAR BUSES	S1 AND 52 OCCURS			4.65E-05	1EV-F18
			EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE DAMAGE
			OPERATOR HALLS	TO ESTABLISH	AFW FLOW	MANUALLY	3.18E-03	05BAF3-MANHE
			COMPRESSOR 18	MECHANICAL	FAILURE		8.44E-02	01-PM-SIAC18-PS
19	9.118 19	27	FIRE NEAR BUSES	ST AND 52 OCCURS			4.65E-05	1EV-F18
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			SW PUMP 181	NELHANICAL	FALLURE		1_40E-02	02-PM-SW181PS
			SW PUMP 182	MECHANICAL	FAILURE		1.40E-02	02-PH-SW182PS
<u>ن</u> ،	5.70F	.26	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-FI8
			EQUIPMENT FALLS	DUE TO FI E			1.00E+00	FIRE-DANAGE
			AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PMAFW18-PS
			" RBINE DRIVEN	AFW PUMP 10	MECHANICAL	FAILURE	1.37E-1	05BPTAFW1C-PS
			COMPRESSOR 18	MECHANICAL	FAILURE		8.44E-02	01-PM-SIAC18-PS
. 1	9. Twe 39	ي، ب	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-F18
			+ JUJEMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			DIESEL GENERATOR	18 UNAVAILABLE	DUE TO TEST OR	MAINTENANCE	1.75E-04	'⊍ GE+DG18™
	શ ્વર જ	<u>)</u>	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-F18
			EQUIPMENT FAILS	ULE TO FIRE			1.00E+00	FIRE-DAMAGE
			<i>пс</i> ₩ неат ексн 18	UNAVAILABLE	DUE TO TEST OR	MAINTENANCE	1,73E-04	31-NECCW18-TM
.3	5.07E-09	. 15	FIRE NEAR BUSES	ST AND SZ OCCURS			4.65E 05	IEV-FI8
			EQUIEMENT FAILS				1.00E+0C	FIRE-DAMAGE

4-117

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 305 of 415

TABLE 4-14 F18

\*\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 3

Title: F18: Fire in TU-95A Between Buses 51 and 52 File: F1RE8.WLK ( File created by linking F1RE8.IN Reduced Sum of Cutsets: 3.3300E-06

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAM	E			EVENT PROB.	IDENTIFIER
			SOV AFW-1118	FAILS TO OPEN			2.00E-03	058SVAFW1118-CC
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FAILURE	1.37E-01	058PTAF21C-PS
			OPERATOR FAILS	TO LOCALLY	ESTABLISH	INSTRUMENT AIR	3.98E-01	01-1 <b>AS-M</b> ANHE
24	4.652-09	_ 14	FIRE NEAR BUSES	51 AND 52 OCCURS	5		4.65E-05	IEV-FI8
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			CHECK VALVE	CC - <b>38</b>	FAILS TO OPEN		1.00E-04	31-CVCC38-FO
25	4.56F-09	. 14	FIRE NEAR BUSES	51 AND 52 OCCURS	;		4.65E-05	IEV-FI8
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			AFW PUMP 18	UNAVAILABLE	DUE TO TEST OR	MAIHTENANCE	1.80E-03	058PHAFW18-TH
			TURBINE DRIVEN	AFW PUMP 1C	MECHANICAL	FALLURE	1.37E-01	05BPTAFW1C-PS
			OPERATOR FAILS	TO LOCALLY	ESTABLISH	INSTRUMENT AIR	3.98E-01	01 · IAS - MAN HE
26	3.92E-09	. 12	FIRE NEAR BUSES	51 AND 52 - 11RS	i		4.65E-05	1EV-F18
			EQUIPMENT FAILS	DUE TO FIRE			1.0Cc+00	FIRE-DAMAGE
			COMMON CAUSE	FAILURES OF	AFW SYSTEM		2.12E-04	058AFWCN
			OPERATOR FALLS	TO LOCALLY	ESTABLISH	INSTRUMENT AIR	3.98E-01	01-145-MANHE
27	2.42E-09	.07	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-F18
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			SW PUMP 181	MECHANICAL	FAILURE		1.40E-02	02-PH-SU181PS
			ROTATING	STRAINER 182	MECHANICAL	FAILURE	3.72E-03	02-FLR-R\$182-P\$
28	2.42E-09	.07	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E.05	IEV-FI8
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			ROTA" ING	STRAINER 181	HECHANICAL	FAILURE	3.72E-03	02-FLR-RS181 PS
			SW PUMP 182	MECHANICAL	FAILURE		1.40E-02	02-PH-SW182PS
29	2.26E 09	.07	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	EV-FI8
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+09	FIRE-DAMAGE
			AFW PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PMAFW18-PS
			HOV MS 102	FAILS TO OPEN			7.50E-03	06-MVMS102-CC
			OPERATOR FALLS	TO LOCALLY	CSTABL (SH	INSTRUMENT AIR	3.98E-01	01-IAS-NANHE
50	1.25E-09	.06	TIRE NEAR BUSES	51 AND 52 OCCURS			4.65E.05	IEV-FI8
			HOUIPMENT FALLS	DHE TO FIRE			1.00E+00	FIRE-DAMAGE
			- PUMP 181	HECHANICAL	FAILURE		1.40E-02	02-PH-SW181-PS
			BREAKER FROM	MCC-62D	FAILS TO CLOSE		3.∩0E-03	40-CB-62D/A5-FC
51	1. 45E - U9	. 06	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	JEV-FI8
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			GREAKER FROM	MCC-620	FAILS TO CLOSE		3.00E-03	40-CB-62D/A4-FC
			SW PUMP 182	MECHANICAL	FAILURE		1.40E-02	02-PM-SW182- PS
32	27E 09	. 04	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-FI8
			EQUIPMENT FAILS	OUE TO FIRE			1.00E+00	FIRE-DAMAGE
			CCW HEAT	EXCHANGER 18	SHELL LEAK		2.74E-05	31-HECCW*B-HS
33	1,128 09	.03	FIRE NEAR BUSES	51 AND LO DICURS			4.65E-05	IEV-F:B

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 306 of 415

TABLE 4-14 F18

\*\*\*\* DOMINANT CUTSETS \*\*\*\*\*

Page: 4

Title: F18: Fire in TU-95A Between Buses 51 and 52 File: FIRE8.WLK ( File created by Linking FIRE8.IN Reduced Sum of Cutsets: 3,3300E-06

NUMBER	CUTSET PROB	PERCENT	BASIC EVENT NAME				EVENT PROB.	IDENTIFIER
•••••			EQUIPMENT FAILS				1.00E+00	FIRE-DAMAGE
			AFH PUMP 18	MECHANICAL	FAILURE		1.63E-02	058PNAFW18-PS
			AFW PUMP 1C	AUX LUBE OIL	PUMP MECHANICAL	FAILURE	3.72E-03	058PM-ALOP1C-PS
			OPERATOR FAILS	TO LOCALLY	ESTABLISH	INSTRUMENT AIR	3.98E-01	01-IAS-MANHE
34	1.12E-09	.03	FIRE NEAR BUSES	51 AND 52 OCCURS	;		4.658-05	1EV-F18
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BREAKER FROM	BUS BRB-102 TO	BUS BRB-104	TRANSFERS OPEN	2.40E-05	38-C89102-04-CO
۰,	1.12E 09	.03	FIRE NEAR BUSES	51 AND 52 OCCURS	i		4.65E-05	IEV-FI8
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BREAKER 16208	TRANSFERS OPEN			2.40E-05	40-CB16208-CC
36	1.12E-09	.05	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-F18
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BREAKER 16201	TRANSFERS OPEN			2.40E-05	40-0816201-00
37	1.12E-09	.03	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-F18
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			TRANSFORME	SUPPLY BREAKER	1-607	TRANSFERS OPEN	2.40E-05	39-081-607-00
58	1.12E-09	.03	FIRE NEAR BUSES	51 AND SE COTURS			4.65E-05	1EV-F18
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			BPEAKER 16101	TRANSFERS OPEN			2.40E-05	40-0816101-00
39	1.11E 09	.03	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-FI8
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			OPERATOR FALLS	TO ESTABLISH	AFW FLOW	MANUALLY	3.18E-03	05BAF3-MANHE
			HOV S1-48	FALLS TO OPEN			7.50E-03	331MV\$148-CC
40	1,118-09	.03	FIRE NEAR BUSES	51 AND 52 JUCURS			4.65E-05	1EV-F18
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO ESTABLISH	AFW FLOW	MANUALLY	3.18E 03	058AF3-MANHE
			MOV 51 3508	FAILS TO OPEN			7.50E-03	34RMV-\$13508-CC
<b>_</b> 1	1.116-09	9 <b>3</b>	FIRE NEAR BUSES	51 Map 52 OCCURS			4.65E-05	IEV-F18
			FOUTEMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			UNERATOR FAILS	TO STABLISH	AFW FLOW	MANUALLY	3. 8E-03	058AF3-MANHE
			MOV 51 3518	FAILS O OPEN			7.50E-03	34RMV-S13518-CC
·	1 116 99	3	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-FI8
			EQUIEMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			OPERATOR FAILS	TO ESTABLISH	AFW FLOW	MANUALLY	3.18E-03	OSBAF3-MANHE
			MOV 710 40118	FALLS TO OPEN			7.50E 03	34RMV-6/24008-CC
43	1.1°E-09	.03	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	1EV-F18
			EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
			OPERATOR FALLS	TO ESTABLISH	AFW FLOW	MANUALLY	3.18E-03	05BAF3-MANHE
			W. V RHR SOCB	FAILS TO OPEN			7.50E-03	33RMVRHR3008-FO

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 307 of 415

TABLE 4-14 F18

\*\*\*\*\* JONINANT CU\*SETS \*\*\*\*\*

Page: 5

Title: F18: Fire in TU-95A Between Buses 51 and 52 File: F1RE8.WLK ( File created by linking F1RE8.1N Reduced Sum of Cutsets: 3.3300E-06

NUMBER	CUTSET	PROB	PERCENT	BASIC EVENT HAM	E			EVENT PROB.	IDENTIFIER
-	-			· · · · · · · · · · · · · · · · · · ·				•••••	
14-54	1.08E	09	.03	FIRE NEAR BUSES	51 AND 52 OCCURS			4.655-05	IEV-FI8
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				SUV AFW-1118	FAILS TO OPEN			2.00E-03	058SVAFW1118-CC
				TURBINE DRIVEN	AFW PUMP 1C	MECHANICA	FAILURE	1.37E-01	058PTAFW1C-PS
				COMPRESSOR 18	MECHANICAL	FAILURE		8.44E-02	01-PM-SIAC18-PS
45	4.68F	10	03	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-F18
				EQUIPMENT FAILS	DUE TO FIRE			1.00€+00	FIRE-DAMAGE
				AFW PUMP 18	UNAVAILABLE	DUE TO TEST OR	MAINTENANCE	1.80E-03	058PHAFW18-TH
				TURBINE DRIVEN	AFW PUNP 1C	HECHANICAL	FAILURE	1.37E-01	058PTAFW1C-PS
				COMPRESSOR 18	MECHANICAL	FAILURE		8.44E-02	01-PH-SIAC18-PS
<b>"</b> b	9 05E	10	.03	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-U5	1EV-F18
				EQUEPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				AFW PUMP 18	MECHANICAL	FAILURE		1.636-02	058PNAFW18-PS
				AFW PUMP 1C	UNAVAILABIE	DUE TO TEST OR	MAINTENANCE	3.00E-03	058PNAFW1C-TH
				OPERATOR FAILS	TO LOCALLY	ESTABLISH	INSTRUMENT AIR	3 98E-01	01-125-MAN HE
41	9-02E	19	. 93	FIRE NEAR BUSES	ST AND 52 OCCURS			4.658-05	IEV-FI8
				FORPHENT FALLS	DUE TO FARE			1.00E+00	FIRE-DAMAGE
				TRANSFORMER	1 62	FAILURE		1.94E-05	40-1R1-62SG
1 <b>.</b> <sup>1</sup> 1	9-02F	10	.03	FIRE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	IEV-FI8
				EQUIPMENT FALLS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				TRANSFORMER	1 61	FAILURE		1.94E-05	40-TR1-61SG
الي. الي	8-32E	1	.2	FIRE NEAK BUSES	51 AND 52 OCCURS			4.65E-05	IEV-FI8
				EDRITHMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				COMMON LAUSE	FAILURES OF	AFW SYSTEM		2.12E-04	058AFWCN
				OMPRESSOR 18	MECHANICAL	FAILURE		8.44E-02	01-PM-SIAE18-PS
50	8.24	10	: 3 : 4	FINE NEAR BUSES	51 AND 52 OCCURS			4.65E-05	1EV-F18
				EQUIPMENT FAILS	DUE TO FIRE			1.00E+00	FIRE-DAMAGE
				VERATOR FAILS	TO ESTABLISH	AFW FLOW	MANUALLY	3.18E 03	05BAF3-MANHE
				THERATOR FALLS	TO ESTABLISH	SAFETY INJECTION	MANUALLY	5.57E-03	33 HPI - MAN HE

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 308 of 415

1

-----

E	Inclosure	e - Q&/	A to Attachr	ment 1 Volu	me 05 (Sect	ion 3.0) Page 308 of	f 415
ABLE 4	15			****	DOMINANT SEQUENCES	****	Page:
File: F		File crea			NK ** Ver. 3.11 **	)	
	SEQUENCE PROBABILITY	CONTRIB				SEQUENCE IDENTIFIER	
1	4.21E-04	42.86	EQUIPMENT FAILS		A DIL FIRE OCCURS	IEV-F16 F1RE-DAMAGI SYS-AF3	E
			AFW SYSTEM BLEED AND FEED			SYS-085	
2	2.91E-05	29.68	AUXILIARY EQUIPMENT FAILS	FEEDWATER PUMP I	BOIL FIRE OCCURS	1 E V - F I 7 F I RE - DAMAGI	E
			AFW SYSTEM	FAILS		SYS-AF3	
3	9.65E 06	9 8 <u>3</u>		FEEDWATER PUMP A	OIL FIRE OCCURS	IEV-F16	-
			EQUIPMENT FAILS COMPONENT	COOLING WATER	SYSTEM FAILS	FIRE-DAMAGE Sys-CCL	2
به	∾.50E÷06	4.59	FIRE NEAR MCC EQUIPMENT FAILS	62A IN B DIESEL DUE TO FIRE	GENERATOR ROOM	OCCURS IEV-F12 / IRE-DAMAGE	E
			CHARGING SYSTEM COMPONENT	FAILS COOLING WATER	SYSTEM FAILS	SYS-CHG SYS-CCT	
5	3.56E 06	3.63	EQUIPMENT FAILS CHARGING SYSTEM		FIRE OCCURS	IEV-FI4 FIRE-DAMAGE SYS-CHP SYS-CCL	:
6	3.13E Q6	3, 19	EQUIPMENT FAILS	51 AND 52 OCCURS DUE TO FIRE COOLING WATER		IEV-FIB FIRE-D <b>AMA</b> GE SYS-CCL	
	2.188-06	2.22	B DIESEL EQUIPMENT FAILS AFW SYSTEM BLEED AND FEED	FAILS	FTRE OCCURS	1EV-F14 F1RE-DAMAGE SYS-AF3 SYS-085	
8	1, "0£ ∩6		EGUTEMEN? FATUS AFW SYSTEM	GENCRATOR OIL DUE TO FIRE FAILS RECIRCULATION		LEV-F14 FIRE-DAMAGE SYS-AF3 SYS-HR1	
¢	9.83E 07		aux lakt Equimen faill	FEEDWATER PUMP A	OIL FIRE OCCURS	IEV-FIG FIRE-DAMAGE SYS-AF3 SYS-HR1	
1,7	76E - 07		EQUIEMENT FAILS Charging System			IEV-FI7 FIRE-DAMAGE SYS-CHP SYS-CCL	

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 309 of 415, TABLE 4:15

Title: Total Core Melt Due to Fires File: FIRETOT.LST ( File created by linking firetot.in — WLINK \*\* Ver. 3.11 \*\*) Reduced Sum of Sequence Probabilities: 9.8116E 05

	CE OUE NCE	DEDCENT	CENTENCE				SEQUENCE
	SEQUENCE PROBABILITY						IDENTIFIER
	PRUBABILIU	CONTRID	DESCRIPTION				
11	3.14E-07	. 32	FIRE IN RELAY	ROOM OCCURS			IEV-F15
			EQUIPMENT FAILS				FIPE-DAMAGE
			AFW SYSTEM	FAILS			SYS-AF3
12	1.79E 07	. 18	FIRE NEAR BUSES	51 AND 52 OCCURS			IEV FI8
			EQUIPMENT FAILS	DUE TO FINE			FIRE-DAMAGE
			AFW SYSTEM	FAILS			SYS-AF3
			BLEED AND FEED	FAILS			SYS-085
13	1.48E-07	. 15	FIRE NEAR MCC	62A IN B DIESEL	GENERATOR ROOM	OCCURS	IEV-F12
			EQUIPMENT FAILS	DUE TO FIRE			FIRE-DAMAGE
			AFW SYSTEM	FAILS			SYS-AF3
			MFW SYSTEM	FALLS			SYS-ON2
			BLEED AND FEED	FAILS			SYS-082
							1EV F18
14	1 85E-08	02		51 AND 52 OCCURS			FIRE-DAMAGE
			EQUIPMENT FAILS				SYS-AF3
			AFW SYSTEM		(41)0		SYS-HR1
			HIGH PRESSURE	RECIRCULATION	FAILS		
		0.1		ROOM OCCURS			1EV-F15
15	6.28E-09	.01	FIRE IN RELAY				FIRE-DAMAGE
			EQUIPMENT FALLS CHARGING SYSTEM				SYS-CHP
			CHARGING STOTEM	COOLING WATER	SYSTEM FALLS		SYS-CCL
			Content				
16	2 52E 09	00	FIRE NEAR MCC	623 OCCURS			LEV-F11
10			EQUIPMENT FAILS				FIRE-DAMAGE
				FATUS			SYS-AF3
			MFW SYSTEM	FATUS			SYS-OM2
			BLEED AND FEED	FAILS			SYS-082
17	1 0.1E 99		FINE IN BUS "	AND BUS 2 ROOM	OCCURS		IEV-FI3
			SUPPRENT FAILS	DUE TO FIRE			FIRE-DAMAGE
			AFW SYSTEM	FALLS			SYS-AF3
			B-LED AND FEED	FA11 S			SYS-086
18	5 Aðt 1.)	۰,	FIRE NEAR MCC	621 OCCURS			LEV FI1
			FUL SIMENT FAILS	DUE TO FIRE			FIRE DAMAGE
			HAR LAND STSTEM				SYS-CHG
			has shell he t	CENCLING WATER	SYSTEM FAILS		SYS CLI
				. No see a second	CALDATOD DOM	on chi <b>d s</b>	1EV F12
19	2 816 11	4.44		NZA IN 8 DIESEL	UENERALUM ROOM		FIRE-DAMAGE
			EGUERMENT FALLS				SYS-AF3
				FAILS			SYS OM2
			MFW SYSTEM		FAILS		SYS-HR1
			6.774 EN\$220N\$	RETIRCULATION	e - Sel Car		-
	5 11 13		NEL IN R.C. 1	AND BUS 2 ROOM	OCCURS		1EV F13
211	2.478 TU		FUULFMENT FALLS				FIRE DANA .F
			and the mean of the state of				

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 310 of 415


TABLE 4	15					
Titlas	Total	Mait	Due	• •	Fires	

\*\*\*\*\* DOMINANT SEQUENCES \*\*\*\*\*


Page: 3

NUMBER	SEQUENCE PROBABILITY	PERCENT	SEQUENCE DESCRIPTION			SEQUENCE IDENTIFI"R
			AFW SYSTEM HIGH PRESSURE	FAILS	FAILS	SYS-AF3 SYS-HR1
21	1.02E-10	. 00	FIRE IN BUS 1 EQUIPMENT FAILS CHARGING SYSTEM COMPONENT	AND BUS 2 ROOM DUE TO FIRE FAILS . XOLING WATER	OCCURS	IEV-FI <b>3</b> FIRE-D <b>AMA</b> GE SYS-CHG SYS-CCT
22	7.05E·13	.00	FIRE NEAR MCC EQUIPMENT FAILS AFW SYSTEM MFW SYSTEM HIGH P°ESSURE	62J OCCURS DUE TO FIRE FAILS FAILS RECIRCULATION	FAILS	IEV-FI1 FIRE-DAMAGE S∀S-AF3 SYS-OM2 SYS-HR1

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 311 of 415 Figure 4-1: AX-23A (FI1) INITIATING EVENT FREQUENCY AUXILIARY BLDG (MCC 1-62J ROOM, EL 642')



## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 312 of 415 Figure 4-2: TU-92 (FI2) INITIATING EVENT FREQUENCY DIESEL GENERATOR ROOM B (MCC 62A)




.


\* The rest of the compartment fire frequency is considered in FI4.

LIC\PRA\IPEEE-4.WP


# Enclosurgigue & Asto Attach (FIG) INTYAIUNG DUR SECTION OF A STORE AND ATTACH (ROOM 16B)



# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 314 of 415 Diesel generator ROOM B (Diesel Fire)




## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 315 of 415 Figure 4-5: AX-30 (FI5) INITIATING EVENT FREQUENCY RELAY ROOM, FIRE NEAR VERTICAL CABLE TRAYS (EL 606')




"The Fire initiation frequency given in Table 4-1 is entirely due to electrical cabinets. Since it was shown in Section 4.3.1.9b that fires in the cabinets do not propagate, these are not applicable to this scenario. Instead it was assumed that the fire is from transient combustibles. This is conservative because transient combustibles in the relay room are kept to an absolute minimum. The compartment fire frequency is then:

F(t) \* WF(LS)0.0013 \* 1/25 = 5.20E-5


## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 316 of 415 Figure 4-6: TU-95C (FI6) INITIATING EVENT FREQUENCY TURBINE BLDG (AFW PUMP A ROOM)



## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 317 of 415 Figure 4-7: TU-95B (FI7) INITIATING EVENT FREQUENCY SWGR ROOM (AFW PUMP B ROOM)



## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 318 of 415 Figure 4-8: TU-95A (FI8) INTY ATING EVENT FREQUENCY SWGR DEDICATED SHULDOWN PANEL ROOM




LICYPRANPEEE-4.WP

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 319 of 415

FIGURE 4 9

TRANSIENTS WITH MAIN FREDWATER AVAILABLE EVENT TREE




THIS EVENT TREE IS USED FOR FIRES FILAND FI2

# Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 320 of 415

FIGURE 4-10


#### TRANSIENTS WITHOUT MAIN FEEDWATER EVENT TREE

		r				<b></b>
	FU	٨Đ	082	Hari	СНС	ccw
1	<u>.</u>		 			



THUS EVENT THEE IS USED FOR FURE FD

.




THIS EVENT TREE IS USED FOR FIRE FM

\* THESE NODES ARE USED IN OTHER EVENT TREES, THEY ARE CONDITIONAL HERE DUE TO THE INITIATOR.



#### DEDICATED SHUTDOWN SYSTEM EVENT TREE






#### THIS EVENT TREE IS USED FOR FIRES FIS AND FIT

"THESE NODES ARE USED IN OTHER FYINT TREES, THEY ARE CONDITIONAL HERE DUE TO THE INITIATOR.



#### ALTERNATE SHUTDOWN SYSTEM EVENT TREE





THIS EVENT TREE IS USED FOR FIRES FM AND FID

"THESE NODES ARE USED IN OTHER EVENT TREES, THEY ARE CONDITIONAL HERE DUE TO THE INITIATOR.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 324 of 415

# 5. Other External Events Analysis

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 325 of 415 SECTION 5

## OTHER EXTERNAL EVENTS ANALYSIS

## TABLE OF CONTENTS

## **SECTION**

## **PAGE**

5. Other E	External Events Analysis
5.0	High Winds, Floods, and Others
	5.0.1 Introduction
	5.0.2 General Methodology
	5.0.3 Methodologies for Specific Events
	A. High Winds and Tornadoes
	B. External Flood
	C. Transportation and Nearby Facility Accidents 5-13
	D. Hazardous Material
	5.0.4 Determination of Need to Analyze Additional Events 5-14
5.1	High Winds and Tornadoes
	5.1.1 Severe Wind Source Screening
	5.1.2 Screening Summary
	5.1.3 Analysis
	High Wind Analysis 5-20
	<b>B.</b> Tornado Analysis
	5.1.4 Results, Recommendations, and Conclusions
5.2	External Floods
	5.2.1 External Flooding Source Screening
	<b>5.2.2 Screening Summary</b>
	<b>5.2.3</b> Analysis
	A. Flooding from Lake Michigan
	<b>B.</b> Flooding from Intense Precipitation
	5.2.4 Results, Recommendations, and Conclusions
5.3	Transportation and Nearby Facility Accidents
	5.3.1 Transportation and Nearby Facility Accidents Source Screening
	5-32
	A. Nearby Facilities
	B. Ground Transportation
	C. Water Transportation
	D. Air Transportation
	<b>5.3.2 Screening Summary</b>
	5.3.3 Analysis
<b>.</b> .	5.3.4 Results, Recommendations and Conclusions
	Hazardous Materials
5.5	<b>References</b>

Enclosure - Q	&A to Attachment 1 Volume 05 (Section 3.0) Page 326 of 415
APPENDIX A:	Wind Data
APPENDIX B:	Derivation Of Depth Rate
APPENDIX C:	Air Traffic Data

.

.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 327 of 415

## **SECTION 5**

## OTHER EXTERNAL EVENTS ANALYSIS

## LIST OF TABLES

### **SECTION**

### PAGE

Table 5-1:	Screening of External Events for KNPP
Table 5-2:	Straight Wind Hazard Data
Table 5-3:	PMP and 100 Year Recurrence Rainfall Depths for Storms with Durations
	from 0.5 To 24 Hours
Table 5-4:	Precipitation
Table 5-5:	Aircraft Accident Acceptance Criteria Calculations & Comparisons 5-35

## **SECTION 5**

## OTHER EXTERNAL EVENTS ANALYSIS

## TABLE OF FIGURES

## SF CTION

### PAGE

Figure 5-1:	IPEEE Approach for Winds, Floods, and Other External Events	5-9
Figure 5-2:	Rainfall PMP Estimates	5-30
Figure 5-3	Rainstorm 100 Year Recurrence Depth	5-31

# **SECTION 5**

## OTHER EXTERNAL EVENTS ANALYSIS

## TABLE OF APPENDICES

APPENDIX A:	Wind Data	-37
APPENDIX B:	Derivation Of Depth Rate	i- <b>46</b>
APPENDIX C:	Air Traffic Data	i-49

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 330 of 415

### 5.0 High Winds, Floods, and Others

### 5.0.1 Introduction

The external events to be considered are those events whose cause is external to all systems associated with normal and emergency operations situations. A comprehensive list of external events is provided in NUREG/CR-2300, "PRA Procedures Guide" (Reference 1). Some external events listed may not pose a significant threat of a severe accident. Some external events were considered in the design of the plant and therefore have sufficiently low contribution to core damage frequency or plant risk. Some events were reviewed under ongoing programs; for instance under the individual plant examination (IPE), the significance of lightning and severe cold weather conditions that could cause loss of off-site power was assessed. Also, internal floods were included in the IPE request. The purpose of this study is to ensure that all potential external hazards are analyzed and pose no undue risk to the plant.

#### 5.0.2 General Methodology

NUREG-1407 presents an acceptable methodology to be followed for the analysis of the "other external events." The three major steps of the general methodology used at the Kewaunee Nuclear Power Plant are:

- Establishing a List of Plant Specific Other External Events
- Progressive Screening
- Documentation

The following is a detailed description of the general methodology.

#### Establishing a List of Plant Specific Other External Events

The first step in the individual plant examination for external events (IPEEE) for "other external events" is to delineate all the events to be analyzed. In the guidelines provided in Generic Letter 88-20 (Reference 2), Supplement 4 (Reference 3), NUREG-1407 (Reference 4), NUREG/CR-2300 and NUREG/CR-5042 (Reference 5) are to be followed in developing the list of plant specific "other external events" for IPEEE analysis. The list of events for Kewaunee are presented on Table 5.1 and is discussed further in Section 5.0.4.

#### Progressive Screening

The overall approach consists of a progressive screening. The screening criterion for reporting potential severe accident sequences is consistent with that used for the IPE. The steps in the progressive screening approach represent a series of analyses in increasing levels of detail, effort, and resolution. One or more steps may be bypassed, however, as long as subsequent steps identify the vulnerabilities or demonstrate that they are insignificant. The screening approach consists of the following steps as presented in Figure 5-1.


- 1. Review plant-specific hazard data and licensing bases.
- 2. Identify significant changes since the operating license (OL) was issued including:

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 331 of 415

(1) military and industrial facilities within 5 miles of the site, (2) on-site storage or other activities involving hazardous materials, (3) transportation, or (4) developments that could affect the original design conditions.

3. Determine if the plant and facilities design meets the 1975 Standard Review Plan (SRP, Reference 6) criteria.

After reviewing the information obtained in the previous two steps a confirmatory walkdown of the plant is performed. The walkdown concentrates on outdoor facilities that could be affected by high winds, on-site storage of hazardous materials, and off-site developments. If the walkdown reveals that potential vulnerabilities have not changed since the original design basis analysis, it is judged that the continuation from the hazard to core damage frequency is less than 1E-06 per year (NUREG-1407) and the IPEEE screening criterion is met.





4. Determine if the hazard frequency is acceptably low.

If the original design basis does not meet current regulatory requirements, the next step is to demonstrate that the original design basis is sufficiently low - that is, less than 1E-05 per year, and the conditional core damage frequency is judged to be less than 1E-01.

If the original design basis hazard combined with the conditional core damage frequency is not sufficiently low (i.e., less than the NUREG-1407 screening criterion of 1E-06 per year), additional analysis is needed.

5. Perform a bounding analysis.

This analysis is intended to provide a conservative calculation showing that either the hazard does not result in core damage or the core damage frequency is below the reporting criterion. The level of detail is that level needed to demonstrate the point; judgement is needed for determining the proper level of detail and needed effort.

6. Perform a probabilistic risk assessment (PRA).

A probabilistic risk assessment consists of the following key elements: hazard analysis, fragility evaluation, plant systems and accident analysis (event/fault trees), and radioactive material release analysis. The detailed procedure is described in NUREG/CR-2300. If the core damage frequency is less than 1E-06 per year, the event need not be considered further. The level of detail is that level needed to conclude that the core damage frequency is low or to find vulnerabilities.

The application of the above approach involves considerable judgment with regard to the scope and depth of the study, level of analytical sophistication, and level of effort to be expended. This judgment depends on how important the external initiators are when compared with internal initiators, and a perceived need for accurately characterizing plant capacity or core damage frequency. The detailed guidelines presented in NUREG-1407 do not preclude use of this type of judgment. Consistent with engineering practice, either expert opinions, simplified scoping studies, or bounding analyses are used, as appropriate, in forming these judgments.

#### **Documentation**

The IPEEE is documented in a traceable manner using a two-tier approach to provide the basis for the findings. The first tier consists of the results of the examination and the second tier is the documentation of the examination itself. The following information on the high winds, floods, and other portions of the IPEEE is documented in accordance with the guidance provided in NUREG-1407.

- 1. A description of the methodologies used in the examination.
- 2. Information on plant-specific hazard data and licensing bases.
- 3. Results of the assessment of the hazard frequency and the associated conditional core damage frequency if step 4 of Figure 5-1 is used.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 334 of 415

- 4. Results of the bounding analysis if step 5 of Figure 5-1 is used.
- 5. If step 6 of Figure 5-1 (PRA) is required, the following is also provided:
  - All systemic event trees, including origin and method of analysis.
  - A description of each systemic sequence selected, including discussion of specific assumptions and human recovery action.
  - The estimated core damage frequency, the timing of the associated core damage, a list of analytical assumptions including their bases, and the sources of uncertainties, if applicable.

### 5.0.3 Methodologies for Specific Events

The approach for performing IPEEE analysis for a select group of "other" external events related to Kewaunee is presented in the following discussion.

### A. High Winds and Tornadoes

For plants designed against NRC's current criteria, high winds pose no significant threat of a severe accident because the current design criteria for wind are dominated by tornadoes having a 1E-07 annual frequency of exceedance. However, Kewaunee has facilities that were designed and built prior to the NRC's current criteria and therefore a systematic examination to identify plant-specific vulnerabilities according to NUREG/CR-5042 (Reference 7) is required.

The purpose of this analysis is to determine the impact on safe plant operation due to the occurrence of high winds at the plant site. This analysis first estimates the expected frequency of exceedance of various wind speeds, and then assesses the likelihood of damage to specific plant structures and components as a result of stresses induced by those winds. The contribution of wind to plant risk depends on structures at the site susceptible to wind damage. Prior PRA experience indicates that, except in special circumstances, wind is generally not a major contributor to risk.

The specific tasks for this evaluation may include the following depending upon how the screening process proceeds.

- Wind Frequency Analysis
- Fragility Analyses
- Plant/Systems Analysis
- Core Damage Quantification

### Wind Frequency Analysis

A scoping assessment of wind speeds is derived by examining wind speed distribution data from such sources as the Kewaunee Updated Safety Analysis Report (USAR) (Reference 8) and the National Weather Service. These sources provide sufficient data for use in the scoping fragility analysis task.

If this analysis indicates that wind may be a significant contributor to the core damage frequency, a more detailed wind speed frequency of exceedance curve would be developed for the site. This curve would indicate, for a given wind speed, the frequency with which winds of an equal or higher speed will occur. This curve would be based primarily on data collected over the past five years obtained from the site meteorological tower. Data on maximum historical wind speeds is obtained from National Weather Service data for locations near the site.

### Fragility Analysis

The fragility analysis estimates the conditional probability that specific plant components or structures will fail when subjected to winds of a given intensity. A scoping analysis is performed to identify those components and structures whose failure could have a significant impact on core damage frequency. For the initial screening, conservative assumptions are made as to the likelihood of failure of various structures subjected to the scoping wind speed/frequency data. If necessary for more detailed analysis, estimates are made for the key items of the wind loading at which failure can be expected to occur.

#### Plant/Systems Analysis

The plant/systems analysis consists of developing logic models (e.g., event or fault trees) to determine the impact of wind speeds of a given intensity distribution. System availabilities are calculated by taking into account system component failures or fragilities as derived in the fragility analysis task.

#### Core Damage Quantification

The results of the wind analysis and plant systems analysis are combined to determine the frequency of degraded core states as a result of wind. The core damage frequency is then calculated as in the IPE. If, based on the screening analysis, the core damage frequency due to wind is significant with respect to that due to other external events, a more detailed wind analysis is required.

#### **B. External Flood**

For plants designed in accordance with Regulatory Guide 1.59 and applicable SRP sections (particularly Section 2.4), floods pose no significant threat of a severe accident. This is because the exceedance frequency of the design basis flood, (excluding floods due to failure of upstream dams) being judged to be less than 1E-05 per year, and the conditional core damage frequency for a design basis flood being judged less than 1E-01. Thus, core damage frequencies are estimated to be less than 1E-06 per year for a plant designed against NRC's current criteria. However, the latest probable maximum precipitation (PMP) criteria published by the National Weather Service (NWS) calls for higher rainfall intensities over shorter time intervals and smaller areas than have previously been considered. This

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 336 of 415

change could result in higher site flo ling levels than have been used in previous design bases. The effects of applying these new criteria in terms of on-site flooding is assessed. Also, systematic examination for plant-specific vulnerabilities are performed if needed.

An external flooding analysis has been performed to account for any significant contribution to core damage frequency resulting from plant damage caused by storms, seiche, dam failure, flash floods, etc., is accounted for.

The basic steps wolved in an external flooding analysis are similar to those described for internal flooding. However, the focus of attention is on arcas that, due to their location and grading, may be susceptible to external flood damage. Thus, information on such items as dikes, surface grading, locations of structures, and locations of equipment within the structures is required. Information such as meteorological data for the site, historical flood height and frequency data is needed. For the scoping analysis, data available from the USAR and from PRAs for plants in similar areas are used to estimate the frequency and severity of external floods. Once the data is collected, a compilation of potential flooding sources and a matrix of flooding areas versus critical components is developed.

Flooding areas are then evaluated for adequacy of flood protection. The consequences of postulated flooding in those areas are determined, in order to identify those areas in which external flooding could lead to initiating events, loss of critical system functions, etc. Electrical power supply equipment, and in particular, off-site power supplies, receive special attention.

Finally, if required, the probabilities of flood-induced initiating events are determined using event trees to account for mitigation and detection actions. These probabilities are then combined with the estimated external flooding frequency for each potential flood area. The core damage frequency is then calculated in a manner similar to that described for the internal flooding analysis

### C. Transportation and Nearby Facility Accidents

These events consist of accidents related to either transportation accidents or accidents at industrial and military facilities. Plants designed against NRC's current criteria (NUREG/CR-5042) should have no significant vulnerability to severe accidents from these events because the initiators considered in the design should have a recurrence frequency less than 1E-06 or have been shown through a bounding analysis not to affect the plant. Changes may have occurred since the original design, however, so there may be exceptions that need systematic examination. Since Kewaunee was designed and built prior to the NRC's current criteria, a systematic examination for plant-specific vulnerabilities is required.

Any transportation of hazardous materials or nearby facility accident has associated with it the potential for hazards. Such hazards can include the accidental release of toxic material, explosion, fire, and so forth. If such a hazard occurs near the plant site, the possibility exists that sufficient damage could occur to the plant, and thus lead to scenarios that result in core damage.

The hazardous material transportation analysis first identifies the types and frequencies of such shipments in the vicinity of the plant. This information is obtained from a variety of sources, including the U.S. Coast Guard and Department of Transportation. Next, an evaluation is made of the types of hazards that could occur near the plant, and then an estimated frequency of occurrence is assigned. Records from sources such as those listed above are used to assess these hazard frequencies. The

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 337 of 415

generic data is then updated with any available local data. For each type of hazard identified, the consequence at the site boundary is calculated based on the type of material involved, the anticipated quantities being shipped, and so forth, using appropriate simplified dispersion models and atmospheric data.

Finally, an assessment is made of the vulnerability of the plant (i.e., the probability of reaching a core damage state) to the consequences of any such event. As a first approximation, an assignment of plant system or structural damage is made, based on the type and magnitude of the postulated event. Then, if such events are determined to be significant contributors to core damage frequency, a more detailed analysis (e.g., a consequence-specific fragility analysis) is performed to determine the true contribution. The internal event plant logic is modified as appropriate for use with the external hazards analysis, and then combined with the vulnerability assessment to determine the conditional annual frequency of each core damage state resulting from hazardous shipping.

The potential for hazards resulting from transportation incidents other than those described above are also evaluated. Truck or rail accidents involving hazardous materials near the plant site cai, pose a threat to safe operation of the plant as well. The magnitude of risk from such incidents depends on the types and frequencies of shipments, proximity to the plant, and so forth. The end result is an estimate of the annual frequency of core damage due to other transportation hazards. Nearby facility accidents are similarly analyzed.

### D. Hazardous Material

These events consist of accidents related to the release of hazardous materials on site. Such hazards would include the release of any toxic material located in or near the plant. If such a hazard occurs, the possibility exists that sufficient damage could occur to the plant or creates an environment which prevents the safe operation of plant equipment, and thus increases the probability of scenarios that could result in core damage.

This analysis first identified the types and quantities of such materials located in or near the plant. This information is obtained from a variety of sources, including current programs involving hazardous chemical control, and plant walkdowns. Next an evaluation is made of the various hazardo to determine their effect on plant equipment or personnel.

Finally, an assessment is made of the vulnerability of the plant (i.e, increased probability of core damage) to the consequences of any such event.

#### 5.0.4 Determination of Need to Analyze Additional Events

In order to determine if any other external event needs to be analyzed, a set of screening criteria is used. This is done to identify those external hazards that can be screened from further consideration based on the screening criteria outlined in NUREG/CR-2300.

An external event is to be excluded from further consideration if:

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 338 of 415

<u>Criterion 1</u> The event is of equal or lesser damage potential than the events for which the plant is designed. This requires an evaluation of the plant design bases in order to estimate the resistance of plant structures and systems to a particular external event.

<u>Criterion 2</u> The event has a significantly lower mean frequency of occurrence than other events with similar uncertainties and cannot result in worse consequences than those events.

<u>Criterion 3</u> The event can not occur close enough to the plant to affect it. This is also a function of the magnitude of the event.

<u>Criterion 4</u> The event is included in the definition of another event.

<u>Criterion 5</u> The event is slow in developing and there is sufficient time to eliminate the source of the threat or to provide an adequate response.

The use of these criteria minimizes the possibility of omitting any significant risk contributors while at the same time reducing the amount of detailed bounding analysis required. A summary of the screening analysis based on the Kewaunce USAR is included in Table 5-1.

Event	Screening Criterion	Remarks
Aircraft Impact	-	A bounding analysis is performed for this event.
Avalanche	3	Topography is such that no avalanche is possible.
Biological Events	5	The only biological event that may affect Kewaunee is zebra mussel blockage of the Circulating Water System intakes. This event is not further considered because flow blockage would be a gradual event to which the plant could easily respond. This is considered in the loss of service water event in the IPE.
Coastal Erosion	5	The shoreline at Kewaunee is not subject to rapid coastal erosion due to the extensive application of rip-rap. The long-time periods required to produce sufficient coastal erosion to endanger the plant preclude further analysis.
Drought	2	The depth of the intake cribs at Kewaunee (about 10 feet below the record low lake level) precludes further analysis.
External Flooding	-	A counding analysis is performed for this event.
Extreme Winds/Tornados		A bounding analysis is performed for this event.

Table 5-1: Screening of External Events for KNPP

٠

Event	Screening Criterion	Remarks	
Fog	4	Fog can increase the frequency of occurrence of accidents. Fog is implicitly included in aircraft and other transportation accident frequency data. Fog, in combination with substation component failures, could result in off-site power line outages. This is considered in the IPE study.	
Frost	1	Snow and ice govern.	
Hail	1	Tornado and turbine missiles govern.	
Nearby Facility Accidents		A bounding analysis is performed	
High Lake Levei	4	Included under external flooding.	
High Summer Temperature	1	The main problem would probably be loss of heat sink, which is included in drought.	
Hurricane	4	Included under high winds.	
Ice Cover	1	Ice or snow loading is considered in the plant design.	
Industrial or Military Facility Accidents	4	Included under hazardous materials.	
Internal Fire		A detailed plant specific analysis is performed in Section 4 of this report.	
Internal Flooding		A detailed plant specific analysis was performed in the IPE.	
Landslide	. 3	Topography is such that a landslide is not possible.	
Lightning	4	Included in loss of off-site power initiating event frequency and external fire analysis.	
Low Lake Level	4	Included under drought.	

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 341 of 415

Event	Screening Criterion	Remarks	
Low Winter Temperature	1	Thermal stresses and embrittlement are insignificant or covered by design codes and standards for plant design; there would also be ample warning time with respect to freezing of the heat sink.	
Meteorite	2	Extremely low frequency according to K. A. Soloman, et. al., "Estimate of the Hazards to a Nuclear Reactor from the Random Impact of Meteorites," UCLA-ENG-7426, March 1974.	
Pipeline Accident	4	Included under hazardous materials.	
Intense Precipitation	4	Included under external flooding.	
River Diversion	4	Included under external flooding; also heat sink is Lake Michigan.	
RWST/CST Rupture	2	The likelihood of such a random failure is extremely low and inlcuded in the IPE. Seismically induced failure of these tanks is analyzed in Section 3 of this report.	
Sandstorm	3	This is not relevant for this region.	
Seiche	4	Included under external flooding.	
Seismic Activity	_	A detailed site and plant specific analysis is performed in Section 3 of this report.	
Snow	1	Ice or snow loading is considered in the plant design.	
Soil Shrink-Swell Consolidation	1	Site-suitability evaluation and site development for the plant are designed to preclude the effects of this hazard.	
Storm Surge	4	Included under external flooding.	
Transportation Accidents	-	Included under transportation and nearby facilities.	

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 342 of 415

Event	Screening Criterion	Remarks
Tsunami	3	This is not relevant for this region.
Volcanic Activity	3	This is not relevant for this region.
Waves	4	Included under external flooding.
Hazardous Materials	-	Control room habitability study includes an evaluation of hazardous materials. A review is performed to ensure that no changes have occurred to invalidate the results of this study.

#### 5.1 High Winds and Tornadoes

This section examines potential severe wind events which might initiate an accident sequence leading to core damage. Potential severe wind sources include: high winds, tornadoes, and hurricanes.

#### 5.1.1 Severe Wind Source Screening

Hurricane wind speeds tend to diminish as they pass over large land masses. According to the Kewaunee USAR, due to the geographic location of Kewaunee, the probability of core damage as a direct result of wind from a hurricane is negligible.

#### 5.1.2 Screening Summary

The only severe wind sources that could potentially impact Kewaunee are strong winds and tornadoes.

#### 5.1.3 Analysis

Severe winds can affect safety related structures at the plant site in at least two ways. If the wind forces exceed the load capacity of a building or other external facility, the incident walls or framing may collapse or the structure may overturn. If strong enough, the winds may be capable of lifting objects and hurling them against some of these structures. If a wind-induced missile breaches a building wall, critical components or other equipment inside the building may be damaged or disabled.

The first step in a severe wind analysis is to determine the frequency of the wind speeds associated with the various wind sources for the area in question. If the hazard frequency is acceptably low ( $\leq 1E$ -06), no further analysis is needed. Otherwise, the allowable wind loading of each pertinent plant structure is coupled with the wind speed frequency data to determine the expected failure frequency of the structure and ultimately the core damage frequency.

### A. High Wind Analysis

The site-specific data is obtained from NUREG/CR-2890 (Reference 9) for the years 1887 through 1979. Data for the years 1980 through 1988 is obtained from the National Oceanic and Atmospheric Administration (NOAA). Appendix A provides the annual extreme wind data collected for the years 1887-1988. All the data is obtained from the weather station at Green Bay, Wisconsin, which is approximately 30 miles from the Kewaunee site. The following justification is provided in NUREG/CR-4458 (Reference 10) Appendix G for using the Green Bay weather station data. NUREG/CR-4458 was developed for the Point Beach Nuclear Plant which is located three miles from the Kewaunee site (Reference 11 and 12).

The possible uncertainty due to the proximity of the weather station to the site and the differences in terrain roughness between the site and station were considered. If a station is located far from a site, then other adjacent stations should also be included in the analysis. In addition, if the terrain roughness is different, then a wind speed correction factor, which is uncertain, should be included.

For Point Beach, the closest weather station is only 30 miles away and the terrain in between is essentially flat. Thus, no uncertainty for station distance or differences in terrain roughness were considered.

Since the Kewaunee site is closer to Green Bay than Point Beach is, and the terrain between Kewaunee and Green Bay is essentially flat, the Green Bay weather station data is also applicable to the Kewaunee site.

In NUREG/CR-4458, a family of mean wind hazard curves for straight winds were developed using the data base from NUREG/CR-2890. The "Straight Wind Hazard Data" from NUREG/CR-4458 is presented in Table 5-2.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 344 of 415

			Frequency	of Exceedance	ce Per Year	
Windspeed	Mean		Pr	obability Va	lue	
(mph)	Value*	0.20	0.20	0.20	0.20	0.20
95	1.00E-02	5.67E-04	3.53E-03	7.37E-03	1.29E-02	2.56E-02
101	5.00E-03	1.79 <b>E-04</b>	1.45E-03	3.34E-03	6.33E-03	1.37E-02
110	2.00E-03	3.64 <i>c</i> -05	4.27E-04	1.14E-03	2.41E-03	5.99E-03
116	1.00E-03	1.15E-05	1.73E-04	4.08E-04	1.16E-03	3.15E-03
123	5.00E-04	3.35E-06	6.68E-05	2.20E-04	5.50E-04	1.66E-03
132	2.00E-04	6.62E-07	1.91 <b>E-05</b>	7.29 <b>E</b> -05	2.04E-04	7.04E-04
138	1.00E-04	2.06E-07	7.58E-06	3.20E-05	9.61E-05	3.64E-04
153	2.00E-05	1.24E-08	8.42E-07	4.53E-06	1.65E-05	7.82E-05
160	1.00E-05	3.51E-09	3.18E-07	1.92E-06	7.60E-06	4.02E-05
175	2.00E-06	2.06 <b>E-1</b> 0	3.45E-08	2.66E-07	1.27E-06	8.43E-06
182	1.00E-06	5.79E-11	1.29E-08	1.12 <b>E</b> -07	5.83E-07	4.29E-06

 Table 5-2:
 Straight Wind Hazard Data

\* Equal to US NRC mean values

Based on the data of Table 5-2, the frequency of exceedance of a wind speed of 182 MPH is 1E-06 per year. Hence, the frequency of exceedance per year for the design wind speed of 300 MPH, from the Kewaunee USAR, is less than 1E-06. Thus, based on step 4 of Figure 5-1, the hazard frequency is acceptably low ( $\leq$  1E-06) and as a result, the high winds do not cause any significant threat to the Kewaunee site.

### B. Tornado Analysis

According to the Kewaunee USAR, Wisconsin lies to the northeast of the principal tornado belt in the United States. During the ten-year period 1960-1969, 161 tornadoes were reported in the state. Only six of these tornadoes occurred in the four counties closest to the Kewaunee site (Brown, Door, Kewaunee, and Manitowoc Counties). During the period 1916-1969, only one tornado caused injury to people or major property damage within these four counties. This one occurred in Green Bay, 27 miles WNW of the site, on May 10, 1959, at 8:50 p.m. Three persons were injured and property damage ranged from \$500,000 to \$5,000,000. The tornado path was 6 miles long and 600 yards wide. The region north of Sheboygan, along the Lake Michigan shore, appears to be relatively free of tornadoes. Approximately six tornadoes occurred in the Green Bay-Kewaunee area on April 22, 1970. Damages were estimated at approximately \$500,000 and four to five people were injured.

Tornadoes tend to advance from the west with most of the tracks from the southwest to northeast. Maximum occurrence during the year is in May, with 90 percent reported in May through September. According to statistical methods proposed by Thom, (Reference 14) the probability of a tornado striking a point within a given area may be estimated as follows:

$$P = \frac{z t}{A}$$

P is the mean probability per year, z is the mean tornado path area, t is the mean number of tornadoes per year in area A. The value of t is 16.7 for Wisconsin and 1.2 for the four counties surrounding the Kewaunee site, if the April 22, 1970 tornadoes are included. The average path length and width for tornadoes occurring in the state are 7 miles and 200 yards, respectively, and yield a value of z equal to 0.80 square miles. Using a value of A equivalent to the total area of Brown, Door, Kewaunee, and Manitowoc counties yields:

$$P = 4.86E-04/yr$$

An equivalent value of 2.45E-04 per year is obtained using data based on the entire state.

At a 95 percent confidence interval Thom's formula becomes:

$$P' = P \left[ 1 \pm \frac{1.96}{(N)^{.5}} \right]$$

N is the total number of tornadoes in the area of concern during the ten years of record, 1960-1969 (the tornadoes of April 1970 are also included for conservatism).

The 95 percent confidence limits in the four counties around the site are 7.65E-04/yr and 2.09E-04/yr. The mean recurrence interval, R = 1/P', is 2060 years, and at the 95 percent confidence limits, the recurrence intervals R = 1/P', range between 1310 and 4770 years. The danger from tornadoes is therefore very slight.

Damage caused by tornadoes result from three principal effects:

- 1. The dynamic forces resulting from the high velocity vortex winds;
- 2. The bursting forces caused by differential static pressure resulting from the sharp pressure reduction in the immediate vicinity of a tornado funnel;
- 3. The impact of missiles generated by (1) and (2) above.

The most widely accepted values of maximum wind speed in a tornado appear to be about 300 mph (References 15, 16, and 17) for a very severe tornado at the peak of its intensity. Some sources mention values as high as 500-600 mph, (References 15 and 18) but these estimates appear to be based on indirect observations of phenomena such as straw driven into trees, etc., and are not regarded as authoritative.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 346 of 415

The highest directly observed wind velocities were derived from motion pictures of debris in the Dallas tornado of April 2, 1957 (Reference 16 and 19). These velocities ranged up to 170 mph and resulted in a maximum wind vector of 227 mph. If higher velocities were present, they must have been very localized and not typical of the average wind on large bodies and structures.

The design wind speed of 300 mph with a forward progression of 60 mph is about 36 percent greater than that of the Dallas tornado and is thought to be conservative in view of the Kewaunee location. The structural design criteria used to assure adequate design to accommodate the most severe storm conditions are discussed in Appendix B of the Kewaunee USAR.

Kewaunee is located in Region I of the NRC tornado risk regionalization scheme given in WASH-1300. This region has the highest tornado hazard of the three NRC regions. The mean values of wind speeds and frequencies of exceedance are tabulated below. Please note that similar values were used in the extreme wind analysis of Point Beach, located 3 miles from Kewaunee.

Wind Speed (mph)	Frequency of Exceedance	
74	5.38E-04	
93	3.20E-04	
134	1.04E-04	
182	2.19E-05	
234	3.95E-06	
290	6.30E-07	
349	7.33E-08	

Hence, based on the design wind speed of 300 mph, the tornadoes pose no significant threat to Kewaunee.

#### 5.1.4 Results, Recommendations, and Conclusions

Due to the low frequency of high winds and tornadoes at the Kewaunee site, it is concluded that the contribution to plant risk from severe wind events is insignificant.

The severe wind protective measures and design features instituted at Kewaunee are consistent with a highly safe plant design with very low risk contribution. Therefore, no design changes are currently recommended to protect the plant from severe winds.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 347 of 415

### 5.2 External Floods

This section examines potential external flooding events that might initiate an accident sequence leading to core damage. The potential flooding events considered include: dam failures, lake flooding, river flooding, and intense precipitation.

### 5.2.1 External Flooding Source Screening

As reported in NUREG-0965 (Reference 20), there are no on- or off-site dams associated with, or in the proximity of Kewaunee. Also, based on the Kewaunee USAR, local topography precludes any flooding from the landward side of the site. For these reasons, dam failure and flooding from inland lakes and streams are not applicable to Kewaunee.

### 5.2.2 Screening Summary

The only sources of external flooding that could potentially impact Kewaunee are Lake Michigan and intense precipitation.

### 5.2.3 Analysis

External flooding methodology involves the determination of the maximum possible flooding levels, and the effect these flooding levels have on the plant. If the plant elevation precludes any flooding from these maximum flooding levels, the analysis is complete; if the elevation is insufficient to preclude flooding, further analysis is required.

#### A. Flooding from Lake Michigan

Provisions were made in the plant design to protect safety-related p'ant structures and equipment from flooding, waves, storms, and other phenomena generated in the lake.

According to U.S. Geological Survey figures from the Kewaunee USAR, the normal water datum of Lake Michigan is 577.5 feet above mean sea level (MSL). The lowest recorded level of the lake was 575.4 feet above MSL in 1964; the highest recorded level was 582.5 feet above MSL in 1986. The current (May 1994) lake level at the Kewaunee site is 579.9 feet above MSL. The lowest plant access doors, the two screenhouse doors, are 586 feet above MSL. Even these doors, however, are 3.5 feet above the highest recorded lake level. In the unlikely event that the lake level would rise above this level, the plant would be protected by solid steel normally closed and locked doors that open toward the outside and would therefore be pushed closed by the flood waters. It is assumed here, as in the internal flooding study, that these doors would remain intact. The next higher doors are at 605 feet above MSL, 22.5 feet higher than the highest recorded lake level.

Although the Kewaunee site is well above the normal lake levels, external flooding from abnormal lake levels is possible. Seiches are phenomena capable of producing large temporary deviations in lake water levels.

Seiches are oscillations in the level of lakes and similar bodies of water caused by the passage of squall lines across the body of water. In Lake Michigan, these squalls have their fronts oriented NE to SW and are accompanied by an abrupt increase in barometric pressure and local high winds. There have been a number of seiches recorded in the Great Lakes, the great majority of which were of only a few inches amplitude and, therefore, of no consequence. A few, however, have caused considerable flooding damage, and even loss of life. The most severe of the large seiches occurred on June 26, 1954 and caused water level increases of up to 10 feet at North Avenue in Chicago, Illinois. The greatest level increase recorded on the lake's eastern shore was 6 feet at Michigan City, Indiana, according to the Kewaunee USAR and the D. C. Cook USAR (Reference 21).

Seiches do not have the rapidity or damaging power of a wind-wave of equal height. Instead, the rise of water is continuous over several minutes, and damage is primarily due to flooding.

Within the bounds of seiche-causing conditions, the most severe initiating meteorological condition may be assumed to be a squall line traveling the entire lake from a direction west of northwest with a progress velocity sufficient to match the natural oscillation mode of the lake's southern sub-basin and producing a seiche front so shaped as to trap against the shore at the plant site.

The infrequency of seiches of significant size on Lake Michigan restricts to some degree the volume of recorded data from which future seiche characteristics may be predicted. The great quantity of information available concerning other large bodies of water, including measurements and observations of actual seiches, the characteristics of the shoreline at the plant site, historical meteorological conditions, computations based upon mathematical models, etc., confirm that no water level increase of as much as 8 feet should ever be experienced at the plant site (Kewaunee and D. C. Cook USARs). In conclusion, such an increase in water level is of no concern to plant safety since the screenhouse doors would prevent water from entering the plant even if such a seiche would occur.

#### **B.** Flooding from Intense Precipitation

Precipitation flooding analysis consists of first determining the maximum amount of precipitation an area can receive followed by an analysis of water removal for the area (i.e., runoff analysis).

The rain water concerning plant safety usually comes from local, convective type heavy rainstorms, which are characterized by high rain intensity over a relatively short duration, normally less than an hour (Reference 22).

#### Probable Maximum Precipitation

Rainfall frequency analysis is best performed using area-specific data from rain gauges or if no rain gauge data is available then the results from nearby gauged sites can be meteorologically transferred to the area in question.

One such frequency analysis performed on recorded point rainfall data at gauged stations and generalized to ungauged stations is the U.S. National Weather Bureau Technical Paper No. 40 (Reference 23).

However, because of the potential seriousness of external flooding induced nuclear plant failure, the use of probable maximum precipitation (PMP) is usually recommended for plant design. The PMP is defined in hte U.S. National Weather Services, NOAA Hydrometeorological Report No. 52 (Reference 25) as "the theoretically greatest depth of precipitation for a given duration that is physically possible over a particular drainage area at a certain time of year". The derivation of the PMP estimate only produces the theoretical maximum precipitation produced by the combination of reasonably conceivable worst drometeorological conditions occurring concurrently; there is no frequency of occurrence implied. Therefore, the PMP is useful only as a guide in plant flood prevention design. Since there is no frequency implied by the PMP, the plant must be designed to withstand the possible flooding effects from the PMP event.

PMP estimates for a 10 mi<sup>2</sup> area about the Kewaunee site for durations from 0.2 to 24 hours are given in Table 5-3, which is based on NOAA Hydrometeorological Report No. 52 and the <u>Standard Handbook</u> for <u>Civil Engineers</u> (Reference 26). For comparison, Table 5-3 also contains the 100 year recurrence interval extreme rainfall estimates calculated in the U.S. National Weather Bureau Technical Paper No. 40, and the PMP to 100 year recurrence extreme rainfall depth ratios.

Although the PMP estimates are all at least five times as great as the respective 100 year recurrence depth for the same storm duration, the SRP Section 2.4.2 requires that plant designs satisfy the PMP flooding criteria. Therefore, it should be demonstrated that safety-related equipment is not prone to flooding from the probable maximum precipitation.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 350 of 415

Duration [hours]	*PMP Estimate [inches]	**100 Year Recurrence Depth [inches]	***PMP to 100 Year Depth Ratio
0.5	10.0	1.8	5.6
1.0	13.0	2.3	5.7
2.0	18.0	2.7	6.7
3.0	20.0	3.0	6.7
6.0	23.0	3 5	6.6
12.0	27.0	4.2	6.4
24.0	29.0	5.0	5.8

Table 5-3:	PMP and 100 Year Recurrence Rainfall Depths for Storms with Durations from
	0.5 To 24 Hours

\* PMP estimates based on 19 square mile drainage area.

PMP estimates for:		0.5 and 1 hour durations from Reference 24
		6, 12 and 24 hour durations from Reference 23
	-	2 and 3 hour durations obtained from interpolation.

**\*\*** From Reference 20

\*\*\* This column underscores the conservatism of PMP criteria.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 351 of 415

As another comparison the results of average, minimum, and maximum annual precipitation for the years 1971-1980 are provided in Table 5-4. These rates fall within the values used for the analysis.

Location	Ten Year Average (1971 - 1980)	Max Annual	Year	Min Annual	Year
Kenosha	32.92	46.12	1972	25.07	1975
Milwaukee	33.39	40.74	1978	26.45	1971
Port Washington	30.24	37.34	1978	21.51	1976
Manitowoc	30.25	36.08	1978	25.20	1976
Two Rivers	30.20	34.6-	1973	24,81	1976
Kewaunee	30.35	34.69	1977	21.68	1976
Green Bay	29.36	35.47	1975	17.85	1976

Table 5-4:Precipitation\*

### **Runoff Analysis**

The <u>Standard Handbook for Civil Engineers</u> describes a method to determine the volume of water from a rainstorm that must be removed (i.e., w. er that does not evapotranspire or seep into the ground). The peak discharge runoff, Q, is defined in the "Rational Formula" as:

Q = CIA; where Q = peak discharge (ft<sup>3</sup>/s) C = runoff coefficient (% of rain that appears as direct runoff) I = rainfall intensity (in/hr) A = drainage area (acres)

A value of 0.15 is used for the runoff coefficient, C, defined in the Handbook based on the soil in the vicinity of the Kewaunee site.

From Table 5-3, the greatest hourly rainfall intensity (13.0 inches) occurs during a one-hour storm. Since the Rational Formula is defined for an hourly rainfall intensity, the more intense half-hour storm (10.0 in/half-hour) is not used.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 352 of 415

As previously stated, the PMP estimates are based on a 10 mi<sup>2</sup> area or 6400 acres (Note: Larger areas tend to produce lower PMP values). However, realizing that water depth and not water volume is the issue here, we will define the runoff depth rate, H, as:

$$H = Q/A = CIA/A = CI (in/hr)$$


Using the above values for "C" and "I," 0.15 and 13.0 inches/hour, the runoff depth, or height of standing water left by the PMP storm that did not evapotranspire or seep into the soil is 2.1 in/hr (see Appendix B for calculation).

For storms greater than one hour the following runoff depth rates are expected (see Appendix B for calculation):


Duration of Storm	<b>Runoff Depth Rate</b>		
<u>(hr)</u>	<u>(in/hr)</u>		
2	1.4		
3	1.0		
6	0.6		
12	0.3		
24	0.2		

The above results are expected since storm intensity tends to decay logarithmically with storm duration. Figures 5-2 and 5-3 show this logarithmic decay for both PMP and 100 year recurrence estimates.

The Kewaunee freeboard protects the plant from rainfall-induced external floods up to 6 inches. General runoff is toward the east to Lake Michigan. However, due to the immense size of Lake Michigan and its normal water level (approximately 23 feet below the plant elevation) no flooding of Lake Michigan from a combination of rain collection and runoff will ever endanger Vowaunee.



Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 353 of 415 Figure 5-2: Rainfall PMP Estimates



Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 354 of 415 Figure 5-3: Rainstorm 100 Year Recurrence Depth

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 355 of 415 **5.2.4 Results, Recommendations, and Conclusions**

In view of the low frequencies and maximum flood levels, as well as the plant elevation, the topographical layout of the site, and the elevation of plant penetrations relative to safety-related equipment, it is concluded that the contribution to plant risk from external flooding is greatly dominated by other risk contributors.

An analysis was also performed to evaluate flooding based on probable maximum precipitation (PMP) criteria. It is concluded that Kewaunee is not endangered by the flooding based on the PMP criteria.

In fact, in 1993 when flood levels across the Midwest were at all time highs, there were no problems experienced at Kewaunee.

The external flooding protective measures and design features instituted at Kewaunee are consistent with a highly safe plant design with very low risk contribution. Therefore, no design changes related to external flooding prevention are currently recommended.

### 5.3 Transportation and Nearby Facility Accidents

This section examines transportation accidents including accidents from other industrial facilities near the plant that may initiate a sequence leading to core damage. The potential transportation events include those caused by aircraft, ship impact, roadway, and railroad accidents. Only nearby facility accidents that have an impact on the core damage frequency are considered. This analysis made extensive use of the control room habitability study performed in response to NUREG-0737 (Reference 33), which includes transportation and nearby facility accidents.

### 5.3.1 Transportation and Nearby Facility Accidents Source Screening

### A. Nearby Facilities

The Kewaunee site is surrounded by sprawling farmland that does not contain any large industrial facilities (chemical, etc.) (Reference 27). This was confirmed by plant walk-down, driving in the vicinity of the plant, and by aerial photographs. Hence, accidents associated with nearby facilities do not contribute to core damage frequency and are not evaluated further.

### **B.** Ground Transportation

Kewaunee receives no hazardous materials via pipeline, air, railway, ship or barge. Furthermore, there are no military installations, missile sites, or industrial facilities located beyond the Kewaunee site boundary at which an accident might cause interaction with the plant affecting public health and safety. Therefore, the only potential source of damage from off-site hazardous materials accidents is ground transportation accidents via road or rail.

The nearest major highway, Interstate 43, is more than 10 miles from the plant. Even though other roads are in the vicinity of the Kewaunee site, including Wisconsin State Highway 42, which crosses the site exclusion area, the volume of chemicals in a single truck shipment is very small. The nearest railway is approximately 10 miles from the plant.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 356 of 415

The results of the analyses performed in NUREG-2462 (Reference 28) are equations relating the minimum standoff distance from an accident site to the hazardous material's equivalent TNT yield and static wall capacity of the structures.

The minimum standoff distance R (feet), is predicted by:

R	=	$f_{\mu}(W \times p_s^{-2})^{1/3}$ ; where,
W		TNT equivalent yield (lbs) for solid explosives,
p <sub>s</sub>	=	static wall capacity (psi), and
f <sub>µ</sub>	=	factor related to the permissible ductility $\mu$ as given by:
	μ	$f_{\mu}$
 	1.0	87
	3.0	54
	5.0	51

NUREG-2462 recommends that  $\mu$  be set to 3.0, therefore  $f_{\mu}$  equals 54. For Kewaunee,  $p_s$  is 3.0 psi, which corresponds to the minimum static lateral load design capacity of walls within tornado zone I, defined in Regulatory Guide 1.76 (Reference 29). Setting the distance to the constant R = 52,800 feet (10.0 miles), which is a conservative estimate for the perpendicular distance from the Kewaunee site to the railroad, the maximum TNT equivalent is found to be 8.413 billion pounds or about 4,207,000 tons.

The TNT equivalent for fuel-air mixtures is calculated from NUREG-2462 by the equation  $W = 2W_F^{1.07}$ ; where,  $W_F = w_{0}$  ight of the hydrocarbon fuel (lbs). Using the above equation, the maximum amount of hydrocarbon fuel at the standoff distance of 52,800 feet is about 811,507 tcns.

Based on the quantity of the chemicals required to cause any significant risk at the plant, the railroad and truck accidents pose no threat to Kewaunee.

#### C. Water Transportation

Due to the physical location of the Kewaunee buildings and structures, the only danger to the plant is from run-aground ships or barges collapsing the circulating water intake structure and ultimately causing flow obstruction of circulating water system intake lines. In the unlikely event of a loss of intake structure the unit wou't be shut down. However, the intake structure is designed so that flow can be maintained to remove heat from the component cooling water system and other service water system loads.

The circulating water inlet structure starts with three 22 foot diameter vertical inlet cones which discharge through 6 foot diameter outlet pipes to the 10 foot diameter intake conduit. The cones are located with their tops one foot above the lake bottom with approximately 15 feet of normal water depth and approximately 1600 feet from shore. A steel grid with 12 inch square openings and a hinged manway serves as a trash screen. The three cones are reduced to 6 foot diameter pipes which join at the 10 foot diameter steel pipe. The 120 inch diameter intake conduit is buried a minimum of 3 feet

below the lake floor to ensure the necessary depth to provide the minimum net positive suction head (NPSH) for the circulating water pumps.

Two 30 inch auxiliary inlets in the top of the 120 inch intake pipe provide auxiliary supplies for service water. The two auxiliary inlets are located 50 ft and 100 ft shoreward from the intake cones. Each auxiliary inlet tee rises vertically to one foot above the lake bottom. Special screened cover plates are suspended 12 inches above the intake openings to prevent the entrance of debris. Each auxiliary water intake can supply in excess of 24,000 gpm. Spacing of the three inlet cones and the auxiliary inlets is such that the largest lake barge cannot directly cover all water inlets.

Therefore, no shipping docks in the vicinity of the plant, and no ships come close to the plant. Only small watercraft come close to the plant, and based on the elevation of the plant embankment adjoining Lake Michigan, they can cause no damage to the plant. Since the plant decay heat load can be removed by the service water system even if a shipping accident causes a loss of the circulating water system, the only credible shipping accident affecting the Kewaunee site cannot cause further plant damage leading to core damage or a radiological release. Therefore, an in-depth analysis is not required.

#### D. Air Transportation

The aircraft accident events that might initiate an accident sequence leading to core damage were evaluated. All private, commercial, and military aircraft and flight paths are examined.

The effect of an aircraft of sufficient weight, traveling at sufficient speed, crashing at a nuclear power plant site may result in physical damage such that a release of radioactive material from the reactor core may result. Only physical damage to the plant is considered because aircraft carry insufficient hazardous material.

The NRC SRP identifies acceptance criteria for siting nuclear power plants near airports and/or airways. The probability of an aircraft accident resulting in radiological consequences greater than 10 CFR Part 100 (Reference 30) exposure guidelines is considered to be less than 1E-07 per year if the plant meets the criteria listed below:

- (a) The plant-to-airport distance D is between 5 and 10 statute miles, and the projected annual number of operations is less than 500  $D^2$ , or the plant-to-airport distance D is greater than 10 statute miles, and the projected annual number of operations is less than 1000  $D^2$ .
- (b) The plant is at least 5 statute miles from the edge of military training routes, including low-level training routes, except for those associated with a usage greater than 1000 flights per year, or where activities (such as practice bombing) may create an unusual stress situation.
- (c) The plant is at least 2 statute miles beyond the nearest edge of a federal airway, holding pattern, or approach pattern.

If the above proximity criteria are not met, or if sufficiently hazardous military activities are identified (see item b above), a detailed review of aircraft hazards must be performed.

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 358 of 415

The Federal Aviation Administration (FAA), in compiling airport use statistics, defines an aircraft operation as the airborne movement of aircraft in controlled or noncontrolled airport terminal areas and about given enroute fixes or at other points where counts can be made. There are two types of operations - local and itinerant. These are defined in the FAA Statistical Handbook of Aviation (Reference 31). Local operations are performed by aircraft that: (1) operate in the local traffic pattern or within sight of the airport, (2) are known to be departing for, or arriving from, flight in local practice areas within a 20 mile radius of the airport, and (3) execute simulated instrument approaches or low passes at the airport. Itinerant operations are all aircraft operations other than local operations.

Although the FAA defines local aircraft operations as those within a 20 mile radius of an airport, a 25 mile radius about the Kewaunee site is used for conservatism. This extra five miles will in fact, increase the area reviewed  $(25^2/20^2 = 1.56)$  by more than 50 percent.

Table 5-5 contains the names, distances and approximate number of operations per year of all airports within a 25 mile radius surrounding the Kewaunee site.

Facility	Distance to Kewaunee Nuclear Plant – D (statute miles)	*No. of Operations per Year – N	**Number- Distance Criterion – C	***Acceptance Criterion Met? (Yes or No)
Austin Straubel Airport	25	125,000	625,000	Yes
Manitowoc County Airport	17	22,000	289,000	Yes
Military (Restricted Area) R-6903	17	145	289,000	Yes
Minnow MOA: Military Operations Area	10	35	50,000	Yes

#### Table 5-5: Aircraft Accident Acceptance Criteria Calculations & Comparisons

\* No. of Operations per Year data found in Appendix C

\*\* Number-Distance Criterion is calculated by:

 $C = 500 * D^2$  for D < 10 statue miles, and

 $C = 1000 * D^2$  for D > 10 statute miles.

\*\*\* Acceptance criteria met if: N < C.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 359 of 415 Using the criterion in (a) above, the probability of radiological consequences greater than 10 CFR Part 100 exposure guidelines from aircraft operations associated with those airports listed in Table 5-5 is considered less than 1E-07 per year (See Appendix C for data and calculations).

The nearest military training route is more than 5 miles from the Kewaunee site (Reference 32 and Appendix C). However, to add conservatism, all military airports within 25 miles from the plant were considered in the analysis. Therefore, criterion (b) concerning military training routes is satisfied, and again probability of exceedance of the radiological exposure guidelines set in 10 CFR Part 100 is considered less than 1E-07.

The distances from the Kewaunee site of local airports preclude danger from aircraft in approach or holding patterns over the airports.

#### 5.3.2 Screening Summary

Based on the screening analysis performed in Section 5.3.1, railroad, roadways, shipping, and nearby facility accidents do not pose any significant threat to the safety of Kewaunee. Using the screening criteria found in the SRP it is determined that commercial and military flight cause no relevant safety hazard to the plant.

### 5.3.3 Analysis

The methodology used to determine the core damage frequency from in-flight crashes begins by first determining the frequency of an in-flight crash into the "effective plant area" for all types of aircraft using the flight path in question.

The total core damage frequency from in-flight crashes is the sum of all the individual core damage frequencies for all types of aircraft.

A core damage frequency less than 1E-07 per year precludes further analysis; otherwise, a more detailed plant specific analysis is required.

#### 5.3.4 Results, Recommendations and Conclusions

Based on the location of Kewaunee with respect to the major roads, rail transportation, air traffic and nearby industrial facilities, there is no threat to the plant safety from any of these sources.

Unless flight patterns change, the air or ground traffic significantly increases, or any new industrial facility is opened in the vicinity of the plant, no plant modifications are recommended due to these events.

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 360 of 415

### 5.4 Hazardous Materials

This analysis began with a review of the 1989 Updated Control Room Habitability Report (Reference 34). This report was the result of a study performed in response to NUREG-0737 and includes an assessment of hazardous materials on-site as well as off-site.

A plant walkdown and a review of plant records was performed to verify that the control room habitability study assumptions were still valid. It was determined that the results and conclusions stated in the study are still valid, and that there is no threat to control room personnel from hazardous spills or releases.

The analysis was further expanded to consider the effects of a release of hazardous materials on safetyrelated equipment or the local operation of plant systems during emergencies. It was determined that a release of hazardous material would have no effect on safety related equipment, and furthermore, no hazardous materials were located near safety-related equipment. It was further determined that there are no credible hazardous material releases that would prevent an operator from locally operating plast equipment during plant emergencies. Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 361 of 415

#### 5.5 References

- 1. USNRC NUREG/CR-2300, "PRA Procedures Guide," American Nuclear Society and Institute of Electrical and Electronic Engineers, January 1983.
- 2. USNRC Generic Letter 88-20, Supplement 4, "Individual Plant Examination of External Events (IPEEE) for Severe Accident Vulnerabilities - 10CFR50.54(f)," June 28, 1991.
- 3. USNRC Generic Letter 88-20, "Individual Plant Examination for Severe Accident Vulnerabilities - 10CFR50.54(f)," November 23, 1988.
- 4. USNRC NUREG-1407, "Procedural and Submittal Guidance for the Individual Plant Examination of External Events (IPEEE) for Severe Accident Vulnerabilities," May 1991.
- 5. USNRC NUREG/CR-5042, Supplement 2, "Evaluation of External Hazards to Nuclear Power Plants in the United States, Other External Events," Lawrence Livermore National Laboratory, February 1989.
- 6. "NRC Standard Review Plan," NUREG-0800, Revision 3, 1990.
- 7. USNRC NUREG/CR-5042, "Evaluation of External Hazards to Nuclear Power Plants in the United States," Lawrence Livermore National Laboratory, December 1987.
- 8. "Updated Safety Analysis Report," Kewaunee Nuclear Power Plant.
- 9. USNRC NUREG/CR-2890, "Historical Extreme Winds for the United States-- Great Lakes and Adjacent Regions," August 1982.
- 10. USNRC NUREG/CR-4458 Shutdown Decay Heat Removal Analysis of a Westinghouse 2-Loop Pressurized Water Reactor, March 1987.
- 11. NRC SER, M. J. David (NRC) to K. H. Evers (WPS), Letter No. K-90-101, dated May 1, 1990.
- 12. Letter No. NRC-89-139, K. H. Evers (WPS) to NRC, November 14, 1989.
- 13. NUMARC 87-00, Guidelines and Technical Basis for NUMARC Initiative Addressing Station Blackout at Light Water Reactors, November 1987.
- 14. Thom, H. C. S., "Tornado Probabilities," Monthly Weather Review, Vol. 91, No. 10-12, pp. 730-736.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 362 of 415

- 15. Flora, S. D., "Tornadoes of the United States," University of Oklahoma, 1954.
- 16. Hoecker, W. H., "Wind Speed and Flow Patterns in the Dallas Tornado of April 2, 1957," Monthly Weather Review, May, 1960.
- 17. Booker, C. A., "Tower Damage Provides Key to Worceste- Tornado Data," <u>Electrical World</u>, August 17, 1953.
- 18. Silberg, P. A., "On the Nature of Tornadoes," Raytheon Co., June, 1961.
- 19. Hoecker. W. H., "Three-Dimensional Pressure Pattern of the Dallas Tornado and Some Resultant Implications," <u>Monthly Weather Review</u>, December. 1961.
- 20. G. E. Lear and O. O. Thompson, "NRC Inventory of Dams," NUREG-0965, U.S. Nuclear Regulatory Commission, Washington, D.C., 1983.
- 21. D.C. Cook FSAR.
- 22. Ben Chie Yen, "Flood Hazards for Nuclear Power Plants," Nuclear Engineering Design (Netherlands), Volume 110 No. 2, pp: 213-19, December 1988.
- 23. D. M. Hershfield, "Rainfall Frequency Atlas of the United States for Durations from 30 Minutes to 24 Hours and Return Periods from 1 to 100 years," United States National Weather Bureau, Technical Paper No. 40, May 1961.
- L. C. Schreiner and J. T. Riedel, "Probable Maximum Precipitation Estimates, United States East of the 105th Meridian," United States National Weather Service, Hydrometeorological Report No. 51, June 1978.
- 25. E. M. Hansen, et al., "Application of Probable Maximum Precipitation Estimates -United States East of the 105th Meridian," United States National Weather Service, NOAA Hydrometeorological Repor<sup>5</sup> No. 52, August 1982.
- 26. F. S. Merritt, ed. "Standard Handbook for Civil Engineers," Third Edition, Sections 21-53 to 21-57, McGraw-Hill, 1983.
- 27. Map of Local Facilities from the Chamber of Commerce. Supplemented by the plant walk-down and dive-down.
- R. P. Kennedy, et. al., "Capacity of Nuclear Power Plant Structures to Resist Blast Loadings," NUREG/CR-2462, also SAND83-1250 R4. RP, September 1983.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 363 of 415

- 29. Regulatory Guide 1.76, "Design Basis Tornado for Nuclear Power Plants," U.S. Atomic Energy Commission, Directorate of Regulatory Standards, April 1974.
- 30. 10 CFR Part 100, "Reactor Siting Criteria."
- 31. "FAA Statistical Handbook of Aviation, Calendar Year 1982," U.S. Department of Transportation, Federal Aviation Administration, Office of Management Systems, Information Analysis Branch, Washington, D. C., December 31, 1982.
- 32. Air Traffic Data near Kewaunee Nuclear Power Plant.
- 33. NUREG-0737, Clarification of TMI Action Plan Requirements, Item III.D.3.4, Control Room Habitability, November 1980.
- 34. <u>Updated Control Room Habitability Evaluation Report</u>, February 1989, Kewaunee Nuclear Power Plant.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 364 of 415

#### APPENDIX A: Wind Data

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 365 of 415 STATION DATA AND RETURN PERIOD VALUES

This attachment provides the annual extreme wind data, anemometer data and selected return period values. The following is a description of the information provided:

- 1. <u>STATION NAME</u> Includes 3-letter station identifier and 5-digit identification number where applicable.
- 2. <u>EXPOSURE TYPE</u> WBO  $z_o = .7$ WBO\*\*  $z_o = .4$ WBO\*  $z_o = .05$ APT  $z_o = .05$
- 3. PERIOD OF RECORD 1887 1988
- 4. LATITUDE, LONGITUDE In degrees-minutes.
- 5. <u>MEASURED SPEED</u> Uncorrected speed extracted from register charts. An "E" preceding indicates estimated speeds. MISSING is self-explanatory.
- 6. <u>TRUE SPEED</u> Measured speed corrected to true using appropriate tables for each anemometer type (Item 11).
- 7. <u>SPEED AT STANDARD HEIGHT</u> Speed standardized to 10 meters (WBO\*, WBO\*\*, APT) or 30 meters (WBO) using appropriate roughness lengths.
- 8. <u>DIRECTION</u> To eight compass points. UNK indicates unknown directions.
- 9. <u>ANEM TYPE</u> 4c = 4 cup anemometer 4c-b = 4 cup beaded anemometer 4c-x = 4 cup experimental anemometer 3c = 3 cup anemometer
- 10. <u>ANEM HT</u> Numbers indicate height of the instrument above ground level. Preceding "E" indicates an estimated height based on:
  - a. The first known instrument height and assuming this height existed from the beginning of the period or record, or
  - b. A 50-foot elevation for locations with no available data. Most nonurban sites were instrumented at approximately this height early in their record history.

- Enclosure Q&A to Attachment 1 Volume 05 (Section 3.0) Page 366 of 415 Following "R" indicates instrument mast is roof mounted. Following "G" indicates instrument mast is ground mounted.
  - 11. <u>**REMARKS**</u> Consecutive numbers for each year necessitating remarks with self-explanatory notes listed after the data set.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 367 of 415 **GREEN BAY, WISCONSIN WBO** Z<sub>o</sub> = .7 1887-1948 44 31 88 01

WBAN #14831

Date	Measured Speed	True Speed	Speed at Standard Ht (30 M)	Direction	Anem Type	Anem Ht	Remarks
ما بن من من من الله من من من من 200 من			·				
10/12/1887	60	47	73	SW	<b>4</b> c	57R	
08/08/1888	45	36	36	SW	н	н	
11/28/1889	60	47	73	N	14	11	
03/28/1890	60	47	73	N		17	
07/13/1891	60	47	73	SW			
04/02/1892	60	47	73	W	**	H	
02/19/1893	60	47	73	N	**	n	
05/18/1894	60	47	73	Ν	*	n	
09/22/1895	56	44	69	SW	++	n	
05/17/1896	50	40	62	SW	11	n	
04/18/1897	40	32	50	SW	н	*	
07/19/1898	50	40	62	SW	*1	'n	
06/04/1899	42	34	53	sw	**	<b>tu</b>	
07/07/1900	50	40	62	S	**	n	
03/03/1901	46	37	58	SW	17	ti	
07/30/1902	52	41	64	NW	"		
07/01/1903	67	52	81	NW	**	82	
04/15/1904	75	58	91	NE	**	**	
10/19/1905	60	47	73	NE	**	17	
11/21/1906	58	46	72	Ν	**	v	
03/19/1907	60	47	73	NW	н		
06/22/1908	66	51	80	W	N	11	
04/07/1909	70	54	84	NW	н	n	
04/23/1910	66	51	80	N	н	11	
05/01/1911	76	59	69	N	н.	123R	
04/16/1912	60	48	55	SW	н		
11/09/1913	60	47	55	Ν	**	11	
06/24/1914	60	47	55	SW	••	ŧ	
09/08/1915	60	47	55	SW	**	19	
05/08/1916	64	50	59	W	**	18	
01/21/1917	60	47	55	N	**	"	
03/09/1918	72	56	66	NE	**	11	
04/07/1919	66	51	60	NE	**	u	
12/14/1920	67	52	61	W	**	"	
02/16/1921	60	47	55	SW	**	u	
07/30/1922	72	56	66	NW	11		
			-				

Date	Measured Speed	True Speed	Standa Ht (30 M)	Direction	Anem Type	Anem Ht	Remarks
03/12/1923	64	50	59	N	м	N	
03/29/1924	56	44	52	NE	11	"	
04/18/1925	48	38	45	NE	55	17	
04/24/1926	58	46	54	N	11	**	
06/09/1927	50	40	47	S	*	17	
04/13/1928	46	43	50	NE	3c	Ħ	
04/01/1929	51	48	56	NE	н	71	
05/01/1930	42	49	57	W	11	н	
03/28/1931	60	56	66	NE	H	Ħ	
05/16/1932	58	46	54	W	4c	77	
03/19/1933	62	49	57	NE		Ħ	
06/23/1934	62	49	57	W	Ħ	*	
09/25/1935	62	49	57	SW	41	H	
08/15/1936	70	54	63	NW	**	*	
04/21/1937	56	44	52	NE	**	н	
08/16/1938	60	47	55	NE	*1	н	
02/10/1939	60	47	55	SW	19	•	
11/11/1940	70	54	63	S	**	Ħ	
08/29/1941	58	46	54	NW	*	**	
01/01/1942	58	46	54	N	H	**	
05/16/1943	44	42	49	SW	3c	**	
08/15/1944	60	56	66	sw	11	*	
04/05/1945	57	53	62	S	Ħ	н	
11/21/1946	45	42	60	SW	17	30 <b>R</b>	1.
01/30/1947	44	42	60	NE	**	н	**
02/19/1948	48	45	5 <b>5</b>	SW	**	+1	83
		-					

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 368 of 415 Speed at

1. Standardized to 30 M using  $Z_0 = .05$  due to exposure at temporary location.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 369 of 415

Probability	Return Period (years)	30 M Wind Speed (mph) Type I Distribution
.50	2	61
.80	5	69
.90	10	73
.95	20	78
.96	25	79
.98	50	84
.99	100	89
.995	200	93
.998	500	99
.999	1000	103

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 370 of 415 GREEN BAY, WISCONSIN (GRB) APT Z<sub>0</sub>=.05 1949-1979 44 29 88 08 WBAN #14898

	Date	Measured Speed	True Speed	Speed at Standard Ht (30 M)	Direction	Anem Type	Anem Ht	Remarks
-	10/10/1949	72	66	62	SW	3c	47R	
	05/05/1950	<b>96</b>	88	83	SW	"		
	03/03/1951	70	65	61	W		Ħ	
	04/13/1952	61	57	54	NE		н	
	06/04/1953	80	73	69	SW		n	
	03/25/1954	65	60	57	SW	n	Ħ	
	11/16/1955	73	67	63	W	71	"	
	07/01/1956	68	63	60	NW	**	H	
	07/29/1957	76	70	66	NE	-	"	
	11/18/1958	64	59	56	SW		Ħ	
	07/08/1959	52	49	46	SW	H		
	04/11/1960	60	56	53	W		•	
	10/11/1961	55	51	48	SW	Ħ	**	
	11/20/1962	50	47	51	S		20 <b>G</b>	
	04/03/1963	54	50	55	SW		**	
	04/13/1964	64	59	65	SW	**	**	
	06/20/1965	48	45	49	W	**	н	
	10/22/1966	42	40	44	SW	"	n	
	05/18/1967	52	49	54	SW	**		
	05/08/1968	58	54	59	SW	*	n	
	08/13/1969	39	37	41	S	11	**	
	06/17/1970	65	60	66	W	**	17	
	02/27/1971	54	50	55	SW	n	n	
	01/25/1972	45	42	46	W	H	11	
	01'09/1973	50	47	51	NE		11	
	∠1/1974	38	36	39	S	n	IJ	
	01/11/1975	64	59	65	SW	"	n	
	06/15/1976	45	42	46	SW	H	*	
	03/29/1977	54	50	55	SW	11	**	
	01/26/1978	50	47	51	NW	"	н	
	04/05/1979	43	41	45	Ν	11	Ħ	

ţ

-----

Probability	Return Period (years)	10 M Wind Speed (mph) Type I Distribution
.50	2	54
.80	5	62
.90	10	67
.95	20	72
.96	25	73
.98	50	78
.99	100	83
.995	200	88
.998	500	94
.999	1000	99

The data for the years 1980 through 1988 was obtained from the National Oceanic and Atmospheric Administration (NOAA) annual summaries.

Green Bay, Wisconsin

#### Table - Wind Speeds 1980 - 1988

<u>Date</u>	Measured Speed	Direction
05/30/80	40	SW
08/06/81	39	SW
04/03/82	48	NW
02/02/83	45	NE
12/16/84	52*	NW
08/06/85	53*	w
07/27/86	44*	NW
07/09/87	46*	SW
07/09/88	56*	NW

\*Maximum Gust Wind Speed

3

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 372 of 415

### APPENDIX B: Derivation Of Depth Rate

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 373 of 415 DERIVATION OF DEPTH RATE OF RUNOFF FOLLOWING A ONE HOUR PMP STORM

Q = CIA, where

Q = peak coefficient (ft<sup>3</sup>/s) C = runoff coefficient (ft<sup>3</sup> hr)/(acre in s) I = rainfall intensity (in/hr), and A = drainage area (acres)

If C = 0.15, I = 13.0 and A = 6400 acres, then Q = 12,480 ft<sup>3</sup> /s, or 44,928,000 ft<sup>3</sup>/hr spread over the 10 square miles drainage basin.

The average depth rate of runoff over the basin, H, would be:

 $H = 44,928,000/(10 \times 5280^2)$ = 1.9 in/hour

Note: The definition of "C" is such that it also equals the % of rain that appears as direct runoff; therefore, we can also say:

H = CI, then

 $H = 0.15 \times 13.0 \text{ in/hr} = 1.9 \text{ in/hr}$ 

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 374 of 415

#### DERIVATION OF DEPTH RATE OF RUNOFF FOR PMP STORMS OF VARIOUS DURATIONS

If	С	=	0.15,	and	Η	=	IC;	
----	---	---	-------	-----	---	---	-----	--

Duration (Hrs)	PMP Estimate (In)	Hourly Intensity (in/hr)	H <sub>ave</sub> (in/hr)
0.5	10.0	20.0	3.0
1.0	13.0	13.0	1.9
2.0	18.0	9.0	1.4
3.0	20.0	6.7	1.0
6.0	23.0	3.8	0.6
12.0	27.0	2.3	0.3
24.0	29.0	1.2	0.2

Note that the 0.5 PMP storm has a greater value for  $H_{ave}$  than the one hour PMP storm, i.e., 3.0 in/hr > 1.9 in/hr. However, the rainfall intensity associated with the 0.5 hour PMP storm does not persist the full one hour. The maximum height for the 0.5 hour PMP storm is 3.0 in/hr X 0.5 hr = 1.7 inches.

Note also that the depth rate of runoff is called  $H_{ave}$  since these storms are not of one hour duration and the Rational Formula is defined for hourly rainfall intensities. Recall that the brunt of the storm usually occurs in the first few hours.

;

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 375 of 415

**APPENDIX C:** Air Traffic Data

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 376 of 415 Kewaunce site Location 87 - 32/44 - 20

- A. Austin Straubel Airport Green Bay
  - 1. 25 statute miles NW of plant by air
  - 2. Rick Remely Austin Staubel Operations
    - Airways are 8 miles wide
    - Flights that could have impact on plant
       IFR flights = 100/day J106 (114°)

VFR flights  $\approx$  10/day V26-55 (115°)

- 3. 125,000 operations/year
- 4. Phone: (414) 431-5751
- B. Door Co. Cherryland Airport Sturgeon Bay
  - 1. 36 statute miles NE of plant by air
  - 2. Travel is N&S along suoreline, traffic expected during summer months
  - 3. Phone: (414) 743-6952
  - 4. = 50 operations/day during June, July and August = 1/4 to 1/3 are N-S bound

C. Manitowoc Co. Airport - Manitowoc

- 1. 17 statue miles SW of plant by air
- 2. 22,000 operations/year for private and industrial. (No commercial flights into or out of the Manitowoc Airport from Manitowoc operations.)
- 3. Phone: (414) 683-4594
- D. Military Training Flights
  - 1. Nearest military training flight path is 27 statue miles NE of plant out over Lake Michigan. (IR609-610).

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 377 of 415

- 2. Military (Restricted area) R-6903
  - 17 miles from plant near Manitowoc
  - Altitude = (surface to 45,000 ft)
  - 145 operations/year  $\approx$  47 total hours during 25 days [(608) 427-1445]
- Minnow MOA (Military Ops area) = 10 miles SE of plant. Altitude = 10,000 to 18,000
   ft., 35 operations/year
- 4. Phone: (608) 427-1445
- E. Ephraim-Fish Creek
  - 1. 50 miles from plant in Door County
  - 2. Travel is N-S along shore line; traffic is expected during summer months
  - 3. Phone: (414) 854-9711 No estimates could be given

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 378 of 415

- 6. Licensee Participation and Internal Review Team
- 7. Plant Improvements and Unique Safety Features
- 8. Summary and Conclusions

### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 379 of 415 SECTIONS 6, 7, 8

## TABLE OF CONTENTS

## **SECTION**

### PAGE

6. Licensee Participation and Internal Review Team	•					•	•								. 6	5-3
6.1 IPEEE Program Organization		 •													. 6	5-3
6.2 Composition of Independent Review Team			•												. 6	<u>5-3</u>
6.3 Areas of Review and Major Comments	• 1														. 6	5-4
6.4 Resolution of Comments	•	 •	• •	•	•	•	•	 •	•	•	•	•	•	•	. 6	5-4
7. Plant Improvements and Unique Safety Features .	•					•									. 7	7-1
7.1 Level 1 Unique Safety Features																
7.2 Level 2 Unique Safety Features																
7.3 Plant Improvements																
8. Summary and Conclusions															. 8	3-1

#### 6. Licensee Participation and Internal Review Team

#### 6.1 IPEEE Program Organization

Wisconsin Public Service Corporation (WPSC) has committed substantial personnel power financial resources to its Individual Plant Examination for External Events (IPEEE) program. Due to the magnitude of the Kewaunee Nuclear Plant IPEEE Program, WPSC engaged the services of consultants (namely Westinghouse, J. R. Benjamin and Associates, and Stevenson and Associates) to support and direct efforts on the IPEEE. WPSC created a Kewaunee IPEEE team from the interval events PRA tear which effectively used its personnel resources and provided WPSC with complete control and involvement in the IPEEE analyses. In the organizational structure, contractor personnel provided the overall task leadership while both the contractor and the WPSC team jointly performed all the analyses. Interactions between WPSC personnel and the contractor were conducted on a continual basis to resolve issues and incorporate plant specific knowledge. In addition to the IPEEE personnel, other WPSC engineering and support staff provided design and operational information, as well as internal review.

WPSC established an IPEEE Project Manager who was responsible for the overall performance of the IPE project and served as the primary point of contact for the Kewaunee IPEEE. For the Kewaunee IPEEE, an Independent Review Team of WPSC middle level management actively reviewed all results and insights.

The WPSC IPEEE team members were trained and involved in all aspects of the IPEEE project. This included taking part in the IPEEE plant walkdowns, becoming familiar with analyses performed by consultants, and authoring/reviewing sections of the various IPEEE analyses.

The IPEEE project was directed by Westinghouse and supported by WPSC in the Kewaunee IPEEE project with a core of experienced IPEEE personnel, led by a Project Coordinator. The Project Coordinator was responsible to the Project Manager for coordinating project activities and maintaining the project schedule. The Project Coordinator was the primary interface between the contractor personnel and the WPSC IPEEE Project Manager.

A task-by-task participation of the WPSC IPEEE team engineers in the development of the Kewaunee IPEEE is presented in Section 2.3 of this report.

#### 6.2 Composition of Independent Review Team

Although the Kewaunee IPEEE program satisfied the requirements of 10 CFR 50, Appendix B, an additional Independent Review Team was organized to review the various IPEEE analyses. This team generally consisted of middle level managers from applicable engineering and operations organizations as indicated in Table 6-1. The team conducted reviews and commented on all aspects of the IPEEE analyses.

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 381 of 415 6.3 Areas of Review and Major Comments

All areas of the IPEEE were subject to independent review through either the 10 CFR 50, Appendix B process or through consultant support. WPSC engineers were directly involved in a majority of the analysis or review tasks associated with the IPEEE. This approach assured WPSC's involvement in the IPEEE. Although consultants did solely develop and review certain inputs to the IPEEE, WPSC engineers became familiar with these efforts and ensured that the IPEEE properly employed these inputs.

#### 6.4 Resolution of Comments

2

All comments were formally documented and resolved. Any resolution items were dispositioned through immediate changes to the IPEEE models if the effects were anticipated to be significant to the results.

## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 382 of 415

#### TABLE 6-1

Title	IPEEE Area Reviewed
Nuclear Engineer (SQUG)	Seismic PRA
Asst. to Licensing Superintendent	All
Safety Systems Inspection Supervisor	Seismic PRA
Quality Assurance Auditor	Fire PRA*
Shift Supervisor	Fire PRA
Risk Assessment Engineering Supervisor <sup>3</sup>	All
Risk Assessment Supervisor <sup>1</sup>	Fire PRA
Senior Risk Assessment Engineer <sup>2</sup>	Seismic PRA Other External Events
Shift Supervisor	Seismic PRA
Structural Engineer - Nuclear	Seismic PRA

#### INDEPENDENT REVIEW TEAM COMPOSITION

\* Had recently assumed new position. Formerly Fire Protection Operations Supervisor.

<sup>1</sup> Responsible for SPRA and Other External Events Analyses

<sup>2</sup> Responsible for Fire PRA Analysis

<sup>3</sup> IPEEE Project Manager

Ĭ

#### 7. Plant Improvements and Unique Safety Features

#### 7.1 Level 1 Unique Safety Features

Based on performance of the Level 1 PRA analysis, several features of the Kewaunce design have been identified that reduce the likelihood of core damage. These include:

- High head safety injection pumps deliver flow if Reactor Coolant System pressure is less than 2200 psig, which is significantly higher than typical Westinghouse plants designated as low pressure plants.
- Containment sump recirculation can be aligned to the high head safety injection, low head safety injection and containment spray pumps from the control room.
- Three auxiliary feedwater (AFW) pumps (two motor-driven and one turbine driven for diversity), which are independent of external cooling water systems as the pumps are cooled by the fluid being pumped. The Service Water System serves as a backup suction supply to the three AFW pumps.
- Separate eight hour batteries for safeguards and non-safeguards equipment.
- Four safety-related service water pumps for a single unit site.
- The Chemical Volume and Control System has three positive displacement charging pumps which are independent of cooling water systems. One of the pumps is driven by a variable speed DC motor for speed control and is not dependent on instrument air for attaining maximum pump output. Two charging pumps have four hour air supply for speed control. All pumps are capable of being powered by an emergency diesel. Two of the pumps have an alternate AC diesel generator to supply power.
- Two independent methods for maintaining reactor coolant pump seal integrity, seal injection from the charging pumps and thermal barrier cooling via the Component Cooling Water System.

#### 7.2 Level 2 Unique Safety Features

Based on performance of the Level 2 PRA analysis, several features of the Kewaunee design have been identified that reduce the likelihood of containment failure.

The first of these features is the Kewaunee containment heat removal capability. The plant is designed with four containment fan cooling units (FCUs) and two internal containment spray (ICS) trains. Only one FCU or ICS train is needed to preclude containment failure on overpressure. The FCU discharge piping is at high enough elevation to preclude the discharge from being submerged following a loss of coolant accident and refueling water storage tank (RWST) injection.

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 384 of 415

The Kewaunee containment free volume is such that complete oxidation of the fuel cladding does not produce enough hydrogen to challenge the containment structure. The open design promotes good communication between compartments, precluding hydrogen pocketing.

The geometry of the cavity and instrument tunnel is such that deentrainment of debris following high pressure melt ejections will occur, precluding direct containment heating (DCH) as a concern. The cavity floor is large enough to allow the debris to spread into a thin layer, allowing coolability through an ablated vessel. This minimizes the likelihood of non-volatile fission product release.

In general the containment design is capable of handling severe accidents. The conservative 95% confidence containment ultimate pressure is 2.7 times the design pressure. The containment penetrations are capable of withstanding high temperature conditions for extended periods of time. These safety features, inherent in the design of containment, allow the containment structure to respond to severe accidents.

#### 7.3 Plant Improvements

•

No major plant changes have been deemed necessary based on the results of the Kewaunee IPEEE. Some equipment outliers were identified during both the seismic IPEEE/USI A-46 and the evaluation of relay chatter walkdowns. Table 7-1 lists the walkdown findings including the specific resolutions and schedules for completion.

Kewaunee is classified as a focused-scope plant for the purposes of performing relay chatter evaluation. Since the plant is included in the USI A-46 program, relays were evaluated in accordance with Section 6 of the GIP. A focused scope plant that is an USI A-46 plant thus needs only to conduct a "bad actor" relay review if such bad actors were found in the USI A-46 scope of review.

The USI A-46 review found 12 installations of the Westinghouse, Model SC relay in the 4160V switchgear. (Relays in Breakers 502 to 508 and 604 to 609.) The scope of the bad actor review was expanded to include the IPEEE equipment with no additional bad actor relays identified.

WPSC initiated Engineering Support Request (ESR) 94-005 to consider outright replacement of the 12 Westinghouse relays, or alternatively, a reworking of the system circuitry to exclude the Westinghouse relays once emergency AC power has initiated. As such, further consideration of the relay capacities in the SPRA model is not required. Details of the recommended solutions will be provided at a later date in the USI A-46 submittal. Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 385 of 415

Table 7-1 EQUIPMENT OUTLIERS SEISMIC WALKDOWN RESULTS									
EQUIPMENT DESCRIPTION	FINDING	RESOLUTION							
Motor Control Centers MCC52F & MCC52FEXT.	Adjacent MCC's not bolted together, which may pose an interaction hazard based on relay chatter concerns.	Cabinet displacements during a design basis seismic event were determined. The evaluation concluded that the cabinets will not impact.							
Diesel Generator Excitation & Control Cabinets DR101 & DR111.	Several fasteners on cast-in- place anchors were found missing. An overhead emergency light posed an interaction hazard to DR101.	Missing fasteners were installed during the 1992 refueling outage and a restraint was installed on the emergency light during 1993 refueling outage.							
Station Service Transformers 51, 52, 61 & 62.	Transformer cabinets were found anchored to the floor with friction clips, which are considered undesirable according to USI A-46 walkdown guidelines.	A design change was initiated to have the transformer cabinet bases welded to embedded floor channels. Transformers 51 and 52 were modified during the 1994 refueling outage. Transformers 61 and 62 are scheduled for modification during a later refueling outage.							
Relay Racks RR186 & RR187.	The relay racks are not bolted to adjacent panels, which may pose an interaction hazard based on relay chatter concerns.	An engineering support request was initiated to have the racks bolted together to eliminate the concern. A schedule for completion has not been determined.							
Reactor Trip Breaker Cabinet RD106.	Several anchor bolts which connect cabinet to embedded channel were found missing.	A design change was initiated to have the cabinet sections welded to the embedded channel in lieu of installing bolts. Work was completed during the 1993 refueling outage.							

.

٠

Table 7-1 EQUIPMENT OUTLIERS SEISMIC WALKDOWN RESULTS			
EQUIPMENT DESCRIPTION	FINDING	RESOLUTION	
SI Pump B Suction Isolation Valve SI5B.	One leg of a Unistrut frame is within 1/2" of the valve motor, which may present an interaction hazard.	IE Bulletin 79-14 pipe stress evaluation determined that displacement of the pipe and valve is approximately 1/8". Issue considered resolved.	
Main Steam Header A Controlled Relief Valve SD3A.	Valve actuator and yoke are independently braced.	An analysis was performed to qualify support configuration as-is.	
SI Pump Makeup Valve SI101B to Accumulator.	Actuator and yoke are independently braced.	An analysis was performed to qualify support configuration as-is.	
Aux Feedwater Pump Lube Oil Pressure Switches 16016, 16019 & 16085.	All three switches identified as Mercoids, which are considered outliers for the USI A-46 program.	A design modification was previously initiated to have the switches replaced for other reasons. Modification completed in 1993.	
Flux Mapping Transfer Cart (GI-131 Issue).	Two concerns identified; (1) lateral restraints for the 10-path assembly frame were never installed, and (2) chain hoist on overhead rail identified as a possible interaction hazard to 10-path assembly.	It was determined by analysis that lateral restraints are not required to support 10-path assembly under seismic loads. Administrative controls were implemented to restrain hoist at the fixed end of crane rail when not in use.	
Overhead Fluorescent Lights.	Generic problem throughout safety-related areas of the plant. S-hooks on the chains supporting the lights are not closed, presenting a possible interaction hazard to equipment below.	A plant walkdown was conducted during the 1994 refueling outage to pinch the S-hooks closed.	
Emergency Lights.	Some of the lights were found to not have seismic restraints installed, presenting a possible interaction hazard to equipment below.	Lights and battery units strapped to supports as required during 1994 refueling outage.	

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 387 of 415

Table 7-1 EQUIPMENT OUTLIERS SEISMIC WALKDOWN RESULTS			
EQUIPMENT DESCRIPTION	FINDING	RESOLUTION	
480V Switchgear Bus 62.	An empty spare breaker cabinet was used for parts storage, presenting a possible interaction hazard on the basis of relay chatter concerns.	Maintenance department notified of problem. Spare parts were removed and all other spare breaker cabinets were inspected for similar problems during 1993 refueling outage.	
Control Room Ceiling.	Aluminum ceiling diffuser panels were considered as a possible hazard to operators if the diffusers were to dislodge from T-bar supports.	An engineering support request was initiated to have the diffuser panels tie-wrapped to the T-bar supports. A schedule for completion has not been determined.	
Control Room Vertical Panel C.	Rear doors on panel could not be latched shut due to interference with cables that extend from rear of cabinet. Unlatched doors present possible interaction hazard on basis of relay chatter.	It was determined that the cables were temporarily in place to support radiation monitoring modifications. Doors could not impact with cabinet because of cable interference. Operations department agreed to latch doors shut following completion of work during 1994 refueling outage.	
All Equipment	Possible interaction hazards due to loose or unrestrained portable equipment.	Plant procedure GNP 1.31.1 drafted to provide guidelines for control of portable equipment. Full implementation occurred June 1, 1994.	

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 388 of 415

#### 8. Summary and Conclusions

WPSC has performed a complete IPEEE including all credible external events at Kewaunee. This study was performed using a seismic and fire PRA with a fault tree linking methodology and a screening approach for other external events that meets the intent of NUREG-1407. The Kewaunee IPEEE documents the computer models and the results of the analysis that together comply with 10 CFR 50, Appendix B. While contract personnel were used for the Kewaunee IPEEE, WPSC personnel were involved in every aspect of this analysis unrough either detailed review of contract work or actual performance of the analysis. The agreement with the contractor includes a complete transfer of technology upon their completion of services. This technology transfer allows WPSC to update the Kewaunee IPEEE in-house with minimal additional contract work.

It is the intention of WPSC to use the Kewaunee IPEEE as a decision-making tool in many aspects of engineering support and plant operations. Since the IPEEE is a highly technical document and uncertainties do exist in the analysis, the use and interpretation of IPEEE results and conclusions is currently limited to those individuals who have been intimately involved with its development. This approach avoids the problems that might arise from misinterpretation of the study.

#### Seismic

The seismic portion of the IPEEE is a Level 1 effort with both a qualitative and quantitative containment performance analysis, using a seismic PRA (SPRA) approach using guidance described in NUREG/CR-4840, "Procedures for the External Event Core Damage Frequency Analysis for NUREG-1150." In keeping with the requirements of NUREG-1407, both Electric Power Research Institute (EPRI) seismic hazard curves and hazard curves developed by the Lawrence Livermore National Laboratory (LLNL) are used in the analysis. Plant walkdowns provided field information for the component fragility analysis.

#### Seismic Core Damage Summary

In general, no significant seismic concerns were discovered during the seismic IPEEE. The core damage frequency based upon the EPRI Kewaunee site-specific seismic hazard curve is 1.10E-05/year, whereas core damage frequency based upon the 1993 LLNL seismic hazard curve is 1.15E-05/year. Rankings of the dominant contributors to seismic core damage frequency remain the same regardless of the seismic hazard curve. Approximately 76 percent of the CDF is contributed by peak ground acceleration (PGA) values in the range 0.25g to 0.65g.

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 389 of 415 Seismic Containment Performance Summary

As part of the seismic containment walkdowns, containment mechanical penetrations and the containment isolation valves were analyzed for the ability to withstand seismic events. The penetrations and isolation valves form both inside and outside of containment were analyzed. Based upon these plant walkdowns, no significant seismic hazards were found to exist and it was determined that these components possess a high capability to withstand seismic events.

The seismic containment failure frequency is 6.24E-06 which is about the same as the containment failure frequency due to internal events (8.03E-06). The seismic containment failure frequency is 57% of the seismic core damage frequency. The containment failure median capacity and HCLPF for Kewaunee are 0.51 and 0.30g PGA, respectively. The median capacity is about four times the SSE and the HCLPF is two and a half times the SSE. The HCLPF is based on an evaluation of the seismic containment systems model that includes both random and seismic failures. No additional Level 2 vulnerabilities were discovered.

The results of the evaluations performed indicated that the containment as well as the systems designed to ensure containment integrity are seismically sound and no vulnerabilities could be identified.

#### **Relay Chatter Issue**

The relay chatter issue involved interfacing with the USI A-46, "Verification of Seismic Adequacy of Equipment in Operating Plants" program at Kewaunee. USI A-46 "bad actors" relays identified as part of the USI A-46 program were also found within systems modeled for the SPRA. Plans have been developed to replace USI A-46 bad actor relays at Kewaunee that affect operability of safety-related equipment.

#### Fire

The internal fires analysis of the IPEEE is performed for Kewaunee using a Level 1 PRA and a qualitative and quantitative containment performance evaluation. A screening study based on the plant walkdowns and the EPRI Fire-induced Vulnerability Examination (FIVE) Methodology is used to screen out the less important fire areas, while a full PRA is performed for the remaining areas. This analysis is a new fire PRA and follows the guidance identified in NUREG-1407. The deficiencies of past fire PRAs identified in NUREG/CR-5088 "Fire Risk Scoping Study" are addressed in the Kewaunee Fire PRA. The Westinghouse WLINK code is used for fault tree and core melt quantification.

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 390 of 415

#### Fire Core Damage Summary

In general, no significant fire concerns were discovered in the Fire PRA. The core damage frequency due to fire is 9.8E-05/year. This is dominated by fires in the A and B auxiliary feedwater (AFW) pump rooms, which contribute 84% to the total fire core melt frequency. These areas each contain cabling for one train of safe shutdown equipment and cabling for numerous non-safety related equipment, such as transformers supplying offsite power. Kewaunee meets all the requirements of 10 CFR 50, Appendix R, (other than exemptions approved by the NRC) and an additional equipment failure or human error in addition to the fire is necessary for core melt to occur.

#### Fire Human Error Summary

Due to manual actions necessary to respond to a fire, human error is an important contributor to fire core damage frequency, contributing 56% (based on Fussel Vesely importance) to the fire core damage frequency. Of these, the largest contributor is failure to locally establish power to the dedicated (A) train of safe shutdown equipment, contributing 17% to the fire core damage frequency.

#### Fire Containment Performance Summary

Due to the robust design of Kewaunee's large dry containment, no containment failure due to overpressurization are produced by any fire-initiated core damage sequence within the 48 hour containment mission time. The containment failure frequency of 3.64E-05/year is due exclusively to failure to isolate containment. No additional containment failure modes unique to internal fires were identified.

#### High Winds, Floods, and Others

This analysis examines all credible external events other than seismic events and internal fires. Specifically examined in the other external events analysis are external flooding, aircraft accidents, severe winds, ship impact accidents, off-site and on-site hazardous materials accidents, and external fires. No vulnerabilities were identified that require detailed quantification of any accident events. It is, therefore, concluded that the effects from any of the other external events described here are not a significant concern at Kewaunee.

#### **Piant Improvements**

No major plant changes have been decrued necessary based on the results of the Kewaunee IPEEE. Some equipment outliers were identified during both the seismic IPEEE/USI A-46 and the evaluation of relay chatter walkdowns. These include 12 installations of the Westinghouse, Model SC relay in the 4160V switchgear. (Relays in Breakers 502 to 508 and 604 to 609.) WPSC initiated Engineering Support Request (ESR) 94-005 to conside, outright replacement of the 12 Westinghouse relays, or alternatively, a reworking of the system circuitry to exclude the Westinghouse relays once emergency AC power has initiated. Details of the recommended solutions will be provided at a later date in the USI A-46 submittal.

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 392 of 415

## Licensee Response/NRC Response/NRC Question Closure

Id	2991
NRC Question Number	ALK-015
Select Application	Licensee Response
Response Date/Time	5/14/2010 7:50 AM
Closure Statement	
Response Statement	During an informal phone conversation on May 13, 2010, the NRC requested the Powerpoint <sup>™</sup> presentation from a March 30, 2010 discussion related to snubbers be added to the responses for this RAI. Attached is the Powerpoint <sup>™</sup> presentation. KPS notes that a more specific snubber accounting exists in correspondence related to a request to identify specific snubbers. Specifics about the presentation were discussed in detail during the phone conversation on March 30, 2010.
Question Closure Date	
Attachment 1	ALK-015 info.pdf (414KB)
Attachment 2	
Notification	NRC/LICENSEE Supervision Victor Cusumano Jerry Jones Bryan Kays Audrey Klett Ray Schiele
Added By	Robert Hanley
Date Added	5/14/2010 7:52 AM
Modified By	
Date Modified	

# Kewaunee Snubber Presentation ITS 3.0.8

Tom Schneider Cognizant Engineer

## Overview

- Hot shutdown plant
- Piping configuration issues
- Snubber design analysis issues
- Maintenance considerations
- Safety conclusion

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 395 of 415

## Hot Shutdown Plant


- Discussed in the LAR
- Designed and licensed for hot shutdown as safe shutdown
- Piping configurations are not consistently separated by train
- Examples:
  - RHR, SI and CC

# Piping configuration issues

- ~98 safety related within the scope of 3.0.8
- Differing cylinder manufacturers
- Unique rod end attachments
  - Male versus female
  - sizes1 <sup>1</sup>/<sub>2</sub>, 2 <sup>1</sup>/<sub>2</sub>, 3 <sup>1</sup>/<sub>4</sub> and 4 inch diameters with 5,
    6 and 10 inch stroke lengths in various styles
- Snubbers are not easily interchangeable

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 397 of 415





#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 399 of 415



### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 400 of 415



#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 401 of 415




#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 402 of 415



## Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 403 of 415



#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 404 of 415



## Snubber Analysis

- Not analyzed for individual train designation per 3.0.8
  - A failed Snubber typically impacts both trains

## Maintenance considerations

- Scaffold
- Spare parts or repair
- Physical location for some
- Confined space
- ALARA
- Off shift hours/Weather

# Safety Conclusions

- 30+ years with 72 hours to repair
- Historically low failure rate – Maintenance and Materials
- Outage snubber performance
- Replacement time versus shutdown
- Repair is safer than a plant shutdown

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 408 of 415

Id	3011
NRC Question Number	ALK-015
Select Application	NRC Response
Response Date/Time	5/17/2010 6:00 PM
Closure Statement	
	The presentation slides provided on 5/14/10 mentioned that the snubbers had a historically low failure rate. Please provide a more detailed historical perspective on how often snubbers are found or declared inoperable in any given year.
Question Closure Date	
Attachment 1	
Attachment 2	
Notification	NRC/LICENSEE Supervision Victor Cusumano Audrey Klett Carl Schulten
Added By	Audrey Klett
Date Added	5/17/2010 8:25 AM
Modified By	
Date Modified	

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 409 of 415

#### Licensee Response/NRC Response/NRC Question Closure

Id 3201

NRC Question ALK-015 Number Select Licensee Response Application Response 5/25/2010 10:00 AM Date/Time Closure Statement

Statement

Response The NRC requested a more detailed historical perspective on how often snubbers are found or declared inoperable in any given year.

> Since 2000, the following were the most significant snubber deviations identified:

In May 2000, during performance of a snubber visual inspection surveillance, a snubber was identified with a missing pipe clamp nut (i.e., not per the applicable drawing), and the reservoir fluid level appeared to be low. Follow on inspection concluded that the reservoir fluid level was normal (i.e., within the inspection acceptance criterion) with the ram extended. No leakage was identified. The snubber was reinstalled with the missing nut replaced. In this case the snubber was concluded to have been operable.

In November 2001, during routine performance of snubber functional testing surveillance during a refueling outage, a single snubber in test group 4 was found out of the acceptance criterion range for bleed rate. The plant was in a refueling outage with the supported system out of service and the snubber was not required, therefore expedited repair was not required. This snubber failure resulted in testing an additional snubber test group (group 5). This snubber was rebuilt, tested satisfactorily, and reinstalled. In this case the snubber was determined to have been operable while installed.

In January 2006, during performance of a snubber visual inspection surveillance, the same snubber discussed above (i.e., May 2000) was again identified with a missing pipe clamp nut (i.e., not per the applicable drawing). The missing nut was replaced. In this case the snubber was initially declared inoperable, and later, following engineering evaluation, was concluded to have been operable.

In summary, during the last 10 years no snubbers were found or ultimately determined to be inoperable. However, note that in the one case above a snubber was initially declared inoperable, and later, following engineering evaluation, was concluded to have been operable.

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 410 of 415

Question Closure Date	
Attachment 1	
Attachment 2	
Notification	NRC/LICENSEE Supervision Jerry Jones Bryan Kays Audrey Klett Ray Schiele
Added By	Robert Hanley
Date Added	5/25/2010 9:58 AM
Modified By	
Date Modified	

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 411 of 415

Id	3431
NRC Question Number	ALK-015
Select Application	NRC Question Closure
Response Date/Time	
Closure Statement	This question is closed, and no further information is required at this time to draft the Safety Evaluation.
Response Statement	
Question Closure Date	6/7/2010
Attachment 1	
Attachment 2	
Notification	NRC/LICENSEE Supervision Victor Cusumano Audrey Klett Carl Schulten
Added By	Audrey Klett
Date Added	6/7/2010 9:04 AM
Modified By	
Date Modified	

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 412 of 415

### **ITS NRC Questions**

	C C
Id	1841
NRC Question Number	ALK-016
Category	Editorial
ITS Section	3.0
ITS Number	3.0
DOC Number	
JFD Number	
JFD Bases Number	7
Page Number (s)	Vol. 5, page 52 of 63
NRC Reviewer Supervisor	Carl Schulten
Technical Branch POC	Add Name
Conf Call Requested	Ν
NRC Question	JFD #7 for ITS 3.0 Bases, page 52 of 63 of Volume 5, states: "Furthermore, these changes are consistent with industry approved TSTF-494T." This TSTF has not been formally resolved by the NRC; therefore, the NRC staff should not reference this TSTF as a basis for accepting the proposed change. Please delete this sentence from the JFD.
Attach File 1	
Attach File 2	
Issue Date	3/5/2010
Added By	Audrey Klett
Date Modified	
Modified By	
Date Added	3/5/2010 3:25 PM
Notification	NRC/LICENSEE Supervision Audrey Klett

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 413 of 415

Id	2591
NRC Question Number	ALK-016
Select Application	Licensee Response
Response Date/Time	3/15/2010 3:40 AM
Closure Statement	
Response Statement	KPS included the reference to TSTF-494T in order to be consistent with the exact same Justification for Deviation in the Davis-Besse ITS conversion. The Davis-Besse JFD (ITS 3.0 Bases, JFD 16) included the same last sentence concerning TSTF-494T, and the NRC did not question its inclusion. KPS maintained these words so that the JFD would be the same as one already approved by the NRC. However, KPS has no problem removing the sentence from the JFD, since the JFD itself provides adequate justification for the change. A draft markup regarding this change is attached. This change will be reflected in the supplement to this section of the ITS conversion amendment.
Question Closure Date	
Attachment 1	ALK-016 Markup.pdf (268KB)
Attachment 2	
Notification	NRC/LICENSEE Supervision Robert Hanley Jerry Jones Bryan Kays Audrey Klett Ray Schiele
Added By	Robert Hanley
Date Added	3/15/2010 3:36 PM
Modified By	
Date Modified	

#### Attachment 1, Volume 5, Rev. 0, Page 52 of 63

#### Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 414 of 415 JUSTIFICATION FOR DEVIATIONS ITS 3.0 BASES, LCO AND SR APPLICABILITY

- 1. These punctuation corrections have been made consistent with the Writer's Guide for the Improved Standard Technical Specifications, TSTF-GG-05-01, Section 5.1.3.
- 2. The ISTS contains bracketed information and/or values that are generic to all Westinghouse vintage plants. The brackets are removed and the proper plant specific information/value is provided. This is acceptable since the ISTS generic information/value is revised to reflect the current plant design.
- 3. The ISTS Figure B 3.0-1 is located within the text portion of LCO 3.0.6. The typical configuration for locations of figures is at the end of the applicable section. The figure is relocated to the end of the LCO section for 3.0. This is acceptable since the relocation of the figure to the end of the section is in accordance with the format of the ITS.
- 4. Typographical/grammatical error corrected.
- 5. These changes are made to be consistent with changes made to LCO 3.0.4.
- 6. Changes made for enhanced clarity.
- 7. The following fixes to incorrect statements for the examples in the LCO 3.0.6 Bases have been made. Specifically:

1) Example B 3.0.6-1 is changed from "If System 2 of Train A is inoperable and System 5 of Train B is inoperable, a loss of safety function exists in supported System 5" to "If System 2 of Train A is inoperable and System 5 of Train B is inoperable, a loss of safety function exists in Systems 5, 10, and 11." Examining Figure B 3.0-1, it is clear that if there is a loss of safety function in System 5, i.e., Systems 10 and 11. This relationship is explicitly listed in Example B 3.0.6-3 and to not do so here is inconsistent and confusing as it leads the reader to believe that Systems 10 and 11 do not have a loss of safety function. Furthermore, System 5 of Train B is not a supported System of System 2 of Train A, since they are in different trains. Thus, the word "supported" has been deleted.

2) Example B 3.0.6-2 is changed from "If System 2 of Train A is inoperable, and System 11 of Train B is inoperable, a loss of safety function exists in System 11 which is in turn supported by System 5" to "If System 2 of Train A is inoperable, and System 11 of Train B is inoperable, a loss of safety function exists in System 11." The phrase "which in turn is supported by System 5" is confusing. System 5 is not inoperable and does not lead to the loss of safety function. Examples B 3.0.6-1 and B 3.0.6-3 do not discuss OPERABLE support systems. This phrase adds no value and leads the reader to believe there is some special relationship with System 5 which does not exist.

Kewaunee Power Station needs to make these changes since the current wording in the ISTS 3.0.6 Bases are not correct. Furthermore, these changes are consistent—with industry approved TSTF-494T.

Kewaunee Power Station

Page 1 of 2

Attachment 1, Volume 5, Rev. 0, Page 52 of 63

Enclosure - Q&A to Attachment 1 Volume 05 (Section 3.0) Page 415 of 415

Id	2601
NRC Question Number	ALK-016
Select Application	NRC Question Closure
Response Date/Time	
Closure Statement	This question is closed, and no further information is required at this time to draft the Safety Evaluation.
Response Statement	
Question Closure Date	3/15/2010
Attachment 1	
Attachment 2	
Notification	NRC/LICENSEE Supervision Victor Cusumano Audrey Klett
Added By	Audrey Klett
Date Added	3/15/2010 3:40 PM
Modified By	
Date Modified	