

July 29, 2010

NRC 2010-0079 10 CFR 50.90

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555

Point Beach Nuclear Plant, Units 1 and 2 Dockets 50-266 and 50-301 Renewed License Nos. DPR-24 and DPR-27

<u>License Amendment Request 241</u> <u>Alternative Source Term</u> <u>Response to Request for Additional Information</u>

- References: (1) FPL Energy Point Beach, LLC letter to NRC, dated December 8, 2008, Submittal of License Amendment Request 241, Alternative Source Term (ML083450683)
  - (2) NRC electronic mail to NextEra Energy Point Beach, LLC, dated May 13, 2010, DRAFT Request for Additional Information from Mechanical and Civil Branch on AST (ML101340533)
  - (3) NextEra Energy Point Beach, LLC letter to NRC dated November 20, 2009, Transmittal of Information to Support License Amendment Request 241, PBNP VNPAB and CREFS Seismic Evaluation (ML093310308 and ML093310309)

NextEra Energy Point Beach, LLC (NextEra) submitted License Amendment Request (LAR) 241 (Reference 1) to the NRC pursuant to 10 CFR 50.90. The license amendment would revise the current licensing basis to implement the alternative source term (AST) through reanalysis of the radiological consequences of the Point Beach Nuclear Plant (PBNP) Final Safety Analysis Report (FSAR) Chapter 14 accidents.

The NRC staff determined that additional information was required (Reference 2) to enable the staff's review of the amendment request. Enclosure 1 provides the NextEra response to this request for additional information. Enclosure 2 provides Revision 1 of S&A Report No. 09Q0839-R-001, PBNP VNPAB and CREFS Seismic Verification, dated July 15, 2010, which supersedes Revision 0 of this report transmitted in Reference (3).

This letter contains no new regulatory commitments and no revisions to existing regulatory commitments.

Document Control Desk Page 2

The information contained in this letter does not alter the no significant hazards consideration contained in Reference (1) and continues to satisfy the criteria of 10 CFR 51.22 for categorical exclusion from the requirements of an environmental assessment.

In accordance with 10 CFR 50.91, a copy of this letter is being provided to the designated Wisconsin Official.

I declare under penalty of perjury that the foregoing is true and correct. Executed on July 29, 2010.

Very truly yours,

NextEra Energy Point Beach, LLC

\* m/ . Larry Meyer

Site Vice President

Enclosures

cc: Administrator, Region III, USNRC Project Manager, Point Beach Nuclear Plant, USNRC Resident Inspector, Point Beach Nuclear Plant, USNRC PSCW

### ENCLOSURE 1

### NEXTERA ENERGY POINT BEACH, LLC POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

### LICENSE AMENDMENT REQUEST 241 ALTERNATIVE SOURCE TERM RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION

The NRC staff determined that additional information is required (Reference 1) to enable the Staff's review of License Amendment Request (LAR) 241, Alternative Source Term (AST) (Reference 2). The following information is provided by NextEra Energy Point Beach, LLC (NextEra) in response to the NRC staff's request.

### EMCB HVAC RAI 1

Reference 2 (pages 3, 8 and 131) states that:

"[T]he HVAC ductwork and plena for most of the CREFS are covered with a lightweight insulating material that obstructs viewing of some of the duct supports and duct stiffeners... the recirculation duct for the CREFS is un-insulated which allowed the Seismic Review Team (SRT) to examine the construction, stiffener spacing, hanger spacing and type, and material condition of the ductwork. This examination of the recirculation duct indicated the same type and quality of construction as that found for the VNPAB system; therefore the SRT considered it reasonable to adjudge that the number and location of CREFS stiffeners and duct supports within the insulated CREFS systems conform to the SMACNA code (Reference 4) and PBNP Ventilation System Design Specification (Reference 3) requirements and that the duct construction is adequate. The dead load, seismic and pressure stresses in the CREFS ducts, duct stiffeners, and duct supports were evaluated based on this approach."

Reference 2 makes a similar assumptions (on page 15 and in SEWS page 122) for judging acceptable the structural integrity of inaccessible ducts and duct supports located "in locked radiation areas or visually blocked by overhead items and construction scaffolds." Also, on page 141 because duct support anchorage is blocked by fireproofing, the assumption of welding is made for anchorage and the support has been called acceptable. The welding though is of unknown size and quality.

### Please consider that:

a) The SRT has reported in the Screening and Evaluation Worksheets (SEWS) and Section 9.0, Outliers (OLs) of Reference 2, that the accessible ductwork, which they were able to examine, requires additional supports, duct stiffeners and repairs for existing supports and anchorage in order that the AST credited HVAC SSCs will be able to maintain their structural integrity and perform their intended function during and after a seismic event.

- b) The SRT found and recorded (see table in page 7 of Ref 2) that the gage of some of the examined installed ductwork does not appear to be in conformance with the PBNP Ventilation System Design Specification 6118-M-41. Some of the as-installed tested ductwork profile (4/5 tested) was found to be of lesser thickness than the 6118-M-41 specified duct gage.
- c) Experience has shown that inadequate welding (such as field welding without design documentation for size and control) can cause brittle type failure of duct supports. Without inspection of non-designed welds, how can assurance be provided that poor quality or inadequate welding does not exist in these inaccessible areas?

Based on the above, the assumption made in Reference 2, that, by comparison to the accessible and examined ductwork, the inaccessible ducts, duct stiffeners, and duct supports are structurally adequate to withstand an earthquake and perform their intended function during and after a seismic event is not regarded as a sound engineering judgment. Provide a technical justification for the structural adequacy of the AST credited SSCs that were not examined during the walkdowns of Reference 2.

### NextEra Response

a) Control Room Emergency Filtration System (CREFS) Area:

The CREFS mechanical equipment room has an uninsulated 46" x 12" duct run and an uninsulated 50" x 40" duct run which have passed all dead load (DL), seismic and pressure integrity calculation checks (DL for angle, rods and anchors; vertical capacity for anchors and rods; stiffener pressure check and DL and seismic check for allowable duct spans).

The encased (insulated) ducts (five runs) consist of four duct runs of 46" x 12" and one duct run of 40" x 40". In all cases the encased ducts pass all calculation checks, except for the stiffener pressure check, which could not be performed because all of the stiffeners could not be counted due to the encasing insulation cover. However, evidence of stiffeners was found in all runs based on the "bulging" of the insulation where stiffeners were expected.

The number of hangers could be counted so all ducts including the encased ducts passed all other aforementioned calculation checks with the exception of the encased 46" x 12" (#43) duct, which is a cantilever and will be modified to correct the condition.

As such, the only feature that is unverified is the stiffener pressure check for the encased runs, since all of the stiffeners could not be seen. Since the uninsulated 50" x 40" duct and 46" x 12" ducts in the same room easily have enough stiffeners (calculations show a Factor of Safety (FS) greater than 2 for pressure allowable stress). The assumption that the encased ducts have adequate numbers of stiffeners (being of identical or similar size, located in the same room, of the same manufacturer, and presumably installed by the same craft) is seen as reasonable. There are no other unverified design features. In addition, the proposed Technical Specification (TS) 3.7.9, Control Room Emergency Filtration System (CREFS) Surveillance Requirement (SR) 3.7.9.6, "Perform required CRE [Control Room Envelope] unfiltered air inleakage testing in accordance with the Control Room Envelope Habitability Program," includes provisions for measurement of the CRE pressure relative to all external areas adjacent to the CRE boundary during the TS emergency mode of operation. The frequency is 18 months. This surveillance requirement ensures that the CREFS ductwork is adequate for pressure.

### b) Duct Thickness

The thickness measurement was performed at random locations in the primary auxiliary building (PAB) area and in the CREFS mechanical equipment room simply to establish duct thicknesses, since they could not be physically measured. In four out of the six cases measured, the gage met or exceeded the Point Beach Nuclear Plant (PBNP) ventilation specification requirement of two gages stronger (heavier) than the Sheet Metal and Air Conditioning Contractors National Association (SMACNA) requirement (three in the PAB and one in CREFS Room area). In the other two instances, the measurement was lighter than required by the PBNP specification but was still stronger than SMACNA requirement. Given this data, the analyses were conducted conservatively by calculating weight assuming the duct was two gages heavier than SMACNA requires, and calculating engineering strength properties (area, section modulus and moments of inertia) using duct thicknesses equal to minimum SMACNA requirements.

In addition, the calculation of the weight density was also performed conservatively. It is based on the weight of duct per unit length assuming the duct thickness as two gages thicker than required by SMACNA, the weight of stiffeners and the weight of the joints. This calculation was performed for three duct sizes: 46" x 26", 104" x 26" and 30" x 12". The calculated additional weight of the stiffeners and joints over the duct weight itself averages 42%. The final calculation used 50%, a factor of 1.5, to allow for other incidentals (e.g., insulation) and unknowns.

c) Weld Inspections

The only welds not visible were for the support of the duct leading to the exhaust stack. A knee-braced strut hanger is attached to a steel column, but the column is encased in what appears to be gypsum board. As a knee-braced strut mounted to a steel column the dead load is the most significant load it experiences, so it was not unreasonable to assume it would be adequate for the additional stresses due to a seismic event.

Subsequent to the walkdown NextEra removed the fire proofing in order to collect data on the subject welds. Calculations were performed that confirmed that the welds are adequate.

### EMCB HVAC RAI 2

- a) Please verify that the SRT, prior to their walkdowns, for all duct sizes involved in this project, prepared duct span table(s) that were used for screening during their walkdowns.
- b) Provide a summary table which shows the allowable horizontal and vertical spans (and or horizontal to vertical span relationships) along with allowable cantilevered duct lengths for all circular and rectangular duct sizes involved in this project and confirm that these data were calculated using the guidance and criteria provided by Reference 4.
- c) Provide assurance that duct spans nonconforming to these allowable values were further evaluated and found acceptable by analysis or by modification using guidance and criteria contained in Reference 4.

### NextEra Response

- a) A duct span table (Attachment 1) was generated prior to the initial walkdown to assist in the initial screening. During the walkdown, it was determined that it was relatively straightforward to collect data such as duct spans for all accessible ducts, so the table was not used for a detailed evaluation.
- b) Attachment 2 tables provide the calculation results for each duct section evaluated for dead load/seismic using the criteria of the Electric Power Research Institute (EPRI) Seismic Evaluation Guidelines for HVAC Duct and Damper Systems (Reference 5). The calculations are based on the existing horizontal and vertical spans of the ducts as well as the applicable spectral accelerations. The allowable span for each duct is included in the tables. Reference (5) provides an equation for determining the allowable vertical span for a duct that has a three or more span configuration. Since some ducts had different span configurations, equations were developed for ducts with less than three spans using the methodology of Appendix C of Reference (5). Similarly, equations were developed for cantilevered duct sections.
- c) For duct spans that did not meet the criteria as specified in Reference (5), further evaluations were performed. Duct spans found not to be acceptable (see Enclosure 2) will be modified.

### EMCB HVAC RAI 3

Reference 2, Section 6.1.2, states that "The last hangers on cantilevered or terminated ducts in the PAB were examined and found to be positively secured to the end hanger." Provide a justification for omitting this observation in the CREFS ductwork walkdown.

### NextEra Response

The cited observation was not omitted for the CREFS ductwork. Section 6.1.7 of Enclosure 2 discusses the cantilevered duct observed on the CREFS ductwork. This cantilevered duct was evaluated and will be modified to add a lateral support.

### EMCB HVAC RAI 4

Reference 2, Section 6.1.2, also states that "VNPAB ductwork is often not positively secured to the horizontal angle cross-member of the trapeze hangers." And that "The SRT judged that this is unimportant since most hangers consist of trapeze supports that "capture" the ductwork between the vertical support rods thereby ensuring that the ducts cannot fall off the hanger during a seismic event."

- a) The above states that <u>most</u> hangers consist of trapeze supports, etc. Are there any ducts that are not tied down securely on supports of the non-trapeze or non-boxed type supports where the non-secured ducts could possibly displace and hit adjacent SSCs, slide and/or fall off during a seismic event and how have these issues been resolved?
- b) For ducts on trapeze supports and/or on supports that provide a mechanism to capture the duct from falling off but not stop it from possibly displace due to a seismic event, has the SRT considered seismic interactions with adjacent SSCs and how has this issue been resolved?

### NextEra Response

- a) The Seismic Review Team observed one non-trapeze support that was not tied down. This support/duct was classified as an outlier (Enclosure 2, Section 9, Outlier No. 8) and will be repaired by adding fasteners.
- b) A calculation to conservatively determine the lateral displacement of selected long ducts was performed. The results of the calculation show that a lateral displacement of 0.4" was calculated at mid-span for a long 59 foot duct run. This mid-span displacement is small and does not result in seismic interactions with adjacent structures, systems and components (SSCs) for any of the ductwork systems observed.

### EMCB HVAC RAI 5

Reference 2, Section 5.0 (page 8) states that "Specification 6118-M-41 gages will conservatively be used for the dead load and seismic evaluations." The staff notes that four (4) out of the six (6) listed ducts in the table of Section 5.0 are shown to have heavier actual gages than the 6118-M-41 specified gage. Therefore, by using Specification 6118-M-41 gages for these ducts, it produces non-conservative lower deadweight and seismic loads. Provide a technical resolution for this issue.

### NextEra Response

As discussed in Section 5 of Enclosure 2, the assessment of the ducts was performed by using the SMACNA gage to compute the duct capacity (structural section properties, area, section modulus and moments of inertia) and the PBNP ventilation specification gage (2 gages heavier than SMACNA) to determine the dead loads and seismic loads. In addition, the calculation of the weight density is also conservatively performed. It is based on the weight of duct per unit length setting the duct thickness as two gages thicker than SMACNA required, the weight of stiffeners and the weight of the joints. This calculation is based on three duct sizes:  $46^{\circ} \times 26^{\circ}$ ,  $104^{\circ} \times 26^{\circ}$ , and  $30^{\circ} \times 12^{\circ}$ . The calculated additional weight of the stiffeners and joints over the duct weight itself averages 42%. The final calculation uses 50%, a factor of 1.5, to allow for other incidentals (e.g., insulation) and any unknowns.

### EMCB HVAC RAI 6

Reference 2, in table of Section 5.0, contains the width and the diameter of the rectangular and circular ducts that were tested for thickness using ultrasonic testing. Majority (4 out of 5) of the duct profiles tested produced an actual lighter gage than the PBNP Ventilation System Design Specification 6118-M-41.

- a) Please update the table to show both dimensions for the field tested rectangular ducts.
- b) Provide a table which shows all the duct sizes, material and type involved in the AST credited HVAC.
- *c)* Please provide a sound justification for the duct sizes that were not field tested for thickness.

### NextEra Response

- a) Reference (1), Section 5 has been updated to show both dimensions for the field tested rectangular ducts and is provided in Attachment 3. A typographical error in the CREFS duct size has also been corrected.
- b) Attachment 4 shows the duct sizes for all ducts in the program. All ducts are made of galvanized carbon steel and consist primarily of rectangular type ducts with a small number of circular ducts.
- c) A sample of six locations were selected for "skin" thickness testing that reasonably represent the duct profile breadth observed at PBNP, ranging from the smallest (10" x 8") to the largest (104" x 26") chosen sections. Four out of the six locations tested produced thicknesses that meet the PBNP ventilation specification. The other two tested locations fell below the specification, but were still heavier than the SMACNA requirement. Since the section (strength) properties are based SMACNA requirements and the weight (dead load) is based on the specification, this issue is conservatively resolved. See the NextEra response to EMCB HVAC RAI 1b) for the discussion of conservatisms.

### EMCB HVAC RAI 7

Reference 2, Section 6.1.1, "Duct Stresses", states that "The allowable bending stress is 8 ksi for carbon steel." It is noted, that while this is true (per Reference 4) for carbon steel, galvanized sheet and stainless steel rectangular ducts, it is not the case for circular ducts. Please verify that all duct stresses, either by calculation or by sound engineering judgment, after including required modifications, meet the Reference 4 allowable values.

### NextEra Response

There are a very small number of non-rectangular duct sections in the scope of the project. Three non-rectangular duct sections are in high radiation areas and are judged to be acceptable using engineering judgment by the Seismic Review Team (SRT). The basis for this judgment is summarized below. Two circular ducts in the high radiation areas are 8" in diameter and one duct is 10" in diameter. They are uninsulated. The transverse joints appear to be beaded crimp joints, which SMACNA requires be secured with no less than 3 rivets/screws. The ducts are small and lightweight; therefore, by judgment, they will not fail their hanger supports.

The SRT judgment is based on the following considerations. To the extent they were observed, the ducts were single strap supported and anchored to concrete by single expansion anchors (reasonably assumed), which is a very ductile overall configuration. The hanger spacing was not observed; however, SMACNA, Fourth Edition (1969), requires a 10 foot maximum spacing. It is pointed out that Figure 6 of Enclosure 2 shows total horizontal lengths of 15 feet and 10 feet (based on scaling) for the 10" diameter and 8" diameter ducts, respectively. SMACNA-1969 does not require greater than 26 gage for this duct size. Round ducts of this size require no reinforcement for low pressure (2" w.g.) design per SMACNA-1969. Sizing the duct to 24 gage to meet the specification requirement, the minimum thickness required is 0.0239". This means the 10" diameter duct probably weighs about 3 lbs per foot, so the dead load on an anchor is slightly less than 30 lbs using the 10 foot hanger spacing. Actually, the 10 foot tributary span weight assumption is conservative, since the longest horizontal span is approximately 15 feet (based on Figure 6) and at least 2 hangers are needed to support any horizontal span. A system like this will swing much like a pendulum in a seismic event inducing little seismic stress

in the duct. The metal strap is not considered to experience fatigue in such a low cycle event. In addition, this overall system is a return air system such that even if it opened at a seam it would still be able to perform its design function of returning (drawing) air.

PBNP is located in a low seismicity region of the country. Therefore, these lightweight circular ducts are judged to be capable of surviving and functioning through the postulated safe shutdown earthquake (SSE) event.

With regard to the overall acceptability of the duct sections, calculations were performed that determined the interactions for the various evaluations required per Reference (5). When interactions exceeded 1.0, more refined calculations were performed. If the interactions still exceeded 1.0, a modification was proposed (for example, the addition of a support) and a new interaction ratio is calculated.

### EMCB HVAC RAI 8

Reference 2 indicates that for duct support evaluations were performed in accordance with the criteria of the AISC Manual of Steel Construction, 9th Edition.

- a) Please state the design basis AISC steel construction manual edition for original construction.
- b) Please provide reference to the specific controlled documentation that supports the AISC steel construction manual reconciliation from your original construction design basis AISC manual to the 9th Edition.

### NextEra Response

- a) The American Institute of Steel Constuction (AISC) code in affect at the time of design for PBNP was AISC Manual of Steel Constuction, 6<sup>th</sup> Edition, 1967.
- b) No specific controlled documentation exists at PBNP that supports the code reconciliation to the AISC 9<sup>th</sup> Edition. The following portions of the duct evaluations were completed in accordance with the AISC 9<sup>th</sup> Edition:
  - 1. Single angle member evaluation: The 9<sup>th</sup> Edition of AISC presents a detailed methodology for evaluation/design of single angle members including using a 25% factor on determining bending stresses in the angle members in order to account for use of geometric axis, as well as reduced allowable stresses dependent on the angle leg width and thickness. The 6<sup>th</sup> Edition does not contain this methodology. Calculations generated in accordance with the 6<sup>th</sup> Edition would not have considered the 25% increase in stresses, when using geometric axis or a reduction in allowable stresses.
  - 2. Density of steel: Unchanged from 6<sup>th</sup> Edition.

- 3. The capacity of the threaded rods in tension: The 9<sup>th</sup> Edition specifies 0.33 times Fu (0.33\*58\*ksi=19.14 ksi) while the 6<sup>th</sup> Edition states 0.4 times Fy (0.4\*36\*ksi=14.4 ksi). The 6<sup>th</sup> Edition allowable stress is less than the 9<sup>th</sup> Edition. The resulting allowable tension on the rod using 6<sup>th</sup> Edition criteria is 1,590 lbs. Since the majority of rods were attached to shell anchors and the shell anchor allowable (1,095 lbs.) is less than either the 6<sup>th</sup> or 9<sup>th</sup> Edition rod allowable, the shell anchor allowable controlled and was used to evaluate the rod supports. For the cases where the rods were not supported by shell anchors, the rod stresses were low and not the controlling component.
- 4. Section properties for the angles used are the same (note that 9<sup>th</sup> edition shows section properties to thousandths while the 6<sup>th</sup> Edition's precision is to the hundredths).
- 5. Compressive strength and bending allowable stress. Differences between the codes are insignificant.

Therefore, the use of the AISC 9<sup>th</sup> Edition is acceptable.

### EMCB HVAC RAI 9

Are there any walls, floors or ceilings other than reinforced concrete that were used to provide ductwork support and how has their seismic integrity been evaluated?

### NextEra Response

The SRT did not observe any walls, floors or ceilings constructed from materials other than reinforced concrete.

### EMCB HVAC RAI 10

Please verify that in cases where beam clamps are used, clamping frictional forces have not been credited to resist deadweight or seismic (horizontal or vertical) loads.

### NextEra Response

The use of beam clamps to support components is allowed by the Reference 5, EPRI HVAC Seismic Guidelines, and the Generic Implementation Procedure (GIP), as long as the clamps are not oriented in such a way that gravity loads are resisted only by the frictional forces developed by the clamps. Beam clamps oriented this way might loosen and slip off in an earthquake and possibly cause a collapse of the system. The beam clamp seen by the SRT (only one instance was observed) was orientated such that it resisted gravity loads without considering frictional forces.

### EMCB HVAC RAI 11

None of the SEWS shows duct sizes. Please provide the duct sizes (including thicknesses or gages) for submitted SEWS.

### NextEra Response

Attachment 4 provides the duct sizes for all ducts.

### EMCB HVAC RAI 12

The SEWS show only galvanized sheet metal for duct material. Please confirm that all AST credited HVAC ductwork utilizes galvanized sheet metal for duct material.

### NextEra Response

Per the PBNP ventilation specification, all ductwork is specified to be constructed using galvanized sheet metal. The SRT review confirmed this.

### EMCB HVAC RAI 13

The staff notes, that the NRC approved GIP is GIP-2. Reference 2, Section 11.8, makes reference to GIP-2. The SRT utilized GIP-3A to evaluated Control Room HVAC control panel C-67, fans W-1 3 B1 & B2 (Control Room Recirculation Fans), W-14 A & B (F-16 Control Room Charcoal Filter Fans), W21 A & B (PAB Exhaust Fans) and W30 A & B (F-23/F-29 PAB Exhaust Fans). Please verify that GIP-3A has been incorporated in the stations' licensing basis FSAR. If this is not the case, the staff requests that the SEWS be revised to show compliance with GIP-2.

### NextEra Response

The Seismic Evaluation Work Sheets (SEWS) for fans and control panels were inadvertently printed with the GIP Revision 3A SEWS forms. They are revised to use GIP Revision 2 (Corrected 2/14/92) forms (see Enclosure 2).

### EMCB HVAC RAI 14

The SRT's walkdown included the charcoal filter banks located in the same rooms with fans W30A and W30B. The SRT comments shown in the SEWS are as stated below:

"In the same room (about 20 ft away) there are charcoal filter banks in the rooms with a footprint of 107" x 180". The visible 107" side has  $10 - \frac{1}{2}$ " concrete expansion anchors with two anchors having nuts that are raised. The 180" side cannot be fully viewed as it is adjacent to a wall but at least 10 anchors were counted, some of which again were missing nuts or for which the nuts were raised. The two other sides are inaccessible. The filter banks are about 10' high and are adjudged to have a natural frequency in excess of about 20 Hz. Since they cannot uplift the anchors only need to resist base shear and there are sufficient visible anchors to accomplish this so they are declared seismically adequate. They pose no interaction potential risk to the fans."

The SRT comments describe degraded conditions which need to be repaired. There are missing anchor nuts and raised anchor nuts on the sides that were accessible for walkdowns, while two sides on each unit were inaccessible. The provided justification for acceptance lacks rigor. No basis is provided for the judgment that they have a natural frequency in excess of 20 HZ. The SRT did not provide a technical justification which either involved actual dimensions and weights or estimated ones nor a calculation or technical discussion to justify that the lifting force at the bolt pattern, which can be developed due to the CG coupled overturning moment, is overcome by the unit's deadweight or anchorage resistance.

Please provide assurance that these SRT commented non-conformances will be corrected for these important to safety components prior to the proposed AST implementation and provide an acceptable justification for the seismic adequacy of these units.

### NextEra Response

Using the peak of the floor response spectrum, it can be shown that the filter bank overturning does not overcome the restoring moment so the bolts experience no tension. Using a conservative density of 35 lbs per cubic feet, the shear force for the anchors (20 minimum per walkdown notes) is about 1.4K lbs. The anchors are 1/2" diameter concrete expansion anchors, which have a capacity in excess of 2.2K lbs in 3 ksi concrete based on the GIP (see Attachment 6 for the simple rigid body mechanics calculation).

The few missing nuts are not consequential, since they would only be important if the bolts experience tension forces which they do not experience when the most conservative assumptions are made. In addition, the filter bank is not safety-related, cannot seismic interact with (i.e., fall on) the fans in the room given its location, or impede the flow of air by collapsing or sliding in any manner. Note also that the VNPAB filters are not credited in the AST radiological analyses.

### EMCB HVAC RAI 15

Resolutions for the floor response spectrum outliers where demand exceeds capacity for fans W13B1, W13B2, W14A and W14B have not been provided. Provide resolution for these outliers and reference of controlled documentation containing information needed to implement resolution.

### NextEra Response

Each of the SEWS for fans W-13B1, W-13B2, W-14A and W-14B identified issues for each of these four outliers. The seismic demand exceeded the capacity in the low frequency range of the spectral curves, anchorage corrosion was observed (W-13B1 & W-13B2), and the fans are mounted on vibration isolators. The modification of these fans involves the installation of 3-way restraints that will render the vibration isolators ineffective. This work will be performed under Engineering Change (EC) 11690, Alternative Source Term Implementation and CREFS Upgrades to Support AST License Amendment Request, which is currently scheduled to be installed by the end of 2010, prior to implementation of the Alternative Source Term license amendment. The identified corrosion will be cleaned and the load path and anchorage will be re-inspected to confirm their effectiveness and repaired, as required, to ensure that seismic capacity exceeds seismic demand.

### EMCB HVAC RAI 16

The SRT observed corroded anchorage of fans W13B1 and W13B2. Shown in the SEWS, the SRT's resolution for these outliers was to replace the corroded anchorage. Please include these outliers in the list of OLs of Section 9.0 and provide reference of controlled documentation which provides information needed to implement these repairs.

### NextEra Response

Section 9.0, Outliers, of Enclosure 2 has been revised to include the three caveats for fans W-13B1 and W-13B2 and is included as Attachment 7. Repairs for the fan outliers will be completed under EC 11690, Alternative Source Term Implementation and CREFS Upgrades to Support AST License Amendment Request, and are currently scheduled to be installed by the end of 2010.

### EMCB HVAC RAI 17

- a) Provide a list of all required HNAC modifications identified in Reference 2. The list of outliers (OLs) and recommended resolutions in Section 9.0 Reference 2 does not contain all SRT identified OLs.
- b) Please provide reference of controlled documentation containing information needed to implement resolution of the identified outliers and documentation which tracks the schedule of repairs and assures that all HVAC required modification will be completed prior to implementing the proposed AST. Also provide resolution where resolution has not been provided.

### NextEra Response

- a) All equipment and duct outliers are now identified in the summary table in Section 7.0 of Enclosure 2. The table (Attachment 7) has been revised to include the three attributes for each of the four fan outliers
- b) The upgrade of the supports for fans W-13B1, W-13B2, W-14A and W-14B is being tracked under EC 11690, Alternative Source Term Implementation and CREFS Upgrades to Support AST License Amendment Request, and are scheduled to be installed by the end of 2010. Other seismic upgrades to the VNPAB and CREFS ventilation systems are being tracked under Engineering Change 14606, Modify PAB Exhaust and CREFS HVAC As Required for Seismic Qualification. The implementation of the Alternative Source Term (AST) license amendment following approval by the NRC staff is controlled under Engineering Change EC 11690, Part H, "Physical, procedural, and licensing basis changes to be implemented once the NRC SE is received for LAR 241." The engineering change package for EC 11690, Part H, includes the development of a transition plan, which will establish and control the required seismic upgrades and other plant modifications to ensure they are completed prior to implementation of LAR 241. In addition, a PBNP High Impact Team (HIT) has been chartered to develop the transition plan and coordinate its implementation to ensure prerequisite modifications are completed prior to LAR 241 implementation.

The following documents are provided as Attachments to Enclosure 1:

Attachment Number	Document
1	Allowable Span Tables
2	Dead Load/Seismic Evaluations
3	Ductwork Ultrasonic Thickness Measurement Results
4	Duct Summary Tables
5	PBNP Ventilation Material Specification
6	Charcoal Filter Bank Calculation
7	Seismic Evaluation Outliers

### **References**

- NRC electronic mail to NextEra Energy Point Beach, LLC, dated May 13, 2010, DRAFT Request for Additional Information from Mechanical and Civil Branch on AST (ML101340533)
- (2) FPL Energy Point Beach, LLC letter to NRC, dated December 8, 2008, License Amendment Request 241, Alternative Source Term (ML083450683)
- (3) NextEra Energy Point Beach, LLC letter to NRC dated November 20, 2009, Transmittal of Information to Support License Amendment Request 241 PBNP VNPAB and CREFS Seismic Evaluation (ML093310308 and ML093310309)
- (4) NextEra Energy Point Beach, LLC letter to NRC dated April 20, 2010, Supplement to License Amendment Request 241, Alternative Source Term, Proposed Technical Specifications for Control Room Emergency Filtration System (CREFS) (ML101100605)
- (5) NextEra Energy Point Beach, LLC letter to NRC dated January 14, 2010, Transmittal of Information to Support License Amendment Request 241, Alternative Source Term, Seismic Evaluation Guidelines for HVAC Duct and Damper Systems (ML100190066),

### ENCLOSURE 1 ATTACHMENT 1

### NEXTERA ENERGY POINT BEACH, LLC POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

### LICENSE AMENDMENT REQUEST 241 EXTENDED POWER UPRATE RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION

### ALLOWABLE SPAN TABLES

### Attachment 1 – Allowable span table Auxiliary Building



Duct wall material density Allowable material stress (=1.7 \* Fb) Horizontal peak spectral acceleration (@26 feet) Vertical peak spectral acceleration Ratio (Horizontal restraint span length/Vertical support span length)

H (in)	W (in)	K1	L (ft) -
20	20	2.8011	13.64
26	16	3.5309	11.86
34	12	4.8526	9.66
36	24	2.2640	12.39
36	36	1.4383	13.94
40	20	2.7432	11.25
48	20	2.7341	10.59
48	70	0.7593	15.00
52	22	2.4540	10.69
•••••••••••••••••••••••••••••••••••••••		·	nage franker i s

THE R	20x20	26x16	34x12	36x24	36x36	40x20	48x20	48x70	52x22
1	 15.00	15.00	15.00	15.00	15.00	15.00	15.00	15.00	15.00
2	15.00	15.00	15.00	15.00	15.00	15.00	15.00	15.00	15.00
<b>3</b>	15.00	15.00	15.00	15.00	15.00	15.00	15.00	15.00	15.00
4	15.00	14.72	12.04	15.00	15.00	13.99	13.18	15.00	13.30
5	13.64	11.85	9.66	12.39	13.94	11.25	10.59	15.00	10.69



Attachment 1 – Allowable span table Auxiliary Building

Attachment 1 – Allowable span table Control Building



Duct wall material density Allowable material stress (=1.7 \* Fb) Horizontal peak spectral acceleration (@74 feet) Vertical peak spectral acceleration Ratio (Horizontal restraint span length/Vertical support span length)

🛛 🕂 (în)	W (in)	K1	L (ft)
20	20	1.0145	15.00
26	16	1.2413	15.00
34	12	1.6716	15.00
36	24	0.7996	15.00
36	36	0.5392	15.00
40	20	0.9565	15.00
.48	20	0.9473	15.00
48	70	0.2840	15.00
52	22	0.8543	15.00
a de la company de la comp			

R. 100	20x20	26x16	34x12	36x24	36x36	40x20	48x20	48x70	52x22
1	15.00	15.00	15.00	15.00	15.00	15.00	15.00	15.00	15.00
2	15.00	15.00	15.00	15.00	15.00	15.00	15.00	15.00	15.00
3	15.00	13.58	11.09	14.19	15.00	12.90	12.15	15.00	12.27
4	11.83	10.26	8.35	10.72	12.09	9.73	9.15	13.25	9.24
5	9.51	8.23	6.69	8.61	9.72	7.81	7.34	10.69	7.41



### ENCLOSURE 1 ATTACHMENT 2

### NEXTERA ENERGY POINT BEACH, LLC POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

### LICENSE AMENDMENT REQUEST 241 EXTENDED POWER UPRATE RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION

### DEAD LOAD/SEISMIC EVALUATIONS

## **DUCT DEAD LOAD & SEISMIC EVALUATION SHEET**

Vertical peak spectral acceleration

(d<sup>-</sup> =) seerial stress (= Fb)

Duct wall material density (=1.5 \* 0.284)

Horizontal peak spectral acceleration (@26 feet) for 7 % damping

**ΟΝΡΑΒ - ΡΥΜΑΙΧΙΧ Αυχιμαγγα - ΒΑ**ΑΝΥ

s'<u>g</u> 4011.0 =v2

Sa= 0.8294 g's

Fb SSE=

]= d

isq 0008

6.426 lb/in3

Increase factor determined to account for miscellaneous components

Seference 3

Per PB Seismic Design Criteria Guidelines, DG-C03 Revision 0 Per PB Seismic Design Criteria Guidelines, DG-C03 Revision 0

	0.42	16.00	1.2473	≥ 3 Spans	6.33	5	61	8	81	53
	0.42	16.00	1.1236	≥ 3 Spans	6.33	7	61	15	81	52
	69.0	28.11	7470.2	≥ 3 Spans	01.8	4	9.04	15	54	61
(£)	21.12	6.34	1049.7	≥ 3 Spans	۲.13	L	29	81	91	81
	0.43	97.6	r097.0	Cantilever	4.00	5	299'6	8	54	21
	0.43	12.04	1.2004	≥ 3 Spans	£.20	4	56	50	40	91
(£)	1.02 20,1	90.7	0489.4	≥ 3 Spans	7.22	8	99	15	30	91
	88.0	16.00	6809.0	1-2 Spans	13.13	L	52.92	34	14	14
	88.0	15.00	9278.0	1-2 Spans	13.13	L	56.25	14	34	14
	0.39	15.00	0.3492	1-2 Spans	58.3	L	29.11	91	34	138
	95.0	74.41	6688.0	≥ 3 Spans	97.29	3	51	50	98	A11
	72.0	19 <sup>.</sup> 00	2,2829	≥ 3 Spans	4.00	5	15	9	01	01
	68.0	5.22	2885.3	≥ 3 Spans	78.4	11	99	50	40	8
	0.43	16.00	£272.1	1-2 Spans	09.9	L	13	9	01	G
	29'0	12.9	2.8219	≥ 3 Spans	4.18	01	97	50	92	4
	0.72	62.3	9262°C	≥ 3 Spans	4.18	01	97	97	99	3
	96'0	21.8	6.2711	≥ 3 Spans	4.92	44	69	56	84	7
	98.0	97.8	2.4245	≥ 3 Spans	4.92	66	69	56	104	٢
	Dead Load/Seismic	(f) nsq2IA (S)	או (ו)	Configuration	Average Tributary Span Per Vertical Support (ft)	stagnsH.V.	(1) uedS	(ui) tuɓiəH	(ui):thbiW	ON.
	IC Stress Check	meie2 bns i	Dead Load			Data				

				Data			Dead Load	and Seism	ic Stress Check
No.	. Width (in)	Height (in)	L Span (ft)	N Hangers	Average Tributary Span Per Vertical Support (ft)	Support Configuration	K1 (1)	All. Span (ft) (2)	Dead Load/Seismic Interaction Ratios
24	12	6	19	2	6.33	≥ 3 Spans	1.9309	15.00	0.42
26	26	16	22.33	3	5.58	≥ 3 Spans	1.2440	14.13	0.40
27	16	30	34	3	8.50	≥ 3 Spans	1.9503	10.78	0.79
28	20	16	35	4	7.00	≥ 3 Spans	2.4328	10.91	0.64
29	30	12	22	3	5.50	≥ 3 Spans	1.1426	14.74	0.37
34	70	48	20	3	5.00	Cantilever	0.4336	6.39	0.78
35	66	40	23.5	3	5.88	Cantilever	0.4671	6.49	0.91
36	24	12	12	2	4.00	≥ 3 Spans	0.8731	15.00	0.27
37	24	12	12	0	12.00	Cantilever	0.2749	14.52	0.83
38	24	12	12	2	4.00	≥ 3 Spans	0.8731	15.00	0.27
39	24	12	12	3	3.00	≥ 3 Spans	1.3988	14.39	0.21

(1) Derived constant K1 in accordance to EPRI Report, "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems", Appendix C (page C-2)

(2) Allowable span calculated in accordance to EPRI Report, "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems", Appendix C (page C-1)
 (3) Detailed evaluation results in an interaction ratio less than 1.0

### **DUCT DEAD LOAD & SEISMIC EVALUATION SHEET**

VNPAB - PIPEWAY # 1

ρ = 0.426 lb/in3 Fb SSE= 8000 psi Sa= 1.2788 g's Sv= 0.1104 g's

Duct wall material density (=1.5 \* 0.284) Allowable material stress (= Fb) Horizontal peak spectral acceleration for 7 % damping Vertical peak spectral acceleration Increase factor determined to account for miscellaneous components Reference 3 Per PB Seismic Design Criteria Guidelines, DG-C03 Revision 0 Per PB Seismic Design Criteria Guidelines, DG-C03 Revision 0

				Data			Dead Lo	ad and Seismic	Stress Check
No.	Width (in)	Height (in)	L Span (ft)	N Hangers	Average Tributary Span Per Vertical Support (ft)	Support Configuration	K1 (1)	All. Span (ft) (2)	Dead Load/Seismic Interaction Ratios
6	10	8	32	5	5.33	≥ 3 Spans	11.5485	7.08	0.75
7	10	6	16	3	4.00	≥ 3 Spans	5.4522	10.94	0.37

Derived constant K1 in accordance to EPRI Report, "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems", Appendix C (page C-2)
 Allowable span calculated in accordance to EPRI Report, "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems", Appendix C (page C-1)

# Attachment 2 - Dead load/seismic evaluations

### **DUCT DEAD LOAD & SEISMIC EVALUATION SHEET**

VNPAB - PIPEWAY #3

ρ=	0.426	lb/in3
-b SSE=	8000	psi
Sa=	1.2618	g's
Sv=	0.1104	g's

Duct wall material density (=1.5 \* 0.284) Allowable material stress (= Fb) Horizontal peak spectral acceleration for 7 % damping Vertical peak spectral acceleration Increase factor determined to account for miscellaneous components Reference 3

Per PB Seismic Design Criteria Guidelines, DG-C03 Revision 0 Per PB Seismic Design Criteria Guidelines, DG-C03 Revision 0

No.         Width (in)         Height (in)         L: Span (ft)         N: Hangers         Average Tributary Span Per Vertical Support (ft)         Support Configuration         K1 (1)         All: Span (ft) (2)         Dead Load/Seismic Interaction Ratios						Data			Dead Lo	ad and Seis	mic Stress Check	
	-AVE COVERAN	No,	Width (in)	Height (in)	L Span (ft)	N Hangers	Average Tributary Span Per-	Support Configuration	K1 (1)	All. Span (ft)	(2) Dead Load/Seismic	
		304	<u>12</u>	14	22	2	5 50	Cantilever	A 1363	1.40		

(1) Derived constant K1 in accordance to EPRI Report, "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems", Appendix C (page C-2)

(2) Allowable span calculated in accordance to EPRI Report, "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems", Appendix C (page C-1)
 (3) Outlier - support will be added. Revised interaction ratio = 0.56.

### DUCT DEAD LOAD & SEISMIC EVALUATION SHEET

VNPAB - PIPEWAY #4

ρ = 0.426 lb/in3 Fb SSE= 8000 psi Sa= 0.8758 g's Sv= 0.1104 g's Duct wall material density (=1.5 \* 0.284) Allowable material stress (≈ Fb) Horizontal peak spectral accelerationfor 7 % damping Vertical peak spectral acceleration Increase factor determinded to account for miscellaneous components Reference 3

Per PB Seismic Design Criteria Guidelines, DG-C03 Revision 0 Per PB Seismic Design Criteria Guidelines, DG-C03 Revision 0

				Data			Dead Lo	ad and Seismi	c Stress Check
No.	Width (in)	Height (in)	L Span (ft)	N Hangers	Average Tributary Span Per Vertical Support (ft)	Support Configuration	K1 (1)	All. Span (ft) (2)	Dead Load/Seismic Interaction Ratios
25	12	6	34.5	4	6.90	Cantilever	4.7691	4.93	1:40

(1) Derived constant K1 in accordance to EPRI Report, "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems", Appendix C (page C-2)
 (2) Allowable span calculated in accordance to EPRI Report, "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems", Appendix C (page C-1)
 (3) Outlier - support will be added. Revised interaction ratio = 0.63.

### **DUCT DEAD LOAD & SEISMIC EVALUATION SHEET**

**CREFS - CONTROL ROOM HVAC ROOM** 

 $\rho = \boxed{ 0.426 \text{ lb/in3} } \\ Fb \ SSE = \boxed{ 8000 \text{ psi} } \\ Sa = \boxed{ 1.512 \text{ g's} } \\ Sv = \boxed{ 0.1104 \text{ g's} } \\$ 

ħ

Duct wall material density (=1.5 \* 0.284) Allowable material stress (= Fb) Horizontal peak spectral acceleration for 7 % damping Vertical peak spectral acceleration Increase factor determined to account for miscellaneous components Reference 3

Per PB Seismic Design Criteria Guidelines, DG-C03 Revision 0 Per PB Seismic Design Criteria Guidelines, DG-C03 Revision 0

				Dead Lo	ad and Seismic	Stress Check	1000			
No.	Width (in)	Height (in)	L Span (ft)	N Hangers	Average Tributary Span Per Vertical Support (ft)	Support Configuration	K1 (1)	All. Span (ft) (2)	Dead Load/Selsmic Interaction Ratios	
43	46	12	42	5	7,00	Cantilever	2.6686	3.67	1.91	(3
44	46	12	10.5	2	3,50	≥ 3 Spans	0.8150	14.86	0.24	
45	46	12			Judg	ed to be accep	otable			]
46	46	12			Judg	ed to be accep	otable			
47	40	40	27	5	4.50	≥ 3 Spans	2.9136	6.69	0.67	]
48	50	40	27	6	3.86	≥ 3 Spans	3.1370	6.08	0.63	
49	46	12	18	3	4.50	≥ 3 Spans	1.2955	11.78	0.38	

(1) Derived constant K1 in accordance to EPRI Report, "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems", Appendix C (page C-2)
(2) Allowable span calculated in accordance to EPRI Report, "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems", Appendix C (page C-1)
(3) Outlier - support will be added. Revised interaction ratio = 0.85.

### ENCLOSURE 1 ATTACHMENT 3

### NEXTERA ENERGY POINT BEACH, LLC POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

### LICENSE AMENDMENT REQUEST 241 EXTENDED POWER UPRATE RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION

### DUCTWORK ULTRASONIC THICKNESS MEASUREMENT RESULTS

PBNP VNPAB and CREFS Seismic Verification S&A Report 09Q0839-R-001

1 All dampers shall be products of reputable manufacturers.

2 Rectangular ducts shall be constructed of galvanized steel in accordance with the latest standards of the American Society of Heating, Refrigeration and Air Conditioning Engineers and the SMACNA requirements for low, medium and high-pressure systems. Round ducts shall be either galvanized steel spiral pipe with four-ply lockseams, or galvanized metal sheets with continuous butt-welded seams reinforced with angular hoop braces. The CREFS and VNPAB HVAC systems are designed as low-pressure systems.

3 Hangers and supports shall be designed to support the weight of the duct or equipment and shall have a minimum factor of safety of five based on ultimate tensile strength of material used.

- 5. Support spacing for ducts shall not exceed approximately;
- a. 96" for ducts whose greater dimension is under 18"
- b.  $66^{\circ}$  plus or minus for ducts  $18^{\circ} 60^{\circ}$  on the maximum side.

The SRT walkdown SEWS are provided in an attachment to this report.

As part of the walkdown the SRT enlisted the help of the PBNP Ventilation System Engineer who is experienced in HVAC duct construction in order to identify and confirm the type of duct joints used in the construction of the ductwork. The results of this effort are discussed in Section 6.1.3 of this report.

Additionally the SRT enlisted the services of the PBNP ISI group in order to confirm the sheet metal gage used for the ductwork. The SRT selected 5 locations in the PAB and one location on the CREFS for ultrasonic testing in order to confirm that the ductwork gage met SMACNA requirements. Specification 6118-M-41 requires that the gage of the duct is two gages heavier than that required by SMACNA. Ductwork for the VNPAB and the CREFS were tested using ultrasonic testing with the following results as shown in the table below:

Duct Dimension (WxH)	Location	Measured (in)	SMACNA Required	6118-M-41 Spec Required
104"x26"	PAB EL 8' Area 4	0.057 (17 gage)	0.0516 (18gage)	0.0635 (16 gage)
76"x20"	PAB EL 8' Area 4	0.053	0.0396 (20 gage)	0.0516 (18 gage)
56"x26"	PAB EL 8' Area 4	0.043	0.0396 (20 gage)	0.0516 (18 gage)
48"x26"	PAB EL 8' Area 4	0.043	0.0336 (22 gage)	0.0396 (20 gage)
10"x8"	PAB EL 8' Area 4	0.033	0.0217 (26 gage)	0.0276 (24 gage)
50"x40"	CREFS Recirc Duct	0.040	0.0336 (22 gage)	0.0396 (20 gage)

The data show that the actual ductwork gages always exceed the SMACNA minimum required gages but not always by 2 gages. Sometimes the actual gage appears to be only one gage heavier. This could also be attributable to measurement precision. For this evaluation the SMACNA minimum gages will be used for the pressure evaluations

### ENCLOSURE 1 ATTACHMENT 4

### NEXTERA ENERGY POINT BEACH, LLC POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

### LICENSE AMENDMENT REQUEST 241 EXTENDED POWER UPRATE RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION

### DUCT SUMMARY TABLES

.

### **DUCT DATA** VNPPB - РКІМАҮҮ АUXILIAY BUILDING

	Judged to be acceptable						SS "Þ		
≥3 Spans	4.05	6	01.8	4	40.5	15	54	61	
snsq2 5 ≤	00.78	0	51.7	۷	29	81	91	81	
Cantilever	5.42	3	4.00	z	<u>49</u> .6	8	54	21	
≥ 3 Spans	21.2	11	2.20	4	92	50	40	91	
≥ 3 Spans	3.82	91	7.22	8	99	15	30	91	
snaq2 2-1	97.6	9	13.13	ŀ	56.25	34	14	14	
sneq2 2-1	97.6	9	13.13	L	56.25	14	34	14	
snsq2 S-f	5.33	4	58.3	ŀ	29.11	91	34	138	
		acceptable	Judged to be		· · · · · ·	81	34	AEL	
	Judged to be acceptable								
		acceptable	Judged to be			50	36	811	
snsq2 5 ≤	3.50	G	6.25	£	51	50	36	Alt	
≥ 3 Spans	12.00	0	4.00	5	12	9	01	01	
		acceptable	ad of begbul			9diq "4		6	
≥ 3 Spans	79.2	50	79.4	11	99	50	40	8	
snaq2 S-f	13.00	0	09.9	ŀ	13	9	01	G	
≥3 Spans	5.42	81	4.18	01	97	50	92	4	
snsq2 č ≤	5.42	81	4,18	01	97	97	99	ε	
snsq2 č ≤	2.68	51	4.92	11	69	56	84	5	
snsq2 5 ≤	2.68	51	4.92	11	69	92	104	L	
Configuration	Average Tributary Span Per Stiffener (ft)	N Stiffeners	Average Tributary Span Per Vertical Support (ft)	siegnsH V	(1) ned2 J	(ni) thgiəH	(ui) dibiW	:oN	
			Data						

	Data							
No.	Width (in)	Height (in)	L Span (ft)	N Hangers	Average Tributary Span Per Vertical Support (ft)	N Stiffeners	Average Tributary Span Per Stiffener (ft)	Support Configuration
21	8	6	Judged to be acceptable					
22	18	12	19	2	6.33	1	9.50	≥ 3 Spans
23	18	8	19	2	6.33	0	19.00	≥ 3 Spans
24	12	6	19	2	6.33	0	19.00	≥ 3 Spans
26	26	16	22.33	3	5.58	7	2.79	≥ 3 Spans
27	16	30	34	3	8.50	13	2.43	≥ 3 Spans
28	20	16	35	4	7.00	12	2.69	≥ 3 Spans
29	30	12	22	3	5.50	6	3.14	≥ 3 Spans
32	54	ļ"Φ		I	Exhaust stack - calculations	s indicate as a	cceptable.	
33	12	6			Judged to be	acceptable		
34	70	48	20	3	5.00	6	2.86	Cantilever
35	66	40	23.5	3	5.88	6	3.36	Cantilever
36	24	12	12	2	4.00	2	4.00	1-2 Spans
37	24	12	12	0	12.00	0	12.00	Cantilever
38	24	12	12	2	4.00	3	3.00	≥ 3 Spans
39	24	12	12	3	3.00	4	2.40	≥ 3 Spans
40A	8"	Φ	Judged to be acceptable					
40B	10	8		Judged to be acceptable				
41	8'	'Φ		Judged to be acceptable				
42	10	)"Ф	Judged to be acceptable					

	Support Configuration	≥ 3 Spans	≥ 3 Spans
	Average Tributary Span Per Stiffener (ft)	32.00	16.00
	N Stiffeners	0	0
Data	Average Tributary Span Per Vertical Support (ft)	5.33	4.00
		5	e
	L.Span (ft)	32	16
	Height (in)	ω	9
	Width (n)	10	10
	No.	9	7

ſ.

# 

VNPAB - PIPEWAY # 3

	Data								
No.	Width (in)	Height (in)	L Span (ft)	N Hangers	Average Tributary Span Per Vertical Support (ft)	N Stiffeners	Average Tributary Span Per Stiffener (ft)	Support Configuration	
30A	12	14	22	3	5.50	0	22.00	Cantilever	
30B	30B Inaccessible Hi Rad areas, judged to be acceptable (1)								
31	Inaccessible Hi Rad areas, judged to be acceptable (1)								

(1) See additional discussion in Reference 1

	Support Configuration	Cantilever	
	Average Tributary Span:Per Stiffener (ft)	34.50	
	N Stiffeners	0	
Data	Average Tributary Span Per Vertical Support (ft)	6.90	
	N'Hangers	4	
	L.Span (ft)	34.5	
	Height (m)	g	
	Width (In)	12	
	No.	25	

### DUCT DATA

CREFS - CONTROL ROOM HVAC ROOM

	Data								
No.	Width (in)	Height (in)	L Span (ft)	N Hangers	Average Tributary Span Per Vertical Support (ft)	N Stiffeners	Average Tributary Span Per Stiffener (ft)	Support Configuration	
43	46	12	42	5	7.00	Note 1	-	Cantilever	
44	46	12	10.5	2	3.50	Note 1	-	≥ 3 Spans	
45	46	12		Judged to be acceptable					
46	46	12		Judged to be acceptable					
47	40	40	27	5	4.50			≥ 3 Spans	
48	50	40	27	6	3.86	10	2.45	≥ 3 Spans	
49	46	12	18	3	4.50	7	2.25	≥ 3 Spans	

-

Note 1 - See additional discussion in Reference 1

### ENCLOSURE 1 ATTACHMENT 5

### NEXTERA ENERGY POINT BEACH, LLC POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

### LICENSE AMENDMENT REQUEST 241 EXTENDED POWER UPRATE RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION

### **PBNP VENTILATION MATERIAL SPECIFICATION**
Specificatio: No. 6118-M-41 Job No. 6118 September, 1968

Seller shall install 3/4 inch couplings welded to duct work, and capped, for pitot tube or other testing apparatus connections.

Test connections shall be located in the duct work downstream of all units or fans, and in plenums or duct work upstream of all units or fans. Where multiple zone systems are used, a connection shall . be installed in each zone duct downstream of the point where the cold duct and hot duct join together. Care shall be used to see that these test connections are installed in straight runs and not close to turns of elbows where possible.

c. Where fans arc in packaged units, a test connection shall be installed in the packaged unit housing upstream of the fan or fans.

4.4 Sheet Metal Work

а.

Test Connections

ā.

ь.

1

Sheet metal WORK shall be required for all systems noted under Scope of Work and shall include furnishing and installation of intake and exhaust louvers and screens, plenum structures and casings (except where otherwise indicated on drawings), access doors, dampers, guards for fan drives, condensate collecting pans, close-off panels around coils, filters, or dampers, flexible connections, duct disconnect couplings, gaskets, fire dampers as required, ductwork, fittings, grilles, registers, outlets, air check valves, testing and testing records.

Ductwork shall comply with the following minimum requirements:

- <u>Rectangular ducts</u> shall be constructed of galvanized steel in accordance with the latest standards of the American Society of Reating, Refrigerating and Air Conditioning Engineers and the SNACNA requirements for low, medium and high pressure systems. Note that all duct dimensions indicated are inside dimension of duct, not including flange dimensions.
- 2. Round ducts shall be either galvanized steel spiral pipe with four-ply lockseams, or

-21--

..... ----Specification No. 6118-M-41 Job No. 61. September 15.3 galvanized metal sheets with continuous butt welded seams reinforced with angular hoop braces. Note that all duct dimensions indicated are inside dimensions. · . \* ... The terms "Low Pressure" and "Low Velocity" means velocities less than 2000 fpm and static pressures in duct of less than 2" of water. ь. The term "Medium Pressure" means pressure in the ċ. duct from 2" up thru 6" of water. . The term "High Pressure" means pressure in the duct over 6" and up to 19" of water. đ. ٠. Ductwork materials shall conform to the followe. ing requirements: All ductwork shall be made of galvanized steel except where otherwise herein specified or in-dicated on the drawings. 1. 2. Galvanized steel ductwork shall be fabricated from galvanized steel of the quality produced in the United Status by The Ryersor Steel Co. under the trade name "Galvancal" and furnished in the minimum gauges herein specified. Welded Ductwork £. All duct and fitting joints where welded duct construction or gas-tight construction is called for shall be continuous welded with Everdur rod. All Duct Systems unless of welded construction g. shall have all joints continuous soldered or seal-ed with plastic conted duct tape as manufactured by Permacel, Arno Adhesive Tape Inc., or Duro Dyne Corp. Ducts and plenums lined with insulation shall be increased in size to allow for the insulation thickness so that dimensions shown on the Jrawings h. will be not inside dimensions. Duct elbows, including supply, exhaust, and return, i. shall be made with a centerline radius of 1.5 times the duct width parallel to the radius. -22--

## ENCLOSURE 1 ATTACHMENT 6

# NEXTERA ENERGY POINT BEACH, LLC POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

## LICENSE AMENDMENT REQUEST 241 EXTENDED POWER UPRATE RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION

# CHARCOAL FILTER BANK CALCULATION

# **Charcoal filter bank calculation**

#### Conditions:

- 1. Dimensions of filter bank are 107" x 180" x 120" high.
- 2. The unit has ten anchors (or more) on each of two adjacent sides (other sides not visible).
- 3. Assume a weight density of 35 pcf (GIP value for electrical cabinets) which is certainly heavier than the filter banks which are really air plena with filters in them.
- 4. Assume it responds at the peak of the PAB floor spectrum which for the SSE is 0.6g horizontal. Vertical acceleration peak is 0.11g which is based on 2/3 x ground spectral peak.

Check overturning moment (OTM) vs. restoring moment (RM):

W = [107 x 180 x 120]/1728 x 35 pcf = 47 kips

OTM = {0.6g x 60" + 0.11g x 107"/2} x W = 42W in-k

RM = 107"/2 x W = 53.5W in-k; therefore, the filter bank cannot uplift and there is no tension in the anchors.

Check anchors in shear

 $V = \{0.6g \times 47\}/20 \text{ anchors} = 1.41 \text{ kips}$ 

 $V_{\text{allowable}} = 2.38 \text{ kip x RF}_{S}$  where RF<sub>S</sub> is the shear force reduction factor for anchorage in 3000 psi concrete and 2.38 kip is the ½" diameter concrete expansion anchor allowed load (GIP Appendix C.2.1)

 $RF_{s} = (3000/10000) + 0.65 = 0.95$  (GIP Appendix C.2.7)

 $V_{\text{allowable}} = 2.38 \text{ kip x } 0.95 = 2.26 \text{ kip} > 1.41 \text{ kip, so OK}$ 

# ENCLOSURE 1 ATTACHMENT 7

# NEXTERA ENERGY POINT BEACH, LLC POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

LICENSE AMENDMENT REQUEST 241 EXTENDED POWER UPRATE RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION

SEISMIC EVALUATION OUTLIERS

.

Roof Intake Enclosure for CREFS HVAC

The CREFS air intake consists of ductwork, which penetrates the roof of the HVAC room in the Turbine Building. The ductwork then penetrates the west wall of the Turbine Building and terminates in a louvered metal enclosure. The SRT examined the ductwork above the HVAC Room (Photo 4) and found it to be rugged and judged seismically adequate. The intake enclosure is a relatively light gage enclosure that was also judged as seismically adequate.

• Charcoal Filter in W30 Fan Room

The SRT examined the charcoal filter for Fans W-30 A & B. In the same room (about 20 ft away) there are charcoal filter banks with a footprint of 107" x 180". The visible 107" side has 10 - ½" concrete expansion anchors with two anchors having nuts that are raised. The 180" side cannot be fully viewed as it is adjacent to a wall but at least 10 anchors were counted, some of which again were missing nuts or for which the nuts were raised. The two other sides are inaccessible. The filter banks are about 10' high and are adjudged to have a natural frequency in excess of about 20 Hz. Since filter banks cannot uplift the anchors only need to resist base shear. There are a sufficient number of anchors visible to accomplish this therefore the filter banks are declared seismically adequate.

The SEWS for Fans W-30 A & B include the charcoal filter assessment.

### 9.0 Outliers

The summary table below identifies the duct, supports, and equipment that have not met the screening guidelines and/or the analytical review criteria of Reference 2. The resolution for each outlier is provided in the following table.

No.	Area	Duct	Туре	Description
1	PAB - Area 4	1	Hanger	Add a new trapeze support to the 104x26 duct (LAR 1)
2	PAB - Area 5	14	Hanger	Add a new trapeze support above the Containment Spray Pumps (LAR 6)
3	PAB - Area 5	26	Hanger	Replace existing "Z" shaped horizontal support with new shop fabricated support (LAR 7)
4	Pipeway 3 - Area 5	30A	Lateral Support	Add a lateral support to the end of the duct in Pipeway 3
5	Pipeway 3 - Area 5	25	Lateral Support	Add a lateral support to the end of the duct in Pipeway 4
6	Unit 1 RHR Hx Room - Area 8	37	Vertical Support	Add a knee brace support at duct corner near column line N/10
7	Unit 1 RHR Hx Room - Area 8	37	Duct Stiffeners	Add two horizontal stiffeners to the top of the EW duct near column line N/10

No.	Area	Duct No.	Туре	Description
8	Unit 2 RHR Hx Room	36	Vertical Support	Fasten existing support to duct near column line N/13
9	CREFS	N/A	Fans (4 total)	A three way support will be installed for W14A&B and W13B1&B2 that will render the vibration isolators as ineffective. The identified corrosion will be cleaned and the load path and anchorage will be re- inspected to determine their effectiveness and repaired as required (W13B1 and W13B2) (see SEWS). By making the vibration isolators ineffective and by correcting any corrosion issues, the equipment fundamental frequencies will not fall in the range where seismic demand exceeds the seismic capacity.
10	CREFS	43	Lateral Support	Add new lateral support on the Intake Duct near the bellows (at entry to charcoal filter)
11	PAB - Area 4	1	Hanger	Shell anchor failed vertical capacity check. Refined analysis found to be acceptable. No additional resolution required.
12	PAB - Area 4	4	Hanger	Shell anchor failed vertical capacity check. Refined analysis found to be acceptable. No additional resolution required.

Note: A broken duct (Duct No. 39) support at the floor penetration near column line P/13 was reported to PBNP and will be repaired (see CAP 01157521)

HVAC System Outlier Sheets (HSOS) for each outlier are included as attachments to this report.

## 10.0 Conclusion

The CREFS and VNPAB exhaust systems were seismically verified using the guidelines and criteria in Reference 2. The ducts, dampers, fans, and supports for the subject systems are found to be acceptable for the application of Reference 2. Systems temperatures and PBNP seismic motions are also found to be acceptable.

The SRT consisted of experienced, licensed engineers with the appropriate required SQUG GIP qualifications.

Dr. Robert P. Kennedy performed the required Peer Review of the seismic verification. Dr. Kennedy's report (Reference 11) is provided in Attachment 12.6 and concludes that as long as outlier issues are resolved the reviewed ductwork and associated components will be seismically adequate for the PBNP seismic design ground motion level.

In plant screening walkdowns regarding HVAC system and duct support structural integrity were performed by the SRT in accordance with the Reference 2 guidelines. SEWS were developed for the components and ductwork included in walkdown.

## **ENCLOSURE 2**

## NEXTERA ENERGY POINT BEACH, LLC POINT BEACH NUCLEAR PLANT, UNITS 1 AND 2

TRANSMITTAL OF INFORMATION TO SUPPORT LICENSE AMENDMENT REQUEST 241 PBNP VNPAB AND CREFS SEISMIC EVALUATION

S&A REPORT NO. 09Q0839-R-001 PBNP VNPAB AND CREFS SEISMIC VERIFCATION REVISION 1, DATED JULY 15, 2010

Document: Report No. 09Q0839-R-001 Title: PBNP VNPAB and CREFS Seismic Verification							
Document Type: Criteria 🗌 Interface 🗌 Report 🔀	Specification	Other 🗌	Drawing				
Project Name: PBNP VNPAB and CRI	EFS Seismic Verifica	ition					
Job No.: 09Q0839							
Client: Nextera Energy / PBNP							

This document has been prepared in accordance with the S&A <u>Quality Assurance Program</u> <u>Manual</u>, Revision <u>16</u> and project requirements:

Initial Issue (Rev. 0)	
Describer Dhillis Conde C. U. Mych	Date: 11/12/09
Prepared by: Philip Gazda	
L'AMT	Date: 11/12/09
Reviewed by: Walter Djordjevic	
What	Date: 11/12/09
Approved by: Walter Djordjevic Viz /	

Revision F	Revision Record:								
Revision No.	Prepared by/ Date	Reviewed by/ Date	Approved by/ Date	Des	cription of Revision				
1	P.A. Gazda/ 7/15/10 <i>G.a. hryot</i>	W. Djordjevic/ 7/15/10	W. Djordjevic 7/15/10	Rev duct desc SEV com SUF IN I	ised cover sheet, table of t thicknesses, and outlier cription table. Revised VS for project opliance. PERSEDES REVISION 0 TS ENTIRETY.				
Stevenson & Associates		DOC APPRO Fig	CUMENT VAL SHEET Jure 2.8		CONTRACT NO. 09Q0839				

# TABLE of CONTENTS

		Page
1.0	Purpose	2
2.0	Background	2
3.0	Methodology and Scope	2
4.0	Applicability and Qualifications	4
4.0	Materials and Components	4
4.2	Temperature	4
4.3	Seismic Motion	4
4.0 A A	SRT Qualifications	5
4.5	Peer Review	5
50	In-Plant Screening Walkdown	6
6.0	Walkdown and Screening Results	8
6.1	Structural Integrity Review	8
611	Duct Stresses	8
612	Tie Downs	9
613	loints	9
614	Annurtenances	10
615	Elevibly Mounted Heavy Equipment	10
616	Branch Elevibility	10
617	Cantilevered Ducts	11
618	Duct Corrosion	11
62	Support System Review	11
621	Duct Support Assessment	11
622	Beam clamps	12
623	Channel Nuts	12
624	Cast Iron Anchor Embedment	12
625	Broken Hardware	12
62.6	Support Corrosion	13
6.2.7	Concrete Quality	13
6.2.8	Welded Attachments	13
6.2.9	Rod Hanger Fatigue	13
6.3	Dampers	13
6.4	Seismic Interaction	13
6.5	Pressure Boundary Integrity Review	14
7.0	Selection of Bounding Configurations (LARs)	14
7.1	Bounding Configurations	14
7.2	Inaccessible Ducts	15
8.0	Miscellaneous	16
9.0	Outliers	17
10.0	Conclusion	18
11.0	References	19
12.0	Attachments	19

## 1.0 Purpose

The purpose of this report to document the results of the seismic verification of the Point Beach Nuclear Plant (PBNP) Primary Auxiliary Building exhaust (VNPAB) and Control Room Emergency Filtration System (CREFS) ductwork, associated supports and components.

### 2.0 Background

NextEra Energy Point Beach, LLC submitted License Amendment Request (LAR) 241 to the NRC pursuant to 10 CFR50.90. The license amendment would revise the current licensing basis to implement the alternative source term (AST) through reanalysis of the radiological consequences of the Point Beach Nuclear Plant (PBNP) Final Safety Analysis Report, Chapter 14 Accidents.

During the review of LAR 241, the NRC staff expressed concern regarding the seismic adequacy of the Control Room Emergency Filtration System (CREFS) and Primary Auxiliary Building Ventilation System (VNPAB) credited in the PBNP AST analysis. In response, PBNP committed (Reference 1) to evaluate the seismic adequacy of CREFS and VNPAB ventilation systems credited in the AST analyses. The evaluation approach would be consistent with the approach used for the Edwin I. Hatch Nuclear Plant (Reference 9) to provide reasonable assurance that the credited post-accident ventilation systems would operate and retain pressure integrity during and following a seismic event.

The PBNP seismic verification evaluation was conducted in accordance with the guidelines provided in the Generic Implementation Procedure (GIP) for Seismic Verification of Nuclear Plant Equipment (SQUG GIP) (Reference 8) for fans, motors and heat exchangers, and the December 2006 Electric Power Research Institute (EPRI) Final Report 1014608, "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems, Revision to 1007896" for ducts, dampers and hangers (Reference 2). This seismic verification process was previously used at the Hatch Nuclear Plant (Reference 9) to provide reasonable assurance that a post LOCA ventilation system would retain pressure integrity during a seismic event. The NRC accepted and approved the Hatch seismic evaluation (see Reference 1 for discussion).

### 3.0 Methodology and Scope

The methodology in EPRI report "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems, Revision to 1007896" was used to evaluate the seismic adequacy of the PBNP Control Room Emergency Filtration System (CREFS) and Primary Auxiliary Building Ventilation System (VNPAB). The screening guidelines are primarily based on seismic experience data that show that most types of HVAC duct and damper systems exhibit extremely good performance under strong-motion seismic loading, with the pressure boundary being retained in all but a handful of cases.

The seismic verification evaluation for PBNP included the following key steps.

 Identified the HVAC systems that required evaluation by conducting interviews with station engineers and reviewing station drawings and design specifications. The HVAC systems reviewed consisted of the Control Room Emergency Filtration System (CREFS) and Primary Auxiliary Building Ventilation System (VNPAB) credited in the PBNP AST analysis. The components for these systems include:

- Control Room HVAC ductwork, dampers, filters, and fans required for the proposed accident mode of operation (makeup and recirculation with filtration).
- Control Room Bathroom HVAC.
- Control Room HVAC roof intake structure.
- Control Room HVAC control panel C-67 (located in the control room).
- PAB exhaust ductwork, dampers, filters and fans located on or below Elevations 8' and 26' that provide exhaust for various ECCS equipment, components and sumps. This also includes ductwork in Pipeways 1, 3, and 4. (Note that there is no ductwork in Pipeway 2 associated with the subject scope of work).
- PAB exhaust stack.
- Confirmation that the power supplies for fans W-13 B1 & B2 (Control Room Recirculation Fans), W-14 A & B (F-16 Control Room Charcoal Filter Fans), W21 A & B (PAB Exhaust Fans) and W30 A & B (F-23/F-29 PAB Exhaust Fans) were found to be seismically adequate in the original USI A-46 program for PBNP.
- Conducted an in-plant screening review of the subject systems for structural integrity, support review, seismic interaction, and pressure boundary integrity.
- 3. Selected bounding/sample configurations for limited analytical review (LAR) evaluations in accordance with Section 4 of Reference 2.
- 4. Developed this report and supporting calculations.
- 5. Submitted this report and sample calculations to an independent reviewer, Dr. Robert P. Kennedy for a Peer Review. Dr. Kennedy conducted the peer review for the previously cited Hatch duct evaluation.

It should be noted that the HVAC ductwork and plena-for most of the CREFS are covered with a lightweight insulating material that obstructs viewing of some of the duct supports and duct stiffeners. The material is in place not only for insulation but also to improve the leak tightness of the system. However, the recirculation duct for the CREFS is un-insulated which allowed the Seismic Review Team (SRT) to examine the construction, stiffener spacing, hanger spacing and type, and material condition of the ductwork. This examination of the recirculation duct indicated the same type and quality of construction as that found for the VNPAB system; therefore the SRT considered it reasonable to adjudge that the number and location of CREFS stiffeners and duct supports within the insulated CREFS systems conform to the SMACNA code (Reference 4) and PBNP Ventilation System Design Specification (Reference 3) requirements and that the duct construction is adequate. The dead load, seismic and pressure stresses in the CREFS ducts, duct stiffeners, and duct supports were evaluated based on this approach.

### 4.0 Applicability and Qualifications

This section addresses the applicability of the materials and components used in the PBNP VNPAB and CREFS construction. Temperature and seismic limits are also discussed along with the SRT and Independent Peer Reviewer qualifications.

### 4.1 Materials and Components

The PBNP CREFS and VNPAB HVAC systems consist of typical ducts, dampers, supports, registers, filters, louvers, and air diffusers that are discussed and addressed in Reference 2. These components were installed in accordance with the original Specification No. 6118-M-41 "Specification for Sheetmetal Ductwork Heating, Ventilating, and Air Conditioning Systems for the Point Beach Nuclear Plant" (Reference 3) which specified that the HVAC system be designed and installed in accordance with the requirements of the Sheet Metal and Air Conditioning Contractor's National Association, Inc (SMACNA) (Reference 4). As specified in Reference 3 the subject systems are constructed from galvanized sheet steel.

### 4.2 Temperature

The CREFS and VNPAB HVAC systems are low temperature systems with design temperatures well below the 400° F limit discussed in Reference 2.

### 4.3 Seismic Motion

The NRC Staff reviewed PBNP's USI A-46 implementation program and determined that the design basis ground spectra and resulting in-structure response spectra are considered conservative spectra (Reference 10). The same response spectra will be used for the seismic verification of the subject HVAC systems.

The screening and seismic verification guidelines given in Reference 2 are applicable to any HVAC duct and damper system at any plant elevation where the plant free-field ground motion 5% damped seismic design spectrum does not exceed the Seismic Motion Bounding Spectrum of the Generic Implementation Procedure (GIP) for Seismic Verification of Nuclear Plant Equipment and the horizontal zero period acceleration (ZPA) of the in-structure spectra at the HVAC support anchorage does not exceed 2.0g. The following table presents the results of the GIP bounding spectrum vs. PBNP free field comparison and the comparison of the PBNP horizontal ZPAs vs. the 2.0g requirements.

Spectra	Reference 2	PBNP	Result
location/damping/type	Criteria	ZPA (OBE x 2)	
Free field/5%/SSE	GIP Bounding	Bounding	Bounding
	Spectrum should	Spectrum	Spectrum
	envelope free field	envelopes	envelopes PBNP
		PBNP free field	free field (Fig 1) -
		······································	OK
PAB EL 8'/7%/OBE	PBNP ZPA < 2.0g	0.17g	PBNP ZPA < 2.0g
	(SSE)		(SSE) -OK
PAB EL 26'/7%/OBE	PBNP ZPA < 2.0g	0.20g	PBNP ZPA < 2.0g
	(SSE)		(SSE) -OK
Pipeway 1	PBNP ZPA < 2.0g	0.32g	PBNP ZPA < 2.0g
EL. 23.5'/5%/OBE	(SSE)		(SSE) –OK
Pipeway 3 aisle way	PBNP ZPA < 2.0g	0.22g	PBNP ZPA < 2.0g
EL. 26'/5%/OBE	(SSE)		(SSE) -OK
Pipeway 3	PBNP ZPA < 2.0g	0.32g	PBNP ZPA < 2.0g
EL. 47'/5%/OBE	(SSE)		(SSE) -OK
Pipeway 4	PBNP ZPA < 2.0g	0.30g	PBNP ZPA < 2.0g
EL. 26'/5%/OBE	(SSE)		(SSE) -OK
Control Building	PBNP ZPA < 2.0g	0.36g	PBNP ZPA < 2.0g
Mechanical Equipment	(SSE)		(SSE) -OK
Room EL. 74'/5%/OBE			

As shown in the above table the PBNP free field spectrum is enveloped by the GIP bounding spectrum and the horizontal ZPAs at all applicable hanger/duct attachment points are less than 2.0g for SSE.

#### 4.4 Seismic Review Team (SRT) Qualifications

The SRT consisted of Mr. Walter Djordjevic and Mr. Philip Gazda of Stevenson & Associates (S&A). Messer Djordjevic and Gazda are both experienced engineers who meet the requirements for Seismic Capability Engineers (SCE) described in the SQUG GIP (Reference 8). They are degreed engineers who have completed the SQUG developed training course on seismic and have performed SQUG walkdowns at numerous nuclear plants. Messer Djordjevic and Gazda each have over 30 years of nuclear plant experience and are licensed professional engineers.

Messer Djordjevic and Gazda have studied and are familiar with the content and intent of Reference 2, the HVAC duct and support design requirements of SMACNA and the seismic experience data for HVAC duct and damper systems.

#### 4.5 Peer Review

Dr. Robert P. Kennedy was enlisted to perform the independent peer review of the seismic verification. Dr. Kennedy is an industry seismic expert and performed an independent peer review of the seismic evaluation guidelines presented in Reference 2.

Dr. Kennedy served as the chairman of the independent Senior Seismic Review and Advisory Panel, which provided considerable technical review and advice during the development of the SQUG GIP approach for evaluating the seismic adequacy of 20 classes of equipment plus Cable and Conduit Raceway Systems and their supports.

The independent review consisted of a site visit and a review of the supporting calculations, Screening and Evaluation Worksheets (SEWS) and Limited Analytical Reviews (LARs). The results of the Dr. Kennedy's independent review are provided in Attachment 12.6 and discussed in Section 10.

### 5.0 In-Plant Screening Walkdown

The initial in-plant screening walkdowns were conducted over 5 days from August 31, 2009 through September 4, 2009 by the SRT. Follow-up walkdowns were performed on September 24 and 30, 2009. Prior to the walkdowns the SRT conducted interviews with plant staff to clearly identify the HVAC systems requiring the seismic verification. Plant documents were collected and reviewed to familiarize the SRT with the subject HVAC systems.

HVAC System	Drwg. No.	Rev.	Title
CREFS	M-109	19	Heating & Ventilation Turbine Building, Area 3, Plans at Elev. 44'-0" & 60'-0"
CREFS	M-113	14	Heating & Ventilation Turbine Building, Area 3, Sections & Details
VNPAB	M-116	10	Heating & Ventilation Auxiliary Building, Area 4, Elev. 8'-0"
VNPAB	M-119	6	Heating & Ventilation Auxiliary Building, Area 5, Elev. 8'-0"
VNPAB	M-122	6	Heating & Ventilation Auxiliary Building, Area 6, Elev. 8'-0"
VNPAB	M-134	7	Heating & Ventilation Auxiliary Building, Area 8, Elev. 8'-0", (-)5'-3", (-)19'-3"
VNPAB	M-135	5	Heating & Ventilation Auxiliary Building, Sections, Area 8
VNPAB	M-136	7	Heating & Ventilation Turbine Building, Area 5, Sections
VNPAB	M-145	5	Heating & Ventilation Auxiliary Building, Area 4, Elev. 8'-0", Sections
VNPAB	C-342	3	Auxiliary Bldg. Vent Stack, Elevations, Sections, Details

The following table provides a list of the PBNP design drawings that show the VNPAB and CREFS HVAC systems.

The original Point Beach Ventilation System Design Specification No. 6118-M-41 (Reference 3) was also reviewed. Key information given in the specification is provided below.

- 1. The work, equipment and materials shall conform to the requirements and recommendations of the following codes and standards.
  - a. American Society of Heating, Refrigeration and Air Conditioning Engineers Guide.
  - Sheet Metal and Air Conditioning Contractor's National Association (SMACNA), Duct Manual and Sheetmetal Construction for Ventilating and Air Conditioning Systems.

- 2. All dampers shall be products of reputable manufacturers.
- 3. Rectangular ducts shall be constructed of galvanized steel in accordance with the latest standards of the American Society of Heating, Refrigeration and Air Conditioning Engineers and the SMACNA requirements for low, medium and high-pressure systems. Round ducts shall be either galvanized steel spiral pipe with four-ply lockseams, or galvanized metal sheets with continuous butt-welded seams reinforced with angular hoop braces. The CREFS and VNPAB HVAC systems are designed as low-pressure systems.
- 4. Hangers and supports shall be designed to support the weight of the duct or equipment and shall have a minimum factor of safety of five based on ultimate tensile strength of material used.
- 5. Support spacing for ducts shall not exceed approximately;
  - a. 96" for ducts whose greater dimension is under 18"
  - b. 66" plus or minus for ducts 18" 60" on the maximum side.

The SRT walkdown SEWS are provided in an attachment to this report.

As part of the walkdown the SRT enlisted the help of the PBNP Ventilation System Engineer who is experienced in HVAC duct construction in order to identify and confirm the type of duct joints used in the construction of the ductwork. The results of this effort are discussed in Section 6.1.3 of this report.

Additionally the SRT enlisted the services of the PBNP ISI group in order to confirm the sheet metal gage used for the ductwork. The SRT selected 5 locations in the PAB and one location on the CREFS for ultrasonic testing in order to confirm that the ductwork gage met SMACNA requirements. Specification 6118-M-41 requires that the gage of the duct is two gages heavier than that required by SMACNA. Ductwork for the VNPAB and the CREFS were tested using ultrasonic testing with the following results as shown in the table below:

Duct Dimension (WxH)	Location	Measured (in)	SMACNA Required	6118-M-41 Spec Required
104"x26"	PAB EL 8' Area 4	0.057 (17 gage)	0.0516 (18gage)	0.0635 (16 gage)
76"x20"	PAB EL 8' Area 4	0.053	0.0396 (20 gage)	0.0516 (18 gage)
56"x26"	PAB EL 8' Area 4	0.043	0.0396 (20 gage)	0.0516 (18 gage)
48"x26"	PAB EL 8' Area 4	0.043	0.0336 (22 gage)	0.0396 (20 gage)
10"x8"	PAB EL 8' Area 4	0.033	0.0217 (26 gage)	0.0276 (24 gage)
50"x40"	CREFS Recirc Duct	0.040	0.0336 (22 gage)	0.0396 (20 gage)

The data show that the actual ductwork gages always exceed the SMACNA minimum required gages but not always by 2 gages. Sometimes the actual gage appears to be only one gage heavier. This could also be attributable to measurement precision. For this evaluation the SMACNA minimum gages will be used for the pressure evaluations

which is conservative. Specification 6118-M-41 gages will conservatively be used for the dead load and seismic evaluations.

#### 6.0 Walkdown and Screening Results

As described in Section 2.0 the methodology in EPRI report "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems, Revision to 1007896" was used to evaluate the seismic adequacy of the CREFS and Primary Auxiliary Building Ventilation System (VNPAB).

The function of the VNPAB exhaust ductwork is to remove and process air from the PAB. The function of the CREFS ductwork is to provide filtered air to the Control Room. Ductwork must remain intact during and after a seismic event. Duct distortions should not be large enough to restrict airflow. The walkdowns were performed considering these functional criteria.

As previously discussed the HVAC ductwork and plena for most of the CREFS are covered with a lightweight insulating material that obstructs viewing of some of the duct supports and duct stiffeners. The material is in place not only for insulation but also to improve the leak tightness of the system. However, the recirculation duct for the CREFS is un-insulated which allowed the Seismic Review Team (SRT) to examine the construction, stiffener spacing, hanger spacing and type, and material condition of the ductwork. This examination of the recirculation duct indicated the same type and quality of construction as that found for the VNPAB system; therefore the SRT considered it reasonable to adjudge that the number and location of CREFS stiffeners and duct supports within the insulated CREFS systems conform to the SMACNA code (Reference 4) and Reference 3 requirements and that the duct construction is adequate. The dead load, seismic and pressure stresses in the CREFS ducts, duct stiffeners, and duct supports were evaluated based on this approach.

This section addresses the structural integrity review, structural support system review, dampers, seismic interaction review, and pressure boundary integrity review. Figures 2 through 8 show the VNPAB exhaust and CREFS ductwork along with duct numbers used in the evaluation.

#### 6.1 Structural Integrity Review

This section describes the analytical and walkdown results for the HVAC duct and duct support attributes that were examined by the SRT during the screening walkdowns. Section 6.1.1 addresses the stresses in the ducts. Sections 6.2.1 and 6.5 address the duct support stresses and the pressure stresses in the ducts.

#### 6.1.1 Duct Stresses

Analytical evaluations were performed on HVAC duct and support configurations in accordance with the methodology given in Section 4 of Reference 2. These evaluations are documented in Reference 5.

The duct evaluation criteria are based primarily on the design approach used in SMACNA's construction standards for round and rectangular duct. The pressure boundary integrity review of the HVAC duct considers the combined effects of pressure, dead weight and seismic loads on the duct. The combined dead load and seismic stress

is checked against a factored allowable working stress for acceptance. Seismic stresses were determined using an equivalent static load approach. The allowable bending stress is 8 ksi for carbon steel per Reference 2.

Duct spans influence the seismic and dead load stresses in the duct. Reference 2, Appendix C provides the allowable span length criteria using the analytical guidelines presented Reference 2, Section 4. This criteria was used to check the HVAC duct spans.

Duct sections were evaluated in Reference 5 for dead load and seismic stresses using the methodology of Reference 2 when the duct has 3 or more spans. Ducts with less than 3 spans or cantilevered sections were evaluated similarly using equations that reflect the actual span conditions. The initial assessment was performed using the peak acceleration 'g' value for the applicable area of the plant. Only five duct sections exceeded the allowable stresses for the initial evaluation. Of the five, three sections are cantilevers and are discussed in Section 6.1.7. The other two sections were found acceptable when evaluated considering actual duct frequency and corresponding acceleration values or using actual duct density.

#### 6.1.2 Tie Downs

VNPAB ductwork is often not positively secured to the horizontal angle cross-member of the trapeze hangers. As discussed in Sections 3 and 6, it is assumed that the CREFS ductwork has similar anchorage construction. The SRT judged that this is unimportant since most hangers consist of trapeze supports that "capture" the ductwork between the vertical support rods thereby ensuring that the ducts cannot fall off the hanger during a seismic event. The last hangers on cantilevered or terminated ducts in the PAB were examined and found to be positively secured to the end hanger.

#### 6.1.3 Joints

As part of the walkdown the SRT enlisted the help of a PBNP Ventilation System Engineer who is experienced in HVAC duct construction in order to identify and confirm the type of duct joints used in the construction of the ductwork. The following joints were identified in the field:

- 1. Drive Slip (No. T-1, Fig. 3-1, Reference 2)
- 2. Standing S (No. T-10, Fig. 3-1, Reference 2)
- 3. Standing S (ALT) (No. T-11, Fig. 3-1, Reference 2)

The VNPAB ductwork has Drive Slip joints that are in place on all 4 sides of smaller rectangular ducts and on the vertical sides of larger rectangular ducts. Standing S and Standing S (ALT) joints are provided on the top and bottom sides of larger rectangular ducts.

The normal allowable bending stress for rectangular ducts may be increased by a factor of 1.7 for DBE loads as discussed in Section 4.1 of Reference 2. However as discussed in Section 4.2.1 of Reference 2 the use of Standing S and Standing S (ALT) duct joints requires the use of a 1.0 factor for the normal allowable bending stress.

As discussed in Sections 3 and 6 it is assumed that the CREFS ductwork is constructed similarly to the VNPAB ductwork.

### 6.1.4 Appurtenances

The SRT observed one large appurtenance attached to the VNPAB ductwork at the entrance of Pipeway 3 (Photo 1). The appurtenance consisted of a 6" diameter capped pipe approximately 3' long which is attached to the side of the duct. This pipe is assumed to be used as a temporary ventilation connection to the duct. It was also determined that the pipe is attached to a nearby post and therefore would not significantly load the duct. The SRT judged this to be acceptable. VNPAB duct access doors and registers appeared to be adequately fastened and attached.

The SRT also observed a large damper located in the mid-span portion of the CREFS ductwork that runs from the charcoal filter plenum to the plenum containing fans W-13B1 and W-13B2. The duct and damper at this location are structurally anchored to the concrete ceiling and was judged to be seismically acceptable (Photo 2). CREFS duct access doors and registers appeared to be adequately fastened and attached.

### 6.1.5 Flexibly Mounted Heavy Equipment

The CREFS fans W-14A and W-14B and W-13B1 and W-13B2 are mounted on vibration isolators (see SEWS) and have been determined to be outliers. The anchorage for these fans will be modified in order to provide an adequate connection for lateral seismic loads.

The anchorages for the four large fans in the PAB were previously modified to remove the vibration isolators. As shown on the SEWS for Fans W-30A and W-30B the new anchorage was designed for the lateral seismic loads. Fans W-21A and W-21B were also modified however it was not clear if after reviewing plant documentation that the anchorage was seismically designed. The SEWS for Fans W-21A and W-21B includes a calculation confirming the seismic adequacy of the anchorage.

The SRT observed the expansion joints connecting the ductwork to fans W-21A, W-21B, W30A and W30B. The expansion joints appeared to be rugged and in excellent condition. Sufficient 'slack' is available to accommodate the small seismic duct movements; therefore the expansion joints are acceptable.

## 6.1.6 Branch Flexibility

VNPAB main ductwork has a number of locations where small branch ducts or pipes are attached to provide exhausts for small rooms and/or sumps. The seismic lateral displacements of the main ducts were computed at these locations and they were determined to be less than 3/8". Therefore, branch flexibility is determined to be acceptable.

No branch lines or hard spots for the CREFS ductwork were observed by the SRT.

### 6.1.7 Cantilevered Ducts

The VNPAB ductwork has a number of small cantilever ducts that terminate in open areas or pipeways or small rooms. Larger ducts are cantilevered in the fan rooms above the W-21 A & B and W-30 A & B fans. The CREFS has one cantilevered duct. These ducts were evaluated in Reference 5. The results are listed below:

- The ducts in Pipeways 3 and 4 require the addition of a lateral support at the end of these cantilevers.
- The ducts above the W-21 A & B and W-30 A & B fans are found to be seismically adequate.
- Two small ducts had ductwork that extended up to 4' beyond the last hanger. This condition was found to seismically adequate.
- The intake duct for CREFS requires a lateral support at the flexible entry point to the filter plenum.

### 6.1.8 Duct Corrosion

The SRT did not observe any instances of duct corrosion in the PAB and found the material condition of the ductwork and duct hangers to be very good in general.

The only corrosion observation was in the CREFS on the anchorage of fans W13B1 and W13B2. This anchorage will be replaced as part of the seismic upgrade of the fan anchorages.

### 6.2 Support System Review

This section describes the results of the duct support analysis and the results of the walkdown for the support attributes discussed below.

### 6.2.1 Duct Support Assessment

Duct supports are found to consist primarily of trapeze supports made up of angles supported by threaded rods anchored to the concrete with concrete expansion anchors. In some case the rods are welded directly to steel embedded plates or other steel members. In some cases wall brackets made up of angle sections are also used.

The supports were evaluated using the methodology included in Appendix F of Reference 2. Checks were performed for the following:

- Dead load check
- Vertical capacity check
- Ductility check
- Rod hanger fatigue

The results of the review are provided in Reference 5. Supports that require modification are discussed in Section 9, Outliers.

The dead load check for the supports performed in Reference 5 included evaluations of the threaded rods, shell anchors, and angle members. Based on the SRT walkdown, the minimum diameter for the threaded rods and shell anchors is 3/8 inch and the

minimum angle size is L2x2x1/8. The evaluations were performed considering an average tributary span for the vertical supports using the minimum size of the component. The evaluations were in accordance with the AISC Manual of Steel Construction 9<sup>th</sup> Edition (Reference 7) and the Generic Implementation Procedure (GIP) for Seismic Verification of Nuclear Plant Equipment (Reference 8). All supports satisfied normal allowable stresses for the rods and shells. All supports satisfied the conservative evaluation for the angle members with the exception of six duct spans. Detailed evaluations were performed for these six sections considering a realistic weight distribution on the angle member and they were also found acceptable.

The vertical capacity check (5 times dead load) for the supports performed in Reference 5 included evaluations of the rods and shell anchors in accordance with Reference 2. The vertical capacity check focuses on the weak link in the support. Per Reference 5, the shell anchor capacity (per Reference 8) controlled over the threaded rod capacity (per Reference 7). All supports for all duct sections met the vertical capacity check.

The walkdown performed by the SRT indicated that the support configurations were primarily rod hanger trapeze supports. In accordance with Reference 2, supports constructed of threaded steel rods with fixed-end connections details behave in a ductile manner under horizontal motion. No additional ductility check is required and no hard spots were identified.

The rod fatigue evaluation is discussed in Section 6.2.9.

#### 6.2.2 Beam clamps

The use of beams clamps was observed in an extremely small number of cases. In each case the clamp was oriented properly to preclude the clamp from slipping off the member it is connected to in a seismic event and therefore found to be acceptable.

#### 6.2.3 Channel Nuts

The large majority of duct supports for the VNPAB and CREFS consist of threaded rod trapeze supports. Except for one hanger in the PAB Containment Spray Pump area the SRT did not observe the use of strut materials that would require the use of channel nuts. The noted hanger is assessed in LAR 6 and it is recommended to replace this hanger with a standard trapeze support.

#### 6.2.4 Cast Iron Anchor Embedment

The use of cast iron embedments was not observed by the SRT.

#### 6.2.5 Broken Hardware

One case of broken hardware was observed by the SRT (PAB, Unit 2, at the floor penetration adjacent to RHR cubicle). This item was reported to the station and will be repaired by PBNP under CAP 01157521.

### 6.2.6 Support Corrosion

No duct support corrosion was observed by the SRT.

#### 6.2 7 Concrete Quality

The VNPAB and CREFS HVAC systems are supported primarily from the reinforced concrete floors (above and below) and walls in proximity to the ducts, plenums, fans and duct supports. The material condition of the concrete was found to be excellent by the SRT.

#### 6.2.8 Welded Attachments

Welded duct attachments were not observed by the SRT

#### 6.2.9 Rod Hanger Fatigue

Rod fatigue evaluations were performed in accordance with Reference 2, Appendix E. An evaluation was completed for the supports in the Auxiliary Building, in Pipeways 3, and 4 (Pipeway 1 has no rod hangers), and in the Control Room. The applicable 5% damped spectra was conservatively considered as enveloped by the 0.75g Bounding Rod Fatigue Spectra (Figure E-1 of Reference 2) for all areas except the Auxiliary Building Central where the applicable spectra was enveloped by the 0.5g Bounding Rod Fatigue Spectra. The screening chart for 3/8 inch diameter rods (Figure E-3) of Reference 2 indicated that all the rod supports were below the bounding values for weight and length.

Based on the above the rod fatigue check was performed and found to be acceptable.

### 6.3 Dampers

The dampers installed at PBNP consist primarily of curtain type fire dampers manufactured by Pacific Air Products (Reference 6) that are mounted in the ducts as they pass through concrete firewalls. The dampers were found to be to be rugged and are typical of those in the Earthquake Experience Equipment Class. The operators and actuators of other miscellaneous dampers are not constructed of cast iron and there is sufficient slack and flexibility for attached lines. The dampers appeared to be well anchored into the supporting concrete walls and damper operation will not be hindered by duct distortion. Photo 3 shows a typical duct/damper installation.

#### 6.4 Seismic Interaction

The VNPAB ductwork is located in the PAB that contains Safety Related systems, structures and components (SSC). As such, these SSCs are seismically designed. The SRT did not identify any falling hazards or credible differential displacement hazards. Any small lines attached to the ductwork contained enough flexibility to absorb the small seismic displacements of the ductwork.

The CREFS ductwork is located in the Control Building Mechanical Equipment Room that is constructed of rugged reinforced concrete walls and slabs. The SRT did not identify any falling hazards or credible differential displacement hazards. Any small lines

attached to the ductwork contained enough flexibility to absorb the very small seismic displacements of the ductwork.

A conservative maximum lateral displacement was computed in Reference 5 by using long span duct sections with small cross sections. The displacement was determined to be less than 3/8 inch. This displacement is judged to be sufficiently small so as not to create any significant duct impact issues.

### 6.5 Pressure Boundary Integrity Review

As stated in Reference 2 earthquake experience and test data have demonstrated that duct systems that meet the SMACNA requirements performed well during earthquakes. The Design Specification (Reference 3) for the VNPAB and CREFS HAVC systems required that the ductwork be designed in accordance with SMACNA requirements. The SRT's walkdown included reviewing the sheetmetal gage, stiffener size and spacing, and duct dimensions to confirm the adherence to the SMACNA requirements.

Project calculations (Reference 5) were performed and confirmed that the duct stresses and duct stiffener stresses due to pressure loads are within the Reference 2 guidelines with the exception of Duct No 37. Per the walkdown notes, the top stiffeners for this duct are missing and must be installed at 2 locations along the duct span.

### 7.0 Selection of Bounding Configurations

This section addresses the selection of the bounding configurations for supports and ducts for limited analytical review and the treatment of inaccessible ducts.

## 7.1 Bounding Configurations (LARs)

The SRT selected seven support configurations and one bounding duct configuration that were judged to be unusual or heavily loaded for Limited Analytical Review (LAR). The LARs and the LAR tracking form are included as attachments to this report.

In addition all trapeze supports which are not evaluated in LARs were evaluated and found to be acceptable for the assessment criteria's dead load check and the 5 times dead load check (Vertical Capacity Check).

LAR 1 addresses a support for the 104x26 duct (Duct No. 1) that also supports one of the rods for an additional duct (52x22). The evaluation for dead load indicates that even when performing a detailed evaluation, the support angle is overstressed. The proposed solution is to add a new hanger at or near the existing hanger. The shell anchors did not meet the acceptance criteria for the vertical capacity check (5 times dead load) however a detailed lateral load evaluation was performed and the shell anchors were found to be acceptable. Since the shell anchors did not meet the initial acceptance criteria, the support is classified as an outlier (see Section 9.0 for additional discussion).

LAR 2 addresses a support for the 76x20 duct (Duct No. 4) that also supports a 72x14 duct, a 10x6 duct, and a 6" diameter steam pipe. All components of the support were acceptable for the dead load check. The ½ inch diameter shell anchors did not meet the acceptance criteria for the vertical capacity check (5 times dead load) however a detailed lateral load evaluation was performed and the shell anchors were found to be

acceptable. Since the shell anchors did not meet the initial acceptance criteria, the support is classified as an outlier (see Section 9.0 for additional discussion).

LAR 3 addresses a support for the 40x20 duct (Duct No. 16) that is attached to a cable tray support. Based on the relatively small weight applied to the support from the duct and the robust nature of the cable tray support, the support is acceptable by engineering judgment.

LAR 4 and LAR 5 address supports on the 54 inch diameter ductwork that leads to the Auxiliary Building Vent Stack. The supports are found to be acceptable.

LAR 6 addresses a support for the 34x14 duct (Duct No. 14). This support consists of a P1000 unistrut member that is connected by friction clamps to vertical conduits. The configuration is unacceptable by engineering judgment due to the orientation of the vertical orientation of the clamps and is considered an outlier. The unistrut member has a long span and also supports other miscellaneous components. The resolution for this LAR is to add a new trapeze support in very close proximity to the existing support.

LAR 7 supports a 26x16 duct (Duct No. 26) with a knee brace configuration that attaches to another duct support. Both ducts are supported by 2 rods that are attached to shell anchors in the ceiling. The knee brace configuration is unacceptable for dead load and is considered an outlier. All other components are acceptable for dead load and the vertical capacity check (5 times dead load). The resolution is to replace the existing knee brace with a more robust steel support.

LAR 8 evaluated the longitudinal seismic stresses of the heaviest duct section with a significantly long span. It was found to be acceptable.

Reference 2 states that when the selected configurations do not pass the analytical review, the selected population should be expanded. Several supports did not pass the analytical review requirements however all duct sections and supports were analyzed for the stresses due to dead load, seismic and pressure stresses. Therefore the requirement for expanding the selected population was satisfied. Reference 5 provides the results of the assessment.

#### 7.2 Inaccessible Ducts

A small amount of ductwork was found to be inaccessible due to being in locked radiation areas or visually blocked by overhead items and construction scaffolds. These ducts have small cross sections and are very lightweight. Given this condition and based on the construction of the majority of the ducts and hangers that were examined during the walkdown, these inaccessible ducts were judged to be acceptable by the SRT.

Duct Location	Duct Size	Remarks
PAB EL. 8', Unit 1, 1Hx	8" Dia	Small diameter lightweight duct that terminates
3 A-B Room (M-119)		in the room. OK by SRT judgment.
PAB EL. 8', Unit 2, 2Hx	10"x 8"	Small lightweight duct that terminates in the
3 A-B Room (M-119)		room. OK by SRT judgment.
PAB EL. 8' and 26',	14" x 6"	Small lightweight duct that runs from PAB EL.
aisle way at EL. 8' and		8' to Pipeway 3. Visible portions appear to be
ducting to and in		well constructed and well supported. Duct
Pipeway 3	1	terminates in Pipeway 3. See Section 9.1.3 for
(M-119)		discussion on appurtenance. Ok by SRT
		judament.

These ducts are described in the following table.

#### 8.0 Miscellaneous

Miscellaneous items in addition to the VNPAB and CREFS ductwork and fans were examined by the SRT and are discussed below.

MCCs for fans W-13 B1 & B2, W-14 A & B, W21 A & B and W30 A & B

MCCS for the above listed fans were seismically evaluated during the PBNP initial SQUG program. The MCCs were found to be seismically adequate. The SEWS for MCCs 2B-42, 1B-42, 1B-32 and 2B-32 documenting the seismic verification of these components are included as an attachment to this report.

The original SEWS for MCC 2B-42 required that the bolting for the MCC top supports be tightened. The SRT reviewed the top anchorage and confirmed that all visible top anchorage is now in place and tight.

• PAB Exhaust Stack

The PAB exhaust stack is a tall steel plate stack that is located in the façade. The stack is laterally braced at two points. The exhaust stack was evaluated in Reference 5 and found to be seismically adequate.

Control Panel C-67

Control Panel C-67 provides the controls for the CREFS fans and dampers. This panel was examined by the SRT and found to be seismically adequate. The SEWS for this panel is included as an attachment to this report.

• Plena for Fans W-14 A & B and W-13 B1 & B2

The plena for the listed fans were examined by the SRT and found to be seismically adequate. The evaluation of the plena is given in the SEWS for the subject fans.

• Roof Intake Enclosure for CREFS HVAC

The CREFS air intake consists of ductwork, which penetrates the roof of the HVAC room in the Turbine Building. The ductwork then penetrates the west wall of the Turbine Building and terminates in a louvered metal enclosure. The SRT examined the ductwork above the HVAC Room (Photo 4) and found it to be rugged and judged seismically adequate. The intake enclosure is a relatively light gage enclosure that was also judged as seismically adequate.

Charcoal Filter in W30 Fan Room

The SRT examined the charcoal filter for Fans W-30 A & B. In the same room (about 20 ft away) there are charcoal filter banks with a footprint of 107" x 180". The visible 107" side has 10 - ½" concrete expansion anchors with two anchors having nuts that are raised. The 180" side cannot be fully viewed as it is adjacent to a wall but at least 10 anchors were counted, some of which again were missing nuts or for which the nuts were raised. The two other sides are inaccessible. The filter banks are about 10' high and are adjudged to have a natural frequency in excess of about 20 Hz. Since filter banks cannot uplift the anchors only need to resist base shear. There are a sufficient number of anchors visible to accomplish this therefore the filter banks are declared seismically adequate.

The SEWS for Fans W-30 A & B include the charcoal filter assessment.

### 9.0 Outliers

The summary table below identifies the duct, supports, and equipment that have not met the screening guidelines and/or the analytical review criteria of Reference 2. The resolution for each outlier is provided in the following table.

No.	Area	Duct No.	Туре	Description
1	PAB - Area 4	1	Hanger	Add a new trapeze support to the 104x26 duct (LAR 1)
2	PAB - Area 5	14	Hanger	Add a new trapeze support above the Containment Spray Pumps (LAR 6)
3	PAB - Area 5	26	Hanger	Replace existing "Z" shaped horizontal support with new shop fabricated support (LAR 7)
4	Pipeway 3 - Area 5	30A	Lateral Support	Add a lateral support to the end of the duct in Pipeway 3
5	Pipeway 3 - Area 5	25	Lateral Support	Add a lateral support to the end of the duct in Pipeway 4
6	Unit 1 RHR Hx Room - Area 8	37	Vertical Support	Add a knee brace support at duct corner near column line N/10
7	Unit 1 RHR Hx Room - Area 8	37	Duct Stiffeners	Add two horizontal stiffeners to the top of the EW duct near column line N/10

No.	Area	Duct No.	Туре	Description
8	Unit 2 RHR Hx Room	36	Vertical Support	Fasten existing support to duct near column line N/13
9	CREFS	N/A	Fans (4 total)	A three way support will be installed for W14A&B and W13B1&B2 that will render the vibration isolators as ineffective. The identified corrosion will be cleaned and the load path and anchorage will be re- inspected to determine their effectiveness and repaired as required (W13B1 and W13B2) (see SEWS). By making the vibration isolators ineffective and by correcting any corrosion issues, the equipment fundamental frequencies will not fall in the range where seismic demand exceeds the seismic capacity.
10	CREFS	43	Lateral Support	Add new lateral support on the Intake Duct near the bellows (at entry to charcoal filter)
11	PAB - Area 4	1	Hanger	Shell anchor failed vertical capacity check. Refined analysis found to be acceptable. No additional resolution required.
12	PAB - Area 4	4	Hanger	Shell anchor failed vertical capacity check. Refined analysis found to be acceptable. No additional resolution required.

Note: A broken duct (Duct No. 39) support at the floor penetration near column line P/13 was reported to PBNP and will be repaired (see CAP 01157521)

HVAC System Outlier Sheets (HSOS) for each outlier are included as attachments to this report.

### 10.0 Conclusion

The CREFS and VNPAB exhaust systems were seismically verified using the guidelines and criteria in Reference 2. The ducts, dampers, fans, and supports for the subject systems are found to be acceptable for the application of Reference 2. Systems temperatures and PBNP seismic motions are also found to be acceptable.

The SRT consisted of experienced, licensed engineers with the appropriate required SQUG GIP qualifications.

Dr. Robert P. Kennedy performed the required Peer Review of the seismic verification. Dr. Kennedy's report (Reference 11) is provided in Attachment 12.6 and concludes that as long as outlier issues are resolved the reviewed ductwork and associated components will be seismically adequate for the PBNP seismic design ground motion level.

In plant screening walkdowns regarding HVAC system and duct support structural integrity were performed by the SRT in accordance with the Reference 2 guidelines. SEWS were developed for the components and ductwork included in walkdown.

Calculations were performed to ensure that duct stresses due to dead load, seismic and pressure loads met the Reference 2 acceptance criteria. Limited analytical review cases were select and analyzed for duct support and duct configurations. Duct supports were evaluated for dead load, vertical capacity check, and rod fatigue.

Outliers were identified that required upgrades. The appropriate documentation was put in place to track each outlier upgrade or modification.

Based on the above it has been determined that the PBNP CREFS and VNPAB exhaust system ductwork, supports, and associated components are seismically adequate for the PBNP earthquake pending the installation of the modifications to resolve the outliers.

### 11.0 References

- 1. NextEra Energy letter to the USNRC dated September 10, 2009 "License Amendment Request 241, Alternative Source Term, Commitment for Seismic Evaluation"
- December 2006 Electric Power Research Institute (EPRI) Final Report 1014608, "Seismic Evaluation Guidelines for HVAC Duct and Damper Systems, Revision to 1007896, "
- 3. Specification No. 6118-M-41 "Specification for Sheetmetal Ductwork Heating, Ventilating, and Air Conditioning Systems for the Point Beach Nuclear Plant".
- 4. Sheet Metal and Air Conditioning Contractor's National Association, Inc (SMACNA), Fourth Edition, 1969.
- 5. S&A Calculation 09Q0839-C-001
- 6. Pacific Air Products Co. Sheets 7108-1 thru 7108-3 showing fire dampers
- 7. AISC Manual of Steel Construction 9th edition
- 8. Seismic Qualification Utility Group Generic Implementation Procedure (GIP) for Seismic Verification of Nuclear Plant Equipment Revision 2, Corrected 2/14/92
- 9. Hatch Nuclear Plant Unit 1 Seismic Verification of the Turbine Building Exhaust Ductwork, 1302241-R-001, Revision 0, October 6, 2004
- 10. Safety Evaluation by the Office of Nuclear Regulation on the Wisconsin Electric Power Company Response to Supplement No. 1 to Generic Letter 87-02 for the Point Beach Nuclear Plant Units 1 and 2, Docket Nos. 50-266 and 50-301, NRC letter 98-0018 dated 7/7/1998
- 11. Independent Peer Review of Seismic Verification of Point Beach Nuclear Plant Primary Auxiliary Building Exhaust (VNPAB) and Control Room Emergency Filtration System (CREFS) Ductwork, Associated Supports, and Components, October 29, 2009, No RPK-91029

### 12.0 Attachments

- 12.1 Figures
  - 1. PBNP free field spectrum vs. Bounding Spectrum
  - 2. M-109, Heating & Ventilation Turbine Building, Area 3, EL. 44' & EL. 60'
  - 3. M-116, Heating & Ventilation Auxiliary Building, Area 4, EL. 8'
  - 4. M-119, Heating & Ventilation Auxiliary Building, Area 5, EL. 8'
  - 5. M-122, Heating & Ventilation Auxiliary Building, Area 6, EL. 8'
  - 6. M-134, Heating & Ventilation Auxiliary Building, Area 8, EL. 8', (-)5'-3", & (-)19'-3"
  - 7. M-135, Heating & Ventilation Auxiliary Building, Area 8, Sections

8. M-145, Heating & Ventilation Auxiliary Building, Area 4, EL. 8' Sections

#### 12.2 Photos

- 1. Pipeway 3 HVAC duct appurtenance
- 2. Damper with seismic supports on CREFS
- 3. Typical duct/damper installation
- 4. Intake ductwork for CREFS above fan room

#### 12.3 SEWS

- 1. MCC 2B-42
- 2. MCC 1B-32
- 3. MCC 1B-42
- 4. MCC 2B-32
- 5. Panel C-67
- 6. Fan W-13B1
- 7. Fan W-13B2
- 8. Fan W-14A
- 9. Fan W-14B
- 10. Fan W-21A
- 11. Fan W-21B
- 12. Fan W-30A
- 13. Fan W-30B
- 14. VNPAB Exhaust Area 4
- 15. VNPAB Exhaust Area 5
- 16. VNPAB Exhaust Area 6
- 17. VNPAB Exhaust Area 8
- 18. CREFS

### 12.4 LARs

- 1. LAR Tracking Form
- 2. LAR 1
- 3. LAR 2
- 4. LAR 3
- 5. LAR 4
- 6. LAR 5
- 7. LAR 6
- 8. LAR 7
- 9. LAR 8

#### 12.5 HSOS

- 1. HSOS 1
- 2. HSOS 2
- 3. HSOS 3
- 4. HSOS 4
- 5. HSOS 5
- 6. HSOS 6
- 7. HSOS 7
- 8. HSOS 8

9. HSOS 9
10. HSOS 10
11. HSOS 11
12. HSOS 12

12.6 Independent Peer Review of the Seismic Verification of PBNP VNPAB and CREFS

## ATTACHMENTS FIGURES

Site - Ground Response Spectra SSE Horizontal

.



Figure 1 - PBNP Free Field Spectra vs. Bounding Spectrum

PBNP VNPAB and CREFS Seismic Verification S&A Report No. 09Q0839-R-001 Revision 1

Page 24 of 172



PBNP VNPAB and CREFS Seismic Verification S&A Report No. 09Q0839-R-001 Revision 1

Page 25 of 172



PBNP VNPAB and CREFS Seismic Verification S&A Report No. 09Q0839-R-001 Revision 1

Page 26 of 172




Page 28 of 172



Page 29 of 172



Page 30 of 172



Page 31 of 172

## ATTACHMENTS PHOTOS



Photo 1 – Pipeway 3 appurtenance braced to large pipe support.



Photo 2 - Damper with seismic supports on CREFS



Photo 3 - Typical duct/damper installation



Photo 4 – Intake ductwork for CREFS above fan room

r.

# ATTACHMENTS SEWS

Page 35 of 172

50-002217

SCREENING EVALUATI	ON WORK SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/92 Status; Yes Sheet 1 of 7
ID: 2B-42 (Rev. 3) Class: 1. Motor Control C		ol Centers
Description : 480V MOTOR CONT	ROL CENTER PAB SAFEGUARDS	}
Building : PAB	Floor El. : 26.00	Room, Row/Col : AREA 5
Manufacturer, Model, Etc. :	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

## SEISMIC CAPACITY VS DEMAND

1. Elevation where equipment receives seismic input			
2. Elevation of seismic input below about 40' from grade (grade = 8.00)		N/A	
3.	Equipment has fundamental frequency above about 8 Hz (est. frequency = )	N/A	
4.	Capacity based on: 1.50 * Bounding Spectrum		
5.	Demand based on: 1.00 * Conservative Design Floor Response Spectra	,	
	1.200		
	GE		
	6.18 LOG Hz 38.91		
Capacity Demand			
	Filè Record		
Capac	ity J:\APPDATA\GIPPER2\GIP\spectra.des Label Bounding Spectrum	-	
Demar	nd 1 J:\APPDATA\GIPPER2\PROJ0032\spectra.des PLANT[Point Beach]BUILDING[Aux Central Part[ELEVATION]26[DIRECTION[Horizontal]EART 2[LOCATION[Area 5]BLDG-DAMP][EQ DAMP]5%	HQUAKEĮOBE x	
Demar	nd 2 J:\APPDATA\GIPPER2\PROJ0032\spectra.des PLANT[Point Beach]BUILDING[Aux Central Part[ELEVATION]26[DIRECTION]Horizontal]EART 2[LOCATION]Area 5[BLDG-DAMP][EQ DAMP]5%	HQUAKEJOBE X	

Does capacity exceed demand?

Yes

÷

ç

77

PBNP VNPAB and CREFS Seismic Verification			
	S&A Report No. 09Q0839-R-001 Revisio	n 1 Page 36 of 172	
		GIP Rev 2, Corrected, 2/14/92	
SCREENING EVAL	Status: Yes		
	official work official (carroy	Sheet 2 of 7	
ID:2B-42 (Rev. 3)	: 2B-42 (Rev. 3) Class : 1. Motor Control C		
Description: 480V MOTOR C	CONTROL CENTER PAB SAFEGUARDS		
Building : PAB	Floor El. : 26.00	Room, Row/Col : AREA 5	
Manufacturer, Model, Etc. :			

į.

\$

## **CAVEATS - BOUNDING SPECTRUM**

	And a second
MCC/BS Caveat 1 - Earthquake Experience Data Base.	Yes
MCC/BS Caveat 2 - Rating of 600 V or Less.	Yes
MCC/BS Caveat 3 - Adjacent Cabinets Bolted Together.	Yes
MCC/BS Caveat 4 - Attached Weight of 100 Pounds or Less.	Yes
MCC/BS Caveat 5 - Externally Attached Items Rigidly Anchored.	N/A
MCC/BS Caveat 6 - General Configuration Similar to NEMA Standards.	Yes
MCC/BS Caveat 7 - Cutouts Not Large.	Yes
MCC/BS Caveat 8 - Doors/Buckets Secured.	Yes
MCC/BS Caveat 9 - Natural Frequency Relative to 8 Hz Limit Considered.	Yes
MCC/BS Caveat 10 - Adequate Anchorage.	Yes
MCC/BS Caveat 11 - Potential Chatter of Essential Relays Evaluated.	Yes
MCC/BS Caveat 12 - No Other Concerns	Yes

Is the intent of all the caveats met for Bounding Spectrum?

## ANCHORAGE

1. The sizes and locations of anchors have been determined.	Yes
2. Appropriate equipment characteristics have been determined (mass, CG, natural freq.,	Yes
damping, center of rotation).	
3. The type of anchorage is covered by the GIP.	Yes
4. The adequacy of the anchorage installation has been evaluated (weld quality and length,	Yes
nuts and washers, expansion anchor tightness, etc.)	
5. Factors affecting anchorage capacity or margin of safety have been considered: embedment	Yes
length, anchor spacing, free-edge distance, concrete strength/condition, and concrete	
cracking.	
6. For bolted anchorages, any gaps under the base are less than 1/4.	Yes
7. Factors affecting essential relays have been considered: gaps under the base, capacity	Yes
reduction for expansion anchors.	
8. The base has adequate stiffness and the effect of prying action on anchors has been	Yes
considered.	
9. The strength of the equipment base and the load path to the CG is adequate.	Yes
10. The adequacy of embedded steel, grout pads or large concrete pads have been evaluated.	Yes
11. The anchorage capacity exceeds the demand.	Yes

Are anchorage requirements met?

<u>Yes</u>

<u>Yes</u>

-

....

#### PBNP VNPAB and CREFS Seismic Verification S&A Report No. 09Q0839-R-001 Revision 1

Page 37 of 172

SCREENING EVALUATION WO	)RK SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 3 of 7
ID: 2B-42 (Rev. 3) Class: 1. Motor Control C		centers
Description : 480V MOTOR CONTROL CE	NTER PAB SAFEGUARDS	
Building : PAB FI	oor El. : 26.00	Room, Row/Col : AREA 5
Manufacturer, Model, Etc. :		

### INTERACTION EFFECTS

1. Soft targets are free from impact by nearby equipment or structures.	Yes
2. If the equipment contains sensitive relays, it is free from all impact by nearby equipment or	Yes
structures.	
3. Attached lines have adequate flexibility.	Yes
4. Overhead equipment or distribution systems are not likely to collapse.	Yes
5. No other adverse concerns were found.	Yes

Is equipment free of interaction effects?

### IS EQUIPMENT SEISMICALLY ADEQUATE?

#### COMMENTS

Rev. 3 SRT is D. P. Brown and R. K. Hanneman on 1/31/05

REF: 1) MR 01-128\*N

**SEWS Revisions** 

Rev 0. Original USI A-46 Seismic Verification Rev 1. MR 93-041\*A - Modification to 2B-42 compartment 11M to use it for a new power supply to W-14B Control Room Filter Fan - 7/25/96. Rev 2. MR 96-033 - Replacement of MCC Control Power Transformers Rev 3. MR 01-128\*N

Description of Design Change:

The attached table lists the components that will be installed during the bucket upgrade. Also, new sheet metal buckets are being fabricated. The new buckets are of the same configuration as the existing buckets. The buckets are mounted into existing MCC's in the same manner as the existing buckets. Thus, the buckets themselves are qualified by comparison to the existing buckets.

Seismic Evaluation of Design Change:

Seismic Qualification Review Report, SQRR, SQ-002079, evaluated the applicability of the Cutler-Hammer seismic testing that is documented therein. The test report is applicable to the components tested provided they are used in MCC's and located where the Floor Response Spectra is <= that of the PAB 26 ft. Since 2B-42 is located in the PAB, el 26 ft, the Cutler-Hammer test report can be used to qualify the components listed in the attached table.

The seismic qualification records for 2B-42 are the Rev. 0, 1, 2 and 3 SEWS.

Yes

· P	BNP VNPAB and CREFS Seismic Verifica	tion Bage 38 of 172	
	A Report No. 0900039-R-001 Revision	GIP Rev 2, Corrected, 2/14/92	
SCREENING EVALUATION V	Status: Yes		
		Sheet 4 of 7	
ID:2B-42 (Rev. 3)	Class: 1. Motor Control C	Centers	
Description : 480V MOTOR CONTROL CENTER PAB SAFEGUARDS			
Building : PAB	Iding : PAB Floor El. : 26.00		
Manufacturer, Model, Etc. :			

This rev. 3 SEWS is identified as SQ-002217.

Evaluated by:

å -

leer anneman

Date:

1/31/05

Attachment: Table

SCREENING EVALUATION WO	RK SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 5 of 7
ID:2B-42 (Rev. 3) Class: 1. Motor Control C		enters
Description : 480V MOTOR CONTROL CE	NTER PAB SAFEGUARDS	
Building : PAB Flo	oor El. : 26.00	Room, Row/Col : AREA 5
Manufacturer, Model, Etc. :		

## <u>Table</u>

----

-----

.

Component	Part Number(s)	SQ-002079	Notes
		Seismic Test	
Circuit Breaker	HFD3015	Table 3	The "L" in the part number of the breaker referenced SQ-002079 is equipped with wire compression fittings. The breaker on the left requires lugged connections that are more positive than compression
			this breaker.
Circuit Breaker	HFD3020 HFD3030 HFD3045 HFD3050 HFD3175	Table 3	Encompassed by the HFD3015L, 15 Amp, and HFD3225L, 225 Amp, breakers tested in SQ-002079.
Circuit Breaker <sup>!</sup> Operating Handle	112D650G03	Table 3	Same style handle used for all sizes of breakers.
Control Power Transformer	C0150E2AXX	Table 3	The "XX" signifies no secondary fuse clips. The SQ-002079 report specifies part number C0150E2A, which includes the secondary fuseclip. The tested configuration envelops the configuration sans secondary fuseclip.
Control Power Transformer	C0250E2AXX	Table 3	The "XX" signifies no secondary fuse clips. The SQ-002079 report specifies part numbers C0150E2A and C0500E2A, which includes the secondary fuseclip. The tested configurations envelope the configuration sans secondary fuseclip.
Control Power Fuse	Bussmann BAF 3 Amp	Table 3	Encompassed by the 1 and 6 Amp fuses tested in SQ-002079.
Control Power Fuse	Bussmann BAF 6 Amp	Table 3	Same part as tested in SQ-002079.
Control Power Fuseblock	NDNF1-WH	Table 3	Same part as tested in SQ-002079.
Control Power Terminal Blocks, Mounting Support Bar	C382MF9 (9-point), C382MF3B (3-point), 412A958G02	Table 3	Maximum number of terminal points used in MCC 2B42: 21, which is encompassed by the terminal blocks tested in SQ-002079.
Full-Voltage Reversing Starter	A200M1CAC, A201K1CA	Table 2	Both starters vertically mounted in the same bucket. The configuration tested in SQ-002079 envelopes this configuration.
Full-Voltage Non-Reversing Starter	A201K1CA	Table 1	The configuration tested in SQ- 002079 envelopes this configuration.

.

7

2

# Page 40 of 172

# SCREENING EVALUATION WORK SHEET (SEWS)

GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 6 of 7

ID : 2B-42 ( Rev. 3 ) Class : 1. Motor Contro Description : 480V MOTOR CONTROL CENTER PAB SAFEGUARDS Building : PAB

۰,

Class: 1. Motor Control Centers

Floor El. : 26.00 Room, Row/Col : AREA 5

Manufacturer, Model, Etc. :

Component	Part Number(s)	SQ-002079	Notes
		Seismic Test	
Full-Voltage Non-Reversing	A201K2CA	Table 2	The configuration tested in SQ-
Starter			configuration.
Full-Voltage Non-Reversing	A200M4CAC	Table 1	The configuration tested in SQ-
Starter			002079 envelopes this
Overload Relay	AA13A	Table 3	The "PB" at the end of the part
,	AA23A		number in the report stands for
	АА43А		additional alarm contact (B). The
			"A" at the end of this part number to
			the left stands for "starter mount."
		•	mount is judged to be as rigid as
			the panel mount. No additional
			amplification needs to be added to starter mount overload relays
			Qualified by comparison to SQ-
			002079.
Overload Relay Reset	1427B27G07	I able 3	1 and size 2 full-voltage reversing
, ushbullon		·	(FVR) starters
Overload Relay Reset	1427B27G02	Table 3	SQ-002079 encompasses the size
Pushbutton			reversing (FVNR) starters.
Overload Relay Reset	1427B27G01	Table 3	SQ-002079 encompasses the
Pushbutton			Size 1 and Size 2 full-voltage
Overload Heater Elemente	Various Sizes	Table 3	non-reversing (FVNR) starters.
Ovenuau meater ciements	Valious Sizes		reused from 2B42, therefore they
· · · · · · · · · · · · · · · · · · ·			do not need to be evaluated.
Auxiliary Relay	NBF22F	Table 2	below), envelops this relay.
Auxiliary Relay	NBF44F	Table 2	Same part as tested in SQ-
· · · · · · · · · · · · · · · · · · ·	47144471140	Table 2	002079
Liapsed Lime Indicator	10250T101	Table 3	Same parts as tested in SQ-002079.
6 Contact Blocks	10250T1		002079.
	10250T2		
	10250T3		1
	10250T51	1	
	10250153		
1	1	1	1

Page 41 of 172

# SCREENING EVALUATION WORK SHEET (SEWS)

GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 7 of 7

 ID: 2B-42 (Rev. 3)
 Class : 1. Motor Control Centers

 Description : 480V MOTOR CONTROL CENTER PAB SAFEGUARDS

 Building : PAB
 Floor El. : 26.00
 Room, Row/Col : AREA 5

Manufacturer, Model, Etc. :

Ş

Notes Part Number(s) SQ-002079 Component Seismic Test Table 3 Same parts as tested in SQ-10250T1353 **3-Position Spring Return** 002079, except for 10250T1343. Right-to-Center, Maintained 10250T1 This is a 3-position spring return-to-Left Selector Switch with 6 10250T2 center selector switch with one **Contact Blocks** 10250T3 contact block with two normally 10250T51 10250T53 open (NO) contacts (10250T2). Selector switch 10250T1343 is similar to 10250T1353, which was tested in SQ-002079. Therefore, 10250T1343 is qualified by similarity. Indicating light, 10250T181N is the 10250T181N, Table 3 Indicating Light with Red same part as tested in SQ-002079. 10250TC1N (red Lens Cap 10250TC1N red lens was tested. lens) Other lenses are same except for 10250TC6N (white color. lens) 10250TC2N (green lens)

Page 42 of 172

	50-002167	
SCREENING EVALUATION	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 1 of 4	
D: 1B-32 (Rev. 3)	trol Centers	
Description : 480V MOTOR CONTROL	CENTER PAB SAFEGUARD	S
Building : PAB	PAB Floor El. : 8.00	
Manufacturer, Model, Etc. :		

Manufacturer, Model, Etc. :

# SEISMIC CAPACITY VS DEMAND

1. Eleva	1. Elevation where equipment receives seismic input 8.00			
2. Elevation of seismic input below about 40' from grade (grade = 8.00) N/A			N/A	
3. Equip	3. Equipment has fundamental frequency above about 8 Hz (est. frequency = ) N/A			
4. Capac	ity based on: 1.50 * Bounding Sp	ectrum		
5. Dema	nd based on: 1.00 * Conservative	Design Floor Response Spectra		
5. Demand based on: 1.00 * Conservative Design Floor Response Spectra				
	C	apacity Demand		
	File	Record		
Capacity	J:\APPDATA\GIPPER2\GIP\spect ra.des	LabellBounding Spectrum		
Demand 1	J:\APPDATA\GIPPER2\PROJ003 2\spectra.des	PLANTIPoint BeachIBUILDINGIAux South WingsIELEVATIONI8IDIRECTIONI ARTHQUAKEIOBE x 2ILOCATION 6IBLDG-DAMPIIEQ DAMPI5%	: North and HorizontallE IlAreas 4 &	
Demand 2	J:\APPDATA\GIPPER2\PROJ003 2\spectra.des	PLANTIPoint BeachBUILDINGIAux South WingsIELEVATIONI8IDIRECTIONI ARTHQUAKEIOBE x 2ILOCATION 6IBLDG-DAMPIEQ DAMPI5%	North and HorizontallE IAreas 4 &	

Does capacity exceed demand?

Yes

6



PBNP VNPAB and CREFS Seismic Verification S&A Report No. 09Q0839-R-001 Revision 1 Page 43 o				
SCREENING EVALU	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 2 of 4			
ID: 1B-32 (Rev. 3)	Class: 1. Motor Con	trol Centers		
Description : 480V MOTOR CONTROL CENTER PAB SAFEGUARDS				
Building : PAB Floor El. : 8.00		Room, Row/Col : AREA 4		

Manufacturer, Model, Etc. :

in the second second

# **CAVEATS - BOUNDING SPECTRUM**

MCC/BS Caveat 1 - Earthquake Experience Data Base.	Yes
MCC/BS Caveat 2 - Rating of 600 V or Less.	Yes
MCC/BS Caveat 3 - Adjacent Cabinets Bolted Together.	Yes
MCC/BS Caveat 4 - Attached Weight of 100 Pounds or Less.	Yes
MCC/BS Caveat 5 - Externally Attached Items Rigidly Anchored.	N/A
MCC/BS Caveat 6 - General Configuration Similar to NEMA Standards.	Yes
MCC/BS Caveat 7 - Cutouts Not Large.	Yes
MCC/BS Caveat 8 - Doors/Buckets Secured.	Yes
MCC/BS Caveat 9 - Natural Frequency Relative to 8 Hz Limit Considered.	Yes
MCC/BS Caveat 10 - Adequate Anchorage.	Yes
MCC/BS Caveat 11 - Potential Chatter of Essential Relays Evaluated.	Yes
MCC/BS Caveat 12 - No Other Concerns	Yes

Is the intent of all the caveats met for Bounding Spectrum?

Yes

# ANCHORAGE

1. The sizes and locations of anchors have been determined.	Yes	
2. Appropriate equipment characteristics have been determined (mass, CG, natural		
freq., damping, center of rotation).		
3. The type of anchorage is covered by the GIP.	Yes	
4. The adequacy of the anchorage installation has been evaluated (weld quality and	Yes	
length, nuts and washers, expansion anchor tightness, etc.)		
5. Factors affecting anchorage capacity or margin of safety have been considered:	Yes	
embedment length, anchor spacing, free-edge distance, concrete strength/condition,		
and concrete cracking.		
6. For bolted anchorages, any gaps under the base are less than 1/4.	Yes	
7. Factors affecting essential relays have been considered: gaps under the base,	Yes	
capacity reduction for expansion anchors.		
8. The base has adequate stiffness and the effect of prying action on anchors has been	Yes	
considered.		
9. The strength of the equipment base and the load path to the CG is adequate.	Yes	
10. The adequacy of embedded steel, grout pads or large concrete pads have been	Yes	
evaluated.		
11. The anchorage capacity exceeds the demand.	Yes	

Are anchorage requirements met?

PBNP VNPAB and	CREFS Seisn	nic Verification
S&A Report No. 09	Q0839-R-001	Revision 1

Page 44 of 172

SCREENING EVALUATION V	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 3 of 4			
ID:1B-32(Rev. 3)	Centers			
Description : 480V MOTOR CONTROL CENTER PAB SAFEGUARDS				
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4		
Manufacturar Madal Eta 1	······································			

#### Manufacturer, Model, Etc. : \_

÷,

## **INTERACTION EFFECTS**

1. Soft targets are free from impact by nearby equipment or structures.	
2. If the equipment contains sensitive relays, it is free from all impact by nearby	
equipment or structures.	
3. Attached lines have adequate flexibility.	
4. Overhead equipment or distribution systems are not likely to collapse.	Yes
5. No other adverse concerns were found.	

Is equipment free of interaction effects?

## IS EQUIPMENT SEISMICALLY ADEQUATE?

## **COMMENTS**

The SRT is D. N. Carter & D. P. Brown on 12/18/2003.

References:

[1] MR 03-007 [2] SQ-002079

SEWS Revisions:

Rev 0. Original USI A-46 Seismic Verification Rev 1. MR 93-041\*A - MR 93-041\*A modifies 1B-32 compartment 9B to use it for a new power supply to W-14A Control Room Filter Fan - 7/25/96. Rev 2. MR 96-032 - Replacement of MCC Control Power Transformers Rev 3. MR 03-007

Description of Change:

Modification MR 03-007 repowers Service Water (SW) to 1P-29 Auxiliary Feedwater (AFW) pump suction motor operated valve (MOV) 1AF-4006 from B-train motor control center (MCC) 1B42 to A-train MCC 1B32. This will involve installing a new conduit and cables for the new valve control circuit.

Yes

PBNP VNPAB and CREFS Seismic Verification				
S&A Report No. 09Q0839-R-001 Revision 1			1 Page 45 of 172	
			GIP Rev 2, Corrected, 2/14/92	
SCREENING EVALUATION	( SHEET (SEWS)	Status: Yes		
			Sheet 4 of 4	
ID: 1B-32 (Rev. 3) Class: 1. Motor Control C			enters	
Description : 480V MOTOR CONTROL CENTER PAB SAFEGUARDS				
Building : PAB	Floor	El. : 8.00	Room, Row/Col : AREA 4	
Manufacturer, Model, Etc. :				

This modification will require the installation of new MCC breaker bucket 1B52-3213F in MCC 1B32. The new bucket will be placed in current spaces 1B00-3213D and 1B00-3213F.

Seismic Evaluation of Change:

The components in the bucket are as follows:

- 1. Cutler Hammer model HFD3015 breaker.
- 2. Cutler Hammer series A200 starter.
- 3. Cutler Hammer model C0150E2AXX control power transformer.
- 4. Terminal block rated for 600 Vac and 40 A.
- 5. Bussmann BAF style control power fuse (3 Amp).
- The breaker, starter, control power transformer and terminal block were tested by Trentec as documented in SQ-002079. Trentec also tested a 1A and 6A style BAF fuse. The 3A fuse used here is comparable to the fuses tested and is acceptable by comparison to the tested fuses. Therefore, all the components in the breaker are seismically qualified.

As part of the original USI A-46 seismic evaluation for 1B-32, the anchorage calculation (using Anchor Version 4.0) for 1B-32 estimated a weight of 800# per MCC section. The replacement CPTs (Control Power Tranformers) installed in MR 96-032 (See Rev. 2 SEWS) increase the weight of the MCC by about 175# from an estimated 5600# to 5775#. The new bucket being added in this modification weighs less than 100# (estimated). The total load increase from this modification and MR 96-032 is  $\rho d \sqrt{1/5/64}$ -approximately 5% of the total MCC load. The original anchorage calculation had a minimum safety factor of 2.474. This load increase will have a negligible affect on the safety factors. Therefore the anchors are acceptable for the revised loads.

The seismic qualification record for 1B-32 is the Rev. 0, 1, 2, & 3 SEWS.

This evaluation vis identified as SQ-002167.

Evaluated by:

Date:

SCREENING EVALUATION W	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 1 of 7		
ID: 1B-42 (Rev. 4)	enters		
Description : 480V MOTOR CONTROL CENTER PAB SAFEGUARDS			
Building : PAB	-loor El. : 26.00	Room, Row/Col : AREA 5	
Manufacturer, Model, Etc. :			

# SEISMIC CAPACITY VS DEMAND

4 -

1. Eleva	1. Elevation where equipment receives seismic input 26.00			26.00	
2. Elevation of seismic input below about 40' from grade (grade = 8.00) N/A			N/A		
3. Equip	ment has funda	mental frequency abov	ve about 8 Hz (est. frequency = )	N/A	
4. Capac	city based on:	1.50 * Bounding Spe	ctrum		
5. Dema	ind based on:	1.00 * Conservative 1	Design Floor Response Spectra		
	5. Demand based on: 1.00 * Conservative Design Floor Response Spectra				
	File		Record		
Capacity	J:\APPDATA ra.des	\GIPPER2\GIP\spect	LabellBounding Spectrum		
Demand 1	J:\APPDATA 2\spectra.des	\GIPPER2\PROJ003	PLANTIPoint BeachBUILDINGAux PartIELEVATIONI26IDIRECTIONIH RTHQUAKEIOBE x 2ILOCATIONIA DAMPIEQ DAMPI5%	Central orizontalIEA Area 5IBLDG-	
Demand 2	J:\APPDATA 2\spectra.des	\GIPPER2\PROJ003	PLANTIPoint BeachIBUILDINGIAux PartIELEVATIONI26IDIRECTIONIH RTHQUAKEIOBE x 2ILOCATIONIA DAMPIEQ DAMPI5%	Central orizontalIEA Area 5IBLDG-	

Does capacity exceed demand?

Yes

.

•	PBNP VNPAB and CREFS Seismic Verification				
	S&A Report No_09Q0839-R-001 Revision 1				
				GIP Rev 2, Corrected, 2/14/92	
SCREENING EVALUATION WORK SHEET (SEWS)				Status: Yes	
Soffeening Evalu	SCREENING EVALUATION WORK UNLET (CERC)			Sheet 2 of 7	
ID: 1B-42 (Rev. 4)	: 1B-42 ( Rev. 4 ) Class : 1. Motor Control C			enters	
Description : 480V MOTOR CONTROL CENTER PAB SAFEGUARDS					
Building : PAB	Floor	Floor El. : 26.00		Room, Row/Col : AREA 5	
Manufacturar Model Etc.					

Manufacturer, Model, Etc. :

Ê

# CAVEATS - BOUNDING SPECTRUM

MCC/BS Caveat 1 - Earthquake Experience Data Base.	Yes
MCC/BS Caveat 2 - Rating of 600 V or Less.	Yes
MCC/BS Caveat 3 - Adjacent Cabinets Bolted Together.	Yes
MCC/BS Caveat 4 - Attached Weight of 100 Pounds or Less.	N/A
MCC/BS Caveat 5 - Externally Attached Items Rigidly Anchored.	N/A
MCC/BS Caveat 6 - General Configuration Similar to NEMA Standards.	Yes
MCC/BS Caveat 7 - Cutouts Not Large.	Yes
MCC/BS Caveat 8 - Doors/Buckets Secured.	Yes*
MCC/BS Caveat 9 - Natural Frequency Relative to 8 Hz Limit Considered.	Yes
MCC/BS Caveat 10 - Adequate Anchorage.	Yes
MCC/BS Caveat 11 - Potential Chatter of Essential Relays Evaluated.	Yes*
MCC/BS Caveat 12 - No Other Concerns	Yes

Is the intent of all the caveats met for Bounding Spectrum?

<u>Yes</u>

# ANCHORAGE

1. The sizes and locations of anchors have been determined.	Yes
2. Appropriate equipment characteristics have been determined (mass, CG, natural	Yes
freq., damping, center of rotation).	
3. The type of anchorage is covered by the GIP.	Yes
4. The adequacy of the anchorage installation has been evaluated (weld quality and	Yes
length, nuts and washers, expansion anchor tightness, etc.)	
5. Factors affecting anchorage capacity or margin of safety have been considered:	Yes
embedment length, anchor spacing, free-edge distance, concrete strength/condition,	
and concrete cracking.	
6. For bolted anchorages, any gaps under the base are less than 1/4.	Yes
7. Factors affecting essential relays have been considered: gaps under the base,	Yes
capacity reduction for expansion anchors.	
8. The base has adequate stiffness and the effect of prying action on anchors has been	Yes
considered.	
9. The strength of the equipment base and the load path to the CG is adequate.	Yes
10. The adequacy of embedded steel, grout pads or large concrete pads have been	Yes
evaluated.	
11. The anchorage capacity exceeds the demand.	Yes

Are anchorage requirements met?

PBNP VNPAB and CREFS Seismic Verification

	A REPORTING, USQU839-R-UUT REVISION	1 Page 48 of 172
SCREENING EVALUATION WORK SHEET (SEWS)		GIP Rev 2, Corrected, 2/14/92 Status: Yes Shoet 3 of 7
		Sileet 3 01 7
ID : 1B-42 ( Rev. 4 ) Class : 1. Motor Col		Centers
Description : 480V MOTOR CONTROL	CENTER PAB SAFEGUARDS	
Building : PAB	Floor El. : 26.00	Room, Row/Col : AREA 5
Manufacturar Madal Eta :		

| Manufacturer, Model, Etc.

## **INTERACTION EFFECTS**

1. Soft targets are free from impact by nearby equipment or structures.	Yes*
2. If the equipment contains sensitive relays, it is free from all impact by nearby	
equipment or structures.	
3. Attached lines have adequate flexibility.	Yes*
4. Overhead equipment or distribution systems are not likely to collapse.	Yes*
5. No other adverse concerns were found.	Yes

Is equipment free of interaction effects?

## IS EQUIPMENT SEISMICALLY ADEQUATE?

## **COMMENTS**

Rev. 4 SRT: D P Brown and D N Carter Date: 10/7/2002

References:

1- MR-01- 128\*C 2- IWP 01-128\*C-1B 3- IWP 01-128\*C-1F 4- IWP 01-128\*C-1J 5- IWP 01-128\*C-2C 6- IWP 01-128\*C-2F 7- IWP 01-128\*C-2J 8- IWP 01-128\*C-3C 9- IWP 01-128\*C-3F 10- IWP 01-128\*C-3J 11- IWP 01-128\*C-4F 12- IWP 01-128\*C-4J 13- IWP 01-128\*C-4M 14- IWP 01-128\*C-5J 15- IWP 01-128\*C-5M 16- IWP 01-128\*C-6C 17- IWP 01-128\*C-6F 18- IWP 01-128\*C-6M 20- IWP 01-128\*C-7C 21- IWP 01-128\*C-7F 22- IWP 01-128\*C-8K

ñ

L

Yes

S8	A Report No. 09Q0839-R-001 Revi	sion 1 Page 49 of 172
		GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION W	ORK SHEET (SEWS)	Status: Yes
	(,	Sheet 4 of 7
ID:1B-42(Rev. 4)	Class: 1. Motor Cont	rol Centers
Description: 480V MOTOR CONTROL C	ENTER PAB SAFEGUARD	S
Building : PAB	Floor El. : 26.00	Room, Row/Col : AREA 5
Manufacturer, Model, Etc. :		

23- IWP 01-128\*C-9M
24- IWP 01-128\*C-10C
25- IWP 01-128\*C-10F
26- IWP 01-128\*C-11B
27- IWP 01-128\*C-11F
28. WE Calculation 85-010, rev. 01
29. WE Calculation Addendum N-97-0154-00-A
30. Seismic Qualification Review Report (SQRR) SQ-002079
31. Rev. 0 SEWS for 1B-42, SQ-000020

SEWS Revisions: Rev. 0 - A-46 Walkdown (SQ-000020) Rev. 1 - MR 91-116 (SQ-001244) Rev. 2 - MR 93-041\*A (SQ-001249) Rev. 3 - MR 96-032 (SQ-001471) Rev. 4 - MR 01-128\*C: Replace/upgrade MCC buckets

Description of Design Change:

The scope of this modification is to replace Motor Control Center (MCC) 1B-42 breaker buckets 1B52-421B, 1F, 1J, 2C, 2F, 2J, 3C, 3F, 3J, 4F, 4J, 4M, 5J, 5M, 6C, 6F, 6M, 7C, 7F, 8K, 8M, 9M, 10C, 10F, 11B-and 11F with new Cutler Hammer (C/H) breaker buckets. These new buckets shall be equipped with the same components as the existing buckets (i.e. breaker, starter, transformer, etc.); however, the new breaker will have an interrupting capability higher than the available short circuit current. In addition, this modification will replace the SPACE door covers for cubicles 1B00-421C, 6J, 7H, 9F, 9H, 10M, 11D, 11G, 12B, 12D and 12G. All other MCC 1B-42 breaker buckets will be replaced by MR 01-128\*D.

The purpose of this modification is to improve personnel and equipment protection by replacing the 1B-42 breakers that have been identified as being overdutied under maximum fault conditions in PBNP Calculation Addendum N-97-0154-00-A, "Refinements to Electrical AC Power Distribution System Short Circuit Analysis." It should also be noted that this modification is one of many modifications (MR 01-128\*A-S) that will resolve maximum fault conditions concerns identified by calculation addendum N-97-0154-00-A.

The components of the replacement buckets have been seismically qualified by shake table testing. The test report has been evaluated by SQRR and is documented on SQ-002079. The new buckets are supported in the MCC in the same manner as the existing buckets.

The doors in front of spaces, (i.e., those places in the MCC where there is no bucket), will be replaced, with new doors. The existing doors are held in place by a minimum of two (2) screws. The new doors will be held in place on one side by a minimum of one (1) hinge, which is attached to the MCC cabinet

5.4

SCREENING EVALUATION	WORK SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 5 of 7
ID: 1B-42 (Rev. 4) Class: 1. Motor Control C		Centers
Description : 480V MOTOR CONTROL	CENTER PAB SAFEGUARDS	
Building : PAB	Floor El. : 26.00	Room, Row/Col: AREA 5
Manufacturer, Model, Etc. :		

by two screws. The other side of the door is held in place by a minimum of one screw. This arrangement is the same as used on the doors in front of the MCC buckets.

## CAVEATS:

MCC/BS Caveat 8 - Doors/Buckets secured. The IWP's listed in the references above, contain steps in section 3.0 to document re-engaging the mounting screws and closing of the door. MCC/BS Caveat 11 - The MCC's contain relays and other seismically sensitive equipment. All these items were seismically qualified by shake table testing, see the SQRR in SQ-002079

## INTEACTION EFECTS:

1. The MCC buckets are internal to the MCC. Therefore, no new soft targets are created. The replacement doors are made of steel, and do not contain soft targets.

2. The MCC's contain relays and other seismically sensitive equipment. All these items were seismically qualified by shake table testing, see the SQRR in SQ-002079.

3. No new lines were attached by mod MR 01-128\*C

4. No new otherhead equipment was added by mod MR 01-128\*C.

Seismic Evaluation of Design Change:

The original A-46 SEWS, SQ-000020, was reviewed. It refers to WE calculation 85-010, rev. 01 for justification of the anchorage for the MCC's. The calculation uses an estimated weight for the MCC. The new MCC buckets do not weigh significantly more than the existing MCC buckets. Therefore, the existing calculation is still acceptable for providing justification for the MCC.

The mounting of the existing MCC buckets in the MCC was compared to the mounting of the new buckets. The new buckets are supported by the MCC in the same manner in which the existing buckets are mounted. The new buckets do not require any changes to the MCC. Four (4) points, two (2) on each side of the bucket, support both the existing and new buckets. Both old and new buckets have a retaining latch at the front of the bucket. Thus, the new buckets are similar to those in the existing earthquake data base (MCC/BS Caveat 1).

The new doors are held in place by at least one hinge, with two screws, and at least one screw on the opposite side from the hinge. This arrangement is the same as that for the doors in front of buckets. The SRT has evaluated this arrangement as being sufficient to hold the door closed during a seismic event.

SRT has determined that the MCC has sufficient strength capacity to remain functional before, during and after a seismic event.

Subcomponents:

-

PBNP VNPAB and CREFS Seismic Verification		
	S&A Report No. 09Q0839-R-001 Revision	n 1 Page 51 of 172
	•	GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION WORK SHEET (SEWS)		Status: Yes
		Sheet 6 of 7
ID: 1B-42 (Rev. 4) Class: 1. Motor Control Cente		l Centers
Description : 480V MOTOR CONTRO	<b>DL CENTER PAB SAFEGUARDS</b>	
Building : PAB	Floor El. : 26.00	Room, Row/Col : AREA 5
Manufacturer, Model, Etc. :		

The following items are sub-components of 1B-42:

... جه

1B52-421B	PWR TO 1SI-850B RHR PUMP SUMP B SUCTION
1B52-421F	PWR TO 1SI-852B LOW HEAD SI CORE DELUGE ISOL
1B52-421J	PWR TO 1SI-866B CORE DELUGE INJ LINE OUTBD ISOL
1B52-421M	PWR TO 1SI-860B CONT SPRAY PUMP DISCH REDUN ISOL
1B52-422C	PWR TO 1SI-896B SI PUMP SUCTION
1B52-422F	PWR TO 1SI-878C RV SAFETY INJECTION
1B52-422J	PWR TO 1SI-878B COLD LEG INJ TO T-34B OUT ISOL
1B52-422M	PWR TO 1SI-860D CONT SPRAY PUMP DISCH REDUN ISOL
1B52-423C	PWR TO 1SI-851B RHR PUMP SUCT FROM CONT SUMP B
1B52-423F	PWR TO 1SI-856B RWST OUT TO P-10A/B SUCTION HDR
1B52-423J	PWR TO 1SI-870B CONT SPRAY PUMP SUCT FROM T-13
1B52-423M	PWR TO 1SI-871B CONT SPRAY PUMP SUCT FROM HX-11B
1B52-424C	PWR TO 1SI-825B RWST OUTLET TO P-15A/B SI PUMP
1B52-424F	PWR TO 1SI-841B SI ACCUMULATOR OUTLET
1B52-424J	PWR TO 1CC-738B RHR HX SHELL SIDE INLET
1B52-424M	PWR TO 1RH-701 RCS TO P-10A/B RHR PUMP SUCT HDR
1B52-425F	PWR TO 1SI-826A SI PUMP SUCTION/BAST SERIES ISOL
1B52-425J	PWR TO 1SI-826B SI PUMP SUCT/BAST PARALLEL ISOL
1B52-425M	PWR TO 1CV-350 (1P-4A/B) BA XFR PMP 1P-2A-C CHG PMP SUCT
1B52-426C	PWR TO 1CC-719 CONT EQUIP CC SUP HDR OUTBD ISOL
1B52-426F	PWR TO 1CV-1298 (1HX-2) REGEN HX OUT/RC LOOP A COLD LEG
1B52-426M	PWR TO 1RC-427 RC LOOP B COLD LEG TO CVCS LETDOWN ISOL
1B52-427C	PWR TO 1RC-596 (1T-2) PRT DRAIN TO 1T-16 RCDT
1B52-427F	PWR TO 1RC-516 PZR RC-430 PWR-OPER RELIEF INLET
1B52-427M	PWR TO P-12B SFP COOLING PUMP
1B52-428C	PWR TO AF-4021 AFP DISCHARGE TO 1HX-1B SG
1B52-428F	PWR TO 1AF-4006 AFP SUCTION FROM SERVICE WATER
1B52-428H	PWR TO C-55 (D-24) SEC BATTERY CHGR PWR SUP SELECTOR PNL
1B52-428K	SPARE
1B52-428M	PWR TO W-13B2 CR RECIRC FAN
1B52-429B	PWR TO X-17B (1FFCP-02A/02B/2FFCP-01A/01B) PAB HTPB XFMR
1B52-429DL	PWR TO XL-10 (LD-10) EMERGENCY SOUTH LIGHTING XFMR
1B52-429DR	PWR TO 1GY-04 INST MG GENERATOR SET (NOT USED)
1B52-429K	PWR TO K-5A (G-01) EDG STARTING AIR COMP MOTOR-DRIVEN
1B52-429M	PWR TO W-12C G-02 ROOM EXHAUST FAN
1B52-4210C	PWR TO 1SW-2908 CONT RECIRC HX EMERGENCY FCV
1B52-4210F	PWR TO 1SW-2880 TB COOLER SERVICE WATER INLET
1B52-4210J	PWR TO SW-2930B SFP HX OUTLET
1B52-4211B	SPARE
1B52-4211D	SPARE

·e	PB	SNP VN	PAB and CREFS Seismic Verificat	ion	Dago 52 of 172
S&A Report No. 09Q0839-R-001 Revis		K SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/8 Status: Yes Sheet 7 of 7		
	ID:1B-42 (Rev. 4)	Class: 1. Motor Control Centers			
	Description : 480V MOTOR CONTROL CENTER PAB SAFEGUARDS				
	Building : PAB	Floor	El.: 26.00	Room, Row/Col: ARE	A 5
	Manufacturer, Model, Etc. :				
	· · ·				

1B52-4211F SPARE 1B52-4211M PWR TO W-2A PAB EXHAUST STACK FAN 1B52-4212M PWR TO W-30A (F-23/F-29) PAB EXHAUST FILTER FAN

The seismic qualification records for 1B-42 is the Rev. 0, 1, 2, 3 and 4 SEWS.

This rev. 4 SEWS is SQ-002078.

Evaluated by:

CONTRACTOR OF

Drd N Centr

Date:

.

10-22-02

SQ-001702

Wisconsin Electric Power Company - Point Beach Nucler Plant SCREENING EVALUATION WORK SHEET (SEWS)		t GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 1 of 4
ID: 2B-32 (Rev. 4) Class: 1. Motor Control Ce		enters
Description : 480V MOTOR CONTROL C	ENTER PAB SAFEGUARDS	
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 6
Manufacturer, Model, Etc. :		

## SEISMIC CAPACITY VS DEMAND

1.	Elevation where equipment receives seismic input	8.00
2.	Elevation of seismic input below about 40' from grade (grade = 8.00)	N/A
3.	Equipment has fundamental frequency above about 8 Hz (est. frequency = )	N/A
4.	Capacity based on: 1.50 * Bounding Spectrum	
5.	Demand based on: 1.00 * Conservative Design Floor Response Spectra	-
	1.200 G LOG 0.016 0.17 LOG Hz 38.76 Capacity Demand	
Capaci	Tile Secolu	
Demar	ity Choir Ispectratues Labelpooling Spectrality	h
Denial	WingsjELEVATION(8)DRECTION(Horizontal)[EART] 2 LOCATION(Areas 4 & 6)BLDG-DAMP(JEQ DAMP)	HQUAKE OBE x 5%
Demar	nd 2 C:\GIP\PROJ0032\spectra.des PLANT Point Beach BUILDING Aux North and South Wings ELEVATION 8 DIRECTION Horlzontal EART  2 LOCATION Areas 4 & 6 BLDG-DAMP/IEQ DAMPI	1 HQUAKE OBE x 5%

Does capacity exceed demand?

Wisconsin Electric Power C SCREENING EVALUA	S&A Report No. 09Q0839-R-001 Rev ompany - Point Beach Nucles TION WORK SHEET (SEWS)	<i>dision</i> 1 Page 54 of 172 <b>r Plant</b> GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 2 of 4
ID: 2B-32 (Rev. 4) Class: 1. Motor Control Cer		ntrol Centers
Description : 480V MOTOR CON	TROL CENTER PAB SAFEGUAR	DS
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 6
Manufacturer, Model, Etc. :		

### **CAVEATS - BOUNDING SPECTRUM**

MCC/BS Caveat 1 - Earthquake Experience Data Base.	Yes
MCC/BS Caveat 2 - Rating of 600 V or Less.	Yes
MCC/BS Caveat 3 - Adjacent Cabinets Bolted Together.	Yes
MCC/BS Caveat 4 - Attached Weight of 100 Pounds or Less.	N/A
MCC/BS Caveat 5 - Externally Attached Items Rigidly Anchored.	N/A
MCC/BS Caveat 6 - General Configuration Similar to NEMA Standards.	Yes
MCC/BS Caveat 7 - Cutouts Not Large.	Yes
MCC/BS Caveat 8 - Doors/Buckets Secured.	Yes
MCC/BS Caveat 9 - Natural Frequency Relative to 8 Hz Limit Considered.	Yes
MCC/BS Caveat 10 - Adequate Anchorage.	Yes
MCC/BS Caveat 11 - Potential Chatter of Essential Relays Evaluated.	Yes
MCC/BS Caveat 12 - No Other Concerns	Yes

Is the intent of all the caveats met for Bounding Spectrum?

## ANCHORAGE

1. The sizes and locations of anchors have been determined.	Yes
2. Appropriate equipment characteristics have been determined (mass, CG, natural freq.,	Yes
damping, center of rotation).	
3. The type of anchorage is covered by the GIP.	Yes
4. The adequacy of the anchorage installation has been evaluated (weld quality and length,	Yes
nuts and washers, expansion anchor tightness, etc.)	······
5. Factors affecting anchorage capacity or margin of safety have been considered: embedment	Yes
length, anchor spacing, free-edge distance, concrete strength/condition, and concrete	,
cracking.	
6. For bolted anchorages, any gaps under the base are less than 1/4.	Yes
7. Factors affecting essential relays have been considered: gaps under the base, capacity	Yes
reduction for expansion anchors.	
8. The base has adequate stiffness and the effect of prying action on anchors has been	Yes
considered.	
9. The strength of the equipment base and the load path to the CG is adequate.	Yes
10. The adequacy of embedded steel, grout pads or large concrete pads have been evaluated.	Yes
11. The anchorage capacity exceeds the demand.	Yes

Are anchorage requirements met?

Yes

<u>Yes</u>

;

Wisconsin Electric Power Compa	iny - Point Beach Nucler Plant	GIP Rev 2, Corrected, 2/14/92	
SCREENING EVALUATION WORK SHEET (SEWS)		Status: Yes	
	(,	Sheet 3 of 4	
ID: 2B-32 (Rev. 4) Class: 1. Motor Control Cen		nters	
Description : 480V MOTOR CONTROL CENTER PAB SAFEGUARDS			
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 6	
Manufacturer, Model, Etc. :			

PRNP VNPAB and CREES Seismic Verification

#### **INTERACTION EFFECTS**

1. Soft targets are free from impact by nearby equipment or structures.	Yes
2. If the equipment contains sensitive relays, it is free from all impact by nearby equipment or	Yes
structures.	
3. Attached lines have adequate flexibility.	Yes
4. Overhead equipment or distribution systems are not likely to collapse.	Yes
5. No other adverse concerns were found.	Yes

Is equipment free of interaction effects?

#### IS EQUIPMENT SEISMICALLY ADEQUATE?

#### **COMMENTS**

The SRT is D. N. Carter and N. Juraydini on 2/3/00.

SUMMARY OF CHANGES TO THE COMPONENT

Remove the spare 50A breaker and replace with a 20A breaker, and install new wireway at the MCC.

SEWS Revisions

Rev 0. Original USI A-46 Seismic Verification

Rev 1. MR 91-116 - ECR 95-117. Relocation of motor starter from 1B52-4210M (1B-42) to 2B2-3213G (2B-32) - 10/09/95.

Rev 2. MR 93-041\*A - Modification of 2B-32 compartment 8H to use it for a new power supply to W-13B1 Control Room HVAC Supply Fan

Rev 3, MR 96-033 - Replacement of MCC Control Power Transformers

Rev 4. MR 98-024\*H - Water Treatment Area Redundant Isolation Valve Motor Operator Modification.

References:

[1] EPRI NP-7148-SL, "Procedure for Evaluating Nuclear Power Plant Relay Seismic Functionality"

[2] MR 98-024\*H, "Water Treatment Area Redundant Isolation Valve Motor Operator Modification"

[3] IWP 98-024\*H-02, "Water Treatment Area Isolation Valve SW-527 Modification (Electrical)"

[4] Drawing SK-MR98-024\*H, Sh. 7, "Wireway Plan & Sections", Rev. 00

[5] Drawing SK-MR98-024\*H, Sh. 8, "Wireway Support Detail", Rev. 00

#### MR 98-024\*H Description:

#### 1. MR 98-024\*H:

Replace the operator for existing gate valve SW-527 with a Limitorque SMB-00 motor operator, and relabel the valve SW-4478. The valve will be powered from a new 20A breaker which replaces the existing spare 50A

Yes

PBNP	VNPAB	and	CREFS	Seismic	Verification	

Wisconsin Electric Power Company SCREENING EVALUATION WO	-Point Beach Nucler Plant ORK SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 4 of 4	
ID: 2B-32 (Rev. 4) Class: 1. Motor Control Cen		enters	
Description : 480V MOTOR CONTROL CENTER PAB SAFEGUARDS			
Building : PAB Flo	or El. : 8.00	Room, Row/Col : AREA 6	
Manufacturer, Model, Etc. :			

breaker in MCC 2B32, and install new wireway at the MCC. A local FVR starter with transformer will be installed in the new local control panel NSW-4478 near the valve. NSW-4478 will also contain a three-position springreturn-to-center control switch for local operation, valve position indication lights, and terminal blocks. New cables will be run in existing cable travs JU06 through JU13, and FU03 through FU06. New cables will also run in new conduits. A local disconnect switch B29-SW-4478 will be installed near NSW-4478. And a new pull box PB-4478 will be installed near the valve SW-4478.

2. IWP 98-024\*H-02:

a) Assemble and install new local control panel NSW-4478.

b) Remove spare 50A breaker and replace with 20A breaker in MCC 2B32, and install new wireway at the MCC (scope of this SEWS).

c) Install new local disconnect switch B29-SW-4478.

d) Install new conduit and pull box PB-4478.

e) Run new cables for MOV SW-4478 and associated components.

Seismic Qualification Evaluation:

This modification removes the spare 50A breaker and replaces it with a 20A breaker in the MCC, and installs a new wireway at one side of the MCC. The new wireway is is supported by three (3) cantilever supports through a L2x2x1/4 angle using two (2) bolts. A N2544 Unistrut makes up the cantilever part of each suport, which attaches to a N1000 Unistrut that is secured to the wall with two (2) 3/8" Hilti bolts.

The 20A breaker is a typical component of MCCs, and therefore, is represented by the seismic experience database.

The wireway supports were tug tested and detemined to be adequately installed.

No spacial interactions are observed.

Based on the above discussion, the new breaker is acceptable.

The change does not affect the equipment weight or center of gravity. Previous anchorage evaluation is still valid.

This document is identified as SQ-001702.

Evaluated by:

Malin Junay

Date:

2/10/00 3-4-00.

PBNP VNPAB and CREFS Seismic Verification			
3	XA REPORTIO. U	JQ0639-R-001 Revision 1	GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION WORK SHEET (SEWS)			Status: Yes
CONCERNING ETAECAMON WORK CHEET (CENC)			Sheet 1 of 7
ID : C-67 ( Rev. 0 )	Class	: 20. Instrumentation	n and Control Panels and Cabinets
Description : CONTROL ROOM AIR CO	NDITIONING	G CONTROL PANEL	
Building : CB	Floor El. : 44	4.00	Room, Row/Col : Area 3
Manufacturer, Model, Etc. :			

## SEISMIC CAPACITY VS DEMAND

T				44.00
1.	1. Elevation where equipment receives seismic input 44.0			44.00
2.	Elevation of seismic inp	out below about 40' from	grade (grade = 8.00)	N/A
3.	Equipment has fundam	ental frequency above a	bout 8 Hz (est. frequency = )	N/A
4.	Capacity based on:	1.50 * Bounding Spectr	rum	
5.	Demand based on:	1.00 * Conservative De	sign Floor Response Spectra	
		1.655 G LOG		
0.17 $106$ Hz $36.63$				
Capacity Demand				
	File		Record	
Capac	ity J:\APPDATA\GIPF	PER2\GIP\spectra.des	Label Bounding Spectrum	
Demar	nd 1 J:\APPDATA\GIPF	PER2\PROJ0032\spectra.des	PLANT/Point Beach/BUILDING/Control Building/ELEVATION/44/DIRECTION/Horizontal/EA x 2  LOCATION/Area 3/BLDG-DAMP//EQ DAMP/59	ARTHQUAKE OBE %
Demar	nd 2 J:\APPDATA\GIPF	PER2\PROJ0032\spectra.des	PLANT/Point Beach/BUILDING/Control Building/ELEVATION/44/DIRECTION/Horizontal/EA x 2 [LOCATION/Area 3]BLDG-DAMP/JEQ DAMP/59	\rthquake obe %

Does capacity exceed demand?

.

PBNP VNPAB and CREFS Seismic Verification			
S&A Report No. 09Q0839-R-001 Revision 1			Page 58 of 172
			GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION WORK SHEET (SEWS)			Status: Yes
		,	Sheet 2 of 7
ID: C-67 (Rev. 0)	Class : 20.	Instrumentatio	n and Control Panels and Cabinets
Description : CONTROL ROOM AIR CO	DNDITIONING COL	NTROL PANEL	
Building : CB	Floor El. : 44.00		Room, Row/Col : Area 3
Manufacturer, Model, Etc. :			

# CAVEATS - BOUNDING SPECTRUM

and the second distance of the second s
Yes
N/A
N/A
Yes
N/A
N/A
Yes
Yes
Yes
N/A
Yes

Is the intent of all the caveats met for Bounding Spectrum?

Yes

# ANCHORAGE

1. The sizes and locations of anchors have been determined.		
2. Appropriate equipment characteristics have been determined (mass, CG, natural	Yes	
freq., damping, center of rotation).		
3. The type of anchorage is covered by the GIP.	Yes	
4. The adequacy of the anchorage installation has been evaluated (weld quality and	Yes	
length, nuts and washers, expansion anchor tightness, etc.)		
5. Factors affecting anchorage capacity or margin of safety have been considered:	Yes	
embedment length, anchor spacing, free-edge distance, concrete strength/condition,		
and concrete cracking.		
6. For bolted anchorages, any gaps under the base are less than 1/4.	Yes	
7. Factors affecting essential relays have been considered: gaps under the base,		
capacity reduction for expansion anchors.		
8. The base has adequate stiffness and the effect of prying action on anchors has been	Yes	
considered.		
9. The strength of the equipment base and the load path to the CG is adequate.	Yes	
10. The adequacy of embedded steel, grout pads or large concrete pads have been	Yes	
evaluated.		
11. The anchorage capacity exceeds the demand.	Yes	

Are anchorage requirements met?

SCREENING EVALUATION V	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 3 of 7			
ID: C-67 (Rev. 0)	Class : 20. Instrumentat	on and Control Panels and Cabinets		
Description : CONTROL ROOM AIR CONDITIONING CONTROL PANEL				
Building : CB	Floor El. : 44.00	Room, Row/Col : Area 3		
Manufacturer Model Etc.		2		

## **INTERACTION EFFECTS**

1. Soft targets are free from impact by nearby equipment or structures.	Yes
2. If the equipment contains sensitive relays, it is free from all impact by nearby equipment or	N/A
structures.	
3. Attached lines have adequate flexibility.	Yes
4. Overhead equipment or distribution systems are not likely to collapse.	Yes
5. No other adverse concerns were found.	Yes

## Is equipment free of interaction effects?

## IS EQUIPMENT SEISMICALLY ADEQUATE?

### COMMENTS

Walkdown Engineers: W. Djordjevic & P. A. Gazda (09/03/09)

Panel C-67 controls CREFS HVAC room. It is a NEMA Hoffman box 66"H x 30"W x 12"D. It is anchored at the top with 2 -3/8" CEAs to concrete wall and secured to a knee-braced frame which in turn is anchored to concrete wall. This panel estimated weight is 500 lbs based on a density of 35 pcf and it is deemed rigid (f1> 33Hz). Each 3/8" anchor can resist about 1500 lbs so the gross seismic capacity is 6g ignoring the bottom anchorage. Therefore, Panel C-67 is declared seismically adequate.

No credible potential seismic interaction was noted.

Evaluated by:

W. Diordievic, PE

P.A.Gazda, PE

Attachment: Walkdown Pictures

9/03/2009

9/03/2009

Yes

Yes

Date:

Page 59 of 172

SCREENING EVALUATION WO	ORK SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 4 of 7
ID: C-67 (Rev. 0)	Class : 20. Instrumentation and Control Panels and Cabine	
Description : CONTROL ROOM AIR CON	DITIONING CONTROL PANE	L
Building : CB F	loor El. : 44.00	Room, Row/Col : Area 3
Manufacturer, Model, Etc. :		



Figure 1: Elevation View

S&A Report No. 09Q0839-R-001 Revision 1		1 Page 61 0f 1/2
		GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION WORK SHEET (SEWS)		Status: Yes
	, , , , , , , , , , , , , , , , , , ,	Sheet 5 of 7
ID : C-67 ( Rev. 0 )	Class : 20. Instrumentat	ion and Control Panels and Cabinets
Description : CONTROL ROOM AIR CC	NDITIONING CONTROL PANE	L
Building : CB	Floor El. : 44.00	Room, Row/Col : Area 3
Manufacturer, Model, Etc. :		



Figure 2: Internal View

S	&A Report No. 09Q0839-R-001 Revision 1	Page 62 of 172	
SCREENING EVALUATION WORK SHEET (SEWS)		GIP Rev 2, Corrected, 2/14/92	
		Status: Yes	
	······	Sheet 6 of 7	
D: C-67 (Rev. 0) Class : 20. Instrumentatio		n and Control Panels and Cabinets	
Description : CONTROL ROOM AIR CONDITIONING CONTROL PANEL			
Building : CB	Floor El. : 44.00	Room, Row/Col : Area 3	
Manufacturer Model Etc.			



Figure 3: Knee-braced Frame to Wall

Page	63	of	172	

SCREENING EVALUATION	WORK SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 7 of 7
ID: C-67 (Rev. 0)	Class: 20. Instrumentation	n and Control Panels and Cabinets
Description : CONTROL ROOM AIR CC	NDITIONING CONTROL PANEL	
Building : CB	Floor El. : 44.00	Room, Row/Col : Area 3
Manufacturer, Model, Etc. :		



Figure 4: Knee-braced Frame Connection
· PE	3NP VNPAB and CREFS Seismic Verit	ication
Sa	A Report No. 09Q0839-R-001 Revisio	n 1 Page 64 of 172
		GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION WORK SHEET (SEWS)		Status: No
		Sheet 1 of 8
ID:W-13B1(Rev. 0)	Class: 9. Fans	
Description : CONTROL ROOM RECIR	C FAN	
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		

### SEISMIC CAPACITY VS DEMAND

1.	Elevation where equipment receives seismic ir	iput	60.00
2.	2. Elevation of seismic input below about 40' from grade (grade = 8.00) N/A		
3.	Equipment has fundamental frequency above	about 8 Hz (est. frequency = )	N/A
4.	Capacity based on: 1.50 * Bounding Spec	trum	
5.	Demand based on: 1.00 * Conservative D	esign Floor Response Spectra	
1.931 G LOG LOG 0.009 0.17 LOG Hz 38.61 Capacity Demand			
Canac	ty	LabellBounding Spectrum	
Demar	d 1 J:\APPDATA\GIPPER2\PROJ0032\spectra.des	PLANT Point Beach BUILDING Control Building ELEVATION 60 DIRECTION Horizontal EA x 2 LOCATION Area 3 BLDG-DAMP EQ DAMP 59	ARTHQUAKE OBE %
Demar	d 2 J:\APPDATA\GIPPER2\PROJ0032\spectra.des	PLANT Point Beach BUILDING Control Building ELEVATION 60 DIRECTION Horizontal EA x 2  LOCATION Area 3 BLDG-DAMP  EQ DAMP 59	ARTHQUAKEJOBE %

Does capacity exceed demand?

PBNP VNPAB and CREFS Seismic Verification S&A Report No. 0900839-R-001 Revision 1 Page 65 of 172		
SCREENING EVALUATION WORK SHEET (SEWS)		GIP Rev 2, Corrected, 2/14/92 Status: No Sheet 2 of 8
ID: W-13B1 (Rev. 0)	Class: 9. Fans	
Description : CONTROL ROOM RECIRC FAN		
Building : CB Floor El. : 60.00		Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		

# **CAVEATS - BOUNDING SPECTRUM**

FAN/BS Caveat 1 - Earthquake Experience Equipment Class.	Yes
FAN/BS Caveat 2 - Drive Motor and Fan Mounted on Common Base.	Yes
FAN/BS Caveat 3 - Long Shafts Supported at Fan and at Motor.	Yes
FAN/BS Caveat 4 - No Possibility of Excessive Duct Distortion Causing Binding or	Yes
Misalignment of Fan.	
FAN/BS Caveat 5 - Base Vibration Isolation System Checked.	No
FAN/BS Caveat 6 - Sufficient Slack and Flexibility of Attached Lines.	Yes
FAN/BS Caveat 7 - Adequate Anchorage.	
FAN/BS Caveat 8 - No Other Concerns	

Is the intent of all the caveats met for Bounding Spectrum?

ANCHORAGE

1. The sizes and locations of anchors have been determined.	Yes
2. Appropriate equipment characteristics have been determined (mass, CG, natural	Yes
freq., damping, center of rotation).	
3. The type of anchorage is covered by the GIP.	Yes
4. The adequacy of the anchorage installation has been evaluated (weld quality and	No
length, nuts and washers, expansion anchor tightness, etc.)	
5. Factors affecting anchorage capacity or margin of safety have been considered:	Yes
embedment length, anchor spacing, free-edge distance, concrete strength/condition,	
and concrete cracking.	
6. For bolted anchorages, any gaps under the base are less than 1/4.	Yes
7. Factors affecting essential relays have been considered: gaps under the base,	N/A
capacity reduction for expansion anchors.	
8. The base has adequate stiffness and the effect of prying action on anchors has been	Yes
considered.	
9. The strength of the equipment base and the load path to the CG is adequate.	Yes
10. The adequacy of embedded steel, grout pads or large concrete pads have been	Yes
evaluated.	
11. The anchorage capacity exceeds the demand.	No

Are anchorage requirements met?

.

<u>No</u>

SCREENING EVALUATION WORK SHEET (SEWS)		GIP Rev 2, Corrected, 2/14/92 Status: No Sheet 3 of 8
ID:W-13B1(Rev. 0) Class:9. Fans		
Description : CONTROL ROOM RECIRC FAN		
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		

#### INTERACTION EFFECTS

1. Soft targets are free from impact by nearby equipment or structures.	Yes
2. If the equipment contains sensitive relays, it is free from all impact by nearby equipment or	N/A
structures.	
3. Attached lines have adequate flexibility.	Yes
4. Overhead equipment or distribution systems are not likely to collapse.	Yes
5. No other adverse concerns were found.	Yes

Is equipment free of interaction effects?

### IS EQUIPMENT SEISMICALLY ADEQUATE?

#### **COMMENTS**

Walkdown Engineers: W. Djordjevic & P. A. Gazda (09/04/09)

#### Ref. 1. Dwg No. P6118-M37-078-2

W13B1 & B2 are outliers. They are located on rubber vibration isolators beneath C4x1.5" rails. The motors are restrained by z-clips and/or "top hat" clips longitudinally (axial w.r.t. direction of channel) and vertically (1/4" thick) but not transversely. The fans have no restraint in any direction. The units rest directly on the concrete floor inside each plenum. There are existing embedded channels over which the rails are mounted and they are secured by ½" shells. The top hats and z-clips are also secured by ½" shells. The shells in W13B1 & B2 are corroded. The conceptual fix is to run an angle along side the channels of both the fans and motors to capture them transversely and to put z-clips at the ends of the fan rail using the existing shells (replace studs) in a manner similar to the motor configurations.

The plena housings are estimated to be 1/8" thickness and they have internal anchorage of 3/8" concrete expansion anchors at approximately 20" centers. The W13B1 & B2 housing is 68"H x 93"D x 13.5 ft long. These plena are light and react relatively small duct reaction loads so they clearly cannot overturn and have sufficient anchorage to resist base shear so they are seismically acceptable.

No adverse potential interactions are noted since the fans are fully contained within their respective plena.

The fans are outliers for three reasons:

- 1. The fans are supported on vibration isolators which are unacceptable.
- 2. The floor response spectrum exceeds the bounding spectrum below approximatley 4 Hz.
- 3. Some of the anchorage shells are corroded.

No

PBNP VNPAB and CREFS Seismic Verification				
		S&A Report No. 09Q0839-R-001 Revision	1	Page 67 of 172
	•		GIP Rev 2, Correc	ted, 2/14/92
SCREEN	ING EVALUATION	WORK SHEET (SEWS)	Status: No	
OUNCER		monar oneer (oerro)	Sheet 4 of 8	
ID : W-13B1 ( Re	ev. 0)	Class: 9. Fans		
Description : CO	NTROL ROOM RECI	RC FAN		
Building : CB		Floor El. : 60.00	Room, Row/Col : A	AREA 3
Manufacturer, Mo	odel, Etc. :			
Evaluated by:	W.Djordjevic, PE	<b></b>	Date:	9/04/2009
	P.A.Gazda, PE G. li . Ingohr			9/04/2009

Attachment: Walkdown Pictures

Page 68 of 172

SCREENING EVALUATION WORK SHEET (SEWS)		GIP Rev 2, Corrected, 2/14/92 Status: No Sheet 5 of 8
ID: W-13B1 (Rev. 0) Class: 9. Fans		
Description : CONTROL ROOM RECIRC	C FAN	
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		

1.1.1.1

Figure 1: Motor anchorage showing corrosion

Page 69 of 172

SCREENING EVALUATION	WORK SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/92 Status: No Sheet 6 of 8
ID : W-13B1 ( Rev. 0 ) Class : 9. Fans		
Description : CONTROL ROOM RECIR	C FAN	
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		



### Figure 2: Fan anchorage showing corrosion

PBNP VNPAB a	and CREFS Seismic V	'erification
S&A Report No.	09Q0839-R-001 Rev	ision 1

Page 70 of 172

SCREENING EVALUATION WORK SHEET (SEWS)		GIP Rev 2, Corrected, 2/14/92 Status: No Sheet 7 of 8
ID: W-13B1 (Rev. 0) Class: 9. Fans		
Description : CONTROL ROOM RECIRC FAN		
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3
Manufacturer Model Etc.		



# Figure 3: Fan rail on isolator

PBNP VNPAB and CREFS Seismic Venilication		
S	&A Report No. 09Q0839-R-001 Revision	n 1 Page 71 of 172
		GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION	SCREENING EVALUATION WORK SHEET (SEWS)	
SCREENING EVALUATION WORK SHEET (DEWO)		Sheet 8 of 8
ID : W-13B1 ( Rev. 0 ) Class : 9. Fans		
Description : CONTROL ROOM RECIRC FAN		
Building : CB Floor El. : 60.00		Room, Row/Col : AREA 3
Manufacturer Model Etc.		



Figure 4: Fan and motor inside plenum

PBNP VNPAB and CREFS Seismic Verification		
SCREENING EVALUATION WORK SHEET (SEWS)		GIP Rev 2, Corrected, 2/14/92 Status: No Sheet 1 of 8
ID : W-13B2 ( Rev. 0 )	Class: 9. Fans	
Description : CONTROL ROOM RECIR	C FAN	
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		

## SEISMIC CAPACITY VS DEMAND

1 [	Flevatio	on where equipment receives seismic inc	nut l	60.00
2 Elevation of seismic input below about 40' from grade (grade = $8.00$ ) N/		N/A		
3	Fauipr	pent has fundamental frequency above a	bout 8 Hz (est. frequency = )	N/A
4	Capaci	ty based on: 1.50 * Bounding Spectr	um	
5.	Deman	d based on: 1.00 * Conservative De	sign Floor Response Spectra	
1.931 G LOG 0.009 UCG 0.17 LOG Hz 38.61 Capacity Demand				
Capaci	itv	J:\APPDATA\GIPPER2\GIP\spectra.des	Label Bounding Spectrum	
Deman	Demand 1 J:\APPDATA\GIPPER2\PROJ0032\spectra.des PLANT Point Beach BUILDING Control Building ELEVATION 60 DIRECTION Horizontal EARTHQUAKE O x 2  LOCATION Area 3 BLDG-DAMP [EQ DAMP]5%		ARTHQUAKE OBE	
Deman	nd 2	J:\APPDATA\GIPPER2\PROJ0032\spectra.des	PLANT Point Beach BUILDING Control Building ELEVATION 60 DIRECTION Horizontal EA x 2  LOCATION Area 3 BLDG-DAMP  EQ DAMP 59	ARTHQUAKE OBE %

Does capacity exceed demand?

	D
S&A Report No. 09Q0839-R-001 Revision 1	Page 73 of 172
GIP Rev 2, Correc	ted, 2/14/92
SCREENING EVALUATION WORK SHEET (SEWS) Status: No	
Sheet 2 of 8	
ID : W-13B2 (Rev. 0) Class : 9. Fans	
Description : CONTROL ROOM RECIRC FAN	
Building : CB Floor El. : 60.00 Room, Row/Col : A	AREA 3
Manufacturer, Model, Etc. :	

### CAVEATS - BOUNDING SPECTRUM

Yes
Yes
Yes
Yes
No
Yes
No
No

Is the intent of all the caveats met for Bounding Spectrum?

# ANCHORAGE

1. The sizes and locations of anchors have been determined.	Yes
2. Appropriate equipment characteristics have been determined (mass, CG, natural	Yes
freq., damping, center of rotation).	
3. The type of anchorage is covered by the GIP.	Yes
4. The adequacy of the anchorage installation has been evaluated (weld quality and	No
length, nuts and washers, expansion anchor tightness, etc.)	
5. Factors affecting anchorage capacity or margin of safety have been considered:	Yes
embedment length, anchor spacing, free-edge distance, concrete strength/condition,	
and concrete cracking.	
6. For bolted anchorages, any gaps under the base are less than 1/4.	Yes
7. Factors affecting essential relays have been considered: gaps under the base,	N/A
capacity reduction for expansion anchors.	
8. The base has adequate stiffness and the effect of prying action on anchors has been	Yes
considered.	
9. The strength of the equipment base and the load path to the CG is adequate.	Yes
10. The adequacy of embedded steel, grout pads or large concrete pads have been	Yes
evaluated.	
11. The anchorage capacity exceeds the demand.	No

Are anchorage requirements met?

<u>No</u>

GIP Rev 2, Corrected, 2/14/92 Status: No SCREENING EVALUATION WORK SHEET (SEWS) Sheet 3 of 8 ID: W-13B2 (Rev. 0) Class: 9. Fans Description : CONTROL ROOM RECIRC FAN Room, Row/Col : AREA 3 Building : CB Floor El. : 60.00 Manufacturer, Model, Etc. :

### INTERACTION EFFECTS

1. Soft targets are free from impact by nearby equipment or structures.	Yes
2. If the equipment contains sensitive relays, it is free from all impact by nearby equipment or	N/A
structures.	
3. Attached lines have adequate flexibility.	Yes
4. Overhead equipment or distribution systems are not likely to collapse.	Yes
5. No other adverse concerns were found.	Yes

Is equipment free of interaction effects?

### IS EQUIPMENT SEISMICALLY ADEQUATE?

#### COMMENTS

Walkdown Engineers: W. Djordjevic & P. A. Gazda (09/04/09)

#### Ref. 1. Dwg No. P6118-M37-078-2

W13B1 & B2 are outliers. They are located on rubber vibration isolators beneath C4x1.5" rails. The motors are restrained by z-clips and/or "top hat" clips longitudinally (axial w.r.t. direction of channel) and vertically (1/4" thick) but not transversely. The fans have no restraint in any direction. The units rest directly on the concrete floor inside each plenum. There are existing embedded channels over which the rails are mounted and they are secured by 1/2" shells. The top hats and z-clips are also secured by 1/2" shells. The shells-in-W13B1 & B2 are corroded. The conceptual fix is to run an angle along side the channels of both the fans and motors to capture them transversely and to put z-clips at the ends of the fan rail using the existing shells (replace studs) in a manner similar to the motor configurations.

The plena housings are estimated to be 1/8" thickness and they have internal anchorage of 3/8" concrete expansion anchors at approximately 20" centers. The W13B1 & B2 housing is 68"H x 93"D x 13.5 ft long. These plena are light and react relatively small duct reaction loads so they clearly cannot overturn and have sufficient anchorage to resist base shear so they are seismically acceptable.

No adverse potential interactions are noted since the fans are fully contained within their respective plena.

The fans are outliers for three reasons:

- 1. The fans are supported on vibration isolators which are unacceptable.
- 2. The floor response spectrum exceeds the bounding spectrum below approximatley 4 Hz.
- 3. Some of the anchorage shells are corroded.

No

Yes

Page 74 of 172

PBNP VNPAB and CREFS Seismic Verification				
		S&A Report No. 09Q0839-R-001 Revision	<u>11</u>	Page 75 of 172
			GIP Rev 2, Correct	ed, 2/14/92
SCREEN	ING EVALUATION	WORK SHEET (SEWS)	Status: No	
JUNCEN			Sheet 4 of 8	
ID : W-13B2 ( Re	ev. 0)	Class: 9. Fans	·····	
Description : CO	NTROL ROOM REC	RC FAN		
Building : CB		Floor El. : 60.00	Room, Row/Col : A	REA 3
Manufacturer, M	odel, Etc. :			
Evaluated by:	W. Djordjevic, PE	-	Date:	9/04/2009
	P. A. Gazda, PE C. li . Maych	· · · ·		9/04/2009

Attachment: Walkdown Pictures

.

PBNP VNPAB and CREFS Seismic Verification
S&A Report No. 09Q0839-R-001 Revision 1

Page 76 of 172

SCREENING EVALUATION WORK SHEET (SEWS)		GIP Rev 2, Corrected, 2/14/92 Status: No Sheet 5 of 8
ID : W-13B2 (Rev. 0) Class : 9. Fans		
Description : CONTROL ROOM RECIR	C FAN	
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		

Figure 1: Motor anchorage showing corrosion

Page 77 of 172 GIP Rev 2, Corrected, 2/14/92

SCREENING EVALUATION	Status: No Sheet 6 of 8	
ID : W-13B2 ( Rev. 0 )	Class: 9. Fans	
Description : CONTROL ROOM RECIR	C FAN	
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3

Manufacturer, Model, Etc. :



S&A Report No. 09Q0839-R-001 Revision 1		
		GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION WORK SHEET (SEWS)		Status: No
		Sheet 7 of 8
ID: W-13B2(Rev. 0)	Class: 9. Fans	
Description : CONTROL ROOM RECIR	C FAN	
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		



### Figure 3: Fan rail on isolator

PBNP VNPAB and CREFS Seismic Verification			
S	&A Report No. 09Q0839-R-001 Revision	1 Page 79 of 172	
		GIP Rev 2, Corrected, 2/14/92	
SCREENING EVALUATION WORK SHEET (SEWS)		Status: No	
		Sheet 8 of 8	
ID : W-13B2 ( Rev. 0 )	Class: 9. Fans		
Description : CONTROL ROOM RECIRC FAN			
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3	
Manufacturer Medel Eta :			



S&	&A Repor	t No. 09Q0839-R-001 Revision 1	Page 80 of 172
			GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION WORK SHEET (SEWS)		Status: No	
		,	Sheet 1 of 8
ID: W-14A (Rev. 0)		Class: 9. Fans	
Description : F-16 CONTROL ROOM CI	HARCO	DAL FILTER FAN	
Building : CB	Floor E	El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :			

### SEISMIC CAPACITY VS DEMAND

-

it 60.00	1. Elevation where equipment receives seismic input 60.0		
rade (grade = 8.00) N/A	2. Elevation of seismic input below about 40' from grade (grade = 8.00) N//		
out 8 Hz (est. frequency = ) N/A	3. Equipment has fundamental frequency above a		
m	4. Capacity based on: 1.50 * Bounding Spect		
ign Floor Response Spectra	5. Demand based on: 1.00 * Conservative De		
1.931 G LOG 0.009 0.17 LOG Hz 38.61 Capacity Demand			
Record			
PLANTIPoint BeachIBUILDINGIControl	Demand 1 J:\APPDATA\GIPPER2\PROJ0032\snectra des		
Building ELEVATION 60 DIRECTION Horizontal EARTHQUAKE OBE x 2  LOCATION Area 3 BLDG-DAMP  EQ DAMP 5%			
PLANT [Point Beach   BUILDING   Control	Demand 2 J:\APPDATA\GIPPER2\PROJ0032\spectra.des		
Building ELEVATION 60 DIRECTION Horizontal EARTHQUAKE OBE			
Juit 8 Hz (est. frequency = )       N/A         m	3.       Equipment has fundamental frequency above a         4.       Capacity based on:       1.50 * Bounding Spectries         5.       Demand based on:       1.00 * Conservative Demand         Image: Solor of Sol		

Does capacity exceed demand?

No

PBNP VNPAB and CREFS Seismic Verification			
S	&A Report No. 09Q0839-R-001 Revisio	on 1 Page 81 of 172	
		GIP Rev 2, Corrected, 2/14/92	
SCREENING EVALUATION WORK SHEET (SEWS)		Status: No	
ID: W-14A (Rev. 0)	Class: 9. Fans		
Description : F-16 CONTROL ROOM C	HARCOAL FILTER FAN		
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3	
Manufacturer, Model, Etc. :			

### CAVEATS - BOUNDING SPECTRUM

FAN/BS Caveat 1 - Earthquake Experience Equipment Class.	Yes
FAN/BS Caveat 2 - Drive Motor and Fan Mounted on Common Base.	Yes
FAN/BS Caveat 3 - Long Shafts Supported at Fan and at Motor.	Yes
FAN/BS Caveat 4 - No Possibility of Excessive Duct Distortion Causing Binding or	Yes
Misalignment of Fan.	
FAN/BS Caveat 5 - Base Vibration Isolation System Checked.	No
FAN/BS Caveat 6 - Sufficient Slack and Flexibility of Attached Lines.	Yes
FAN/BS Caveat 7 - Adequate Anchorage.	No
FAN/BS Caveat 8 - No Other Concerns	Yes

Is the intent of all the caveats met for Bounding Spectrum?

## ANCHORAGE

1. The sizes and locations of anchors have been determined.	Yes	
2. Appropriate equipment characteristics have been determined (mass, CG, natural	Yes	
freq., damping, center of rotation).		
3. The type of anchorage is covered by the GIP.	Yes	
4. The adequacy of the anchorage installation has been evaluated (weld quality and	Yes	
length, nuts and washers, expansion anchor tightness, etc.)		
5. Factors affecting anchorage capacity or margin of safety have been considered:	Yes	
embedment length, anchor spacing, free-edge distance, concrete strength/condition,		
and concrete cracking.		
6. For bolted anchorages, any gaps under the base are less than 1/4.		
7. Factors affecting essential relays have been considered: gaps under the base,	N/A	
capacity reduction for expansion anchors.		
8. The base has adequate stiffness and the effect of prying action on anchors has been	Yes	
considered.		
9. The strength of the equipment base and the load path to the CG is adequate.		
10. The adequacy of embedded steel, grout pads or large concrete pads have been		
evaluated.		
11. The anchorage capacity exceeds the demand.	No	

Are anchorage requirements met?

No

# PBNP VNPAB and CREFS Seismic Verification

Si	n 1 Page 82 of 172		
		GIP Rev 2, Corrected, 2/14/92	
SCREENING EVALUATION WORK SHEET (SEWS)		Status: No	
		Sheet 3 of 8	
ID: W-14A (Rev. 0)	Class: 9. Fans		
Description : F-16 CONTROL ROOM CHARCOAL FILTER FAN			
Buildina : CB	Floor El. : 60.00	Room, Row/Col : AREA 3	
Manufacturer, Model, Etc. :			

### INTERACTION EFFECTS

1. Soft targets are free from impact by nearby equipment or structures.	Yes
2. If the equipment contains sensitive relays, it is free from all impact by nearby equipment or	N/A
structures.	
3. Attached lines have adequate flexibility.	Yes
4. Overhead equipment or distribution systems are not likely to collapse.	Yes
5 No other adverse concerns were found.	Yes

Is equipment free of interaction effects?

#### IS EQUIPMENT SEISMICALLY ADEQUATE?

#### COMMENTS

Walkdown Engineers: W. Djordjevic & P. A. Gazda (09/04/09)

Ref. 1. Dwg No. P6118-M37-080-1, Sh 3 of 3

W14A & B are outliers. They are located on rubber vibration isolators beneath C4x1.5" rails. The motors are restrained by z-clips and/or "top hat" clips longitudinally (axial w.r.t. direction of channel) and vertically (1/4" thick) but not transversely. The fans have no restraint in any direction. The units rest directly on the concrete floor inside each plenum. There are existing embedded channels over which the rails are mounted and they are secured by ½" shells. The top hats and z-clips are also secured by ½" shells. The conceptual fix is to run an angle along side the channels of both the fans and motors to capture them transversely and to put z-clips at the ends of the fan rail using the existing shells (replace studs) in a manner similar to the motor configurations.

The plena housings are estimated to be 1/8" thickness and they have internal anchorage of 3/8" concrete expansion anchors at approximately 20" centers. The W14A&B housing dimension is 68"H x 62"D x 20 ft long. These plena are light and react relatively small duct reaction loads so they clearly cannot overturn and have sufficient anchorage to resist base shear so they are seismically acceptable.

No adverse potential interactions are noted since the fans are fully contained within their respective plena.

The fans are outliers for two reasons:

1. The fans are supported on vibration isolators which are unacceptable.

2. The floor response spectrum exceeds the bounding spectrum below approximatley 4 Hz.

No

	P	BNP VNPAB and CREFS Seismic V	erification	
	S	&A Report No. 09Q0839-R-001 Rev	ision 1	Page 83 of 172
			GIP Rev 2, Correct	ed, 2/14/92
SCREEN	ING EVALUATION	WORK SHEET (SEWS)	Status: No	
JUREEN	ING EVALUATION	WORR SHEET (GEWO)	Sheet 4 of 8	
ID : W-14A ( Rev	. 0)	Class : 9. Fans		
Description : F-1	6 CONTROL ROOM C	HARCOAL FILTER FAN		
Building : CB		Floor El. : 60.00	Room, Row/Col : A	REA 3
Manufacturer, Mo	odel, Etc. :			
Evaluated by:	W. Djordjevic, PE		Date:	9/04/2009
	W Burt	~		
	P. A. Gazda, PE			9/04/2009
	C.U. Mych			

Attachment: Walkdown Pictures

PBNP VNPAB and CREFS Seismic Verification S&A Report No. 09Q0839-R-001 Revision 1 Page 84 of 172			
		GIP Rev 2, Corrected, 2/14/92	
SCREENING EVALUATION WORK SHEET (SEWS)		Status: No	
		Sheet 5 of 8	
ID : W-14A ( Rev. 0 )	Class: 9. Fans		
Description : F-16 CONTROL ROOM CHARCOAL FILTER FAN			
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3	
Manufacturer, Model, Etc. :			



Figure 1: Motor Anchorage

PBNP VNPAB and CREFS Seismic Verification				
Se	&A Report No. 09Q0839-R-001 Revision	1 Page 05 01 172		
		GIP Rev 2, Corrected, 2/14/92		
SCREENING EVALUATION WORK SHEET (SEWS)		Status: No		
		Sheet 6 of 8		
ID: W-14A (Rev. 0) Class: 9. Fans				
Description : F-16 CONTROL ROOM CHARCOAL FILTER FAN				
Building : CB Floor El. : 60.00		Room, Row/Col : AREA 3		
Manufacturer Model Etc.		· · · · · · · · · · · · · · · · · · ·		



Figure 2: Frame and motor anchorage

PBNP VNPAB and CREFS Seismic Verification S&A Report No. 09Q0839-R-001 Revision 1 Page 86 of 172		
		GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION WORK SHEET (SEWS)		Status: No
		Sheet 7 of 8
ID: W-14A (Rev. 0)	Class : 9. Fans	
Description : F-16 CONTROL ROOM CHARCOAL FILTER FAN		
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		



Figure 3: Plenum anchorage

Page 87 of 172

0

0

OID D

SCREENING EVALUATION	Status: No Sheet 8 of 8	
ID: W-14A (Rev. 0)	Class: 9. Fans	
Description : F-16 CONTROL ROOM C	HARCOAL FILTER FAN	
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		



Figure 4: Motor rail end restraints

Dee	- 00	-5	470
Pag	e 88	OT	172

SCREENING EVALUATION V	VORK SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/92 Status: No Sheet 1 of 8
ID : W-14B ( Rev. 0 ) Class : 9. Fans		
Description : F-16 CONTROL ROOM CH	ARCOAL FILTER FAN	
Building : CB Floor El. : 60.00		Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		

#### SEISMIC CAPACITY VS DEMAND

1	Elevation where equir	ment receives seismic inr	but	60.00
2.	Elevation of seismic in	put below about 40' from	grade (grade = 8.00)	N/A
3.	Equipment has funda	mental frequency above a	bout 8 Hz (est. frequency = )	N/A
4.	Capacity based on:	1.50 * Bounding Spectr	um	
5.	Demand based on:	1.00 * Conservative De	sign Floor Response Spectra	
	· · ·	1.931 G LOG 0.009 0.17 Ca	LOG Hz 38.61 apacity Demand	
			Depart	
Canaci		PER2\GIP\spectra des	LabellBounding Spectrum	
Demar	nd 1 J:\APPDATA\GIF	PPER2\PROJ0032\spectra.des	PLANT/Point Beach/BUILDING/Control Building/ELEVATION/60/DIRECTION/Horizontal/EA x 2  LOCATION/Area 3 BLDG-DAMP/JEQ DAMP/59	ARTHQUAKE OBE %
Demar	nd 2 J:\APPDATA\GIF	PPER2\PROJ0032\spectra.des	PLANT Point Beach BUILDING Control Building ELEVATION 60 DIRECTION Horizontal EA x 2  LOCATION Area 3 BLDG-DAMP  EQ DAMP 59	ARTHQUAKE OBE %

Does capacity exceed demand?

No

,

PBNP VNPAB and CREFS Seismic Verification S&A Report No. 09Q0839-R-001 Revision 1 Page 89 of 17				
SCREENING EVALUATION WORK SHEET (SEWS)		GIP Rev 2, Corrected, 2/14/92 Status: No Sheet 2 of 8		
ID: W-14B (Rev. 0)	Class: 9. Fans			
Description : F-16 CONTROL ROOM C	HARCOAL FILTER FAN			
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3		
Manufacturer, Model, Etc. :				

# CAVEATS - BOUNDING SPECTRUM

FAN/BS Caveat 1 - Earthquake Experience Equipment Class.	Yes
FAN/BS Caveat 2 - Drive Motor and Fan Mounted on Common Base.	Yes
FAN/BS Caveat 3 - Long Shafts Supported at Fan and at Motor.	Yes
FAN/BS Caveat 4 - No Possibility of Excessive Duct Distortion Causing Binding or	Yes
Misalignment of Fan.	
FAN/BS Caveat 5 - Base Vibration Isolation System Checked.	No
FAN/BS Caveat 6 - Sufficient Slack and Flexibility of Attached Lines.	Yes
FAN/BS Caveat 7 - Adequate Anchorage.	No
FAN/BS Caveat 8 - No Other Concerns	Yes

Is the intent of all the caveats met for Bounding Spectrum?

## ANCHORAGE

1. The sizes and locations of anchors have been determined.	Yes
2. Appropriate equipment characteristics have been determined (mass, CG, natural	Yes
freq., damping, center of rotation).	
3. The type of anchorage is covered by the GIP.	Yes
4. The adequacy of the anchorage installation has been evaluated (weld quality and	Yes
length, nuts and washers, expansion anchor tightness, etc.)	
5. Factors affecting anchorage capacity or margin of safety have been considered:	Yes
embedment length, anchor spacing, free-edge distance, concrete strength/condition,	
and concrete cracking.	
6. For bolted anchorages, any gaps under the base are less than 1/4.	Yes
7. Factors affecting essential relays have been considered: gaps under the base,	N/A
capacity reduction for expansion anchors.	·
8. The base has adequate stiffness and the effect of prying action on anchors has been	Yes
considered.	
9. The strength of the equipment base and the load path to the CG is adequate.	Yes
10. The adequacy of embedded steel, grout pads or large concrete pads have been	
evaluated.	
11. The anchorage capacity exceeds the demand.	No

Are anchorage requirements met?

<u>No</u>

St	A Report No. 09Q0839-R-001 Revision 1	Page 90 of 172
		GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION WORK SHEET (SEWS)		Status: No
		Sheet 3 of 8
ID: W-14B (Rev. 0)	Class: 9. Fans	
Description : F-16 CONTROL ROOM C	HARCOAL FILTER FAN	
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :	1	

#### INTERACTION EFFECTS

1. Soft targets are free from impact by nearby equipment or structures.	Yes
2. If the equipment contains sensitive relays, it is free from all impact by nearby equipment or	N/A
structures.	
3. Attached lines have adequate flexibility.	Yes
4. Overhead equipment or distribution systems are not likely to collapse.	Yes
5. No other adverse concerns were found.	Yes

Is equipment free of interaction effects?

#### IS EQUIPMENT SEISMICALLY ADEQUATE?

#### COMMENTS

Walkdown Engineers: W. Djordjevic & P. A. Gazda (09/04/09)

Ref. 1. Dwg No. P6118-M37-080-1, Sh 3 of 3

W14A & B are outliers. They are located on rubber vibration isolators beneath C4x1.5" rails. The motors are restrained by z-clips and/or "top hat" clips longitudinally (axial w.r.t. direction of channel) and vertically (1/4" thick) but not transversely. The fans have no restraint in any direction. The units rest directly on the concrete floor inside each plenum. There are existing embedded channels over which the rails are mounted and they are secured by 1/2" shells. The top hats and z-clips are also secured by 1/2" shells. The conceptual fix is to run-an angle along side the channels of both the fans and motors to capture them transversely and to put z-clips at the ends of the fan rail using the existing shells (replace studs) in a manner similar to the motor configurations.

The plena housings are estimated to be 1/8" thickness and they have internal anchorage of 3/8" concrete expansion anchors at approximately 20" centers. The W14A&B housing dimension is 68"H x 62"D x 20 ft long. These plena are light and react relatively small duct reaction loads so they clearly cannot overturn and have sufficient anchorage to resist base shear so they are seismically acceptable.

No adverse potential interactions are noted since the fans are fully contained within their respective plena.

The fans are outliers for two reasons:

1. The fans are supported on vibration isolators which are unacceptable.

2. The floor response spectrum exceeds the bounding spectrum below approximately 4 Hz.

No

	1	PBNP VNPAB and CREFS Seismic Verific	ation	
		S&A Report No. 09Q0839-R-001 Revision	1	Page 91 of 172
			GIP Rev 2, Correct	ed, 2/14/92
SCREEN	NG EVALUATION	WORK SHEET (SEWS)	Status: No	
			Sheet 4 of 8	
ID : W-14B ( Rev.	0)	Class: 9. Fans		
Description : F-16	CONTROL ROOM	CHARCOAL FILTER FAN		
Building : CB		Floor El. : 60.00	Room, Row/Col : A	REA 3
Manufacturer, Mo	del, Etc. :			
Evaluated by:	W. Djordjevic, PE	· · · · · · · · · · · · · · · · · · ·	Date:	9/04/2009
	P. A. Gazda, PE			9/04/2009

Attachment: Walkdown Pictures

PBNP VNPAB and CREFS	Seismic Verification
CRA Report No. 0000920	D 001 Devision 1

Page	92	of	172

SCREENING EVALUATION WORK SHEET (SEWS)		GIP Rev 2, Corrected, 2/14/92 Status: No Sheet 5 of 8
ID: W-14B (Rev. 0)	Class: 9. Fans	
Description : F-16 CONTROL ROOM C	HARCOAL FILTER FAN	
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		



Figure 1: Motor Anchorage

PBNP VNPAB and CREFS Seismic Verification			
S	&A Repo	ort No. 09Q0839-R-001 Revision 1	Page 93 of 172
			GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION WORK SHEET (SEWS)		Status: No	
		Sheet 6 of 8	
ID:W-14B(Rev. 0)		Class: 9. Fans	
Description : F-16 CONTROL ROOM C	HARC	OAL FILTER FAN	
Building : CB	Floor	El. : 60.00	Room, Row/Col : AREA 3
Manufacturer Model Etc.			



Figure 2: Frame and motor anchorage

PBNP VNPAB and CREFS Seismic Verification			
S	&A Report No. 09Q0839-R-001 Revision 1	Page 94 of 172	
		GIP Rev 2, Corrected, 2/14/92	
SCREENING EVALUATION WORK SHEET (SEWS)		Status: No	
		Sheet 7 of 8	
ID: W-14B (Rev. 0)	Class: 9. Fans		
Description : F-16 CONTROL ROOM C	HARCOAL FILTER FAN		
Building : CB	Floor El. : 60.00	Room, Row/Col : AREA 3	
Manufacturer Model Etc.			



Figure 3: Plenum anchorage

PBNP VNPAB	and CREFS	Seismic Ve	erification
S&A Report No		R-001 Revi	sion 1

Page 95 of 172

001110		
SCREENING EVALUATION WORK SHEET (SEWS)		GIP Rev 2, Corrected, 2/14/92 Status: No Sheet 8 of 8
ID : W-14B ( Rev. 0 )	Class: 9. Fans	
Description : F-16 CONTROL ROOM CHARC	OAL FILTER FAN	
Building : CB Floor	El. : 60.00	Room, Row/Col : AREA 3
Manufacturer, Model, Etc. :		



Figure 4: Motor rail end restraints

PBNP VNPAB and CREFS Seismic Verification			
S	&A Report No. 09Q0839-R-001 Revision	1 Page 96 of 172	
		GIP Rev 2, Corrected, 2/14/92	
SCREENING EVALUATION WORK SHEET (SEWS)		Status: Yes	
		Sheet 1 of 13	
ID: W-21A (Rev. 0)	Class: 9. Fans		
Description : PAB EXHAUST STACK F	AN		
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4	
Manufacturer Model Etc. :			

### SEISMIC CAPACITY VS DEMAND

1.	Elevation where equipment receives seismic input	8.00
2. Elevation of seismic input below about 40' from grade (grade = 8.00)		
3.	Equipment has fundamental frequency above about 8 Hz (est. frequency = )	N/A
4.	Capacity based on: 1.50 * Bounding Spectrum	
5.	Demand based on: 1.00 * Conservative Design Floor Response Spectra	
	1.200 G LOG 0.016 0.17 LOG Hz 38.76 Capacity Demand	
Canad	File Record	
Demar	d 1 J:\APPDATA\GIPPER2\PROJ0032\spectra.des PLANT[Point Beach]BUILDING[Aux North and Sout Wings[ELEVATION]8 DIRECTION Horizontal EART 2 LOCATION Areas 4 & 6 BLDG-DAMP [EQ DAMP]	h HQUAKE OBE x  5%
Demar	d 2 J:\APPDATA\GIPPER2\PROJ0032\spectra.des PLANT Point Beach[BUILDING Aux North and Sout Wings ELEVATION 8 DIRECTION Horizontal EART 2 I_OCATIONIAreas 4 & 6 BLDG-DAMPIIEQ DAMPI	h 'HQUAKE OBE x I5%

Does capacity exceed demand?

P	SNP VNPAB and CREFS Seismic v	remication
S	&A Report No. 09Q0839-R-001 Rev	ision 1 Page 97 of 172
SCREENING EVALUATION	WORK SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 2 of 13
ID : W-21A ( Rev. 0 )	Class: 9. Fans	
Description : PAB EXHAUST STACK F.	AN	
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4
Manufacturer, Model, Etc. :		

......

. . . . . .

## **CAVEATS - BOUNDING SPECTRUM**

FAN/BS Caveat 1 - Earthquake Experience Equipment Class.	Yes
FAN/BS Caveat 2 - Drive Motor and Fan Mounted on Common Base.	Yes
FAN/BS Caveat 3 - Long Shafts Supported at Fan and at Motor.	Yes
FAN/BS Caveat 4 - No Possibility of Excessive Duct Distortion Causing Binding or	Yes
Misalignment of Fan.	
FAN/BS Caveat 5 - Base Vibration Isolation System Checked.	Yes
FAN/BS Caveat 6 - Sufficient Slack and Flexibility of Attached Lines.	Yes
FAN/BS Caveat 7 - Adequate Anchorage.	Yes
FAN/BS Caveat 8 - No Other Concerns	Yes

Is the intent of all the caveats met for Bounding Spectrum?

## ANCHORAGE

1. The sizes and locations of anchors have been determined.	Yes
2. Appropriate equipment characteristics have been determined (mass, CG, natural	Yes
freq., damping, center of rotation).	
3. The type of anchorage is covered by the GIP.	Yes
4. The-adequacy of the anchorage installation has been evaluated (weld quality and	Yes
length, nuts and washers, expansion anchor tightness, etc.)	
5. Factors affecting anchorage capacity or margin of safety have been considered:	Yes
embedment length, anchor spacing, free-edge distance, concrete strength/condition,	·
and concrete cracking.	
6. For bolted anchorages, any gaps under the base are less than 1/4.	Yes
7. Factors affecting essential relays have been considered: gaps under the base,	N/A
capacity reduction for expansion anchors.	
8. The base has adequate stiffness and the effect of prying action on anchors has been	Yes
considered.	
9. The strength of the equipment base and the load path to the CG is adequate.	Yes
10. The adequacy of embedded steel, grout pads or large concrete pads have been	Yes
evaluated.	
11. The anchorage capacity exceeds the demand.	Yes

Are anchorage requirements met?

Yes

S	&A Report No. 09Q0839-R-001 Revisio	n 1 Page 98 of 172
SCREENING EVALUATION WORK SHEET (SEWS)		GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 3 of 13
ID: W-21A (Rev. 0)	Class: 9. Fans	
Description : PAB EXHAUST STACK F.	AN	
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4
Manufacturer, Model, Etc. :		

### INTERACTION EFFECTS

<ol> <li>Soft targets are free from impact by nearby equipment or structures.</li> </ol>	Yes
2. If the equipment contains sensitive relays, it is free from all impact by nearby equipment or	N/A
structures.	
3. Attached lines have adequate flexibility.	Yes
4. Overhead equipment or distribution systems are not likely to collapse.	Yes*
5. No other adverse concerns were found.	Yes

Is equipment free of interaction effects?

### IS EQUIPMENT SEISMICALLY ADEQUATE?

### COMMENTS

Walkdown Engineers: W. Djordjevic & P. A. Gazda (8/31/09)

Ref. 1. Dwg P6118-M37-023-1, Sh 3 of 3

Fans W21A&B are positively anchored clearly and recently modified. There are no vibration isolators. They are each anchored by 6 - 3/4" concrete expansion anchors. The footprint is 60" x 84" with 3 anchors spaced equally on each 60" side.

Possible interactions are an overhead cast iron pipe, which is continuously supported such that it cannot credibly disengage from its supports to fall; and cable "pigtails" which are deemed too light to be of consequence even if they were to fall.

Evaluated by:

W. Djordjevic, PE

P. A. Gazda, PE

Q.U. Angeh

8/31/09

Attachment: ANCHOR Report : Walkdown Pictures

Yes

Date: 8/31/09

Page 99 of 172

SCREENING EVALUATIO	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 4 of 13		
ID: W-21A ( Rev. 0 )	Class: 9. Fans		
Description : PAB EXHAUST STACK	( FAN		
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4	
Manufacturer, Model, Etc. :			

#### **ANCHOR Report**

#### Earthquake :

Response Spectrum : Instructure Conservative Frequency : GIP - Flexible Percent Damping : GIP - 5.00

Spectral Values :

Direction	Acceleration (g's)
North - South	0.647
East - West	0.647
Vertical	0.107

Angle (N-S Direction makes with the X Axis) : 0.00 Combination Criteria : SRSS

#### Weights :

Number of Weights : 1

No	Weight	Х	Y	Z	
1	3200.00	30.000	44.000	52.250	

#### Forces : Number of External Forces : 0

#### Moments :

Number of External Moments : 0

#### Allowables :

Anchor : Number of Anchor types : 1

		· ·				Tension	Shear	
		···		Ultimate	Ultimate	Inter	Inter	Saf
No.	Dia	Manufact	Product	Tension	Shear	Coeff	Coeff	Fact
1	3/4	Hilti	Kwik-Bolt	4690.00	5480.00	1.00	0.30	1.00
			(N)					

<u>Concrete :</u> Ultimate Stress : 3000.00 psi. Reduction Factor : 0.85

<u>Weld :</u> Allowable Stress : 30600 psi.

<u>Surfaces :</u> Number of Surfaces : 1 Surface Orientation
Page 100 of 172

#### GIP Rev 2, Corrected, 2/14/92 Status: Yes SCREENING EVALUATION WORK SHEET (SEWS) Sheet 5 of 13 ID: W-21A (Rev. 0) Class: 9. Fans Description : PAB EXHAUST STACK FAN Room, Row/Col : AREA 4 Floor El. : 8.00 Building : PAB Manufacturer, Model, Etc. :

	Direction	Direction	Direction
	Comp	Comp	Comp
No	Nx	Ny	Nz
1	0.000	0.000	1.000

Anchor Pattern for Surface #1

쪻

麕



¥ z\_x



	( Rand Shack
Concrete Lines :	
Concrete Points :	
Weld Lines :	

**Geometry**: Anchor : Number of Anchors : 6

Class: 9. Fans

Page 101 of 172

# SCREENING EVALUATION WORK SHEET (SEWS)

GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 6 of 13

Room, Row/Col : AREA 4

ID : W-21A ( Rev. 0 ) Description : PAB EXHAUST STACK FAN

Building : PAB Floor El. : 8.00

Manufacturer, Model, Etc. :

Ŷ Surf Anch Х Ζ No. ld Coord Coord Coord ld 2.000 2.000 0.000 1 1 1 30.000 2.000 0.000 1 2 1 2.000 0.000 1 3 1 58.000 0.000 1 1 2.000 86.000 4 1 0.000 5 1 30.000 86.000 0.000 1 6 58.000 86.000 1

<u>Concrete Lines :</u> # of elements per line : 4 Number of Concrete Lines : 0

<u>Concrete Points :</u> Number of Concrete Points : 6

	Х	Y	Z	Surf	Conc-Pt
No.	Coord	Coord	Coord	ld	Area
1	2.000	2.000	0.000	1	16.000
2	58.000	2.000	0.000	1	16.000
3	30.000	2.000	0.000	1	16.000
4	2.000	86.000	0.000	1	16.000
5	58.000	86.000	0.000	1	16.000
6	30.000	86.000	0.000	1	16.000

Weld Lines : # of elements per line : 4 Number of Weld Lines : 0

**Determination of Reduction Factors :** 

Reduction Factor Input for Anchor #1

Adequately Installed : Yes Embedment Length : ( 3.25 in. Min Reqd. to achieve full capacity) := 3.25 in. Gap at Threaded Anchor : 0.00 in. Edge Distance - Edge 1 : 7.50 in. Crack Size : 0.000 in. - Cracks Affect <= 50% Bolts Essential Relays in Cabinet : Yes Adequate Equipment Base Strength and Structural Load Path : Yes Embedment Steel and Pads Adequately Installed : Yes

Reduction Factor Input for Anchor #2

Adequately Installed : Yes Embedment Length : ( 3.25 in. Min Reqd. to achieve full capacity) := 3.25 in. Gap at Threaded Anchor : 0.00 in. Edge Distance - Edge 1 : 7.50 in.

c c	28 A Depart No. 0000930 D.001 De	wision 1 Page 102	of 172
SCREENING EVALUATION	WORK SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 7 of 13	2
ID: W-21A (Rev. 0)	Class: 9. Fans		
Description : PAB EXHAUST STACK F	AN		
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4	
Manufacturer, Model, Etc. :			
Crack Size : 0.000 in Cracks Affect Essential Relays in Cabinet : Yes Adequate Equipment Base Strength ar Embedment Steel and Pads Adequate	<= 50% Bolts nd Structural Load Path : Yes ly Installed : Yes	5	
Reduction Factor Input for Anchor # 3			
Adequately Installed : Yes Embedment Length : ( 3.25 in. Min Red Gap at Threaded Anchor : 0.00 in. Edge Distance - Edge 1 : 7.50 in. Crack Size : 0.000 in Cracks Affect Essential Relays in Cabinet : Yes Adequate Equipment Base Strength ar Embedment Steel and Pads Adequate	qd. to achieve full capacity) : <= 50% Bolts nd Structural Load Path : Yes ly Installed : Yes	= 3.25 in. s	
Reduction Factor Input for Anchor #4			
Adequately Installed : Yes Embedment Length : ( 3.25 in. Min Red Gap at Threaded Anchor : 0.00 in. Edge Distance - Edge 1 : 7.50 in. Crack Size : 0.000 in Cracks Affect Essential Relays in Cabinet : Yes Adequate Equipment Base Strength an Embedment Steel and Pads Adequate	qd. to achieve full capacity) : <= 50% Bolts nd Structural Load Path : Yes ly Installed : Yes	= 3.25 in. s	
Reduction Factor Input for Anchor # 5			
Adequately Installed : Yes Embedment Length : ( 3.25 in. Min Red Gap at Threaded Anchor : 0.00 in. Edge Distance - Edge 1 : 7.50 in. Crack Size : 0.000 in Cracks Affect Essential Relays in Cabinet : Yes Adequate Equipment Base Strength an Embedment Steel and Pads Adequate	qd. to achieve full capacity) : <= 50% Bolts nd Structural Load Path : Yes ly Installed : Yes	s 3.25 in.	
Reduction Factor Input for Anchor # 6			
Adequately Installed : Yes Embedment Length : ( 3.25 in. Min Re Gap at Threaded Anchor : 0.00 in. Edge Distance - Edge 1 : 7.50 in. Crack Size : 0.000 in Cracks Affect Essential Relays in Cabinet : Yes Adequate Equipment Base Strength an Embedment Steel and Pads Adequate Reduction Factors Data Current : Yes	qd. to achieve full capacity) : <= 50% Bolts nd Structural Load Path : Ye ly Installed : Yes	:= 3.25 in. s	

Class: 9. Fans

Page 103 of 172

# SCREENING EVALUATION WORK SHEET (SEWS)

GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 8 of 13

ID : W-21A ( Rev. 0 ) Description : PAB EXHAUST STACK FAN

Building : PAB

Floor El. : 8.00

Room, Row/Col : AREA 4

Manufacturer, Model, Etc. :

	Anc	Pall/	Pallr/												
No	ld	Vall	Vallr	RT	RN	RL	RG	RS	RE	RF	RC	RR	RP	RB	RM
1	1	2638.13	N/A	1.00	1.00	1.00	1.00	1.00	1.00	0.75	1.00	0.75	1.00	1.00	1.00
		3904.50	N/A	1.00	1.00	1.00	1.00	1.00	1.00	0.95	1.00	0.75	1.00	1.00	1.00
2	1	2638.13	N/A	1.00	1.00	1.00	1.00	1.00	1.00	0.75	1.00	0.75	1.00	1.00	1.00
		3904.50	N/A	1.00	1.00	1.00	1.00	1.00	1.00	0.95	1.00	0.75	1.00	1.00	1.00
3	1	2638.13	N/A	1.00	1.00	1.00	1.00	1.00	1.00	0.75	1.00	0.75	1.00	1.00	1.00
		3904.50	N/A	1.00	1.00	1.00	1.00	1.00	1.00	0.95	1.00	0.75	1.00	1.00	1.00
4	1	2638.13	N/A	1.00	1.00	1.00	1.00	1.00	1.00	0.75	1.00	0.75	1.00	1.00	1.00
		3904.50	N/A	1.00	1.00	1.00	1.00	1.00	1.00	0.95	1.00	0.75	1.00	1.00	1.00
5	1	2638.13	N/A	1.00	1.00	1.00	1.00	1.00	1.00	0.75	1.00	0.75	1.00	1.00	1.00
		3904.50	N/A	1.00	1.00	1.00	1.00	1.00	1.00	0.95	1.00	0.75	1.00	1.00	1.00
6	1	2638.13	N/A	1.00	1.00	1.00	1.00	1.00	1.00	0.75	1.00	0.75	1.00	1.00	1.00
		3904.50	N/A	1.00	1.00	1.00	1.00	1.00	1.00	0.95	1.00	0.75	1.00	1.00	1.00

#### Legend :

N/A	= Not Applicable
Pall	= Allowable Pull without Reduced Inspection
Vall	= Allowable Shear without Reduced Inspection
Pallr	= Allowable Pull with Reduced Inspection
Valir	= Allowable Shear with Reduced Inspection
*	= Outlier
Х	= Reduction Factor Not Used
RT	= Reduction Factor for Type of Anchorage
RN	= Reduction Factor for Installation Adequacy
RL	= Reduction Factor for Embedment
RG	= Reduction Factor for Gap at Anchors
RS	= Reduction Factor for Spacing
RE	= Reduction Factor for Edge Distance
RF	= Reduction Factor for Concrete Strength
RC	= Reduction Factor for Concrete Cracks
RR	= Reduction Factor for Essential Relays
RP	= Reduction Factor for Base Stiffness and Prying Action
RB	= Reduction Factor for Base Strength and Load Path
RM	= Reduction Factor for Embed. Steel and Pads

## <u>Analysis Results :</u> Analysis Performed : Yes

#### Type of Analysis : Regular

	Spect			
No	N-S	E-W	Vertical	Safety Factor
1	0.647	0.259	0.043	4.756
2	-0.647	-0.259	-0.043	5.104
3	-0.647	0.259	0.043	4.756
4	0.647	-0.259	-0.043	5.104
5	0.647	-0.259	0.043	4.756
6	-0.647	0.259	-0.043	5.104
7	0.647	0.259	-0.043	5.104
8	-0.647	-0.259	0.043	4.756

PBNP VNPAB and CREFS Seismic Verification							
		1 Page 104 of 172					
		GIP Rev 2, Corrected, 2/14/92					
SCREENING	EVALUATION	WORK SHEE	T (SEWS)	Status: Yes			
OUNCLINING	LIALOANON	Sheet 9 of 13					
V-21A (Rev. 0)		Class :	9. Fans				
ription : PAB EX	HAUST STACK	FAN					
ing : PAB		Floor El. : 8.0	0.	Room, Row/Col : AREA 4			
ufacturer, Model,	Etc. :						
0.259	0.647	0.043	6.567				
-0.259	-0.647	-0.043	6.820				
0.259	-0.647	0.043	6.567				
-0.259	0.647	-0.043	6.820				
-0.259	0.647	0.043	6.567				
0.259	-0.647	-0.043	6.820				
0.259	0.647	-0.043	6.820				
-0.259	-0.647	0.043	6.567				
0.259	0.259	0.107	10.013	•			
-0.259	-0.259	-0.107	13.162				
	SCREENING V-21A ( Rev. 0 ) ription : PAB EX ing : PAB ifacturer, Model, 0.259 -0.259 0.259 -0.259 0.259 0.259 0.259 0.259 -0.259 0.259 -0.259 -0.259 -0.259 -0.259 -0.259 -0.259	SCREENING EVALUATION           V-21A (Rev. 0)           ription : PAB EXHAUST STACK           ing : PAB           ifacturer, Model, Etc. :           0.259         0.647           -0.259         -0.647           0.259         0.647           -0.259         0.647           -0.259         0.647           -0.259         0.647           -0.259         0.647           -0.259         0.647           -0.259         0.647           0.259         -0.647           0.259         0.647           0.259         0.647           0.259         0.647           0.259         0.647           0.259         0.647           0.259         0.647           0.259         0.647           0.259         0.647           0.259         0.259	PBNP VNPAB and 0 S&A Report No. 090           SCREENING EVALUATION WORK SHEE           V-21A ( Rev. 0 )         Class :           ription : PAB EXHAUST STACK FAN ing : PAB         Floor El. : 8.0           afacturer, Model, Etc. :         Floor El. : 8.0           0.259         0.647         0.043           -0.259         -0.647         -0.043           0.259         0.647         0.043           -0.259         0.647         0.043           -0.259         0.647         0.043           -0.259         0.647         0.043           -0.259         0.647         0.043           -0.259         0.647         0.043           -0.259         0.647         0.043           -0.259         0.647         0.043           -0.259         0.647         0.043           0.259         0.647         0.043           0.259         0.647         0.043           0.259         0.647         0.043           0.259         0.647         0.043           0.259         0.647         0.043           0.259         0.259         0.107           -0.259         0.259         0.107	PBNP VNPAB and CREFS Seismic Verifica           S&A Report No. 09Q0839-R-001 Revision           SCREENING EVALUATION WORK SHEET (SEWS)           V-21A ( Rev. 0 )         Class : 9. Fans           ription : PAB EXHAUST STACK FAN           ing : PAB           Floor El. : 8.00           afacturer, Model, Etc. :           0.259         0.647         0.043         6.820           0.259         -0.647         -0.043         6.820         -0.259         -0.647         -0.043         6.820         -0.259         -0.647         -0.043         6.820           0.259         -0.647         -0.043         6.820           -0.259         -0.647         -0.043         6.820         -0.259         -0.647         -0.043         6.820         -0.259         -0.647         -0.043         6.820         -0.259         -0.647         -0.043         6.820         -0.259         -0.107			

0.259 13.162 -0.107 19 0.259 10.013 20 -0.259 -0.259 0.107 0.259 -0.259 0.107 10.013 21 -0.107 13.162 -0.259 22 0.259 -0.259 0.107 10.013 0.259 23 -0.107 13.162 0.259 24 -0.259

Minimum Safety Factor: 4.756

The anchorage can withstand 4.756 times greater seismic demand

The large Safety Factor will more than account for excentricities of the concrete expansion anchors.

.

PBNP VNPAB and CREFS Seismic Verification						
S&A Report No. 09Q0839-R-001 Revision 1 Page 105 of 172						
		GIP Rev 2, Corrected, 2/14/92				
SCREENING EVALUATION	Status: Yes					
ID : W-21A ( Rev. 0 )	Class : 9. Fans					
Description : PAB EXHAUST STACK F.	Description : PAB EXHAUST STACK FAN					
Building : PAB	Room, Row/Col : AREA 4					
Manufacturer, Model, Etc. :						



Figure 1: One side of anchorage

PBNP VNPAB and CREFS Seismic Verification					
S	&A Report No. 09Q0839-R-001 Revisi	on 1 Page 106 of 172			
		GIP Rev 2, Corrected, 2/14/92			
SCREENING EVALUATION	SCREENING EVALUATION WORK SHEET (SEWS)				
		Sheet 11 of 13			
ID: W-21A (Rev. 0)	Class: 9. Fans				
Description : PAB EXHAUST STACK FAN					
Building : PAB	Room, Row/Col : AREA 4				
Manufacturer Model Etc.					



Figure 2: Cast iron drain line overhead

PBNP VNPAB and CREES Seismic ventication					
St	&A Report No. 09Q0839-R-001 Revisio	on 1 Page 107 of 172			
SCREENING EVALUATION	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 12 of 13				
ID:W-21A(Rev. 0)	Class: 9. Fans				
Description : PAB EXHAUST STACK FAN					
Building : PAB	Room, Row/Col : AREA 4				
Manufacturer, Model, Etc. :					



# Figure 3: Overall view of anchorage





## Figure 4: Cabling "pigtail" overhead

PBNP VNPAB and CREFS Seismic Verification					
S	&A Report No. 09Q0839-R-001 Revisio	on 1 Page 109 of 172			
		GIP Rev 2, Corrected, 2/14/92			
SCREENING EVALUATION	WORK SHEET (SEWS)	Status: Yes			
		Sheet 1 of 3			
ID: W-21B(Rev. 0)	Class: 9. Fans				
Description : PAB EXHAUST STACK F	AN				
Building : PAB	Room, Row/Col : AREA 4				
Manufacturer, Model, Etc. :					

# SEISMIC CAPACITY VS DEMAND

1. Elevation where equipment receives seismic input		
2. Elevation of seismic input below about 40' from grade (grade = 8.00)		
3.	Equipment has fundamental frequency above about 8 Hz (est. frequency = )	N/A
4.	Capacity based on: 1.50 * Bounding Spectrum	
5.	Demand based on: 1.00 * Conservative Design Floor Response Spectra	
	1.200 G LOG 0.016 0.016  Capacity Demand	
Canac	ty LiAPPDATA\GIPPER2\GIP\spectra des LabellBounding Spectrum	······
Demar	Demand 1 J:\APPDATA\GIPPER2\PROJ0032\spectra.des PLANT Point Beach BUILDING Aux North and South Wings ELEVATION 8 DIRECTION Horizontal EARTHQUAKE OBE 2 LOCATION Areas 4 & 6 BLDG-DAMPIEQ DAMPI5%	
Demar	d 2 J:\APPDATA\GIPPER2\PROJ0032\spectra.des PLANT[Point Beach BUILDING Aux North and South Wings ELEVATION 8 DIRECTION Horizontal EART 2 LOCATION Areas 4 & 6 BLDG-DAMP  EQ DAMP	h HQUAKE OBE x  5%

Does capacity exceed demand?

PBNP VNPAB and CREFS Seismic Verification				
5	EA REPORTING. U9QU839-R-UUT REVISIO			
		GIP Rev 2, Corrected, 2/ 14/92		
SCREENING EVALUATION	Status: Yes			
ID: W-21B (Rev. 0)	Class: 9. Fans			
Description : PAB EXHAUST STACK FAN				
Building : PAB Floor El. : 8.00		Room, Row/Col : AREA 4		
Manufacturer, Model, Etc. :				

# CAVEATS - BOUNDING SPECTRUM

FAN/BS Caveat 1 - Earthquake Experience Equipment Class.	
FAN/BS Caveat 2 - Drive Motor and Fan Mounted on Common Base.	Yes
FAN/BS Caveat 3 - Long Shafts Supported at Fan and at Motor.	Yes
FAN/BS Caveat 4 - No Possibility of Excessive Duct Distortion Causing Binding or	
Misalignment of Fan.	
FAN/BS Caveat 5 - Base Vibration Isolation System Checked.	
FAN/BS Caveat 6 - Sufficient Slack and Flexibility of Attached Lines.	
FAN/BS Caveat 7 - Adequate Anchorage.	
FAN/BS Caveat 8 - No Other Concerns	

Is the intent of all the caveats met for Bounding Spectrum?

# ANCHORAGE

1. The sizes and locations of anchors have been determined.		
2. Appropriate equipment characteristics have been determined (mass, CG, natural		
freq., damping, center of rotation).		
3. The type of anchorage is covered by the GIP.	Yes	
4. The adequacy of the anchorage installation has been evaluated (weld quality and	Yes	
length, nuts and washers, expansion anchor tightness, etc.)		
5. Factors affecting anchorage capacity or margin of safety have been considered:	Yes	
embedment length, anchor spacing, free-edge distance, concrete strength/condition,		
and concrete cracking.		
6. For bolted anchorages, any gaps under the base are less than 1/4.		
7. Factors affecting essential relays have been considered: gaps under the base,		
capacity reduction for expansion anchors.		
8. The base has adequate stiffness and the effect of prying action on anchors has been		
considered.		
9. The strength of the equipment base and the load path to the CG is adequate.		
10. The adequacy of embedded steel, grout pads or large concrete pads have been		
evaluated.		
11. The anchorage capacity exceeds the demand.	Yes	

Are anchorage requirements met?

.

Yes

 S&A Report No. 09Q0839-R-001 Revision 1
 Page 111 of 172

 GIP Rev 2, Corrected, 2/14/92

 Status: Yes

 Sheet 3 of 3

 ID : W-21B ( Rev. 0 )
 Class : 9. Fans

 Description : PAB EXHAUST STACK FAN

 Building : PAB
 Floor El. : 8.00
 Room, Row/Col : AREA 4

 Manufacturer, Model, Etc. :
 Status : Yes
 Status : Yes

## INTERACTION EFFECTS

1. Soft targets are free from impact by nearby equipment or structures.	
2. If the equipment contains sensitive relays, it is free from all impact by nearby equipment or	
structures.	
3. Attached lines have adequate flexibility.	Yes
4. Overhead equipment or distribution systems are not likely to collapse.	
5. No other adverse concerns were found.	

Is equipment free of interaction effects?

## IS EQUIPMENT SEISMICALLY ADEQUATE?

#### COMMENTS

Identical to W21A (see notes, photographs and anchorage analysis for W21A)

Evaluated by:

W. Djordjevic, PE

P. A. Gazda, PE G.U. Mych

8/31/09

8/31/09

Date:

<u>Yes</u>

SCREENING EVALUATION V	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 1 of 5		
ID: W-30A (Rev. 0)	Class: 9. Fans		
Description : F-23/F-29 PAB EXHAUST	FILTER FAN		
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4	
Manufacturer, Model, Etc. :			

## SEISMIC CAPACITY VS DEMAND

1 Elevation where equipment receives seismic input			8.00		
2. Elevation of seismic input below about 40' from grade (grade = 8.00)			N/A		
3.	Equipment has fundam	nental frequency above a	bout 8 Hz (est. frequency = )	N/A	
4.	Capacity based on:	1.50 * Bounding Spectr	um		
5.	Demand based on:	1.00 * Conservative De	sign Floor Response Spectra		
	1.200 G LOG 0.916 0.17 LOG Hz 38.76 Capacity Demand				
Capac	ity INAPPDATA\GIP	PER2\GIP\spectra des	LabellBounding Spectrum		
Demand 1 J:\APPDATA\GIPPER2\PROJ0032\spectra.des PLANT Point Beach BUILDING Aux North and South Wings ELEVATION 8 DIRECTION Horizontal EARTHQUAKE 0 2 LOCATION Areas 4 & 6 BLDG-DAMP  EQ DAMP 5%		th l'HQUAKE OBE x r 5%			
Demai	nd 2 J:\APPDATA\GIPF	PER2\PROJ0032\spectra.des	PLANTIPoint Beach BUILDING Aux North and Sou Wings ELEVATION 8 DIRECTION Horizontal EART 2 LOCATION Areas 4 & 6 BLDG-DAMP EQ DAMP	th FHQUAKEJOBE x YI5%	

Does capacity exceed demand?

<u>Yes</u>

-

PDNP VNPAD and OREPS Seisinic Venication			
S	&A Report No. 09Q0839-R-001 Revision 1	Page 113 of 172	
SCREENING EVALUATION	WORK SHEET (SEWS)	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 2 of 5	
ID: W-30A (Rev. 0)	Class : 9. Fans		
Description : F-23/F-29 PAB EXHAUST	FILTER FAN		
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4	
Manufacturer, Model, Etc. :	L		

# CAVEATS - BOUNDING SPECTRUM

FAN/BS Caveat 1 - Earthquake Experience Equipment Class.	
FAN/BS Caveat 2 - Drive Motor and Fan Mounted on Common Base.	Yes
FAN/BS Caveat 3 - Long Shafts Supported at Fan and at Motor.	Yes
FAN/BS Caveat 4 - No Possibility of Excessive Duct Distortion Causing Binding or	
Misalignment of Fan.	
FAN/BS Caveat 5 - Base Vibration Isolation System Checked.	
FAN/BS Caveat 6 - Sufficient Slack and Flexibility of Attached Lines.	Yes
FAN/BS Caveat 7 - Adequate Anchorage.	
FAN/BS Caveat 8 - No Other Concerns	

Is the intent of all the caveats met for Bounding Spectrum?

# ANCHORAGE

1. The sizes and locations of anchors have been determined.	Yes
2. Appropriate equipment characteristics have been determined (mass, CG, natural	
freq., damping, center of rotation).	
3. The type of anchorage is covered by the GIP.	Yes
4. The adequacy of the anchorage installation has been evaluated (weld quality and	Yes
length, nuts and washers, expansion anchor tightness, etc.)	
5. Factors affecting anchorage capacity or margin of safety have been considered:	Yes
embedment length, anchor spacing, free-edge distance, concrete strength/condition,	
and concrete cracking.	
6. For bolted anchorages, any gaps under the base are less than 1/4.	
7. Factors affecting essential relays have been considered: gaps under the base,	
capacity reduction for expansion anchors.	
8. The base has adequate stiffness and the effect of prying action on anchors has been	
considered.	
9. The strength of the equipment base and the load path to the CG is adequate.	
10. The adequacy of embedded steel, grout pads or large concrete pads have been	
evaluated.	
11. The anchorage capacity exceeds the demand.	Yes

Are anchorage requirements met?

Yes

Yes

DDND VNDAB and CREES Seismic Verification

Status: Yes

# SCREENING EVALUATION WORK SHEET (SEWS)

		Sheet 3 of 5	
ID : W-30A ( Rev. 0 )	Class: 9. Fans		
Description : F-23/F-29 PAB EXHAUST	FILTER FAN		
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4	
Manufacturer Model Etc.			

## INTERACTION EFFECTS

1. Soft targets are free from impact by nearby equipment or structures.	
2. If the equipment contains sensitive relays, it is free from all impact by nearby equipment or	
structures.	
3. Attached lines have adequate flexibility.	
4. Overhead equipment or distribution systems are not likely to collapse.	
5. No other adverse concerns were found.	

Is equipment free of interaction effects?

#### IS EQUIPMENT SEISMICALLY ADEQUATE?

#### COMMENTS

Walkdown Engineers: W. Djordjevic & P. A. Gazda (8/31/09)

Ref. 1. S&A Calc. No. 98Q0020-C-001, Rev. 1., "PAB Fans W30A and W30B Anchorage Qualification"

The W30A&B fans are also seismically designed (by Stevenson & Associates, Ref. 1) with no vibration isolators.

In the same room (about 20 ft away) there are charcoal filter banks in the rooms with a footprint of 107" x 180". The visible 107" side has 10 - 1/2" concrete expansion anchors with two anchors having nuts that are raised. The 180" side cannot be fully viewed as it is adjacent to a wall but at least 10 anchors were counted, some of which again were missing nuts or for which the nuts were raised. The two other sides are inaccessible. The filter banks are about 10' high and are adjudged to have a natural frequency in excess of about 20 Hz. Since they cannot uplift the anchors only need to resist base shear and there are sufficient visible anchors to accomplish this so they are declared seismically adequate. They pose no interaction potential risk to the fans.

No issues found.

No potential seismic interactions noted.

Evaluated by:

W. Djordjevic, PE

P. A. Gazda, PE

J. U. Mach

Date: 8/31/09

8/31/09

Attachment: Walkdown Pictures

Yes

Yes

Page 114 of 172 GIP Rev 2, Corrected, 2/14/92

PI	BNP VNPAB and CREFS Seismic Vernica	Page 115 of 172
5	an Report No. 03 20000 11 001	GIP Rev 2, Corrected, 2/14/92
SCREENING EVALUATION WORK SHEET (SEWS)		Status: Yes
		Sheet 4 of 5
$D: W_{-30A} (\text{Rev. 0})$	Class: 9. Fans	
Description : F-23/F-29 PAB EXHAUST	FILTER FAN	Boom Row/Col: AREA 4
Building : PAB	Floor El. : 8.00	Room, Rowroot: ARE/14

Manufacturer, Model, Etc. :



Figure 1: View of one side of anchorage

PBNP VNPAB and CREFS Seismic Verification					
S&A Report No. 09Q0839-R-001 Revision 1 Page 116 of 17					
		GIP Rev 2, Corrected, 2/14/92			
SCREENING EVALUATION WORK SHEET (SEWS)		Status: Yes			
		Sheet 5 of 5			
ID: W-30A (Rev. 0)	Class: 9. Fans				
Description : F-23/F-29 PAB EXHAUST FILTER FAN					
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4			
Manufacturer, Model, Etc. :					



Figure 2: View of Duct Bellows

SCREENING EVALUATION	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 1 of 5	
ID:W-30B(Rev. 0)	Class: 9. Fans	
Description : F-23/F-29 PAB EXHAUST	FILTER FAN	
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4
Manufacturer, Model, Etc. :		

## SEISMIC CAPACITY VS DEMAND

1.	Elevati	on where equip	ment receives seismic in	put	8.00
2.	Elevati	on of seismic in	out below about 40' from	grade (grade = 8.00)	N/A
3.	Equipn	nent has fundam	nental frequency above a	bout 8 Hz (est. frequency = )	N/A
4.	Capaci	ity based on:	1.50 * Bounding Spectr	rum	
5.	Demar	nd based on:	1.00 * Conservative De	esign Floor Response Spectra	
	1.200 G LOG 0.016 0.17 LOG Hz 38.76 Capacity Demand				
Canadi		File		Record	
Deman	nd 1	J:\APPDATA\GIPF	PER2/PRO.10032/spectra des	PLANTIPoint BeachIBUIL DINGIAux North and Sout	th
				Wings ELEVATION 8 DIRECTION Horizontal]EART 2 LOCATION Areas 4 & 6 BLDG-DAMP  EQ DAMP	HQUAKE OBE x  5%
Deman	nd 2	J:\APPDATA\GIPF	PER2\PROJ0032\spectra.des	PLANT/Point Beach/BUILDING/Aux North and Sout Wings/ELEVATION/8/DIRECTION/Horizontal/EART 2/LOCATION/Areas 4 & 6/BLDG-DAMP/JEQ DAMP	th THQUAKE OBE x 15%

Does capacity exceed demand?

1

PBNP VNPAB and CREFS Seismic Verification					
Si	Page 118 of 172				
	GIP Rev 2, Corrected, 2/14/92				
SCREENING EVALUATION WORK SHEET (SEWS)		Status: Yes			
		Sheet 2 of 5			
ID: W-30B (Rev. 0)	Class: 9. Fans				
Description : F-23/F-29 PAB EXHAUST	FILTER FAN				
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4			
Manufacturer, Model, Etc. :					

# CAVEATS - BOUNDING SPECTRUM

FAN/BS Caveat 1 - Earthquake Experience Equipment Class.	Yes
FAN/BS Caveat 2 - Drive Motor and Fan Mounted on Common Base.	Yes
FAN/BS Caveat 3 - Long Shafts Supported at Fan and at Motor.	Yes
FAN/BS Caveat 4 - No Possibility of Excessive Duct Distortion Causing Binding or	Yes
Misalignment of Fan.	
FAN/BS Caveat 5 - Base Vibration Isolation System Checked.	Yes
FAN/BS Caveat 6 - Sufficient Slack and Flexibility of Attached Lines.	Yes
FAN/BS Caveat 7 - Adequate Anchorage.	Yes
FAN/BS Caveat 8 - No Other Concerns	Yes

Is the intent of all the caveats met for Bounding Spectrum?

# ANCHORAGE

1. The sizes and locations of anchors have been determined.	Yes
2. Appropriate equipment characteristics have been determined (mass, CG, natural	Yes
freq., damping, center of rotation).	
3. The type of anchorage is covered by the GIP.	Yes
4. The adequacy of the anchorage installation has been evaluated (weld quality and	Yes
length, nuts and washers, expansion anchor tightness, etc.)	
5. Factors affecting anchorage capacity or margin of safety have been considered:	Yes
embedment length, anchor spacing, free-edge distance, concrete strength/condition,	
and concrete cracking.	
6. For bolted anchorages, any gaps under the base are less than 1/4.	Yes
7. Factors affecting essential relays have been considered: gaps under the base,	N/A
capacity reduction for expansion anchors.	
8. The base has adequate stiffness and the effect of prying action on anchors has been	Yes
considered.	
9. The strength of the equipment base and the load path to the CG is adequate.	Yes
10. The adequacy of embedded steel, grout pads or large concrete pads have been	Yes
evaluated.	
11. The anchorage capacity exceeds the demand.	Yes

Are anchorage requirements met?

Yes

SCREENING EVALUATION	GIP Rev 2, Corrected, 2/14/92 Status: Yes Sheet 3 of 5	
ID:W-30B(Rev. 0)	Class: 9. Fans	
Description : F-23/F-29 PAB EXHAUST	FILTER FAN	
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4
Manufacturer, Model, Etc. :		

## INTERACTION EFFECTS

1. Soft targets are free from impact by nearby equipment or structures.	Yes
2. If the equipment contains sensitive relays, it is free from all impact by nearby equipment or	N/A
structures.	
3. Attached lines have adequate flexibility.	Yes
<ol><li>Overhead equipment or distribution systems are not likely to collapse.</li></ol>	Yes
5. No other adverse concerns were found.	Yes

Is equipment free of interaction effects?

#### IS EQUIPMENT SEISMICALLY ADEQUATE?

#### COMMENTS

Walkdown Engineers: W. Djordjevic & P. A. Gazda (8/31/09)

Ref. 1. S&A Calc. No. 98Q0020-C-001, Rev. 1., "PAB Fans W30A and W30B Anchorage Qualification"

The W30A&B fans are also seismically designed (by Stevenson & Associates, Ref. 1) with no vibration isolators.

In the same room (about 20 ft away) there are charcoal filter banks in the rooms with a footprint of 107" x 180". The visible 107" side has 10 - 1/2" concrete expansion anchors with two anchors having nuts that are raised. The 180" side cannot be fully viewed as it is adjacent to a wall but at least 10 anchors were counted, some of whichagain were missing nuts or for which the nuts were raised. The two other sides are inaccessible. The filter banks are about 10' high and are adjudged to have a natural frequency in excess of about 20 Hz. Since they cannot uplift the anchors only need to resist base shear and there are sufficient visible anchors to accomplish this so they are declared seismically adequate. They pose no interaction potential risk to the fans.

No issues found.

No potential seismic interactions noted.

Evaluated by:

W. Djordjevic, PE

P. A. Gazda, PE

G.U. Mach

Date:

8/31/09

8/31/09

Attachment: Walkdown Pictures

Yes

Page 119 of 172

PBNP VNPAB and CREFS Seismic Ventication				
0839-R-001 Revision 1 Page 120 of 172				
GIP Rev 2, Corrected, 2/14/92				
T (SFWS) Status: Yes				
Sheet 4 of 5				
9. Fans				
Description : F-23/F-29 PAB EXHAUST FILTER FAN				
) Room, Row/Col : AREA 4				



Figure 1: View of one side of anchorage

PBNP VNPAB and CREFS Seismic Ventication				
S&A Report No. 09Q0839-R-001 Revision 1 Page 12				
	GIP Rev 2, Corrected, 2/14/92			
SCREENING EVALUATION	Status: Yes			
SCILLINING EVALUATION WORK ONLET (CEWS)		Sheet 5 of 5		
ID:W-30B(Rev. 0)	Class : 9. Fans			
Description : F-23/F-29 PAB EXHAUST FILTER FAN				
Building : PAB	Floor El. : 8.00	Room, Row/Col : AREA 4		
Manufacturer, Model, Etc. :				



Page 122 of 172

.

	Exhibit 5-1			Sheet 1 of			· <u>3</u>	
SC	REENING AND EVALUATION	I WORK SHEET (SEWS)						
HVAC System I.D.	VNPAB Exhaust Area 4							
Damper Equipment I.D.	See M-116			·				
System Description and Bour	ndaries							
PAB Exhaust system.	El 8' Area 4							
		······································						
HVAC System Locations and	Reference Drawings	M-116						
Duct Materials and Sizes	Galvanized Carbon Stee	el - See M-116						
Linear Weight:						~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		
Duct	Insulation	Total		F	Referen	ces		
·	=							
+								
+	=							
Concurrent Pressure and Ter	neprature Low Temp	& Low Pressure System			<b></b>			
Applicability			Y	Ν	U	N/A		
1. Operating temperating temperation in Table 2-1	ture less than the temperate	ure limitations	X			••••		
2. Plant ground spectrum enveloped by the SQUG Bounding Spectrum (Figure 2-1) and ZPAh is less than 2.0g			<u>X</u>					
Does duct meet applicability	criteria?		X	<u></u>				
Pressure Boundary Integrity	Review							
1. Is pressure bounda	γ integrity required?		X					
IF the answer to the a	bove question is NO, SKIP T	HIS SECTION and						
proceed to the Struct	ural Integrity Review							
2. Stiffener spacings a	re within the guidelines		X	·			,	
<ol><li>Bolted flanged joint</li></ol>	s satisfy SMACNA requirem	ents				X		
4. No point-supported round duct (Calculation shows Duct OK)		X						
5. Flexible bellows can accommodate motions		<u> </u>			•			
6. No additional conce	erns		X					
Are the above caveats met?			X					

## Exhibit 5-1

Sheet 2 of 3

# SCREENING AND EVALUATION WORK SHEET (SEWS)

20	REENING AND EVALOATION WORK SHEET (SEWS)				
HVAC System I.D.	VNPAB Exhaust Area 4				
Damper Equipment I.D.	See M-116				
Structural Integrity Review		Y	N	U	N/A
1. Support spans satisfy t	the criteria	Х			
2. Ducts are properly tied	d-down to the supports	X			
3. Industry standard duct	t joints are utilized	X			
4. Slip joints can accomm	nodate displacements				X
5. Round duct joints excl	ude riveted lap joints	X			
6. Appurtenances are po	sitively attached to duct				x
7. Heavy in-line equipme	nt is adequately restrained	<u></u>		p	x
8. No stiff branch with fle	exible header (See note 7 & 8)	X		<u></u>	
9. Cantilevered duct sect	ion is attached to last support	X			
10. Ducts are free of corr	rosion detrimental to integrity	X ·			
11. System is free of obv	X			· · · · · · · · · · · · · · · · · · ·	
12. No other concerns		X			
Are the above caveats met?		X			
Concert Deview				<u></u>	•
Support Review					
<ol> <li>Beam clamps are orier</li> </ol>	nted to preclude slipping off the support				. <u> </u>
<ol><li>Channel nuts have tee</li></ol>	th or ridges				X
<ol><li>No cast iron inserts</li></ol>		<u> </u>			
<ol><li>No broken or obviousl</li></ol>	y defective hardware	<u> </u>			
5. Support is free of exce	essive corrosion	X			
<ol><li>Welded joints appear</li></ol>	to be of good quality				X
<ol><li>Anchorage appears ad</li></ol>	lequate (LARS 1 & 2)	<u> </u>			
<ol><li>No stiff supports or hat</li></ol>	rd spots in long flexible duct runs	<u> </u>			
<ol><li>No short, fixed ended</li></ol>	heavily loaded rod hangers subject to potential				
fatigue failure		X			
10. No additional concer	ns (LAR 1 shows angle overstress)		X		
Are the above caveats met?			X		-
Damper Review					
1 Damper is similar to a	nd hounded by the seismic experience data for				
dampers in Attachment	B	х			
2 Damper operator/acti	uator not of cast iron	X	*********		-
2. Attached lines have su	ufficient clack and flexibility	X			
4. Damper controls mou	inted separately from the damper adequately				
4. Damper controls mou	nied separately nom the damper adequately				х
E Motor or proumatic o	perator mounted on the damper has adequate				-
anchorage and load nath	perator mounted on the damper has adequate				х
6 Duct at the damper le	reation free from signs of distortion that could				· · · · · · · · · · · · · · · · · · ·
interfore with democra	neration	х			
7. No other advarce com	corps	- <u>x</u>			
7. NO other adverse com	LC113				
Are the above caveats met?		~			-

Page 124 of 172

Exhibit 5-1						Sheet	3 of	3
S	SCREENING AND EVALUATION WORK SHEET (SEWS)							
HVAC System I.D.	VNPAB Exhau	st Area 4						
Damper Equipment I.D.	See M-116							
Seismic Interaction Review				Y	N	U	N/A	
1. Free from impact by n	earby equipmer	nt		X				
2. No collapse of overhea	ad equipment, c	listribution systems	or					
masonry walls	masonry walls					Laurence		
3. Able to accommodate	3. Able to accommodate differential displacements							
4. No other adverse cond	erns			<u>    X     </u>				
Are the above caveats m	et?			<u>    X     </u>				
IS THE HVAC DUCT AND DAMPE Supports Selected for Analytica	ER SYSTEM SEISI	MICALLY ADEQUATE	2 3) Duct 32 4) Du		<u> </u>			
Duct System Selected for Analy	tical Review	1) Duct 1						
Comments		<u></u>						
1) One support on Duct 1 chose	en for A.R.							
2) One support on Duct 4 chose	en for A.R.							
3) Two supports on Duct 32 cho	osen for A.R.					······································		
4) See SEWS for fans W21A&B	and W30A&B							
5) Dampers found to be well at	tached and acce	eptable						
6) Supports for Ducts 5, 6 & 7 ju	udged adequate	)		· · · · · · · · · · · · · · · · · · ·				
7) Branch Duct 5 judged OK sine	ce Duct 4 can no	ot move laterally at v	vall penetration					
8) Branch Duct 10 judged OK						·····		

CERTIFICATION: (Signatures of at least two Seismic Capability Engineers are required; one of whom is a licensed professional engineer.)

Philip A. Gazda, PE

Print or Type Name/Title

C.a. Mych

Signature

9/23/2009

Date

9/23/2009

Walter Djordjevic, PE

Print or Type Name/Title

Signature

Date

Page 125 of 172

Exhibit 5-1			Sheet	1 of	3
SCREENING AND EVALUATION WORK SHEET (SEWS)					
HVAC System I.D. VNPAB Exhaust Area 5					
Damper Equipment I.D. See M-119					
System Description and Boundaries					
PAB Exhaust system. El 8' Area 5					
HVAC System Locations and Reference Drawings M-119					
Duct Materials and Sizes Galvanized Carbon Steel - See M-119					
Linear Weight:					
Duct Insulation Total		I	Referen	ces	
+ =					
+ =					
+ =					
Concurrent Pressure and Temeprature Low Temp & Low Pressure System					
Applicability	Y	. <b>N</b>	U	N/A	
1. Operating temperature less than the temperature limitations in Table 2-1	х				
2. Plant ground spectrum enveloped by the SQUG Bounding Spectrum (Figure 2-1) and ZPAh is less than 2 Og	х				
Does duct meet applicability criteria?	х				
Pressure Boundary Integrity Review	Record of the local distances				
1. Is pressure boundary integrity required?	X				
IF the answer to the above question is NO, SKIP THIS SECTION and proceed to the Structural Integrity Review					
2. Stiffener spacings are within the guidelines	х				
3. Bolted flanged joints satisfy SMACNA requirements				X	
4. No point-supported round duct	X				
5. Flexible bellows can accommodate motions				X	
6. No additional concerns	Х				
Are the above caveats met?	X				

Page 126 of 172

Exhibit	5-1
---------	-----

Sheet 2 of 3

## SCREENING AND EVALUATION WORK SHEET (SEWS)

HVAC System I D VNPAB Exhaust Area 5				
Damper Equipment I.D. See M-119				
Structural Integrity Review	Y	N	U	N/A
1 Support spans satisfy the criteria	х			
2. Ducts are properly tied-down to the supports	X			*******
<ol> <li>Industry standard duct joints are utilized</li> </ol>				Para and a second
4. Slin joints can accommodate displacements				X
5. Bound duct joints exclude riveted lap joints	X		-	And and a second s
6. Appurtenances are positively attached to duct	X			P
7 Heavy in-line equipment is adequately restrained				X
8 No stiff branch with flexible header (See notes 4&5)	X			
9. Cantilevered duct section is attached to last support (See note	6)	X		Concernation of the second second
10. Ducts are free of corrosion detrimental to integrity	X			Land Land
11. System is free of obvious damage or defects	X			And the second sec
12. No other concerns	X		-	
Are the above caveats met?		X		
				•
Support Review		~		
1. Beam clamps are oriented to preclude slipping off the support (	Duct 14)			
2. Channel nuts have teeth or ridges				
3. No cast iron inserts		-		
4. No broken or obviously defective hardware		at 10000000000	P	-
5. Support is free of excessive corrosion			<b></b>	·
6. Welded joints appear to be of good quality				
7. Anchorage appears adequate		-	<b>.</b>	. <u></u>
8. No stiff supports or hard spots in long flexible duct runs				
9. No short, fixed ended heavily loaded rod hangers subject to po	v v			
tatigue failure		- <u></u>		
10. No additional concerns (Duct 14 support and Duct 17 ca	nulever)	- <u> </u>		-
Are the above caveats met?				•
Damper Review				
1. Damper is similar to and bounded by the seismic experience da	ita for			
dampers in Attachment B	X			
2. Damper operator/actuator not of cast iron	X	-		
3. Attached lines have sufficient slack and flexibility	X	-		-
<ol><li>Damper controls mounted separately from the damper adequa</li></ol>	itely			
anchored	8-00 <sub>10-001</sub>	-		X
5. Motor or pneumatic operator mounted on the damper has ade	quate			
anchorage and load path				X
6. Duct at the damper location free from signs of distortion that c	ould			
interfere with damper operation	X		<u></u>	
7. No other adverse concerns	·			al 1000000000000000000000000000000000000
Are the above caveats met?	X			-

.--

Page 127 of 172

Exhibit 5-1				Sheet	3 of	3
SCREENING	AND EVALUATION WORK SHEET (SEWS)					
HVAC System I.D. VNPAB Ex	haust Area 5					
Damper Equipment I.D. See M-11	9					
Seismic Interaction Review		Y	N	U	N/A	
1. Free from impact by nearby equip	oment	<u> </u>				
2. No collapse of overhead equipme	nt, distribution systems or					
masonry walls	masonry walls					
3. Able to accommodate differentia	displacements	X			· ·	
4. No other adverse concerns		<u> </u>			·	
Are the above caveats met?						
IS THE HVAC DUCT AND DAMPER SYSTEM	SEISMICALLY ADEQUATE?		<u> </u>		s	
Supports Selected for Analytical Review	1) Duct 14 2) Duct 26					
Duct System Selected for Analytical Review	v None					
Comments						
1) One support on Duct 14 chosen for A.R.						
2) One support on Duct 26 chosen for A.R.						
3) Ducts 40A, 40B, 30A are inaccessible du	e to high radiation. The ducts are small	and the vi	sible po	rtions		
appear well constructred and well support	ed. Judged OK					
4) Vent exhaust pipes on Duct 16 and Duc	19 do not pose a risk of a hard spot sin	ce the atta	achment	s points		
are near locations where the main ducts p	enetrates the wall.					
5) Duct 17 cantilevers 4 feet past last supp	ort. Calculation 09Q0839-C-001 shows	it is OK				
6) Pipeway 3 Duct is a long cantilever that	requires an end lateral support.					

CERTIFICATION: (Signatures of at least two Seismic Capability Engineers are required; one of whom is a licensed professional engineer.)

Philip A. Gazda, PE

Print or Type Name/Title

.

Signature

C. U. Mych

9/23/2009

9/23/2009

Date

Walter Djordjevic, PE

Print or Type Name/Title

Signature

Date

Page 128 of 172

.

			Exhibit 5-1			Sheet	1 of	3
	SCREENING AND	EVALUAT	ION WORK SHEET (SEWS)					
HVAC System I.D.	VNPAB EX	khaust Area	a 6					
Damper Equipment I.D	. See M-12	2						
System Description and	d Boundaries							
PAB Exhaust sys	tem. El 8' Area 6							
<b></b>								
HVAC System Location	s and Reference Dra	wings	M-122				un <sub>erti</sub> s - 1	
Duct Materials and Size	es Galvanize	ed Carbon S	Steel - See M-122					
Linear Weight:	an hannan an <sub>ba</sub> aran karan dan di Bagan yan adalah sa di Angara		· · · · · · · · · · · · · · · · · · ·					
Duct	Insulation	ı	Total		F	Referen	ces	
		=						
	Ф <sub>ана</sub> лар от 1996 г. 1999 у 1997 г. 1							
	+ 	=						
	, P	4000 8000						
Concurrent Pressure ar	nd Temeprature	Low Te	emp & Low Pressure System					
Applicability				Y	N	U	N/A	
1. Operating ten	nperature less than	the tempe	rature limitations					
in Table 2-1				X				
2. Plant ground : (Figure 2-1) and	spectrum envelope ZPAh is less than 2.	d by the SC Og	UG Bounding Spectrum	X				
Does duct meet application	ability criteria?			X				
Pressure Boundary Inte	egrity Review							
1. Is pressure bo	oundary integrity red	quired?		X	Performance and address of the second second			
IF the answer to	the above question	n is NO, SKI	P THIS SECTION and					
proceed to the S	Structural Integrity I	Review						
2. Stiffener spac	ings are within the	guidelines		X				
3. Bolted flange	d joints satisfy SMA	CNA requir	ements				X	
4. No point-supp	ported round duct						X	
5. Flexible bellov	ws can accommodat	te motions			P		X	
6. No additional	concerns			X	Manual 2010	·		
Are the above caveats	met?			X	Paramiti and			

Page 129 of 172

## Exhibit 5-1

Sheet 2 of 3

# SCREENING AND EVALUATION WORK SHEET (SEWS)

HVAC System I.D.	VNPAB Exhaust Area 6				
Damper Equipment I.D.	See M-122				
Structural Integrity Review	Y	N	U	N/A	
1. Support spans satisfy t	he criteria	X			
2. Ducts are properly tied	l-down to the supports	X			
3. Industry standard duct	joints are utilized	X			
4. Slip joints can accomm	odate displacements				X
5. Round duct joints excl	ude riveted lap joints				X
6. Appurtenances are pos	sitively attached to duct				_ <u>_ X</u>
7. Heavy in-line equipme	nt is adequately restrained				_ <u>_ X</u>
8. No stiff branch with fle	exible header	X			
9. Cantilevered duct sect	ion is attached to last support (N	ote 2)	X		
10. Ducts are free of corr	osion detrimental to integrity	X	-		and Burkeysterning
11. System is free of obvi	ous damage or defects	X			
12. No other concerns		X			
Are the above caveats met?			X		_
Support Review					
1 Ream clamps are orier	ated to preclude slipping off the support	Х			
2. Channel nuts have tee	th or ridges				- <u> </u>
3. No cast iron inserts		X			
4. No broken or obviousl	v defective hardware	X			and Annual Contraction of the second
5. Support is free of exce	ssive corrosion	>			
6. Welded joints appear	to be of good quality				- <u> </u>
7. Anchorage appears ad	equate	~~~>			
8. No stiff supports or ha	rd spots in long flexible duct runs	>			
9. No short, fixed ended	heavily loaded rod hangers subject to poten	ntial			
fatigue failure		>			
10. No additional concer	ns	>	(		
Are the above caveats met?		>	(		
Damper Review					
1. Damper is similar to a	nd bounded by the seismic experience data	for			
dampers in Attachment I	в	>	(		
2. Damper operator/actu	lator not of cast iron	>	(		***** ********************************
3. Attached lines have su	fficient slack and flexibility	Stapped and			X
4. Damper controls mou	nted separately from the damper adequatel	ly			
anchored		-			X
5. Motor or pneumatic o	perator mounted on the damper has adequ	ate			
anchorage and load path					X
6. Duct at the damper lo	cation free from signs of distortion that cou	ld			
interfere with damper o	peration	>	< <u> </u>		
7. No other adverse cond	cerns	)	(		
Are the above caveats met?		>	(		

Page 130 of 172

	Exhibit 5-1			Sheet	3 of	3
SC	CREENING AND EVALUATION WORK SHEET (SEWS)					
HVAC System I.D.	VNPAB Exhaust Area 6					
Damper Equipment I.D.	See M-122					
Seismic Interaction Review		Y	N	U	N/A	
	earby equipment Id equipment, distribution systems or differential displacements erns et? <u>R SYSTEM SEISMICALLY ADEQUATE?</u> Review <u>None</u> tical Review <u>None</u>		X			
regarding a stiff branch and flex	ible header.		concert			
2) Pipeway 4 Duct is a long cant	ilever that requires a lateral support at the end.					
CERTIFICATION: (Signatures of a a licensed professional engineer	t least two Seismic Capability Engineers are required r.)	d; one of	whom is	5		

Philip A. Gazda, PE

Print or Type Name/Title

C.a. Mych

9/23/2009

Date

Signature

9/23/2009

Walter Djordjevic, PE

Print or Type Name/Title

Signature

Date

Page 131 of 172

Exhibit 5-1					Sheet 1	L of	3
	SCREENING AND EVALUAT	TION WORK SHEET (SEWS)					
HVAC System I.D.	VNPAB Exhaust Are	a 8					
Damper Equipment I.D.	Ñone						
System Description and Bo	oundaries						
PAB Exhaust system	n. El 8', - 5'-3" and - 19'-3".	<u>.</u>					
HVAC System Locations ar	nd Reference Drawings	M-134 and M-135					
Duct Materials and Sizes	Galvanized Carbon	Steel - See M-119					
Linear Weight:				<u> </u>			
Duct	Insulation	Total		F	leferen	ces	
+	=		<u> 1997 - 1997 - 1997 - 1997 - 1997</u>				
			<u></u>				, ,
+ ·							
Concurrent Pressure and	Temeprature Low T	emp & Low Pressure System					<u></u>
Applicability			Y	Ν	U	N/A	
1. Operating tempe	erature less than the temp	erature limitations					
in Table 2-1			X				-
2. Plant ground spe	ctrum enveloped by the S	QUG-Bounding Spectrum					
(Figure 2-1) and ZPA	Ah is less than 2.0g		X	<b></b>			-
Does duct meet applicabil	lity criteria?		<u> </u>	<b>-</b>			
Pressure Boundary Integri	ity Review					·	
1. Is pressure boun	dary integrity required?		X	·			-
IF the answer to the	e above question is NO, SK	(IP THIS SECTION and					
proceed to the Stru	ictural Integrity Review						
2. Stiffener spacing	s are within the guidelines	; (Duct 37)		<u> </u>			-
<ol><li>Bolted flanged jo</li></ol>	ints satisfy SMACNA requi	irements	1			<u> </u>	-
4. No point-suppor	ted round duct (Only very	small ducts, Ducts 41&42)		\		X	-
5. Flexible bellows	can accommodate motion:	S		<u></u>			-
6. No additional co	ncerns				<u></u>		-
Are the above caveats me	et?		<b>,</b> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	X			

#### Exhibit 5-1

Sheet 2 of 3

## SCREENING AND EVALUATION WORK SHEET (SEWS)

HVAC System I.D. VNPAB Exhaust Area 8				
Damper Equipment I.D. None				
Structural Integrity Review	. Y	N	U	N/A
1. Support spans satisfy the criteria (Duct 15)		X		
2. Ducts are properly tied-down to the supports (Duct 29)		X		
3. Industry standard duct joints are utilized	X			
4. Slip joints can accommodate displacements				X
5. Round duct joints exclude riveted lap joints		*******		X
6. Appurtenances are positively attached to duct	have been a second state			X
7. Heavy in-line equipment is adequately restrained				X
8. No stiff branch with flexible header	X	Real Property in the local day		-
9. Cantilevered duct section is attached to last support	X	-		
10. Ducts are free of corrosion detrimental to integrity	X			-
11. System is free of obvious damage or defects	X			
12. No other concerns	X			to the second second
Are the above caveats met?		X		
Support Review				
1. Beam clamps are oriented to preclude slipping off the support				х
2 Channel nuts have teeth or ridges				X
3 No cast iron inserts	X			
4 No broken or obviously defective hardware (Duct 39)		X		
5 Support is free of excessive corrosion	X			
6. Welded joints appear to be of good quality				-X.
7 Anchorage appears adequate	X			
8 No stiff supports or hard spots in long flexible duct runs	X			
9 No short fixed ended heavily loaded rod hangers subject to potential				
fatigue failure	х			
10. No additional concerns	X			
Are the above caveats met?	in case of the second	X		
				•
Damper Review				
<ol> <li>Damper is similar to and bounded by the seismic experience data for</li> </ol>				V
dampers in Attachment B			-	. <u> </u>
2. Damper operator/actuator not of cast iron				- <u>X</u>
3. Attached lines have sufficient slack and flexibility				. <u> </u>
<ol><li>Damper controls mounted separately from the damper adequately</li></ol>				
anchored			<b></b>	X
5. Motor or pneumatic operator mounted on the damper has adequate				V
anchorage and load path				- <u>X</u>
6. Duct at the damper location free from signs of distortion that could				
interfere with damper operation				- <u>X</u>
7. No other adverse concerns				X
Are the above caveats met?				-

Page 133 of 172

	Exhibit 5-1				Sheet 3 of		3
S	CREENING AND EV	VALUATION WORK SHEET (SE	EWS)				
HVAC System I.D.	VNPAB Exhaust	Area 8					
Damper Equipment I.D.	None						
Seismic Interaction Review			Y	N	U	N/A	
<ol> <li>Free from impact by r</li> <li>No collapse of overhe masonry walls</li> <li>Able to accommodate</li> <li>No other adverse con</li> </ol>	<ol> <li>Free from impact by nearby equipment</li> <li>No collapse of overhead equipment, distribution systems or masonry walls</li> <li>Able to accommodate differential displacements</li> <li>No other adverse concerns Are the above caveats met?</li> </ol>						
IS THE HVAC DUCT AND DAMP	ER SYSTEM SEISM al Review No	ICALLY ADEQUATE?		X			
Duct System Selected for Analy Comments	tical Review	None					
1) Duct 37 has top stiffeners ei	ther missing or be	nt - Outlier					
<ul> <li>3) Duct 15 is unsupported at D</li> <li>3) Duct 29 has a support at the slip off - Outlier</li> <li>4) Duct 39 has broken support</li> </ul>	e Duct 29 & 36 junc at floor penetratio	ction which is not screwed to	o the duct and cou	Id allo	ow duct t	to	

CERTIFICATION: (Signatures of at least two Seismic Capability Engineers are required; one of whom is a licensed professional engineer.)

Philip A. Gazda, PE

.

Print or Type Name/Title

G.U. Mych Signature

9/23/2009 Date

9/23/2009

Walter Djordjevic, PE

Print or Type Name/Title

Signature

Date

Page 134 of 172

	Exhibit 5-1				Sheet 1	of	3		
SCREENING AND EVALUATION WORK SHEET (SEWS)									
HVAC System I.D.	CREFS, Control Room ceiling ducts and control room bathroom			n					
Damper Equipment I.D. S	ment I.D. See M-109								
System Description and Boundarie	es								
Control Room Emergency F	iltration System (CR	EFS)							
HVAC System Locations and Refer	ence Drawings	M-109							
Duct Materials and Sizes	Galvanized Carbon St	teel with flexible insulation. See	M-109						
Linear Weight:									
Duct I	Insulation Total			References					
+									
	eners i d'Alleman eners de Calification de Cal	•							
4									
4									
Concurrent Pressure and Temepra	ature Low Ter	mp & Low Pressure System							
Applicability				Ν	U	N/A			
1. Operating temperature less than the temperature limitations									
in Table 2-1 X									
2. Plant ground spectrum enveloped by the SQUG Bounding Spectrum									
(Figure 2-1) and ZPAh is less than 2.0g									
Does duct meet applicability criteria?									
Pressure Boundary Integrity Revie	<u>ew</u> *								
1. Is pressure boundary integrity required?			<u>x</u>						
IF the answer to the above question is NO, SKIP THIS SECTION and									
proceed to the Structural Integrity Review									
2. Stiffener spacings are within the guidelines						. <u></u>			
3. Bolted flanged joints satisfy SMACNA requirements				-		X			
4. No point-supported round duct X									
5. Flexible bellows can accommodate motions X									
6. No additional concerns									
Are the above caveats met?			<u> </u>						

## Exhibit 5-1

Sheet 2 of 3

# SCREENING AND EVALUATION WORK SHEET (SEWS)

HVAC System I.D.	CREFS					
Damper Equipment I.D. See M-109						
Structural Integrity Review	*	Y	Ν	U	N/A	
1. Support spans satisfy the criteria		х				
2. Ducts are properly tied-down to the supports		X	******			
3. Industry standard duct joints are utilized						
4. Slip joints can accommodate displacements					Х	
5. Round duct joints exclude riveted lap joints					Х	
6. Appurtenances are positively attached to duct						
7. Heavy in-line equipment is adequately restrained						
8. No stiff branch with flexible header						
9. Cantilevered duct section is attached to last support (Intake Duct)			Х			
10. Ducts are free of corrosion detrimental to integrity						
11. System is free of obvious damage or defects						
12. No other concerns						
Are the above caveats met?			X			
Current Deview Y						
Support Review *					V.	
<ol> <li>Beam clamps are oriented to preclude slipping off the support</li> </ol>					·	
<ol><li>Channel nuts have tee</li></ol>	th or ridges				·	
<ol><li>No cast iron inserts</li></ol>		<u> </u>		<b></b>		
<ol><li>No broken or obviously defective hardware</li></ol>						
5. Support is free of excessive corrosion					· ·····	
6. Welded joints appear to be-of-good quality						
7. Anchorage appears adequate				pro-		
8. No stiff supports or hard spots in long flexible duct runs				<u> </u>		
9. No short, fixed ended heavily loaded rod hangers subject to potential						
fatigue failure						
10. No additional concerns						
Are the above caveats met?					-	
Damper Review *						
1. Damper is similar to a	nd bounded by the seismic experience data for					
dampers in Attachment B						
2. Damper operator/actuator not of cast iron			h			
3. Attached lines have sufficient slack and flexibility						
4. Damper controls mounted separately from the damper adequately						
anchored						
5. Motor or pneumatic operator mounted on the damper has adequate						
anchorage and load path						
6. Duct at the damper location free from signs of distortion that could						
interfere with damper operation						
7. No other adverse concerns						
Are the above caveats met?		Х			_	
SCREENING AND EVALUATION WORK SHEET (SEWS)						
--	----------	-----------	---------			
SCILLINING AND EVALOAMON WORKSHEET (SEWS)						
HVAC System I D CREES						
Damper Equipment I D See M-109						
Seismic Interaction Review Y N	U	N/A				
1. Free from impact by nearby equipmentX						
2. No collapse of overhead equipment, distribution systems or						
masonry walls X						
3. Able to accommodate differential displacements						
4. No other adverse concerns X						
Are the above caveats met?						
IS THE HVAC DUCT AND DAMPER SYSTEM SEISMICALLY ADEQUATE?						
Supports Solocted for Applytical Review None						
Duct System Selected for Analytical Review None						
Comments						
* 1) The HVAC ductwork and plena for most of the CREFS are covered with a lightweight insulatin	ng mate	erial the	at			
obstructs viewing of some of the duct supports and duct stiffeners. The material is in place not only	for ins	ulatior				
but also to improve the leak tightness of the system. However, the recirculation duct for the CREFS is	s un-in	sulated	1			
which allowed the SRT to examine the construction, stiffener spacing, hanger spacing and type, and	mater	ial				
condition of the ductwork. This examination of the recirculation duct indicated the same type and q	uality	of				
construction as that found for the VNPAB system: therefore the SRT considered it reasonable to adju	udge th	at				
the number and location of CREES stiffeners and duct supports within the insulated CREES systems of	confor	n to				
the SMACNA code requirements and that the duct construction is adequate. The dead load, seismic	c and p	ressur	2			
stresses in the CREFS ducts, duct stiffeners, and duct supports were evaluated based on this approac	ch.					
2) The intake duct is separated from the charcoal filter plenum by a rubber bellows therefore the du	ıct is a					
cantilever in the lateral direction Outlier						
3) The control room ceiling ducts and bathroom exhaust were examined by the SRT. Ceiling panels w	vere re	moved	<u></u>			
to examine the ducts. The ducts vary in size from 24"x24" to approximately 16"x10". The small duct	ts are g	general	ly			
supported by strut anchors on approximately 8' centers. These insulated ducts are very lightweight	and ar	e judge	ed			
acceptable by the SRT.						
In general all Control Room ceiling and bathroom exhaust ducts appear well constructed and well su	upporte	ed and				
judged OK by SRT.						
	:-					
CERTIFICATION: (Signatures of at least two Seismic Capability Engineers are required; one of whom i	15					
a licensed professional engineer.)						
C. C. Might	9/21/	2009				
Print or Type Name/Title Signature		Date	<u></u>			

Walter Djordjevic, PE

Print or Type Name/Title

W JUNY

9/21/2009

Date

Signature

.

Page 137 of 172

# ATTACHMENTS LARs

1

\_\_\_\_

### Exhibit 5-3

### Sheet 1 of

## HVAC DUCT SUPPORT ANALYTICAL REVIEW TRACKING SUMMARY

HVAC Duct System <u>Designation</u>	Plant <u>Location</u>	Selection <u>Number</u>	Final <u>Resolution</u>	Initials/ <u>Date</u>
VNPAB	Aux Bldg	LAR No. 1	Add new support	MMD/10-16-09
VNPAB	Aux Bldg	LAR No. 2	Acceptable	MMD/10-16-09
VNPAB	Aux Bldg	LAR No. 3	Acceptable	MMD/10-16-09
VNPAB	Aux Bldg	LAR No. 4	Acceptable	MMD/10-16-09
VNPAB	Aux Bldg	LAR No. 5	Acceptable	MMD/10-16-09
VNPAB	Aux Bldg	LAR No. 6	Add new support	MMD/10-16-09
VNPAB	Aux Bldg	LAR No. 7	Add new steel	MMD/10-16-09

Page 139 of 172

		Exhibit 5-2		Sheet 1 of	2
	DUCT S	UPPORT ANALYTICAL REVIE	N DATA SHEET		
HVAC Duct System:	VNPAB		Selection No.:	LAR No. 1	
Plant Location:	Int Location: Auxiliary Building Central El. 8'-0"				
Description and Sketch					

See attached sheet.

CERTIFICATION: (Signatures of at least two Seismic Capability Engineers are required; one of whom is a licensed professional engineer.)

Philip A. Gazda, PE

Print or Type Name/Title

Signature

G. U. Mych

10/16/2009

Date

failure M Selan

Marlene M. Delaney, PE

Print or Type Name/Title

Signature

10/16/2009

Exhibit 5-2 LAR No. 1

The hanger for the 104x26 duct with a tributary span equal to one half of 113" also supports the 52x22 duct with an 11' span.



		Exhibit 5-2		Sheet 1 of	2
	DUCT SI	JPPORT ANALYTICAL REVIEW	DATA SHEET		
HVAC Duct System:	VNPAB		Selection No.:	LAR No. 2	-
Plant Location: Auxiliary Building Central El. 8'-0"					

Description and Sketch

See attached sheet.

CERTIFICATION: (Signatures of at least two Seismic Capability Engineers are required; one of whom is a licensed professional engineer.)

Philip A. Gazda, PE

Print or Type Name/Title

G.U. Mych

Signature

10/16/2009

Date

line M Selane

10/16/2009

Marlene M. Delaney, PE

Print or Type Name/Title

Signature

Exhibit 5-2 LAR No. 2

LAR No. 2

Multiple ducts and a pipe are attached to the duct support. Tributary length for both ducts is 58".



Page 143 of 172

		Exhibit 5-2		Sheet 1 of	2
	DUCT S	UPPORT ANALYTICAL REVIEV	V DATA SHEET		
HVAC Duct System:	VNPAB		Selection No.:	LAR No. 3	
Plant Location: Auxiliary Building Central El. 8'-0"					
Description and Sketch	L				

See attached sheet.

CERTIFICATION: (Signatures of at least two Seismic Capability Engineers are required; one of whom is a licensed professional engineer.)

Philip A. Gazda, PE

Print or Type Name/Title

Signature

C. t. Shych

10/16/2009

Date

Marlene M. Delaney, PE

live M Selary

10/16/2009

Print or Type Name/Title

Signature

Exhibit 5-2 LAR No. 3 Page 144 of 172 Sheet 2 of 2

LAR No. 3

Duct attached to cable tray support that supports an 18" ladder cable tray and 5 conduits. Tributary length for the duct is 75".



Page 145 of 172

		Exhibit 5-2		Sheet 1 of	2
	DUCT SI	JPPORT ANALYTICAL REVIE	N DATA SHEET		
HVAC Duct System:	VNPAB		Selection No.:	LAR No. 4	
Plant Location:		Auxiliary Building Cen			
Description and Sketch					

See attached sheet.

CERTIFICATION: (Signatures of at least two Seismic Capability Engineers are required; one of whom is a licensed professional engineer.)

G.U. Mych

Signature

10/16/2009

Date

Mailene M Selan

Marlene M. Delaney, PE

Philip A. Gazda, PE

Print or Type Name/Title

Print or Type Name/Title

Signature

Date

10/16/2009

Support for 54" diameter duct – support cannot fall off blocked by RMWT. Anchorage blocked by fireproofing (assume welding).



Page 147 of 172

		Exhibit 5-2		Sheet 1 of	3
	DUCT SU	PPORT ANALYTICAL REVIEW	V DATA SHEET		
HVAC Duct System:	VNPAB		Selection No.:	LAR No.5	
Plant Location:		Auxiliary Building Cent			
Description and Sketch					

See attached sheet.

CERTIFICATION: (Signatures of at least two Seismic Capability Engineers are required; one of whom is a licensed professional engineer.)

Philip A. Gazda, PE

Print or Type Name/Title

C. tr. Mych

Signature

10/16/2009

Date

Yailere M Selary

Marlene M. Delaney, PE

Print or Type Name/Title

Signature

10/16/2009

Exhibit 5-2 LAR No. 5

Support for 54" diameter duct



Elevation



Plan

.

.

Page 150 of 172

		Exhibit 5-2		Sheet 1 of	2
	DUCT SUI	PPORT ANALYTICAL REVIEW	/ DATA SHEET		
HVAC Duct System:	VNPAB		Selection No.:	LAR No. 6	
Plant Location:	Auxiliary Building Central El. 8'-0"				
Description and Sketch					

See attached sheet.

CERTIFICATION: (Signatures of at least two Seismic Capability Engineers are required; one of whom is a licensed professional engineer.)

Philip A. Gazda, PE

Print or Type Name/Title

Signature

G. U. Mych

10/16/2009

Date

Mailere My Selan

10/16/2009

Marlene M. Delaney, PE

Print or Type Name/Title

Signature

Exhibit 5-2 LAR No. 6

The hanger for the 34x14 duct is supported by a horizontal unistrut member clamped to conduits.



	PBNP VNPAB and CREFS Seismic Verification S&A Report No. 09Q0839-R-001 Revision 1			Page 152 of 172		
		Exhibit 5-2		Sheet 1 of	2	
	DUCT	SUPPORT ANALYTICAL REVIE	W DATA SHEET			
HVAC Duct System:	VNPAB		Selection No.:	LAR No. 7		
Plant Location:						
Description and Sketch						

See attached sheet.

CERTIFICATION: (Signatures of at least two Seismic Capability Engineers are required; one of whom is a licensed professional engineer.)

Philip A. Gazda, PE

Print or Type Name/Title

Signature

G.U. Mych

10/16/2009

Date

Mailere M Selan

10/16/2009

Marlene M. Delaney, PE

Print or Type Name/Title

Signature

Exhibit 5-2 LAR No. 7

The support for duct 26x16 is attached to a cable tray support and to the support for a duct 26x16.



Page 154 of 172

	Exh	ibit 5-4		Sheet 1 of	2
	HVAC DL	JCT SYSTEM			
	ANALYTICAL RE	VIEW DATA SHE	ET		
HVAC Duct System:	VNPAB		Selection No.: LAR No.	8	
Plant Location: <u>'VNP/</u>	\B El. 8'-0" Duct no. 1				
Description and Sketch					
			-		
	•				
see attache	d sketch				
CERTIFICATION: (Signatu a licensed professional e	res of at least two Seismic Ca ngineer.)	pability Enginee	rs are required; one of w	'hom is	

Philip A. Gazda, PE

Print or Type Name/Title

10/16/2009

Date

G.a. Mych Signature Mailine M. Selan

Marlene M. Delaney, PE

Print or Type Name/Title

Signature

10/16/2009

Exhibit 5-4 LAR No. 8

Consider the longitudinal load due to seismic for the largest duct in the evaluation.

◀	58'	→	
	104x26 duct		<b>A</b>
			7'

Page 156 of 172

# ATTACHMENTS HSOS

•

	Exhibit 5-5	Sheet 1 of 1
HVAC SYSTEM OUTLIER	M OUTLIER SHEET (HSOS)	
1. OUTLIER IDENTIFICATION AND LOCATION		· · · ·
Location Area 4 -Auxiliary Building El. 8'-0" Du	ict no. 1	
2. OUTLIER ISSUE IDENTIFICATION		
a. Identify the screening guidelines that are ne analysis criteria.	ot met, or indicate if the analytical reviev	v selection fails the
Applicability	Damper Review	
Pressure Boundary Integrity	Interaction Effects	
Structural Integrity Review	Support Analytical Review	x (LAR 1)
Support Review	Duct Analytical Review	
b. Describe all the reasons for the outlier:		
The horizontal angle of the support is overs	stressed due to dead load because of an	
additional duct attached to the angle.		
3 PROPOSED METHOD OF OUTLIER RESULTIO	ON (OPTIONAL)	'
a. Define the proposed method(s) for resolvin	ng the outlier:	
Add a new vertical trapeze support at or ne	ear the existing overstressed support.	
h Provide information needed to implement	proposed method(s) for resolving the ou	tlier:
b. Howe mornation needed to implement		
	· · · · · · · · · · · · · · · · · · ·	
CERTIFICATION: (Signatures of at least two Seismi	ic Capability Engineers are required; one	of whom is
a licensed professional engineer.)		
	Cn. Marke	
Philip A. Gazda, PE		10/16/2009
Print or Type Name/Title	Signature	Date
·· · ·	Mailine M Selary	_
	`` J	
Marlene M. Delaney, PE		10/16/2009
Print or Type Name/Title	Signature	Date

•

E	whibit 5-5	Sheet 1 of1
HVAC SYSTEM (	OUTLIER SHEET (HSOS)	
OUTLIER N	0	
1. OUTLIER IDENTIFICATION AND LOCATION		
HVAC System I.D. VNPAB		
Location Area 5 - Aux Bldg. El. 8'-0" -Duct no. 14		
2. OUTLIER ISSUE IDENTIFICATION		
<ul> <li>a. Identify the screening guidelines that are not analysis criteria.</li> </ul>	met, or indicate if the analytical review	w selection fails the
Applicability	Damper Review	
Pressure Boundary Integrity	Interaction Effects	
Support Review	- Support Analytical Review	X (LAR 6)
Describe all the reacons for the outlier	·	
The existing support is not adequate since it u	utilizes friction clamps attached to vert	tically spanning
conduits.		
3 PROPOSED METHOD OF OUTLIER RESULTION	(OPTIONAL)	
a. Define the proposed method(s) for resolving	the outlier:	
Add a new support at or near the existing sup	port. The existing support cannot be	removed because
other components are attached to it.		
b Provide information needed to implement or	apased method(s) for resolving the ou	utlier:
	******	
CERTIFICATION: (Signatures of at least two Seismic (	Capability Engineers are required; one	of whom is
a licensed professional engineer.)		
Dhilin A. Condo DE	G.C. Myen	10/16/2009
Print or Type Name/Title	Signature	Date
·· ·	Ma, OIAI AIA. 1.	
	, prince , y suckey	
Marlene M. Delaney, PE		10/16/2009
Print or Type Name/Title	Signature	Date

.

Exhibit	5-5	Sheet 1 of1
HVAC SYSTEM OUTL	IER SHEET (HSOS)	
OUTLIER NO.	3	
1. OUTLIER IDENTIFICATION AND LOCATION		
HVAC System I.D. VNPAB		
Location Area 5 - Aux Bldg. El 8'-0" - Duct no. 26		
2. OUTLIER ISSUE IDENTIFICATION		
<ul> <li>a. Identify the screening guidelines that are not met, analysis criteria.</li> </ul>	or indicate if the analytical reviev	v selection fails the
Applicability	Damper Review	
Pressure Boundary Integrity	Interaction Effects	
Structural Integrity Review	Support Analytical Review Duct Analytical Review	<u>x (LAK 7)</u>
b. Describe all the reasons for the outlier:	·	A Designation of the second
The existing structural steel that supports two duc	t sections is overstressed due to t	he dead load
of the ducts.		
	(IONAL)	
- Define the proposed method(c) for receiving the o	utlier:	
Replace the existing horizontal steel assembly (Z s	haped member) with a new fabric	cated support.
h Provide information needed to implement propos	ed method(s) for resolving the ou	tlier:
CERTIFICATION: (Signatures of at least two Seismic Capal a licensed professional engineer.)	oility Engineers are required; one	of whom is
	O. M. I	
Philip A Gazda PE	G.C. Major	10/16/2009
Print or Type Name/Title	Signature	Date
	Mailere M Selary	_
	``` J	10/16/2009
Mariene M. Delaney, PE	Signaturo	
Print or Type Name/Title	JIBIIALULE	Date

.

HVAC SYSTEM OUTLIER SHEET (HSOS) OUTLIER NO4         1. OUTLIER IDENTIFICATION AND LOCATION         HVAC System 1.D. VNPAB         Location       Pipeway 3       Area 5 Duct no. 30A	E	Exhibit 5-5	Sheet 1 of1
OUTLIER NO.       4         1. OUTLIER IDENTIFICATION AND LOCATION         HVAC System I.D.       VNPAB         Location       Pipeway 3         Area 5 Duct no. 30A	HVAC SYSTEM	OUTLIER SHEET (HSOS)	
1. OUTLIER IDENTIFICATION AND LOCATION         HVAC System I.D.       VNPAB         Location       Pipeway 3       Area 5 Duct no. 30A         2. OUTLIER ISSUE IDENTIFICATION       a. Identify the screening guidelines that are not met, or indicate if the analytical review selection fails the analysis criteria.         Applicability       Damper Review         Pressure Boundary Integrity       Interaction Effects         Structural Integrity Review       X         Support Review       Duct Analytical Review         b. Describe all the reasons for the outlier:	OUTLIER	NO. 4	
HVAC System I.D.       VNPAB         Location       Pipeway 3       Area 5 Duct no. 30A         2. OUTLIER ISSUE IDENTIFICATION       a. Identify the screening guidelines that are not met, or indicate if the analytical review selection fails the analysis criteria.         Applicability       Damper Review         Pressure Boundary Integrity       Interaction Effects         Structural Integrity Review       x         Support Review       Duct Analytical Review         b. Describe all the reasons for the outlier:	1. OUTLIER IDENTIFICATION AND LOCATION		
Location       Pipeway 3       Area 5 Duct no. 30A         2. OUTLIER ISSUE IDENTIFICATION       a. Identify the screening guidelines that are not met, or indicate if the analytical review selection fails the analysis criteria.         Applicability       Damper Review         Pressure Boundary Integrity       Interaction Effects         Structural Integrity Review       X         Support Review       Duct Analytical Review         b. Describe all the reasons for the outlier:	HVAC System I.D. VNPAB		
2. OUTLIER ISSUE IDENTIFICATION  a. Identify the screening guidelines that are not met, or indicate if the analytical review selection fails the analysis criteria.  Applicability Pressure Boundary Integrity Interaction Effects Structural Integrity Review X Support Review Duct Analytical Review b. Describe all the reasons for the outlier: The methods is a factor of the structure in the structure is a structure in the structure in the structure is a structure in the structure in the structure is a structure in the structure in the structure is a structure in the structure	Location Pipeway 3 Area 5 Duct no. 30A		
2. OUTLIER ISSUE IDENTIFICATION  a. Identify the screening guidelines that are not met, or indicate if the analytical review selection fails the analysis criteria.   Applicability Damper Review   Pressure Boundary Integrity Interaction Effects   Structural Integrity Review x   Support Review Duct Analytical Review   b. Describe all the reasons for the outlier:			
<ul> <li>a. Identify the screening guidelines that are not met, or indicate if the analytical review selection fails the analysis criteria.</li> <li>Applicability Damper Review Interaction Effects</li> <li>Structural Integrity Review Support Analytical Review</li> <li>b. Describe all the reasons for the outlier:</li> </ul>	2. OUTLIER ISSUE IDENTIFICATION		
Applicability       Damper Review         Pressure Boundary Integrity       Interaction Effects         Structural Integrity Review       x         Support Review       Duct Analytical Review         b. Describe all the reasons for the outlier:	<ul> <li>a. Identify the screening guidelines that are not analysis criteria.</li> </ul>	t met, or indicate if the analytical review	v selection fails the
Pressure Boundary Integrity       Interaction Effects         Structural Integrity Review       x         Support Review       Duct Analytical Review         b. Describe all the reasons for the outlier:	Applicability	Damper Review	
Structural Integrity Review     x     Support Analytical Review       Support Review     Duct Analytical Review       b. Describe all the reasons for the outlier:	Pressure Boundary Integrity	Interaction Effects	
Support Review        Duct Analytical Review          b. Describe all the reasons for the outlier:	Structural Integrity Review x	Support Analytical Review	
b. Describe all the reasons for the outlier:	Support Review	Duct Analytical Review	
where the second state is a state for the law device the device of	b. Describe all the reasons for the outlier:		
The cantilevered duct section is not acceptable for dead load and seismic stresses.	The cantilevered duct section is not acceptat	ble for dead load and seismic stresses.	
		······································	
3 PROPOSED METHOD OF OUTLIER RESULTION (OPTIONAL)	3 PROPOSED METHOD OF OUTLIER RESULTION	I (OPTIONAL)	
a. Define the proposed method(s) for resolving the outlier:	a. Define the proposed method(s) for resolving	the outlier:	
Add a lateral support at the end of the duct span.	Add a lateral support at the end of the duct	span.	
		· ·	
b. Provide information needed to implement proposed method(s) for resolving the outlier:	b. Provide information needed to implement p	roposed method(s) for resolving the out	tlier:
			an a shina an a saan waxaa waxaa ahaan ahaan ahaan ahaan ahaa ahaa a
CERTIFICATION: (Signatures of at least two Solsmic Capability Engineers are required; one of whom is	CERTIFICATION: (Signatures of at least two Soismis	Capability Engineers are required: one	of whom is
a licensed professional engineer)	centrication: (signatures of at least two seisinic	capability Engineers are required, one o	JI WHOTH IS
	a iterised professional engineer.		
C. R. Mach		C. M. March	
Philip A. Gazda, PE 10/16/2009	Philip A. Gazda, PE		10/16/2009
Print or Type Name/Title Signature Date	Print or Type Name/Title	Signature	Date
		M. A	
Maillere M Selary		Martene M Selary	~
Marlene M. Delanev, PE 10/16/2009	Marlene M. Delanev. PE	$\bigcirc$	10/16/2009
Print or Type Name/Title Signature Date	Print or Type Name/Title	Signature	Date

	Exhibit 5-5	Sheet 1 of1
HVAC SYSTEM OUTLIER	I OUTLIER SHEET (HSOS) NO5_	
1. OUTLIER IDENTIFICATION AND LOCATION		
HVAC System I.D. VNPAB Location Pipeway 4 - Duct 25		
2. OUTLIER ISSUE IDENTIFICATION		<u>,</u>
<ul> <li>a. Identify the screening guidelines that are no analysis criteria.</li> </ul>	t met, or indicate if the analytical review select	tion fails the
Applicability	Damper Review	
Pressure Boundary Integrity	Interaction Effects	
Structural Integrity Review x	Support Analytical Review	44-11. mail # 1. mail # 1. mail # 1.
Support Review	Duct Analytical Review	19 May - 19 Mar - 19 Mar - 19 Mar - 19 Mar - 19
<ul> <li>b. Describe all the reasons for the outlier: The cantilevered duct section is not acceptal</li> </ul>	ble for dead load and seismic stresses.	
		n <sub>nan</sub> - 1999 - 1999 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 19
3 PROPOSED METHOD OF OUTLIER RESULTION	N.(OPTIONAL)	
a. Define the proposed method(s) for resolving	g the outlier:	
Add a lateral support at the end of the duct	span.	
b. Provide information needed to implement p	proposed method(s) for resolving the outlier:	
		<u></u>
CERTIFICATION: (Signatures of at least two Seismic	Capability Engineers are required; one of who	m is
a licensed professional engineer.)		
	G.C. Myon	10/10/2020
Philip A. Gazda, PE	<b>6</b> ******	
Print or Type Name/Title	Signature	Date
	Mailere M Selary	
Martine M. Deler et D.	, , , , , , , , , , , , , , , , , , ,	10/16/2009
Wariene W. Delaney, PE		
Print or Type Name/Title	Signature	Date

·

Exh	ibit 5-5	Sheet 1 of1
	JTLIER SHEET (HSOS)	
1 OUTLIER IDENTIFICATION AND LOCATION		
Location Unit 1 RHR Hx Room Area 8		
2. OUTLIER ISSUE IDENTIFICATION		
<ul> <li>a. Identify the screening guidelines that are not m analysis criteria.</li> </ul>	et, or indicate if the analytical review selection	on fails the
Applicability	Damper Review	
Pressure Boundary Integrity	Interaction Effects	****
Structural Integrity Review x	Support Analytical Review	H
Support Review	Duct Analytical Review	m
b. Describe all the reasons for the outlier:		· .
The duct is a cantilever section without a latera	I support at the end of the run where it turns	s into
	· · · · · · · · · · · · · · · · · · ·	
3 <u>PROPOSED</u> METHOD OF OUTLIER RESULTION (0	OPTIONAL)	
a Define the proposed method(s) for resolving th	e outlier:	
Add a lateral knee brace support at the duct co	rner near column line N/10.	
b Browide information paeded to implement pro-	accod method/s) for resolving the outlier	
b. Provide mormation needed to implement prop		
CERTIFICATION, (Signatures of at least two Sairmis Ca	pability Engineers are required; one of whom	nic
a licensed professional engineer.)	pablicy Engineers are required, one of whom	
	G.a. Mych	
Philip A. Gazda, PE		10/16/2009
Print or Type Name/Title	Signature	Date
	Marline M Selary	
Marlene M. Delaney, PE	$\bigcirc$	10/16/2009
Print or Type Name/Title	Signature	Date

•

Page 163 of 172

Sheet 1 of 1
view selection fails the
a a gana da a fara ya a da a sa a a a a a a a a a a a a a a
- and a start and a start - and a start a start and a start - a start a start - a start - a start - a start - a
<b>*******************************</b> *******
**************************************
·
******
e outlier:
ane of whom is
ine of whom is
10/16/2009
Date
4
ナ
10/16/2009
Date

Page 164 of 172

	Exhibit 5-5	Sheet 1 of1
HVAC SYST	TEM OUTLIER SHEET (HSOS)	
OUTL	IER NO. <u>8</u>	
1. OUTLIER IDENTIFICATION AND LOCATION		
HVAC System I.D. VNPAB		
Location Unit 2 RHR Hx Room - Duct No. 38	}	
2. OUTLIER ISSUE IDENTIFICATION		
<ul> <li>a. Identify the screening guidelines that are analysis criteria.</li> </ul>	e not met, or indicate if the analytical review	selection fails the
Applicability	Damper Review	
Pressure Boundary Integrity	Interaction Effects	
Structural Integrity Review x	Support Analytical Review	
Support Review	Duct Analytical Review	
b. Describe all the reasons for the outlier:		
The end support of the duct does not ha	ve a positive connection between the duct a	nd the support
such that the duct could slide off the ang	gle member.	
·		
	· · · · · · · · · · · · · · · · · · ·	
3 <u>PROPOSED</u> METHOD OF OUTLIER RESUL	TION (OPTIONAL)	
a. Define the proposed method(s) for resol	lving the outlier:	
Fasten existing support to the duct near	column line N/13.	
		<u></u>
b. Provide information needed to impleme	ent proposed method(s) for resolving the out	lier:
		*****
CERTIFICATION: (Signatures of at least two Seis	smic Capability Engineers are required; one o	f whom is
a licensed professional engineer.)		
, o ,		
	G.a. Myen	
Philip A. Gazda, PE	بر المراجع الم	10/16/2009
Print or Type Name/Title	Signature	Date
	Mailere M Selary	
	· · · · ·	
Marlene M. Delaney, PE		10/16/2009
Print or Type Name/Title	Signature	Date

.

•

	Exhibit 5-5	Sheet 1 of 1
HVAC SYS	TEM OUTLIER SHEET (HSOS)	
OUTL	IER NO9_	
1. OUTLIER IDENTIFICATION AND LOCATION		
HVAC System I.D. CREFS		
Location Fans W14A & B, W13B1 & B2		
2. OUTLIER ISSUE IDENTIFICATION		
a. Identify the screening guidelines that are analysis criteria.	e not met, or indicate if the analytical revie	w selection fails the
Applicability x	Damper Review	<u></u>
Pressure Boundary Integrity	Interaction Effects	•
Structural Integrity Review	Support Analytical Review	
Support Review	Duct Analytical Review	
b. Describe all the reasons for the outlier:		
Vibration isolators are used at the ancho	rage of the subject fans which are not seis	mically qualified.
3 PROPOSED METHOD OF OUTLIER RESUL	τιον (ορτιοναι)	
<ul> <li>Define the proposed method(c) for recol</li> </ul>	ving the outline:	
a. Denne the proposed method(s) for reso	fans	
Provide seismic anchorage details at the	10115.	
b. Provide information needed to impleme	nt proposed method(s) for resolving the o	utlier:
CERTIFICATION: (Signatures of at least two Seis	mic Capability Engineers are required; one	e of whom is
a licensed professional engineer.)		
	G.C. Myoh	
Philip A. Gazda, PE		10/16/2009
Print or Type Name/Title	Signature	Date
	Mailere M Selare	
Marlene M. Delaney, PE	<u> </u>	10/16/2009
Print or Type Name/Title	Signature	Date

Page 166 of 172

	Exhibit 5-5	Sheet 1 of 1
HVA	AC SYSTEM OUTLIER SHEET (HSOS) OUTLIER NO. 10	
1. OUTLIER IDENTIFICATION AND LOCATI	 ON	
HVAC System I.D. CREFS		
Location Duct No. 43		
2. OUTLIER ISSUE IDENTIFICATION		
<ul> <li>a. Identify the screening guidelines t analysis criteria.</li> </ul>	hat are not met, or indicate if the analytical review se	lection fails the
Applicability	Damper Review	
Pressure Boundary Integrity	Interaction Effects	
Structural Integrity Review x	Support Analytical Review	
Support Review	Duct Analytical Review	
b. Describe all the reasons for the ou	tlier:	
The cantilevered duct section is no	ot acceptable for dead load and seismic stresses.	······································
3 <u>PROPOSED</u> METHOD OF OUTLIER	RESULTION (OPTIONAL)	,
a. Define the proposed method(s) for	r resolving the outlier:	
Add a lateral support at the intake	e duct near the bellows.	1971 - 1971 - 1971 - 1971 - 1971 - 1971 - 1971 - 1971 - 1971 - 1971 - 1971 - 1971 - 1971 - 1971 - 1971 - 1971 -
h Provide information needed to im	plement proposed method(s) for resolving the outlier	r:
		•
CERTIFICATION: (Signatures of at least tw a licensed professional engineer.)	vo Seismic Capability Engineers are required; one of v	vhom is
	On the 1.	
DEBLA Conde DE	G. U. Mazora	10/16/2000
Philip A. Gazda, PE	Signaturo	0710/2009
Print of Type Name/ Iffie	Signature	Dale
	Mailine M Selary	
Marlana M. Dolanov, Dr	, , , O,	10/16/2000
		10/10/2003
Print or Type Name/Title	Signature	Date

	Exhibit 5-5	Sheet 1 of1
HVAC SY	STEM OUTLIER SHEET (HSOS)	
OUT	TLIER NO. <u>11</u>	
1. OUTLIER IDENTIFICATION AND LOCATION		
HVAC System I.D. VNPAB		
2. OUTLIER ISSUE IDENTIFICATION		
<ul> <li>a. Identify the screening guidelines that a analysis criteria.</li> </ul>	are not met, or indicate if the analytical review	v selection fails the
Applicability	Damper Review	
Pressure Boundary Integrity	Interaction Effects	
Structural Integrity Review	Support Analytical Review	<u>x</u>
Support Review	Duct Analytical Review	
b. Describe all the reasons for the outlier The shell anchorage was overstressed the overstress condition.	: for the vertical capacity check. A refined ana	lysis eliminated
3 <u>PROPOSED</u> METHOD OF OUTLIER RESU a. Define the proposed method(s) for res No additional resolution required.	JLTION (OPTIONAL) olving the outlier:	
b. Provide information needed to implem	nent proposed method(s) for resolving the ou	tlier:
CERTIFICATION: (Signatures of at least two Se a licensed professional engineer.)	eismic Capability Engineers are required; one	of whom is
	G.a. March	
Philip A. Gazda, PE		10/16/2009
Print or Type Name/Title	Signature	Date
	Mailine M Selary	~
Marlene M. Delaney, PE	0	10/16/2009
Print or Type Name/Title	Signature	Date

Exhib	bit 5-5	Sheet 1 of1
HVAC SYSTEM OU	TLIER SHEET (HSOS)	
OUTLIER NO.	12	
1. OUTLIER IDENTIFICATION AND LOCATION		
HVAC System I.D. VNPAB		
Location Duct No. 4		
2 OUTUER ISSUE IDENTIFICATION		
- Identify the crooping guidelines that are not me	t or indicate if the analytical review	selection fails the
analysis criteria.	t, or maleate in the analytical review.	
Applicability	Damper Review	
Pressure Boundary Integrity	Interaction Effects	5
Structural Integrity Review	Support Analytical Review	<u>X</u>
Support Review	Duct Analytical Neview	
b. Describe all the reasons for the outlier: The shell anchorage was overstressed for the ver	tical capacity check A refined analy	sis eliminated
the overstress condition.	thear capacity eneck. Arrenned analy	
	<mark></mark>	
3 PROPOSED METHOD OF OUTLIER RESULTION (O	PTIONAL)	
a Define the proposed method(s) for resolving the	outlier:	
No additional resolution required.		
b Dury ide information provided to implement propo	and mathed/s) for recoluing the out	
. b. Provide information needed to implement prope	sed method(s) for resolving the odd	
CEPTIEICATION: (Signatures of at least two Seismic Can	ability Engineers are required: one o	f whom is
a licensed professional engineer.)	ability Engineers are required, one o	
	G.C. Major	10/10/2000
Philip A. Gazda, PE	Signature	10/16/2009
Print of Type Name/ fille		bute
	Mailine M Selary	
Marlene M. Delaney, PE	0	10/16/2009
Print or Type Name/Title	Signature	Date

# ATTACHMENTS KENNEDY INDEPENDENT PEER REVIEW REPORT

.

.

Page 170 of 172 **RPK-91029** 

Independent Peer Review of Seismic Verification of Point Beach Nuclear Plant (PBNP) Primary Auxiliary Building Exhaust (VNPAB) and Control Room Emergency Filtration System (CREFS) Ductwork, Associated Supports, and Components

Robert P. Kennedy

October 29, 2009

## 1. Introduction

I have performed an independent peer review of the seismic verification of the Point Beach Nuclear Plant (PBNP) Primary Auxiliary Building Exhaust (VNPAB) and Control Room Emergency Filtration System (CREFS) ductwork, associated supports, and components documented in Refs. 1 and 2. This seismic verification was conducted by Mr. Walter Djordievic and Mr. Phil Gazda of Stevenson & Associates (S&A) and was performed in accordance with the criteria presented in Ref. 3. I am very familiar with the qualifications of both Messrs. Djordjevic and Gazda and can attest to their qualifications to perform these seismic verifications in accordance with the Ref. 3 criteria.

Previously (February 7, 2004), I performed a peer review of the seismic evaluation guidelines presented in an earlier version of Ref. 3. All of my previous review comments have been incorporated into Ref. 3. Therefore, I support the use of the Ref. 3 guidelines for the seismic verification of HVAC ductwork and damper systems.

Within my experience, these Ref. 3 guidelines were initially applied for the seismic verification of the Turbine Building exhaust ductwork for Hatch Nuclear Plant Unit 1. I performed (November, 2004) the independent peer review of that seismic verification. Subsequently, the U.S. Nuclear Regulatory Commission has accepted and approved this Hatch seismic verification of ductwork.

A primary goal of my independent peer review of the Point Beach Nuclear Plant (PBNP) seismic verification of HVAC ductwork presented in Refs. 1 and 2 was to verify that it was conducted in accordance with the criteria of Ref. 3 in at least the same degree of rigor as that previously performed for Hatch Unit 1.

### 2. Scope of Peer Review

Initially (September 25), I conducted a one day peer review seismic walkdown of the PBNP ductwork, associated supports, and component which were being assessed by the S&A engineers. My walkdown was subsequent to the seismic walkdowns previously conducted by the S&A engineers. I was accompanied by Mr. Phil Gazda of S&A during my walkdown. The purpose of my walkdown was to assess:

 $\mathcal{RPK}$ 

**Structural Mechanics Consulting** 

28625 Mountain Meadow Road, Escondido, CA 92026 (760)751-3510 • (760) 751-3537 (Fax) email: bob@rpkstruct.com

- (1) the extent to which the Ref. 3 guidelines were being followed,
- (2) the thoroughness with which the seismic walkdown had been conducted,
- (3) the reasonableness of the assumptions being made, and of the preliminary results obtained, and
- (4) whether I observed any potential deficiencies not previously identified by S&A engineers.

During my peer review seismic walkdown, I observed essentially 100% of all ductwork, and components being assessed by S&A engineers that were accessible outside of locked radiation areas. I also observed a significant fraction of ductwork supports visible from the floor. I did not request that fan plena be opened so that I could observe the fan mounting therein. However, through a review of the Seismic Evaluation Work Sheets (SEWS), I have confirmed that the Seismic Review Team (SRT) did open these fan plena and observed the fan mounting therein. For example, see the photos attached to the SEWS between Pages 70 and 123 of Ref. 1.

In addition to my peer review walkdown, I have reviewed Ref. 1 which documents the seismic verification performed, and Ref. 2 which provides the analytical reviews performed for this verification. The purpose of these reviews was to:

- (1) confirm compliance with the Ref. 3 guidelines,
- (2) fully understand the methodology and basis for any assumptions made by the SRT for situations which could not be observed,
- (3) appropriateness of all calculations,
- (4) completeness in describing and resolving outliers, and
- (5) adequacy of documentation of the seismic verification program.

I did not perform any numerical check of calculations since such checks are a checker function, and not a peer review function. However, I did note that all calculations do appropriately contain the initials of both the preparer and the reviewer.

## 3. Overall Findings

This experience based seismic verification of the Point Beach Nuclear Plant Primary Auxiliary Building exhaust and Control Room Emergency Filtration System ductwork, associated supports, and components is of very high quality. It fully complies with the guidelines of Ref. 3. The documentation is excellent. The walkdown team performed a very thorough and competent evaluation. I didn't identify any open issues
not considered by the walkdown team. I concur with the methodology used, and all assumptions made by the SRT. I fully concur with the findings and conclusions of Ref. 1.

So long as the outlier issues identified in Section 9 of Ref. 1 are resolved as suggested therein, I have confidence in the seismic adequacy of the reviewed ductwork, supports, and associated components for the Point Beach Nuclear Plant design ground motion level.

## References

- 1. *PBNP VNPAB and CREFS Seismic Verification*, Report No. 09Q0839-R-001, Stevenson & Associates, October 2009
- 2. Analysis and Documentation for Report 09Q0839-R-001, Calculation No. 09Q0839-C-001, Stevenson & Associates, October 2009
- 3. Seismic Evaluation Guidelines for HVAC Duct and Damper Systems, Final Report 1014608, Revision to Report 1007896, Electric Power Research Institute (EPRI), December 2006