

Dominion Nuclear Connecticut, Inc. Millstone Power Station Rope Ferry Road Waterford, CT 06385

JUL 2 5 2010

U.S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, DC 20555 Serial No. 10-430 NSSL/MLC R0 Docket No. 50-423 License No. NPF-49

DOMINION NUCLEAR CONNECTICUT, INC. MILLSTONE POWER STATION UNIT 3 INSERVICE INSPECTION PROGRAM – OWNER'S ACTIVITY REPORT

Dominion Nuclear Connecticut, Inc. (DNC) hereby submits the American Society of Mechanical Engineers (ASME), Section XI, Form OAR-1, Owner's Activity Report, for the period from November 25, 2008 through Refueling Outage 13, completed on May 18, 2010 for Millstone Power Station Unit 3. The enclosure is in accordance with the requirements of ASME Code Case N-532-4.

If you have any questions or require additional information, please contact Mr. William Bartron at (860) 444-4301.

Sincerely,

A. J. Jofdan

Site Vice President – Millstone

Enclosure:

1. Inservice Inspection Program – Owner's Activity Report, Refueling Outage 13.

Commitments made in this letter: None

150.1

Serial No. 10-430 MPS3 Owner's Activity Report Docket No. 50-423 Page 2 of 2

U.S. Nuclear Regulatory Commission Region I 475 Allendale Road King of Prussia, PA 19406-1415

1.] _þ

. : . .

20

C. J. Sanders Project Manager - Millstone Power Station U.S. Nuclear Regulatory-Commission One White Flint North 11555 Rockville Pike Mail Stop O-8B3 Rockville, MD 20852-2738

NRC Senior Resident Inspector Millstone Power Station

CC:

ENCLOSURE 1

INSERVICE INSPECTION PROGRAM - OWNER'S ACTIVITY REPORT

REFUELING OUTAGE 13

DOMINION NUCLEAR CONNECTICUT, INC. MILLSTONE POWER STATION UNIT 3

MILLSTONE POWER STATION

UNIT NO. 3

OWNER'S ACTIVITY REPORT

REFUELING OUTAGE 13

Revision 0

Contents:

OAR-1 Report Number: MP3-3R13

Table 1:Items with Flaws or Relevant Conditions That RequiredEvaluation for Continued Service.

 Table 2:
 Abstract of Repairs/Replacement Activities Required for Continued Service

Prepared By:

ISI Program Owner

Reviewed By:

1). (1) eseru Independent Review

Reviewed By:

Authorized Nuclear Inservice Inspector

Date: 07/07/10

Date: 07 07 2010

Date: 07/08/800

Dominion	•

Form OAR-1 Owner's Activity Report

Attachment 1, ER-AA-ISI-100





Attachment 1, ER-AA-ISI-100

Page 2 of 8

A PA		A 1141			A 41 1	· ·
		('onditiono	I hot Doguisod			L A B U A A
\mathbf{n}	Flaws or Relevants		1020 6000000	Evaluation 1		SHIVE
 \mathbf{r}		OOHAILIORD				
 					-,	
			, =			

Examination Category and Item Number	Item Description	Evaluation Description
C-F-2 / C5.51	Weld FWS-11-FW-7-BM	Linear surface indication, evaluated as
		acceptable in accordance with ASME
		Section XI, IWB 3514 (UIR MP3-10-002).
C-F-1 / C5.11	Weld SIL-504-FW-15	Linear surface indication, evaluated as
		acceptable in accordance with ASME
		Section XI, IWB 3514 (UIR MP3-10-003).
F-A / F1.20A	Pipe support	Spherical bearing partially dislodged.
	3-FWS-4-PSR064	The support condition has been
· · · · · ·		evaluated by Engineering and found to
· .	· · · · · ·	be acceptable with support performing its
		intended design function
		(UIR MP3-10-004). Rework performed
		to reposition bearing to restore support
		back to original design condition.
F-A / F1.20A	Pipe support	Pipe clamp out of alignment with support
	3-FWS-4-PSR011	strut. The support condition has been
		evaluated by Engineering and found to
		be acceptable with support performing its
		intended design function
		(UIR MP3-10-005). Rework performed
	· ·	to realign clamp to restore support back
		to original design condition.
F-A / F1.20A	Pipe support	Loose locking nut on strut assembly.
	3-SIL-1-PSST493	The support condition has been
		evaluated by Engineering and found to
,	· · ·	be acceptable with support performing its
	· · ·	intended design function (UIR MP3-10-
		006). Rework performed to tighten
		locking nut to restore support back to
<u> </u>		original design condition.
F-A/F1.10C		Spring can setting outside its tolerance.
	3-503-1-2301121	welveted by Engineering and ferred to
	· ·	evaluated by Engineering and found to
		functioning within its working range and
		design value (LIIP MP2 10,007)
E A / E1 200	Pipo support	Spring con softing outside its telerance
F-A/F1.200		The support condition has been
	0-FV0-1-F00HUUZ	evaluated by Engineering and found to
		be acceptable with the spring can
		functioning within its working range and
		design value (LIR MP3-10-008)
· · · · · · · · · · · · · · · · · · ·		design value (UIR MP3-10-008).



Attachment 1, ER-AA-ISI-100

Page 3 of 8

Examination	Item Description	Evaluation Description
Category and Item Number		
F-A / F1.10A	Pipe support	Spherical bushing partially dislodged and
	3-RCS-1-PSR 68	loose locking nut on strut assembly. The
		support condition has been evaluated by
		Engineering and found to be acceptable
		with support performing its intended
		design function (UIR MP3-10-009).
· .		Rework performed to tighten loose lock
:		nut to restore support back to its original
	1	design condition
C-H/C7 10	Restricting orifice	Evidence of leakage detected at holted
	3BSS*BO39B	connection Evaluated in accordance
		with ASME Code Case N-566-2 and
		found to be acceptable for continued
		service (M3- $EV_10-0021$)
CHI/C7 10		Evidence of leakage detected at holted
0-117 07.10	Valve SSIN AVOUDA	connection Evaluated in accordance
		with ASME Code Case N 566 2 and
		Found to be acceptable for continued
	,	
D. D. / D45 40		Service (W3-EV-10-0022).
D-P / D 15.10	valve SRCS AV6036D	Evidence of leakage detected at bolted
		with ASME Code Cose N 566 2 and
		with ASINE Code Case N-500-2 and
	· *	apprice (M2 EV 10.0010)
D D / D45 10		Evidence of lockage detected at holted
B-P7 B15.10	valve SRCS V 147	expression Evolusted in accordance
		with ASME Code Cose N 566 2 and
		found to be acceptable for continued
		pround to be acceptable for continued
		Evidence of lockage detected at holted
D-r / D 10. IV	Valve SILUS AVOUS/D	
	· · · ·	with ASME Code Case N SEC 2 and
· · · · ·		with ASIVE Code Case N-300-2 and
	:	Tound to be acceptable for continued
	N/ L 0011 19 /04 7	Service (M3-EV-10-0019).
B-P / B15.10	Valve 3SIL-V017	Evidence of leakage detected at bolted
	68 m	connection. Evaluated in accordance
		WIT ASME CODE Case N-566-2 and
	;	Tound to be acceptable for continued
		j service (IVI3-EV-10-0019).
В-Р / В15.10		Evidence of leakage detected at bolted
		connection. Evaluated in accordance
		With ASME CODE Case N-500-2 and a second sec
		Tound to be acceptable for continued
	L.,	service (M3-EV-10-0019).



Attachment 1, ER-AA-ISI-100

Page 4 of 8

Examination Category and Item Number	Item Description	Evaluation Description		
B-P / B15.10	Valve 3RCS*V031	Evidence of leakage detected at bolted		
		connection. Evaluated in accordance		
	· · · · · ·	with ASME Code Case N-566-2 and		
		found to be acceptable for continued		
· · · · · · · · · · · · · · · · · · ·		service (M3-EV-10-0019).		
B-P / B15.10	Valve 3RCS*MV8003A	Evidence of leakage detected at bolted		
	1. A	connection. Evaluated in accordance		
		with ASME Code Case N-566-2 and		
· · ;		found to be acceptable for continued		
		service (M3-EV-10-0019).		
B-P / B15.10	Valve 3RCS*MV8003C	Evidence of leakage detected at bolted		
· · ·		connection. Evaluated in accordance		
		with ASME Code Case N-566-2 and		
· .		found to be acceptable for continued		
ļ		service (M3-EV-10-0019).		
С-Н / С7.10	Valve 3SIL*V987	Evidence of leakage detected at bolted		
		connection. Evaluated in accordance		
		with ASME Code Case N-566-2 and		
		found to be acceptable for continued		
	1	Service (M3-EV-10-0019).		
B-P / B15.10	Valve 3SIL-V015	Evidence of leakage detected at bolted		
		connection. Evaluated in accordance		
		with ASIME Code Case N-500-2 and		
· · · ·		nound to be acceptable for continued		
P. D. / P15 10	1 Value 2019 \$ 41/9704 A	Evidence of lookage detected at holted		
B-P7 B15.10	Valve SKHS WV070TA	connection Evaluated in accordance		
		with ASME Code Case N-566-2 and		
	· · ·	found to be acceptable for continued		
	·	service (M3-EV-10-0019)		
C-H/C7 10	Valve 3SiL*V012	Evidence of leakage detected at bolted		
		connection. Evaluated in accordance		
		with ASME Code Case N-566-2 and		
		found to be acceptable for continued		
		service (M3-EV-10-0019).		
C-H / C7.10	Valve 3SIL*V013	Evidence of leakage detected at bolted		
		connection. Evaluated in accordance		
		with ASME Code Case N-566-2 and		
		found to be acceptable for continued		
,	<i>i</i> .	service (M3-EV-10-0019).		
B-P / B15.10	Valve 3RHS*MV8702B	Evidence of leakage detected at bolted		
· · ·		connection. Evaluated in accordance		
		with ASME Code Case N-566-2 and		
• • • •		found to be acceptable for continued		
		service (M3-EV-10-0019).		



Attachment 1, ER-AA-ISI-100

Page 5 of 8

Examination Category and Item Number	Item Description	Evaluation Description		
С-Н / С7.10	Valvè 3SIL*V006	Evidence of leakage detected at bolted connection. Evaluated in accordance with ASME Code Case N-566-2 and found to be acceptable for continued service (M3-EV-10-0019).		
C-H / C7.10	Valve 3SIL*V007	Evidence of leakage detected at bolted connection. Evaluated in accordance with ASME Code Case N-566-2 and found to be acceptable for continued service (M3-EV-10-0019).		
B-P / B15.10	Valve 3RCS*AV8037C	Evidence of leakage detected at bolted connection. Evaluated in accordance with ASME Code Case N-566-2 and found to be acceptable for continued service (M3-EV-10-0019).		
B-P / B15.10	Valve 3RCS*V108	Evidence of leakage detected at bolted connection. Evaluated in accordance with ASME Code Case N-566-2 and found to be acceptable for continued service (M3-EV-10-0019).		
B-P / B15.10	Valve 3RCS*V102	Evidence of leakage detected at bolted connection. Evaluated in accordance with ASME Code Case N-566-2 and found to be acceptable for continued service (M3-EV-10-0019).		
B-P / B15.10	Valve 3RCS*AV8153	Evidence of leakage detected at bolted connection. Evaluated in accordance with ASME Code Case N-566-2 and found to be acceptable for continued service (M3-EV-10-0019).		
B-P / B15.10	Valve 3RCS*LC459	Evidence of leakage detected at bolted connection. Evaluated in accordance with ASME Code Case N-566-2 and found to be acceptable for continued service (M3-EV-10-0019).		
C-H / C7.10	Valve 3CHS*AV8146	Evidence of leakage detected at bolted connection. Evaluated in accordance with ASME Code Case N-566-2 and found to be acceptable for continued service (M3-EV-10-0019)		
С-Н / С7.10	Valve 3CHS*AV8147	Evidence of leakage detected at bolted connection. Evaluated in accordance with ASME Code Case N-566-2 and found to be acceptable for continued service (M3-EV-10-0019).		

And the second s



Fcrm OAR-1 Owner's Activity Report

Attachment 1, ER-AA-ISI-100 Page 6 of 8

Examination Category and Item Number	Item Description	Evaluation Description
C-H / C7.10	Valve 3CHS*AV8149C	Evidence of leakage detected at bolted
, , , , , , , , , , , , , , , , , , ,		connection. Evaluated in accordance
		with ASME Code Case N-566-2 and
·		found to be acceptable for continued
		service (M3-EV-10-0019).
B-P / B15.10	Valve 3SIH*V887	Evidence of leakage detected at bolted
		connection. Evaluated in accordance
·		with ASME Code Case N-566-2 and
		found to be acceptable for continued
	· · ·	service (M3-EV-10-0019).
C-H / C7.10	Valve 3RHS*V021	Evidence of leakage detected at bolted
	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	connection. Evaluated in accordance
		with ASME Code Case N-566-2 and
	· · · · .	found to be acceptable for continued
	<u></u>	service (M3-EV-10-0008).
C-H / C7.10	Flow element 3RHS*FE618	Evidence of leakage detected at bolted
		connection. Evaluated in accordance
		with ASME Code Case N-566-2 and
		found to be acceptable for continued
	· · · · · · · · · · · · · · · · · · ·	service (M3-EV-10-0014).
С-Н / С7.10	Heat exchanger 3RHS*E1A	Evidence of leakage detected at bolted
	· · · · ·	connection. Evaluated in accordance
		with ASME Code Case N-566-2 and
	×.7	found to be acceptable for continued
		service (M3-EV-05-0016 Rev. 3).
С-Н / С7.10	Heat exchanger 3RHS*E1B	Evidence of leakage detected at bolted
		connection. Evaluated in accordance
		with ASME Code Case N-566-2 and
	- 15	found to be acceptable for continued
0.11/07/40		service (M3-EV-05-0016 Rev. 3).
С-н/С/.10	Valve 3KHS*V029	Evidence of leakage detected at bolted
		connection. Evaluated in accordance
		with ASME Code Case N-506-2 and
		convice (M2 EV 05 0012)
0 4 / 07 40	Chostople flance	Evidence of lockage detected at holted
	SKIIS FLOID	with ASME Code Case N 566 2 and
		found to be acceptable for continued
		service (M3-FV-10-0013)
C-H / C7 10	Pump 3RHS*P1R	Evidence of leakage detected at holted
0-117 07.10		connection Evaluated in accordance
		with ASME Code Case N-566-2 and
		found to be acceptable for continued
		service (M3-EV-10-0013)
<u></u>	^	service (NI3-EV-10-0013).



Attachment 1, ER-AA-ISI-100

Page 7 of 8

Table 2 Abstract of Repair/Replacement Activities Required for Continued Service

Code Class Item Description Description of Work		Date Completed	Repair/Replacement Plan Number	
3	Pipe Spool	Replace piping at the CCE Heat Exchanger.	04/19/2010	53102322014
3	Pipe Spool	Fabricate and install replacement inlet and outlet channel head flanges for heat exchanger 3EGS*E2A.	10/28/2008 (work completed during previous period)	53M30517833
2	Valve 3CHS*CV8152	Replace body to bonnet fasteners on 3CHS*CV8152.	02/27/2009	53102234037
3	Pipe Spool	Coatings and Cladding repair of the Inlet/Outlet Channel Head Flange for Heat Exchanger 3CCP*E1C.	03/21/2009	53102195579
3	Pipe Spool	Replace a portion of line 3-SWP-002-383-3.	03/26/2009	53102188990
3	Valve 3SWP*V696	Replace plug valve 3SWP*V696.	03/28/2009	53102241929
3	Valve 3SWP*V866	Replace flange bolting for valve 3SWP*V866.	06/01/2009	53102203933
3	Valve 3SWP*V867	Replace Flange Bolting for Valve 3SWP*V867.	06/01/2009	53102203934
3	Pipe Spool	Replace brazed pipe line 3-SWP-003-101-3 with butt welds IAW DM3-00- 0076-08.	07/22/2009	53102268587
3	Pump 3CCP*P1B	Replace casing studs and nuts on pump 3CCP*P1B.	10/31/2009	53102292101
3	Pipe Spool	Replace a portion of Line 3-SWP-003-59-3 in the ESF building.	12/28/2009	53102313861
3	Pipe Spool	Replace a portion on 3SWP-150-103-3(A-) due to a pinhole leak.	01/19/2010	53102318157
1	Valves 3RCS*SV8095A and 3RCS*SV8096A	Replace reactor head vent valves 3RCS*SV8095A and 3RCS*SV8096A.	04/02/2010	53102334985
3	Pipe Spool	Replace a portion of line on 3SWP-150-61-3 and 3SWP-150-064-03(B-).	04/18/2010	53102317914
2	Pipe Spool	Rework / remove unacceptable surface indications located on line 3-FWS-018-86-2.	04/19/2010	53102341108



Form OAR-1 Owner's Activity Report

Attachment 1, ER-AA-ISI-100

Page 8 of 8

Table 2 Abstract of Repair/Replacement Activities Required for Continued Service

Code Class	Item Description	Description of Work	Date Completed	Repair/Replacement Plan Number
3	Pipe Spool	Replace pipe on line 3- SWP-006-50-3.	04/21/2010	53M30709070
.3	Heat:Exchanger 3EGS*E1B	Install replacement tube assembly in diesel generator intercooler heat exchanger 3EGS*E1B.	04/23/2010	53M30709271
2	Snubber 3-MSS-1-PSSP0450	Replace pivot pin on snubber for pipe support 3-MSS-1-PSSP0450.	04/25/2010	53102261798
1	Snubber 3-RCS-1-PSSP0928	Replace snubber for pipe support 3-RCS-1- PSSP0928.	04/28/2010	53102262076
3	Pipe Spool	Replace a portion of line 3-SWP-150-72-3, Outlet line from 3CCI*E1A.	05/07/2010	53102347647
2	Pipe Spool	Remove arc-strike on line 3-CHS-003-072-2 IAW CRED CR380222.	05/08/2010	53102351290