

Tennessee Valley Authority, Post Office Box 2000, Decatur, Alabama 35609-2000

August 16, 2010

10 CFR 50.73

ATTN: Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555-0001

> Browns Ferry Nuclear Plant, Unit 2 Facility Operating License No. DPR-52 NRC Docket No. 50-260

Subject: Licensee Event Report 50-260/2010-004-00

The enclosed Licensee Event Report provides details of inadvertent isolation of the high pressure coolant injection system during testing activities. The Tennessee Valley Authority is submitting this report in accordance with 10 CFR 50.73(a)(2)(v)(D), any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident.

There are no new regulatory commitments contained in this letter. Should you have any questions concerning this submittal, please contact Dan Williamson, Acting Site Licensing and Industry Affairs Manager, at (256) 729-2636.

Respectfully,

APol

K. J. Polson Vice President

Enclosure cc (w/ Enclosure):

> NRC Regional Administrator - Region II NRC Senior Resident Inspector - Browns Ferry Nuclear Plant



NRC FORM 3	66	U.S. NUCLE	AR REGULA	TORY (COMMIS	SION	APPR	VED	BY OMB NO.	3150-0104		ΕX	KPIRES	6 08/3	31/2010
(9-2007)							Estima Repor	ted bu	urden per response ssons learned are	to comply wi incorporated	th this mar into the l	ndatory co licensing	llection i	reques and f	st: 80 hours. fed back to
							indust Servic	ry. So e Brar	end comments reg rch (T-5 F52), U.S	arding burde Nuclear Rec	n estimate sulatory Co	to the R	lecords Washir	and F	OIA/Privacy DC 20555-
	LICEN	SEE EVENT R	EPORT (L	.ER)			0001,	or by	internet e-mail to	infocollects	Dnrc.gov, a	and to th	e Desk	Office	er, Office of
			•	,			Budge	t, Was	shington, DC 2050	B. If a means	used to im	npose an i	nformati	on coli	lection does
							a pers	on is n	ot required to resp	ond to, the info	per, the Ni connation co	C may no ollection.	ot condu	ct of s	ponsor, and
1. FACILITY	NAME						2. DO	CKE	TNUMBER		3. PAC	GE			
Browns F	erry Nucl	ear Plant Unit 2	2						05000260				1 of 5	i	
4. TITLE: H	PCI Isolat	ion During Time	e Delay R	elay Ca	alibratio	on									
5. EVENT	DATE	6. LER NU	MBER	7. F	REPORT	DATE			8. OT	HER FAC	LITIES	INVOL	VED		
MONTH DAY	YEAR			молтн	DAY	YEA		сіціту І /А	NAME				DOCKE	T NUI N/	MBÉR
06 16	2010	2010 - 004	- 00	08	16	201			NAME				DOCKE		MBER
						SUAN				TS OF 40	CED S.	(Chook		4 0.01	
9. UPERATIN	GMODE		2PUKT 13 3		ED PUR 0 2203(a)	30AN (3)(i)	1 10 1	א בר ר			CFR 9:		all tha 3(a)(2	n app Nyii	UIY)
		20.2201(d)			0.2203(a)	(3)(ii)		Ē	350.73(a)(2)	(i)(C) (ii)(A)	ſ		'3(a)(2)(viii))(A)
1		20.2203(a)(1)		0.2203(a))(4)			50.73(a)(2)	(ii)(B)	Ì	50.7	'3(a)(2)(viii))(B)
		20.2203(a)(2	2)(i)	5	0.36(c)(1))(i)(A)		Ē		(iii)	Ī	50.7	'3(a)(2)(ix)((A)
10. POWER L	EVEL	20.2203(a)(2	2)(ii)	5	0.36(c)(1))(ii)(A)			50.73(a)(2)	(iv)(A)	[50.7	'3(a)(2)(x)	
		20.2203(a)(2	2)(iii)		0.36(c)(2)			50.73(a)(2)	(v)(A)	[73.7	'1(a)(4)	
89		20.2203(a)(2	2)(iv)		0.46(a)(3 0.73(a)(2)(ii) Viv a v		Ļ	」 50.73(a)(2) □ 50.73(a)(2)	(v)(B) (v)(C)	l	∐ 73.7	/1(a)(5)	
		\Box 20.2203(a)(2	2)(v) 2)(vi)		0.73(a)(2 0.73(a)(2)(i)(A))(i)(B)		L D	」 50.73(a)(2) 【 50.73(a)(2)	(v)(C) (v)(D)	Ĺ	Speci	TER ify in Absti	ract bek	ow or in NRC
			12		SEE COI							Form	368A		
NAME			14					1110		TELÈ	PHONE N	UMBER (nclude A	Area C	ode)
Eric Bates,	Licensing	Engineer									2	256-61	4-718	80	
		13. COMPLETE C		OR EAC	н сомр	ONEN	IT FAIL	URE	DESCRIBED	IN THIS F	REPORT	Г			
CAUSE	SYSTEM	COMPONENT	MANU- FACTURER	REP T	ORTABLE		CAUSE		SYSTEM	COMPON	ENT	MANU FACTUR	ER	REP T	ORTABLE O EPIX
						×									
	14.	SUPPLEMENTAL	. REPORT B	EXPECT	ED				15. EX	PECTED	N	MONTH	DA	۲	YEAR
YES (If ye	es, complete	9 15. EXPECTED S	SUBMISSIO	N DATE,		NO			SUBM D/	ISSION ATE		NA	N/	1	NA
ABSTRACT (Li	mit to 1400 s	paces, i.e., approxima	tely 15 single	spaced ty	/pewritten	lines)					·				
On	June 16, 1	2010, at 1258 (Central Da	ylight	Time (C	DT),	the H	igh	Pressure C	oolant Ir	ijectior	n (HPC	CI)		
syst	em receiv	ved an isolation	i signal du	ring th	e perfo	rman	ce of p	proc	edure 2-SF	R-3.3.6.1	6(3), t	the			
SUL	eillance f	or the HPCI tim	ne delay re	elay ca	libration	n. At	1320	hou	rs CDT, op	erations	persor	nnel			
disc	overed 2	-FCV-73-2 (HP	CI steam	ine inb	oard is	olatio	n valv	e) a	nd 2-FCV-7	73-3 (HP	Cl stea	am lin	e		
Gro		ation valve) we		и Оре		pers	onnei	ente	ered Abnorr	1907 b	rating I	INSTRUC	tion,		
	up 4 nFC veillance v	Nas re-nerform	or-04-20. ed without	incide	nt at 20	34 h	ours (vas resel al	1007 11		ו .ום	ne		
						/0-1 II			•						
Sub duri	sequent i ng the tes	nvestigation de sting of this rela	etermined ly.	that co	ntacts	1 and	l 2 of r	elay	/ 2-RLY-07	3-23A-K	9 made	e cont	act		
	-	-													
The	cause is	relay contact p	rotective l	poots fa	ailed to	prev	ent a d	cont	act pair from	n makin	g conta	act du	ring		
test	ng that re	esulted in the H	PCI Isolat	ion. II	ne cont		001S 11 T\/A h		are used du	ring the	surveil	llance	are		
of b	oot used	for circuit isolat	ion during	testing	g is a w	eak r	nainte	nan	ce practice		enung	y 011 til	nə tyf	50	
The	correctiv	e action is to su	urvey othe	r sites	and uti	lities	to det	ermi	ine what alt	ernative	"booti	ng" m	ethoc	ls	
are	available,	and implemen	t use of th	ie appr	opriate	alter	native	me	thod at BFN	N to impr	ove bo	oot			
ene	cuveness	anu reliability.													

\$

NRC FORM 366A (9-2007)			U.S. NUCLEAF	REGULAT	ORY COMMISSION
LICENSE	E EVENT R	EPORT	(LER)		
FACILITY NAME (1)	DOCKET (2)	L	ER NUMBER (6)	PAGE (3)
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Browns Ferry Nuclear Plant Unit 2	05000260	2010	004	00	2 of 5
NARRATIVE (If more space is required, use additional co	pies of NRC Form	366A) (17)			

I. PLANT CONDITION(S)

At the time of discovery, Browns Ferry Nuclear Plant (BFN), Units 1 and 3 were at approximately 100 percent power (3458 MWT) and unaffected by the event. Unit 2 was at approximately 89 percent power.

II. DESCRIPTION OF EVENT

A. <u>Event:</u>

On June 16, 2010, at 0900 Central Daylight Time (CDT), the High Pressure Coolant Injection (HPCI) [BJ] system was declared inoperable for the purpose of performing the surveillance instruction for the "HPCI Time Delay Relay Calibration" (2-SR-3.3.6.1.6(3)). Operations entered Technical Specification (TS) Limiting Condition for Operation (LCO) 3.5.1 Condition C, requiring immediate verification by administrative means that the RCIC system is operable and restoring the HPCI system to operable status in 14 days. The Reactor Core Isolation Cooling (RCIC) [BN] system was verified operable.

At 1258 CDT, the HPCI system received an isolation signal during the performance of 2-SR-3.3.6.1.6(3). Operations personnel discovered the 2-FCV-73-2 (HPCI steam line inboard isolation valve) and 2-FCV-73-3 (HPCI steam line outboard isolation valve) were isolated, at 1320 hours CDT, while removing Unit 2 Loop II Residual Heat Removal from the Suppression Pool Cooling mode of operation. Operations personnel entered Abnormal Operating Instruction, Group 4 HPCI Isolation, 2-AOI-64-2B.

At 1807 hours CDT, HPCI Auto Isolation Logic was reset.

At 2034 hours CDT, 2-SR-3.3.6.1.6(3) was re-performed without incident.

On June 17, 2010, at 0230 hours CDT, HPCI was declared operable.

Subsequent investigation determined that contacts 1 and 2 of relay 2-RLY-073-23A-K9 made contact during the testing of this relay.

TVA is submitting this report in accordance with 10 CFR 50.73(a)(2)(v)(D), as any event that could have prevented fulfillment of a safety function of structures or systems that are needed to mitigate the consequences of an accident.

B. <u>Inoperable Structures, Components, or Systems that Contributed to the Event:</u>

None

C. Dates and Approximate Times of Major Occurrences:

June 16, 2010, at 0900 hours CDT	HPCI inoperable for performance of procedure 2-SR-3.3.6.1.6(3). HPCI entered in TS LCO 3.5.1 Condition C. RCIC verified operable.
June 16, 2010, at 1258 hours CDT	HPCI isolated during 2-SR-3.3.6.1.6(3).
June 16, 2010, at 1320 hours CDT	Operations personnel discovered an isolation signal that resulted in isolation of 2-FCV-73-2 (HPCI steam line inboard isolation valve) and 2-FCV-73-3 (HPCI steam line outboard isolation valve).

NRC FORM 3	66A	·····			U.S. NUCLEAF	R REGULAT	ORY COMMISSION
(9-2007)		LICENSE			/I FR)		
						3	PAGE (3)
				YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Browns Fer	ry N	luclear Plant Unit 2	05000260	2010	004	00	3 of 5
NARRAT	ĪVE	(If more space is required, use additional cop	ies of NRC Form	366A) (17)	<u> </u>		· · · · · · · · · · · · · · · · · · ·
		June 16, 2010, at 1807 hours CDT	HPCI	Auto Isola	tion Logic res	set.	
		June 16, 2010, at 2001 hours CDT	Opera eight I 10 CF	tions pers nour NRC R 50.72(b	sonnel made a phone call in b)(3)(v)(D).	a non-eme accordan	ergency ice with
		June 16, 2010, at 2034 hours CDT	Surve withou	illance 2-8 it incident	SR-3.3.6.1.6(3	3) was re-	performed
		June 17, 2010, at 0230 hours CDT	HPCI	declared o	operable.		
	D.	Other Systems or Secondary Fu	nctions Affec	<u>ted</u>			
		None					
	Ε.	Method of Discovery					
		Operations personnel noted the HF control room panel.	CI isolation in	idicating li	ght was illumi	inated on	the main
	F.	Operator Actions					
		Operations personnel performed ad	ctions in 2-AO	I-64-2B to	reset Group	4 HPCI is	olation.
	G.	Safety System Responses					
		None					
111.	CA	USE OF THE EVENT					
	Α.	Immediate Cause					
		The immediate cause for HPCI Isol made contact during the testing of testing o	ation was con this relay.	tacts 1 an	d 2 of relay 2	-RLY-073	-23A-K9
	В.	Root Cause					
		The cause is relay contact protective contact during testing that resulted during the surveillance are made by determined that depending on this weak maintenance practice.	ve boots failed in the HPCI is y cutting off th type of boot u	to prever colation. T e fingers o sed for cir	nt a contact pa The contact bo of a heavy rub cuit isolation	air from m bots that a bber glove during tes	aking are used e. TVA has sting is a
	С.	Contributing Factors					
		None		-			
IV.	AN	ALYSIS OF THE EVENT					
	The	e HPCI system responded as design	ned by isolating	g valves 2	-FCV-73-2 ar	nd 2-FCV-	73-3.
	lt w sho sys	as determined the isolation occurred build have had contacts 2 and 4 boot tem indicated that only contact 4 wa	d from an even ed for testing. as effectively b	nt involvin Data obta ooted.	g relay 2-RLY ained from the	(-073-23A e integrate	A-K9, which ed computer
	Sul dur	osequent investigation determined c ing the testing of this relay.	ontacts 1 and	2 of relay	2-RLY-073-2	3A-K9 ma	ade contact

-2007)	366A				U.S. NUCLEA	R REGULATOR	RY COMMISSION			
5-2007)		LICENSE	E EVENT R	EPORT	(LER)					
		FACILITY NAME (1)	DOCKET (2)	I	ER NUMBER (6	5)	PAGE (3)			
				YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				
Browns Ferry Nuclear Plant Unit 2			05000260	2010	004	00	4 of 5			
NARRA	TIVE (II	f more space is required use additional co	pies of NRC Form	366A) (17)			· · · · · · · · · · · · · · · · · · ·			
	The cut-c activ How caus	boots, which are used for testing, off glove fingers. There have been rities in the past. Currently, BFN u rever, the protective boots failed to sed the HPCI isolation.	are the tips of issues with b ses two boots prevent relay	heavy rub oots comin on a relay contacts	ber gloves the ng off of the c / contact (dou 1 and 2 from r	at are shop i ontacts durir ble booting) naking conta	made from ng testing act, which			
V .	ASS	ESSMENT OF SAFETY CONSEC	QUENCES							
	The for u out o Eme accie was 3.3.6 redu	safety consequences of this event p to 14 days with the HPCI system of service for planned testing when ergency Core Cooling Systems were dents and transients assumed in the verified operable before declaring 5.1.6(3) and entering LCO 3.5.1 Co ction in the protection of the public	t were not sign n inoperable w n the isolation of re operable an ne Updated Fin HPCI system ondition C. TV c by this event	ificant. TS hen the R occurred. d remaine nal Safety inoperable A conclud	S allow contin CIC system is For this even d capable of Analysis Rep e for the perfo les that there	ued power of s operable. t, the other r mitigating de ort. The RC ormance of 2 was no sign	peration HPCI was equired esign basis IC system I-SR- ificant			
VI.	COF	CORRECTIVE ACTIONS								
	The	The corrective actions are being managed within TVA's Corrective Action Program.								
	A.	A. Immediate Corrective Actions								
		The HPCI isolation was reset. Involved employees were removed from work and an investigation was immediately performed. The testing was re-performed with a different work crew without incident.								
	В.	B. <u>Corrective Actions to Prevent Recurrence</u>								
		Survey other sites and utilities to determine what alternative "booting" methods are available, and implement use of the appropriate alternative method at BFN to improve boot effectiveness and reliability.								
VII	. ADC	DITIONAL INFORMATION								
	Α.	Failed Components								
		None								
	В.	PREVIOUS LERS ON SIMILAR	EVENTS							
		None								
	C.	Additional Information								
	The corrective action document for this report is PER 235338.									
	D. <u>Safety System Functional Failure Consideration:</u>									
	D.	Safety System Functional Fail	ure Consider	ation:						

NRC FORM 366A 9-2007)			U.S. NUCLEAR	R REGULATOR	Y COMMISSION
	ENSEE EVENT R	EPORT	(LER)		
FACILITY NAME (1)	DOCKET (2)	VEAD	LER NUMBER (6		PAGE (3)
		YEAR	NUMBER	NUMBER	
Browns Ferry Nuclear Plant Unit 2	05000260	2010	004	00	5 of 5
NARRATIVE (If more space is required, use addit	tional copies of NRC Form	366A) (17)			
E. <u>Scram With Complication</u>	ons Consideration:				
This event did not include	a reactor scram.				
VIII. COMMITMENTS					
None					
			,		