

DiabloCanyonNPEm Resource

From: Pick, Greg
Sent: Wednesday, November 10, 2010 9:39 AM
To: DiabloCanyonNPEm Resource
Subject: FW: Notification 50341635
Attachments: 50341635.pdf

From: Grebel, Terence [<mailto:TLG1@pge.com>]
Sent: Monday, November 01, 2010 8:54 AM
To: Pick, Greg
Subject: FW: Notification 50341635

From: Tan, Miranda
Sent: Friday, October 29, 2010 6:43 PM
To: Grebel, Terence
Cc: 'Terence Grebel'
Subject: Notification 50341635

Terry,

Attached is the updated notification 50341635 on the strain gauge cover plates.

Miranda

<<50341635.pdf>>

Hearing Identifier: DiabloCanyon_LicenseRenewal_NonPublic
Email Number: 2162

Mail Envelope Properties (CA7A6E1C5CB1204FA832458074C4571BFF1493B726)

Subject: FW: Notification 50341635
Sent Date: 11/10/2010 9:39:13 AM
Received Date: 11/10/2010 9:39:20 AM
From: Pick, Greg

Created By: Greg.Pick@nrc.gov

Recipients:
"DiabloCanyonNPEm Resource" <DiabloCanyonNPEm.Resource@nrc.gov>
Tracking Status: None

Post Office: R4CLSTR01.nrc.gov

Files	Size	Date & Time
MESSAGE	501	11/10/2010 9:39:20 AM
50341635.pdf	91546	

Options
Priority: Standard
Return Notification: No
Reply Requested: No
Sensitivity: Normal
Expiration Date:
Recipients Received:

U-0

Notification: **50341635**Type: **DN** Work Type: **EVAL ENGR**Description: **Evaluate the need for strain gauge PM**

Order:

Funct. Loc: **DC-0-80-F****U0 SYS 80 FACIL**Reported By: **KMMH** Kristin M. ZaitzRpt By Work Ctr: **EDC-008**

Contact Info:

Created On: **15 Sep 10 12:20**

Planner Group:

Main Wrk Ctr: **EDC-008** Zaitz Kristin - KMMH

PROBLEM DESCRIPTION

09/15/2010 12:16:45 Kristin M. Zaitz (KMMH) Phone 805/545-6058

The purpose of this notification is to evaluate the need for preventative and/or corrective maintenance to maintain a water tight seal around the containment strain gauges. This notification does not report an equipment problem. Existing drawings and descriptions of these strain gauges are not adequate for engineering to determine if a water leak path exists that could over time expose the containment rebar to corrosive conditions and pose an aging management concern. These gauges are out-of-service (abandoned in place), and do not impact the design function of the containment structure. The results of this evaluation will be used to enhance containment inspections and the associated aging management program, if deemed necessary.

Background:

Strain gauges were installed at various locations on the containment structure to assess the performance of the structure during the Structural Integrity Test. For Unit 1, this test was conducted between August 1 and 11, 1975. For Unit 2, this test was conducted between October 26 and November 5, 1977. These strain gauges were required only for these tests #they are no longer in service.

Event Date **15 Sep 10**Notif Required By **31 Dec 11**Station Sig.: **5 Other**

U-0

Notification: **50341635**

Type: **DN** Work Type: **EVAL ENGR**

Description: **Evaluate the need for strain gauge PM**

Order:

The strain gauges are mounted on the containment structure no. 18 reinforcing bars. The cable used for the strain gauges wiring to the strain indication equipment is routed through a flexible conduit that is embedded in the concrete, extending from the gauge area to junction boxes attached to the outside surface of containment. A cover plate with silicone caulking is installed at the surface of containment, but the details of this configuration are vague. Refer to the following drawings for more information:

103512

663075-654

663075-657

Containment structure inspections performed in accordance with ASME Section XI Subsection IWL have noted locations where the strain gauge cover plates have partially disengaged or fallen out of place. The IWL concrete inspections have investigated the condition of the concrete around these cover plates and found there to be no degradation or indications of corrosion of the underlying reinforcing bars. Although there is currently no evidence of corrosion on the surface, the configuration of the strain gauges may be such that there is a water leak path that could extend from the surface of containment to the rebar in the long term. If this path exists, then inspections and PM should focus on ensuring a watertight seal at these locations to preclude degradation of the rebar at these locations.

09/15/2010 13:50:37 David G. Wong (DGW1) Phone 805/545-6546

As the civil engineering supervisor, I have reviewed the above writeup and provide my approval. This notification does not report a non-conforming or degraded condition, rather it is a tracking tool that engineering will use to determine whether or not a maintenance plan is needed to provide enhanced monitoring of the strain gauges and their cover plates for any degraded conditions of the gauges. If a degraded condition is found, a separate notification will be written to place it into the corrective action program.

Notification assigned to the responsible engineer to determine the best

U-0

Notification: **50341635**

Type: **DN** Work Type: **EVAL ENGR**

Description: **Evaluate the need for strain gauge PM**

Order:

way to monitor the strain gauges/cover plates (does the present IWL inspections suffice or does a new maintenance plan need to track it?)

.

09/15/2010 15:40:22 Behrooz Shakibnia (BXS5) Phone 805/545-6094
For concrete surface conduit box details, see drawing 663075-655.

.

09/16/2010 14:59:59 Jana M. Orlando (JMSO) Phone 805/545-3126
The issue/event documented on this notification was reviewed by the Notification Review Team (NRT) and determined to be the indicated significance level per OM7.ID1. If additional information is discovered that would affect the significance level determination, contact a member of the NRT or e-mail DCPN NRT Members.

.

09/16/2010 18:38:41 David G. Wong (DGW1) Phone 805/545-6546
The containment structure system engineer should also consider instituting a more permanent fix, such as sealing up of the entire strain gauge wire box.

.

10/28/2010 23:22:04 David G. Wong (DGW1) Phone 805/545-6546
Civil Engineering will be creating a maintenance plan that will ensure enhanced monitoring of the strain gauges and their cover plates for degraded conditions. Civil Engineering will also be issuing a design change or N-Mod to provide permanent fix options (including sealing up of the entire strain gauge wire box) that can be implemented depending upon the as-found condition (extent of damage) of the strain gauge wire boxes.

.

U-0

Notification: **50341635** Type: **DN** Work Type: **EVAL ENGR**

Description: **Evaluate the need for strain gauge PM**

Order:

STATUS DETAILS

System Status: **OSNO**

User Status: **25** **ASGN** Assigned to Target Workcenter
