

Eric Larson
Plant General Manager

CENG

a joint venture of



**Constellation
Energy**



R.E. Ginna Nuclear Power Plant, LLC
1503 Lake Road
Ontario, New York 14519-9364

585.771.5205
585.771.3900 Fax

Eric.Larson@cengllc.com

November 8, 2010

U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

ATTENTION: Document Control Desk

SUBJECT: R.E. Ginna Nuclear Power Plant
Docket No. 50-244

**LER 2010-002, Unanalyzed Condition due to Leakage of Residual
Heat Removal Pump Suction Relief Valves**

The attached Licensee Event Report (LER) 2010-002 is submitted under the provisions of NUREG 1022, Event Reporting Guidelines. There are no new commitments contained in this submittal. Should you have any questions regarding the information in this letter, please contact Mr. Thomas Harding at (585) 771-5219.

Very truly yours,

Eric A Larson

Attachments: (1) LER 2010-002

cc: W. Dean, NRC
D. Pickett, NRC
Resident Inspector, NRC (Ginna)

IE 22

NRK

ATTACHMENT 1

LER 2010-002

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME R.E. Ginna Nuclear Power Plant	2. DOCKET NUMBER 05000 244	3. PAGE 1 OF 5
---	--------------------------------------	--------------------------

4. TITLE
Unanalyzed Condition due to Leakage of Residual Heat Removal Pump Suction Relief Valves

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
09	09	2010	2010	- 2 -	0	11	08	2010		05000
									FACILITY NAME	DOCKET NUMBER
										05000

9. OPERATING MODE I	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)									
	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)						
10. POWER LEVEL 100%	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(vii)(A)						
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input checked="" type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)						
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)						
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)						
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)						
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)						
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER							
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A							

12. LICENSEE CONTACT FOR THIS LER

FACILITY NAME Thomas Harding, Licensing Director	TELEPHONE NUMBER (Include Area Code) (585) 771-5219
---	--

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
	BP								

14. SUPPLEMENTAL REPORT EXPECTED	15. EXPECTED SUBMISSION DATE	MONTH	DAY	YEAR
<input checked="" type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input type="checkbox"/> NO		12	03	2010

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On September 9, 2010, after isolation of Residual Heat Removal (RHR) pump suction relief valves for maintenance, the shift operating crew identified that the rate of level rise in the Auxiliary Building (AB) sump tank had slowed. Prior to the isolation, leakage into the AB sump tank was estimated to be approximately 6 gph. The source of the elevated leakage was attributed to the RHR pump suction relief valves. The Technical Specification program for primary coolant leakage outside of containment has a limit of 2 gph and the current site dose calculation assumes Emergency Core Cooling System leakage of 4 gph. During certain accident conditions, with the continued leakage of RHR suction relief valves, the plant would have been in an unanalyzed condition for dose. An evaluation was performed upon identification of the condition and concluded that the safety system would have been able to perform its required function and no regulatory dose limits would have been exceeded. The cause of the leakage is unknown and corrective actions have not been finalized.

**LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
R.E. Ginna Nuclear Power Plant	05000 244	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF 5
		2010	- 002	- 0	

NARRATIVE

I. DESCRIPTION OF EVENT

A. PRE-EVENT PLANT CONDITIONS:

The reactor was in Operational Mode 1 at 100% power, 2235 psig and 573 degrees F.

B. EVENT:

A modification was implemented in January of 2009 to address a concern with the ability of the Residual Heat Removal (RHR) system suction valves (MOV-850A/B) to open when required for system alignment to Sump 'B' during the recirculation mode of accident mitigation. Specifically, redundant relief valve trains each consisting of two (2) relief valves in series were installed. RV-686G and RV-686I comprise the 'A' train and RV-686H and RV-686J comprise the 'B' train. These relief valve trains are physically connected to the RHR pumps recirculation line and discharge to a common drain line leading to the Auxiliary Building sump tank.

In March of 2009, it was identified that all four relief valves had a setpoint of 150 psig in lieu of the 150 psia identified by the modification documents. RV-686G and RV-686I were replaced with re-set valves in July of 2009 and RV-686H and RV-686J were replaced with re-set valves in March of 2010. The as-found setpoint for RV-686H was 240 psig in lieu of 150 psig as originally set (this valve was tested two more times and each time it lifted at approx 150 psig). The evaluation performed as a result of the RV-686H setpoint concern generated a work order to verify that the set point of RV-686J had not shifted.

On September 9, 2010, the isolation valve to RV-686H and RV-686J was closed in preparation for performing the set point verification of RV-686J. Following the isolation, the shift operating crew identified that the rate of level rise in the Auxiliary Building sump tank had slowed. A review of plant computer data indicated that the rate of level rise appeared to be elevated since March 2010. RV-686J was removed, and the as-found testing identified that it failed its seat leakage requirement at a pressure of 50 psig. The acceptance criteria is 122 psig. Subsequent testing of RV-686H determined that this valve failed its set point test by leaking at a pressure of 10 psig. The desired set point is 135 psig. Both valves were replaced with tested spares. These valves are designed to ensure that RHR pump suction valves can open against a differential pressure postulated for specific accident scenarios. Given that the lift setpoint was lower than design, there is reasonable assurance that these valves could still perform in an accident. However the additional flow to the auxiliary building sump tank was not accounted for in the Emergency Core Cooling System (ECCS) leakage criteria of 2 gph. The current control room and offsite dose calculation assumes a leakage of 4 gph and it is estimated that the flow rate into the sump was approximately 6 gph. If an accident condition were to occur, portions of the plant would be in an unanalyzed condition for dose.

To date, the valves have been extensively tested, disassembled and inspected. Although some minor contamination was found on the seating surfaces, there was no clear indication that valve degradation occurred. New valves have been installed and have been observed to lift during surveillance testing. Evaluation has identified an unexpected consequence of the test configuration. When the isolation valve in the pump recirculation flow line is closed, the relief valves are exposed to higher pressure than would otherwise be experienced during operational conditions. It is unknown at this time if this could have led to the leakage originally identified. Additional causal evaluation is in progress and corrective actions have not been finalized.

**LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
R.E. Ginna Nuclear Power Plant	05000 244	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 5
		2010	- 002	- 0	

NARRATIVE

C. INOPERABLE STRUCTURES, COMPONENTS OR SYSTEMS THAT CONTRIBUTED TO THE EVENT:

None

D. DATES AND APPROXIMATE TIMES OF MAJOR OCCURRENCES:

01/06/2009 Relief Valves installed
 07/21/2009 RV-686G and RV-686I replaced to correct setpoint
 03/17/2010 RV-686H and RV-686J replaced to correct setpoint
 09/09/2010 RV-686J seat leakage and RV-686H setpoint found below acceptance criteria. Replaced with new valves and returned to service.

E. OTHER SYSTEMS OR SECONDARY FUNCTIONS AFFECTED:

None

F. METHOD OF DISCOVERY:

Planned Maintenance and Surveillance testing

G. MAJOR OPERATOR ACTION:

The valves were isolated at the time of discovery. No actions were required.

H. SAFETY SYSTEM RESPONSES:

No safety systems actuated or were required to respond to this event.

II. CAUSE OF EVENT:

This event was entered into the site corrective action program (CR-2010-005530). The cause of the event is still under investigation. A complete description of corrective actions will be included in a supplemental licensee event report (LER)

III ANALYSIS OF THE EVENT:

This event is reportable in accordance with 10 CFR50.73, Licensee Events Report System under item (a)(2)(ii)(B) based on the plant being in an unanalyzed condition that significantly degraded plant safety. The event is also considered to be reportable in accordance with item (a)(2)(i)(B) based on operation or condition prohibited by Technical Specifications.

**LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
R.E. Ginna Nuclear Power Plant	05000 244	YEAR	SEQUENTIAL NUMBER	REV NO.	4 OF 5
		2010	- 002	- 0	

NARRATIVE

An assessment was performed considering both the safety consequences and implications of this event with the following conclusions:

The valves were isolated at the time of discovery and no immediate actions were required. Since the valves were found with setpoints lower than expected, the pressure relieving function was preserved. It appears the valves could have been leaking since replacement in March of 2010. The existing analysis uses twice the programmatic limit for ECCS leakage to calculate post-accident doses. With a Technical Specification program limit of 2 gph leakage, the analysis uses 4 gph. A preliminary evaluation was performed against 10CFR50.67(b)(2)(iii) criteria for access to and occupancy of the control room as well as offsite dose under accident conditions. It was calculated that under worst case conditions, the leakage would not have resulted in exceeding regulatory limits.

An evaluation was performed and concluded that there is reasonable assurance that there would have been no loss of safety function or significant impact on ECCS inventory as a result of this condition.

Based on the above considerations, the nuclear safety consequences of this event are very low.

This event does not have any impact on NRC performance indicators.

IV CORRECTIVE ACTIONS:

A. ACTION TAKEN TO RETURN AFFECTED SYSTEMS TO PRE-EVENT NORMAL STATUS:

Relief valves RV-686H and RV-686J were replaced

B. ACTION TAKEN OR PLANNED TO PREVENT RECURRENCE

A complete description of corrective actions will be included in a supplemental LER

**LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
R.E. Ginna Nuclear Power Plant	05000 244	YEAR	SEQUENTIAL NUMBER	REV NO.	5 OF 5
		2010	- 002	- 0	

NARRATIVE

V. ADDITIONAL INFORMATION:

A. FAILED COMPONENT

It is not clear at this time that a component failure occurred. This may be updated in a supplemental LER pending the results of the causal evaluation.

B. PREVIOUS LERS ON SIMILAR EVENTS

A review of Ginna events over the past five years identified no similar events

C. THE ENERGY INDUSTRY IDENTIFICATION SYSTEM (EIS) COMPONENT FUNCTION IDENTIFIER AND SYSTEM NAME OF EACH COMPONENT OR SYSTEM REFERRED TO IN THIS LER:

COMPONENT	IEEE 803 FUNCTION IDENTIFIER	IEEE 805 SYSTEM IDENTIFICATION
RV-686J	RV	BP
RV-686H	RV	BP

D. SPECIAL COMMENTS

None