NRC FORM 591M PART 1 U.S NUCLEAR REGULATORY COMMISSION (06-2010) 10 CFR 2.201						
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION						
1. LICENSEE/LOCATION INSPECTED: St. Louis Testing Laboratories, Inc. 2810 Clark Avenue St. Louis, MO 63103 REPORT NUMBER(S) 2010-003		^{2. NRC/REGIONAL OFFICE} U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4351				
3. docket number(s) 030-05064	4. LICENSEE NUMBER 24-00188-02	(S)	5. DATE(S) OF INS	SPECTION 2, 2010		
LICENSEE:						
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: 1. Based on the inspection findings, no violations were identified. 2. Previous violation(s) closed.						
3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied						
 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11 						
Statement of Corrective Actions						
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.						
Title	Printed Name	Signa	iture	Date		
LICENSEE'S REPRESENTATIVE						
Deborah A. Pis	kura	DAMERY	12	11/2/2010		
Branch Chief Tamara E. Blo	omer	Famara	Storm	11/15/10		

NRC FORM 591 M PART 3 (06-2010)		U.S. NUCLEAR REGULATORY COMMISSION					
10 CFR 2.201							
Docket File Information							
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION							
1. LICENSEE		2. NRC/REGIONAL OFFICE					
St Louis Testing Laboratories, Inc.		U.S. Nuclear Regulatory Commission					
2810 Clark Avenue		Region III					
St. Louis, INO 63103		2443 Warrenville Road, Suite 210					
REPORT NUMBER(S) 2010-003		Lisle, IL 60532-4351					
3. DOCKET NUMBER(S) 4. LICENSE NUM		BER(S)	5. DATE(S) OF INSPECTION				
030-05064 24-00188-0		2	Nov. 2, 2010				
6. INSPECTION PROCEDURES 7. INSPECTION F		OCUS AREAS					
87120 03.01-03.08							
SUPPLEMENTAL INSPECTION INFORMATION							
1.PROGRAM	2. PRIORITY	3. LICENSEE CONTACT		4. TELEPHONE NUMBER			
03320	1	Don Baumer, RSO		314-531-8080			
S main office inspection Next inspection Date: <u>unchanged</u>							
x Temporary Job Site InspectionX Control Contro							

PROGRAM SCOPE

This inspection was conducted to follow up on the licensee's corrective actions for violations identified during the previous inspection between March 18 to May7, 2010, as described in Inspection report no. 03005065/2010-001 and -002 (ML 1016803542). During this inspection, the inspector toured the facilities and performed radiation surveys of the storage area, reviewed selected records, and interviewed three radiographers. This inspection included a review of the licensee's activities at a temporary job site by a 2-man crew at General Mechanical, St. Louis, Missouri, with emphasis on security and personnel monitoring. The inspector observed the radiographers maintain adequate control of the licensed material while at the job site. The crew conducted several radiographs using an iridium-192 source. The inspector performed a confirmatory radiation survey around the outside perimeter of the job site boundary. The inspector observed the radiographers as they entered the restricted area and conducted radiation surveys of the camera and guide tube. The inspector also observed the radiographers' use of safety equipment (survey instrument, assigned personnel monitoring badges, pocket dosimeters, and alarming rate meters). The inspector verified documents pertaining to shipping papers, utilization logs, certifications, operating emergency procedures and NRC Regulations. Based on interviews with licensee personnel, review of selected records, and observations at the temporary job site, the licensee implemented its corrective actions.

The year-to-date 2010 maximum TEDE dose to a radiographer was reported as 1,978 mrem.