

NOV 1 5 2010

Serial: HNP-10-127 10 CFR 50.73

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1 DOCKET NO. 50-400/RENEWED LICENSE NO. NPF-63 LICENSEE EVENT REPORT 2010-003-00

Ladies and Gentlemen:

The enclosed Licensee Event Report (LER) 2010-003-00 is submitted in accordance with 10 CFR 50.73, paragraph (a)(2)(i)(B), any operation or condition which was prohibited by the plant's Technical Specification. This report describes an event in which the plant operated under a Technical Specification prohibited condition by exceeding the Allowed Completion Time for an Inoperable Refueling Water Storage Tank. In accordance with 10 CFR 50.73(a) requirements, this LER is submitted within 60 days following the event.

This document contains no new Regulatory Commitments.

Please refer any questions regarding this submittal to Mr. John Caves, Supervisor - Licensing/Regulatory Programs, at (919) 362-3137.

Sincerely

Kelvin Henderson Plant General Manager Harris Nuclear Plant

KH/kab

Enclosure

cc: Mr. J. D. Austin, NRC Sr. Resident Inspector, HNP Mrs. B. L. Mozafari, NRC Project Manager, HNP Mr. L. A. Reyes, NRC Regional Administrator, Region II

Progress Energy Carolinas, Inc. Harris Nuclear Plant P. O. Box 165 New Hill, NC 27562

				٦,	[18](19]](19]	· . ? ⁰ /* ?	. 4	计学 新闻	计数据 网络							
					۰.	· ·	1	2	• •							
NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION						SION	APPROVED BY OMB: NO. 3150-0104 EXPIRES: 10/31/201									
(10-2010) LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)								Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.								
1. FACI	LITY N/	AME	1999 - Anno 1997 - Anno 19	4*, •		•		2. DOC	KET NUM	BER	***	3. PA	\GE			
Harri	s Nucl	ear Plant	- Unit 1					0	5000	04	00		1 (OF		3
4. TITLE																
Condition prohibited by Technical Specifications when non-seismic system was aligned to Refueling Water Storage Tank																
5. E	VENT	DATE	6. LER NUMBER 7. REPORT DATE				DATE	8. OTHER FACILITIES INVOLVED								
монтн	DAY	YEAR	YEAR SEQUEN	ITIAL REV	MONTH	DAY	YEAF		ILITY NAME					DOC	KET NU	MBER
· · ·								FAC	ILITY NAME	AME			DOCKET NUMBER			
09	09 16 2010 2010 - 003 - 00 11 15 20			2010) N/A											
9. OPERATING MODE			11. THIS REPORT IS SUBMITTED PURSUANT 20.2201(b) 20.2203(a)(3)(i) 20.2201(d) 20.2203(a)(3)(ii) 20.2203(a)(1) 20.2203(a)(4) 20.2203(a)(2)(i) 50.36(c)(1)(i)(A) 20.2203(a)(2)(ii) 50.36(c)(1)(i)(A)				$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$))			
100			20.2203(a)(2)(iii) 50.36(c)(2) 20.2203(a)(2)(iv) 50.46(a)(3)(ii) 20.2203(a)(2)(v) 50.73(a)(2)(i)(A) 20.2203(a)(2)(vi) 50.73(a)(2)(i)(B)					50.73(a)(2)(v)(A) 73.71(a)(4) 50.73(a)(2)(v)(B) 73.71(a)(5) 50.73(a)(2)(v)(C) OTHER 50.73(a)(2)(v)(D) Specify in Abstract be or in NRC Form 3664					below SA			
				12.	LICENS	EE CON	TACT	FOR TH	IIS LER							
FACILITY NAME TELEPHONE NUMBER (Include Area Code) John Caves - Supervisor, Licensing/Regulatory Programs 9193623137									Code)							
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT																
CAUSE		SYSTEM	COMPONENT	MANU- FACTURER	REPO TO	RTABLE EPIX	с 	AUSE	SYST	EM	COMPON	IENT	MANU	J- RER	REP(T(ORTABLE D EPIX
									15. EXPECTED MONTH SUBMISSION			MONTH	D	٩Y	YEAR	
	CT (Lim	it to 1400 sr	aces i.e. approxima	telv 15 sinale-si	DATE)	written liv				DA	ATE					

On March 3, 2006, procedure OP-116.01, Fuel Pool Purification System, was revised to permit purification of the Refueling Water Storage Tank (RWST) using the non-seismic Fuel Pool Purification system in Modes 1-4 without declaring the RWST inoperable and entering the Technical Specification (TS) Limiting Condition for Operation (LCO) action statement. In 2010, the NRC Resident Inspector questioned this practice, which led to the conclusion that Harris Nuclear Plant should have obtained prior NRC approval to perform this activity. The root cause investigation concluded that ambiguous procedural guidance resulted in a misinterpretation of requirements. Corrective actions include procedure revisions to eliminate RWST purification in Modes 1-4 and clarification of guidance regarding the impact of proposed activities on the design and licensing bases.

NRC FORM 366A (10-2010)	LICENSEE EVENT R CONTINUATION	EPORT	(LER) ^{U.S. NU} Г	ICLEAR R	EGULATORY COMMISSION		
1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE		
Harris Nuclear Plant - Unit 1	05000 400	YEAR	SEQUENTIAL NUMBER	REV NO.	2 05 3		
	05000 400	2010	- 003 -	00			

2 1 71 -

1.54

NARRATIVE

EVENT DESCRIPTION

The Refueling Water Storage Tank (RWST) is seismically-qualified, safety-related and within the scope of plant Technical Specifications (TS). Plant design includes the capability of using the Fuel Pool Purification System for cleanup of the RWST. The Fuel Pool Purification System is a non-safety, non-seismic system and is separated from the RWST by a normally closed, safety-related, manually-operated boundary valve 1CT-23.

On March 3, 2006, procedure OP-116.01, Fuel Pool Purification System, was revised to permit purification of the RWST in plant operating Modes 1-4 without declaring the RWST inoperable and entering the TS Limiting Condition for Operation (LCO) action statement. The alignment for purification of the RWST opens manual valve 1CT-23, RWST to the Spent Fuel Pool (SFP) Pump suction valve, which un-isolates safety and seismic piping from non-safety piping. The 10CFR50.59 evaluation supporting the procedure revision credited a manual action to shut 1CT-23 to maintain operability of the system. The evaluation concluded that a license amendment was not required to implement the procedure change.

In 2010, the NRC Resident Inspector at Harris Nuclear Plant (HNP) questioned this practice. HNP placed a caution tag on valve 1CT-23 to prevent operation of the valve until the question was resolved. A discussion was held between the plant staff and the NRC Nuclear Reactor Regulation staff. During that discussion, plant staff realized that HNP should have obtained prior approval from the NRC to perform this activity without entering the TS LCO action statement. The condition was entered into the corrective action program and the procedure was revised to prevent the activity without entering the action statement.

TS LCO 3.1.2.6 Action (b) requires "with the RWST inoperable, restore the tank to Operable status within 1 hour or be in at least hot standby within the next 6 hours and in cold shutdown within the following 30 hours." Since the RWST was not declared inoperable, TS LCO actions were not entered. This resulted in a condition prohibited by TSs. Purification of the RWST while online in Modes 1-4 from August 16, 2007, through August 16, 2010, occurred for approximately 91 hours in 2008, 30 hours in 2009, and 24 hours in 2010.

SAFETY CONSEQUENCES

Sensitivity calculations show that with the RWST considered out of service during the cleanup period (72 hours) the increase in core damage frequency due to a seismic event is 1.50E-8/yr. The result is considered very low risk.

CAUSE OF EVENT

A 10CFR50.59 evaluation failed to identify that opening valve 1CT-23, RWST to SFP pump suction valve, when purifying the RWST online would require declaring the RWST inoperable regardless of what controls could be put into place to close the valve. Ambiguous procedural guidance resulted in a misinterpretation of requirements when performing the 10CFR50.59 evaluation for procedure OP-116.01.

NRC FORM 366A LICENS (10-2010) CC	SEE EVENT R		(LER) ^{U.S. N}	UCLEAR RE	GULATC	RY COM	MISSION			
				, I		3 PAGE				
Harris Nuclear Plant - Unit 1		YEAR	SEQUENTIAL NUMBER	REV NO.		OF	3			
	05000 400	2010	- 003	- 00	3					
NARRATIVE										
CAUSE OF EVENT (continued)										
NEI 96-07 Revision 1 states: Although this criteri requirements and other acceptance criteria to wh nationally recognized industry consensus standar from the design, fabrication, construction, testing (Appendix A to 10 CFR 50) are not compatible w Because the RWST is required to be seismically-	on allows minima tich they are comr ds, e.g., the ASMI g and performance ith a "no more the qualified, opening	l increases, nitted (sucl E B&PV Co e standards an minimal 1CT-23 to	, licensees mu h as contained ode and IEEI s as outlined i l increase" sta	ast still mee d in regula E standard n the Gene andard. Fuel Pool P	et applic tory gui s). Furt eral Desi Purificat	able reg des and her, dep gn Crite	ulatory partures eria em			
(non-seismic) to the RWST resulted in a deviation from GDC 2. The change should have been considered "more than a minimal increase" which requires prior NRC approval to perform the activity.										
CORRECTIVE ACTIONS										
Immediate Corrective Actions Revised procedure OP-116.1, Fuel Pool Purificati	ion System, to ren	nove the ca	pability to pu	rify the R	WST in [Modes 1	-4.			
Actions to Prevent Recurrence Clarify procedural guidance regarding the impac	t of proposed acti	vities on th	e design and	licensing t	bases.					
PREVIOUS SIMILAR EVENTS										
On August 1, 1996, HNP personnel identified, via basis". This condition was that the RWST had be consideration was the purification system piping to the NRC in Licensee Event Report (LER) 96-1 operating procedure lineups with the plant design that LER included placing administrative control ensuring procedure requirements do not permit of subsequent changes to the industry 50.59 process approval for the activity was no longer needed. The Condition for Operation action statement during Specifications and requires this Licensee Event R	a review of indus een connected to r and piping leading 3. The cause of th 1 basis during orig ls on 1CT-23 by lo opening without d under NEI 96-07 This error resulted g the purification deport in accordan	try operation-seismic g to the hydris LER wa ginal processing the provided a l in not entra activity, wh	ing experienc cally qualified drostatic test is determined dure develop ying 1CT-23 s e LCO. In 20 additional flex ering the Tec nich is a cond CFR 50.73(a)	e, a "condi l piping (no pump). H to be a fai ment. Cor shut as an 006, HNP s cibility such hnical Spe ition not al 0(2)(i)(B).	ition out on-seism NP repo- lure to r rective a immedia immedia itaff con h that pr cificatio llowed b	side the ic pipin rted this econcile actions f ate action cluded t rior NR0 n Limiti y Techn	design g under s event rom n and that C ng ical			

n i dan Majiri Majiri Majiri