Virginia Electric and Power Company North Anna Power Station P. O. Box 402 Mineral, Virginia 23117

November 22, 2010

Attention: Document Control Desk U. S. Nuclear Regulatory Commission Washington, DC 20555-0001 
 Serial No.:
 10-584

 NAPS:
 RAP

 Docket No.:
 50-338, 339

 License No.:
 NPF-4, NPF-7

Dear Sirs:

 $\tilde{\mathbf{v}}_{T_1}$ 

Pursuant to 10CFR50.73, Virginia Electric and Power Company hereby submits the following Licensee Event Report applicable to North Anna Power Station Units 1 and 2.

Report No. 50-338/2010-003-00

This report has been reviewed by the Facility Safety Review Committee and will be forwarded to the Management Safety Review Committee for its review.

Sincerely,

richard and for

N. Larry<sup>4</sup>Lane Site Vice President North Anna Power Station

Enclosure

Commitments contained in this letter: None

cc: United States Nuclear Regulatory Commission Region II Marquis One Tower 245 Peachtree Center Ave., NE, Suite 1200 Atlanta, Georgia 30303-1257

NRC Senior Resident Inspector North Anna Power Station

LÉZZ NR

	DM 266		11.9		EGULA		MISSIC	N						
(9-2007) U.S. NUCLEAR REGULATORY COMMISSION							\$/39Z	ABPROVED BY OMB NO. 3150-0104 EXPIRES:					5:	
Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor and a person is not required to respond to the														
1 FACIL	ΤΥ ΝΑΜ	F			1			inform	CKET NUMB	FR			3 PA(	3F
						TS 1 an	4.2	050	5. FAGE					
4. TITLE		NATC		STATION	, UNI	15 I all	u z	1050	00 330				1 1	
Potent	tial for	Contai	nment	Sump Stra	ainer	Blockag	e due	e to Ur	nacceptab	le Ins	ulatio	n In Cor	Itainme	ent
5. E	VENT DA	TE	6.	LER NUMBER	2	7. REI	PORT D	ATE	•	8. OTH	ER FAC	ILITIES INV	OLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NA	ME na Pow	er Stat	ion	DOCUMEN 050003	T NUMBER 39
09	24	2010	2010	003	00	11	22	2010	FACILITY NA	ME			DOCUMEN 05000	IT NUMBER
9. OPERATING MODE         11. THIS REPORT IS SUBMIT           20.2201(b)         20           20.2201(d)         20           Defueled         20.2203(a)(1)         20           20.2203(a)(2)(i)         50					BMITTED P 20.2203(a 20.2203(a 20.2203(a 50.36(c)(1	URSUA a)(3)(i) a)(3)(ii) a)(4) 1)(i)(A)	ΝΤ ΤΟ Τ	D THE REQUIREMENTS OF 10 CFR §:         (Check all that is a constraint of the constrain				ck all that a 73(a)(2)(vii 73(a)(2)(vii 73(a)(2)(vii 73(a)(2)(ix)	apply) i)(A) i)(B) )(A)	
10. PO	10. POWER LEVEL         20.2203(a)(2)(ii)         50.36(c)(1)(ii)(A)           20.2203(a)(2)(iii)         50.36(c)(2)           20.2203(a)(2)(iv)         50.46(a)(3)(ii)           20.2203(a)(2)(v)         50.73(a)(2)(i)(A)           0%         20.2203(a)(2)(vi)						50.73(a) 50.73(a) 50.73(a) 50.73(a) 50.73(a) X 50.73(a)	50.73(a)(2)(iv)(A)       50.73(a)(2)(x)         50.73(a)(2)(v)(A)       73.71(a)(4)         50.73(a)(2)(v)(B)       73.71(a)(5)         50.73(a)(2)(v)(C)       OTHER         X       50.73(a)(2)(v)(D)						
					12. LI	CENSEE C	ONTAC	T FOR T	HIS LER					
FACILITY		F. Mla	den, D	irector Sta	tion S	Safety a	nd Lic	ensin	g		(540	10NE NUMBE ) 894-21	R (Include)	Area Code)
CAUSE	13. COMPLETE ONE LINE FOR EACH COMPONEI           CAUSE         SYSTEM         COMPONENT         MANU- ELECTURE         REPORTABLE         CAUSE			CAUS		SYSTEM COMPONENT MANU-								
				I NOTOKEN	101							TROTONEI		
		14. SUPP	LEMENT	AL REPORT E	ХРЕСТІ	ED			15. EXPE	CTED		MONTH	DAY	YEAR
YES (If yes, complete 15. EXPECTED SUBMISSION DATE)														
ABSTRA	CT (Limi	t to 1400 s	spaces, i.e	., approximatel	y 15 sin	gle-spaced i	typewritt	en lines)				1	1	
On September 22, 2010, with Unit 1 defueled during a scheduled refueling outage, an insulation discrepancy was noted while investigating the supplementary neutron shielding														
that installed the shielding noted the original Tempmat insulation was replaced with														
Microtherm insulation per Design Change 79-S07 This conflicted with the GSI-191 vendor														
walk-down report. On September 24, 2010 subsequent inspections revealed Microtherm														
insulation on the Intermediate RCS Loop which is within the North Anna 1 containment														
GSI-191 Zone of Influence. The corresponding Unit 2 Intermediate RCS Loop insulation														
had been mitigated. On September 28, 2010, additional Microtherm insulation was														
identified on the Unit 1 Reactor Coolant Pumps. On September 28, 2010, management														
decided to voluntarily shutdown Unit 2 based on inconsistent documentation to perform														
insulation inspections in equivalent areas. The visual inspections confirmed the existence of Microtherm in Unit 2 Containment. On September 20, 2010, at 1415 hours, an														
Information Only notification was made to the NRC Operations Center. This event is														
-			ארועווע		10011	וטעיד וט ו	u 10 I N		<u>, , , , , , , , , , , , , , , , , , , </u>		4. III	13 57511	10	
	report	able ne	er 10 C	ER 50 730	a $(2)$	(v)(D) fo	r a co	, nditio	n that cou	ld hav	/e pre	vented	he	
	report fulfillm	able peneric	er 10 C a safet	FR 50.73(	a)(2) need	(v)(D) fo led to m	r a co itigate	, onditio e the c	n that cou	ild hav	ve pre f an a	vented accident	he	

NRC FORM 366A (9-2007)	NUCLEAR REG	<b>JULATORY COMMISSION</b>							
LICENSEE EVENT REPORT (LER) CONTINUATION SHEET									
1. FACILI	TY NAME	2. DOCKET	YEAR	6. LER NUMBER	REV NO.	3.	PAGE		
NORTH ANNA POWER	STATION UNITS 1 & 2	05000 - 338	2010	003	00	2	OF 4		
NARRATIVE (If more space is requ	red_use additional copies of NRC E	orm 366A) (17)							

## 1.0 DESCRIPTION OF THE EVENT

During the Unit 2 Spring 2010 Refueling Outage (RFO) evidence of minor leakage at the cavity seal ring was identified. A boric acid inspection of the Reactor Pressure Vessel (RPV) nozzles (EIIS System – AB, Component – NZL) was subsequently performed. The inspection identified the degraded condition of the supplemental neutron shielding saddle assemblies. The configuration of the supplemental neutron shielding saddle assemblies were determined to be acceptable. Based on the degraded condition of the Unit 2 supplemental neutron shielding saddle assemblies, a decision was made to inspect the Unit 1 supplemental neutron shielding saddle assemblies during the Fall 2010 RFO.

On September 13, 2010, the inspection of the Unit 1 supplemental neutron shielding saddle assemblies determined it was not configured as indicated on plant drawings. The supplemental neutron shielding installed on top of the nozzles contained gaps preventing it from fully performing its intended function. The length of time the Units 1 and 2 supplemental neutron shielding saddle assemblies have been degraded is unknown. Corrective actions were initiated to evaluate removal of the supplemental neutron shielding saddle assemblies.

During development of the Design Change to remove the supplemental neutron shielding saddle assemblies, Engineering review of the Design Change that installed the supplemental neutron shielding saddle material noted that the original Tempmat insulation on the Unit 1 RPV nozzles was replaced with thinner Microtherm insulation per Design Change (DC 79-S07). This conflicted with the GSI-191 vendor walk-down. A review of GSI-191 walk-down reports, material specifications, design changes, and drawings was initiated. As a result of this review, on September 24, 2010 subsequent inspections revealed Microtherm insulation on the Intermediate RCS Loop which is within the North Anna 1 containment GSI-191 Zone of Influence. The corresponding Unit 2 RCS Intermediate loop insulation had been mitigated. In addition, on September 28, 2010, Microtherm was visually verified to exist on the Unit 1 Reactor Coolant Pumps (RCPs) (EIIS Component – P) bowls, which is within the Zone of Influence (ZOI). On September 28, 2010, management decided to voluntarily shutdown Unit 2 based on inconsistent documentation to perform insulation inspections in equivalent areas. The visual inspection confirmed the existence of Microtherm in Unit 2 containment ZOI. In subsequent investigations, Microtherm was discovered to be installed in Units 1 and 2 on the RCPs, the RCP outlet nozzles, the Intermediate Leg elbows (on Unit 1 only), and other locations. In addition, Calcium Silicate (Cal-Sil) insulation was determined to be installed in both Units containment ZOIs. Based on hand-over-hand walk-downs that were performed there were approximately 58 cubic feet of Microtherm and 8 cubic feet of Cal-Sil identified in the Unit 1 containment ZOI. Hand-over-hand walk-downs for the Unit 2 containment ZOI identified approximately 62 cubic feet of Microtherm and 9 cubic feet of Cal-Sil.

The debris source walk-downs conducted in 2003 and 2004 for the original GSI-191 project identified the existence of Microtherm insulation in Unit 2 containment but not in Unit 1.

# \_\_\_\_\_\_ ۲۰٬۰۶۰

NRC FORM 366A (9-2007)

#### U.S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT (LER)

CONTINOATION SHEET									
1. FACILITY NAME	2. DOCKET	6. LER NUMBER				3. PAGE			
		YEAR	SEQUENTIAL NUMBER	REV NO					
NORTH ANNA POWER STATION UNITS 1 & 2	05000 - 338	2010	003	00	3	OF 4			
NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)									

Design Change (DCP 07-004) was implemented to replace Microtherm and most Cal-Sil (in the ZOI) in Unit 2 with approved insulation. The Design Change for Unit 1 (DCP 07-129) addressed only Cal-Sil. The existence of encapsulated Microtherm on the RPV nozzles was unknown to the original GSI-191 project team and it was only identified during the investigation of the supplemental neutron shielding. The presence of Microtherm and Cal-Sil in the Unit 1 and 2 containment ZOIs was not bounded by debris load testing of the containment sump strainers (EIIS System – BP, Component – STR). The North Anna Power Station (NAPS) Supplemental Response to NRC Generic Letter 2004-02, Serial No. 08-0019 dated February 29, 2008 stated that Microtherm insulation had been removed from the Unit 2 containment and that no Microtherm was installed in the Unit 1 containment.

## 2.0 SIGNIFICANT SAFETY CONSEQUENCES AND IMPLICATIONS

This event posed no significant safety implications since no Design Basis Accident (DBA) occurred on either Unit during the time the unacceptable insulation remained within the Unit 1 and 2 containment ZOIs. The unacceptable insulation in the Unit 1 and 2 containment ZOIs was not bounded by debris load testing of the containment sump strainers. Dominion preliminary PRA calculations show a Conditional Core Damage Frequency (CCDF) of 5.04E-07 due to this event. This is below the regulatory threshold of 1.0E-06. The likely-hood of a Loss of Coolant Accident event is very small and the operations staff has procedures to mitigate such a condition in addition to receiving training to recognize sump blockage conditions. Therefore, the health and safety of the public were not affected by this event.

There is no ongoing vulnerability as a result of the comprehensive actions taken as described in section 4.0 below. The hand-over-hand walk-downs identified the extent of condition and ensured that unacceptable insulation does not exist within Unit 1 and 2 containment ZOIs.

On September 29, 2010, at 1415 hours, an Information Only notification was made to the NRC Operations Center to identify the Unit 2 shutdown to allow inspections for unacceptable insulation. The visual inspections confirmed the existence of Microtherm in Unit 2 Containment ZOI. This event is reportable pursuant to 10 CFR 50.73(a)(2)(v)(D), any event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident.

## 3.0 <u>CAUSE</u>

The preliminary root cause evaluation of the event determined a flawed methodology was used to determine the types and quantities of insulation during the GSI-191 containment walkdowns, resulting in unacceptable insulation not being included in the containment debris inventory and subsequently remediated. Contributors to this event were an incomplete set of insulation drawings to perform plant walk-downs, ineffective oversight

	(9-2007)		0.5.	NUCLEAR REC	JULATUR	CON	101331011				
	LICENSEE EVE	NT REPORT (LER)	ł								
	CONTINUATION SHEET										
	1. FACILITY NAME	2. DOCKET	6. LER NUMBER 3. PA								
			YEAR	SEQUENTIAL NUMBER	REV NO.						
	NORTH ANNA POWER STATION UNITS 1 & 2	05000 - 338	2010	003	00	4	OF 4				
ĺ	NARRATIVE (If more space is required, use additional copies of NRC	Form 366A) (17)									

and over-reliance on vendors, and ineffective project management during inventory walkdowns and subsequent remediation.

# 4.0 IMMEDIATE CORRECTIVE ACTION(S)

13 1 1 St 14

ETE-NA-2010-0008, Disposition of Microtherm Insulation on North Anna Unit 1, and ETE-NA-2010-0009, Final Disposition of Microtherm Insulation on North Anna Unit 2, governed the actions necessary to identify and remediate unacceptable insulation within the ZOIs for NAPS Units 1 and 2. The information for these ETEs was determined by a complete review of the insulation vendor drawings, Stone and Webster design changes for specifications associated with insulation, insulation specification changes, and design changes which could have impacted insulation. These document reviews provided the bases for engineering hand-over-hand walk-down of piping and components to determine the installed insulation type. Unacceptable insulation (Cal-Sil and/or Microtherm) was fully remediated when identified during walk-downs within the ZOIs for Units 1 and 2.

# 5.0 ADDITIONAL CORRECTIVE ACTIONS

The root cause evaluation team evaluated other aspects of the NAPS GSI-191 sump modification project—specifically coating program health, debris source classification, longterm chemical effects, and sump strainer design configuration. The Team determined that initial and subsequent actions associated with the aspects of the NAPS GSI-191 sump project were, and continue to be effectively governed by station policies and procedures.

Additional corrective actions from the final root cause evaluation will be documented in the Corrective Action Program and tracked to completion.

## 6.0 ACTIONS TO PREVENT RECURRENCE

Actions to prevent recurrence from the final root cause evaluation will be documented in the Corrective Action Program and tracked to completion.

## 7.0 SIMILAR EVENTS

None.

# 8.0 ADDITIONAL INFORMATION

None.

U.S. NUCLEAD DECULATORY COMMISSION