



FPL

POWERING TODAY.
EMPOWERING TOMORROW.®

FEB 4 2011

10 CFR § 50.73
L-2011-040

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555-0001

Re: Turkey Point Unit 4
Docket No. 50-251
Reportable Event: 2010-008-00
Date of Event: December 9, 2010
Manual Reactor Trip Due to Condenser Tube Leak

The attached Licensee Event Report 05000251/2010-008-00 is being submitted pursuant to 10 CFR 50.73(a)(2)(iv)(A) due to a valid manual actuation of the reactor protection system and associated manual reactor trip. If there are any questions, please call Mr. Robert J. Tomonto at 305-246-7327.

Very truly yours,

Michael Kiley
Vice President
Turkey Point Nuclear Plant

Attachment

cc: Regional Administrator, USNRC, Region II
Senior Resident Inspector, USNRC, Turkey Point Nuclear Plant

JE22
NRK

1. FACILITY NAME Turkey Point Unit 4 **2. DOCKET NUMBER** 05000251 **3. PAGE** 1 of 3

4. TITLE
Manual Reactor Trip Due to Condenser Tube Leak

MONTH			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
12	9	2010	2010	008	00	2	4	2011	FACILITY NAME	DOCKET NUMBER

9. OPERATING MODE 1 **11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)**

<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

12. LICENSEE CONTACT FOR THIS LER

NAME: Ronald Everett TELEPHONE NUMBER (Include Area Code): 305-246-6190

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
B	SG	TBG	T310	Y					

14. SUPPLEMENTAL REPORT EXPECTED YES (If yes, complete 15. EXPECTED SUBMISSION DATE) NO

15. EXPECTED SUBMISSION DATE

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

At 22:00 on December 9, 2010 Unit 4 had indication (high sodium) of a condenser tube leak. A rapid power reduction to less than 5% was commenced in accordance with plant procedures as the sodium levels increased to greater than 250 ppb (action level 3). Chemistry confirmed that the high sodium level was due to salt water intrusion from the 4BN Main Condenser tube bundle. A management decision was made to shutdown the reactor in accordance with plant procedures by manually opening the reactor trip breakers at about 22:58:13 from approximately 17.5% power. All systems functioned as designed and there was no impact on the health and safety of the public. The NRC was notified (Event Number 46471) at approximately 01:25 (EST) on December 10, 2010.

The direct cause of the condenser tube leak is considered to be a manufacturing defect (seam weld failure). Corrective actions involved plugging the failed tube and four other tubes with minimal indications. The failed tube will be removed during the next refueling outage (RFO PT4-26) and sent for analysis. Eddy Current Testing will be performed during RFO PT4-26 with conservative plugging criteria to plug all tubes with indications of greater than 50% wall-loss. Long term, the Unit 3 and Unit 4 condenser tube bundles are currently planned for replacement under the Extended Power Uprate Project.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Turkey Point Unit 4	05000251	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	Page 2 of 3
		2010	- 008	- 00	

NARRATIVE

DESCRIPTION OF THE EVENT

At 22:00 on December 9, 2010 Unit 4 had indication (high sodium) of a condenser tube leak. A rapid power reduction was commenced in accordance with plant procedures 4-ONOP-100, "Fast Load Reduction", 4-ONOP-071.1, "Secondary Chemistry Deviation from Limits" and 0-ADM-651, "Nuclear Chemistry Parameters Manual" as the sodium levels increased to greater than 250 ppb (action level 3). Chemistry confirmed that the high sodium level was due to salt water intrusion from the 4BN Main Condenser tube bundle. A management decision was made to shutdown the reactor in accordance with plant procedures by manually opening the reactor trip breakers at about 22:58:13 from approximately 17.5% power. All systems functioned as designed and there was no impact on the health and safety of the public. The NRC was notified (Event Number 46471) at approximately 01:25 (EST) on December 10, 2010.

CAUSE OF THE EVENT

The direct cause of the condenser tube leak is considered to be a manufacturing defect (seam weld failure). Corrective actions involved plugging the failed tube and four other tubes with minimal indications. The failed tube will be removed during the next refueling outage (RFO PT4-26) and sent for analysis. Eddy Current Testing will be performed during RFO PT4-26 with conservative plugging criteria to plug all tubes with indications of greater than 50% wall-loss. Long term, the Unit 3 and Unit 4 condenser tube bundles will be replaced under the Extended Power Uprate Project. A root cause analysis was performed of the Unit 4 event.

The power reduction to less than 5% was required because secondary chemistry parameters reached Action Level 3 (250 ppb) as defined in 0-ADM-651, "Nuclear Chemistry Parameters Manual," requiring an orderly power reduction to be initiated immediately as rapidly as other plant constraints permit.

ANALYSIS OF THE EVENT

The seawater contamination event and sodium level increase led to the decision to shutdown the reactor in accordance with plant procedures and therefore is reportable under 10 CFR 50.73(a)(2)(iv)(A) as "any event or condition that resulted in manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B) of this section." The Reactor Protection System (RPS) including reactor scram or reactor trip is included in the systems listed. All systems operated as expected during the reactor shutdown and there was no impact on the health and safety of the public.

Review of the operating history of Units 3 and 4 revealed no tube leakage events in Unit 3; however, in Unit 4 there was at least one event in 1990 due to welded seam defects in tubes. Both units have had previous tube leaks due to other causes, e.g. damage from flashing, plug leakage, rolled joint failures, and vibration. The Units 3 and 4 condensers have some tube bundles from the same manufacturer.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Turkey Point Unit 4	05000251	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	Page 3 of 3
		2010	- 008	- 00	

NARRATIVE

CORRECTIVE ACTIONS

Corrective actions involved plugging the failed tube and four other tubes with minimal indications. The failed tube will be removed during the next refueling outage (RFO PT4-26) and sent for analysis. Eddy Current Testing will be performed during RFO PT4-26 with conservative plugging criteria to plug all tubes with indications of greater than 50% wall-loss. Long term, the Unit 3 and Unit 4 condenser tube bundles are currently planned for replacement under the Extended Power Uprate Project.

ADDITIONAL INFORMATION

EIIS Codes are shown in the format [IEEE system identifier, component function identifier, second component function identifier (if appropriate)].

SIMILAR EVENTS

There have been no similar Turkey Point LERs in the last five years. Based on internal operating experience review, the only similar tube leak event resulting from a tube manufacturing welded seam defect was back in 1990.