

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8104170430 DUC DATE: 81/04/09 NOTARIZED: NO
 FACIL: 50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au
 AUTH. NAME AUTHOR AFFILIATION
 MILLS, L.M. Tennessee Valley Authority
 RECIP. NAME RECIPIENT AFFILIATION
 O'REILLY, J.P. Region 2, Atlanta, Office of the Director

DOCKET #
 05000438
 0700043

SUBJECT: Third interim deficiency rept re fillet weld misspec,
 initially reported 801107. Each individual plant, American
 Inst of Steel Const Stds & affected welds are being
 evaluated. Next rept expected by 810707.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:


	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
ACTION:	A/D LICENSNG 04	1	1	YOUNGBLOOD, B 05	1	1
	RUSHBROOK, M. 06	1	1	BOURNIA, T. 07	1	1
INTERNAL:	ASLBP/J. HARD	1	1	D/DIR HUM FAC15	1	1
	EDO & STAFF 19	1	1	EQUIP QUAL BR11	1	1
	HYD/GEO BR 22	1	1	I&E 09	1	1
	IE/EES	1	1	LIC QUAL BR 12	1	1
	MPA 20	1	1	NRC PDR 02	1	1
	DELD 21	1	1	PROC/IST REV 13	1	1
	QA BR 14	1	1	REG FILE 01	1	1
	RUTHERFORD, W. IE	1	1	STANDORDS DEV 21	1	1
EXTERNAL:	ACRS 16	16	16	LPDR 03	1	1
	NSIC 08	1	1			

TOTAL NUMBER OF COPIES REQUIRED: LTTR 38 ENCL 38

50-436
439

400 Chestnut Street Tower II

April 9, 1981



Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - FILLET WELD MISSPECIFICATION - NCR
BLN BLP 8007 - THIRD INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. W. Wright on November 7, 1980, in accordance with 10 CFR 50.55(e). This was followed by our interim reports dated December 3, 1980 and January 19, 1981. Enclosed is our third interim report. We expect to submit our next report by July 7, 1981. This deficiency has also been reported for every TVA nuclear plant.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

810.4170430

5

13019
S/1

ENCLOSURE
BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2
FILLET WELD MISSPECIFICATION
NCR BLN BLP 8007
10 CFR 50.55(e)
THIRD INTERIM REPORT

Description of Deficiency

In a number of Bellefonte Nuclear Plant systems, fillet welds were specified, in lieu of beveled groove welds, to connect members whose angle of intersection is outside the limits for fillet weld application as stipulated in the American Institute of Steel Construction (AISC) Standards. The AISC Standard states that the welds which are made joining members at an angle of 60° or less are to be defined as acute angle welds. Acute angle welds should be specified as beveled groove welds according to AISC.

Interim Progress

A design review of the TVA nuclear facilities has revealed the above discrepancy exists in some form at every TVA plant. TVA is evaluating each individual plant and will issue reports on each. TVA is also in the process of evaluating the AISC Standards and the affected welds in order to determine a satisfactory resolution.