1	an a	
PART 21 IDENTIFICA	TION. 81-409-000	O'PANY NAME TVA
DATE OF LETTER	DOCKET NO. 50.	-439
DATE DISTRIBUTED	ORIGINAL REPO	RT SUPPLEI'ENTARY
DISTRIBUTION:		·
REACTOR (R) 2	FUEL CYCLE &	SAFEGUARDS (S)
IE FILES	MATERIALS (M)	IE FILES
ES - mills	IE FILES	AD/SG
•	AD/FFMSI	AD/ROI
REGIONS I, II, III, IV	REGIONS I, II, III, IV, V	REGIONS I, II, III, IV, V
VENDOR BR. R-IV	VENDOR BR. R-IV	VENDOR BR. RIV
LOEB / MPA MNB 571	5 NMSS / FOMS SS-395	NRR/DOL
AEDD MNB 760	LOEB / MPA MAB 5715	NMSS / SG SS-881
NRVDE	AEOD MAB 7602	LDEB / MPA MUB 5715
NRR/DSI	ASLEP E/W 450	AEOD MNB 7602
NPR/DST	SAP/SP MNB-7210A	ASIBP FAU 1150
NFR/DOL -		
ASLBP E/W 450	CENTRAL FILES ULD	CENTRAL FILES UID
	- COR	CENTRAL FILES (CHRUN)
		CENTRAL FILES SS-395
	- LPUR STORM.	
אעז	LIERA 27 APP	
	U. S. NUCLEAR RECT.	- IERA
	1. The second rock	· ·
ACTION:	SILIE! LINE	•
PRELIMINARY EVALUATIO	ON OF THE ATTACHED REPORT INDICATES	S LEAD RESPONSIBILITY FOR
FOLLOWUP AS SHOWN BEI	_OW:	•
		MISS OTHER
EES		
5 8104280049	• • • • • •	DI 8/1/5
	e de la construcción de la const	

NNESSEE VALLEY AUTHO

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

April 13, 1981

81-409-000

BLRD-50-349/81-04

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNIT 2 - ATWOOD AND MORRILL VALVE DEFICIENCY - BLRD-50-439/81-04 - FINAL REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector M. Thomas on December 12, 1980, in accordance with 10 CFR 50.55(e) as NCR 1312. This was followed by our first interim report dated January 12, 1981. Enclosed is our final report. We consider 10 CFR Part 21 to be applicable to this nonconformance.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure) Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

## ENCLOSURE BELLEFONTE NUCLEAR PLANT UNIT 2 ATWOOD AND MORRILL VALVE DEFICIENCY 10 CFR 50.55(e) BLRD-50-439/81-04 FINAL REPORT

## Description of Deficiency

Decay heat removal valve Mark No. 3RW0413-ND-3D (12" check valve) S/N 142-13894 (ASME III-2), which was manufactured by Atwood and Morrill (A&M) has a surface crack approximately two inches long. The crack is located in the upper body of the valve. In addition, an area\_ approximately 2-5/8" by 3-5/8" has been ground to an approximate depth of 1/4". The grinding activity was performed without engineering authorization. The site's welding unit was unable to determine minimum wall thickness because of different contours in the valve's inner and outer diameters.

## Safety Implications

The subject value is intended for use in emergency core flooding piping. Failure of this value could result in an escape of the heat transfer medium and, consequently, in a degraded ability to remove decay heat.

## Corrective Action

The valve in question was returned to A&M for examination. A&M's preliminary examination indicated a surface discontinuity. Therefore, A&M ground out the affected area and performed a liquid penetrant test. A&M verified minimum wall thickness for pressure boundary and also verified minimum wall thickness used in the seismic analysis and found it to be acceptable. A&M blended out the affected area to the proper contour per the ASME B&PV Code. TVA will visually inspect the valve at A&M before it is released to be returned to the site.

During the inspection of the valve surface discontinuity by A&M, it was discovered that the incorrect material was used for the pressure seal cover locking plate. The drawings and specifications of the valve designate that it must be made of stainless steel; the finished plate was made of carbon steel. A&M replaced the locking plate with the correct material and submitted a Supplier's Nonconformance Report to TVA. The locking plate is used to guide the pressure seal cover into place during pressurization and is not a "pressure retaining" component of the valve.

In order to prevent recurrence, TVA inspectors shall witness MT and PT when required and do a complete visual inspection on all ASME Section III castings whenever possible. Primary emphasis shall be placed on Class I castings.

TVA Division of Construction personnel have been cautioned to alert Division of Engineering Design (EN DES) personnel of questionable or unacceptable surface discontinuities before repairs are initiated.