REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8005160319 DOC.DATE: 80705/07 NOTARIZED: NO DOCKET # FACIL:50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439 AUTH-NAME AUTHOR AFFILIATION

MILLS, L.M.

Tennessee Valley Authority

RECIP NAME

RECIPIENT AFFILIATION

SUBJECT: Sixth interim deficiency rept re tensile anchor capabilities lower than design allowables. Testing & evaluation programs for welded stud anchors w/flexible plate connections is progressing. Next rept will be submitted by 800905.

DISTRIBUTION CODE: 8019S COPIES RECEIVED:LTR _ ENCL _ SIZE:________
TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:_____

ACTION:	RECIPIENT ID CODE/NAME 14 PM BOURNIA 20 LA CWR #3	COPIES LTTR ENCL 1 1	RECIPIENT ID CODE/NAME 15 BC LWR #3 21 AD LWR	COPIES LTTR ENCL 1
INTERNAL:	REG FILE 05. 18E 08 MPA 10 GAB 13FIELD COOR/IE 17 AD PLANT SYS 22 DIR DPM AD/RCI/IE AEOD GEOSCIENCES BR 18C SYS BR MECH ENG BR STRUCT ENG BR	1 1	02 NRC PDR 07 EDO & STAFF 09 DEPY DIR DPM 11 STANDRDS DEV 16 AD FOR ENGR 17 AD REAC SFTY 23 OELD AD/SITE TECH DIRECTOR DSE HANAUER,S. MATL ENG BR POWER SYS BR	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
EXTERNAL:	03 LPDR 24 ACRS	1 16 16	04 NSIC	1

MAY 2 0 1960

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA. TENNESSEE 37401 400 Chestnut Street Tower II

May 7, 1980

Mr. James P. Q'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - TENSILE ANCHOR CAPACITIES LOWER THAN DESIGN ALLOWABLES - NCR CEB 79-7 - SIXTH INTERIM REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector T. Burdette on February 12, 1979, in accordance with 10 CFR 50.55(e). This was followed by our interim reports dated March 14, May 17, July 30, and December 17, 1979, and February 29, 1980. TVA is progressing with its testing and evaluation programs for welded stud anchors with flexible plate connections. We expect to submit our next written report by September 5, 1980. This deficiency was also reported for Watts Bar, Sequoyan, Hartsville, and Phipps Bend Nuclear Plants.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager Nuclear Regulation and Safety

office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555