					•		
•. •	REGUL	ATORY I	ORMATION	DISTRIBUTI	ON SYS	(RIDS)	
ACCESSION FACIL:50 AUTH.N	N NBR:8008110 D-438 Bellefo D-439 Bellefo AME AU	0446 DO onte Nucle onte Nucle UTHOR AFFI	C.DATE: ar Plant ar Plant LIATION	80/08/01 N , Unit 1, T , Unit 2, T	OTARIZED ennessee ennessee	NO Valley Au Valley Au	DOCKET # 05000438 05000439
MILLS,L RECIP.	M. Ten NAME RE	nessee Va CIPIENT A	lley Aut FFILIATI	hority ON	·.	en p	4,
SUBJECT	Einal defic fixture sup modified to	iency rep port rods show pla	t re exc "Cause n cement o	essive dist ot stated.I f addl supp	ance bety nstallati	een light on drawing	ing gs
DISTRIBU	JTION CODE: B TITLE: C	0195 COP Constructi	IES RECE on Defic	IVEDILTR	ENCL _/	SIZE:	2
NOTES			i	•			
ACTION:	RECIPIENT ID CODE/NAM A/D LICENSNG RUSHBROOK,M.	COP IE LTT 21 1 20 1	IES R ENCL 1 1	RECIPIE ID CODE/ YOUNGBLOO BOURNIA,T	NT NAME D,B 15 . 14	COPIES LTTR ENCL 1 1 1 1	· .
INTERNAL	AD/RCI/IE D/DIR HUM FA EDO & STAFF I&E MPA OELD QA BR RUTHERFORD,W	1 07 05 08 1 23 1 10 1 1E 1	1 1 2 1 1 1 1	AEOD DIR,HUM F EQUIP QUA LIC QUAL NRC PDR PRO <u>C/I</u> SI REG FILE STANDRDS	AC SFY L BR16 BR 02 REV BR 01 DEV 11	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	•••
EXTERNAL:	ACRS NSIC	24 16 04 1	16 1	LPDR	03	1 1	

AUG 12 1980

ENCL 39

39

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401 400 Chestnut Street Tower II

August 1, 1980

50-4258

8019 ^s/,

Mr. James P. O'Reilly, Director Office of Aspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - SEISMIC SUPPORTS FOR LIGHTING FIXTURES - NCR 1172 - FINAL REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector R. W. Wright on April 21, 1980, in accordance with 10 CFR 50.55(e). This was followed by our first interim report dated May 21, 1980. Enclosed is our final report.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555



BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 SEISMIC SUPPORTS FOR LIGHTING FIXTURES NCR 1172 10 CFR 50.55(e) FINAL REPORT

ENCLOSURE

Description of Deficiency

The distance between lighting fixture support rods in the following areas have as much as 96 inches between the 3/8-inch unistrut support rods. TVA drawings limit this distance to 72 inches.

Control Building

- EL 610 Corridor, battery rooms C4, C5, C6, C7, C8, C9, and communcation room
- EL 629 Auxiliary Instrument Rooms C2 and C5, computer room, and corridor
- EL 658 Spreading Room (upper level)

Auxiliary Building

EL 590 Corridor A5-A10

The length of lighting fixture support rods (3/8-inch unistrut support rods) in the following areas exceed the maximum length of 96 inches allowed by TVA drawings.

Control Building

- EL 610 Corridor, battery rooms C4, C5, C6, C7, C8, C9, and communication room The length of the 3/8-inch rods is 100 to 104 inches.
- EL 629 Auxiliary instrument rooms C2 and C5, computer room, and corridor Maximum length of 3/8-inch rods is 128 inches.

Safety Implications

Failure of light fixtures to hang in place during and after the SSE could lead to damaging of safety-related euqipment. Inadequate supports could allow the lights to fall, possibly damaging equipment required to bring the plant to a safe shutdown condition post-SSE.

Corrective Action

Evaluation of the installed design was performed and necessary modifications were specified to bring the existing installation in line with design requirements for seismic qualification. Since the installations are physically sound except for earthquakes, modifications to the existing installation will consist of the addition of structural tubes and/or auxiliary stainless steel cable as required to protect any equipment located in the area. Installation drawings have been modified to show placement of additional supports.

In the future, installation problems are to be brought to the attention of Engineering Design in a timely manner so that new designs for fixture supports can be evaluated and furnished before proceeding with installation.