

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8009160377 DOC. DATE: 80/09/08 NOTARIZED: NO DOCKET #
 FACIL: 50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438
 50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439
 AUTH. NAME AUTHOR AFFILIATION
 MILLS, L.M. Tennessee Valley Authority
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: First interim deficiency report re 480-volt motor control ctr
 control transformer fuses per 10CFR50.55e & 10CFR21. Design
 of control circuits is being reevaluated to determine cause
 of fuse operation & what changes are required.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR: 1 ENCL: 1 SIZE: 2
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

ACTION:	RECIPIENT		COPIES		RECIPIENT	COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME	LTR
ACTION:	A/D LICENSING 04		1	1	YOUNGBLOOD, B 05	1	1
	RUSHBROOK, M. 06		1	1	BOURNIA, T. 07	1	1
INTERNAL:	AD/RCI/IE 17		1	1	AEOD 18	1	1
	ASLB/P/J. HARD		1	1	D/DIR HUM FAC 15	1	1
	DIR, HUM FAC S10		1	1	EDO & STAFF 19	1	1
	EQUIP QUAL BR 11		1	1	I&E 09	2	2
	LIC QUAL BR 12		1	1	MPA 20	1	1
	NRC PDR 02		1	1	OELD 21	1	1
	PROC/TST REV 13		1	1	QA BR 14	1	1
	REG FILE 01		1	1	RUTHERFORD, W. IE	1	1
EXTERNAL:	STANDRDS DEV 21		1	1			
	ACRS 16	16	16		LPDR 03	1	1
	NSIC 08	1	1				

SEP 17 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 41 ENCL 41

R

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

September 8, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - 480V MCC CONTROL TRANSFORMER FUSES
- NCR 1234 - FIRST INTERIM REPORT

The subject nonconformance was initially reported to NRC-OIE Inspector M. Thomas on August 8, 1980, in accordance with 10 CFR 50.55(e). Enclosed is our first interim report. We expect to submit our next written report by October 24, 1980. We consider 10 CFR Part 21 to be applicable to this nonconformance.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
S
1/1

ENCLOSURE

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2
480V MCC CONTROL TRANSFORMER FUSES

NCR 1234

10 CFR 50.55(e)

FIRST INTERIM REPORT

Description of Deficiency

The motor control centers (MCC) at Bellefonte were supplied by GOULD-BROWN BOVERI, Westminster, Maryland. The 5 kVA and 10 kVA control transformers for these MCC's utilize 15 and 30 amp type J fuses, respectively. These fuses have operated when the control circuit is energized. The fuses apparently were not properly chosen to coordinate with the inrush current.

Corrective Action

TVA and GOULD-BROWN BOVERI are reevaluating the design of the control circuits to determine the cause of the fuse operation and what changes are required to correct the problem.