



LIC-11-0022  
April 4, 2011

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555-0001

Reference: Docket No. 50-285

**Subject: Licensee Event Report 2011-002, Revision 0, for the Fort Calhoun Station**

Please find attached Licensee Event Report 2011-002, Revision 0, dated, April 4, 2011. This report is being submitted pursuant to 10CFR50.73(a)(2)(i)(B). If you should have any questions, please contact me.

Sincerely,

A handwritten signature in black ink, appearing to read "Jeffrey Reinhart", is written over a faint, larger version of the signature.

Jeffrey Reinhart  
Site Vice President

JAR/epm

Attachment

c: E. E. Collins, Jr., NRC Regional Administrator, Region IV  
L. E. Wilkins, NRC Project Manager  
J. C. Kirkland, NRC Senior Resident Inspector  
INPO Records Center

# LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to [infocollects.resource@nrc.gov](mailto:infocollects.resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NE0B-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

<b>1. FACILITY NAME</b> Fort Calhoun Station	<b>2. DOCKET NUMBER</b> 05000285	<b>3. PAGE</b> 1 OF 4
---	-------------------------------------	--------------------------

**4. TITLE**  
Failure of an RPS Trip Unit

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
2	4	2011	2011	- 002	- 04		4	2011		05000
									FACILITY NAME	DOCKET NUMBER
										05000

<b>9. OPERATING MODE</b>  1	<b>11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §:</b> <i>(Check all that apply)</i>									
	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)						
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)						
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)						
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)						
<b>10. POWER LEVEL</b>  100	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)						
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)						
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)						
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER	Specify in Abstract below or in NRC Form 366A					
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)							

**12. LICENSEE CONTACT FOR THIS LER**

FACILITY NAME Erick Matzke	TELEPHONE NUMBER <i>(Include Area Code)</i> 402-533-6855
-------------------------------	---

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE SY	STEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE SY	STEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

<b>14. SUPPLEMENTAL REPORT EXPECTED</b> <input checked="" type="checkbox"/> YES <i>(If yes, complete 15. EXPECTED SUBMISSION DATE)</i> <input type="checkbox"/> NO	<b>15. EXPECTED SUBMISSION DATE</b>	MONTH	DAY	YEAR
		7	29	2011

**ABSTRACT** *(Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)*

On November 29, 2010, during the performance of a work order, voltage at reactor protective system (RPS) connection T-74 was found 39 millivolt (mV) higher than connection T-17 (RPS ground). The allowed limit is 4 mV. T-74 is the signal common lead for steam generator (SG) pressure channels 902 and 905 inputs to Trip Unit 6 (Low SG Pressure) and Trip Unit 7 (Asymmetric SG Transient). Further investigation determined that the affected channels should have been declared inoperable. With a channel of RPS inoperable the appropriate section of Technical Specifications should have been entered. The TS LCO action times were not met.

A root cause analysis is in progress the results of the analysis will be reported in a revision to this LER.

The wire between terminals T-74 and relay contact terminal 12 was replaced. Additional corrective actions will be documented in a revision to this LER.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF	4
		2011	- 002	- 0		

**NARRATIVE**

**BACKGROUND**

The Fort Calhoun Station (FCS) reactor protective system (RPS) is designed to rapidly shut down the nuclear chain reaction prior to reaching a condition that could damage the reactor core. The RPS generates a reactor trip signal, which releases the control element assemblies and allows the control rods to fall into the core.

The RPS protects the plant from abnormal events that have the potential to threaten safe operation and is designed in accordance with the proposed Institute of Electrical and Electronics Engineers (IEEE) 279-1968, Criteria for Protection Systems for Nuclear Power Generating Stations. The RPS comprises four independent instrumentation channels. Each channel has a separate vital power supply with parallel cable raceways. Two out of four logic is used to initiate a trip to ensure a single failure will neither cause nor prevent system operation. Each channel monitors 12 safety parameters; each parameter input is derived from an isolated instrument channel. Each parameter operates a two out of four coincidence logic matrix to maintain or remove power from the control element drive mechanism (CEDM) clutches. Individual channel trips occur when the measurement reaches a preselected value. The channel trips are combined in six two out of four matrices. Each individual measurement channel has inputs to three of the six logic matrices. The logic matrix trip relays are deenergized when two channels of the same measurement channel trip. Each of the two out of four logic matrices provides a trip signal to the interposing relays which in turn causes a direct trip of the contactors in the AC supply to the CEDM clutch power supplies. Any one of the six logic matrices will deenergize the four clutch power supplies. The logic matrices are arranged in a one out of six logic configuration. The clutch power supply DC outputs are ungrounded.

FCS Technical Specifications (TS) 2.15 requires:

The operability, permissible bypass, and Test Maintenance and Inoperable bypass specifications of the plant instrument and control systems shall be in accordance with Tables 2-2 through 2-5.

- (1) In the event the number of channels of a particular system in service falls one below the total number of installed channels, the inoperable channel shall be placed in either the bypassed or tripped condition within one hour if the channel is equipped with a bypass switch, and eight hours if jumpers or blocks must be installed in the control circuitry. The inoperable channel may be bypassed for up to 48 hours from time of discovering loss of operability; however, if the inoperability is determined to be the result of malfunctioning RTDs or nuclear detectors supplying signals to the high power level, thermal margin/low pressurizer pressure, and axial power distribution channels, these channels may be bypassed for up to 7 days from time of discovering loss of operability. If the inoperable channel is not restored to OPERABLE status after the allowable time for bypass, it shall be placed in the tripped position or, in the case of malfunctioning RTDs or linear power nuclear detectors, the reactor shall be placed in hot shutdown within 12 hours. If active maintenance and/or surveillance testing is being performed to return a channel to active service or to establish operability, the channel may be bypassed during the period of active maintenance and/or surveillance testing. This specification applies to the high rate trip-wide range log channel when the plant is at or above 10-4% power and is operating below 15% of rated power.

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF	4
		2011	- 002	- 0		

**NARRATIVE**

(2) In the event the number of channels of a particular system in service falls to the limits given in the column entitled "Minimum Operable Channels," one of the inoperable channels must be placed in the tripped position or low level actuation permissive position for the auxiliary feedwater system within one hour, if the channel is equipped with a bypass switch, and within eight hours if jumpers or blocks are required; however, if minimum operable channel conditions for SIRW [Safety Injection Refueling Water] tank low signal are reached, both inoperable channels must be placed in the bypassed condition within eight hours from time of discovery of loss of operability. If at least one inoperable channel has not been restored to OPERABLE status after 48 hours from time of discovering loss of operability, the reactor shall be placed in a hot shutdown condition within the following 12 hours; however, operation can continue without containment ventilation isolation signals available if the containment ventilation isolation valves are closed.

**EVENT DESCRIPTION**

On November 29, 2010, during the performance of a work order, voltage at RPS connection T-74 was found 39 millivolt (mV) higher than connection T-17 (RPS ground). The allowed voltage difference is 4 millivolt (mV). T-74 is the signal common lead for steam generator (SG) pressure channels 902 and 905 which are inputs to Trip Unit 6 (Low SG Pressure) and Trip Unit 7 (ASGT). T-74 is electrically connected to the Thermal Margin/Low Pressure (TM/LP) calculator common T-17 (RPS ground) through a relay. Since T-74 and T-17 are normally connected through closed relay contacts, the electric potential between the terminal points remains zero so long as there is electrical continuity.

Electrical continuity between T-74 and T-17 was assumed following the installation of the Asymmetric SG Transient Trip (ASGT) modification MR-FC-83-44 in 1984. T-74 and T-17 need to be at nearly the same potential to maintain SG Low Pressure and ASGT trip setpoint calibration accuracy.

Multiple occurrences of poor electrical continuity (e.g. potential difference) between TM/LP calculator AI-31A-AW12 points T-74 and T-17 have been documented since 1993. Over several years it was assumed that the relay contacts or terminal points had degraded. In response to condition report (CR) 1998-0443, a quarterly surveillance test (IC-ST-RPS-0018, Quarterly Functional Test of Steam Generator Low Pressure and Asymmetric Steam Generator Transient RPS Bistable Trip Units) was revised to verify appropriate value of signal common. A refueling cycle surveillance test (IC-ST-RPS-0044, Calibration of Steam Generator Low Pressure Trip Unit A/TU-6 and Asymmetrical Steam Generator Transient Trip Unit A/TU-7) checked for proper functioning of the circuit. CR 2010-5667 describes an out-of-tolerance (OOT) condition found on November 8, 2010, which resulted in daily measurement of the voltage difference between T-74 and T-17. On November 29, 2010, during the performance of the daily measurement, a 39 millivolt difference was measured between T-74 and T-17. During subsequent troubleshooting personnel discovered intermittent continuity in the wire between T-74 and relay contact terminal 12.

The wire between terminals T-74 and relay contact terminal 12 was replaced. The suspected section of wire was removed for examination. Initial failure analysis has proved inconclusive. No failure or degradation of the wire has been detected. Further investigation determined that the affected channels should have been declared inoperable. With a channel of RPS inoperable TS 2.15 should have been entered. The TS LCO action times were not met. This report is being made in accordance with 10 CFR 50.73(a)(2)(i)(B).

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Fort Calhoun Station	05000285	YEAR	SEQUENTIAL NUMBER	REV NO.	4 OF	4
		2011	- 002	- 0		

**NARRATIVE**

**CONCLUSION**

A root cause analysis is in progress. The results of the analysis will be reported in a revision to this LER.

**CORRECTIVE ACTIONS**

The wire between terminals T-74 and relay contact terminal 12 was replaced. Additional corrective actions will be documented in a revision to this LER.

**SAFETY SIGNIFICANCE**

The overall effect on the one SG Low Pressure trip setpoint was less than 10 pounds per square inch (psi) at 39 millivolts and not more than 30 psi at the highest ever recorded difference of 120 millivolts recorded on May 14, 2009.

Even with a failed instrument channel, the margin of safety as defined in the basis of the FCS TS was maintained. The plant was always able to trip on Low SG pressure in, at least, a two out of two reactor protection logic. Even with these RPS channels inoperable, the single failure criteria for the RPS system was met. Therefore the health and safety of the public was not impacted by this RPS failure.

**SAFETY SYSTEM FUNCTIONAL FAILURE**

This event does not result in a safety system functional failure in accordance with NEI-99-02.

**PREVIOUS EVENTS:**

No previous LER have documented problems with this circuitry in RPS.