

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED: BRUCK ENGINEERING LTD. 7266 Devonshire Dr. St. Louis, MO 63119 REPORT NUMBER(S) 2011/01</p>	<p>2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warranville Rd. S.W. 210 LISIC, IL 60532-4351</p>
--	--

<p>3. DOCKET NUMBER(S) 030-34708</p>	<p>4. LICENSEE NUMBER(S) 24-32076-01</p>	<p>5. DATE(S) OF INSPECTION 3/15/11</p>
---	---	--

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied

_____ Non-cited violation(s) were discussed involving the following requirement(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	E. L. KULZEP	<i>E. L. Kulzer</i>	3/15/11
Branch Chief	T. Bloomer	<i>T. Bloomer</i>	3/25/11

NRC FORM 591 M PART 3
(06-2010)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE
Brucker Engineering, LTD
7266 Devonshire Dr.
St. Louis, MO 63119

2. NRC/REGIONAL OFFICE
NRC Region III
2443 Warrenville, Rd
Lisle, IL 60532

REPORT NUMBER(S) **2011-001**

3. DOCKET NUMBER(S)

030-34708

5. LICENSE NUMBER(S)

24-32076-01

6. DATE(S) OF INSPECTION

03/15/2011

7. INSPECTION

PROCEDURES **87124**

8. INSPECTION FOCUS AREAS

03/01-03.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM

03121

2. PRIORITY

5

3. LICENSEE CONTACT

J. Leo Turek

4. TELEPHONE NUMBER

314-961-4495

Main Office Inspection

Next Inspection Date: 3/2016

Field Office Inspection

Temporary Job Site Inspection

PROGRAM SCOPE

The licensee is a small soils engineering firm. The licensee possesses four Humbolt moisture density gauges, containing approximately 10 millicuries of cesium-137 and 40 millicuries of americium-241. The licensee also has a Seaman density gauge containing radium-226. The licensee stores these gauges in an outside locked building in a locked storage cabinet. The licensee transports these gauges in a pickup truck with a locked cap and a second locked cable. The licensee does not perform any service or maintenance activities on its gauges; these services are performed by the manufacturer. Currently, the licensee employs three authorized gauge users who have completed manufacturers training.

Performance Observations

At the time of this inspection, the gauges were not in use. The operator possessed required shipping papers which contained all appropriate information and were accessible in the transport vehicle. The operator demonstrated an adequate level of understanding of emergency and handling procedures during interviews. Security during transport and at the job-site was described with no problems noted.