

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9403040333 DOC. DATE: 94/02/17 NOTARIZED: NO DOCKET #
FACIL: 50-438 Bellefonte Nuclear Plant, Unit 1, Tennessee Valley Au 05000438
50-439 Bellefonte Nuclear Plant, Unit 2, Tennessee Valley Au 05000439

AUTH. NAME AUTHOR AFFILIATION
MCCLUSKEY, H.F. Tennessee Valley Authority
RECIP. NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Final deficiency rept re Foxboro cabinets w/missing vibration dampening equipment. Initially reported on 940121. Affected cabinets which do not comply w/requirements noted in vendor manual will be reworked as necessary.

DISTRIBUTION CODE: IE27D COPIES RECEIVED: LTR / ENCL / SIZE: 4
TITLE: 50.55(e) Construction Deficiency Report

NOTES:

| | RECIPIENT | | COPIES | | RECIPIENT | | COPIES | |
|-----------|---------------|-----------|--------|------|---------------|-----------|--------|------|
| | ID | CODE/NAME | LTTR | ENCL | ID | CODE/NAME | LTTR | ENCL |
| | PD2-4 | | 1 | 1 | THADANI, M | | 1 | 1 |
| INTERNAL: | ACRS | | 16 | 16 | DEDRO | | 1 | 1 |
| | NRR/DORS/OEAB | | 1 | 1 | NRR/DRIL/RPEB | | 1 | 1 |
| | NRR/DRIL/RVIB | | 1 | 1 | OGC/HDS1 | | 1 | 1 |
| | REG FILE | 02 | 1 | 1 | RES/DSIR/EIB | | 1 | 1 |
| | RGN2 FILE | 01 | 1 | 1 | | | | |
| EXTERNAL: | NRC PDR | | 1 | 1 | NSIC SILVER | | 1 | 1 |

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 28 ENCL 28

A02



Tennessee Valley Authority, Post Office Box 2000, Hollywood, Alabama 35752

H. Fred McCluskey
Site Vice President, Bellefonte Nuclear Plant

FEB 17 1994

BLRD-50-438/94-03
BLRD-50-439/94-03

10 CFR 50.55(e)

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

Gentlemen:

In the Matter of the Application of)
Tennessee Valley Authority)

Docket Nos. 50-438
50-439

BELLEFONTE NUCLEAR PLANT (BLN) - FOXBORO CABINETS WITH MISSING
VIBRATION DAMPENING EQUIPMENT - BLRD-50-438/94-03 AND
BLRD 50-439/94-03 - FINAL REPORT

The subject deficiency was reported to NRC Operations Center on January 21, 1994 in accordance with 10 CFR 50.55(e)(3) as Problem Evaluation Report (PER) BLP930119. This deficiency involves Foxboro cabinets that have been found to have inadequately installed vibration dampening equipment. Enclosure 1 provides the final report for the subject deficiency. Enclosure 2 identifies the commitments being made as a result of this report.

Should there be any questions regarding this information, please telephone G. M. Morrison, BLN Acting Site Licensing Manager, at (205) 574-8057.

H. F. McCluskey
H. Fred McCluskey *[Signature]*

Enclosures

9403040333 940217
PDR ADDCK 0500043B
B PDR

JE27

U.S. Nuclear Regulatory Commission

Page 2

FEB 17 1994

cc (Enclosures):

NRC Resident Inspector
Bellefonte Nuclear Plant
P. O. Box 2000
Hollywood, Alabama 35752

Mr. R. V. Crlenjak
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Mr. M. C. Thadani, Project Manager
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852

ENCLOSURE 1

BELLEFONTE NUCLEAR PLANT (BLN) - UNITS 1 AND 2 FOXBORO CABINETS WITH MISSING VIBRATION DAMPENING EQUIPMENT PER BLP930119 - BLRD-50-438/94-03 AND BLRD-50-439/94-03

FINAL REPORT

Description of Deficiency

Safety-related Foxboro cabinets at BLN were found to have missing bumpers, guides, and dummy modules as well as empty nests and bumpers and guides not properly installed as the result of the review and evaluation of the problems identified in NRC IE Notice 91-070. Proper installation of equipment is required to ensure that the equipment will perform the needed safety function during a seismic event.

Safety Implications

A loss of redundancy in safety-related circuits could occur preventing the safety-related equipment from performing during an accident. The cabinets contain multiple system circuits involving various safety-related circuits such as auxiliary feedwater, essential raw cooling water, and decay heat removal.

Corrective Actions

Maintenance Instruction MI 2AN-105, which provides installation instructions for the nests, will be reviewed and included into the BLN vendor manual program for the Foxboro Spec 200 equipment as part of the vendor manual. The vendor manual will be the basis for evaluation of the deficient cabinets. The affected cabinets which do not comply with the requirements identified in the vendor manual will be reworked as necessary to correct the deficiencies identified in PER BLP930119.

ENCLOSURE 2

**BELLEFONTE NUCLEAR PLANT - UNITS 1 AND 2
FOXBORO CABINETS WITH MISSING VIBRATION DAMPENING MATERIAL
PER BLP930119 - BLRD-50-438/94-03 AND BLRD-50-439/94-03**

COMMITMENT

The affected Foxboro cabinets which do not comply with the requirements identified in the vendor manual will be reworked as necessary to correct the deficiencies identified in PER BLP930119 by one year before fuel load for each unit.