



April 22, 2011

NRC 2011-0043
10 CFR 50.73

Regional Administrator, Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

Point Beach Nuclear Plant, Units 1 and 2
Dockets 50-266 and 50-301
Renewed License Nos. DPR-24 and DPR-27

Licensee Event Report 301/2011-001-00
Both Trains of SI Inoperable

Enclosed is Licensee Event Report (LER) 301/2011-001-00 for Point Beach Nuclear Plant (PBNP), Unit 2. Pursuant to 10 CFR 50.73(a)(2)(v)(D), the event is reportable as a degraded accident mitigation because of 2-emergency core cooling system (ECCS) trains were inoperable.

This submittal contains no new or revised regulatory commitments.

If you have questions or require additional information, please contact Mr. James Costedio at 920/755-7427.

Very truly yours,

NextEra Energy Point Beach, LLC

A handwritten signature in black ink, appearing to read "Larry Meyer". The signature is fluid and cursive, with a large loop at the beginning and a small flourish at the end.

Larry Meyer
Site Vice President

Enclosure

cc: Administrator, Region III, USNRC
Project Manager, Point Beach Nuclear Plant, USNRC
Resident Inspector, Point Beach Nuclear Plant, USNRC
PSCW

LICENSEE EVENT REPORT (LER)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

| | | |
|--|-------------------------------------|--------------------------|
| 1. FACILITY NAME Point Beach Nuclear Plant | 2. DOCKET NUMBER 05000301 | 3. PAGE 1 of 3 |
|--|-------------------------------------|--------------------------|

4. TITLE
Both Trains of SI Inoperable

| 5. EVENT DATE | | | 6. LER NUMBER | | | 7. REPORT DATE | | | 8. OTHER FACILITIES INVOLVED | |
|---------------|-----|------|---------------|-------------------|---------|----------------|-----|------|------------------------------|---------------|
| MONTH | DAY | YEAR | YEAR | SEQUENTIAL NUMBER | REV NO. | MONTH | DAY | YEAR | FACILITY NAME | DOCKET NUMBER |
| 02 | 27 | 2011 | 2011 | 001 | 00 | 04 | 22 | 2011 | FACILITY NAME | DOCKET NUMBER |

9. OPERATING MODE
MODE 1

10. POWER LEVEL
100%

11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)

| | | | |
|---|---|---|---|
| <input type="checkbox"/> 20.2201(b) | <input type="checkbox"/> 20.2203(a)(3)(i) | <input type="checkbox"/> 50.73(a)(2)(i)(C) | <input type="checkbox"/> 50.73(a)(2)(vii) |
| <input type="checkbox"/> 20.2201(d) | <input type="checkbox"/> 20.2203(a)(3)(ii) | <input type="checkbox"/> 50.73(a)(2)(ii)(A) | <input type="checkbox"/> 50.73(a)(2)(viii)(A) |
| <input type="checkbox"/> 20.2203(a)(1) | <input type="checkbox"/> 20.2203(a)(4) | <input type="checkbox"/> 50.73(a)(2)(ii)(B) | <input type="checkbox"/> 50.73(a)(2)(viii)(B) |
| <input type="checkbox"/> 20.2203(a)(2)(i) | <input type="checkbox"/> 50.36(c)(1)(i)(A) | <input type="checkbox"/> 50.73(a)(2)(iii) | <input type="checkbox"/> 50.73(a)(2)(ix)(A) |
| <input type="checkbox"/> 20.2203(a)(2)(ii) | <input type="checkbox"/> 50.36(c)(1)(ii)(A) | <input type="checkbox"/> 50.73(a)(2)(iv)(A) | <input type="checkbox"/> 50.73(a)(2)(x) |
| <input type="checkbox"/> 20.2203(a)(2)(iii) | <input type="checkbox"/> 50.36(c)(2) | <input type="checkbox"/> 50.73(a)(2)(v)(A) | <input type="checkbox"/> 73.71(a)(4) |
| <input type="checkbox"/> 20.2203(a)(2)(iv) | <input type="checkbox"/> 50.46(a)(3)(ii) | <input type="checkbox"/> 50.73(a)(2)(v)(B) | <input type="checkbox"/> 73.71(a)(5) |
| <input type="checkbox"/> 20.2203(a)(2)(v) | <input type="checkbox"/> 50.73(a)(2)(i)(A) | <input type="checkbox"/> 50.73(a)(2)(v)(C) | <input type="checkbox"/> OTHER |
| <input type="checkbox"/> 20.2203(a)(2)(vi) | <input type="checkbox"/> 50.73(a)(2)(i)(B) | <input checked="" type="checkbox"/> 50.73(a)(2)(v)(D) | Specify in Abstract below or in NRC Form 366A |

12. LICENSEE CONTACT FOR THIS LER

| | |
|--------------------------------------|---|
| NAME Brenda M. Scherwinski | TELEPHONE NUMBER (Include Area Code) 920/755-7752 |
|--------------------------------------|---|

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO EPIX | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO EPIX |
|-------|--------|-----------|--------------|--------------------|-------|--------|-----------|--------------|--------------------|
| B | BQ | P | B580 | N | | | | | |

14. SUPPLEMENTAL REPORT EXPECTED
 YES (If yes, complete 15. EXPECTED SUBMISSION DATE) NO

15. EXPECTED SUBMISSION DATE

| MONTH | DAY | YEAR |
|-------|-----|------|
| | | |

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On February 27, 2011, at 2159 CST, during the testing of the A train safety injection (SI) system [BQ], it was discovered that the oiler for the Unit 2, B train SI pump, had rotated and the oil had drained out. The B train SI pump was declared inoperable. At the time of the event, the A train of SI was out of service for performance of a routine inservice test. Because both trains of SI were inoperable, LCO 3.0.3 was entered. Upon completion of the A train inservice test, Unit 2 exited LCO 3.0.3 at 2211 CST.

Immediate corrective actions taken included restoring the oiler to the vertical position, refilling it and performing a 5-minute pump run. The root cause of the event was determined to be a 1995 modification to the SI pump oiler which introduced a latent design/configuration flaw. Additional corrective actions will include a design change to the SI pumps and oiler assemblies for both units to reduce the possibility of accidental misalignments. The actions are being tracked to completion in the corrective action program.

An 8-hour ENS report was made in accordance with 10 CFR 50.72(b)(3)(v)(D) on February 28, 2011 at 0345 CST.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

| 1. FACILITY NAME | 2. DOCKET | 6. LER NUMBER | | | 3. PAGE |
|---------------------------|-----------|---------------|-------------------|-----------------|-------------|
| Point Beach Nuclear Plant | 05000301 | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | Page 2 of 3 |
| | | 2011 | - 001 | - 00 | |

NARRATIVE

Event Description

On February 27, 2011, at 2159 CST, with Unit 2 at 100% power, it was discovered that the oiler for the Unit 2 B train SI pump (2P-15B) [BQ], had rotated and the oil had drained out. The B train SI pump was immediately declared inoperable. At the time of the event, the A train of SI was out of service for performance of a routine inservice test. Because both trains of SI were inoperable, LCO 3.0.3 was entered. Upon completion of the A train inservice test, Unit 2 exited LCO 3.0.3 at 2211 CST.

This licensee event report is being submitted in accordance with 10 CFR 50.73(a)(2)(v)(D), an event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident. This event is classified as a safety system functional failure per NEI 99-02.

Cause of the Event

The root cause of the event was a 1995 modification to the SI pump oiler which introduced a latent design/configuration flaw. The flaw made the oilers susceptible to failure as a result of an inadvertent bumping event. There is no definitive time when the B SI pump oiler was rotated other than the time of discovery at 2159 on February 27, 2011, and there is no conclusive indication that the discrepancy existed prior to the discovery.

Analysis of the Event

The SI system is part of the emergency core cooling system (ECCS). Its primary purpose is to automatically deliver borated cooling water to the reactor core in the event of a loss of coolant accident (LOCA). The SI system will also insert negative reactivity into the core in the form of borated water during an uncontrolled plant cool down following a main steam line break or an accidental steam release.

The design basis of the ECCS is to provide two independent trains of ECCS for accident mitigation. During the 12-minute period that 2P-15A was out of service for inservice testing and 2P-15B was inoperable, high head safety injection could not be automatically initiated.

Analysis of Safety Significance

Following a large-break loss of coolant accident (LOCA), the reactor coolant system (RCS) would be depressurized and voided of coolant rapidly and a high flow rate is required to quickly recover the exposed fuel rods and limit possible core damage. To achieve this objective, one residual heat removal (RHR) pump (high flow, low head) was available to deliver borated water to the core during the period both SI pumps were out of service.

During the time both trains of SI were inoperable, the delta core damage frequency (CDF) and delta large early release frequency (LERF) were below the annual cumulative probabilities. Therefore, the safety significance of the event is low.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

| 1. FACILITY NAME | 2. DOCKET | 6. LER NUMBER | | | 3. PAGE |
|---------------------------|-----------|---------------|-------------------|-----------------|-------------|
| Point Beach Nuclear Plant | 05000301 | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | Page 3 of 3 |
| | | 2011 | - 001 | - 00 | |

NARRATIVE

Corrective Actions

The immediate corrective action included restoration of the oiler to the vertical position, refilling the oiler with oil, performing 5-minute pump run.

In addition to the above, the SI pump oiler assemblies for both units will be redesigned to reduce the possibility of an accidental misalignment. This action is being tracked to completion in the corrective action program (CAP).

Similar Events

None

Failed Components

None