



T. PRESTON GILLESPIE, JR.  
Vice President  
Oconee Nuclear Station

Duke Energy  
ONO1VP / 7800 Rochester Hwy.  
Seneca, SC 29672

864-873-4478  
864-873-4208 fax  
T.Gillespie@duke-energy.com

April 22, 2011

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Oconee Nuclear Station  
Docket Nos. 50-269, -270, -287  
Licensee Event Report 269/2011-03, Revision 0  
Problem Investigation Process No.: O-10-03882

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a)(1) and (d), please find attached Licensee Event Report (LER) 269/2011-03, Revision 0, regarding the inoperability of the Standby Shutdown Facility (SSF) due to a design oversight resulted in a condition which exceeded the 7-days allowed by Technical Specification (TS) 3.10.1 (D). Consequently, this report is being submitted in accordance with 10 CFR 50.73(a)(2)(i)(b), as an operation prohibited by the station's TSS. This event is considered to have no consequence with respect to the health and safety of the public.

Other than the commitment to submit a LER supplement, there are no regulatory commitments contained in this report. Duke Energy Carolinas, LLC, expects to provide the supplement within 60 days, but does not consider that time frame to be a commitment.

Any questions regarding the content of this report should be directed to Stephen C. Newman, Regulatory Compliance Group, Oconee Nuclear Station, at (864) 873-4388.

Sincerely,

T. Preston Gillespie, Jr.  
Vice President  
Oconee Nuclear Station

Attachment

Document control Desk  
April 22, 2011  
Page 2

cc: Mr. Victor McCree  
Administrator, Region II  
U.S. Nuclear Regulatory Commission  
Marquis One Tower  
245 Peachtree Center Ave., NE, Suite 1200  
Atlanta, GA 30303-1257

Mr. John Stang  
Project Manager  
U.S. Nuclear Regulatory Commission  
Office of Nuclear Reactor Regulation  
Washington, D.C. 20555

Mr. Andrew Sabisch  
NRC Senior Resident Inspector  
Oconee Nuclear Station

INPO (Word File via E-mail)

# LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

APPROVED BY OMB: NO. 3150-0104 EXPIRES: 10/31/2013  
Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME Oconee Nuclear Station, Unit 1	2. DOCKET NUMBER 05000-0269	3. PAGE 1 of 1
--	--------------------------------	-------------------

4. TITLE  
Inoperability of the Standby Shutdown Facility, due to a design oversight, for a period that exceeded that allowed by the Technical Specifications

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
02	24	2011	2011	03	00	04	22	2011	Unit 2	05000-0270
									Unit 3	05000-0287

9. OPERATING MODE Unit 1 - 1 Unit 2 - 1 Unit 3 - 1	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)											
	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
10. POWER LEVEL Unit 1 - 100% Unit 2 - 100% Unit 3 - 100%	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

12. LICENSEE CONTACT FOR THIS LER

NAME S. C. Newman, ONS Regulatory Compliance Group	TELEPHONE NUMBER (Include Area Code) (864) 873-4388
---	--

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED <input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE) <input type="checkbox"/> NO	15. EXPECTED SUBMISSION DATE MONTH: 06 DAY: 30 YEAR: 2011
---	--

16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On May 13, 2010, at approximately 2245 hours, an unanticipated Standby Shutdown Facility (SSF) differential lockout relay (86D) actuation occurred while performing an emergency power switching logic function test. The 86D lockout relay is actuated by various safety and non-safety trip signals. The non-safety trip signals are disabled during emergency operation of the SSF diesel generator (D/G). One of the 86D non-safety input signals is for high bearing temperature. The safety function of the SSF is to mitigate certain design basis events for 1, 2, or all 3 units.

The preliminary root cause was attributed to a design oversight involving the Fall 2008 replacement of two (2) chart recorders whose output contacts provided the high bearing temperature trip signal to the SSF D/G. The design change package failed to consider the recorder's 25-60 second boot-up delay. During the test, the chart recorders were load shed and repowered (as expected) but, due to the boot-up delay, had defaulted to a tripped state that led to the lockout relay actuation. Once the lockout relay is actuated, the lockout relay must be manually reset in order for the SSF diesel to start in any mode.

Since the period of SSF inoperability exceeded the 7-days allowed by Technical Specification (TS) 3.10.1 (D), the event is reportable as a condition prohibited by the TSs. The high bearing temperature trip function of the chart recorder has been eliminated. Additional corrective actions are pending following the completion of an ongoing root cause evaluation. The root cause(s) and applicable corrective actions from this evaluation will be submitted in a supplement to this report. This event is considered to have no consequence with respect to the health and safety of the public.