

NRC FORM 591M PART 1 (06-2010) 10 CFR 2.201		U.S. NUCLEAR REGULATORY COMMISSION	
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
1. LICENSEE/LOCATION INSPECTED: Medical Clinic of Northville 308 S. Main St. Northville, Michigan REPORT NUMBER(S): 11-01		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission, Region III 2443 Warrenville Road, Suite 210 Lisle, Illinois 60532	
3. DOCKET NUMBER(S) 030-35012	4. LICENSEE NUMBER(S) 21-32174-01	5. DATE(S) OF INSPECTION April 13, 2011	
<p>LICENSEE:</p> <p>The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:</p> <p><input type="checkbox"/> 1. Based on the inspection findings, no violations were identified.</p> <p><input type="checkbox"/> 2. Previous violation(s) closed.</p> <p><input type="checkbox"/> 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1800, to exercise discretion, were satisfied.</p> <p>_____ Non-cited violation(s) were discussed involving the following requirement(s):</p> <p><input checked="" type="checkbox"/> 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.</p> <p>One Severity Level IV violation was identified, and is described in Part 2, below.</p>			
Statement of Corrective Actions			
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.			
Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	WENDY KAY BOUFFORD	<i>Wendy Kay Boufford</i>	4-26-2011
NRC INSPECTOR	Andrew M. Bramnik	<i>Andrew M. Bramnik</i>	4/21/2011
Branch Chief	Tamara E. Bloomer	<i>TE Bloomer</i>	4/25/11

NRC FORM 591M PART 2
(08-2010)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Medical Clinic of Northville

2. NRC/REGIONAL OFFICE
U.S. Nuclear Regulatory Commission, Region III
2443 Warrenville Road, Suite 210
Lisle, Illinois 60532

REPORT NUMBER(S) 11-01

3. DOCKET NUMBER(S)
030-35012

4. LICENSEE NUMBER(S)
21-32174-01

5. DATE(S) OF INSPECTION
April 13, 2011

(Continued)

Condition 1B of NRC License No. 21-32174-01 requires, in part, that the licensee shall conduct its program in accordance with the statements, representations, and procedures contained in the Application dated May 11, 2009. The application dated May 11, 2009, references the Application dated April 3, 1999.

Item 10.4 "Model Rules for Safe Use of Radiopharmaceuticals" of the Application dated April 3, 1999, states, in part, "Do not store food, drink, or personal effects in areas where radioactive material is stored or used."

Contrary to the above, between January 1 and April 13, 2011, the licensee stored drinks in an area where radioactive material was stored or used. Specifically, the licensee stored a drinking water cooler for office staff use in the injection room where radioactive materials were administered to patients.

This violation is being cited because it was identified by the NRC.

The root cause of this violation was an oversight of the requirement to prohibit drinks from areas where radioactive material is stored or used. As corrective actions, the licensee committed to remove the drinking water cooler from the injection room by April 30, 2011.

This is a Severity Level IV Violation (Section 6.3.d.3)

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE Medical Clinic of Northville REPORT NUMBER(S) 11-01	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission, Region III 2443 Warrenville Road, Suite 210 Lisle, Illinois 60532
---	---

3. DOCKET NUMBER(S) 030-35012	4. LICENSEE NUMBER(S) 21-32174-01	5. DATE(S) OF INSPECTION April 13, 2011
----------------------------------	--------------------------------------	--

6. INSPECTION PROCEDURES 87130	7. INSPECTION FOCUS AREAS 03.01 – 03.07
-----------------------------------	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM 2201	2. PRIORITY 5	3. LICENSEE CONTACT Wendy Boufford, NMT Won Chae, M.D., RSO	4. TELEPHONE NUMBER 248-348-3645 248-349-1900
--------------------	------------------	---	---

Main Office Inspection
 Field Office Inspection
 Temporary Job Site Inspection

Next Inspection Date: April 2016

PROGRAM SCOPE

This was a routine inspection of a private clinic that performed approximately 5-7 diagnostic nuclear medicine procedures per day. One part time nuclear medicine technologist performed all patient procedures on Tuesdays and Wednesdays only. The licensee obtained licensed material as unit doses from an area nuclear pharmacy, and did not use xenon-133, bulk doses, or molybdenum/technetium generators. The licensee performed primarily cardiac, thyroid, and bone scans, and was not authorized to perform or administer therapeutic doses.

PERFORMANCE OBSERVATIONS

The inspector observed one resting dose of technicium-99m being administered during the inspection. This observation, combined with interviews of available staff, revealed an adequate level of understanding of emergency and material handling procedures and techniques. Dose calibrator constancy checks, package receipt, daily surveys, and waste handling and disposal procedures were successfully demonstrated. An outside consultant performed quarterly program audits that were adequate to oversee the program.

Licensed material was adequately secured and not readily accessible to members of the general public. The licensee possessed a radiation survey meter that was calibrated, operational, and performed well in side-by-side comparison with an NRC instrument.

Independent measurements did not indicate readings in excess of Title 10 of the Code of Federal Regulations (10 CFR) Part 20 limits in restricted or unrestricted areas. Personal whole body and extremity dosimetry were observed worn by the staff during the inspection, and records did not indicate doses in excess of 10 CFR Part 20 limits. Dosimetry records indicated that the highest annual whole body and extremity readings for the past four years were 188 millirem (mrem) and 475 mrem, respectively.

One Severity Level IV violation was identified for storing drinks in an area where radioactive materials were stored or used, and is described in Part 2, above.