## REGULATORY I DRMATION DISTRIBUTION SYST (RIDS)

DITED NO DOCKET

ACCESSION NBR:8012170588 DOC.DATE: 80/12/14 NOTARIZED: NO DOCKET # FACIL:50-305 Kewaunee Nuclear Power Plant, Wisconsin Public Servic 05000305

AUTHOR AFFILIATION

NALEPKA, D.S. Wisconsin Public Service Corp.

RECIPIENT AFFILIATION

Region 3, Chicago, Office of the Director

SUBJECT: LER 80-019/03X-3:on 800326, check damper SBV-10A failed to open causing sys inability to create vacuum in annulus. Caused by controller setpoint drift, faulty component &

transistor.Parts repaired.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR \_\_ ENCL \_\_ SIZE:\_\_\_\_\_TITLE: Incident Reports

NOTES:18E:3 copies all material.

05000305

ACTION:	RECIPIENT ID CODE/NAME VARGA,S. 0		COPIE LTTR 3		RECIPIENT ID CODE/NAME	COPIE LTTR E	
INTERNAL:	A/D COMP&STRUO	6	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QUO	8	1	1	A/D OP REACTOO9	1	1
	A/D PLANT SYS1	0	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE1	2	1	1	A/D TECHNOLOG13	1	1
	ACC EVAL BR 1	4	1	1	AEOD	2	2
	ASLBP/J.HARD		1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 1	6	1	1	CONT SYS BR 17	1	1
	CORE PERF BR 1	8	1	1	D/DIR, HUM FAC19	1	1
	DIR, DIV OF LIC		1	1	DIR, ENGINEERI20	1	1
	DIR, HUM FAC S2		1	1	DIR, SYS INTEG22	1	1
	EFF TR SYS BR2		1	1	EQUIP QUAL BR25	1	1
	GEOSCIENCES 2	26	1	1	I&C SYS BR 29	1	1
	I&E 0	5.	2	2	JORDAN, E./IE	1	1
	LIC GUID BR 3	0	1	1	LIC QUAL BR 31	1	1
	MATL ENG BR 3	2	1	1	MECH ENG BR . 33	1	1
	MPA		3	3	NRC PDR 02	1	1
	OP EX EVAL BR3	4	3	3 3	OR ASSESS BR 35	1	1
	POWER SYS BR 3	6	1	1	RAD ASSESS BR39	1	1
	REACT SYS BR 4	0	1	1	REG FILE 01	1	1
	REL & RISK A 4	1	1	1	SFTY PROG EVA42	1	1
•	STRUCT ENG BR4	14	1	1	SYS INTERAC 845	1	1
EXTERNAL:	ACRS 4	16	16	16	LPDR 03	1	1
		5	1	1	TERA: DOUG MAY	1	1

LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE REQUIRED INFORMATION) 2 0 0 -0 0 0 0 0 0 - 0 0 3 4 CON'T 0 1 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) While performing surveillance testing on the Shield Building Ventilation System (SBV) 0 2 check damper SBV-10A failed to fully open resulting in the inability of the system 0 3 to draw a measurable vacuum in the annulus. This placed the system under TS 3.6.b.1 0 4 Since the redundant train. Train "B" SBV was tested operable within TS time limits. 0 5 of SBV is capable of providing the required vacuum there was no effect on plant 0 6 operation or public safety. 0 7 0 8 COMP. VALVE SUBCODE CAUSE CAUSE COMPONENT CODE SUBCODE CODE CODE E | (13) 18 REVISION OCCURRENCE SEQUENTIAL LER/RO EVENT YEAR CODE NO. REPORT NO. 3 0 1 9 REPORT NUMBER NPRD-4 FORM SUB. COMPONENT ATTACHMENT SUBMITTED SHUTDOWN METHOD HOURS (22) MANUFACTURER SUPPLIER 00000 N (23) Z (21) E(18) G(19) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) SBV-10A controller setpoint had drifted low thus causing SBV-10A damper to throttl 1 0 in mid-cycle. It was subsequently found following a similar event on 7/13/80 that 777 one controller (SBV 20-A) required total component replacement and the other (SBV 10-A) 1 2 Following repairs the system operated satisfactorily. contained a faulty transistor. 1 3 It is believed that these controller repairs will prevent future occurences. 1 4 OTHER STATUS (30) FACILITY STATUS DISCOVERY DESCRIPTION % POWER Surveillance Testing B(31)NA LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) RELEASED\_OF RELEASE NA NA ] (33) [z](34)| 10 11
PERSONNEL EXPOSURES DESCRIPTION (39) PERSONNEL INJURIES DESCRIPTION (41) NA LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION NRC USE ONLY PUBLICITY DESCRIPTION (45) NA 8012170588 NAME OF PREPARER. PHONE: (414) 388-2560 David S. Nalepka