REGULACRY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:	8801280147 DOC. DATE: 88/01/28 NOTARIZED: NO	DOCKET #
AUTH NAME	AUTHOR AFFILIATION	05000305
BERGMANN, J. W.	Wisconsin Public Service Corp.	
HINTZ, D. C.	Wisconsin Public Service Corp.	
RECIP. NAME	RECIPIENT AFFILIATION	

SUBJECT: LER 87-011-00: on 871208, util advised of potential failure of. ModeI 62H controller internal relays. Caused by overvoltage condition. Periodic surveillance testing provided & final corrective actions being investigated. W/880122 ltr.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR] ENCL 1 SIZE: 5 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT	COPIES		RECIPIENT	COP	IES
	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL
	PD3-3 LA	1	1	PD3-3 PD	1	1
	QUAY, T	1	1			
INTERNAL:	ACRS MICHELSON	1	1	ACRS MOELLER	2	2
	AEOD/DOA	1	1	AEOD/DSP/NAS	1	1
	AEOD/DSP/ROAB	2	2	AEOD/DSP/TPAB	1	1
	ARM/DCTS/DAB	1	1	DEDRO	1	1
	NRR/DEST/ADS	1	0	NRR/DEST/CEB	1	1
	NRR/DEST/ELB	1	1	NRR/DEST/ICSB	1	1
	NRR/DEST/MEB	1	1	NRR/DEST/MTB	1	1
	NRR/DEST/PSB	1 1	1	NRR/DEST/RSB	1	1
	NRR/DEST/SGB	1	1	NRR/DLPQ/HFB	1	1
	NRR/DLPQ/QAB	1	1	NRR/DOEA/EAB	1	1
	NRR/DREP/RAB	1	1	NRR/DREP/RPB	2	2
	-NRR_(DRIS(SIB	1	1	NRR/PMAS/ILRB	1	1
	REGETLE 02	1	1	RES TELFORD, J	1	1
	RES/DE/EIB	1	1	RES/DRPS DIR	1	1
	RGN3 FILE 01	1	1			
EXTERNAL:	EG&G GROH, M	5	5	FORD BLDG HOY, A	1	1
	H ST LOBBY WARD	1 -	1	LPDR	1	1
	NRC PDR	1	1	NSIC HARRIS, J	1	1
	NSIC MAYS, G	1	1			

TOTAL NUMBER OF COPIES REQUIRED: LTTR 46 ENCL 45

· · · · ·							_	_										
NRC Feri	C Ferm 386 U.S. NUCLEAR REDULATORY COMMISSION UI APPROVED ONE NO 3150-0104								11000010000 Q4									
	LICENSEE EVENT REPORT (LER)																	
FACILITY	PACILITY NAME (1) DOCKET NUMBER (2) PAGE (3																	
TITLE (4	Kewaunee Nuclear Power Plant [0]51010131015110F014										1014							
	Potential Failure of Model 62H Controller Internal Kelays Due to Overvoltage Condition as Described By Foxboro in a 10CFR21 Report																	
EVI	EVENT DATE (6) LER NUMBER (6) REPORT DATE (7) OTHER FACILITIES INVOLVED (8)																	
MONTH	DAY	YEAR	YEAR	-	SEGUENTIAL NUMBER	NUM	BION	MONTH	DAY	YEAR	N1.A	FACILI	TY NAME	ES DOCKET NUMBER(SI				
1 2	1 2 2 1 8 7 8 7 0 1 1 0 0 0 1 2 2 8 8 0 0 1 5 0 0 0 0 1 2 2																	
00	OPERATINO THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR & (Check are or more of the following) (11)																	
		<u>N</u>		0.402 (h)			20.406	(e)			80,73(a)(3	[]{ w]		-1	73,71(b)		
LEVE (10)	נן ז	0+0	H	10.402 (a	1){1){U			90.36(c	a)(2)			90.736H3	t) (vii)	ł	\mathbf{x}	OTHER /S	Specify in Ab	atract
				10. 405 (s);[]}(W)			90.7 3 4	122102			90.7364	}{ viii }{A}	ŗ		below and 30EA/	in Toxt, NR	C Form
			•	10.40 5 (a	s){1){///			90.73ta	H(2)(H)			\$0.72(4)(2	(){ viii)(0)			10CF	R21	
<u> 1997 - 19</u>				0.405 (a))(1)(v)			90.73ia ICENSEE	EONTACT	FOR THI	LER (12)	90.73(a)(2	()(=)	i				
NAME														1	ELEPH	ONE NU	MBER	
	Jeft	frey	W. B	lerg	mann -	Assoc	ia	te Ei	ngine	er				AREA CODE	÷			
							608	EACH C	Control E M		DESCRIP		REPORT	<u> 4 1 4 </u>	318	18 1-	- 12 15	16 10
					ANUFAC.	REPORTA								MANUFAC	hear			
CAUSE	SYSTEM	COMP	ONENT		TURER	TO NPR	OS			CAUBE	EVSTEM	COMPON	IENT	TURER	TO	NPRDE		
											╉╌┺╌	+ $+$ $+$ $+$ $+$ $+$ $+$ $+$ $+$ $+$			+			
	1		1 1										1	1 1 1				
					SUPPLEME	NTAL REI	PORT	EXPECT	ED (14)					EXFECTE		MONT	TH DAY	YEAR
VIVE	5 //f yes, c	ompiete E	XPECTE	D SUBI	MISSION OATE	7		⊢						DATE (15) }		1 2 10	818
ABETRA	CT (Limit	to 1400 µ	wcw, i.e.,	, 60010	rimetely fifteen	single spec	e type	neritten hi	nee/ (18)							101	<u>+12 </u> 5	
0	n Dec	ember	r 8,	198	37, while	le th	e p	plant	was	opera	ting	at 100)% po	wer, Wis	con	SIN H	Jublic	ha
	rvic	e com ure 1	rpor Fail	dill Ureg	s of cer	rtain	s a re	auvis	in F	oxbor	o 62H	l contr	olle	ers. The	se	same	relay	S
W	ere i	nsta.	lled	at	KNPP as	s par	ti	of an	over	all c	ontro	oller r	refur	bishment	pr	ojeci	t for	
bo	oth t	he r	eact	or i	protect	ion (RP:	5) an	d pla	nt pr	ocess	s contr	rol s	ystems.	In	clude	ed in	the
S	cope	of r	efurl	bisl	hment 19	s the	CI ini	nange sto f	out c	n a r	ion-ne	ermetic	cally	/ sealed	nei	ay to	o a ne	r-
110	erica	i i y	sean	eui		6110	1 1 1 1	ule i	arra		luscu	0, 00,	i cuc c		••••			
Т	he in	vest	igat	ion	into tl	he ca	use	e of	the r	elay	failu	ires is	s not	complet	e;	howe	ver, i	ni-
t	ial i	nves	tiga	tio	ns stro	ngly	sug	ggest	: that	the	relay	/s fail	led o	lue to an	00	ervo	ltage	con-
d	ition	. P	rese	ntl	y, the	volta lavc	ige je	acro)SS D(hor th	oth th	le ori	iginali rated v	iy ir volta	istalled How	and	r tl	recen he ori	oi-
l n	al re	lavs	do	not	appear	as s	us:	cepti	ible t	o pre	ematur	re fail	lures	5.		., .		
		. uj e									-	-						
A	lthou	igh t	he r	epl	acement	rela	ys	are	susce	ptib	le to	premat	ture	failure,	th	ey al	re	
operable and capable of performing their safety related function. Periodic sur-																		
letter which identifies the systems which use the 62H controller and provides con-																		
ť	inger	it in	stru	icti	ons has	been	í m	ade r	requi	red re	eading	g for a	all d	operators	•			
First connective actions and still being investigated. However a colution to																		
resolve the RPS circuitry concerns, as a minimum, is expected to be implemented																		
during the next refueling outage in March of 1988.																		
[]		,				5	. 9							<u>.</u> .			••••	
T	This report is submitted to supplement the IOCFR 21 report which Foxboro provided to																	
t	he N	RC or	n Dec	cemb	per 21,	1987	•	8	8012	8014	7 88	0128	=			ובא	7 1	
NRC Fee (9-83)	m 320							P	DR	ADOC	K 05	PDR	7					

.

NRC Form 386A (9-83)	Farm 386A LICENSEE EVENT REPORT (LER) TEXT CONTINUATION APPROVED ONE NO. 3180-0104 EXPIREE: 8/21/86								
FACILITY NAME (1)		DOCKET NUMBER (2)	LER NUMB	ER (6)	FAGE (3)				
			YEAR SEOUEN	TIAL SE REVISION					
Kewaunee Nu	uclear Power Plant	0 5 0 0 0 3 0 5	8 7 - 0 1	11 - 010	0 12 0 = 0 1				
TEXT (II man shere is standard	une additional MRC Form SIEA's/ (17)								

Description of Event

On December 8, 1987, while the plant was operating at 100% power, Wisconsin Public Service Corporation (WPSC) was advised by another utility of a concern regarding the premature failures of certain relays [RLY] (Foxboro Part B8002DN, relay numbers K1 and K2) in Foxboro 62H controllers [STC]. The apparent failure mechanism is an opening of the coil due to overvoltage. An investigation was immediately initiated to determine if similar failures had occurred at the Kewaunee Nuclear Power Plant (KNPP).

In 1987, WPSC began a refurbishment project to recondition the original plant Foxboro controllers. The refurbishment project will eventually include eight (8) 62H controllers in the reactor protection system (RPS) [JC] and twenty-seven (27) 62H controllers in the plant's process control systems. However not all of these controllers have been refurbished. As recommended by Foxboro, the scope of refurbishment included the changeout of a non-hermetically sealed relay (Foxboro part NO196ZN) to a hermetically sealed unit (Foxboro part B8002DN) to eliminate failures caused by contact corrosion. The electrical characteristics of the two relays are identical. Approximately 65% of the Kewaunee Nuclear Power Plant (KNPP) controllers were refurbished in 1987 and the balance are scheduled to be refurbished in 1988. The KNPP has experienced a relay failure in a control system since the controller refurbishment and it is highly suspected that the relay failure mechanism was the same as that occurring at the aforementioned plant.

WPSC and Foxboro have been performing investigations and on December 21, 1987, Foxboro filed a 10 CFR 21 report with the NRC regarding the potential for relay failures in the 62H Controller. This report is being submitted to supplement Foxboro's 10 CFR 21 Report.

Cause of Event

During the 1987 operating cycle, KNPP and the aforementioned plant have experienced failures of the Foxboro Part B8002DN relay. Although the cause of the failures has not been conclusively identified, it is highly suspected that the failures are a result of an overvoltage condition. Presently the voltage across the relay coils exceeds the nominal rating of of 48 volts + 10%. Since the electrical characteristics of the B002DN and the N0196ZN relays are identical, both relay types experience the overvoltage condition. However, the N0196ZN relays do not appear as susceptible to premature failures.

	PORT (LER) TEXT CONTIN	U.S. NUCLEAR R NUATION APPROVED EXFIRES	EDULATORY COMMERCIA CMB NO. 3190-0104 /31/86
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (S)	FAGE (3)
		VEAR SEQUENTIAL NUMBER	
Kewaunee Nuclear Power Plant	0 5 0 0 0 <u> </u> 3 0	5 8 7 - 0 11 11 - 0 p	0 13 0= 0 14

Analysis of Event

The 62H Controllers have either a K1 relay or K1 and K2 relays in their circuitry. The K1 relay controls the auto/manual mode of the controller. The K2 relay controls the source of the controlling input when the controller is in the automatic mode.

KNPP had a failure of a B8002DN (K2) relay in the main feedwater control system [JB] on October 13, 1987. Based on information received from another utility of a concern regarding premature relay failure, WPSC reevaluated the October K2 relay failure. WPSC suspects that the K2 relay failure mechanism was the same as that experienced by the other utility since the K2 relay coil had burnt open at both plants.

A review performed to identify all uses of the 62H Controllers at KNPP concluded that the controllers are used in the plant process control systems and the reactor protection system. The effects of the relay failure (i.e., coil burnout) have been evaluated for each system. It has been determined that the failure of a controller in the plant process control system will not adversely affect plant safety.

There are eight (8) 62H controllers which perform a safety related function in the Reactor Protection System (RPS). Four of these controllers have been refurbished and utilize the B8002DN relay and the other four utilize the N0196ZN relay. The 62H controllers perform a safety related function in the RPS by adding a Delta Flux penalty to the overtemperature and overpower delta temperature (OTAT & OPAT) trip setpoints when Delta Flux is outside of the specified band of +9% to -12%. A relay failure in the 62H controller in the RPS circuitry could cause the flux penalty adjustment to be non-existent, resulting in non-conservative OTAT and OPAT reactor trip setpoints. The KNPP is normally operated within a delta flux target band which is more limiting than the +9% to -12% band. Operations personnel periodically monitor the delta flux indication and log the delta flux hourly. Additionally, the plant process computer monitors delta flux and alarms when the target band is exceeded. Therefore, indications of possible target band exceedance are available which provide early indications of an approach to the +9% to -12% limit.

It must be noted that these relays are operable and remain capable of performing their intended function; however, they may be susceptible to heat induced deterioration resulting in a shortened life expectancy. Monthly surveillance testing of the RPS circuitry provides continued assurance of relay operability.

IPRO Form 200A	T (LER) TEXT CONTINU	U.S. NUCLEAR REG APPROVED O EXPIRES 8/3	ULATOR & COMMERICA ME NO: 3180-0104 1/85
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (S)	PAGE (3)
Kewaunee Nuclear Power Plant	0 6 0 0 0 3 0 5	817 - 01111 - 010	0 4 0 - 0 4

TEXT // more space is required, use additional NRC Form 3884's/ (17)

Corrective Actions

The effect of the failure in the currently installed 62H Controllers has been reviewed and a letter which is required reading for all operators has been placed in the Control Room. The letter identifies the systems which utilize 62H Controllers and emphasizes that KNPP utilizes these controllers in Reactor Protection System circuitry for the OPAT and OTAT trip setpoints. Operations personnel are instructed to notify Instrument and Control (I&C) personnel immediately if the Delta Flux is out of the target band. I&C personnel will then ensure that the controllers are operable.

The monthly operability surveillance along with the added requirement to notify I&C upon exiting the target band will, for the short term, provide added assurance of relay operability in these protection circuits.

WPSC is working with Foxboro to develop a permanent hardware solution to the relay problem. A solution to resolve the RPS circuitry concerns, as a minimum, is anticipated to be implemented during the next refueling outage scheduled for March 1988.

A supplemental report will be provided at a later date as final corrective actions are implemented.

Additional Information

Similar Events: None

Equipment Failure: None

Related Information: Letter from M. J. Berberian (Foxboro) to Joseph Petrosino (NRC) dated December 21, 1987.

WPSC (414) 433-1598 TELECOPIER (414) 433-1297



NRC-88-7

EASYLINK 62891993

WISCONSIN PUBLIC SERVICE CORPORATION

800 North Adams • P.O. Box 19002 • Green Bay, WI 54307-9002

January 22, 1988

10 CFR 50.73

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Gentlemen:

Docket 50-305 Operating License DPR-43 Kewaunee Nuclear Power Plant Reportable Occurrence 87-011-00

Reference 1: Letter from M. J. Berberian (Foxboro) to Joseph Petrosino (NRC) dated December 21, 1987

This report is being supplied to respond to concerns raised by the December 21, 1987, 10 CFR 21 report issued by Foxboro (reference 1).

Very truly yours,

D. C. Hintz Vice President - Nuclear Power

TJW/jms

Attach.

cc - INPO Records Center Suite 1500, 1100 Circle 75 Parkway Atlanta, GA 30339 Mr. Robert Nelson, NRC Resident Inspector RR #1, Box 999, Kewaunee, WI 54216 US NRC, Region III 799 Roosevelt Road Glen Ellyn, IL 60137