

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8904050111 DOC.DATE: 89/03/29 NOTARIZED: NO DOCKET #  
 FACIL:50-305 Kewaunee Nuclear Power Plant, Wisconsin Public Service 05000305  
 AUTH.NAME AUTHOR AFFILIATION  
 NALEPKA,D.S. Wisconsin Public Service Corp.  
 STEINHARDT,C.R. Wisconsin Public Service Corp.  
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 89-004-00:on 890227,inadequate testing of containment  
 isolation valves due to leak testing method.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 7 w/8 ltr.  
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD3-3 LA GIITTER,J	1 1 1 1	PD3-3 PD	1 1
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	IRM/DCTS/DAB	1 1
	NRR/DEST/ADE 8H	1 1	NRR/DEST/ADS 7E	1 0
	NRR/DEST/CEB 8H	1 1	NRR/DEST/ESB 8D	1 1
	NRR/DEST/ICSB 7	1 1	NRR/DEST/MEB 9H	1 1
	NRR/DEST/MTB 9H	1 1	NRR/DEST/PSB 8D	1 1
	NRR/DEST/RSB 8E	1 1	NRR/DEST/SGB 8D	1 1
	NRR/DLPQ/HFB 10	1 1	NRR/DLPQ/QAB 10	1 1
	NRR/DOEA/EAB 11	1 1	NRR/DREP/RPB 10	2 2
	<del>NRR/DRIS/SIB</del> 9A	1 1	NUDOCS-ABSTRACT	1 1
	REG FILE 02	1 1	RES/DSIR/EIB	1 1
	RES/DSR/PRAB	1 1	RGN3 FILE 01	1 1
EXTERNAL:	EG&G WILLIAMS,S	4 4	FORD BLDG HOY,A	1 1
	H ST LOBBY WARD	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC MAYS,G	1 1
	NSIC MURPHY,G.A	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 44 ENCL 43

*A10 4*  
*ca*

R  
I  
D  
S  
/  
A  
D  
S  
/  
A  
D  
D  
S

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) **Kewaunee Nuclear Power Plant** DOCKET NUMBER (2) **05000305** PAGE (3) **1 OF 016**

TITLE (4) **Leak Testing Method Not In Accordance With 10 CFR 50 Appendix J Results In Inadequate Testing Of Containment Isolation Valves**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
02	27	89	89	004	00	03	29	89			050000
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)											

OPERATING MODE (9)	N	20.482(a)	20.484(a)	60.73(a)(2)(iv)	72.71(b)
POWER LEVEL (10)	0.010	60.485(a)(1)(ii)	60.30(a)(1)	60.73(a)(2)(v)	72.71(a)
		20.485(a)(1)(iii)	60.30(a)(2)	60.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 308A)
		20.485(a)(1)(iv)	X 60.73(a)(2)(i)	60.73(a)(2)(vii)(A)	
		20.485(a)(1)(v)	60.73(a)(2)(ii)	60.73(a)(2)(vii)(B)	
		20.485(a)(1)(vi)	60.73(a)(2)(iii)	60.73(a)(2)(i)	

LICENSEE CONTACT FOR THIS LER (12)

NAME: **David S. Nalepka - Plant Licensing Supervisor** TELEPHONE NUMBER: **414 388-1256**

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15) **NA** MONTH: **NA** DAY: **NA** YEAR: **NA**

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On February 27, 1989, with the plant in a refueling shutdown, a concern regarding the leak test methods of a containment penetration providing nitrogen gas to the safety injection accumulators was identified. The penetration isolation boundary includes three containment isolation valves (NG-110, NG-108A and NG-108B) located inside the containment and one valve (NG-107) located outside the containment.

Valves NG-108A and NG-108B are not tested and pressurized in the same direction as that when the valves are required to perform their safety function. Due to the orientation of valves NG-108A and NG-108B, the test method is non-conservative and is in conflict with 10 CFR 50, Appendix J. Valve NG-107 is normally closed and successfully passed its leakage test and was capable of isolating the penetration as necessary.

The short term solution will include developing and implementing a test method during the current refueling outage which will enable testing of valves NG-108A and NG-108B in accordance with 10 CFR 50 Appendix J utilizing existing system configurations. In addition a design change will be initiated to modify the nitrogen supply line to the accumulators. This will enable future testing with methods consistent with those currently used on other penetrations.

8904050111 890329  
PWR ADOCK 05000305  
S PDC

IE22

FACILITY NAME (1)  Kewaunee Nuclear Power Plant	DOCKET NUMBER (2)  05000305	LER NUMBER (8)			PAGE (3)		
		YEAR 89	SEQUENTIAL NUMBER -004	REVISION NUMBER -00			
					02	OF	06

TEXT (If more space is required, use additional NRC Form 388A's) (17)

Description of Event

On February 27, 1989 with the plant in a refueling shutdown, a concern regarding the leak test methods of a containment penetration was identified. As a result of a previously conducted Technical Review of the Kewaunee Plant's Local Leak Rate Testing (LLRT) program, by Wisconsin Public Service personnel, it was determined that a physical inspection of several containment penetrations should be performed. The intent of the inspection was to ensure that the current leak test methods meet the requirements of 10 CFR 50 Appendix J.

Specifically the inspections were to be performed on those valves where the penetration test method does not pressurize the valve in the same direction as that when the valve is required to perform its safety function. Upon inspecting the orientation of two valves (NG-108A and NG-108B) on February 27, 1989 it was determined that the test method used on these valves appears to be in conflict with 10 CFR 50 Appendix J.

Penetration #31 is a containment penetration that provides nitrogen cover gas to the safety injection accumulators [ACC] in containment. The outside containment valve [ISV] NG-107 and the inside containment valves NG-108A, NG-108B, and NG-110 provide the isolation boundaries for this penetration (see Figure 1).

The current testing method utilized in procedure SP 56A-09D, "Containment Local Leak Rate Type B and C Test", requires pressurizing between the containment isolation valves and monitoring for leakage. NG-107 is pressurized in the same direction as that when the valve is required to perform its safety function (containment isolation) therefore it is acceptable. Valves NG-110, NG-108A, and NG-108B are not tested and pressurized in the same direction as that when the valves are required to perform their safety function (see Figure 1).

The testing of a containment isolation valve in a direction different than required to perform its safety function is acceptable if it can be proven to be an equivalent or more conservative test.

Cause of Event

The root cause of the problem was the failure to adequately evaluate the orientation of valves NG-108A and NG-108B when developing the test procedure and associated Technical Specifications. The current Type C test method applies pressure from above and across the plug on these globe valves (see Figure 2). If these valves were required to perform a containment isolation function the containment pressure would be applied to the bottom of the plug. The current test method provides pressure above the plug which assists the valve in closing and thus limits leakage. This is a non-conservative test and therefore does not comply with 10 CFR 50 Appendix J test requirements.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Kewaunee Nuclear Power Plant	DOCKET NUMBER (2)  0 5 0 0 0 3 0 5	LER NUMBER (8)			PAGE (3)	
		YEAR 8 9	SEQUENTIAL NUMBER - 0 0 4	REVISION NUMBER - 0 0		
					0 3	OF 0 6

TEXT (If more space is required, use additional NRC Form 306A's) (17)

NG-110 is not pressurized in the same direction as that when the valve would be required to perform its safety function. However, the valve orientation is such that this test method provides equivalent or conservative results and therefore it is acceptable.

Analysis of Event

10 CFR 50, Appendix J Section II.C.1 states that, "Type C tests shall be performed by local pressurization. The pressure shall be applied in the same direction as that when the valve would be required to perform its safety function, unless it can be determined that the results from the tests for a pressure applied in a different direction will provide equivalent or more conservative results." Testing performed on valves NG-108A and NG-108B is not being performed in strict accordance with 10 CFR 50, Appendix J.

Valve NG-107 which was leak tested successfully will automatically close on a containment isolation signal. Even though NG-108A and NG-108B are not tested in the direction required by 10 CFR 50 Appendix J the test method currently used provides reasonable assurance that gross leakage through the valves does not exist.

Valves NG-107, NG-108A, NG-108B, and NG-110 are normally closed during conditions where containment integrity is required. Safety injection system pre-startup checklist (N-SI-33-CL) ensures that these valves are closed. Valves NG-107 and NG-108A(B) are opened only if the nitrogen pressure in the accumulators is outside the normal operating band. The nitrogen pressure is then either relieved or increased to restore the accumulator pressure to a nominal 750 psig. The accumulators historically experience minimal leakage and the need to add nitrogen to maintain pressure occurs infrequently. Should a transient occur requiring containment isolation when any of these valves are open for an accumulator pressure adjustment, NG-107 would automatically close on a containment isolation signal.

Based on the fact that NG-107 is normally closed and has successfully passed its leakage test, containment integrity is maintained as required even if valves NG-108A and NG-108B are assumed to have questionable leak tightness. During the infrequent and short duration periods in which these valves are opened, valve NG-107 provides the capability to automatically isolate the penetrations as necessary.

The failure to perform the leakage test in accordance with the provisions of 10 CFR 50 Appendix J is a violation of the intent of Technical Specification 4.4.b and is being reported as a condition prohibited by the plant's Technical Specifications in accordance with 10 CFR 50.73(a)(2)(1)(B).

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Kewaunee Nuclear Power Plant	DOCKET NUMBER (2)  0 5 0 0 0 3 0 5	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 9	- 0 0 4	- 0 0	0 4	OF	0 6

TEXT (If more space is required, use additional NRC Form 388A's) (17)


Corrective Actions

1. A test method will be developed in the short term which will enable testing of valves NG-108A and NG-108B in accordance with 10 CFR 50 Appendix J utilizing existing system configurations. This test method utilizing pressurized safety injection accumulators will be implemented during the 1989 outage (currently in progress), however, this method is not the preferred long term solution.
2. The long term solution will require that the nitrogen supply line to the accumulators be modified to enable leakage testing in accordance with 10 CFR 50, Appendix J using methods consistent with those currently used on other penetrations. A Design Change will be initiated to accomplish this by either:
  - a. modifying piping and installing valves necessary to enable testing of valves NG-108A and NG-108B in the same direction as that when the valve would be required to perform its safety function; or
  - b. adding a new valve, possibly a check valve, on the nitrogen gas line inside containment near the penetration. Proper Appendix J testing of the valves would then be possible utilizing the existing valves and piping. This option would enable valves NG-108A and NG-108B to be reclassified as non-containment isolation valves.

### LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Kewaunee Nuclear Power Plant	DOCKET NUMBER (2)  0 5 0 0 0 3 0 5	LSR NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 9	- 0 0 4	- 0 0	0 6	OF	0 6

TEXT (If more space is required, use additional NRC Form 388A's) (17)



From NG-107

To Accumulators

Figure 2  
Valves NG-108A(B)

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Kewaunee Nuclear Power Plant	DOCKET NUMBER (2)  0 5 0 0 0 3 0 5	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 9	- 0 0 4	- 0 1 0	0 5	OF	0 6

TEXT IF more space is required, use additional NRC Form 368A's (17)




Figure 1

Penetration #31

Nitrogen Supply to SI Accumulators



**WISCONSIN PUBLIC SERVICE CORPORATION**

600 North Adams • P.O. Box 19002 • Green Bay, WI 54307-9002

March 29, 1989

10 CFR 50.73

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Gentlemen:

Docket 50-305  
Operating License DPR-43  
Kewaunee Nuclear Power Plant  
Reportable Occurrence 89-004-00

The attached Licensee Event Report for reportable occurrence 89-004-00 is being submitted in accordance with the requirements of 10 CFR 50.73, "Licensee Event Report System."

Sincerely,

A handwritten signature in cursive script, appearing to read "C. R. Steinhardt".

C. R. Steinhardt  
Manager - Nuclear Power

SLB/jms

Attach.

cc - INPO Records Center  
Mr. Robert Nelson  
US NRC, Region III

IE22  
1/1