

50-305

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: Mr J G Keppler

FROM: Wisconsin Public Service Corp
Green Bay, Wis
E W JamesDATE OF DOCUMENT
3-2-77

DATE RECEIVED 3-7-77

☒ LETTER
☐ ORIGINAL
☒ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1 cc

DESCRIPTION

Ltr trans the following:

1p

PLANT NAME: Kewaunee

ENCLOSURE

Licensee Event Report (RO# 77-3) on 2-15-77
concerning high water level reactor trip
settings on pressurizer level transmitters
which were out of tech specs.....

2p

ACKNOWLEDGED
DO NOT REMOVENOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

3-11-77

ehf

BRANCH CHIEF:

W/3 CYS FOR ACTION

LIC. ASST.:

W/1 CYS

ACRS 16 CYS HOLDING/SENT

Schwencer

Sheppard

As CATB

INTERNAL DISTRIBUTION

REG FILE

NRC-PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

CASE

BUTLER

HANAUER

TEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LPDR: Kewaunee, Wis

TIC:

NSIC:

CONTROL NUMBER

2794

WISCONSIN PUBLIC SERVICE CORPORATION

Public Service

P.O. Box 1200, Green Bay, Wisconsin 54305

March 2, 1977

Mr. J. G. Keppler, Regional Director
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Keppler:

Subject: Docket 50-305
Operating License DPR-43
Reportable Occurrence RO 77-3

In accordance with the requirements of Technical Specifications,
Section 6.9, the attached Licensee Event Report for reportable occurrence
RO 77-3 is being submitted.


Very truly yours,

E. W. James
E. W. James
Senior Vice President
Power Supply & Engineering

EWJ:sna

Enc.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, D. C. 20555
Dir, Office of Management Info & Program Control
US NRC, Washington, D. C. 20555



2794

LICENSEE EVENT REPORT

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	W	I	K	N	P	1	0	0	-	0	0	0	0	-	0	0	4	1	1	1	1	9	9			
7	8	9				14	15								25		26				30	31	32			

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER							EVENT DATE					REPORT DATE									
01	CON'T	P	O	T	L	0	5	0	-	0	3	0	5	0	2	1	5	7	7	0	3	0	2	7	7
7	8	57	58	59	60	61							68	69				74	75						80

[illegible]

02 Three of three pressurizer level transmitters were found to have high water level re-
7 8 9 80

03 actor trip settings less conservative than allowed by Technical Specifications. A re-
7 8 9 80

04 actor trip would have occurred, but not by the required high level setpoint. The
7 8 9 80

05 three channel settings were found 1%, 2% and 4% high. This incident is similar to
7 8 9 30

06 RO 76-19 and similarly the actual trip values did not exceed the pressurizer level
7 8 9 80

used in the accident analysis pre- PRME sented in the FSAR. (RO 77-3)

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION		
0	7	I A	E	I	N	S	T	R	U	N	B	0	8	0	Y
7	8	9	10	11	12				17	43	44				48

CAUSE DESCRIPTION

08	One transmitter had a defective bellows and the transmitter was replaced and re-	
7 8 9		80
09	calibrated. The other two channels had drifted and caused the out of specification	
7 8 9		80
10	readings. They were recalibrated. As a result of RO 76-19, the manufacturer (Cont.	
7 8 9		80
	on attached sheet)	80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	1	H	0	0	0	NA	B	NA		
7	8	9	10	11	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1	2	Z	NA	NA
7	8	9	10	11
				44
				45
				80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	Z	NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	NA

OFFSITE CONSEQUENCES

[illegible]

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	Z		NA

PUBLICITY

17	NA
7 8 9	80

ADDITIONAL FACTORS

18 The high level reactor trip settings are being investigated and will be set more
7 8 9 80

19 conservative to allow for the observed drift of these instruments.
7 8 9 80

NAME: Mark L. Marchi

PHONE: 414/432-3311

Cause Description (Cont.)

was contacted and asked to provide a solution to the drift problem encountered with this type of level transmitter. The manufacturer has sent us a new type of strain gage to insert in this model transmitter, which they expect to alleviate the problem. We have replaced the strain gage in several transmitters of this type and we will do so for all of these transmitters if it proves to be the solution.