UNITED STATES



NUCLEAR REGULATORY COMMISSION

DIRECTORATE OF REGULATORY OPERATIONS REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

MAR 1 7 1975

Wisconsin Public Service Corporation ATTN: Mr. E. W. James, Senior Vice President Power Generation and Engineering P.O. Box 1200 Green Bay, Wisconsin 54305

Docket No. 50-305

(

A0 (2)

Gentlemen:

Enclosed is IE Bulletin No. 75-03 which requires action by you with regard to your power reactor facility(ies) with operating license or construction permit.

Should you have questions regarding this Bulletin or the action required of you, please contact this office.

Sincerely,

James G. Keppler Regional Director

Enclosure: IE Bulletin No. 75-03

> Approved by GAO, B-180225 (ROO72), clearance expires 7-31-77. Approval was given under a blanket clearance specifically for identified generic problems.

bcc: Central Files IE Files PDR Local PDR



INCORRECT LOWER DISC SPRING AND CLEARANCE DIMENSION IN SERIES 8300 AND 8302 ASCO SOLENOID VALVES

DESCRIPTION OF CIRCUMSTANCES:

Series

Recent abnormal occurrences have been reported at the Point Beach and Kewaunee nuclear stations in which safety related solenoid air-pilot valves manufactured by Automatic Switch Company (ASCO) failed to operate properly due to an incorrect lower disc spring and/or improper lever to lower disc stem clearance. Information contained in the reports submitted by NRC licensees and subsequent discussions between NRC and ASCO personnel have revealed the potential for similar failures with ASCO, 120 volt, 60 cycle solenoid valves of the types listed below.

Form

8300-C			•	F,	υ,	RF	or	RU
8302-C	-			F,	U,	RF	or	RU

According to the manufacturer, values of the types listed above should have a heavier duty spring on the upper than on the lower disc section. These springs are identified by a specific part number and color which may differ for each value type. Incorrect lower disc springs as well as improper clearance between the lever and lower value disc stem have been identified as the causes of recent value failures.

It has also been reported that incorrect valve discs springs have been included in repair kits supplied by the valve manufacturer. In case of uncertainty, licensees are advised to contact the ASCO valve service department regrading the proper disc springs and clearance for specific valve types.

ACTION TO BE TAKEN BY LICENSEES:

For all power reactor facilities with operating license or construction permit:

- 1. Determine if ASCO values of the types described above are in use or planned for use in safety related systems.
- 2. Report to this office in writing, within 30 days for facilities with operating license and within 60 days for facilities with construction permit, the results of your findings with regard to Item 1.
- 3. If solenoid values of the types described are in use or planned for use in safety related systems, include in your written reply the actions you have taken, or plan to take, to prevent failure of the type described above. Your written reply should also include the date when such actions were, or will be completed.