

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

TO:
Mr. J. G. Ksppler

FROM:
Wisconsin Public Service Corp.
Green Bay, Wisconsin
E. W. James

DATE OF DOCUMENT
8/13/76

DATE RECEIVED
8/16/76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP
INPUT FORM

NUMBER OF COPIES RECEIVED
One signed

DESCRIPTION

Ltr. trans the following:

DO NOT REMOVE

PLANT NAME:
Kewaunee (1-P)

ENCLOSURE

Licensee Event Report (RO 50-305/76-13) on 7/15/76 concerning containment particulate and radio-gas monitors R-11 & R-12 not sampling containment for a 19 hour period.

(RO 50-305/76-14) on 7/16/76 concerning special ventilation train B being taken out of service prior to testing the operability of train A.

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED SEND DIRECTLY TO KREGER/J. COLLINS (2-P)

FOR ACTION/INFORMATION 8/20/76

RJL

BRANCH CHIEF: Schwencer
w/3 CYS FOR ACTION

LIC. ASST.: Sheppard
w/1 CYS
ACRS/6 CYS HOLDING/SENT TO LA

INTERNAL DISTRIBUTION

<input checked="" type="checkbox"/>	REG FILE			
<input checked="" type="checkbox"/>	NRC PDR			
<input checked="" type="checkbox"/>	I & E (2)			
<input checked="" type="checkbox"/>	MIPC			
<input checked="" type="checkbox"/>	SCHROEDER/IPPOLITO			
<input checked="" type="checkbox"/>	HOUSTON			
<input checked="" type="checkbox"/>	NOVAK/CHECK			
<input checked="" type="checkbox"/>	GRIMES			
<input checked="" type="checkbox"/>	CASE			
<input checked="" type="checkbox"/>	BUTLER			
<input checked="" type="checkbox"/>	HANAUER			
<input checked="" type="checkbox"/>	TEDESCO/MACCARY			
<input checked="" type="checkbox"/>	EISENHUT			
<input checked="" type="checkbox"/>	BAER			
<input checked="" type="checkbox"/>	SHAO			
<input checked="" type="checkbox"/>	VOLLMER/BUNCH			
<input checked="" type="checkbox"/>	KREGER/J. COLLINS			

EXTERNAL DISTRIBUTION

LPDR: Kewaunee, WI,
 TIC:
 NSIC:

CONTROL NUMBER

8332

D. LANHAM

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

August 13, 1976

Mr. J. G. Keppler, Reg Dir
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



Dear Mr. Keppler:

Subject: Docket 50-305
Operating License DPR-43
Reportable Occurrences 76-13 and 76-14

C.D. 7/14/76

In accordance with the requirements of Technical Specifications, Section 6.9.2, the attached reports for Reportable Occurrences RO 76-13 and RO 76-14 are submitted.

Very truly yours,

E. W. James
Senior Vice President
Power Supply & Engineering

EWJ:sna
Attach.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, D.C. 20555
Dir, Office of Management Info & Program
Control, US NRC, Washington, D.C. 20555

8607

AUG 16 1976

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER										LICENSE TYPE					EVENT TYPE				
01	W	I	K	N	P	1	0	0	-	0	0	0	0	0	0	-	0	0	4	1	1	1	1		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
01 CONT			CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER					EVENT DATE				REPORT DATE							
01	CONT	P	O	L	L	0	5	0	-	0	3	0	5	0	7	1	5	7	6	0	8	1	3	7	6
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

EVENT DESCRIPTION

02	Containment particulate and radio-gas monitors R-11 and R-12 were not sampling																							80
03	containment for a 19 hour period. The back-up radiation monitor for sampling also																							80
04	was not in service. This is contrary to T.S. requirements for Reactor Coolant Leakage																							80
05	detection in which this system may not be inoperable for more than 12 hours. (RO 76-13)																							80
06																								80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION										
07	B	B	A	X	X	X	X	X	X	N	W	1	2	0	Y										
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

CAUSE DESCRIPTION

08	R-11 and R-12 were out of service for repair, R-21 was monitoring containment air.																							80
09	R-11 and R-12 were returned to service but the manual isolation valves were not																							80
10	opened, R-21 was taken out of service. The condition went undetected for 19 hours.																							80

FACILITY STATUS		% POWER			OTHER STATUS			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION															
11	E	1	0	0	NA	a	Visual																		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY					LOCATION OF RELEASE																
12	Z	Z	NA	NA																					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION																					
13	0	0	0	Z	NA																				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

PERSONNEL INJURIES

NUMBER		DESCRIPTION																							
14	0	0	0	NA																					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

OFFSITE CONSEQUENCES

15	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																							
16	Z	NA																							
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

PUBLICITY

17	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	None																							80
----	------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: Mark L. Marchi PHONE: 414-432-3311

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME [01] W I K N P i						LICENSE NUMBER 0 0 - 0 0 0 0 0 0 - 0 0						LICENSE TYPE 4 1 1 1 1				EVENT TYPE 31 32	
CATEGORY [01] CONT		REPORT TYPE P O		REPORT SOURCE L L		DOCKET NUMBER 0 5 0 - 0 3 0 5				EVENT DATE 0 7 1 6 7 6				REPORT DATE 0 8 1 3 7 6			

EVENT DESCRIPTION

[02]	Special ventilation train B was taken out of service prior to testing the operability	80
[03]	of train A. This is contrary to the requirements of T.S. section 3.6.b.2.	80
[04]	(RO 76-14)	80
[05]		80
[06]		80

SYSTEM CODE [07] S H	CAUSE CODE A	COMPONENT CODE X X X X X X	PRIME COMPONENT SUPPLIER A	COMPONENT MANUFACTURER Z 9 9 9	VIOLATION N
-------------------------	-----------------	-------------------------------	-------------------------------	-----------------------------------	----------------

CAUSE DESCRIPTION

[08]	A plant electrician performing maintenance on a circuit breaker in special ventilation	80
[09]	system train B forgot to inform the shift supervisor before taking train B out of	80
[10]	service. Subsequent surveillance testing indicates Train A was operable.	80

FACILITY STATUS [11] E	% POWER 1 0 0	OTHER STATUS NA	METHOD OF DISCOVERY a	DISCOVERY DESCRIPTION NA
FORM OF ACTIVITY RELEASED Z	CONTENT OF RELEASE Z	AMOUNT OF ACTIVITY NA	LOCATION OF RELEASE NA	

PERSONNEL EXPOSURES

NUMBER [13] 0 0 0	TYPE Z	DESCRIPTION NA
----------------------	-----------	-------------------

PERSONNEL INJURIES

NUMBER [14] 0 0 0	DESCRIPTION NA
----------------------	-------------------

OFFSITE CONSEQUENCES

[15] NA

LOSS OR DAMAGE TO FACILITY

TYPE [16] Z	DESCRIPTION NA
----------------	-------------------

PUBLICITY

[17] NA

ADDITIONAL FACTORS

[18] NA

[19] NA

NAME: Mark L. Marchi PHONE: 414-432-3311

WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

August 13, 1976

Regulatory Docket File

Mr. J. G. Keppler, Reg Dir
Office of Inspection & Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



Dear Mr. Keppler:

Subject: Docket 50-305
Operating License DPR-43
Reportable Occurrences 76-13 and 76-14


In accordance with the requirements of Technical Specifications, Section 6.9.2, the attached reports for Reportable Occurrences RO 76-13 and RO 76-14 are submitted.

Very truly yours,

E. W. James
Senior Vice President
Power Supply & Engineering

EWJ:sna
Attach.

cc - Dir, Office of Inspection & Enforcement
US NRC, Washington, D.C. 20555
Dir, Office of Management Info & Program
Control, US NRC, Washington, D.C. 20555



0200

8332

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME:

0	1	W	I	K	N	P	I
---	---	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE:

--	--

CATEGORY:

0	1
---	---

 CONT P O REPORT TYPE:

L

 REPORT SOURCE:

L

 DOCKET NUMBER:

0	5	0	-	0	3	0	5
---	---	---	---	---	---	---	---

 EVENT DATE:

0	7	1	5	7	6
---	---	---	---	---	---

 REPORT DATE:

0	8	1	3	7	6
---	---	---	---	---	---

EVENT DESCRIPTION

0	2
---	---

 Containment particulate and radio-gas monitors R-11 and R-12 were not sampling

0	3
---	---

 containment for a 19 hour period. The back-up radiation monitor for sampling also

0	4
---	---

 was not in service. This is contrary to T.S. requirements for Reactor Coolant Leakage

0	5
---	---

 detection in which this system may not be inoperable for more than 12 hours. (RO 76-13)

0	6
---	---

SYSTEM CODE:

B	B
---	---

 CAUSE CODE:

A

 COMPONENT CODE:

X	X	X	X	X	X
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

N

 COMPONENT MANUFACTURER:

W	1	2	0
---	---	---	---

 VIOLATION:

Y

CAUSE DESCRIPTION

0	8
---	---

 R-11 and R-12 were out of service for repair, R-21 was monitoring containment air.

0	9
---	---

 R-11 and R-12 were returned to service but the manual isolation valves were not

1	0
---	---

 opened, R-21 was taken out of service. The condition went undetected for 19 hours.

FACILITY STATUS:

E

 % POWER:

1	0	0
---	---	---

 OTHER STATUS:

NA

 METHOD OF DISCOVERY:

a

 DISCOVERY DESCRIPTION:

Visual

FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

NA

 LOCATION OF RELEASE:

NA

PERSONNEL EXPOSURES

NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION:

NA

PERSONNEL INJURIES

NUMBER:

0	0	0
---	---	---

 DESCRIPTION:

NA

OFFSITE CONSEQUENCES

1	5
---	---

 NA

LOSS OR DAMAGE TO FACILITY

TYPE:

Z

 DESCRIPTION:

NA

PUBLICITY

1	7
---	---

 NA

ADDITIONAL FACTORS

1	8
---	---

 None

1	9
---	---

NAME: Mark L. Marchi PHONE: 414-432-3311

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

01	WIKNPI	00-000000-00	41111					
7	8 9	14 15	25 26	30 31 32				
01	CONT	P0	L	L	050-0305	071676	081376	
7	8	57 58	59	60	61	68 69	74 75	80

EVENT DESCRIPTION

02	Special ventilation train B was taken out of service prior to testing the operability								80
7	8	9						80	
03	of train A. This is contrary to the requirements of T.S. section 3.6.b.2.								80
7	8	9						80	
04	(RO 76-14)								80
7	8	9						80	
05									80
7	8	9						80	
06									80
7	8	9						80	

07	S	H	A	X	X	X	X	X	X	A	Z	9	9	9	N	
7	8	9	10	11	12	13	14	15	16	17	43	44	45	46	47	48

CAUSE DESCRIPTION

08	A plant electrician performing maintenance on a circuit breaker in special ventilation								80
7	8	9						80	
09	system train B forgot to inform the shift supervisor before taking train B out of								80
7	8	9						80	
10	service. Subsequent surveillance testing indicates Train A was operable.								80
7	8	9						80	

11	E	1	0	0	NA	a	NA		
7	8	9	10	11	12 13	44	45	46	80

12	Z	Z	NA	NA			
7	8	9	10	11	44	45	80

PERSONNEL EXPOSURES

13	0	0	0	Z	NA	
7	8	9	11	12	13	80

PERSONNEL INJURIES

14	0	0	0	NA	
7	8	9	11	12	80

OFFSITE CONSEQUENCES

15	NA		
7	8	9	80

LOSS OR DAMAGE TO FACILITY

16	Z	NA		
7	8	9	10	80

PUBLICITY

17	NA		
7	8	9	80

ADDITIONAL FACTORS

18	NA		
7	8	9	80

19									80
7	8	9						80	

NAME: Mark L. Marchi PHONE: 414-432-3311