## NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL (TEMPORARY FORM)

CONTROL NO: 523:

FILE: INCIDENT REPORT FILE

ROM:Wisconsin Public	Service Co	DATE OF DOC	DAT	E REC'D	LTR	TWX	RPT	OTHER	
Green Bay, Wisc.			DATE HEOD			1			
E.W. Iames		5-8-75	5-1	2-75	XX				
TO:		ORIG	CC OTHER SENT A		NT AE	CPDR_	XXX		
Benard Rusche		1 Signed			SENT LOCAL PDF		XXXX		
			<u></u>			. <del> </del>			
CLASS UNCLASS PR	OP INFO	INPUT	NOC	YS REC'D	D	OCKET	NO:	50-305	
DESCRIPTION:	,	ENCL	OSURES:						
tr. trank the following	ng		Abno	rm. Occur	rr.#	75 <b>-</b> 9。	on 4-29	-75, concecn	
•			ing	a burned	out C	oil (A	FP-2-XB	)	
	•						•		
		٠.					•	,	
		( 1 cy. Encl. Rec			<b>'</b> d)	•			
Varrauma								<b>.</b>	
PLANT NAME: Kewaune	:e	٠	ŀ				· ·		
		FOR ACTION/	NFOR	MATION				VCR 5-14-7	
BUTLER (L) SC	HWENCER (I	L) ZIEMANN (	L)	REGAN	1 (E)		14	, · ·	
	V/ Copies	W/ Copies		W/ Co	opies			15	
CLARK (L) ST	OLZ (L)	DICKER (E)		LEAR (	L)		. ,	1.	
	// Copies	W/ Copies		W/ Co	opies –				
PARR (L) VA	ASSALLO (L)	KNIGHTON	(E)	SPELS				•	
W/ Copies W	// Copies	W/ Copies		W/ Co	opies ,		•		
	RPLE (L)	YOUNGBLO	OOD (E						
	V/ <b>a</b> Copies	· W/ Copies		W/ C	opies				
		INTERNAL D	ISTRIE		<u> </u>				
REG FILE TE	CH REVIEW	DENTON		LIC AS			A/T II		
TRC PDR SC	HROEDER	**GRIMES		R. DIGGS			BRAI		
OGC, ROOM P-506A 🛮 🖋 MA	ACCARY	GAMMILL		H. GEARI				ZMAN	
	NIGHT	KASTNER		E. GOULE			MELT	۷	
	WLICKI	BALLARD		P. KREUT		=)	PLAN	c	
	IAO	SPANGLER		J. LEE (L				NALD .	
ST ***ST	ELLU	ENIVEDO		M. MAIGR					
MOORE (L) ** HOUSTON END DEYOUNG (L) ** NOVAK MU		ENVIRO	S. REED (E)				CHAPMAN DUBE (Ltr)		
			M. SERVICE (L)			E. COUPE			
SKOVHOLT (L) RC	ROSS DICKER		S. SHEPPARD (L) M. SLATER (E)			PETERSON			
	IPPOLITO KNIGHTON  WITEDESCO YOUNGBLO					HARTFIELD (2)			
	, , , , , , , , , , , , , , , , , , , ,		S. TEETS (L)			KLECKER			
					,	EISENHUT			
	1,440 0,11		=			WIGGINTON			
REG OPR LA				AV AMILICA	NI III		ANIGG	SINION	
REG OPR LA	NAROYA	HARIESS		V. WILSO					
REG OPR LA FILE &, REGION (2) BE		HARLESS		V. WILSO R. INGRA				TILLIAMS.	

1 - LOCAL PDR ARCHARD (1)(2)(10) - NATIONAL LABS

1 - NSIC (BUCHANAN)

1 - W. PENNINGTON, Rm E-201 GT

1 - ASLB

- CONSULTANTS

1 – Newton Anderson ACRS SENT TO LIC ASST

\*\* SEND ONLY TEN DAY REPORTS

NEWMARK/BLUME/AGBABIAN

- 1 PDR-SAN/LA/NY
- 1 BROOKHAVEN NAT LAB
- 1 G. ULRIKSON, ORNL
- 1 AGMED (RUTH GUSSMAN) Rm B-127 GT
- 1 J. D. RUNKLES, Rm E-201 GT

## WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

May 8, 1975

noticed fortion flatter

Mr. Benard Rusche, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission

Washington, D. C. 20555

Dear Mr. Rusche:

Subject: Docket 50-305

Operating License DPR-43

Abnormal Occurrence Report AO 75-9

In accordance with the requirements of Technical Specifications,

paragraph 6.6.2, we submit the attached Licensee Event Report form.

Very truly yours,

E. W. Jame

Senior Vice President

Power Generation & Engineering

EWJ:sna

Attach.

cc - Mr. James G. Keppler

Mr. Dwane Boyd

NAME:

PHONE: 414-432-3311

GPO 881 - 667


## TELEGRAM

5/8/75

April 30, 1975

Mr. Duane Boyd
Resident Inspector - US Nuclear Regulatory Commission
Directorate of Regulatory Operations - Region III
Two Rivers Municipal Hospital
Two Rivers, Wisconsin 54241

SUBJECT: Docket 50-305
OPERATING LICENSE: DPR-43
ABNORMAL OCCURRENCE REPORT



In accordance with the requirements of Technical Specifications, Paragraph 6.6.2.a and 1.0.a.1.(d), we submit the following:

Report Number: 50/305 75-9

Occurrence Date: April 29, 1975

Facility: Kewaunee Nuclear Plant

Kewaunee, Wisconsin 54216

Identification of Occurrence:

Coil failure on Relay AFP2-XB

Condition Prior to Occurrence:

Cold Shutdown Reactor Coolant System 170°F Residual Heat Removal System in Service

Description of Occurrence:

Manufacturer requested coils of six relays installed in the Engineered Safeguard Racks and Reactor Protection Racks be verified for correct coil style. Verification was made by measuring coil resistance of the subject relays and comparing resistance to values supplied by Manufacturer. The resistance of coil in relay AFP2-XB read infinity. Coil was replaced under Maintenance Work Request 55-00449.

Offerma

-