

**AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 783

FILE: INCIDENT REPORT

FROM: Wisconsin Public Service Corp. Green Bay, Wis. 54305 E.W. James			DATE OF DOC 1-21-75	DATE REC'D 1-23-75	LTR XX	TWX	RPT	OTHER
TO: Mr. E. Case			ORIG 1 signed	CC	OTHER	SENT AEC PDR <u>XX</u> SENT LOCAL PDR <u>XX</u>		
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-305		
	XXX							

DESCRIPTION: Ltr reporting Abnormal Occurrence
AO-50-305/75-2 on 1-9-75 re failure of air operated
valve BT-31A, 1A steam generator blowdown sample
valve, to close upon isolation signal from R-19
radiation monitor.... *W/attchmt*

ENCLOSURES:

ACKNOWLEDGED

Do Not Remove

PLANT NAME: Kewaunee

FOR ACTION/INFORMATION

DHL 1-25-75

BUTLER (S) W/ Copies	SCHWENCER (S) W/ Copies	ZIEMANN (S) W/ Copies	REGAN (E) W/ Copies
CLARK (S) W/ Copies	STOLZ (S) W/ Copies	DICKER (E) W/ Copies	LEAR (S) W/ Copies
PARR (S) W/ Copies	VASSALLO (S) W/ Copies	KNIGHTON (E) W/ Copies	SPEIS (S) W/ Copies
KNIEL (S) W/ Copies	<i>✓</i> PURPLE (S) W/ <i>✓</i> Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION

<i>✓</i> REG FILE <i>✓</i> AEC PDR <i>✓</i> OGC, ROOM P-506-A <i>✓</i> MUNTZING/STAFF <i>✓</i> CASE GIAMBUSSO BOYD MOORE (S) (BWR) DEYOUNG (S) (PWR) SKOVHOLT (S) GOLLER (S) P. COLLINS DENISE REG OPR <i>✓</i> FILE & REGION T.R. WILSON	TECH REVIEW <i>✓</i> SCHROEDER <i>✓</i> MACCARRY <i>✓</i> KNIGHT <i>✓</i> PAWLICKI <i>✓</i> SHAO <i>✓</i> STELLO <i>✓</i> HOUSTON <i>✓</i> NOVAK <i>✓</i> ROSS <i>✓</i> IPPOLITO TEDESCO <i>✓</i> LONG <i>✓</i> LAINAS <i>✓</i> BENAROYA <i>✓</i> STEELE <i>✓</i> VOLIMER	DENTON GRIMES GAMMILL <i>✓</i> KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	LIC. ASST. DIGGS (S) GEARIN (S) GOULBOURNE (S) KREUTZER (E) LEE (S) MAIGRET (S) REED (E) SERVICE (S) <i>✓</i> SHEPPARD (S) SLATER (E) SMITH (S) TEETS (S) WILLIAMS (E) WILSON (S) INGRAM (S)	A/T IND BRAITMAN SALTZMAN B. HURT PLANS MCDONALD CHAPMAN DUBE w/input E. COUPE <i>✓</i> R. Hartfield (2) <i>✓</i> KLEGGER <i>✓</i> F. WILLIAMS
---	---	---	---	---

EXTERNAL DISTRIBUTION

<i>✓</i> 1-LOCAL PDR Kewaunee, Wis.	(1) (2) (10) -NATIONAL LABS	1-PDR SAN/LA/NY
<i>✓</i> 1-TIC (ABERNATHY)	1-W. PENNINGTON, RM E-201 G.T.	1-BROOKHAVEN NAT LAB
<i>✓</i> 1-NSIC (BUCHANAN)	1-CONSULTANTS	1-G. ULRIKSON, ORNL
1-ASLB	NEWMARK/BLUME/ASBABIAN	1-AGMED (RUTH GUSSMAN) RM B-127 G.T.
1-NEWTON ANDERSON		1-J. RUNKLES, RM E-201 G.T.
<i>✓</i> 5-ACRS SENT TO LIC. ASST. Sheppard 1-25-75		

WISCONSIN PUBLIC SERVICE CORPORATION

Public Service



P.O. Box 1200, Green Bay, Wisconsin 54305

Regulatory Docket File January 21, 1975

Mr. Edson Case, Acting Director
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Case:

Subject: Docket 50-305
Operating License DPR-43
Abnormal Occurrence Report



In accordance with the requirements of Technical Specifications, Paragraph 6.6.2.a and 1.0.a.1.d, we submit the following:

Report Number: 50-305/75-2

Occurrence Date: January 9, 1975

Facility: Kewaunee Nuclear Power Plant
Kewaunee, Wisconsin

Identification of Occurrence: Failure of air operated valve BT-31A; 1A steam generator blowdown sample valve, to close upon isolation signal from R-19, radiation monitor.

Conditions Prior to Occurrence: Reactor Critical - 75% power
Normal Reactor Coolant System Temperature - 556°F
Normal Reactor Coolant System Pressure - 2220 psig/Tavg.

Description of Occurrence: During performance of Surveillance Procedure SP-049 "Radiation Monitoring System Test" valve BT-31A failed to close when radiation monitor R-19 tripped.

Analysis of Occurrence: Valve BT-31A is a redundant valve in the steam generator blowdown sample flow path. Valve BT-31A is located within containment and its backup, valve BT-32A is located outside of containment. Valve BT-32A operated correctly; therefore, no danger existed to the health and safety of the public. The redundant valve BT-32A was closed and remained closed until completion of the repair to valve BT-31A, thereby, assuring containment integrity.

783


January 21, 1975

Corrective Action: The cause of failure was investigated and was determined to be a failure of the solenoid valve associated with the air supply to BT-31A. Upon the de-energization of solenoid by R-19, the air solenoid did not stroke and vent air from the BT-31A operator; thereby allow operation of the spring to close BT-31A. The solenoid was tapped with screw driver which resulted in stroking of the solenoid to the de-energized position and operation of BT-31A. Valve BT-31A was then operated in excess of 10 times without failure. The solenoid was then removed for disassembly and inspection. The inspection revealed no evidence as to cause of failure and no imperfections were noted within the solenoid valve body or in any parts of the valve. The solenoid was reassembled, checked for proper operation, and reinstalled. No further corrective action appears to be warranted at this time.

Failure Data: The cause has not been determined. It can only be assumed that it was a result of random sticking of the solenoid internals.

Manufacturer	ASCO, Automatic Switch Company
Model	8302-C-4

Very truly yours,



E. W. James
Senior Vice President
Power Generation & Engineering

EWJ:sna

cc - Mr. James G. Keppler, US AEC - Region III
Mr. Dwane Boyd, US AEC - Resident Inspector

CENSEE EVENT REPORT

Regulatory Docket File

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

Controlled by Licensee 1-21-75

LICENSEE NAME <div style="display: flex; justify-content: space-between;">01WIKNPI</div>														LICENSE NUMBER <div style="display: flex; justify-content: space-between;">00-00000-00</div>										LICENSE TYPE <div style="display: flex; justify-content: space-between;">41111</div>				EVENT TYPE <div style="display: flex; justify-content: space-between;">01</div>	
7	8	9	14	15	25	26	30	31	32																				
CONT			CATEGORY <div style="display: flex; justify-content: space-between;">PO</div>		REPORT TYPE <div style="display: flex; justify-content: space-between;">T</div>		REPORT SOURCE <div style="display: flex; justify-content: space-between;">L</div>		DOCKET NUMBER <div style="display: flex; justify-content: space-between;">050-0305</div>						EVENT DATE <div style="display: flex; justify-content: space-between;">010975</div>				REPORT DATE <div style="display: flex; justify-content: space-between;">012175</div>										
7	8	57	58	59	60	61	66	69	74	75																			

EVENT DESCRIPTION

02 During Surveillance Testing SG Blowdown Sample Valve BT-31A failed to operate																		80
03 due to failure of a solenoid valve sticking in the energized position. The																		80
04 redundant valve functioned properly. No danger to health and safety of the																		60
05 public existed																		80
06																		80

SYSTEM CODE <div style="display: flex; justify-content: space-between;">07C6</div>		CAUSE CODE <div style="display: flex; justify-content: space-between;">E</div>		COMPONENT CODE <div style="display: flex; justify-content: space-between;">VALVEX</div>				PRIME COMPONENT SUPPLIER <div style="display: flex; justify-content: space-between;">A</div>		COMPONENT MANUFACTURER <div style="display: flex; justify-content: space-between;">A610</div>				VIOLATION <div style="display: flex; justify-content: space-between;">N</div>	
7	8	9	10	11	12	17	43	44	47	48					

CAUSE DESCRIPTION

08 Cause of solenoid sticking could not be determined. Solenoid was dismantled																		80
09 and inspected - no indication of cause was noted.																		80
10																		80

FACILITY STATUS <div style="display: flex; justify-content: space-between;">11E</div>		% POWER <div style="display: flex; justify-content: space-between;">075</div>		OTHER STATUS <div style="display: flex; justify-content: space-between;">NA</div>				METHOD OF DISCOVERY <div style="display: flex; justify-content: space-between;">B</div>		DISCOVERY DESCRIPTION <div style="display: flex; justify-content: space-between;">NA</div>			
7	8	9	10	12	13	44	45	46					
FORM OF ACTIVITY RELEASED <div style="display: flex; justify-content: space-between;">12Z</div>		CONTENT OF RELEASE <div style="display: flex; justify-content: space-between;">Z</div>		AMOUNT OF ACTIVITY <div style="display: flex; justify-content: space-between;">NA</div>				LOCATION OF RELEASE <div style="display: flex; justify-content: space-between;">NA</div>					
7	8	9	10	11	44	45							

PERSONNEL EXPOSURES

NUMBER <div style="display: flex; justify-content: space-between;">13000</div>			TYPE <div style="display: flex; justify-content: space-between;">Z</div>		DESCRIPTION <div style="display: flex; justify-content: space-between;">NA</div>													
7	8	9	11	12	13													

PERSONNEL INJURIES

NUMBER <div style="display: flex; justify-content: space-between;">14000</div>			DESCRIPTION <div style="display: flex; justify-content: space-between;">NA</div>																
7	8	9	11	12															

OFFSITE CONSEQUENCES

15 NA																		80
-------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE <div style="display: flex; justify-content: space-between;">16Z</div>		DESCRIPTION <div style="display: flex; justify-content: space-between;">NA</div>																	
7	8	9	10																

PUBLICITY

17 NA																		80
-------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18																		80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																		80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: M. E. Stern

PHONE: 414/432-3311