10% FOR PART 50 DOCKET MATE (TEMPORARY FORM)

CONTROL NO: 13150

FILE: INCIDENT REPORT

FROM: Wisconsin Public Svc. Corp Green Bay, Wis. 54305			DATE OF DOC	12-30-74		LTR	TWX	RPT	OTHER
Mr. E.W. James		12-26-74	_x			<u> </u>	<u> </u>	XXX	
TO: E.Case		ORIG	CC	OTHER	SE	SENT AEC PDR			
		l signed			SENT LOCAL PDR XX			XXX	
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D		DOCKET NO:			
	XXX				1		50-305		
DESCRIPTION:				ENCL	OSURES:				

Ltr reporting an abnormal Occurrence at the Kewaunee Nuclear Faciltiy....trans the following.....

Abnormal Occurrence Report:# 50-305/74-20 concerning....Failure of Valve SI-2B (8809B), in the boric acid suction to the Safety injection pumps, to open during surveillance testing

Kewaunee PLANT NAME:

(1 cy encl rec'd)

			-	
		FOR ACTION/INFORM	IATION 1	2-30-74 ЈВ
BUTLER (S) S	CHWENCER (S)	ZIEMANN (S)	REGAN (E)	
W/ Copies W	// Copies	W/ Copies	W/ Copies	ALLE LILL BURNER
	STOLZ (S)	DICKER (E)	LEAR (S)	ACKNOWLEDGE
W/ Copies W	// Copies	W/ Copies	W/ Copies	_
PARR (S) V	ASSALLO (S)	KNIGHTON (E)	SPEIS (S)	
W/ Copies W	V/ Copies	W/ Copies	W/ Copies	DO NOT REMOV
	PURPLE (S)	YOUNGBLOOD (E)		MOT TRANSPORT
W/ Copies W	// / Copies	W/ Copies	W/ Copies	
	•	INTERNAL DISTRIB	JTION !	
REG FILE	TECH REVIEW	DENTON	LIC. ASST.	A/T IND
AEC PDR	SCHROEDER	GRIMES	DIGGS (S)	BRAITMAN
GGC, ROOM P-506-A	MACCARRY	GAMMILL	GEARIN (S)	SALTZMAN
MUNIZING/STAFF	KNIGHT	KASTNER	GOULBOURNE (S	B. HURT
CASE .	PAWLICKI	BALLARD	KREUTZER (E)	
GIAMBUSSO	€SHAO	SPANGLER	LEE (S)	PLANS
BOYD	ESTELLO		MAIGRET (S)	MCDONALD
MOORE (S) (BWR)	HOUSTON	ENVIRO	REED (E)	CHAPMAN
DEYOUNG (S) (PWR)	NOV AK	MULLER	SERVICE (S)	DUBE w/input
SKOVHOLT (S)	ROSS	DICKER	SHEPPARD (S)	E. COUPE
GOLLER (S)	PIPPOLITO	KNIGHTON	SLATER (E)	PD. THOMPSON (2)
P. COLLINS	TEDE SCO	YOUNGBLOOD	SMITH (S)	KLECKER
DENISE	LONG	REGAN	TEETS (S)	F. WILLIAMS
REG OPR	LAINAS	PROJECT LDR	WILLIAMS (E)	· ·
FILE & REGION (2)	BENAROYA		WILSON (S)	
T.R. WILSON STE	A	HARLESS	INGRAM (S)	
1		EXTERNAL DISTRIB	UTION	AUR.
	aunee. Wis. (1) (2) (10) -NATIONAL 1		1-PDR SAN/LA/NY
AT-TOOME TOW VEM	STATE COMMANDO	-/ /-/ //		4

√1-TIC (ABERNATHY)

图-NSIC(BUCHANAN)

1-ASLB

1-NEWION ANDERSON

K5-ACRS SENT TO LIC. AASST.

1-W. PENNINGTON, RM E-201 G.T.

1-CONSULTANTS

NEWMARK/BLUME/AGBABIAN

1-BROOKHAVEN NAT LAB

1-G. ULRIKSON, ORNL

1-AGMED (RUTH GUSSMAN)

RM B-127 G.T.

, Atta Continue 1-J. RUNKLES, RM E-201

"™G.T.



WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305


December 26, 1974


Mr. Edson Case, Acting Director Directorate of Licensing Office of Regulation U. S. Atomic Energy Commission Washington, D. C. 20545

Dear Mr. Case:

Subject: Docket 50-305

Operating License DPR-43
Abnormal Occurrence Report





In accordance with the requirements of Technical Specifications Paragraph 6.6.2.a and 1.0.a.l.d, we submit the following:

Report Number:

50-305/74-20

Report Date:

December 26, 1974

Occurrence Date:

December 16, 1974

Facility:

Kewaunee Nuclear Power Plant

Kewaunee, Wisconsin

Identification of Occurrence:

Failure of valve SI-2B (8809B), in the boric acid suction to the safety injection pumps, to open during

surveillance testing.

Conditions Prior to Occurrence:

Plant operating base loaded

Reactor Power - 76%

Reactor Coolant Average Temperature - 556°F

Reactor Coolant Pressure - 2235 psig

Surveillance Test - 098 "Safety Injection Pump Test"

in progress

Description of Occurrence:

During performance of Surveillance Test 098, which verifies operability of all valves and pumps required to operate in an accident situation, it was determined that valve SI-2B failed to open upon demand. The thermal overload protection heaters were found to be

tripped.

Designation of the Apparent Cause of Occurrence:

Thermal overload protection heaters will trip on locked rotor current which occurs when a valve fails to open upon energization of the drive motor. The cause is attributed to the jamming of the valve upon previous closure, which is an equipment malfunction.

Analysis of Occurrence: The valve's closure force is limited by the closure setting of the motor operator's torque switch. This switch setting was and is at its minimum value to minimize the probability of jamming the valve disk into the seat. The valve was manually operated immediately following the incident without difficulty. Upon manual closure and resetting of the heater trips, the valve was electrically operated a number of times without encountering a malfunction and returned to service.

There were no personnel injuries or exposures attributable to this occurrence. Since this valve is a redundant component and its counterpart SI-2A operated properly during the surveillance test, no consequences would result which would affect public safety.

Corrective Action: No further corrective action beyond that noted above is warranted at the present time.

Failure Data:

During the preoperational test program, the valve internals were inspected. The seats and disk were verified to be properly mating and the disk guides were checked for burs and imperfections which would cause operating difficulties. This inspection was prompted by a failure to open during preliminary valve testing. This inspection revealed no apparent reason for the failure to open.

Following that inspection the valve was cycled a number of times, > 10, without malfunction and returned to service.

Valve Manufacturer - Anchor

Motor Operator Manufacturer - Limitorque

Valve Size/Type - 8"/Wedge disk gate

Motor Operator Type - SNMB

Motor Operator Size - 00

Motor Operator Serial Number - 108864

Motor Operator HP - 1.4

Very truly yours,

EW James Ras

E. W. James, Senior Vice President Power Generation & Engineering

EWJ:sna

cc - Mr. James G. Keppler, US AEC - Region III Mr. Dwane Boyd, US AEC - Resident Inspector



	CONTROL BLOCK: [] [PLEASE PRINT ALL REQUIRED INFORMATI	QN]
01 7 B	LICENSEE NUMBER LICENSE TYPE W I K N P I	
01 7 B	CON'T P 0 T L 0 5 0 — 0 3 0 5 1 2 1 6 7 4 1 2 2 6 7 5 57 58 59 60 61 68 69 74 75	4 80
	EVENT DESCRIPTION Valve S1 2B (8809B) failed to open during Surveillance Testing.	
7 B	The motor thermal overload protection heaters were found tripped.	80
7 B	Valve was manually operated, then electrically operated a number of times without	BO
7 B 05	failure and placed back in service.	SO
7 B 06 7 6		<u>60</u>
07	SYSTEM CAUSE COMPONENT CODE COMPONENT CODE COMPONENT SUPPLIER MANUFACTURER VIOLATION SYSTEM CAUSE COMPONENT CODE COMPONENT SUPPLIER MANUFACTURER VIOLATION N CAUSE DESCRIPTION SYSTEM CAUSE COMPONENT CODE COMPONENT SUPPLIER MANUFACTURER VIOLATION N CAUSE DESCRIPTION	80
08 7 8	Spurious failure. Limitorque Type - SNMB, Size - 00	لِـ
	Serial Number 108864; Motor Size 1.4 hp; Anchor 8 inch	80
	Wedge disk gate valve	BO
	FACILITY STATUS BOOKER OTHER STATUS DISCOVERY DESCRIPTION [E] [0] 7 6 [B] [B] [B] [DISCOVERY DESCRIPTION DISCOVERY DISCOV	80
12 7 8	FORM OF ACTIVITY CONTENT RELEASED OF RELEASE 9 10 11 44 45 PERSONNEL EXPOSURES	80
13 7 8	NUMBER TYPE DESCRIPTION	 80
14	PERSONNEL INJURIES NUMBER OESCRIPTION	
	OFFSITE CONSEQUENCES	80
15 7 8	9	80
16 7 8	LOSS OR DAMAGE TO FACILITY TYPE DESCRIPTION 9 10	لِـ
	PUBLICITY	80
7 8		80
18	ADDITIONAL FACTORS	
7 8 1 119	y 	80.
7 8	NAME: Michael Stern PHONE: 414-432-3311	 80