

Original

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 10304

FILE: _____

FROM: Wisconsin Public Service Green Bay, Wisc. 54305 E. W. James		DATE OF DOC 10-1-74	DATE REC'D 10-4-74	LTR XX	TWX	RPT	OTHER
TO: J. F. O'Leary		ORIG 1 signed	CC	OTHER	SENT AEC PDR <u>XX</u>		
					SENT LOCAL PDR <u>XX</u>		

CLASS	UNCLASS XX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-305
-------	---------------	-----------	-------	-------------------	----------------------

DESCRIPTION:

Ltr reporting Abnormal Occurrence 50-305/74-16 on 9-20-74 re failure to have automatic isolation devices capable of limiting gaseous release rate in operations

ENCLOSURES:

Do Not Remove
ACKNOWLEDGED

PLANT NAME: Kewaunee

FOR ACTION/INFORMATION

LMB 10-12-74

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/4Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u> AEC PDR OGC, ROOM P-506A MUNTZING/STAFF CASE GIAMBUSO BOYD MOORE (L) (BWR) DEYOUNG (L) (PWR) SKOVHOLT (L) GOLLER (L) P. COLLINS DENISE REG OPR FILE & REGION (3) MORRIS STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA VOLIMER	<u>DENTON</u> GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR <u>HARLESS</u>	<u>LIC ASST</u> DIGGS (L) GEARIN (L) GOULBOURNE (L) KREUTZER (E) LEE (L) MAIGRET (L) REED (E) SERVICE (L) SHEPPARD (L) SLATER (E) SMITH (L) TEETS (L) WILLIAMS (E) WILSON (L)	<u>A/T IND</u> BRAITMAN SALTZMAN B. HURT <u>PLANS</u> MCDONALD CHAPMAN DUBE w/input E. COUPE D. THOMPSON (2) KLECKER EISENHUT
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Kewaunee, WI	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - ASLBP(E/W Bldg, Rm 529)	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - W. PENNINGTON, Rm E-201 GT	1 - G. ULRIKSON, ORNL
1 - ASLB	1 - B&M SWINEBROAD, Rm E-201 GT	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson	1 - CONSULTANTS	1 - R. D. MUELLER, Rm E-201 GT
5 - ACRS [REDACTED] SENT TO L/A SHEPPARD	NEWMARK/BLUME/AGBABIAN	

BN

3

Regulatory File Cy.
WISCONSIN PUBLIC SERVICE CORPORATION





P.O. Box 1200, Green Bay, Wisconsin 54305

October 1, 1974

Mr. J. F. O'Leary, Director
Directorate of Licensing
Office of Regulation
U.S. Atomic Energy Commission
Washington, D.C. 20545

Dear Mr. O'Leary:

Subject: Docket 50-305
Operating License DPR-43
Abnormal Occurrence Report



In accordance with the requirements of Technical Specifications 3.9b.4b and 6.6.2.a, we submit the following:

Report Number: 50-305/74-16

Report Date: October 1, 1974

Occurrence Date: September 20, 1974

Facility: Kewaunee Nuclear Power Plant
Kewaunee, Wisconsin

Identification of Occurrence: Failure to have automatic isolation devices capable of limiting gaseous release rates in operations.

Condition Prior to Occurrence: Reactor Shutdown
Normal Operating Temperature 549°F
Normal System Pressure 2235 psig

Description of Occurrence: Radiation Monitors R-11 and R-12, Containment Vessel or Containment System Vent - Air Particulate Monitor and Containment Vessel or Containment System Vent - Radioactivity Gas Monitor, respectively, are used to monitor containment atmosphere or purge exhaust. The containment was being purged to reduce the activity to allow entry. The purge was terminated to allow a containment sample to be drawn. The three position switch, "Containment Sample, Vent Sample, Purge" was

10304

Mr. J. F. O'Leary, Director
Page 2
October 1, 1974

placed in "Containment Sample", an air sample was drawn and analyzed. Instructions were given by the Health Physics Supervisor to restart the purge. The operator, upon restarting the purge, turned the selector switch to "Purge". When the switch is in the "Purge" position, Monitors R-11 and R-12 are not sampling the containment ventilation exhaust, although R-21 is sampling the exhaust. With R-11 and R-12 not sampling the containment ventilation exhaust, it invalidates the capability of the isolation devices on R-11 and R-12 to automatically stop the containment ventilation exhaust.

Description of
Apparent Cause
of Occurrence:

Operator error.

Analysis of
Occurrence:

Upon discovery that Monitors R-11 and R-12 were not monitoring the containment vent, the filters were removed from Monitor R-21 Containment System Vent - Activity Monitor, and taken to the lab for analysis. The analysis was for halogens and particulates. The results of this analysis was as follows:

Flow - approximately 20 cfm

Volume - 1.71×10^9 cc

Air Filter Activity

Gross Beta-Gamma	1.41×10^{-12} $\mu\text{c/cc}$
Gross Alpha	2.89×10^{-13} $\mu\text{c/cc}$
Gamma Emitters	
Isotope	Rn ²²²
Activity	2.40×10^{-11} $\mu\text{c/cc}$

Charcoal Filter Activity

I ₁₃₁	$= 1.99 \times 10^{-10}$ $\mu\text{c/cc}$
I ₁₃₃	$= 1.52 \times 10^{-11}$ $\mu\text{c/cc}$
XE ₁₃₃	$= 1.92 \times 10^{-9}$ $\mu\text{c/cc}$
XE ₁₃₅	$= 6.62 \times 10^{-11}$ $\mu\text{c/cc}$
XE _{133M}	$= 1.84 \times 10^{-4}$ $\mu\text{c/cc}$

The results did not exceed the limits allowed by the Technical Specifications, therefore, there was no immediate risk to the health and safety of the public.

Mr. J. F. O'Leary, Director
Page 3
October 1, 1974

Corrective Action: The Operations Supervisor questioned the operator, as to whether he (1) understood the discharge permit instructions and (2) understood that the "Purge" position on the switch meant that this purged the detector with clean air. In both cases, he said he understood the instructions. The Operations Supervisor stressed again the importance of knowing changes in plant conditions. No further corrective action is anticipated at this time.

Failure Data: Not applicable.

Sincerely,



E. W. James
Senior Vice President
Power Generation & Engineering

EWJ:jm

cc: Mr. James G. Keppler, Region III
Mr. Dwane Boyd, Resident Inspector

TELEGRAM

Sent 9-21-74 - 1135

September 21, 1974

Mr. Dwane Boyd
Resident Inspector - U. S. Atomic Energy Commission
Directorate of Regulatory Operations-Region III
Two Rivers Municipal Hospital
Two Rivers, Wisconsin

Subject: Docket 50-305
Operating License DPR-43
Abnormal Occurance Report



In accordance with the requirements of Technical Specifications, Paragraph 6.6.2.a and 1.0.d.(b), we submit the following.

S. 96.4.6

Report Number: 50-305/74-16

Occurrence Date: September 20, 1974

Facility: Kewaunee Nuclear Power Plant
Kewaunee, Wisconsin

Identification of
Occurrence:

Failure to have automatic isolation devices capable of
limiting gaseous release rates in operation.

Conditions prior
to Occurrence:

Reactor Shutdown
Normal Operating Temperature 549°F
System Operating Pressure 2235 psig

Description of
Occurrence:

At 0950 Containment purge was stopped and Radiation Monitors RM-11 and RM-12 were switched from the vent position to contain position. This was done to permit the Health Physics Department to draw an air sample.

At 1020 Containment purge was restarted and the Operator selected the purge position on RM-11 and RM-12 instead of vent position. This then prevented a sample to be drawn through RM-11 and RM-12 while the Containment was being purged.

The above continued until 1515 when the selector switch on RM-11 and RM-12 was put in the vent position. During the period from 1020 until 1550 samples were taken in Containment and on Radiation Monitor RM-21 and analyzed. Samples



demonstrated that there was no release to atmosphere that exceeded Technical Specifications limitations.

This occurrence was discussed with Jack Hind of the Region III Staff on 9-21-74.

OK Luma