	REGULATOR	Y INFORMATION	N DISTRIBUTION SYST	(RIDS)	
FACTL +5()-305 KEWAUNEE NU Ame Author G.H. Wiscons NAME Recipi	CLEAR POWER F AFFILIATION IN PUBLIC SEF ENT AFFILIAT	79/05/31 NOTARIZE PLANT, WISCONSIN PL RVICE CORP, ION , OFFICE OF THE DIF	JBLIC SERVIC	
SUBJECT:	BETWEEN BA TRAN FILTER FOUND TO	SFER PUMPS CO BE INOPERABI	DNE TRAIN OF HEAT 1 DMMON DISCHARGE HEA LE DURING INSTALLAT ILED HEAT TRACER RE	ADER & BA FION, CAUSED	· .
DISTRIBU	JTION CODE: A002S TITLE: INCID	COPIES RECH ENT REPORTS	EIVED:LTR ENCL	SIZE	र स्था के स्था के स्था का राज
NOTES:	یک بیک میں بات ایک بیک بیک بیک بیک بیک بیک بیک بیک بیک ب	و حله الله، حين الله خله الله الله حيد حيد إلي الي الله الله		ه خ بل خ به خ ج به ج ه به ·) की की की की की की की का आ की
ACTION:	ID CODE/NAME	LTTR ENCL	RECIPIENT ID CODE/NAME	LTTR ENCL	,
INTERNAL:	01 REG FILE 09 I&E 14 TA/EDO 16 EEB 18 PLANT SYS BR 20 AD PLANT SYS 22 REAC SAFT BR 24 KREGER 26 AD/SITE ANAL 28 ACDENT ANLYS E JORDAN/IE	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	02 NRC PDR 11 MPA 15 NOVAK/KNIEL 17 AD FOR ENGR 19 I&C SYS BR 21 AD SYS/PROJ 23 ENGR BR 25 PWR SYS BR 27 OPERA LIC BR 29 AUX SYS BR HANAUER,S,	1 1 3 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	TMI DOC CENTER 03 LPDR 29 ACRS	1 1 1 1 16 16	04 NSIC	1 1	

TOTAL NUMBER OF COPIES REQUIRED: LTTR 48 ENCL 48

:

..

WISCONSIN PUBLIC SERVICE CORPORATION



A002/5

P.O. Box 1200, Green Bay, Wisconsin 54305

May 31, 1979

Mr. J. G. Keppler, Regional Director Office of Inspection & Enforcement Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305 Operating License DPR-43 Reportable Occurrence LER 79-007/03L-0 and LER 79-008/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Reports for reportable occurrences LER 79-007/03L-0 and LER 79-008/03L-0 are being submitted.

Very truly yours,

ER h

E. R. Mathews, Vice President Power Supply & Engineering

enf

Attach.

cc - Dir, Office of Inspection & Enforcement US NRC, Washington, D. C. 20555 Dir, Office of Mgt Info & Program Control US NRC, Washington, D. C. 20555

(7-77)	
* *-	CONTROL BLOCK:
0 1	$ \underbrace{W \mid I \mid K \mid N \mid P \mid 1}_{9 \text{LICENSEE CODE} 14} 0 \mid 0 \mid - \mid 0 \mid 0 \mid 0 \mid 0 \mid - \mid 0 \mid 0 \mid $
CON'T	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
	pressure transmitters was out of calibration such that it would have initiated a
	contmt. spray signal 0.075 psi above the setpoint specified in TS 3.5.a. The oper-
	able transmitters did satisfy the requirements of TS 3.5.c; containment spray would
	have been initiated within the pressure limit if required. There was no effect on
	plant operation or public safety.
· ()	
- Langer and the second se	9 SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE SUBCODE
09 7 8	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $
· · ·	Image: Non-Report Number Event year Sequential Occode Type No. Image: Non-Report Number Image: Non-Report No. Image: Non-Repo
	$ \underbrace{\begin{array}{c} E \\ 33 \end{array}}_{33} \underbrace{\begin{array}{c} 13 \\ 34 \end{array}}_{34} \underbrace{\begin{array}{c} 19 \\ 35 \end{array}}_{35} \underbrace{\begin{array}{c} Z \\ 36 \end{array}}_{36} \underbrace{\begin{array}{c} 2 \\ 37 \end{array}}_{37} \underbrace{\begin{array}{c} 0 \\ 40 \end{array}}_{40} \underbrace{\begin{array}{c} 0 \\ 41 \end{array}}_{41} \underbrace{\begin{array}{c} 0 \\ 33 \end{array}}_{42} \underbrace{\begin{array}{c} V \\ 43 \end{array}}_{43} \underbrace{\begin{array}{c} 0 \\ 43 \end{array}}_{43} \underbrace{\begin{array}{c} 0 \\ 44 \end{array}}_{43} \underbrace{\begin{array}{c} 0 \\ 44 \end{array}}_{47} \underbrace{\begin{array}{c} 0 \\ 47 \end{array}}_{47} \underbrace{\end{array}{}_{47} \underbrace{\end{array}}_{$
101	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Instrument drift caused the pressure transmitter to be out of calibration. The transmitter was recalibrated and returned to service. No further action is re-
· • • • • • • • • • • • • • • • • • • •	Instrument drift caused the pressure transmitter to be out of calibration. The
	Instrument drift caused the pressure transmitter to be out of calibration. The transmitter was recalibrated and returned to service. No further action is re-
	Instrument drift caused the pressure transmitter to be out of calibration. The transmitter was recalibrated and returned to service. No further action is re- quired.
	Instrument drift caused the pressure transmitter to be out of calibration. The transmitter was recalibrated and returned to service. No further action is re- quired.
$ \begin{array}{c} 1 \\ 1 \\ 1 \\ 1 \\ 2 \\ 1 \\ 3 \\ 1 \\ 7 \\ 8 \\ 1 \\ 7 \\ 8 \\ 8 \\ 7 \\ 8 \\ 8 \\ 8 \\ 8 \\ 8 \\ 8 \\ 8 \\ 8 \\ 8 \\ 8$	Instrument drift caused the pressure transmitter to be out of calibration. The Itransmitter was recalibrated and returned to service. No further action is re- quired. 9 PACILITY STATUS % POWER 010 12 13 44 45 46
$ \begin{array}{c} 1 \\ 1 \\ 1 \\ 1 \\ 2 \\ 1 \\ 3 \\ 1 \\ 7 \\ 8 \\ 1 \\ 7 \\ 8 \\ 8 \\ 7 \\ 8 \\ 8 \\ 8 \\ 8 \\ 8 \\ 8 \\ 8 \\ 8 \\ 8 \\ 8$	Instrument drift caused the pressure transmitter to be out of calibration. The Itransmitter was recalibrated and returned to service. No further action is re- quired. 9 FACILITY STATUS % POWER 0 0
$ \begin{array}{c} 1 \\ 1 \\ 1 \\ 1 \\ 2 \\ 1 \\ 3 \\ 1 \\ 7 \\ 8 \\ 1 \\ 6 \\ 1 \\ 6 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1$	Instrument drift caused the pressure transmitter to be out of calibration. The Itransmitter was recalibrated and returned to service. No further action is re- quired.
$ \begin{array}{c} 1 \\ 1 \\ 1 \\ 1 \\ 2 \\ 1 \\ 3 \\ 1 \\ 7 \\ 8 \\ 1 \\ 6 \\ 1 \\ 6 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1$	Instrument drift caused the pressure transmitter to be out of calibration. The Itransmitter was recalibrated and returned to service. No further action is re- quired.
$ \begin{array}{c} 1 \\ 1 \\ 1 \\ 1 \\ 2 \\ 1 \\ 3 \\ 1 \\ 7 \\ 8 \\ 1 \\ 5 \\ 7 \\ 8 \\ 1 \\ 7 \\ 1 \\ 7 \\ 1 \\ 1 \\ 7 \\ 1 \\ 1 \\ 7 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1$	Instrument drift caused the pressure transmitter to be out of calibration. The transmitter was recalibrated and returned to service. No further action is re- quired.
$ \begin{array}{c} 1 \\ 1 \\ 1 \\ 1 \\ 2 \\ 1 \\ 1 \\ 2 \\ 1 \\ 3 \\ 1 \\ 4 \\ 7 \\ 8 \\ 1 \\ 6 \\ 7 \\ 8 \\ 1 \\ 7 \\ 8 \\ 1 \\ 6 \\ 7 \\ 8 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1$	Instrument drift caused the pressure transmitter to be out of calibration. The Itransmitter was recalibrated and returned to service. No further action is re- quired.
$ \begin{array}{c} 1 \\ 1 \\ 1 \\ 1 \\ 2 \\ 1 \\ 2 \\ 1 \\ 3 \\ 1 \\ 7 \\ 8 \\ 1 \\ 7 \\ 8 \\ 1 \\ 7 \\ 8 \\ 1 \\ 7 \\ 8 \\ 1 \\ 7 \\ 8 \\ 1 \\ 9 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1 \\ 1$	Instrument drift caused the pressure transmitter to be out of calibration. The Itransmitter was recalibrated and returned to service. No further action is re- quired.

11 HU FUHIVE340 (7.77) LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) (1)CONTROL BLOCK: 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 57 K N P 0 0 1(2)LICENSE NUMBER LICENSEE CODE CON'T 3 0 5 7 0 5 0 3 7 9 3 0 5 1 1 ER 68 69 EVENT DATE 74 75 REPORT DATE REPORT L 6 0 5 0 0 0 0 1 SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During full power operation, installation of the Boric Acid Heat Tracing design 0 2 one change was in progress when Atrain of heat tracing on the piping between the BA trans-0 3 fer pumps common discharge header and the BA filter was discovered to be inoperable. 0 4 The other train of heat tracing was This placed the facility under LCO TS 3.2.b.5. 0.5 There was no effect on plant operation or public safety. operable. 0 6 0 7 3 80 SYSTEM COMP VALVE CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBCODE CODE CODE Ε Т R U (14) (16)S E (12 A (13) E 18 10 REVISION SEQUENTIAL OCCURRENCE REPORT REPORT NO. CODE TYPE NO. EVENT YEAR LER/RO 0 3 0 I. 0 0 8 (17) REPORT 9 NUMBER 30 28 ATTACHMENT SUBMITTED NPRD-4 PRIME COMP. COMPONENT ACTION FUTURE TAKEN ACTION SHUTDOWN METHOD EFFECT ON PLANT HOURS (22) FORM SUB. MANUFACTUREF SUPPLIER C121618 N 23 Y 24 N (25) A 18 Z 19 Z. (20 0 0 0 0 70 1 Z (21 (26) 44 4 34 35 33 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) An open circuited connector caused the heat tracing train to be inoperable. System 1 0 lineup was changed to bypass the effected piping using existing lines. The effected 1 1 section was then flushed and the failed heat tracing train was repaired, by re-1 2 placing the failed connector, and returned to service. 1 3 4 80 9 Я METHOD OF FACILITY OTHER STATUS DISCOVERY DESCRIPTION (32) DISCOVERY % POWER A 31 Design Change Installation 1 0 0 (29 E (28) NA 5 80 44 46 12 8 ACTIVITY CONTENT LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35) OF RELEASE RELEASED Z 33 Z 34 NA NA 6 80 44 10 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE LZI (38) NA 0 0 0 7 80 11 12 PERSONNEL INJURIES 13 DESCRIPTION (41) NUMBER 0 0 (40) NA З 01 80 11 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION Z (42) NA 9 80 10 NRC USE ONLY PUBLICITY ISSUED DESCRIPTION 45 917-92 0 68 69 80 10 (414) 433-1329 049 G. H. Ruiter PHONE: NAME OF PREPARER -