	ATORY INFORMATION DISTRIBUTION N FOR INCOMING MATERIAL	SYSTEM (RIDS) 50-305
REC: KEPPLER J G NRC	ORG: JAMES E W WI PUB SVC	DOCDATE: 02/10/78 DATE RCVD: 02/14/7
DOCTYPE: LETTER SUBJECT: LICENSEE EVENT REP SERVICE WATER PUMP:	T. NO. 50-305/78-003/03L-0 CONC	COPIES RECEIVED LTR 1 ENCL 1 CERNING ONE OF FOUR
PLANT NAME: KEWAUNE	E	REVIEWER INITIAL: XRL DISTRIBUTOR INITIAL:
****	DISTRIBUTION OF THIS MATERIAL I	[S AS FOLLOWS ****************
	F ALL MATERIAL TO I&E - 1 COPY ALL MATERIAL	
INCIDENT REPORT: (DISTRIBUTION C		
FOR ACTION:	BRANCH CHIEF STHWENCER ** W/4 EN	NC
INTERNAL:	REG_EILE**W/ENE I & E**W/2 ENCL SCHROEDER/IPPOLITO**W/ENCL NOVAK/CHECK**W/ENCL KNIGHT**W/ENCL HANAUER**W/ENCL EISENHUT**W/ENCL SHAO**W/ENCL KREGER/J. COLLINS**W/ENCL L. CROCKER**W/ENCL	NRC PDR**W/ENCL MIPC**W/3 ENCL HOUSTON**W/ENCL GRIMES**W/ENCL BUTLER**W/ENCL TEDESCO**W/ENCL BAER**W/ENCL VOLLMER/BUNCH**W/ENCL ROSA**W/ENCL K SEYFRIT/IE**W/ENCL
EXTERNAL:	LPDR'S KEWAUNEE, WI**W/ENCL TIC**W/ENCL NSIC**W/ENCL ACRS CAT B**W/16 ENCL	COPIES NOT SUBMITTED PER REGULATORY GUIDE 10.1

DISTRIBUTION: LTR 46 ENCL 46 SIZE: 1P+1P

780460250 Ao 4 CONTROL NBR:

\*\*\*

THE END

\*\*\*\*\*

WISCONSIN PUBLIC SERVICE CORPORATION



78-003 DACS 09

P.O. Box 1200, Green Bay, Wisconsin 54305

February 10, 1978

Mr. J. G. Keppler, Regional Director Offica of Inspection & Enforcement Region III U. S. Nuclear Regulatory Commission 799 Roosavelt Road Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305 **Operating License DPR-43** Reportable Occurrence LER 78-003/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence LER 76-003/03L-0 is being submitted.

Very truly yours,

E. W. James Senior Vice Precident Power Supply & Engineering

88

Attach.

cc - Dir, Office of Inspection & Enforcement US NRC, Wnshington, D. C. 20555 Dir, Office of Mgt Info & Program Control / US NRC. Washington, D. C. 20555

1002/5 780460250

NHC FUH (7-77)	LICENSEE EVENT REPORT
2 <sup>-</sup>	CONTROL BLOCK:
0 1 7 8	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$
CON'T	REPORT L 6 0 5 0 0 0 3 0 5 7 0 1 1 2 7 8 8 0 2 1 0 7 8 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9
02	During full power operation, one of four service water (SW) pumps failed to start.
0.3	This placed the facility under LCO TS 3.3.d.2.A. The SW pump was returned to service
04	in two hours. Since only two SW pumps are required to operate during accident con-
0 5	ditions and three pumps were operating, there was no effect on plant operation or
06	public safety.
07	
08 78	SYSTEM CAUSE CAUSE COMP. VALVE
09 78	$\begin{array}{cccccc} \hline CODE & CODE & SUBCODE & COMPONENT CODE & SUBCODE & S$
	17     REPORT     7     8      0     0     3      NO.
- ·	NUMBER $21$ $22$ $23$ $24$ $26$ $27$ $28$ $29$ $30$ $31$ $32$ ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT METHOD HOURS (22) ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER $23$ $33$ $33$ $34$ $35$ $20$ $27$ $28$ $29$ $30$ $31$ $31$ $32$ ACTION FUTURE ON PLANT METHOD HOURS (22) ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER $23$ $33$ $34$ $35$ $20$ $21$ $20$ $2$ $21$ $0$ $0$ $0$ $0$ $0$ $0$ $1$ $1$ $23$ $24$ $43$ $25$ $1$ $1$ $7$ $5$ $26$ $37$ $40$ $41$ $23$ $42$ $43$ $25$ $44$ $47$ $44$ $47$
10	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)   The SW pump failed to start due to a failed XY relay in its circuit breaker.
11	The circuit breaker was replaced with a spare breaker and the SW pump was returned
12	to service. The XY relay was replaced in the defective circuit breaker.
13	
14 7 8	9 FACILITY OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32)
$\begin{bmatrix} 1 & 5 \\ 7 & 8 \end{bmatrix}$	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $
	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE   9 10 11 44   45 80
17	NUMBER TYPE DESCRIPTION (39)
7 8	9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
18 7 8	
19	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION 2 (42) NA 80
, °	PUBLICITY NRC USE ONLY
2 0 7 8	
	NAME OF PREPARER G. H. Ruiter PHONE: (414) 433-1329 &

D. Lankan

## WISCONSIN PUBLIC SERVICE CORPORATION



P.O. Box 1200, Green Bay, Wisconsin 54305

ile copy

AD 4

FEB 1 3 1978

February 10, 1978

Mr. J. G. Keppler, Regional DirectorOffice of Inspection & EnforcementRegion 1IIU. S. Nuclear Regulatory Commission799 Roosevelt RoadGlen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305 Operating License DPR-43 Reportable Occurrence LER 78-003/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence LER 78-003/03L-0 is being submitted.

Very truly yours,

E. W. James

Senior Vice President Power Supply & Engineering

sa

Attach.

cc - Dir, Office of Inspection & Enforcement US NRC, Washington, D. C. 20555 Dir, Office of Mgt Info & Program Control US NRC, Washington, D. C. 20555

•	CONTROL BLOCK:
0 1	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$
CON'T	REPORT L 6 0 5 0 0 0 3 0 5 7 0 1 1 2 7 8 8 0 2 1 0 7 8 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02	During full power operation, one of four service water (SW) pumps failed to start.
03	This placed the facility under LCO TS 3.3.d.2.A. The SW pump was returned to service
04	in two hours. Since only two SW pumps are required to operate during accident con-
0 5	ditions and three pumps were operating, there was no effect on plant operation or
06	public safety.
0 7	
08 78	SYSTEM CAUSE CAUSE COMP. VALVE
09 78	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $
	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
10	The SW pump failed to start due to a failed XY relay in its circuit breaker.
11	The circuit breaker was replaced with a spare breaker and the SW pump was returned
12	to service. The XY relay was replaced in the defective circuit breaker.
13	
	9 FACILITY DISCOVERY DESCRIPTION (32)
15 78	$ \underbrace{E}_{9} \underbrace{28}_{10} \underbrace{1}_{12} \underbrace{0}_{12} \underbrace{12}_{13} \underbrace{13}_{44} \underbrace{A}_{45} \underbrace{46}_{46} \underbrace{10}_{46} \underbrace{10}_{12} \underbrace{10}_{12} \underbrace{13}_{13} \underbrace{10}_{44} \underbrace{10}_{45} \underbrace{10}_{46} \underbrace{10}_{46} \underbrace{10}_{12} $
	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE   9 10 11 44   45 45 80
17	NUMBER     TYPE     DESCRIPTION (39)       0     0     (37)     Z     (38)     NA
7 8	9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
1 8 7 8	
19 7 <b>8</b>	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION 2 (42) NA 9 10 80 NDO UNE ON M
20	PUBLICITY NRC USE ONLY
	NAME OF PREPARER G. H. Ruiter PHONE: (414) 433-1329

WISCONSIN PUBLIC SERVICE CORPORATION



FILE COPY

P.O. Box 1200, Green Bay, Wisconsin 54305

February 10, 1978

2

Mr. J. G. Keppler, Regional Director Office of Inspection & Enforcement Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr. Keppler:

Docket 50-305 Operating License DPR-43 Reportable Occurrence LER 78-003/03L-0

In accordance with the requirements of Technical Specifications, Section 6.9, the attached Licensee Event Report for reportable occurrence LER 78-003/03L-0 is being submitted.

Very truly yours,

E. W. James Senior Vice President Power Supply & Engineering

sa

Attach.

cc - Dir, Office of Inspection & Enforcement/ US NRC, Washington, D. C. 20555 Dir, Office of Mgt Info & Program Control US NRC, Washington, D. C. 20555

	LICENSEE EVENT REPORT
	CONTROL BLOCK:
01	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$
CON'T	REPORT SOURCE L 6 0 5 0 0 0 3 0 5 0 0 1 2 1 0 7 8 9 GO 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02	During full power operation, one of four service water (SW) pumps failed to start.
03	This placed the facility under LCO TS 3.3.d.2.A. The SW pump was returned to service
04	in two hours. Since only two SW pumps are required to operate during accident con-
05	ditions and three pumps were operating, there was no effect on plant operation or
06	public safety.
07	L
08 78	SYSTEM CAUSE CAUSE COMP. VALVE
09 78	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $
	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
	$ \begin{array}{c} \begin{array}{c} \text{ACTION} & \text{FUTURE} \\ \text{TAKEN} & \text{ACTION} \\ \text{ACTION} \end{array} \\ \begin{array}{c} \text{ON PLANT} \\ \text{ON PLANT} \end{array} \\ \begin{array}{c} \text{METHOD} \\ \text{METHOD} \end{array} \\ \begin{array}{c} \text{HOURS} \end{array} \\ \begin{array}{c} (22) \\ \text{SUBMITTED} \end{array} \\ \begin{array}{c} \text{SUBMITTED} \\ \text{SUBMITTED} \end{array} \\ \begin{array}{c} \text{FORM SUB} \\ \text{SUBMITTED} \end{array} \\ \begin{array}{c} \text{SUPPLIER} \\ \text{SUPPLIER} \end{array} \\ \begin{array}{c} \text{MANUFACTURER} \\ \text{M} \end{array} \\ \begin{array}{c} 1 \\ 7 \\ 5 \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} 1 \\ 7 \\ 5 \end{array} \\ \begin{array}{c} \text{SUPPLIER} \\ \text{M} \end{array} \\ \begin{array}{c} 1 \\ 7 \\ 42 \end{array} \\ \begin{array}{c} \text{SUPPLIER} \\ \text{M} \end{array} \\ \begin{array}{c} \text{MANUFACTURER} \\ \begin{array}{c} \text{MANUFACTURER} \\ \text{M} \end{array} \\ \begin{array}{c} 1 \\ 7 \\ 5 \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} 1 \\ 7 \\ 40 \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} 1 \\ 42 \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} 1 \\ 1 \\ 44 \end{array} \\ \begin{array}{c} \text{MANUFACTURER} \\ \begin{array}{c} \text{MANUFACTURER} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} 1 \\ 7 \\ 5 \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} 1 \\ 7 \\ 40 \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} 1 \\ 1 \\ 1 \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} 1 \\ 1 \\ 1 \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} 1 \\ 1 \\ 1 \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} 1 \\ 1 \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} 1 \\ 1 \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \end{array} \\ \end{array} $ \\ \begin{array}{c} \text{M} \end{array} \\ \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \end{array} \\ \end{array}  \\ \begin{array}{c} \text{M} \end{array} \\ \end{array} \\ \end{array}  \\ \begin{array}{c} \text{M} \end{array} \\ \end{array} \\ \end{array} \\ \begin{array}{c} \text{M} \end{array} \\ \end{array} \\ \end{array} \\ \end{array}  \\ \begin{array}{c} \text{M} \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \end{array}  \\ \begin{array}{c} \text{M} \end{array} \\ \end{array} \\ \end{array} \\ \end{array} \\ \end{array}  \\ \end{array} \\ \end{array} \\ \end{array} \\ \end{array}  \\ \end{array} \\ \end{array}
110	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)   The SW pump failed to start due to a failed XY relay in its circuit breaker.
	The circuit breaker was replaced with a spare breaker and the SW pump was returned
1 2	to service. The XY relay was replaced in the defective circuit breaker.
13	
$\begin{bmatrix} 1 \\ 4 \\ 7 \\ 8 \end{bmatrix}$	y
15	FACILITY % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)   E (28) 1 0 0 (29) NA A (31) Pump Start Failure Observed (32)
1 6 <sup>R</sup>	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 NA
7 8	PERSONNEL EXPOSURES     NUMBER     TYPE     DESCRIPTION (39)       0     0     0     (37)     Z     (38)     NA
7 8	9 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
1 8 7 8	0 0 40 NA   9 11 12 80   LOSS OF OR DAMAGE TO FACILITY TYPE 43 80
19 7 8	Z 42 NA 9 10 80
20	
, 0	NAME OF PREPARER G. H. Ruiter PHONE: (414) 433-1329

-----