

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8003180564 DOC. DATE: 80/03/10<sup>10</sup> NOTARIZED: NO DOCKET #  
 FACIL: 50-305 Kewaunee Nuclear Power Plant, Wisconsin Public Service 05000305  
 AUTH. NAME: AUTHOR AFFILIATION  
 RUITER, G. H. Wisconsin Public Service Corp.  
 RECIP. NAME: RECIPIENT AFFILIATION  
 Region 3, Chicago, Office of the Director

SUBJECT: LER 80-008/03L-0: on 800211, during normal full operation,  
 w/one of three charging pumps out of svc, one of remaining  
 pumps failed when switched from start to auto position.  
 Caused by sticking seal-in contact in pump circuit breaker.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1  
 TITLE: Incident Reports

NOTES: I & E - 3 CYS ALL MATL.

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	05 BC <u>ORB #1</u>	4	4			
INTERNAL:	<u>01 REG FILE</u>	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	22 REAC SAFT BR	1	1
	23 ENGR BR	1	1	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 AD/SITE ANAL	1	1
	27 OPERA LIC BR	1	1	28 ACIDENT ANLYS	1	1
	29 AUX SYS BR	1	1	AD/GRP=DOR	1	1
	AEOD	1	1	DOUG MAY=TERA	1	1
	HANAUER, S.	1	1	IRELAND, R.	3	3
	JORDAN, E./IE	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

MAR 20 1980

AC/F

TOTAL NUMBER OF COPIES REQUIRED: LTTR

55

52 ENCL

55

52

## LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 W I K N P 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE 57 CAT 58

CON'T

REPORT  
SOURCE

L 6 0 5 0 0 0 3 0 5 7 0 2 1 1 8 0 8 0 3 0 7 8 0 9  
 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100  
 DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

During normal full power operation, with one of three charging pumps out of service

for scheduled maintenance, one of the remaining charging pumps failed to remain

running when its control switch was returned to AUTO from START position. This

placed the facility under LCO TS 3.2.c.1. One charging pump has sufficient capacity

to provide makeup water for the largest allowable RCS leakage. The charging pump

was returned to service in less than one hour. No effect on plant operation or

public safety.

SYSTEM  
CODECAUSE  
CODECAUSE  
SUBCODECOMPONENT  
CODECOMP.  
SUBCODEVALVE  
SUBCODE

C J 11 E 12 X 13 C K T B R K 14 A 15 Z 16  
 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

LER/RO  
REPORT  
NUMBER

EVENT YEAR

SEQUENTIAL  
REPORT NO.OCCURRENCE  
CODEREPORT  
TYPEREVISION  
NO.

ACTION TAKEN

FUTURE ACTION

EFFECT  
ON PLANTSHUTDOWN  
METHOD

HOURS

ATTACHMENT  
SUBMITTEDNPRD-4  
FORM SUB.PRIME COMP.  
SUPPLIERCOMPONENT  
MANUFACTURER

B 18 Z 19 Z 20 Z 21 0 0 0 0 22 N 23 Y 24 N 25 G 0 8 0 26  
 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The charging pump ckt. bkr. would not stay closed due to a sticking seal-in

contact. The contact was cleaned and exercised and the bkr. tested satisfactory.

The charging pump was returned to service. No future corrective action necessary.

FACILITY  
STATUS

% POWER

OTHER STATUS

METHOD OF  
DISCOVERY

DISCOVERY DESCRIPTION

ACTIVITY

CONTENT

RELEASED OF RELEASE

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

PERSONNEL EXPOSURES  
NUMBER

TYPE

DESCRIPTION

PERSONNEL INJURIES  
NUMBER

TYPE

DESCRIPTION

LOSS OF OR DAMAGE TO FACILITY  
TYPE

DESCRIPTION

PUBLICITY  
ISSUED

DESCRIPTION

NRC USE ONLY

NAME OF PREPARER

G. H. Ruiter

PHONE:

(414-388-2560)

8003180564