REGULATORY INFOMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8006200469 DOC,DATE: 80/06/18 NOTARIZED: NO DOCKET #
FACIL:50-305 Kewaunee Nuclear Power Plant, Wisconsin Public Servic 05000305

AUTH-NAME AUTHOR AFFILIATION

NALEPKA, D.S. Wisconsin Public Service Corp.

RECIP.NAME RECIPIENT AFFILIATION

Region 3, Chicago, Office of the Director

SUBJECT: LER 80-022/03L+0:on 800519, during refueling outage, pressurizer pressure transmitter found out of calibr. Caused by instrument drift. Transmitter recalibr.

NOTES: INE - 3 CYS ALL MATE.

1001001		tinks take pinging o	هر خاکن هست استان طبقه خان		Committee and the second states of the second secon		
	RECIPIENT		COPIE	S	RECIPIENT	COPI	(ES
	ID CODE/NAME		LTTR		ID CODE/NAME	LTTR	ENCL
ACTION:	BC VARGA, S.	05	4	4	•		
INTERNAL:	A/D RAD PROT		1	1	A/D REACT SYS	1	1
	A/D TECHNOLOG	Υ	1	1	AEOD	10	10
	AUX SYS BR		1	1	CHEM ENG BR	1	1
	CONT SYS BR		1	1	EISENHUT, D.	1	1
	EMERG PREP		1	1	EQUIP QUAL BR	1	1
	HANAUER, S.		1	1	I&C SYS BR	. 1	1
		09	2	2	JORDAN, E./IE	1	1
	MPA	1 1	3	3	NRC PDR 02	1	1
	OP EX EVAL BR		3	3	OR ASSESS BR	1	1
	PPAS		1	1	QA BR	1	1
		01	1	1	SIT ANAL BR	1	1
	SYS INTERAC B		1	1	TERA: DOUG MAY	1	1
EXTERNAL:	ACRS		16	16	LPDR 03	1	1
		04	1.	1			

LICENSEE EVENT REPORT

	CONTROL BLOCK: PLEASE PRINT OR	TYPE A EQUIRED INFORMATION)
0 1	W I K N P 1 2 0 0 - 0 0 0 0 - 0 0	3 4 1 1 1 1 1 (4) 57 CAT 58 (5)
CON'T	REPORT L 6 0 5 0 0 0 3 0 5 7 0 5 1 9 8 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE	0 8 0 6 1 8 8 0 9 74 REPORT DATE 80
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During refueling outage, surveillance testing indica	ted that one of three pres-
0 3	surizer pressure transmitters was out of calibration	such that its lo-pressure
0 4	safety injection would have occurred 1.65% lower tha	n the Tech. Spec. specified
0 5	value. This placed the facility under reporting req	uirement of Tech. Spec. 3.5a.
0 6	The remaining two channels were operable within spec	ified limits and would have
0 7	initiated safety injection as required. There was n	o effect on plant operation
	or public safety.	·
0 8	9 SYSTEM CAUSE CAUSE COMPONENT CODE CODE SUBCODE COMPONENT CODE	COMP. VALVE SUBCODE SUBCODE
0 9	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	DEVICION
	SEQUENTIAL REPORT NO. 17 REPORT NUMBER 8 0 0 2 2 0 3 28 28	TYPE NO. 0 31 32
	ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT SUBMITTED E 18 Z 19 Z 20 Z 21 J 0 0 0 0 0 N (23) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)	NPRD-4 PRIME COMP. COMPONENT MANUFACTURER N 24 N 25 F 1 8 0 26 42 43 43 44 47
10	Instrument drift of the Foxboro pressure transmitter of	aused it to be out of calibra-
11	tion. The transmitter was recalibrated with no indica	tion of other problems. No.
1 2	further action required.	
1 3		
1 4		
7 8	STATUS % POWER OTHER STATUS (30) ME THOU OF DISCOVERY	DISCOVERY DESCRIPTION (32)
7 8	9 10 12 13 44 45 46	LOCATION OF RELEASE 36
1 6	RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z 33 Z 34 NA NA 45	ECCATION OF RELEASE
7 8	9 10 11 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)	
1 7	0 0 0 37 Z 38 NA	80
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41 0 0 0 40 NA	80
, 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION	800620046 9
1 9	Z (42) NA	80
	PUBLICITY 1SSUED DESCRIPTION (45) N (44) NA	NRC USE ONLY
2 0	9 10 D. S. Malanka	68 69 80 8 PHONE: (414) 388-2560
	NAME OF DEPARED D. S. Nalepka	