

Part 21 (PAR)

Event # 47015

<b>Rep Org:</b> AUTOMATIC VALVE CORPORATION	<b>Notification Date / Time:</b> 07/01/2011 15:56 (EDT)
<b>Supplier:</b> AUTOMATIC VALVE CORPORATION	<b>Event Date / Time:</b> 06/28/2011 07:00 (EDT)
	<b>Last Modification:</b> 07/01/2011
<b>Region:</b> 3	<b>Docket #:</b>
<b>City:</b> NOVI	<b>Agreement State:</b> No
<b>County:</b>	<b>License #:</b>
<b>State:</b> MI	
<b>NRC Notified by:</b> KEVIN ARMSTRONG	<b>Notifications:</b> CHRISTINE LIPA R3DO
<b>HQ Ops Officer:</b> JOE O'HARA	MARK FRANKE R2DO
<b>Emergency Class:</b> NON EMERGENCY	PART 21 GRP EMAIL
<b>10 CFR Section:</b>	
21.21 UNSPECIFIED PARAGRAPH	

SEAL FAILURE AND LEAKAGE ASSOCIATED WITH MODEL B5497-301 VALVES

The following was received via fax:

Automatic Valve Corporation made this report based upon its investigation and engineering evaluation of valve serial number 57056 which was leaking following an outage test stroke at McGuire Station. Automatic Valve Corporation determined that the cause of the leakage was seal failure as a result of the seal being displaced from its retaining groove. The displaced seal became trapped between the poppet face and valve seat inside the valve body. Automatic Valve Corporation reported that seal replacement combined with inspection; and testing would prevent additional failures.

Shearon Harris and McGuire utilize these types of valves. Automatic Valve Corporation has no reported failures of these valves at Shearon Harris.

\*\*\*\*\*

IE19  
NRR

**NRC Operations Center 301-816-5151 (FAX)****10 CFR PART 21 Notification:**

Automatic Valve Corporation  
41144 Vincenti Court, Novi MI 48375  
Contact: Kevin Armstrong, President, 248-474-6700 ext. 170

**Basic Component Model Numbers:**

B5497-301

**Nature of the Defect:**

Extrusion of internal seals creates seal displacement and leakage.

**Number and Location of Components:**

<u>Valve Model</u>	<u>Quantity</u>	<u>Customer</u>
B5497-301	20	RA Hiller

**Corrective Action to Be Taken:**

Please see attached report.



**Advice to Purchasers:**

Please see attached report. Automatic Valve will rebuild units as necessary.

**Date the Evaluation of the Defect was Complete: 06/28/2011**

AUTOMATIC VALVE	NUMBER: D7174-003	Page 1 of 8
TITLE: CORRECTIVE ACTION	LOCN: I:\WORD\DOCUMENT\D7174003.DOC	DATE: 10-21-1999
SUBJ: CORRECTIVE ACTION	TYPE: FORM	DEPT RESP: DQA
		REV: F-CN8020

REQUIREMENTS:

<b>NUMBER: 543</b>			
<b>Type of Problem:</b>	Part <u>B5497-301</u>	Procedure	Date: <u>06-09-2011</u>
<b>Who found Problem:</b>	Supplier	Distributor	X Customer
<b>Company:</b> Duke - McGuire Station	<b>Contact Name:</b> Ryan Priny		
<b>Address:</b> 12700 Hager's Ferry Road Huntersville, NC 28078-9340			
<b>1. Team Working on Problem:</b>	Leader: Kevin Armstrong	Members:	
Brian Bielat, Tom Troy, Todd Hutchins			
<b>2. Describe Problem (Initial Concern and Symptoms):</b>	Valve, serial number 57056, was noted to be leaking after an outage test stroke.		
<b>Contain Symptom (Action):</b>	All elastomeric components require replacement. Valve to be returned to customer in as originally shipped condition.		
Approved by: 	Title: <u>President</u>	Date: <u>7.1.11</u>	
<b>4. Root Cause/s of Problem:</b>	<b>10 CFR Part 21 Report Required: Yes</b>		
A 10 CFR 21is report required based on the statement made by plant staff on June 28 <sup>th</sup> :			
"when the 4-way for 2CF-26AB failed we drained the tank in a relatively short period of time and we actually started to drain the main nitrogen header the leak was so large. If this happens again during a feedwater isolation we would violate one of our requirements to maintain a minimum of 50 psig in the tank for a 24 hour period."			
The root cause of the valve leakage is seal failure.			
The seal on item 3, A5497-314, is displaced from its retaining groove. (See attached print Sheets 1and 3; photograph 1) This created a condition where the displaced seal was trapped between the poppet face and the valve seat inside the valve body. This creates a gap through which nitrogen passes directly between the inlet port and exhaust port. The exact size of this leak is dependent on several factors including volume and pressure of nitrogen available to force the piston (item 6, attached print sheet 1) into its fully stroked position. This piston, in turn, drives the unsealed seal back into the poppet groove, and creates an (imperfect) seal on the rolled edge or the face of the poppet. At normal operating pressure, above 265 psi, testing shows the displaced seal is forced back (imperfectly) into its retaining groove. The valve leaks but still functions. At lower pressures, the displaced seal will create a larger leak path.			
The seal failed due to compression set. It extruded and rolled over the wall of the poppet face (Photograph 2).Note that the extrusion only occurs on the end of poppet which is exposed to ambient pressure ( 344 psig) around the entire area of an unconstrained seal. The seal on the poppet face which mated to the valve body seat during in-service operation does not extrude. (Photograph 3).			
As the extrusion continues the seal begins to cut. The cut either creates a leak path, which is formed where the high pressure nitrogen can pass under the seal causing it to lift or the cut causes the seal to loose squeeze and high pressure differentials during shift create the lift. Automatic Valve has not been able to duplicate the displacement of an extruded seal.			
Other issues of note not directly related to the failure:			
FME was noted at disassembly of the vale (photograph 4). If the FME is taken into the valve through vent ports it would be expected to degrade lubrication. Degraded lubrication can be expected to both increase minimum operating pressures and slow movement of internal components. This will tend to increase the impact of the displaced seal.			
Plant staff indicate a low pressure requirement of 50 psig. The valve prints do not specify this pressure. No testing was done by Automatic Valve below 90 psig. Please see print sheet 2 of 3, Notes 5 and 10.			
The only other installation of these valves is at Shearon Harris. Automatic Valve has had no reports of failures from that plant. Three replacement units were purchased by Shearon Harris in October of 2008, after an original installation in 1999.			
Approved by: 	Title: <u>President</u>	Date: <u>7.1.11</u>	

AUTOMATIC VALVE	NUMBER: D7174-003	Page 2 of 8
TITLE: CORRECTIVE ACTION	LOCN: I:\WORD\DOCUMENT\D7174003.DOC	DATE: 10-21-1999
SUBJ: CORRECTIVE ACTION	TYPE: FORM	DEPT RESP: DQA
		REV: F-CN8020

**5. Corrective Action:**

Time required for compression set and extrusion to occur is unknown. The valve has, however, functioned without failure since 1999. Replacement of seals combined with additional inspection; testing and replacement protocols would prevent an in-service unit from developing the same failure mode.

Additional work is required to modify the seal such that compression set will not impact performance.

Approved by: *[Signature]* Title: *President* Date: *7.1.11*

**6. Implementation:**

Approved by: Title: Date:

**7. Corrective Action to System to Prevent Recurrence:**

Approved by: Title: Date:

**8. Verification (Describe):**

Approved by: Title: PRS Date:

**AUTOMATIC VALVE**  
**TITLE: CORRECTIVE ACTION**  
**SUBJ: CORRECTIVE ACTION**

**NUMBER: D7174-003**  
**LOCN: I:\WORD\DOCUMENT\D7174003.DOC**  
**TYPE: FORM**  
**DEPT RESP: DQA**

**Page 3 of 8**  
**DATE: 10-21-1999**  
**REV: F-CN8020**

B5497-301 Revision D, Print Sheet 1

REV	CHANGE	DATE	BY	CHK
A	ORIGINATED	02-25-93	KT	7002
E	RELEASED	03-19-93	KT	7020A
C	ADDED SHEET 3	05-19-93	KT	7702
E	REWORK ROOSTER	10-19-93	KT	776E

NOTE: THE NOTICES IN BUSHINGS MUST BE FACING TOWARDS PORTS AND TO THE REAR OF THE VALVE.

NOTE 9.1

NOTE 9.2

NOTE 9.3 & 9.4

SECTION A-A

SECTION B-B

1/4" NPTF PILOT PORT

12/32 DIA. (2) HLG. HOLES


BILL OF MATERIAL			
QTY	ITEM	DESC	UNIT
2	1	1/2" DIA. 1/8" THICK	PLATE
2	2	1/2" DIA. 1/8" THICK	PLATE
2	3	1/2" DIA. 1/8" THICK	PLATE
2	4	1/2" DIA. 1/8" THICK	PLATE
2	5	1/2" DIA. 1/8" THICK	PLATE
2	6	1/2" DIA. 1/8" THICK	PLATE
2	7	1/2" DIA. 1/8" THICK	PLATE
2	8	1/2" DIA. 1/8" THICK	PLATE
2	9	1/2" DIA. 1/8" THICK	PLATE
2	10	1/2" DIA. 1/8" THICK	PLATE
2	11	1/2" DIA. 1/8" THICK	PLATE
2	12	1/2" DIA. 1/8" THICK	PLATE
2	13	1/2" DIA. 1/8" THICK	PLATE
2	14	1/2" DIA. 1/8" THICK	PLATE
2	15	1/2" DIA. 1/8" THICK	PLATE
2	16	1/2" DIA. 1/8" THICK	PLATE
2	17	1/2" DIA. 1/8" THICK	PLATE
2	18	1/2" DIA. 1/8" THICK	PLATE
2	19	1/2" DIA. 1/8" THICK	PLATE
2	20	1/2" DIA. 1/8" THICK	PLATE
2	21	1/2" DIA. 1/8" THICK	PLATE
2	22	1/2" DIA. 1/8" THICK	PLATE
2	23	1/2" DIA. 1/8" THICK	PLATE
2	24	1/2" DIA. 1/8" THICK	PLATE
2	25	1/2" DIA. 1/8" THICK	PLATE
2	26	1/2" DIA. 1/8" THICK	PLATE
2	27	1/2" DIA. 1/8" THICK	PLATE
2	28	1/2" DIA. 1/8" THICK	PLATE
2	29	1/2" DIA. 1/8" THICK	PLATE
2	30	1/2" DIA. 1/8" THICK	PLATE
2	31	1/2" DIA. 1/8" THICK	PLATE
2	32	1/2" DIA. 1/8" THICK	PLATE
2	33	1/2" DIA. 1/8" THICK	PLATE
2	34	1/2" DIA. 1/8" THICK	PLATE
2	35	1/2" DIA. 1/8" THICK	PLATE
2	36	1/2" DIA. 1/8" THICK	PLATE
2	37	1/2" DIA. 1/8" THICK	PLATE

DATE	02-25-93	DRW	KT	CHECKED		<b>AUTOMATIC VALVE</b> VALVE, AIR/VAIR AND GAS/VAIR PERFORMANCE VALVE	SERIES: D71 DESCRIPTION: VALVE 5/2 FV 1/4" MODEL NUMBER: B5497-301	B5497-301 SHEET 1 OF 3
------	----------	-----	----	---------	--	---	--	---------------------------



AUTOMATIC VALVE	NUMBER: D7174-003	Page 5 of 8
TITLE: CORRECTIVE ACTION	LOCN: I:\WORD\DOCUMENT\D7174003.DOC	DATE: 10-21-1999
SUBJ: CORRECTIVE ACTION	TYPE: FORM	DEPT RESP: DQA
		REV: F-CN8020

B5491-307 Revision D, Print Sheet 3



AUTOMATIC VALVE  
TITLE: CORRECTIVE ACTION  
SUBJ: CORRECTIVE ACTION


NUMBER: D7174-003  
LOCN: I:\WORD\DOCUMENT\D7174003.DOC  
TYPE: FORM  
DEPT RESP: DQA

Page 6 of 8  
DATE: 10-21-1999  
REV: F-CN8020

Photograph 1: Displaced, as found, Seal




Photograph 2: Seal Extrusion



AUTOMATIC VALVE	NUMBER: D7174-003	Page 7 of 8
TITLE: CORRECTIVE ACTION	LOCN: I:\WORD\DOCUMENT\D7174003.DOC	DATE: 10-21-1999
SUBJ: CORRECTIVE ACTION	TYPE: FORM	DEPT RESP: DQA
		REV: F-CN8020

Photograph 3: Seal Face -Without Extrusion - Compressed Against Face In Service



AUTOMATIC VALVE	NUMBER: D7174-003	Page 8 of 8
TITLE: CORRECTIVE ACTION	LOCN: I:\WORD\DOCUMENT\D7174003.DOC	DATE: 10-21-1999
SUBJ: CORRECTIVE ACTION	TYPE: FORM	DEPT RESP: DQA
		REV: F-CN8020

Photograph 4: FME As Found Normally Closed Side, Inlet Face

