Scrams with Reactive Inspections 2007 - Present

| PUGRIM | ant scient of the science last | on Putticeonts | Brie Summer to complete |
|----------------------------|---|---|---|
| | TRIP FROM INTERMEDIATE RANGE | special inspection realition - in progress | ouPourP unbroations |
| ROBINSON 2 | 10/07/10 THE REACTOR TRIPPED WHEN A MOTOR FAULT OCCURRED ON A REACTOR COOLANT PUMP (RCP) CAUSING A SINGLE LOOP LOW FLOW TRIP. THE ROOT CAUSE OF THIS EVEN WAS INADEQUATE END WINDING BRACING ON THE "C" RCP. | SIT - ML103440401 - 2 Green Findings & 1 unresolved item (URI) ML110280299 - 1 Green Finding (URI) T | Three Green findings of very low safety significance were identified for: 1) Bypassing the feedwater isolation safety function for three hours and twenty minutes, a condition prohibited by Technical Specifications and procedural requirements. 2) The failure to correct a known equipment deficiency, which adversely affected the operators' ability to respond to reactor trip transients. Specifically, the turbine building lubrication oil area fire protection detectors were known to actuate the turbine building lube oil deluge system during a non-fire event when the feedwater heater relief valves lift after a scram. 3) The failure to perform vendor recommended inspections of the reactor coolant nump motors |
| BRAIDWOOD 1 BRAIDWOOD 2 | 08/16/10 BRAIDWOOD 1 - THE REACTOR TRIPPED FOLLOWING A TURBINE GENERATOR TRIP. THE TURBINE TRIPPED DUE TO LOSS OF CONDENSE VACUUM CAUSED BY THE LOSS OF TH- ELECTRICAL BUS SUPPLYING THE CIRC WATER PUMPS. THE BUS WAS LOST WHEN WATER OVERFLOWED FROM THE AFW STANDPIPES. BRAIDWOOD 2 - THE REACTOR TRIPPED FOLLOWING A TRIP OF THE TURBINE GENERATOR. THE TURBINE GENERATOR TRIPPED DUE TO A GENERATOR LOCKOUT RELAY ACTUATION. THE LOCKOUT RELAY ACTUATION WAS CAUSED BY A PHASI TO-GROUND FAULT IN THE ISOLATED PHASE (ISOPHASE) BUS DUCT. | SIT - ML103190505 - 4 Green Findings | Four Green findings of very low safety significance were identified for: 1) The failure to establish adequate inspect-and-clean controls for the forebay. Specifically, the operability margin of one train of the essential service water system decreased below pre-established limiting conditions due to fouling. 2) The failure to establish measures for the selection and review of equipment suitability. Fuses were replaced with a lower ampere rating than specified. 3) The failure to correct a condition that resulted in water being discharged to the turbine building floor during the reject of condensate from the condenser hotwell. Specifically, water had been observed overflowing to the turbine building floor in multiple instances in the past during hotwell condensate reject. However, the licensee did not implement corrective actions to correct this condition or evaluate its impact on plant equipment as required by the licensee's corrective action program. The water discharged from the condensate hotwell reject caused a reactor trip on the other unit. 4) The inadequate evaluation of operating experience. Specifically, the evaluation of an event at another plant that resulted in dislodged building material and a loss of off-site power was not properly addressed. During the dual unit trip, reactor building flashing was dislodged during a steam release and was found on power lines and in the vicinity of the off- site power supplies. |
| SURRY 1 | 06/08/10 THE REACTOR TRIPPED ON STEAM FLOW/FEED FLOW MISMATCH. THE EVENT WAS THE RESULT OF LOSS OF J VITAL 120VAC BUS. THE BUS LOSS WA CAUSED BY THE FAILURE OF AN UNINTERUPTIBLE POWER SUPPLY (UPS) INVERTER WHICH OCCURRED WHILE THE BUS'S ALTERNATE POWER SOURCE WAS OUT OF SERVICE FOR MAINT. | SIT- ML102560333 - 1 Green Finding A S | A Green finding of very low safety significance was identified for the failure to identify and correct degraded nuclear Instrument resistance capacitor filters. |

| B. A. T. HARPE | EREM | of the sconcase been the | a autoreans | Sete Sufferen Set and | |
|----------------|----------|---|---|---|--|
| ROBINSON 2 | 03/28/10 | LOSS OF 4KV BUS 5 DUE TO A FIRE RESULTED IN LOSS OF REACTOR COOLANT SYSTEM PUMP B AND A SUBSEQUENT REACTOR AND TURBINE TRIP. THE INITIAL FAULT WAS CAUSED BY THE FAILURE OF A FEEDER CABLE SUPPLYING 4KV BUS 5. | Augmented Inspection Team (AIT) - ML101830101 - 14 URIs ML103160382 - 2 Apparent Violations (AVs) & 3 Green Findings ML102810633 - 1 Green Finding, 2 AV (1 Traditional Enforcement) ML103620095 - 1 AV ML110310409 - 2 White Findings (EA-10-257) ML103410289 - 1 White Finding & Severity Level (SL) III (EA-10-205) ML111090365 - 95001 (Performance Indicator (PI) - Scrams) Supplemental inspections required. Currently in Degraded Cornerstone Column of Action Matrix | On March 28, 2010, an event occurred at H. B. Robinson that involved a reactor trip, an electrical fault, a fire, a partial loss of offsite power, a safety injection actuation, a temporary concurrent loss of seal injection and thermal barrier heat exchanger cooling to reactor coolant pump seals, and operator errors. A 95001 supplemental inspection was performed to follow-up on these risk-significant issues (performance indicator scrams) to provide assurance that the root causes and contributing causes were understood, extent of condition and extent of cause were identified, and that the licensee's corrective actions were sufficient to address the root and contributing causes and prevent recurrence. Three White notice of violations were issued for low to moderate safety significance violations associated with: (1a) The failure to promptly correct a condition adverse to quality involving the failure of an Emergency Diesel Generator output breaker; and (1b) The failure to ensure the Emergency Diesel Generator remained operable as required by Technical Specifications. 2) Multiple and significant failures to adhere to procedures requirements 3) Failures to adequately design and implement operator training based on learning objectives A 95002 supplemental inspection will be performed to follow-up on these risk-significant issues to provide assurance that the root causes and contributing causes where understood, extent of cause were identified, and that the licensee's corrective actions were sufficient to address the root and contributing causes and prevent recurrence. In addition to independently determine if safety culture components caused or significantly contributed to the individual and collective (multiple white inputs) risk-significant performance issues. A Severity Level III traditional enforcement (TE) violation was issued for the submission of materially inaccurate information. | |
| | | | | Four Green findings of very low safety significance were identified for: 1) The failure to follow the site's corrective action program procedure. Specifically, a degraded control power condition for an electrical breaker was not identified and evaluated appropriately, which led to a fire and a reactor trip. 2) The failure to have adequate work orders to properly configure and post maintenance test the volume control tank level comparator module. This resulted in the failure of the charging pump suction to automatically transfer from the volume control tank to the refueling water storage tank when the auto transfer volume control tank low level setpoint was reached. 3) The failure to appropriately install electrical cables. This eventually led to a fire and a reactor trip. 4) The failure to correctly model the effects associated with a loss of electric power in the simulator (e.g., loss of component cooling water to the reactor coolant pump seals). The simulator is used to train operators and administer operating tests. | |

| paart and CALVERT CLIFFS 1 CALVERT CLIFFS 2 | 02/18/10 | ORAC GROWN CLIFFS 1 - THE REACTOR TRIPPED DUE TO THE LOSS OF AN RCP FOLLOWING A PARTIAL LOSS OF OFFSITE POWER. THE RCP WAS LOST DUE TO AN ELECTRICAL MALFUNCTION. THE FAULT WAS CAUSED BY A SHORT DUE TO WATER INTRUSION INTO THE RELAY PROTECTION CIRCUITRY CUBICLE. CALVERT CLIFFS 2 - THE REACTOR TRIPPED ON LOW FLOW FOLLOWING A PARTIAL LOSS OF AN RCP WAS CAUSED BY AN ELECTRICAL MALFUNCTION DUE TO FAILURE OF A GROUND FAULT RELAY. | Pythic Regions SIT - ML101650723 - 1 AV & 4 Green Findings ML102150484 - 1 White Finding (EA-10-080) ML111190104 - 95001 | A White notice of violation was issued for the failure to develop and implement scheduled preventative maintenance for the Agast time delay relays. Specifically, the relays were not replaced after the 10 year service life as recommended by the vendor nor did the licensee establish a performance monitoring program to monitor the relays for degredation. The failure of the relay resulted in inoperability of the Emergency Diesel Generator and loss of the power to a safeguards bus. A 95001 supplemental inspection was performed to follow-up on this risk-significant issue to provide assurance that the root causes and contributing causes were understood, extent of condition and extent of cause were identified, and that the licensee's corrective actions were sufficient to address the root and contributing causes and prevent recurrence. Four Green findings of very low safety significance were identified for: 1) The failure to implement effective corrective actions to address auxiliary building roof leakage problems occuring over a 7 year period that ultimately resulted in switchgear grounds, a reactor trip, and the loss of several safety related systems. 2) The failure to translate the design calculations of phase overcurrent relays into the actual relay settings. The overcurrent relays protect the unit service transformer against electrical faults and the as-found relay setting could potentially cause the breakers to fail prior to tripping open. 3) The failure to evaluate and correct relay diss ticking or binding issues. This degraded condition can adversely impact the function of the Emergency Diesel Generators and the electrical distribution protection scheme. 4) The failure to exablish adequate procedures for restoration of Ichemical and Volume Control System letdown flow. Deficient operating instructions prevented timely restoration of previous following the initial transient and led to pressurizer level exceeding the Technical Specification limit for pressurizer level. |
|---|----------|--|---|---|
| CALVERT CLIFFS 1 | 02/18/10 | CALVERT CLIFFS 1 - THE REACTOR TRIPPED DUE TO THE LOSS OF AN RCP FOLLOWING A PARTIAL LOSS OF OFFSITE POWER. THE RCP WAS LOST DUE TO AN ELECTRICAL MALFUNCTION. THE FAULT WAS CAUSED BY A SHORT DUE TO WATER INTRUSION INTO THE RELAY PROTECTION CIRCUITRY CUBICLE. | SIT - ML101650723 - 4 Green Findings | |

| | | , , | | | 1.exe |
|--------------|---|---|--|---|--|
| PLANTARA | te gran ont | ave Destriction | Pastereonts | Sie sumer test | 9 9 9 |
| WOLF CREEK | 08/19/09 THE REACTOR TRIPPED FOL TURBINE TRIP AND MOMEI OF OFFSITE POWER. THE CA THE TRIP WAS LOSS OF OFF POWER DUE TO A LIGHTNII | LOWING A SIT - ML100330574 - NTARY LOSS 05000482/2009007-0 AUSE OF 05000482/2009007-0 SITE NG STRIKE. | 7 Green Findings & 2 URIs 8 - Open 8 - Open 1) The failure to recogn to identify and enter per corrective action progra 2) The failure to monito and feedwater isolation selectable alarm for the 3) The failure to perforn system. Several throug 4) The failure to proper corrosion and loss of of 5) The failure to providé essential service water This resulted in delaying 6) The failure to porvidé service water system. 7) The failure to establi: power resulted in fire p watches were not initia | very low safety significance were identified for: ize the adverse conditions related to their offsite power rrtinent switchyard operating experience and six occurre am. or and control steam generator water levels, which resul b. Contributing to the loss of level control was the disabil is steam generator level. m an operability evaluation for the impact of a pressure h wall leaks were observed due to significant internal co ly screen condition reports for the essential service wate fsite power induced system pressure transient. e adequate guidance to identify and address pitting, corr system. Chemistry control procedures did not contain qu g repairs until such degradations (pitting) had become th e adequate guidance to address the impact of a loss of o sh a fire watch in a timely manner following a fire troubl rotection trouble alarms which required the establishme ted until the following day. | system. Specifically, the licensee failed nces of loss of offsite power into their ted in an unanticipated turbine trip signal ng of a previously established operator transient on the essential service water rrosion. er system adverse conditions of internal rosion, and surface indications in the uality standards or acceptance criteria. Irough-wall leaks. ffsite power event on the essential e alarm. The complete loss of offsite ent of a compensatory fire watch. These |
| OYSTER CREEK | 07/12/09 THE REACTOR TRIPPED FOL TURBINE TRIP DUE TO LOSS POWER CAUSED BY LIGHTN STRIKES. | LOWING A SIT - ML092710122, 2 5 OF OFFSITE ML101200165 - No Fi IING | Green Findings & 1 URI ndings (URI) 2) Not identifying and c resulted in emergency 2) Allowing foreign mat level indication and Isol | ery low safety significance were identified for: orrecting problems with the operation of the Generator diesel generator inoperability. erial to enter the Isolation Condenser level instrumental ation Condenser unavailability. | Breaker Close relay contacts, which tion piping. This resulted in erratic water |
| COLUMBIA | 05/08/09 THE REACTOR WAS MANU/ TRIPPED DUE TO THE LOSS MAIN GENERATOR SEAL OI THE SEAL OIL FILTER BECAN CLOGGED DURING TESTING OIL PRESSURE COULD NOT RESTORED. | ALLY SIT - ML093280158 - 2 OF THE L SYSTEM. JE 5 AND SEAL BE | 2 Green Findings 2 Green Findings of v 1) The failure to correct feedwater pumps. The to an erroneous design The new reactor feedw resulting in improper fe 2) A failure to include to the licensee removed to considering operating e | rery low safety significance were identified for: ly implement plant design changes to the digital electron new digital electrohydraulic control system was installed calculation. This ultimately resulted in exceeding the co ater level control system was installed with improper su edwater pump control. orque verifications of rigid and flexible bus connections a orque verification and potential testing from their preve xperience. This omission most likely contributed to the | -hydraulic control system and the reactor I with an incorrect pressure setpoint due oldown safety limit of 100°F per hour. ction pressure setpoints and trip delays and high potential testing. Specifically, ntive maintenance program without bus failure. |
| СООК 1 | 09/20/08 THE REACTOR WAS MANU/ TRIPPED AFTER A MALFUN THE MAIN TURBINE GENER RESULTED IN HIGH TURBIN VIBRATIONS AND A FIRE IN GENERATOR. | ALLY SIT - ML090260032 - : CTION OF ATOR E THE | L Green Finding A Green finding of very room operator actions. failed to provide approj operation of all three fi | low safety significance was identified for the failure to h Specifically, a control room annunciator response proce oriate guidance for diagnosing a fire protection system fa re pumps. | ave appropriate procedures for control dure for a fire protection alarm panel ailure as evidenced by the simultaneous |

| PLAN | EVEN | Scia. | Publi | ye ^e |
|------------------|----------|---|---|--|
| MONTICELLO | 09/11/08 | WITH THE 1R TRANSFORMER OUT FOR MAINTENANCE, THE 2R TRANSFORMER EXPERIENCED A LOCKOUT RESULTING IN LOSS OF OFFSITE POWER, WHICH RESULTED IN A REACTOR TRIP. | SIT - ML083510254 - 5 Green Findings | Five Green findings of very low safety significance were identified for: 1) Inadequate procedures to control reactor pressure vessel level. Specifically, the operating instructions for the control rod drive system were inadequate since they did not provide direction to control the addition of water to the reactor pressure vessel following a scram with reactor pressure vessel isolation. 2) A failure to establish an effective monitoring and corrective action plan for the underground cables. Preventive maintenance and testing methodology implemented was not sufficient to establish the condition of the cables (e.g., cable insulation resistance) to ensure functionality. 3) A failure to establish and implement an effective test control program for cables subjected to submersion. 4) A temporary loss of shutdown cooling. Specifically, operators failed to complete the shutdown checklist following the scram and did not close the reference leg fill valve from the control rod drive system. When the control rod drive pump was started, the reference leg experienced a pressure spike and the resulting full reactor protection system actuation resulted in a loss of shutdown cooling. 5) A failure of the high pressure coolant injection (HPCI) system to trip when reactor pressure vessel water level reached the trip setpoint. It was determined that the normally de-energized HPCI trip solenoid valve failed to trip promptly when actuated and was degraded due to improper reassembly of the solenoid valve after refurbishment and degraded elastomers. An engineering evaluation recommended a periodic replacement of the elastomers in this valve. No preventive maintenance activity was created or performed prior to the failure even though the recommended interval had been exceeded since the last overhaul. |
| PRAIRIE ISLAND 1 | 07/31/08 | THE REACTOR SCRAMMED DURING REACTOR PROTECTION SYSTEM TESTING. ONE OVER TEMPERATURE DELTA T CHANNEL WAS IN TEST WHEN A CONTROLLER IN THE OTHER CHANNEL FAILED. | SIT - ML083120510 - 1 Preliminary Greater than Green ML102500641 - White Finding (EA-08-272) ML092890143 - 95001 | A White notice of violation was issued for a low to moderate safety significance violation of Technical Specifications associated with the licensee's failure to adequately control the position of a valve that could isolate the Turbine Driven Auxiliary Fresh Water Pump's (TDAFWP's) discharge pressure switch. Because of the valve being closed, the TDAFWP failed to run as required, subsequent to a reactor trip. The manifold isolation valve was determined to have been shut for 138 days, rendering the TDAFWP inoperable for a time period that significantly exceeded the Technical Specification allowed outage time (72 hours) for the pump. A 95001 supplemental inspection was performed to follow-up on this risk-significant issue to provide assurance that the root causes and contributing causes were understood, extent of condition and extent of cause were identified, and that the licensee's corrective actions were sufficient to address the root and contributing causes and prevent recurrence. |
| PERRY | 11/28/07 | THE REACTOR TRIPPED DUE TO A TURBINE CONTROL VALVE FAST CLOSURE SIGNAL. THE CAUSE OF THE TRIP WAS FAILURE OF THE POWER SUPPLIES IN THE DIGITAL FEEDWATER CONTROL SYSTEM. | SIT - ML080280499 - 1 Green Finding, 3 URIs ML081290566 - 4 Green Findings | Five Green findings of very low safety significance were identified for: 1) The improper installation of replacement power supplies in the digital feedwater control system. The installed replacement power supplies were oriented incorrectly to assure proper cooling. 2) The failure of the reactor core isolation cooling (RCIC) to perform its design function during the reactor scram and plant response. The RCIC system started automatically on low reactor water level, began to inject into the reactor pressure vessel, and then tripped on low suction pressure. The RCIC pump flow controller was found to have been incorrectly tuned. 3) Improper testing of the RCIC system. Specifically, the program failed to incorporate the requirements and acceptance limits contained in applicable design documents to assure that RCIC flow controller configuration and performance met design requirements during testing. 4) The failure to perform adequate corrective actions to preclude repetition of a significant condition adverse to quality in response to a similar previously declared RCIC inoperably condition. 5) The failure to identify the RCIC failures as a significant condition adverse to quality within their corrective action program. |
| NORTH ANNA 2 | 06/29/07 | A SPURIOUS "B" TRAIN Safety Injection (SI) SIGNAL RESULTED IN A TURBINE TRIP AND SUBSEQUENT REACTOR TRIP. | SIT - Report ML072410359, 2 URIs ML083020663 - No Findings (URI) | No findings were identified |

NAME

TDATE

| Plant Name, Unit Number | NRC Reactor Unit Web Page | Docket Number |
|---|---------------------------|------------------|
| Oyster Creek Nuclear Generating Station, Unit 1 | Oyster Creek | 5000219 |
| Nine Mile Point Nuclear Station, Unit 1 | Nine Mile Point 1 | 5000220 |
| Dresden Nuclear Power Station, Unit 2 | Dresden 2 | 5000237 |
| Ginna Nuclear Power Plant | <u>Ginna</u> | 5000244 |
| Indian Point Nuclear Generating, Unit 2 | Indian Point 2 | 5000247 |
| Dresden Nuclear Power Station, Unit 3 | Dresden 3 | 5000249 |
| Turkey Point Nuclear Generating, Unit 3 | Turkey Point 3 | 5000250 |
| Turkey Point Nuclear Generating, Unit 4 | Turkey Point 4 | 5000251 |
| Quad Cities Nuclear Power Station, Unit 1 | Quad Cities 1 | 5000254 |
| Palisades Nuclear Plant | Palisades | 5000255 |
| Browns Ferry Nuclear Plant, Unit 1 | Browns Ferry 1 | 5000259 |
| Browns Ferry Nuclear Plant, Unit 2 | Browns Ferry 2 | 5000260 |
| Robinson Steam Electric Plant, Unit 2 | Robinson 2 | 5000261 |
| Monticello Nuclear Generating Plant, Unit 1 | <u>Monticello</u> | 5000263 |
| Quad Cities Nuclear Power Station, Unit 2 | Quad Cities 2 | 5000265 |
| Point Beach Nuclear Plant, Unit 1 | Point Beach 1 | 5000266 |
| Oconee Nuclear Station, Unit 1 | Oconee 1 | 5000269 |
| Oconee Nuclear Station, Unit 2 | Oconee 2 | 5000270 |
| Vermont Yankee Nuclear Power Plant, Unit 1 | Vermont Yankee | 5000271 |
| Salem Nuclear Generating Station, Unit 1 | Salem 1 | 5000272 |
| Diablo Canyon Nuclear Power Plant, Unit 1 | Diablo Canyon 1 | 5000275 |
| Peach Bottom Atomic Power Station, Unit 2 | Peach Bottom 2 | 5000277 |
| Peach Bottom Atomic Power Station, Unit 3 | Peach Bottom 3 | 5000278 |
| Surry Nuclear Power Station, Unit 1 | Surry 1 | 5000280 |
| Surry Nuclear Power Station, Unit 2 | Surry 2 | 5000281 |
| Prairie Island Nuclear Generating Plant, Unit 1 | Prairie Island 1 | 5000282 |
| Fort Calhoun Station, Unit 1 | Fort Calhoun | 5000285 |
| Indian Point Nuclear Generating, Unit 3 | Indian Point 3 | 5000286 |
| Oconee Nuclear Station, Unit 3 | Oconee 3 | 5000287 |
| Three Mile Island Nuclear Station, Unit 1 | Three Mile Island 1 | 5000289 |
| Pilgrim Nuclear Power Station | Pilgrim 1 | 5000293 |
| Browns Ferry Nuclear Plant, Unit 3 | Browns Ferry 3 | 5000296 |
| Cooper Nuclear Station | <u>Cooper</u> | 5000298 |
| Point Beach Nuclear Plant, Unit 2 | Point Beach 2 | 5000301 |
| Crystal River Nuclear Generating Plant, Unit 3 | Crystal River 3 | 5000302 |
| Kewaunee Power Station | <u>Kewaunee</u> | 5000305 |
| Prairie Island Nuclear Generating Plant, Unit 2 | Prairie Island 2 | 5000306 |
| Salem Nuclear Generating Station, Unit 2 | Salem 2 | 5000311 |
| Arkansas Nuclear One, Unit 1 | Arkansas Nuclear 1 | 5000313 |
| Donald C. Cook Nuclear Power Plant, Unit 1 | D.C. Cook 1 | 5000315 |
| Donald C. Cook Nuclear Power Plant, Unit 2 | D.C. Cook 2 | 5000316 |
| Calvert Cliffs Nuclear Power Plant, Unit 1 | Calvert Cliffs 1 | 5000317 |
| Calvert Cliffs Nuclear Power Plant, Unit 2 | Calvert Cliffs 2 | 5000318 |
| Hatch Nuclear Plant, Unit 1 | Hatch 1 | 5000321 |
| Diablo Canyon Nuclear Power Plant, Unit 2 | Diablo Canyon 2 | 5000323 |

Brunswick Steam Electric Plant, Unit 2 Brunswick Steam Electric Plant, Unit 1 Sequoyah Nuclear Plant, Unit 1 Sequoyah Nuclear Plant, Unit 2 **Duane Arnold Energy Center** FitzPatrick Nuclear Power Plant Beaver Valley Power Station, Unit 1 St. Lucie Plant, Unit 1 Millstone Power Station. Unit 2 North Anna Power Station, Unit 1 North Anna Power Station, Unit 2 Fermi. Unit 2 Davis-Besse Nuclear Power Station, Unit 1 Farley Nuclear Plant, Unit 1 Limerick Generating Station, Unit 1 Limerick Generating Station, Unit 2 Hope Creek Generating Station, Unit 1 San Onofre Nuclear Generating Station, Unit 2 San Onofre Nuclear Generating Station, Unit 3 Farley Nuclear Plant, Unit 2 Hatch Nuclear Plant, Unit 2 Arkansas Nuclear One, Unit 2 McGuire Nuclear Station, Unit 1 McGuire Nuclear Station, Unit 2 LaSalle County Station, Unit 1 LaSalle County Station, Unit 2 Waterford Steam Electric Station, Unit 3 Susquehanna Steam Electric Station, Unit 2 Susquehanna Steam Electric Station, Unit 1 St. Lucie Plant, Unit 2 Watts Bar Nuclear Plant, Unit 1 Virgil C. Summer Nuclear Station, Unit 1 Columbia Generating Station, Unit 2 Harris Nuclear Power Plant, Unit 1 Nine Mile Point Nuclear Station, Unit 2 Beaver Valley Power Station, Unit 2 Catawba Nuclear Station, Unit 1 Catawba Nuclear Station, Unit 2 Grand Gulf Nuclear Station, Unit 1 Millstone Power Station, Unit 3 Vogtle Electric Generating Plant, Unit 1 Vogtle Electric Generating Plant, Unit 2 Perry Nuclear Power Plant, Unit 1 Seabrook Station, Unit 1 Comanche Peak Steam Electric Station, Unit 1 Comanche Peak Steam Electric Station, Unit 2 Byron Station, Unit 1

Brunswick 2 5000324 Brunswick 1 5000325 Sequoyah 1 5000327 Sequoyah 2 5000328 **Duane Arnold** 5000331 FitzPatrick 5000333 **Beaver Valley 1** 5000334 Saint Lucie 1 5000335 Millstone 2 5000336 North Anna 1 5000338 North Anna 2 5000339 Fermi 2 5000341 **Davis-Besse** 5000346 Farlev 1 5000348 Limerick 1 5000352 Limerick 2 5000353 Hope Creek 1 5000354 San Onofre 2 5000361 San Onofre 3 5000362 Farley 2 5000364 Hatch 2 5000366 Arkansas Nuclear 2 5000368 McGuire 1 5000369 McGuire 2 5000370 La Salle 1 5000373 La Salle 2 5000374 Waterford 3 5000382 Susquehanna 1 5000387 5000388 Susquehanna 2 Saint Lucie 2 5000389 Watts Bar 1 5000390 Summer 5000395 **Columbia Generating Station** 5000397 Shearon Harris 1 5000400 Nine Mile Point 2 5000410 **Beaver Valley 2** 5000412 Catawba 1 5000413 Catawba 2 5000414 Grand Gulf 1 5000416 Millstone 3 5000423 Vogtle 1 5000424 Vogtle 2 5000425 Perry 1 5000440 Seabrook 1 5000443 **Comanche Peak 1** 5000445 **Comanche Peak 2** 5000446 5000454 Byron 1

| Byron Station, Unit 2 | Byron 2 | 5000455 |
|---|-----------------|---------|
| Braidwood Station, Unit 1 | Braidwood 1 | 5000456 |
| Braidwood Station, Unit 2 | Braidwood 2 | 5000457 |
| River Bend Station, Unit 1 | River Bend 1 | 5000458 |
| Clinton Power Station, Unit 1 | <u>Clinton</u> | 5000461 |
| Wolf Creek Generating Station, Unit 1 | Wolf Creek 1 | 5000482 |
| Callaway Plant | <u>Callaway</u> | 5000483 |
| South Texas Project, Unit 1 | South Texas 1 | 5000498 |
| South Texas Project, Unit 2 | South Texas 2 | 5000499 |
| Palo Verde Nuclear Generating Station, Unit 1 | Palo Verde 1 | 5000528 |
| Palo Verde Nuclear Generating Station, Unit 2 | Palo Verde 2 | 5000529 |
| Palo Verde Nuclear Generating Station, Unit 3 | Palo Verde 3 | 5000530 |

Location

Forked River, NJ (9 MI S of Toms River, NJ) Scriba, NY (6 MI NE of Oswego, NY) Morris, IL (9 MI E of Morris, IL)

Ontario, NY (20 MI NE of Rochester, NY)

Buchanan, NY (24 MI N of New York City, NY)

Morris, IL (9 MI E of Morris, IL)

Homestead, FL (20 MI S of Miami, FL)

Homestead, FL (20 MI S of Miami, FL)

Cordova, IL (20 MI NE of Moline, IL)

Covert, MI (5 MI S of South Haven, MI)

Athens, AL (32 MI W of Huntsville, AL)

Athens, AL (32 MI W of Huntsville, AL)

Hartsville, SC (26 MI from Florence, SC)

Monticello, MN (30 MI NW of Minneapolis, MN)

Cordova, IL (20 MI NE of Moline, IL)

Two Rivers, WI (13 MI NNW of Manitowoc, WI) Seneca, SC (30 MI W of Greenville, SC)

Seneca, SC (30 MI W of Greenville, SC)

Vernon, VT (5 MI S of Brattleboro, VT)

Hancock Bridge, NJ (18 MI S of Wilmington, DE)

Avila Beach, CA (12 MI WSW of San Luis Obispo, CA)

Delta, PA (17.9 MI S of Lancaster, PA)

Delta, PA (17.9 MI S of Lancaster, PA)

Surry, VA (17 MI NW of Newport News, VA)

Surry, VA (17 MI NW of Newport News, VA)

Welch, MN (28 MI SE of Minneapolis, MN)

Fort Calhoun, NE (19 MI N of Omaha, NE) Buchanan, NY (24 MI N of New York City, NY)

Seneca, SC (30 MI W of Greenville, SC)

Middletown, PA (10 MI SE of Harrisburg, PA)

Plymouth, MA (4 MI SE of Plymouth, MA)

Wheeler Lake, AL (10 MI SW of Athens, AL)

Brownville, NE (23 MI S of Nebraska City, NE)

Two Rivers, WI (13 MI NNW of Manitowoc, WI) Crystal River, FL (80 MI N of Tampa, FL)

Kewaunee, WI (27 MI E of Green Bay, WI)

Welch, MN (28 MI SE of Minneapolis, MN)

Hancock Bridge, NJ (18 MI S of Wilmington, DE)

Russellville, AR (6 MI WNW of Russellville, AR)

Stevensville, MI (11 MI S of Benton Harbor, MI)

Stevensville, MI (11 MI S of Benton Harbor, MI)

Lusby, MD (40 MI S of Annapolis, MD)

Lusby, MD (40 MI S of Annapolis, MD)

Baxley, GA (11 MI N of Vidalia, GA)

Avila Beach, CA (12 MI WSW of San Luis Obispo, CA)

NRC Region Licensee Exelon Generation Co., LLC 1 1 Nine Mile Point Nuclear Station, LLC Exelon Generation Co., LLC 3 1 R.E. Ginna Nuclear Power Plant, LLC 1 Entergy Nuclear Operations, Inc. 3 Exelon Generation Co., LLC 2 Florida Power & Light Co. 2 Florida Power & Light Co. 3 Exelon Generation Co., LLC 3 Entergy Nuclear Operations, Inc. 2 **Tenessee Valley Authority** 2 Tenessee Valley Authority 2 Carolina Power & Light Co., Northern States Power Company 3 3 Exelon Generation Co., LLC 3 FPL Energy Duane Arnold, LLC 2 Duke Energy Carolinas, LLC 2 Duke Energy Carolinas, LLC Entergy Nuclear Operations, Inc. 1 1 PSEG Nuclear, LLC 4 Pacific Gas & Electric Co. 1 Exelon Generation Co., LLC Exelon Generation Co., LLC 1 2 Virginia Electric & Power Co. 2 Virginia Electric & Power Co. 3 Northern States Power Co. Minnesota Omaha Public Power District 4 1 Entergy Nuclear Operations, Inc. 2 Duke Energy Carolinas, LLC 1 Exelon Generation Co., LLC

1 Entergy Nuclear Operations, Inc.

2 Tenessee Valley Authority

4 Nebraska Public Power District

3 FPL Energy Duane Arnold, LLC

2 Florida Power Corp.

3 Dominion Energy Kewaunee, Inc.

3 Northern States Power Co. Minnesota

1 PSEG Nuclear, LLC

4 Entergy Nuclear Operations, Inc.

3 Indiana Michigan Power Co.

3 Indiana Michigan Power Co.

1 Calvert Cliffs Nuclear Power Plant Inc.

1 Calvert Cliffs Nuclear Power Plant Inc.

2 Southern Nuclear Operating Co.

4 Pacific Gas & Electric Co.

Southport, NC (2 MI N of Southport, NC) Southport, NC (2 MI N of Southport, NC) Soddy-Daisy, TN (9.5 MI NE of Chattanooga, TN) Soddy-Daisy, TN (9.5 MI NE of Chattanooga, TN) Palo, IA (8 MI NW of Cedar Rapids, IA) Scriba, NY (6 MI NE of Oswego, NY) Shippingport, PA(17 MI W of McCandless, PA) Jensen Beach, FL (10 MI SE of Ft. Pierce, FL) Waterford. CT (3.2 MI WSW of New London, CT) Louisa, VA (40 MI NW of Richmond, VA) Louisa, VA (40 MI NW of Richmond, VA) Newport, MI (25 MI NE of Toledo, OH) Oak Harbor, OH (21 MI ESE of Toledo, OH) Columbia, AL (18 MI S of Dothan, AL) Limerick, PA (21 MI NW of Philadelphia, PA) Limerick, PA (21 MI NW of Philadelphia, PA) Hancock Bridge, NJ (18 MI SE of Wilmington, DE) San Clemente, CA (4 MI SE of San Clemente, CA) San Clemente, CA (4 MI SE of San Clemente, CA) Columbia, AL (18 MI S of Dothan, AL) Baxley, GA (11 MI N of Vidalia, GA) Russellville, AR (6 MI WNW of Russellville, AR) Huntsville, NC (17 MI N of Charlotte, NC) Huntsville, NC (17 MI N of Charlotte, NC) Marseilles, IL (11 MI SE of Ottawa, IL) Marseilles, IL (11 MI SE of Ottawa, IL) Killona, LA (25 MI W of New Orleans, LA) Berwick, PA (7 MI NE of Berwick, PA) Berwick, PA (7 MI NE of Berwick, PA) Jensen Beach, FL (10 MI SE of Ft. Pierce, FL) Spring City, TN (60 MI S of Spring City, TN) Jenkinsville, SC (26 MI NW of Columbia, SC) Richland, WA (12 MI NW of Richland, WA) New Hill, NC (20 MI SW of Raleigh, NC) Scriba, NY (6 MI NE of Oswego, NY) Shippingport, PA (17 MI W of McCandless, PA) York, SC (18 MI S of Charlotte, NC) York, SC (18 MI S of Charlotte, NC) Port Gibson, MS (25 MI S of Vicksburg, MS) Waterford. CT (3.2 MI WSW of New London, CT) Waynesboro, GA (26 MI SE of Augusta, GA) Waynesboro, GA (26 MI SE of Augusta, GA) Perry, OH (35 MI NE of Cleveland, OH) Seabrook, NH (13 MI S of Portsmouth, NH) Glen Rose, TX (4 MI N of Glen Rose, TX) Glen Rose, TX (4 MI N of Glen Rose, TX) Byron, II (17 MI SW of Rockford, IL)

2 Carolina Power & Light Co. 2 Carolina Power & Light Co. 2 **Tenessee Valley Authority** 2 **Tenessee Valley Authority** 3 FPL Energy Duane Arnold, LLC 1 Entergy Nuclear Operations, Inc. 1 First Energy Nuclear Operating Co. 2 Florida Power & Light Co. 1 Dominion Nuclear Conneticut, Inc. 2 Virginia Electric & Power Co. 2 Virginia Electric & Power Co. 3 The Detroit Edison Co. 3 First Energy Nuclear Operating Co. 2 Southern Nuclear Operating Co. 1 Exelon Generation Co., LLC Exelon Generation Co., LLC 1 1 PSEG Nuclear, LLC 4 Southern California Edison Co. 4 Southern California Edison Co. 2 Southern Nuclear Operating Co. 2 Southern Nuclear Operating Co. 4 Entergy Nuclear Operations, Inc. 2 Duke Energy Carolinas, LLC 2 Duke Energy Carolinas, LLC 3 Exelon Generation Co., LLC 3 Exelon Generation Co., LLC 4 Entergy Nuclear Operations, Inc. PPL Susquehanna, LLC 1 1 PPL Susquehanna, LLC 2 Florida Power & Light Co. 2 **Tenessee Valley Authority** 2 South Carolina Electric & Gas Co. 4 **Energy Northwest** 2 Carolina Power & Light Co. Nine Mile Point Nuclear Station, LLC 1 1 First Energy Nuclear Operating Co. 2 Duke Energy Carolinas, LLC 2 Duke Energy Carolinas, LLC 4 Entergy Nuclear Operations, Inc. 1 Dominion Nuclear Conneticut, Inc. 2 Southern Nuclear Operating Co. 2 Southern Nuclear Operating Co. 3 First Energy Nuclear Operating Co. 1 FPL Energy Seabrook, LLC 4 Luminant Generation Co., LLC 4 Luminant Generation Co., LLC 3 Exelon Generation Co., LLC

Byron, II (17 MI SW of Rockford, IL)

- Braceville, IL (20 MI SSW of Joilet, IL)
- Braceville, IL (20 MI SSW of Joilet, IL)
- St. Francisville, LA (24 MI NNW of Baton Rouge, LA)
- Clinton, IL (6 MI E of Clinton, IL)
- Burlington, KS (3.5 MI NE of Burlington, KS)
- Fulton, MO (25 MI ENE of Jefferson City, MO)
- Bay City, TX (12 MI SSW of Bay City, TX)
- Bay City, TX (12 MI SSW of Bay City, TX)
- Wintersburg, AZ (50 MI W of Phoenix, AZ)
- Wintersburg, AZ (50 MI W of Phoenix, AZ)
- Wintersburg, AZ (50 MI W of Phoenix, AZ)

- 3 Exelon Generation Co., LLC
- 3 Exelon Generation Co., LLC
- 3 Exelon Generation Co., LLC
- 4 Entergy Nuclear Operations, Inc.
- 3 Exelon Generation Co., LLC
- 4 Wolf Creek Nuclear Operating Corp.
- 4 Union Electric Co.
- 4 STP Nuclear Operating Co.
- 4 STP Nuclear Operating Co.
- 4 Arizona Public Service Company
- 4 Arizona Public Service Company
- 4 Arizona Public Service Company