

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9211030327 DOC.DATE: 92/10/26 NOTARIZED: NO DOCKET #  
FACIL:50-305 Kewaunee Nuclear Power Plant, Wisconsin Public Servic 05000305  
AUTH.NAME AUTHOR AFFILIATION  
DRESSEN,J.D. Wisconsin Public Service Corp.  
SCHROCK,C.A. Wisconsin Public Service Corp.  
RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 92-018-00:on 920922,licensed power exceeded due to inaccurate feedwater flow indication.Caused by corrosion product build up between ultrasonic flow meters.Ultrasonic flow meters transducers replaced.W/921026 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 7  
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD3-3 LA		1	1		PD3-3 PD		1	1
	HANSEN,A.		1	1					
INTERNAL:	ACNW		2	2	ACRS		2	2	
	AEOD/DOA		1	1	AEOD/DSP/TPAB		1	1	
	AEOD/ROAB/DSP		2	2	NRR/DET/EMEB 7E		1	1	
	NRR/DLPQ/LHFB10		1	1	NRR/DLPQ/LPEB10		1	1	
	NRR/DOEA/OEAB		1	1	NRR/DREP/PRPB11		2	2	
	NRR/DST/SELB 8D		1	1	NRR/DST/SICB8H3		1	1	
	NRR/DST/SPLB8D1		1	1	NRR/DST/SRXB 8E		1	1	
	<u>REG FILE</u> 02		1	1	RES/DSIR/EIB		1	1	
	RGN3 FILE 01		1	1					
EXTERNAL:	EG&G BRYCE,J.H		2	2	L ST LOBBY WARD		1	1	
	NRC PDR		1	1	NSIC MURPHY,G.A		1	1	
	NSIC POORE,W.		1	1	NUDOCS FULL TXT		1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.  
ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
TOTAL NUMBER OF COPIES REQUIRED: LTR 31 ENCL 31

NO-4  
JBP



**WISCONSIN PUBLIC SERVICE CORPORATION**

600 North Adams • P.O. Box 19002 • Green Bay, WI 54307-9002

October 26, 1992

10 CFR 50.73

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Gentlemen:

Docket 50-305  
Operating License DPR-43  
Kewaunee Nuclear Power Plant  
Reportable Occurrence 92-018-00

In accordance with the requirements of 10 CFR 50.73, "Licensee Event Report System," the attached Licensee Event Report for reportable occurrence 92-018-00 is being submitted.

Sincerely,

A handwritten signature in cursive script that reads "C. A. Schrock".

C. A. Schrock  
Manager-Nuclear Engineering

VJC\jac

Attach.

cc - INPO Records Center  
Mr. Patrick Castleman, US NRC  
US NRC, Region III

9211030327 921026  
PDR ADDCK 05000305  
S PDR

Handwritten initials, possibly "JEJ", written in the bottom right corner of the page.

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Kewaunee Nuclear Power Plant	DOCKET NUMBER (2) 0 5 0 0 0 3 0 1 5	PAGE 15 1 OF 0 6
---	--	---------------------

TITLE (4)  
Licensed Power Exceeded Due to Inaccurate Feedwater Flow Indication

EVENT DATE (8)			LER NUMBER (8)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0 9	2 4	9 2	9 2	0 1 8	0 0	1 0	2 6	9 2	N/A		0 5 0 0 0
											0 5 0 0 0

OPERATING MODE (8) N

POWER LEVEL (10) 1 0 0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

20.402(b)	20.408(e)	80.73(a)(2)(iv)	78.71(b)
20.408(a)(1)(ii)	80.38(a)(1)	80.73(a)(2)(v)	73.71(a)
20.408(a)(1)(iii)	50.38(a)(2)	80.72(a)(2)(iv)	OTHER (Specify in Abstract below and in Text, NRC Form 388A)
20.408(a)(1)(iv)	X 80.73(a)(2)(ii)	80.73(a)(2)(vi)(A)	
20.408(a)(1)(v)	50.73(a)(2)(iii)	80.73(a)(2)(vi)(B)	
20.408(a)(1)(vi)	80.73(a)(2)(iv)	80.78(a)(2)(i)	

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
Jay D. Dressen - Plant Nuclear Engineer	AREA CODE 4 1 4 3 8 8 - 2 5 6 0

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRPDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRPDS
X	S	J	F I C I G	2 6 N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15) N/A

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (18)

On September 22, 1992, the plant was returning to 100 percent power after a September 15, 1992, unit trip. After applying the ultrasonic flow meters (UFMs) correction factor to in-line venturi feedwater (FW) flow measurements and escalating to 100 percent power, it was noted that the electric output was 1 to 2 megawatts higher than before the unit trip. This prompted an engineering evaluation. On September 24, 1992, the evaluation determined indicated FW flow, measured by the UFMs, was 0.41 percent low and reactor power was approximately 0.2 percent greater than licensed thermal power. Immediate actions were taken to decrease power to within licensed limits.

The change in UFM output was caused by corrosion product build up between the UFM transducers and the FW pipe in conjunction with age related degradation of the transducers. This results in a decrease in UFM signal repeatability.

The FW UFMs were calibrated, using the full flow bypass line venturi, to accurately measure FW flow and determine actual 100 percent reactor power on September 24, 1992. The FW pipe surface between the UFM transducers is scheduled to be cleaned during the 1993 refueling outage. Additionally, a program is being developed to replace the UFM transducers on a regular basis. These actions will ensure UFM repeatability. Until the 1993 refueling outage the full flow bypass line venturi will be used to calibrate the UFMs after a trip. This will ensure the UFMs are calibrated until the corrective actions can be taken.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Kewaunee Nuclear Power Plant	DOCKET NUMBER (2)  0 5 0 0 0 3 0 5	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 2	- 0 1 8	- 0 0	0 2	OF	0 6

TEXT (If more space is required, use additional NRC Form 388A's) (17)

Description of Event

This report describes a violation of Kewaunee's Technical Specifications. Section 2.c.1 of Kewaunee's Operating License limits steady-state core power level to 1650 megawatts thermal (MWt). On September 24, 1992, an engineering investigation into a slight increase in electrical output concluded Kewaunee had been operating at 1653 MWt since achieving full power on September 22, 1992. Immediate actions were taken to decrease power to within licensed limits.

On September 22, 1992 the plant was returning to 100 percent power after a unit trip on September 15th. Steady-state 100 percent reactor power was determined by performance of a secondary calorimetric.

At Kewaunee, ultrasonic feedwater flow meters (UFMs)[FI], are used in conjunction with in-line feedwater (FW) venturies to determine the FW flow rate used in the calorimetric calculation. The UFMs are used to apply a correction factor to the in-line FW flow venturi measurements.

At the beginning of an operating cycle, the UFMs are calibrated using a more accurate venturi located in a full flow main feedwater bypass line. The bypass line venturi measurement is compared to the UFM measurements and a calibration factor is determined. The UFMs are then used to determine a correction factor for the in-line venturi measurements.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Kewaunee Nuclear Power Plant	DOCKET NUMBER (2)  0   5   0   0   0   3   0   5	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 2	- 0 1 8	- 0 0	0 3	OF	0 6

TEXT (If more space is required, use additional NRC Form 306A's) (17)

Following any transient (approximately a 5 percent power decrease from 100 percent power), the in-line venturi correction factor is conservatively removed from the computation of flow measurement until its accuracy can be ascertained by the examination of other plant parameters.

When escalating to full power after the unit trip, there were no apparent changes in plant parameter values from those that existed prior to the trip. Since plant parameters (including FW flow, steam flow, and in-line venturi differential pressure measurements) had not changed noticeably, it was determined that the UFM calibration factor and the in-line venturi correction factor used prior to the trip were appropriate.

When the UFM's were used to correct FW flow, and power was escalated to 100 percent indicated thermal power, electric output was noted to be 1 to 2 megawatts higher than before the trip. Upon closer scrutiny, other plant parameters were identified that differed slightly from before and after the trip. This prompted an engineering evaluation to determine if licensed reactor power was being exceeded. Numerous instrument checks and comparisons were initially performed, including the lengthy preparations (approximately eighteen hours to warm the FW bypass line and perform the test) necessary for verifying the calibration of the UFM's.

Reactor power was definitively determined by calibrating the UFM's in accordance with the annual calibration procedure RXT-2I, "Calibration of Feedwater Ultrasonic Flowmeters using the Feedwater Bypass Line," on September 24, 1992. The results indicated that the UFM's were

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Kewaunee Nuclear Power Plant	0   5   0   0   0   3   0   5	9   2	-   0   1   8	-   0   0	0   4	OF	0   6

TEXT (If more space is required, use additional NRC Form 388A's) (17)

reading 0.41 percent low and reactor power was approximately 0.2 percent greater than the licensed limit.

The maximum steady state power level allowed by the Kewaunee Nuclear Power Plant Facility Operating License is 1650 megawatts thermal. It was calculated that the power level was approximately 1653 megawatts thermal with the UFM's out of calibration.

**Cause of the Event**

The change in UFM output was caused by corrosion product build-up between the UFM transducers and the FW pipe in conjunction with age related degradation of the transducers. This resulted in a decrease in UFM signal repeatability. This is consistent with information obtained from the vendor and experience of other licensees.

**Analysis of Event**

This report is submitted as a violation of Kewaunee Technical Specifications. Section 2.c.1 of the Kewaunee Nuclear Power Plant Facility Operating License states, " The licensees are authorized to operate the facility at steady-state reactor core power levels not in excess of 1650 megawatts (thermal)." Contrary to this from September 22, 1992 to September 24, 1992 reactor power was approximately 1653 megawatts thermal.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Kewaunee Nuclear Power Plant	DOCKET NUMBER (2)  0 5 0 0 0 3 0 5	LER NUMBER (8)			PAGE (3)		
		YEAR 9 2	SEQUENTIAL NUMBER - 0 1 8	REVISION NUMBER - 0 0			

TEXT (If more space is required, use additional NRC Form 388A's) (17)

Section 14 of the USAR, titled Safety Analysis states, "For accident evaluation, the initial conditions are obtained by adding maximum steady-state error to rated values." The rated values for power are plus or minus 2 percent of 1650 MWt (or 33 MWt) for calorimetric error. The error associated with the FW flow measurement using the FW bypass line is  $\pm 0.461$ . This is well within the error of  $\pm 1.25\%$  assumed by the USAR for FW flow measurement. With reactor power reaching 100.2 percent, the reactor power limits of USAR section 14 were not exceeded. Therefore the assumptions in the safety analysis are still applicable and there was no increased risk to the health and safety of the public.

Corrective Actions

When it was noticed that there was a difference in electric output from before the trip on September 15, 1992, an engineering evaluation was conducted. A review of plant parameters provided no firm indication as to why there was a difference in electric output. It was determined to verify the calibration of the UFM's, by using the FW bypass line, in accordance with procedure RXT-21, "Calibration of Feedwater Ultrasonic Flowmeters using the Feedwater Bypass Line," on September 24, 1992. After calibrating the UFM's reactor power was returned to 100 percent power at 1900 on September 24, 1992.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		1992	0018	0	06	OF 06

TEXT (If more space is required, use additional NRC Form 305A's) (17)

The FW pipe surface between the UFM transducers is scheduled to be cleaned and polished during the 1993 refueling outage. Additionally, a program is being developed to replace the UFM transducers on a regular basis. These actions will ensure UFM repeatability.

Until the 1993 refueling outage the FW bypass line will be used to calibrate the UFM's after a trip. This will ensure the UFM's are accurate until the corrective actions can be taken.

**Additional Information:** None

**Equipment Failure:** Controlotron Inc., Model number 960 ultrasonic flow meter.

**Similar Events:** None.