

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Weyerhaeuser NR Company
4111 West Four Mile Rd.
Grayling, MI 49738

2. NRC/REGIONAL OFFICE
U.S. Nuclear Regulatory Commission
Region III
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4351

REPORT NUMBER(S) 2011-001

3. DOCKET NUMBER(S)
030-18287

4. LICENSEE NUMBER(S)
21-20351-01

5. DATE(S) OF INSPECTION
July 21-28, 2011

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied

_____ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Deborah A. Piskura		7/28/2011
Branch Chief	Tamara E. Bloomer		7/28/11

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE Weyerhaeuser NR Company 4111 West Four Mile Rd Grayling, MI	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4351
REPORT NUMBER(S) 2011-001	

3. DOCKET NUMBER(S) 030-18287	4. LICENSE NUMBER(S) 21-20351-01	5. DATE(S) OF INSPECTION July 21-28, 2011
----------------------------------	-------------------------------------	--

6. INSPECTION PROCEDURES 87124	7. INSPECTION FOCUS AREAS 03.01-03.08
-----------------------------------	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM 03120	2. PRIORITY 5	3. LICENSEE CONTACT Kathi Moss, RSO	4. TELEPHONE NUMBER 989-348-3475
---------------------	------------------	--	-------------------------------------

Main Office Inspection Next Inspection Date: July 2016
 Field Office Inspection
 Temporary Job Site Inspection _____

PROGRAM SCOPE

This licensee was a manufacturer and distributor of wooden structural board used in residential and commercial construction. The company is licensed to use Am-241 sealed sources in gauging devices for thickness measurements of structural boards. The RSO served as the primary authorized user and performed the required leak tests, shutter checks, inventory, and general inspections of the licensed material. All maintenance and service was performed by the device manufacturer. The licensee possessed no generally licensed devices at this location (a formally possessed was transferred in 2006, through the device manufacturer to another company site).

This inspection consisted of interviews with select licensee personnel; a review of select records including lock-out/tag-out procedures; a tour of the facility; and observations of security of byproduct material, postings and environmental conditions. The licensee's RSO was not available during the on-site inspection. The inspection included an in-office review of leak tests, shutter checks, material transfer, and training.