



# Anticipated Transient Without Scram (ATWS)

## Chapter 4.7

# Objectives

1. Define the term “**Anticipated Transient Without Scram**” (ATWS).
2. Describe the limiting (most severe) ATWS case for a pressurized water reactor (PWR).
3. List three parameters or components that affect a plant’s sensitivity to an ATWS event.

# Objectives (cont)

4. Describe the modification made to Westinghouse reactor trip breakers after the Salem ATWS.
5. State the functions of the ATWS mitigation system.
6. Delete

# ATWS 10CFR50.62

- “an anticipated operational occurrence... followed by failure of the reactor trip portion of the protection system”
- An anticipated operational occurrence is defined as those conditions of normal operation that are expected to occur one or more times during the life of a nuclear unit (e.g., Rx Trip, Turb Trip, LOOP, Loss of FW, etc.)




Fig 4.7-1 Solid State Protection

# History

- 1968 Advisory Committee on Reactor Safety (ACRS) found that separation of control and protection systems to be adequate.
- 1969 ACRS: Evaluate likelihood of RPS common mode failures and analyze consequences of postulated ATWS events.
- 1980 NUREG 460 ATWS (USI A-9)
  - PRA to estimate benefit of modifications
- 1984 ATWS Rule 10CFR50.62

# History

- 1984 ATWS Rule -10CFR50.62

**Diverse Trip System:** Not required for Westinghouse.

**ATWS mitigation system:** Required to initiate AFW & Turbine trip under conditions indicative of ATWS.

# History

- Sept. 2003 NUREG-1780, Regulatory Effectiveness of the Anticipated Transient Without Scram Rule
  - Concluded that ATWS rule was effective in reducing risk and costs associated with implementation were reasonable.
  - Report also stated “uncertainties in the reactor protection system and mitigative capability may warrant further attention to ensure the expected levels of safety are maintained”




# ATWS Principal Transients


- Loss of Load/Turbine Trip
- Loss of Offsite Power
- Accidental RCS Depressurization
- Uncontrolled RCCA Bank Withdrawal
- Loss of Normal Feedwater (worst case)

# ATWS Loss of FW Worst Case


- The loss of FW/Loss of Heat Sink without trip causes increase in RCS Temperature. Temp increase raises SG Press. Safeties open, SG's Dry out. AFW can't keep up.
- Coolant Expansion due to temp increase causes a large in-surge to the Pressurizer.
- The In-Surge compressed the PZR bubble increasing RCS pressure >3000 psia
- Concern failure of RCS boundary/ECCS interface connections.




Loss of FW ATWS–Nuclear Pwr<sub>1</sub>



# Loss of FW ATWS – Tave



Loss of FW ATWS-PZR Pressure<sub>3</sub>



Loss of FW ATWS-PZR Level<sub>14</sub>

# Severity of Peak Pressure

- Value of MTC - Determines how much neg reactivity is added with the temp increase – worst BOL
- Pressurizer Volume -Time to reach solid
- Pressurizer Safety Valve Capacity - Affects ultimate pressure reached when solid
- Secondary Inventory – determines time to S/G dry-out
- Turbine Trip- preserves secondary inventory




Fig 4.7-2 RTB Original Design



# Salem ATWS Events (1983)

2/22/83

- 20% pwr with 1 MFP I/S & 1 MFP min speed.
- During transfer from offsite pwr to Main Gen control power to MFP is lost, SG levels drop.
- SG levels decrease to trip setpoint but trip does not occur. Operator manually trips 3.5 seconds later. Operators think they tripped Rx prior to level setpoint being reached.

# Salem ATWS Events (1983)

2/25/83

- Plant recovers from 2/22 trip and starts up.
- During low power operation there is difficulty controlling SG levels. One SG drops to the Low Low Level setpoint.
- Once again trip does not occur but alarm indication tells operators that trip setpoint has been reached.
- Operators manually trip plant 23 seconds after auto trip signal generated.

# Salem ATWS Events (1983)

- Investigation determined problem with Rx Trip Breakers.
- UV coils operated properly but mechanical interference in mechanisms prevents breakers from opening.
- Similar problems found at McGuire in 1987. NRC Bulletin 88-01 issued as result.




Fig 4.7-5 RTB modification




Fig 4.7-4 Trojan AMSAC Pg 4.7-7

Table 1 Categories of Initiating Events for Callaway Nuclear Generating Station, Unit 1 <sup>(1,3)</sup>

Row	Approximate Frequency	Event Type	Initiating Event Likelihood (IEL)		
			1	2	3
I	1 per 1-10 yr	Transients With PCS Available (Reactor Trip) (TRANS), Transients With Loss of PCS (TPCS)	1	2	3
II	1 per 10-10 <sup>2</sup> yr	Loss of Offsite Power (LOOP), Loss of (Normal) Service Water System (LSWS) <sup>(4)</sup>	2	3	4
III	1 per 10 <sup>2</sup> - 10 <sup>3</sup> yr	Steam Generator Tube Rupture (SGTR), Stuck-Open PORV (SORV), Small LOCA Including RCP Seal Failures (SLOCA), Main Steam Line Break Outside Containment (MSLB), Loss of Instrument Air (LIA), Loss of Vital DC Bus (LBDC)	3	4	5
IV	1 per 10 <sup>3</sup> - 10 <sup>4</sup> yr	Medium LOCA (MLOCA), LOOP and Loss of Vital 4.16 kV AC Bus (LEAC)	4	5	6
V	1 per 10 <sup>4</sup> - 10 <sup>5</sup> yr	Large LOCA (LLOCA), Loss of Component Cooling Water (LCCW)	5	6	7
VI	less than 1 per 10 <sup>5</sup> yr	Anticipated Transients Without Scram (ATWS) <sup>(2)</sup> , Interfacing System LOCA (ISLOCA)	6	7	8
			> 30 days	3-30 days	< 3 days
			Exposure Time for Degraded Condition		

### Turbine trip

ATWS	TTP	SRV	AFW	EMBO	#	STATUS	
<p>PZR Safeties &amp; PORVs</p>						1	OK
						2	CD
						3	CD
						4	CD
						5	CD
Plant name abbrev.: CALL							