

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
 I.C.S Services Corporation

 4225 Miller Road
 Suite 118
 Flint, MI 48507
 REPORT NUMBER(S): 11-01

2. NRC/REGIONAL OFFICE
 U.S. Nuclear Regulatory Commission, Region III
 2443 Warrenville Road, Suite 210
 Lisle, Illinois 60532

3. DOCKET NUMBER(S)
 030-36932

4. LICENSEE NUMBER(S)
 21-32573-01

5. DATE(S) OF INSPECTION
 7/29/11

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied
 _____ Non-cited violation(s) were discussed involving the following requirement(s):
- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Bob Hays Bill C. Lin	 	8/1/11
Branch Chief	Tamara E. Bloomer		8/4/11

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE I.C.S. Services Corporation 4225 Miller road Suite 118 Flint, MI 48601 REPORT NUMBER(S) 11-01		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission, Region III 2443 Warrenville Road, Suite 210 Lisle, Illinois 60532	
3. DOCKET NUMBER(S) 030-36932		4. LICENSEE NUMBER(S) 21-32573-01	5. DATE(S) OF INSPECTION 07/29/2011
6. INSPECTION PROCEDURES 87124		7. INSPECTION FOCUS AREAS 03.01 – 03.07	
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM 03121	2. PRIORITY 5	3. LICENSEE CONTACT Craig Stephenson	4. TELEPHONE NUMBER 810-760-4301
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: 07/2016	
<input type="checkbox"/> Field Office Inspection _____			
<input type="checkbox"/> Temporary Job Site Inspection _____			

PROGRAM SCOPE

The address on the license is 4225 Miller Rd, Suite 118, Flint, MI. This is actually the mailing address. The licensee and the gauge are actually located at 4401 Western Road, Flint, MI. The licensee is a company that provides roofing and exterior work for industrial facilities. The licensee possesses one Troxler Model 3216 moisture density gauge for use daily/weekly during the construction season (May-November) for roofing projects. The licensee does not perform any service or maintenance activities on its gauge; these services are performed by the manufacturer. Currently, the licensee employs two authorized gauge users who have completed manufacturers training. Device is stored in a vault in the licensee's office in Flint, Michigan.

Performance Observations

At the time of this inspection, the gauge was not in use. The gauge case was locked and stored in a storage container which was bolted to the floor. This licensee locked and labeled this container. Security during transport and at the job-site was described and observed respectively with no problems noted. The inspectors performed independent radiation measurements around the storage area. The inspectors closed out the previous violation, the licensee had a Troxler Alert Meter.