

D. L. Hammond
FILE

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406
July 21, 1978
DAEC - 78 - 352

Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission-Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

U.S. NRC
DIST. DIVISION
SERVICES
BRANCH

1978 AUG 2 11 0 57

U.S. NRC
DIST. DIVISION
SERVICES
BRANCH

Subject: Licensee Event Report No. 77-95 UPDATE REPORT
(14 day) PREVIOUS REPORT DATE 123077

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,

Ellery L. Hammond
Ellery L. Hammond
Chief Engineer
Duane Arnold Energy Center

Docket 50-331

attachment

ELH/JVS/nf

cc: Director, Office of Inspection and Enforcement (40)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director, Management Information and Program Control (3)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

JUL 24 1978

AS 4
Aug 5/11/80

LICENSEE EVENT REPORT

CONTROL BLOCK:

							(1)
--	--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	I	A	D	A	C	1	2	0	0	-	0	0	0	0	0	0	-	0	0	3	4	1	1	1	1	1	4	5	
7	8	LICENSEE CODE						14	LICENSE NUMBER												25	LICENSE TYPE					30	CAT		58

CON'T

0 1 7 8

REPORT SOURCE

L 6 0 5 0 0 0 3 3 1 7 1 2 2 0 7 7 8 0 7 2 1 7 8 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During surveillance testing the HPCI system discharge flow rate did not
0 3 | reach the required flow of 3000 GPM in the 25 seconds allowed by the s
0 4 | urveillance test. Two additional restarts of the system were required t
0 5 | o reach design flow rates and time. Flow rate requirement listed in Tec
0 6 | h Spec 4.5.D.1. Repetitive occurrence (see RO 77-77). Redundant emerg
0 7 | ency core cooling systems operable.
0 8 |

0 9		SYSTEM CODE S F		CAUSE CODE X	CAUSE SUBCODE Z	COMPONENT CODE T U R B I N				COMP. SUBCODE Z	VALVE SUBCODE Z					
7	8	9	10	11	12	13	14	15	16							
LER/RO REPORT NUMBER 17		EVENT YEAR 7 7			SEQUENTIAL REPORT NO. 0 9 5			OCCURRENCE CODE 0 1		REPORT TYPE T		REVISION NO. 1				
21		22		23	24		25	26		27	28	29	30	31	32	
ACTION TAKEN E		FUTURE ACTION L		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED Y		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER N		COMPONENT MANUFACTURER T 1 4 7
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Improper adjustment of two throttle screws on the stop valve bonnet caus

1 1 | ed the balancing chamber pressure to exceed manufacturer's recommendatio

1 2 | n. Higher balancing chamber pressure made hydraulic cylinder pressure in

1 3 | adequate for positioning valve disc. Throttle screws were adjusted to br

1 4 | ing balancing chamber pressure within manufacturer's recommendation.

FACILITY STATUS (28) 1 5 E 7 8 9
% POWER 0 9 9 29 10 12 13
OTHER STATUS NA 30 44
METHOD OF DISCOVERY B 31 45
DISCOVERY DESCRIPTION 32 Surveillance Test 46

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 7 8 9 Z 33 10 Z 34 NA 11 44

LOCATION OF RELEASE (36)

45 NA 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z	(38) NA	(39)		

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	3	0	0
0	0	0	40
		NA	

		LOSS OF OR DAMAGE TO FACILITY		
		TYPE	DESCRIPTION	(43)
1	9	Z	(42) NA	

20		N44		NA		NRC USE ONLY									
----	--	-----	--	----	--	--------------	--	--	--	--	--	--	--	--	--

NRC USE ONLY

NAME OF PREPARER J. Van Sickle

PHONE: 319-851-5611

DUANE ARNOLD ENERGY CENTER

Iowa Electric Light and Power Company

LICENSEE EVENT REPORT-Supplemental Data

Docket Number 050-0331

Licensee Event Report Date: 072178

Reportable Occurrence No: 77-095

Event Description:

During surveillance testing of the HPCI system, the HPCI pump did not reach the required discharge flow rate (3000 gpm) due to failure of the turbine to reach full rated speed. The HPCI system was declared inoperable and redundant emergency core cooling systems were demonstrated to be operable. This occurrence was repetitive (see RO 77-96, 78-25).

Cause of Occurrence:

The occurrence was caused by improper adjustment of two throttle screws on the turbine stop valve which caused the balancing chamber pressure to exceed the manufacturer's recommendation. The turbine stop valve, which is a Schutte and Koerting inverted oil type, is designed to utilize steam pressure in a balancing chamber for assisting in closing and tightly seating the valve disc. For opening, the valve is equipped with an internal pilot valve which opens in the first $\frac{1}{4}$ " of valve stem travel to exhaust steam from the balancing chamber through the valve disc to the outlet side of the valve. By controlling steam flow into the balancing chamber and through the pilot unit, a controlled pressure differential is established across the valve disc enabling it to be opened easily by the hydraulic cylinder. Two throttle screws in the valve bonnet control the steam flow into the balancing chamber thereby establishing the pressure differential across the valve disc. Improper throttle screw adjustment had the balancing chamber pressure making the hydraulic system pressure inadequate for fully opening the valve.

Corrective Action:

The throttle screws were adjusted so that the balancing chamber pressure equalled manufacturer's recommended pressure (10% of inlet steam pressure). The HPCI turbine was then successfully tested and returned to service.