TION FOR PART 50 DOCKET MATERIAL (TEMPORARY FORM) NRC DISTRIP

CONTROL NO: 4360

FILE: INCIDENT REPORT FILE

FROM: Iowa Electric Light &			DATE OF DOC	DATE REC'D		LTR	тwх	RPT	OTHER
Cedar Rapids, Iowa		, Iowa	4-17-75	4-	21-75	xx			
G.G. Hunt TO: James G. K		ppler	ORIG	CC	OTHER	SE	NTAE	CPDR_	XXXXX XXXXX
. oures of vehiter			1 Signed		SENT LOCAL PDR				
	UNCLASS	PROP INFO	INPUT	NOC	YS REC'D	D	DCKET	NO:	······································
CLASS	XXXX	PROFINED		NOC	1		JUNET		50-331
	AMAMA .					L	.		
DESCRI	PTION:	• • • • • • • • • • • • • • • • • • •	· · · · · ·	ENCL	OSURES:				: .
			• •					· <u>.</u> ·	
Ltr. tr	ans the fol	lowing							-7-75, cond
		•	without an initial	ST.		ency Se	ervice	water	Pump Flow r
· ·		and the second	and the work where	1 1 . (4)	•••••		· · · · ·		· . · ·
			· · ·		(1	cv. I	Encl. 1	rec'd)	
		·) •	المتقفية المناقبة المناقبة المناقبة. الم	٦٢ المراد بي ا		-, •		/	
		E.	ENCTRE!		J				· · ·
PLANT	NAME: Du	ane Armold	· · ·		•			· <u>·</u> ·	· · · · · · · · · · · · · · · · · · ·
			FOR ACTION/	INFOR	MATION			V	CR_4=23=75
BUTLEF	R (L)	SCHWENCER	(L) ZIEMANN (L)	REGAN				
W/ Co		W/ Copies	W/ Copies		W/ Co				· · · ·
CLARK		STOLZ (L)	DICKER (E		LEAR (• •
W/ Co		W/ Copies	W/ Copies		W/3Co	pies	•		• •
PARR (I		VASSALLO (L) KNIGHTON W/ Copies		SPELS W/ Co	nies			
W/ Co KNIEL (W/ Copies PURPLE (L)	YOUNGBL			vhies			
W/ Co		W/ Copies	W/ Copies		′ W/ Co	opies			
TV/ CO	pica ·		INTERNAL D						
REG EI	/c 3	TECH REVIE			LIC AS			A/T I	ND.
NRC PD		SCHROEDER			R. DIGGS				TMAN
	DOM P-506A	MACCARY	GAMMILL		H. GEARI			SALT	ZMAN
GOSSIC	K/STAFF	KNIGHT	KASTNER		E. GOULB	OURN		MEL	TZ,
CASE		PAWLICKI	BALLARD		P. KREUT		Ξ)·	01.04	10
GIAMBL		SHAO	SPANGLER		J. LEE (L)			PLAN MCD	<u>NS</u> ONALD
BOYD	(1)	*_STELLO *_HOUSTON	ENVIRO		M. MAIGR S. REED (PMAN
MOORE DEYOU		* NOVAK	MULLER		M. SERVIC				E (Ltr)
		ROSS	DICKER		S. SHEPPA		.)	E.CC	DUPE
	R(L)(Ltr)	IPPOLITO	KNIGHTON		M. SLATE		-		RSON
P. COLL	INS	TEDESCO	YOUNGBL	DOC	H. SMITH	(L)			TFIELD (2)
DENISE		LONG	REGAN		S. TEETS		· ·	- KLE	CKER NHUT
REG OP			PROJECT L	UK	G. WILLIA)		GINTON
MIPC/I	REGION (2)	BENAROYA	HARLESS		V. WILSON			•	WILLIAMS
STEELE				•				we HAN	
	, 		EXTERNAL D	ISTRIE	RUTION			- 11211	An
		- 1					•		
1 - LC 1 - TI	CALPDR <u>C</u> (ABERNAT	edar_Rapids, 1 HY) (1)(2)(10)	Lowa 	\BS				-SAN/L	
1 NS	IC (BUCHAN		– W. PENNINGT	ON, Rn	n E-201 GT				EN NAT LA
1 - AS		1	- CONSULTANT						IN, ORNL ITH GUSSMA
	wton Anderso		NEWMARK/BI	_UME//	AGRABIAN	. .		B-127 G	
	CRS SENT T	O LIC ASST DAY REPORTS	TANTS		·· .	_ 1	J. D	, RUNK	LES, Rm E-2
	ND UNDI IEN	DAI AEPUKIS							
							GT		
						. ••			MA

IOWA ELECTRIC LIGHT AND POWER CORPANY

General Office CEDAR RAPIDS, IOWA DUANE ARNOLD ENERGY CENTER PALO, IOWA APRIL 17, 1975 DAEC-75-165

Mr. James G. Keppler, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission-Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

> SUBJECT: Abnormal Occurrence No. A.O. 50-331/75-18 FILE: A-110 A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center, please find enclosed a written report on the subject abnormal occurrence.

Mr. C. Feierabend, of your office, was notified of the abnormal occurrence on April 8, 1975.

Very truly yours,

G. G. Hunt Chief Engineer Duane Arnold Energy Center

DLW:GGH:bh Enclosure

- CC: B. C. Rusche
 - C. W. Sandford
 - J. A. Wallace
 - E. L. Hammond
 - H. W. Rehrauer-Chairman, Safety Committee
 - J. R. Newman

4360

107. T. S.

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office Cedar Rapids, Iowa

Subject:	Abnormal Occurrence
Report Number:	A. 0. 50-331/75-18
Report Date:	April 17, 1975
Occurrence Date:	April 7, 1975
Facility:	Duane Arnold Energy Center, Unit #1, Palo, Iowa

Identification of Occurrence

Out-of-specification Emergency Service Water Pump Flow Rates, reportable in accordance with Appendix A to Operating License DPR-49, Specification 1.0.4.b and 3.8.C.1.

Description of Occurrence

During the performance of Surveillance Test Procedure No. 48C001 - Emergency Service Water System, it was determined that the flow rates for the Emergency Service Water Pumps were as follows:

Flow Rate

Pump 1P-99A Pump 1P-99B 1130 gpm @ 73.5 psig TDH (170 Ft.) 1125 gpm @ 73.5 psig TDH (170 Ft.)

In accordance with Specification 4.8.C.1, the required flow rate for the pumps is 1200 gpm at a TDH of 73.5 psig (170 Ft.).

The Surveillance Test was performed after plant personnel determined that the wrong flow element orifice curve had been used when verifying pump flow rates during previous surveillance testing.

Designation of Apparent Cause of Occurrence

The cause of the occurrence was normal wear of the pump impellers. A contributing cause to the occurrence was the use of the wrong flow element orifice curve when verifying pump flow rates during previous surveillance testing.

Analysis of Occurrence.

Investigation into the affect of the occurrence on plant safety has not been completed. The results of the investigation will be included in a Supplementary Report.

A.O. 50-331/75-18

- 2 -

4/7/75

Corrective Action

The impeller clearances on the pumps were reduced and Surveillance Test No. 48C001 was repeated. The flow rates after readjustment of the impeller clearances were as follows:

Flow Rate

Pump	1P-99A	•		1200	gpm	0	73.5	TDH
Pump	1P-99B			1230	gpm	9	73.5	TDH

Pump 1P-99A was returned to service on April 8, 1975 and pump 1P-99B was returned to service on April 10, 1975.

The proper flow element orifice curve has been incorporated in the Emergency Service Water Surveillance Test Procedure.

Conclusion

This report was reviewed and approved by the DAEC Operations Committee on April 17, 1975.

Zhan

G. G. Hunt Chief Engineer Duane Arnold Energy Center

DLW:GGH:bh