# NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL (TEMPORARY FORM)

. .•


CONTROL NO: 3885

FILE: INCIDENT REPORT FI

FROM:			arDAJE OF DOC	DAT	E REC'D	LTR	TWX	RPT	OTHER	
	Cedar Rapids Ellery Hammo		4-4-75		<b>-10-</b> 75	XX				
TO:	CITELY DAMME		ORIG	CC	OTHER	ŚE	NT AE	CPDR_		
	James G. Keppler		1 Signed			1		CALPD		
CLASS	UNCLASS	PROP INFO	INPUT	NO C	YS REC'D	D	OCKET	NQ:		
<del></del>	XXX		·	1				50-	331	
DESCRIPTION:				ENCLOSURES:				· .		
Lt . ti	rans the fol		Abnorm. Occurr. # 75-16, on 3-28-75, con- cerning Inoperable Drywell Floor Drain O							
							n Valve CV-3705			
	. *		· · ·				·-··		•	
	•	•			( 1 cy	. Encl	. Rec'	d)	· · · · · ·	
	;	•	ACKNOWL	EDG	EDNOI	VOT	REN	IOVE		
PLANT	NAME:				<u>}</u> 0.0 1		25 W 26 W	<b></b>		
<u></u>	Dua	ne Arnold	FOR ACTION/	INFOR	MATION	<del></del>		VCR	4-10-75	
BUTLE	R (I)	SCHWENCER			REGAN	J (F)				
W/ Co		W/ Copies	W/ Copies	•	W/ Co				•	
CLARK		STOLZ (L)	DICKER (E		LEAR			·	· •.	
W/ Co		W/ Copies	W/ Conies		W/BC					
PANN		VASSALLO (			SPELS	•				
W/ Co		W/ Copies	W/ Copies		W/ Co	opies				
KNIEL		PURPLE (L)	YOUNGBLO			•				
W/ C		W/ Copies	W/ Copies		′ w/ co	opies				
			INTERNAL D		UTION	·			······································	
REG E		TECH REVIE	N DENTON		LIC AS	ST		A/T I	ND.	
NRC P		SCHROEDER			R. DIGGS		•	BRAI	TMAN	
	ROOM P-506A	MACCARY	GAMMILL	•	H. GEARI		•	SALT	ZMAN	
GOSSI	CK/STAFF	KNIGHT	KASTNER		E. GOULE		E (L):	MEL	rz .	
CASE		PAWLICKI	BALLARD		P. KREUT					
GIAMB	02211	SHAO	SPANGLER		J. LEE (L		- /	PLAN	IS	
BOYD		STELLO	0		M. MAIGR			MCDO	DNALD	
MOORI	F (1) **	HOUSTON	ENVIRO		S. REED (	'E)	•	CHAP		
	JNG (L) **	HOUSTON	MULLER		M. SERVI				E (Ltr)	
	OLT (L)	ROSS	DICKER		S. SHEPP		}	E. CO		
	R (L) (Ltr)	IPPOLITO	KNIGHTON	1	M. SLATE		••		RSON	
P. COL		TEDESCO	YOUNGBL		H. SMITH			HAR	FFIELD (2)	
DENIS		LONG	REGAN		S. TEETS			- KLEC		
REG O		LAINAS	PROJECT L		G. WILLIA				VHUT	
	REGION (2)	BENAROYA			V. WILSO		1. 		SINTON	
	ILSON(3)	VOLLMER	HARLESS				• •		·	
STEEL		VULLINEN	HANGE 50	<u>)</u>	R. INGRA			-	VILLIAMS	
	<u> </u>						Z	TAN	R R	
	A	<u>.</u>	EXTERNAL D	121 815				104		
01 - LI	OCAL PDR 💪	Edar Raf	an vo.					0 A A 4 / A		
⊿1 - T	IC (ABERNAL	HY) (1)(2)(10)	- NATIONAL LA	48S		-		-SAN/LA		
1 – N	SIC (BUCHAN)	AN) 1	- W. PENNINGT	ON, Rn	າ E-201 GT				EN NAT LAE	
1 - A		1	- CONSULTANT			- 1			N, ORNL	
	ewton Anderson	n .	NEWMARK/BL		AGBABIAN	1 1			TH GUSSMA	
	CRS SEIT TO							B-127 G		
	END CMLY TEN		÷.			1		RUNK	LES, Rm E·2	
		•					GT			
		•								



## IOWA ELECTRIC LIGHT AND POWER COMPANY



General Office CEDAR RAPIDS, IOWA DUANE ARNOLD ENERGY CENTER PALO, IOWA APRIL 4, 1975 DAEC-75-146



Mr. James G. Keppler, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission-Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

> SUBJECT: Abnormal Occurrence No. A.O. 50-331/75-16 FILE: A-110 A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center, please find enclosed a written report on the subject abnormal occurrence.

Mr. C. Feierabend, of your office, was notified of the abnormal occurrence on March 28, 1975.

Very truly yours,

Clery L. Hamme

Ellery W. Hammond Assistant Chief Engineer Duane Arnold Energy Center

DLW:ELH:bh Enclosure

CC: B. C. Rusche

C. W. Sandford

J. A. Wallace

G. G. Hunt

- H. W. Rehrauer-Chairman, Safety Committee
- J. R. Newman

3885

### IOWA ELECTRIC LIGHT AND POWER COMPANY General Office

Cedar Rapids, Iowa

Subject:	Abnormal Occurrence							
Report Number:	A.O. 50-331/75-16							
Report Date:	April 4, 1975							
Occurrence Date:	March 27, 1975							
Facility:	Duane Arnold Energy Center, Unit #1, Palo, Iowa							

#### Identification of Occurrence

Inoperable Drywell Floor Drain Outboard Isolation Valve CV-3705, reportable in accordance with Appendix A to Operating License DPR-49, Specifications 1.0.4.b and 3.7.D.1.

#### Description of Occurrence

During the performance of Surveillance Test Procedure No. 47D003, PCIS Valve Functional Test, Drywell Floor Drain Outboard Isolation Valve CV-3705 did not fully close. The inboard isolation valve was immediately closed in compliance with the Technical Specifications.

#### Designation of Apparent Cause of Occurrence

The apparent cause of the occurrence is unknown.

#### Analysis of Occurrence

In compliance with the Technical Specifications, the other outboard isolation valve was immediately closed, which ensured that the integrity of the primary containment would not be violated upon receipt of an isolation signal. Therefore, the occurrence did not present a hazard to the health and safety of the public.

#### Corrective Action

The Drywell Floor Drain Outboard Isolation Valve CV-3705 was repeatedly tested, and was observed to operate properly at all times. The valve was returned to an operable status and surveillance testing has been increased from quarterly to twice weekly for a period of one month.

3/27/75

#### <u>Conclusion</u>

ه به به مسویتین در

This report was reviewed and approved by the DAEC Operations Committee on April 4, 1975. The Committee concluded that the occurrence did not present a hazard to the health and safety of the public.

ant

G. G. Hunt Chief Engineer Duane Arnold Energy Center

SR/GGH/DLW/bh