NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL (TEMPORARY FORM)

 \mathbf{P}

CONTROL NO: 3881

FILE: INCIDENT REPORT FI

EROM	.Iowa Electric	Light & Powe	DATE OF DOC	DATE R	EC'D	LTR	тwх	RPT	OTHER
FUM	Palo, Iowa G.G. Hunt		3_31_75	/_10	-75	vv			
			0816			SE	NTAF	CPDB	
10:	James G. Keppler		1Cton d	CC OTHER					
			ISigned			SENT LOCAL PDR XXXX			
CLASS	UNCLASS	PROP INFO	INPUT	NOCYS	REC'D		JCKEI	NU:	
•			· · · ·	40	D			3.7,	
	DURTION	L		ENCLOS					<u> </u>
DESCI	RIP HUN:			LINCLUS		•		• • •	
Ttr	teans the fol	lowing		Abnor	m 0.001		75-14		3-75 000
HELO CEANS CHE LOLLOWING				Abioim. Occurr. # 75-14, on 5-25-75 con				3=75 COH	
•				the primary containment					
	· ·			the p	rimary	conta	Linnen L	0,000	· · · ·
		A MERT	NOT	n ral	•	•	· ·	•	· ·
	•	AUG 1		D .	(Hocy	. Encl	Rec'	d) ·	•
			•		.1	- 			
PLAN	TNAME: Du	ane Arnold		•	D		iyana Manazara		
• 			FOR ACTION/	INFORMA	TION			VCR	4-11-75
DUT		SCHWENCER	(I) ZIEMANN	(1.)	REGAN	I (E)			
BUIL	ER (L)	W/ Copies	W/ Conies		W/ Co	noies		· _	· · · · · ·
	K (I)	STOL 7 /11) 4	LEAR	Ĺ)		÷	• . • .
		WI Conies	W/ Copies		W/SCO	Dies	• •		
DADD		VASSALLO	L) KNIGHTON	(E)	SPELS	• .		•	•
- ERDE MUL (W/ Copies	W/ Copies	· · <u>-</u> ·	W/ Co	opies		· · ·	- ·
KNIE		PURPLE (I.)	YOUNGBL	00D (E)		•	¹	•	
WL-	Conies	W/ Copies	W/ Copies	S	W/ Co	opies	• • •		
	oopico		INTERNAL D	ISTRIBUT	TION				•
DEC.		TECH REVIE	W DENTON	· · ·	LIC AS	ST		A/T I	ND .
-NRC	PDR	SCHROEDER	* GRIMES	R.	DIGGS	(L)	·	BRAI	TMAN
060	ROOM P-506A	MACCARY	GAMMILL	H.	GEARI	Ň (L)		SALT	ZMAN
GOSS	ICK/STAFF	KNIGHT	KASTNER	E	GOULE	OURN	E (L)	MEL	ΓZ
-CASE		PAWLICKI	BALLARD	P.	KREUT	ZER (E)	•	
GIAM	BUSSO	SHAO	SPANGLEF	β J.	LEE (L)		PLAN	IS
BOYE) *1	STELLO		́М.	MAIGR	ET (L)		MCD	JNALD
MOOF	RE(L) **	HOUSTON	ENVIRO	S.	REED	E)	•	CHAP	
DEYC	DUNG (L)	NOVAK	MULLER	Μ.	SERVIO	CE(L)	、		= (LIT) NIDE
SKOV	HOLT (L)	ROSS	DICKER	S.	SHEPP		.)		BSON
GOLL	ER (L) (Ltr)	IPPOLITO	KNIGHTOP	M.	SLAIE	K (E)		HAR	TELELD (2)
P. CO	LLINS	TEDESCO	TUUNGBL	ουυ H.	SIVILIH	(L) (L)			IKEB
DENI	SE	LUNG		DR S.	16615	NAC IE	,	FISE	NHUT
<u>HEG (</u>	UPR CLONE (2)	LAINAS	PRUJEUI	LUN G.	WILLIA	ANIO (E NI / L) -	/	WIGO	SINTON
FILE.	& REGION(2)	BENAKUYA	LADIECC	· V.	WILSU	N (L) - NA (L) -	••		
I.K. V	WIESON (3)	≁ VUELMER	HANLE 33	К.	INGRA	.ivi (L)	•	ا با عمر دور در ممر	NTEFT749
SILL	LE	·						TA L	The second
	· · · · · · · · · · · · · · · · · · ·	- Par	EXIENNALL	<u>191 KIBU</u>			Q	107	
⊳ 1-	LOCAL PDR C.	Edas Nep	~~ VO.	A DC			ph c	CAN/L	
<u>_1-</u>	TIC (ABERNAT	HY) (1)(2)(10)	- NATIONAL L	4B2				1-3HN/L/ 1050/10/1/	VPF EN NATEZ
1-	NSIC (BUCHAN	AN) 1	- W. PENNINGT	UN, Km E	-201 G I	1	- onu		N OBM
<u> </u>	ASLB	1	- CONSULTAN	TS		. 1		AED 1011	H, UNICE
1	Newton Anderso	n	NEWMARK/B	LUME/AG	BARIAN	4 1	P-AGP	R. 127 G	T
- 2-	ACRS SELT T	O LIC ASST					nm 1 C	D RIMV	IFS SMF
**	SEND CULY TEN	DAY REPORTS				. (- J. L הד	A HONK	LLU, MAR C
		·•					04		
	· •		a tha an				•		
			• .		• •	• • • •	• • • • • •		

٣

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office CEDAR RAPIDS, IOWA DUANE ARNOLD ENERGY CENTER PALO, IOWA MARCH 31, 1975 DAEC-75-131



Mr. James G. Keppler, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission-Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

> SUBJECT: Abnormal Occurrence No. A.O. 50-331/75-14 FILE: A-110 A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center, please find enclosed a written report on the subject abnormal occurrence.

Very truly yours,

Alexander .

G. G. Hunt Chief Engineer Duane Arnold Energy Center

DLW:GGH:bh

- CC:E. G. Case
 - C. W. Sandford
 - J. A. Wallace
 - E. L. Hammond
 - D. L. Wilson
 - H. W. Rehrauer-Chairman, Safety Committee

3881

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office Cedar Rapids, Iowa

Subject:	Abnormal Occurrence							
Report Number:	A.O. 50-331/75-14							
Report Date:	March 31, 1975							
Occurrence Date:	March 23, 1975							
Facility:	Duane Arnold Energy Center, Unit #1, Palo, Iowa							

Identification of Occurrence

سې ري⊷ _____

Unidentified coolant leakage into the primary containment, reportable in accordance with Appendix A to Operating License DPR-49, Specifications 1.0.4.b and 3.6.C.1.

Conditions Prior to Occurrence

Reactor at steady-state power conditions, 430 MWt and 119 MWe.

Unidentified drywell coolant leakage rate - 0.6 gpm. Identified leakage rate - 2.0 gpm.

Description of Occurrence

At approximately 0245 hours, the following alarms were received in the Control Room:

Hi Drywell Equipment Drain Sump Temperature Drywell Equipment Drain Sump - Hi Leak

An immediate investigation by operating personnel determined that the drywell equipment drain and drywell floor drain integrators were indicating 21.3 gpm and 10.4 gpm respectively. A later analysis of the rate of accumulation of water in the radwaste processing facilities indicated that the actual equipment drain and floor drain leakage rates were 14.6 gpm and 4.0 gpm, respectively. The high readings on the sump flow integrators apparently were caused by the high temperature water flashing to steam across the flow elements.

Preparations for a reactor shutdown and subsequent drywell entry were commenced at 0315 hours.

The main turbine-generator was removed from the grid at 0700 hours.

A.O. 50-331/75-14

3/23/75

Designation of Apparent Cause of Occurrence

The cause of the occurrence was an internal packing leak on the "B" Recirculation Loop discharge valve. (MOV 4628) Leakage from the packing is piped directly to the drywell equipment drain sump. The increased leakage to the drywell floor drain sump was caused by overflow from the equipment drain sump.

Analysis of Occurrence

All of the leakage from the packing on MOV 4628 was handled by the drywell equipment and floor drain sumps and processed as liquid radwaste, therefore, the occurrence did not present a hazard to the health and safety of the public.

Corrective Action

MOV 4628 was backseated and the drain line from the internal packing to the drywell equipment drain sump was isolated. An inspection of the drywell verified that the outer packing on MOV 4628 was not leaking. Any future leakage from the MOV 4628 outer packing will be detected by the drywell floor drain sump and classified as unidentified leakage for determination of Technical Specification limits.

Conclusion

This report was reviewed and approved by the DAEC Operations Committee on March 31, 1975. The Committee concluded that the occurrence did not present a hazard to the health and safety of the public.

Very truly yours,

7 hand

G. G. Hunt Chief Engineer Duane Arnold Energy Center

DLW:GGH:bh