UTION FOR PART 50 DOCKET MA AEC DIST (TEMPORARY FORM)

CONTROL NO: 185

FILE: INCIDENT REPORT

FROM: Iowa Elec.	Light & Power	DATE OF DOC	DAT	E REC'D	LTR	TWX	RPT	OTHER
Co. Palo, Iowa Ellery L. Hammond		1 - 3 - 75	1-7-7	5	XXX			
TO:		ORIG	CC	OTHER	SENT AEC POR XX			
Mr. E. Case		1 signed			SENT LOCAL PDRXX		<u> </u>	
CLASS UNCLASS	PROP INFO	INPUT	ио с,	YS REC'D	DO	OCKET	NO:	
XXX				1		5	0-331	
DECODISTION: The			ENCL	OSURES:				•

DESCRIPTION: Ltr reporting an occurrence on 12-26-74 involving isokinetic sample line being plugged, thereby obstructing flow through the sample line....

PLANT NAME:

Duane Arnold Plant .

		FOR ACTION/INFORMA	ATION DHI	1-8-75	
BUTLER (S)	SCHWENCER (S)	ZIEMANN (S)	REGAN (E)	•	
W/ Copies	W/ Copies	W/ Copies	W/ Copies		
CLARK (S)	STOLZ (S)	DICKER (E)	LEAR (S)	•	
W/ Copies	W/ Copies	W/ Copies	W/ ∜ Copies	•	
PARR (S)	VAŜSALLO (S)	KNIGHTON (E)	SPEIS (S)		
W/ Copies	W/ Copies	W/ Copies	W/ Copies		€.
KNIEL (S)	PURPLE (S)	YOUNGBLOOD (E)			
W/ Copies	W/ Copies	W/ Copies	W/ Copies		
		INTERNAL DISTRICT	TION		

		INTERNAL DISTR	IBUTION
REG FILE	TECH REVIEW	DENTON	LIC. ASST. A/T IND
VAEC FDR	SCHROEDER	GRIMES	DIGGS (S) BRAITMAN
OGC, ROOM P-506-A	MACCARRY	GAMMILL	GEARIN (S) SALTZMAN
MUNIZING/STAFF	KNIGHT	KASTNER	GOULBOURNE (S) B. HURT
CASE .	PAWLICKI	BALLARD	KREUTZER (E)
GIAMBUSSO	osh ac	SPANGLER	LEE (S) PLANS
BOYD	€TELLO		MAIGRET (S) MCDONALD
MOORE (S) (BWR)	HOUSTON	ENVIRO	REED (E) CHAPMAN
DEYOUNG (S) (PWR)	NOVAK	MULLER	SERVICE (S) DUBE w/input
SKOVHOLT (S)	€ ROSS	DICKER	SHEPPARD (S) E. COUPE
GOLLER (S)	PIPPOLITO	KNIGHTON	SLATER (E) D. THOMPSON (2)
P. COLLINS	TEDESCO	YOUNGBLOOD	SMITH (S) SKLECKER
DENISE	LONG	REGAN	TEETS (S) F. WILLIAMS
REG OPR	LAINAS	PROJECT LDR	WILLIAMS (E)
FILE & REGION (2)	BENAROYA	and the second of the second of the second	WILSON (S)
OT.R. WILSON STE	ELE 🗳 VOLIMER	HARLESS	INGRAM (S)

t ₁	EXTERNAL DISTRIBUTION	AO K
VI-LOCAL PDR Cedar Rapids	, Iowa(1)(2)(10)-NATIONAL LABS	1-PDR SAN/LA/NY
-TIC(ABERNATHY)	1-W, PENNINGTON, RM E-201 G.T.	1-BROOKHAVEN NAT LA
enste (Riichanan)	1-CONSULTANTS	1-G. ULRIKSON, ORNL

·NSIC(BUCHANAN) 1-ASLB

1-NEWION ANDERSON 5-ACRS SENT TO LIC. ASST. S. Teets 1-8-75 NEWMARK/BLUME/AGBABIAN

AB 1-AGMED (RUTH GUSSMAN) RM B-127 G.T. 1-J. RUNKLES, RM E-201

G.T.

TOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS, IOWA

DUANE ARNOLD ENERGY CENTER

PALO, IOWA

JANUARY 3, 1975

DAEC - 75 - 1

Mr. Edson G. Case
Acting Director of Licensing
Directorate of Licensing
U. S. Atomic Energy Commission
Washington, D. C. 20545

6 1 MIN 1975

SUBJECT: Technical Specification Violation 74-14

FILE: A-110, A-117

Dear Mr. Case:

This letter is to report to you in accordance with Appendix B, Operating License DPR-49, Specification 2.3.1.C.8.

Problem

At approximately 0300 hours on December 26, 1974, with reactor power at 1000 MWt the Off-Gas Sample Hi-Lo Flow Alarm sounded. Investigation revealed that the isokinetic sample line was plugged, thereby obstructing flow through the sample line. The monitors measuring the radiation in the sample were therefore not able to make measurements. Specification 2.3.1.C.8 states that the "Off-Gas Radiation Monitors shall be operable or operating whenever steam pressure is available to the air ejectors".

Investigation

Investigation revealed that condensate in the isokinetic sample line had frozen and plugged the sample line. Pre-treatment and post-treatment off-gas monitors and the steamline monitors did not detect any increase in radiation during the time the Off-Gas Radiation Monitoring System was out of operation. Therefore, the inoperability of the Off-Gas Radiation Monitoring System did not present a potential hazard to the health and safety of the public.

A previous Technical Specification Violation involving a frozen Off-Gas Sample Line occurred on December 4, 1974. (See Technical Specification Violation Report No. 74-13). The sample line was heat traced to prevent freezing, however, it was not considered necessary to insulate the line at that time.

Corrective Action

The isokinetic sampling line was de-iced and the Off-Gas Radiation Monitoring System was back in operation by 0850 hours on the same day. In order to prevent the sample line from freezing again, fiberglass insulation was added to the portion of the line that was heat traced.

Conclusion

The DAEC Operations Committee and Safety Committee reviewed and approved the actions taken and conclusions reached in this report on January 3, 1975. The Committees concluded that the subject incident did not present a hazard to the health and safety of the public.

Very truly yours,

Ellery L. Hammond

Clery L. Hammo

Assistant Chief Engineer Duane Arnold Energy Center

DLW/ELH/mg

cc: J. G. Keppler

C. W. Sandford

J. A. Wallace

E. L. Hammond

B. R. York

R. G. Graybeal

D. L. Wilson

R. R. Rinderman

H. W. Rehrauer-Chairman, Safety Committee

B. L. Hopkins