# AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

(TEMPORARY FORM)

DATE REC'D

FROM: Iowa Electric Light & Pwr DATE OF DOC

10817

OTHER

CONTROL NO:\_\_

RPT

FILE:\_

TWX

LTR

Cedar Rapids, Iowa										
Mr. G.G. Hunt		10 <b>-7-74</b> ORIG		8-74	X	NIT A F	CDDD	VVV		
				CC OTHER			SENT LOCAL PDR XXX			
J.G. Keppler			1 signed		JENT LOCALI DIT					
CLASS	UNCLASS	<b>P</b> ROP INFO	INPUT	NO C,	YS REC'D	DO	OCKET	NO:		
	XXX		•	4	0	5	0-331			
DESCRIPTION:				ENCL	OSURES:	I				
_	~	normal Occurre Centertran		con		HPCI T	urbine	Steam	331/74-40 Line High F1	
					(40	cys e	ncl re	c'd)		
PL'ANT I	NAME: Du	ane Arnold				A	CKN	OWL	EDGED	
	~ 4.		EOD ACTION/	INFOR	MATION		10.0	1 7/	***	
DUTL CC	\ /I \	COLUMENOED	FOR ACTION/				10-2	1-/4	JB	
BUTLER W/ Copi		SCHWENCER W/ Copies	(L) ZIEMANN ( W/ Copies	L)	REGAN W/ Cop		D ( )	TOM T	TARKOTTI	
CLARK (L)		STOLZ (L)	DICKER (E)	)	LEAR (	1 )	DON	IOL I	REMOVE	
V/ Copies W/ Copies		W/ Copies	,	W/ <b>Y/C</b> op						
PARR (L) VASSALLO (I			(E)	, <b>,</b> 00p	103					
N/ Copies W/ Copies		W/ Copies		W/ Cop	ies					
KNIEL (L) PURPLE (L)		YOUNGBLO	OOD (E)							
N/ Copies W/ Copies		W/ Copies		W/ Cop	ies			• •		
			INTERNAL D	ISTRIB	UTION				-	
REG FIL		TECH REVIE			LIC ASS	ST_		A/T II		
AEC PDI	OM P-506A	SCHROEDER	GRIMES GAMMILL		DIGGS	/ L \		BRAI	INAN ZMAN	
	NG/STAFF	✓ MACCARY	KASTNER		GEARII			B. HU		
CASE	,,,	KNIGHT	BALLARD		GOULB		E (L)	D. 110		
GIAMBU	ISSO	PAWLICKI	SPANGLER		KREUT	ZER (E		PLAN		
		SHAO			LEE (L)				ÑALD	
		STELLO	ENVIRO		MAIGR			CHAP		
DEYOUNG (L) (PWR) ✓HOUSTON SKOVHOLT (L) ✓NOVAK			MULLER		REED (		٠		w/input	
GOLLER (L) ROSS		DICKER KNIGHTON		SERVIC SHEPPA		١	E. CO	JPE		
	COLLINS / IPPOLITO		YOUNGBLO		SLATE			∕D TH	OMPSON (2)	
DENISE			REGAN SMITH (				KLEC			
REG OPE	3	<b>✓</b> LONG	✔ PROJECT L	DR	✓ TEETS			✓EISEN		
	REGION (3)	LAINAS	St. Mary		WILLIA					
MORRIS		<b>✓</b> BENAROYA	HARLESS		WILSON	J (L)				
STEELE		✓ VOLIMER			·					
			EXTERNAL DI	STRIB	UTION					
1 - LO	CAL PDR <u>c</u> e	edar Rápids, I	owa.							
<b>′</b> 1 TIC (ABERNATHY)′ (1)(2)(10) - NATIONAL LABS					<del></del>			SAN/LA		
			- ASLBP(E/W Bldg, Rm 529)				1 – BROOKHAVEN NAT LAB 1 – G. ULRIKSON, ORNL			
1 – ASI			– W. PENNINGTO							
	vton Andersor BS <b>XXXXXXXX</b>		B&M SWINEBR		rm E-201 G	1			TH GUSSMAN)	
D – ACI	DO PROBANCE	Teets	<ul><li>CONSULTANT: NEWMARK/BL</li></ul>		GRARIAN	1		3-127 GT Mueli	ER, Rm E-201	
		10-21-74	ALMINATIN DE	JIVIL/A	COUDIUM	1 '	GT	WOLLL	LII, IIIII L-201	

A finite of the control of the control

e de la companya de l

# Regulatory Docket File

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

#### CEDAR RAPIDS, IOWA

DUANE ARNOLD ENERGY CENTER
PALO, IOWA
OCTOBER 7, 1974
DAEC - 74 - 350



Mr. James G. Keppler, Director Regulatory Operations Regional Office U. S. Atomic Energy Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

SUBJECT: Abnormal Occurrence No. DPR 50-331/74-40

FILE: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center, please find enclosed a written report on the subject abnormal occurrence.

Very truly yours,

G. G. Hunt

Chief Engineer

Duane Arnold Energy Center

DLW:GGH:bh Enclosure

CC: E. G. Case

C. W. Sandford

J. A. Wallace

E. L. Hammond

B. R. York

R. R. Rinderman

L. D. Root

H. W. Rehrauer, Chairman, Safety Committee

G. A. Cook

D. L. Wilson

J. R. Newman

B. L. Hopkins



10817

# IOWA ELECTRIC LIGHT AND POWER COMPANY

# General Office

# CEDAR RAPIDS, IOWA

Subject:

Abnormal Occurrence

Report Number:

AO 50-331/74-40

Report Date:

October 7, 1974

Occurrence Date:

October 2, 1974

Facility:

Duane Arnold Energy Center, Unit #1, Palo, Iowa

#### Identification of Occurrence

HPCI Turbine Steam Line High Flow trip setting, reportable in accordance with Appendix A to Operating License DPR-49, Specifications, 1.0.4.a and 3.2.B.

#### Description of Occurrence

During the performance of Surveillance Test Procedure No. 42B025 - HPCI Steam Line High DP Instrument Functional Test and Calibration, it was determined that the trip setting of PDIS 2244 (Channel A) was + 250"  $\rm H_2^0$  (Tech. Spec. Limit + 225"  $\rm H_2^0 + 15$ "  $\rm H_2^0$ ).

#### Designation of Apparent Cause of Occurrence

The apparent cause of the occurrence was an intermittent micro-switch fault in PDIS 2244. Previous Surveillance Testing on PDIS 2244 indicated no trending towards an out-of-specification condition.

#### Analysis of Occurrence

It has been determined that the occurrence did not present an unsafe plant condition. A redundant pressure differential indicating switch (PDIS 2245) was verified operable during the Surveillance Test and would have provided HPCI Turbine Steam Line High Flow Trip capabilities if required.

### Corrective Action

PDIS 2244 was replaced and the micro-switch in PDIS 2244 was retested.

#### Failure Data

Nomenclature:

Pressure Differential Indicating Switch

Model Number:

288A

Manufacturer:

ITT - Barton

There have been no other malfunctions of this type at this facility to date.

#### Conclusion

This report was reviewed and approved by the DAEC Operations Committee on October 7, 1974. The Committee concluded that the occurrence did not present a hazard to the health and safety of the public.

GGX lamb

G. G. Hunt Chief Engineer Duane Arnold Energy Center

DLW:GGH:bh